| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0020012 | Cadillac Premium Care - Oil Change | Z2262 | GMNA |
| 0020042 | Cadillac Premium Care - Tire Rotation | Z2263 | GMNA |
| 0020072 | Cadillac Premium Care - Passenger Air Filter | Z2264 | GMNA |
| 0020102 | Cadillac Premium Care - Engine Air Filter | Z2265 | GMNA |
| 0020132 | Cadillac Premium Care - Clutch Hydraulic Service (CTS-V Only) | Z2266 | GMNA |
| 0020162 | Cadillac Premium Care - Front Wheel/Rotor Face Cleaning | Z2288 | GMNA |
| 0030019 | MPVI: Tire Tread Green - 8/32 or Greater (Notation Only - No Work Needed) | | |
| 0030039 | MPVI: Tire Tread Green (Notation Only - No Work Needed) | | |
| 0030056 | MPVI: Tire Tread Yellow - 7/32 (Notation for Future Repairs) | | |
| 0030076 | MPVI: Tire Tread Yellow - 6/32 (Notation for Future Repairs) | | |
| 0030096 | MPVI: Tire Tread Yellow - 5/32 (Notation for Future Repairs) | | |
| 0030116 | MPVI: Tire Tread Yellow - 4/32 (Notation for Future Repairs) | | |
| 0030136 | MPVI: Tire Tread Yellow (Notation for Future Repairs) | | |
| 0030157 | MPVI: Tire Tread Red - 3/32 (Repairs Recommended) | | |
| 0030177 | MPVI: Tire Tread Red - 2/32 (Repairs Recommended) | | |
| 0030197 | MPVI: Tire Tread Red - 1/32 or Less (Repairs Recommended) | | |
| 0030217 | MPVI: Tire Tread Red (Repairs Recommended) | | |
| 0030239 | MPVI: Brake Lining Green - 7 mm or Greater - (Notation Only - No Work Needed) | | |
| 0030259 | MPVI: Brake Lining Green (Notation Only - No Work Needed) | | |
| 0030276 | MPVI: Brake Lining Yellow - 6 mm - (Notation for Future Repairs) | | |
| 0030296 | MPVI: Brake Lining Yellow - 5 mm - (Notation for Future Repairs) | | |
| 0030316 | MPVI: Brake Lining Yellow - 4 mm - (Notation for Futre Repairs) | | |
| 0030336 | MPVI: Brake Lining Yellow (Notation for Future Repairs) | | |
| 0030357 | MPVI: Brake Lining Red - 3 mm (Repairs Recommended) | | |
| 0030377 | MPVI: Brake Lining Red - 2 mm (Repairs Recommended) | | |
| 0030397 | MPVI: Brake Lining Red - 1 mm or Less (Repairs Recommended) | | |
| 0030417 | MPVI: Brake Lining Red (Repairs Recommended) | | |
| 0030439 | MPVI: Brake Lining Green - 8 mm (Notation Only - No Work Needed) | | |
| 0030459 | MPVI: Brake Lining Green - 9 mm (Notation Only - No Work Needed) | | |
| 0030479 | MPVI: Brake Lining Green - 10 mm (Notation Only - No Work Needed) | | |
| 0030499 | MPVI: Brake Lining Green - 11 mm (Notation Only - No Work Needed) | | |
| 0030519 | MPVI: Brake Lining Green - 12 mm (Notation Only - No Work Needed) | | |
| 0030539 | MPVI: Brake Lining Green - 13 mm (Notation Only - No Work Needed) | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0030559 | MPVI: Brake Lining Green - 14 mm (Notation Only - No Work Needed) | | |
| 0030579 | MPVI: Tire Tread Green - 9/32 (Notation Only - No Work Needed) | | |
| 0030599 | MPVI: Tire Tread Green - 10/32 (Notation Only - No Work Needed) | | |
| 0030619 | MPVI: Tire Tread Green - 11/32 (Notation Only - No Work Needed) | | |
| 0030639 | MPVI: Tire Tread Green - 12/32 (Notation Only - No Work Needed) | | |
| 0030659 | MPVI: Tire Tread Green - 13/32 (Notation Only - No Work Needed) | | |
| 0030679 | MPVI: Tire Tread Green - 14/32 (Notation Only - No Work Needed) | | |
| 0030699 | MPVI: Tire Tread Green - 15/32 (Notation Only - No Work Needed) | | |
| 0030719 | MPVI: Tire Tread Green - 16/32 (Notation Only - No Work Needed) | | |
| 0030739 | MPVI: Tire Tread Green - 17/32 (Notation Only - No Work Needed) | | |
| 0030759 | MPVI: Tire Tread Green - 18/32 or Greater (Notation Only - No Work Needed) | | |
| 0030777 | MPVI: Air Conditioning - Red (Repairs Recommended) | | |
| 0030796 | MPVI: Air Conditioning - Yellow (Notation Only for Future Repair) | | |
| 0030810 | MPVI: Engine Air Filter - Red (Replacement Recommended) | | |
| 0030836 | MPVI: Engine Air Filter - Yellow (Notation Only for Future Repair) | | |
| 0030856 | MPVI: Alignment Recommended | | |
| 0030877 | MPVI: Drive Axle (Leak, Other) - Red (Repairs Recommended) | | |
| 0030896 | MPVI: Drive Axle (Leak, Other) - Yellow (Notation for Future Repair) | | |
| 0030916 | MPVI: Tire Balance Recommended | | |
| 0030930 | MPVI: Battery - Red (Replacement Recommended) | | |
| 0030956 | MPVI: Battery - Yellow (Notation Only for Future Repair) | | |
| 0030970 | MPVI: Belts - Red (Replacement Recommended) | | |
| 0030996 | MPVI: Belts - Yellow (Notation Only for Future Repair) | | |
| 0031017 | MPVI: Body Components Lubrication - Red (Repairs Recommended) | | |
| 0031036 | MPVI: Body Components Lubrication - Yellow (Notation for Future Repair) | | |
| 0031057 | MPVI: Brake System - Red (inc. Hoses, Lines, Parking Brake) (Repairs Recommended) | | |
| 0031076 | MPVI: Brake System - Yellow (inc. Hoses, Lines, Parking Brake) - (Notation for Future Repair) | | |
| 0031097 | MPVI: Battery Cable and Connections - Red (Repairs Recommended) | | |
| 0031116 | MPVI: Battery Cable and Connections - Yellow (Notation for Future Repair) | | |
| 0031130 | MPVI: Passenger Compartment Air Filter - Red (Replacement Recommended) | | |
| 0031156 | MPVI: Passenger Compartment Air Filter - Yellow (Notation for Future Repair) | | |
| 0031177 | MPVI: Chassis Components Lubrication - Red (Recommended Service) | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0031196 | MPVI: Chassis Components Lubrication - Yellow (Notation for Future Repair) | | |
| 0031217 | MPVI: CV Drive Axle Boots or Driveshafts and U-Joints - Red (Repairs Recommended) | F911100 | Holden New Zealand |
| 0031236 | MPVI: CV Drive Axle Boots or Driveshafts and U-Joints - Yellow (Notation for Future Repair) | | |
| 0031257 | MPVI: Engine Cooling System (Leak, Other) - Red (Repairs Recommended) | | |
| 0031276 | MPVI: Engine Cooling System (Leak, Other) - Yellow (Notation for Future Repair) | | |
| 0031297 | MPVI: Evaporative Control System - Red (Repairs Recommended) | | |
| 0031316 | MPVI: Evaporative Control System - Yellow (Notation for Future Repair) | | |
| 0031336 | MPVI: Rotation Recommended | | |
| 0031357 | MPVI: Exhaust System - Red (Repairs Recommended) | | |
| 0031376 | MPVI: Exhaust System - Yellow (Notation for Future Repair) | | |
| 0031397 | MPVI: Fuel System - Red (Repairs Recommended) | | |
| 0031416 | MPVI: Fuel System - Yellow (Notation for Future Repair) | | |
| 0031437 | MPVI: Hoses (Engine, Power Steering, and HVAC) - Red (Repairs Recommended) | | |
| 0031456 | MPVI: Hoses (Engine, Power Steering, and HVAC) - Yellow (Notation for Future Repair) | | |
| 0031477 | MPVI: Oil Life Reading - Red - Oil Life 20% or Less (Oil Change Needed) | | |
| 0031496 | MPVI: Oil Life Reading - Yellow - Oil Life 20% - 50% (Notation for Future Repairs) | | |
| 0031537 | MPVI: Restraint System - Red (Repairs Recommended) | | |
| 0031556 | MPVI: Restraint System - Yellow (Notation for Future Repair) | | |
| 0031577 | MPVI: Shock/Strut - Red (Repairs Recommended) | | |
| 0031596 | MPVI: Shock/Strut - Yellow (Notation for Future Repair) | | |
| 0031617 | MPVI: Steering Components and Steering Linkage - Red (Repairs Recommended) | | |
| 0031636 | MPVI: Steering Components and Steering Linkage - Yellow (Notation for Future Repair) | | |
| 0031657 | MPVI: Engine, Transmission, Drive Axle, or Transfer Case - Red (Repairs Recommended) | | |
| 0031676 | MPVI: Engine, Transmission, Drive Axle, or Transfer Case - Yellow (Notation for Future Service) | | |
| 0031690 | MPVI: Wiper - Red (Replacement Recommended) | | |
| 0031716 | MPVI: Wiper - Yellow (Notation for Future Service) | | |
| 0031730 | MPVI: Windshield - Red (Replacement Recommended) | | |
| 0031756 | MPVI: Windshield - Yellow (Notation for Future Service) | | |
| 0031776 | Recommended Service: Maintenance 1 | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0031796 | Recommended Service: Maintenance 2 | | |
| 0031819 | MPVI: Declined to have MPVI Performed | | |
| 0031836 | Recommended Service: 25k Service | | |
| 0031856 | Recommended Service: 50k Service | | |
| 0031876 | Recommended Service: 75k Service | | |
| 0031899 | Recommended Service: 100k Service | | |
| 0031919 | Recommended Service: 125k Service | | |
| 0031939 | Recommended Service: 150k Service | | |
| 0031959 | Recommended Service: 175k Service | | |
| 0031979 | Recommended Service: 200k Service | | |
| 0031999 | Recommended Service: 250k Service | | |
| 0032019 | Recommended Service: 275k Service | | |
| 0032039 | Recommended Service: 300k Service | | |
| 0032056 | Recommended Service: LOF | | |
| 0032076 | Recommended Service: Misc. Maintenance | | |
| 0032096 | Recommended Service: Water Pump | | |
| 0032116 | Declined Recommended Service - Tune-Up | | |
| 0032136 | Recommended Service: Emission System Service | | |
| 0032156 | Recommended Service: Interior Electrical Service | | |
| 0032176 | Recommended Service: Differential Axle Maintenance | | |
| 0032196 | Recommended Service: Clutch Requires Attention | | |
| 0040032 | LOF/Tire Rotate/MPVI Promotion - Conventional Oil | | |
| 0040052 | LOF/Tire Rotate/MPVI Promotion - Synthetic Oil | | |
| 0040072 | LOF/Tire Rotate/MPVI Promotion - DEXOS Oil | | |
| 0040092 | Brake Promotion - Durastop | | |
| 0040112 | Brake Promotion - OE | | |
| 0040132 | Brake Promotion - Advantage | | |
| 0040152 | Brake Promotion - Durastop Front | | |
| 0040172 | Brake Promotion - OE Front | | |
| 0040192 | Brake Promotion - Advantage Front | | |
| 0040212 | Brake Promotion - Durastop Rear | | |
| 0040232 | Brake Promotion - OE Rear | | |
| 0040252 | Brake Promotion - Advantage Rear | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0040272 | Tire Promotion | | |
| 0040292 | Dexos Promotion | | |
| 0070012 | Smart Care: Chassis Lube, Oil, Filter ($0-$20) | M0011 | GMNA |
| 0070042 | Smart Care: Chassis Lube, Oil, Filter ($20.01 - $23.00) | M0012 | GMNA |
| 0070072 | Smart Care: Chassis Lube, Oil, Filter ($23.01 - $26.00) | M0013 | GMNA |
| 0070102 | Smart Care: Chassis Lube, Oil, Filter ($26.01 - $29.00) | M0014 | GMNA |
| 0070132 | Smart Care: Chassis Lube, Oil, Filter ($29.01 - $32.00) | M0015 | GMNA |
| 0070162 | Smart Care: Chassis Lube, Oil, Filter ($32.01 - $35.00) | M0016 | GMNA |
| 0070192 | Smart Care: Chassis Lube, Oil, Filter ($35.01 and Above) | M0017 | GMNA |
| 0070222 | Tire Rotation | M0021 | GMNA |
| 0500010 | New Vehicle Delivery Key or Transmitter Replacement | S0011 | GMNA |
| 0500032 | Floor Panel Repair | A9280 | GMNA |
| 0500032 | Floor Panel Repair | A9281 | GMNA |
| 0500032 | Floor Panel Repair | A9300 | GMNA |
| 0500032 | Floor Panel Repair | A9301 | GMNA |
| 0500032 | Floor Panel Repair | A9360 | GMNA |
| 0500032 | Floor Panel Repair | A9361 | GMNA |
| 0500032 | Floor Panel Repair | A9402 | GMNA |
| 0500032 | Floor Panel Repair | A9403 | GMNA |
| 0500032 | Floor Panel Repair | A9931 | GMNA |
| 0500032 | Floor Panel Repair | B9424 | GMNA |
| 0500032 | Floor Panel Repair | S0012 | GMNA |
| 0500032 | Floor Panel Repair | S0060 | GMNA |
| 0500032 | Floor Panel Repair | S5200 | GMNA |
| 0500032 | Floor Panel Repair | S5210 | GMNA |
| 0500032 | Floor Panel Repair | S5211 | GMNA |
| 0500032 | Floor Panel Repair | S5230 | GMNA |
| 0500032 | Floor Panel Repair | C000054 | Holden Australia |
| 0500032 | Floor Panel Repair | C000619 | Holden Australia |
| 0500032 | Floor Panel Repair | S521000 | Holden Australia |
| 0500032 | Floor Panel Repair | S523000 | Holden Australia |
| 0500032 | Floor Panel Repair | A202300 | Holden New Zealand |
| 0500032 | Floor Panel Repair | A9400 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0500032 | Floor Panel Repair | C000619 | Holden New Zealand |
| 0500052 | Underbody Side Rail Reinforcement Repair | S0013 | GMNA |
| 0500070 | Warranty Folder or Portfolio Replacement | I1003 | GMNA |
| 0500070 | Warranty Folder or Portfolio Replacement | I1004 | GMNA |
| 0500070 | Warranty Folder or Portfolio Replacement | I1012 | GMNA |
| 0500070 | Warranty Folder or Portfolio Replacement | I1027 | GMNA |
| 0500070 | Warranty Folder or Portfolio Replacement | I2000 | GMNA |
| 0500070 | Warranty Folder or Portfolio Replacement | I2002 | GMNA |
| 0500070 | Warranty Folder or Portfolio Replacement | I3001 | GMNA |
| 0500070 | Warranty Folder or Portfolio Replacement | S0016 | GMNA |
| 0500070 | Warranty Folder or Portfolio Replacement | A000000 | Holden Australia |
| 0500070 | Warranty Folder or Portfolio Replacement | C000406 | Holden Australia |
| 0500070 | Warranty Folder or Portfolio Replacement | A000000 | Holden New Zealand |
| 0500092 | Drivetrain and Front Suspension Frame Reinforcement Repair | S0017 | GMNA |
| 0500110 | Tire and Wheel Replacement | S0030 | Holden Australia |
| 0500130 | Radiator Upper Support Replacement | S0100 | GMNA |
| 0500170 | Hood Replacement | S0150 | GMNA |
| 0500170 | Hood Replacement | A500110 | Holden Australia |
| 0500170 | Hood Replacement | B149000 | Holden Australia |
| 0500170 | Hood Replacement | C896100 | Holden Australia |
| 0500170 | Hood Replacement | S0150 | Holden Australia |
| 0500170 | Hood Replacement | S015500 | Holden Australia |
| 0500170 | Hood Replacement | A500100 | Holden New Zealand |
| 0500170 | Hood Replacement | A500110 | Holden New Zealand |
| 0500170 | Hood Replacement | C896100 | Holden New Zealand |
| 0500170 | Hood Replacement | 956030B | GMK Overseas |
| 0500170 | Hood Replacement | 9730100 | GMK Overseas |
| 0500170 | Hood Replacement | 9730200 | GMK Overseas |
| 0500170 | Hood Replacement | 9730300 | GMK Overseas |
| 0500190 | Front Fender Replacement | A9119 | GMNA |
| 0500190 | Front Fender Replacement | A9120 | GMNA |
| 0500190 | Front Fender Replacement | A9121 | GMNA |
| 0500190 | Front Fender Replacement | A9480 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0500190 | Front Fender Replacement | A9481 | GMNA |
| 0500190 | Front Fender Replacement | B0625 | GMNA |
| 0500190 | Front Fender Replacement | B1820 | GMNA |
| 0500190 | Front Fender Replacement | B1821 | GMNA |
| 0500190 | Front Fender Replacement | B1870 | GMNA |
| 0500190 | Front Fender Replacement | B9824 | GMNA |
| 0500190 | Front Fender Replacement | B9944 | GMNA |
| 0500190 | Front Fender Replacement | S0280 | GMNA |
| 0500190 | Front Fender Replacement | S0281 | GMNA |
| 0500190 | Front Fender Replacement | S1280 | GMNA |
| 0500190 | Front Fender Replacement | S1281 | GMNA |
| 0500190 | Front Fender Replacement | S5090 | GMNA |
| 0500190 | Front Fender Replacement | S5091 | GMNA |
| 0500190 | Front Fender Replacement | A530100 | Holden Australia |
| 0500190 | Front Fender Replacement | A530200 | Holden Australia |
| 0500190 | Front Fender Replacement | B187000 | Holden Australia |
| 0500190 | Front Fender Replacement | B187100 | Holden Australia |
| 0500190 | Front Fender Replacement | S028000 | Holden Australia |
| 0500190 | Front Fender Replacement | S0281 | Holden Australia |
| 0500190 | Front Fender Replacement | S028100 | Holden Australia |
| 0500190 | Front Fender Replacement | S509000 | Holden Australia |
| 0500190 | Front Fender Replacement | A530100 | Holden New Zealand |
| 0500190 | Front Fender Replacement | A530200 | Holden New Zealand |
| 0500190 | Front Fender Replacement | A9121 | Holden New Zealand |
| 0500190 | Front Fender Replacement | S0280 | Holden New Zealand |
| 0500300 | Roof Outer Panel Replacement | S0550 | GMNA |
| 0500320 | Folding Top Replacement | S0570 | GMNA |
| 0500430 | Front Side Door Replacement | A9339 | GMNA |
| 0500430 | Front Side Door Replacement | A9340 | GMNA |
| 0500430 | Front Side Door Replacement | A9341 | GMNA |
| 0500430 | Front Side Door Replacement | A9344 | GMNA |
| 0500430 | Front Side Door Replacement | A9345 | GMNA |
| 0500430 | Front Side Door Replacement | A9780 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0500430 | Front Side Door Replacement | A9781 | GMNA |
| 0500430 | Front Side Door Replacement | B6400 | GMNA |
| 0500430 | Front Side Door Replacement | B6401 | GMNA |
| 0500430 | Front Side Door Replacement | B6402 | GMNA |
| 0500430 | Front Side Door Replacement | S0800 | GMNA |
| 0500430 | Front Side Door Replacement | S0801 | GMNA |
| 0500430 | Front Side Door Replacement | S0802 | GMNA |
| 0500430 | Front Side Door Replacement | S0803 | GMNA |
| 0500430 | Front Side Door Replacement | S0850 | GMNA |
| 0500430 | Front Side Door Replacement | S0851 | GMNA |
| 0500430 | Front Side Door Replacement | S5250 | GMNA |
| 0500430 | Front Side Door Replacement | S5251 | GMNA |
| 0500430 | Front Side Door Replacement | A313500 | Holden Australia |
| 0500430 | Front Side Door Replacement | A313600 | Holden Australia |
| 0500430 | Front Side Door Replacement | B001299 | Holden Australia |
| 0500430 | Front Side Door Replacement | B400500 | Holden Australia |
| 0500430 | Front Side Door Replacement | B400600 | Holden Australia |
| 0500430 | Front Side Door Replacement | S085000 | Holden Australia |
| 0500430 | Front Side Door Replacement | S085100 | Holden Australia |
| 0500430 | Front Side Door Replacement | S525000 | Holden Australia |
| 0500430 | Front Side Door Replacement | A313100 | Holden New Zealand |
| 0500430 | Front Side Door Replacement | A313500 | Holden New Zealand |
| 0500430 | Front Side Door Replacement | A313600 | Holden New Zealand |
| 0500430 | Front Side Door Replacement | B001199 | Holden New Zealand |
| 0500430 | Front Side Door Replacement | B001299 | Holden New Zealand |
| 0500430 | Front Side Door Replacement | B400500 | Holden New Zealand |
| 0500480 | Rear Side Door Replacement | B6403 | GMNA |
| 0500480 | Rear Side Door Replacement | S0900 | GMNA |
| 0500480 | Rear Side Door Replacement | S0901 | GMNA |
| 0500480 | Rear Side Door Replacement | S0930 | GMNA |
| 0500480 | Rear Side Door Replacement | S0950 | GMNA |
| 0500480 | Rear Side Door Replacement | S5252 | GMNA |
| 0500480 | Rear Side Door Replacement | S5253 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0500480 | Rear Side Door Replacement | A314500 | Holden Australia |
| 0500480 | Rear Side Door Replacement | A314600 | Holden Australia |
| 0500480 | Rear Side Door Replacement | B440500 | Holden Australia |
| 0500480 | Rear Side Door Replacement | S095000 | Holden Australia |
| 0500480 | Rear Side Door Replacement | A314500 | Holden New Zealand |
| 0500480 | Rear Side Door Replacement | A314600 | Holden New Zealand |
| 0500620 | Pickup Box Outer Side Panel Replacement | S1250 | GMNA |
| 0500670 | Pickup Box Replacement | S1260 | GMNA |
| 0500692 | Rear Compartment Panel Repair | A9180 | GMNA |
| 0500692 | Rear Compartment Panel Repair | A9181 | GMNA |
| 0500692 | Rear Compartment Panel Repair | A9560 | GMNA |
| 0500692 | Rear Compartment Panel Repair | A9600 | GMNA |
| 0500692 | Rear Compartment Panel Repair | B0779 | GMNA |
| 0500692 | Rear Compartment Panel Repair | B1890 | GMNA |
| 0500692 | Rear Compartment Panel Repair | B5281 | GMNA |
| 0500692 | Rear Compartment Panel Repair | S0690 | GMNA |
| 0500692 | Rear Compartment Panel Repair | S1170 | GMNA |
| 0500692 | Rear Compartment Panel Repair | S1171 | GMNA |
| 0500692 | Rear Compartment Panel Repair | S1300 | GMNA |
| 0500692 | Rear Compartment Panel Repair | S1301 | GMNA |
| 0500692 | Rear Compartment Panel Repair | S1322 | GMNA |
| 0500692 | Rear Compartment Panel Repair | S1323 | GMNA |
| 0500692 | Rear Compartment Panel Repair | S1390 | GMNA |
| 0500692 | Rear Compartment Panel Repair | S1460 | GMNA |
| 0500692 | Rear Compartment Panel Repair | S1650 | GMNA |
| 0500692 | Rear Compartment Panel Repair | S5430 | GMNA |
| 0500692 | Rear Compartment Panel Repair | 8532700 | GMK Domestic |
| 0500692 | Rear Compartment Panel Repair | 8648600 | GMK Domestic |
| 0500692 | Rear Compartment Panel Repair | A000333 | Holden Australia |
| 0500692 | Rear Compartment Panel Repair | B001500 | Holden Australia |
| 0500692 | Rear Compartment Panel Repair | S541000 | Holden Australia |
| 0500692 | Rear Compartment Panel Repair | S543000 | Holden Australia |
| 0500740 | Rear Compartment Lid Replacement | A9579 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0500740 | Rear Compartment Lid Replacement | S1700 | GMNA |
| 0500740 | Rear Compartment Lid Replacement | A319900 | Holden Australia |
| 0500740 | Rear Compartment Lid Replacement | A319910 | Holden Australia |
| 0500740 | Rear Compartment Lid Replacement | A319900 | Holden New Zealand |
| 0500740 | Rear Compartment Lid Replacement | A319910 | Holden New Zealand |
| 0500740 | Rear Compartment Lid Replacement | 984H3D0 | GMK Overseas |
| 0500740 | Rear Compartment Lid Replacement | 984M2D0 | GMK Overseas |
| 0500760 | Liftgate Replacement | A9650 | GMNA |
| 0500760 | Liftgate Replacement | A9906 | GMNA |
| 0500760 | Liftgate Replacement | B9913 | GMNA |
| 0500760 | Liftgate Replacement | S1750 | GMNA |
| 0500760 | Liftgate Replacement | 8341000 | GMK Domestic |
| 0500760 | Liftgate Replacement | A321400 | Holden Australia |
| 0500760 | Liftgate Replacement | A321410 | Holden Australia |
| 0500760 | Liftgate Replacement | B570500 | Holden Australia |
| 0500760 | Liftgate Replacement | A321400 | Holden New Zealand |
| 0500760 | Liftgate Replacement | B570500 | Holden New Zealand |
| 0500780 | Endgate Replacement | A9640 | GMNA |
| 0500780 | Endgate Replacement | A9900 | GMNA |
| 0500780 | Endgate Replacement | B5800 | GMNA |
| 0500780 | Endgate Replacement | S1800 | GMNA |
| 0500780 | Endgate Replacement | S1850 | GMNA |
| 0500780 | Endgate Replacement | C000622 | Holden Australia |
| 0500780 | Endgate Replacement | S1850 | Holden Australia |
| 0500780 | Endgate Replacement | A321410 | Holden New Zealand |
| 0500800 | Rear Door Replacement | A9680 | GMNA |
| 0500800 | Rear Door Replacement | A9681 | GMNA |
| 0500800 | Rear Door Replacement | S1880 | GMNA |
| 0500800 | Rear Door Replacement | A327000 | Holden Australia |
| 0500800 | Rear Door Replacement | A327100 | Holden Australia |
| 0500800 | Rear Door Replacement | A327200 | Holden Australia |
| 0500800 | Rear Door Replacement | B610500 | Holden Australia |
| 0500800 | Rear Door Replacement | B610600 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0500800 | Rear Door Replacement | B610700 | Holden Australia |
| 0500800 | Rear Door Replacement | S185500 | Holden Australia |
| 0500800 | Rear Door Replacement | S185600 | Holden Australia |
| 0500800 | Rear Door Replacement | S188000 | Holden Australia |
| 0500800 | Rear Door Replacement | A327000 | Holden New Zealand |
| 0510012 | Paint Sealant/Protection Installation | I9180 | GMNA |
| 0510042 | Seat/Fabric/Leather Protection Installation | I9181 | GMNA |
| 0510072 | Cruise Control Package Installation | I9182 | GMNA |
| 0510102 | Locking Gas Cap Package Installation | | |
| 0510132 | Spare Tire Kit Installation | 9510500 | GMK Overseas |
| 0510162 | Wheel Lock Package Installation | I9186 | GMNA |
| 0510192 | Vehicle Protective Cover/Lock/Stowage Bag Package Installation | I9187 | GMNA |
| 0510222 | Interior Storage Box Package Installation | I9188 | GMNA |
| 0510252 | Engine Performance Data Plate Package Installation | I9189 | GMNA |
| 0510282 | Personal Audio Link Module Package Installation | I9191 | GMNA |
| 0510312 | Rear Parking Assist Alarm Sensor Package Installation | I9192 | GMNA |
| 0510312 | Rear Parking Assist Alarm Sensor Package Installation | 5813200 | GMK Domestic |
| 0510312 | Rear Parking Assist Alarm Sensor Package Installation | 6425700 | GMK Domestic |
| 0510312 | Rear Parking Assist Alarm Sensor Package Installation | 9784300 | GMK Overseas |
| 0510342 | Toolbox Package Installation | I9193 | GMNA |
| 0510372 | Ambient Lighting Package Installation | I9194 | GMNA |
| 0510402 | Engine Oil Heater Package Installation | I9195 | GMNA |
| 0510432 | Liftgate Applique Package Installation | I9196 | GMNA |
| 0510462 | Battery/Charger/Heater Package Installation | | |
| 0510492 | License Plate Frame Package Installation | I9198 | GMNA |
| 0510522 | Exhaust Tail Pipe Extension Package Installation | I9199 | GMNA |
| 0510552 | Intake Manifold Package Installation | I9222 | GMNA |
| 0510582 | Turbocharger Kit Installation | I9224 | GMNA |
| 0510612 | Performance Muffler Exhaust Package Installation | I9227 | GMNA |
| 0510642 | Front Stabilizer Shaft Package Installation | I9228 | GMNA |
| 0510672 | Audio/XM Radio Package Installation | I9230 | GMNA |
| 0510702 | Engine Wiring Harness Package Installation | I9231 | GMNA |
| 0510732 | Engine Control Module Kit Installation | I9232 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0510742 | Transmission Fluid Auxiliary Cooler Kit Installation | | |
| 0510762 | Bumper/Bumper Protector Installation | I9235 | GMNA |
| 0510792 | Fascia Extension/Tow Hook Installation | I9236 | GMNA |
| 0510822 | Engine Coolant Heater Package Installation | I9240 | GMNA |
| 0510852 | Engine Cover Kit Installation | I9241 | GMNA |
| 0510852 | Engine Cover Kit Installation | J000848 | Holden New Zealand |
| 0510882 | Underhood Appearance Package Installation | I9242 | GMNA |
| 0510912 | Wheel Opening Flare/Liner Package Installation | I9245 | GMNA |
| 0510942 | Floor Mat Package Installation | I9250 | GMNA |
| 0510942 | Floor Mat Package Installation | 8523900 | GMK Domestic |
| 0510942 | Floor Mat Package Installation | 8642800 | GMK Domestic |
| 0510972 | Front Fog Lamp Package Installation | I9255 | GMNA |
| 0511002 | Headlamp Kit Installation | I9256 | GMNA |
| 0511032 | Front End Cover/Molded Hood Protector Installation | I9260 | GMNA |
| 0511062 | Hood, Hood Insert, or Hood Louver Installation | I9261 | GMNA |
| 0511092 | Garage Door Opener Transmitter Package Installation | I9265 | GMNA |
| 0511102 | Instrument Panel Ashtray Package Installation | | |
| 0511122 | Body Decal Kit Installation | I9270 | GMNA |
| 0511132 | Body Side Decal Package Installation | | |
| 0511152 | Passenger Compartment Screen Air Deflector Package Installation | I9273 | GMNA |
| 0511152 | Passenger Compartment Screen Air Deflector Package Installation | 8671300 | GMK Domestic |
| 0511182 | Cigarette Lighter Package Installation | I9274 | GMNA |
| 0511182 | Cigarette Lighter Package Installation | 5810400 | GMK Domestic |
| 0511212 | Rear Compartment Floor Stowage Compartment Tray Package Installation | I9275 | GMNA |
| 0511242 | Multifunction Auxiliary Gauge Package Installation | I9276 | GMNA |
| 0511272 | Shifter/Parking Brake Handle Installation | I9277 | GMNA |
| 0511302 | Accelerator Pedal Cover Package Installation | I9278 | GMNA |
| 0511332 | Cargo Organizer Package Installation | I9279 | GMNA |
| 0511332 | Cargo Organizer Package Installation | 8521600 | GMK Domestic |
| 0511332 | Cargo Organizer Package Installation | 8641700 | GMK Domestic |
| 0511332 | Cargo Organizer Package Installation | 9383300 | GMK Overseas |
| 0511332 | Cargo Organizer Package Installation | 9392950 | GMK Overseas |
| 0511362 | Outside Rearview Mirror/Cover Installation | I9280 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0511362 | Outside Rearview Mirror/Cover Installation | 9466100 | GMK Overseas |
| 0511392 | Body Side Molding Insert Package Installation | I9281 | GMNA |
| 0511422 | Body Exterior Molding Package Installation | I9285 | GMNA |
| 0511452 | Exterior Latch, Handle, or Fuel Door Installation | I9286 | GMNA |
| 0511482 | Front Grill/Guard Installation | I9287 | GMNA |
| 0511512 | Tail Lamp Guard Package Installation | I9288 | GMNA |
| 0511542 | Oil Pan Skid Plate Package Installation | I9289 | GMNA |
| 0511542 | Oil Pan Skid Plate Package Installation | 9561900 | GMK Overseas |
| 0511572 | Navigation/Information Package Installation | I9290 | GMNA |
| 0511572 | Navigation/Information Package Installation | 5524100 | GMK Domestic |
| 0511572 | Navigation/Information Package Installation | 6111400 | GMK Domestic |
| 0511602 | Remote Start/Keyless Entry Transmitter Installation | I9291 | GMNA |
| 0511602 | Remote Start/Keyless Entry Transmitter Installation | R9005 | GMNA |
| 0511602 | Remote Start/Keyless Entry Transmitter Installation | R9010 | GMNA |
| 0511602 | Remote Start/Keyless Entry Transmitter Installation | R9015 | GMNA |
| 0511602 | Remote Start/Keyless Entry Transmitter Installation | R9020 | GMNA |
| 0511602 | Remote Start/Keyless Entry Transmitter Installation | R9030 | GMNA |
| 0511602 | Remote Start/Keyless Entry Transmitter Installation | R9040 | GMNA |
| 0511602 | Remote Start/Keyless Entry Transmitter Installation | R9041 | GMNA |
| 0511602 | Remote Start/Keyless Entry Transmitter Installation | R9042 | GMNA |
| 0511602 | Remote Start/Keyless Entry Transmitter Installation | R9060 | GMNA |
| 0511602 | Remote Start/Keyless Entry Transmitter Installation | R9778 | GMNA |
| 0511632 | Windshield Washer Solvent Heater Package Installation | I9292 | GMNA |
| 0511662 | Multimedia Player Interface Module Package Installation | I9293 | GMNA |
| 0511692 | Rearview Driver Information Camera Package Installation | I9294 | GMNA |
| 0511722 | Cellular Telephone Package Installation | I9295 | GMNA |
| 0511722 | Cellular Telephone Package Installation | R300400 | Holden Australia |
| 0511722 | Cellular Telephone Package Installation | R300400 | Holden New Zealand |
| 0511752 | Roof Rack/Rail/Panel Installation | I9300 | GMNA |
| 0511782 | Air Deflector Installation | I9301 | GMNA |
| 0511782 | Air Deflector Installation | I9302 | GMNA |
| 0511812 | Rear Sliding Window Package Installation | I9305 | GMNA |
| 0511842 | Ski Carrier Recreation Package Installation | I9307 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0511872 | Running Board Step Package Installation | I9310 | GMNA |
| 0511902 | Tubular Assist Step Package Installation | I9311 | GMNA |
| 0511932 | Highway Emergency Package Installation | I9315 | GMNA |
| 0511962 | Front and Rear Seat Cover Package Installation | I9320 | GMNA |
| 0511992 | Driver or Passenger Seat Cushion Heater Kit Installation | I9321 | GMNA |
| 0511992 | Driver or Passenger Seat Cushion Heater Kit Installation | D130400 | Holden Australia |
| 0511992 | Driver or Passenger Seat Cushion Heater Kit Installation | D130410 | Holden Australia |
| 0512022 | Steering Wheel Package Installation | I9322 | GMNA |
| 0512052 | Rear Window Inside Sunshade Kit Installation | I9323 | GMNA |
| 0512082 | Vehicle Remote Security Package Installation | I9325 | GMNA |
| 0512092 | Front Floor Illumination Lamp Package Installation | | |
| 0512112 | Front and Rear Side Door Sill Trim Plate Kit Installation | I9331 | GMNA |
| 0512112 | Front and Rear Side Door Sill Trim Plate Kit Installation | S0691 | GMNA |
| 0512112 | Front and Rear Side Door Sill Trim Plate Kit Installation | 9382800 | GMK Overseas |
| 0512122 | Instrument Panel and Steering Wheel Accessory Trim Package Installation | | |
| 0512142 | Spare Wheel Cover Package Installation | I9335 | GMNA |
| 0512172 | Mud Flap Guard Installation | I9340 | GMNA |
| 0512172 | Mud Flap Guard Installation | 9520500 | GMK Overseas |
| 0512202 | Vehicle Appearance Ground Effects Installation | I9345 | GMNA |
| 0512212 | Rear End Spoiler Package Installation | 8523200 | GMK Domestic |
| 0512212 | Rear End Spoiler Package Installation | 8523700 | GMK Domestic |
| 0512212 | Rear End Spoiler Package Installation | 8642600 | GMK Domestic |
| 0512232 | Pickup Box Tonneau Cover Package Installation | I9350 | GMNA |
| 0512232 | Pickup Box Tonneau Cover Package Installation | 8534800 | GMK Domestic |
| 0512232 | Pickup Box Tonneau Cover Package Installation | 8660300 | GMK Domestic |
| 0512262 | Pickup Box Cover Package Installation | I9351 | GMNA |
| 0512292 | Roof Panel Storage Bag Package Installation | I9355 | GMNA |
| 0512322 | Trailer Hitch/Wiring Harness Installation | I9360 | GMNA |
| 0512322 | Trailer Hitch/Wiring Harness Installation | 9784100 | GMK Overseas |
| 0512322 | Trailer Hitch/Wiring Harness Installation | 9784200 | GMK Overseas |
| 0512352 | Pickup Box Liner Package Installation | I9365 | GMNA |
| 0512382 | Pickup Box Platform Extension Package Installation | I9370 | GMNA |
| 0512412 | Endgate Spoiler Package Installation | I9371 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0512442 | Truck Bed - Bike Chock/Stake Hook/Tie Down Installation | I9372 | GMNA |
| 0512472 | Rear Cargo Organizer/Cargo Net Installation | I9374 | GMNA |
| 0512502 | Cargo Box Side Rail Package Installation | I9375 | GMNA |
| 0512532 | Daytime Running Lamp Kit Installation | I9380 | GMNA |
| 0512562 | Folding Top Cover Package Installation | I9385 | GMNA |
| 0512592 | Body Side Window Package Installation | I9390 | GMNA |
| 0512622 | Video Disc Player Package Installation | I9392 | GMNA |
| 0512652 | Wheel/Wheel Cover Installation | I9395 | GMNA |
| 0520010 | Paint Sealant/Protection | R0010 | GMNA |
| 0520010 | Paint Sealant/Protection | R9180 | GMNA |
| 0520010 | Paint Sealant/Protection | R700300 | Holden Australia |
| 0520040 | Seat/Fabric/Leather Protection | R9181 | GMNA |
| 0520070 | Cruise Control Package Replacement | R0020 | GMNA |
| 0520070 | Cruise Control Package Replacement | R9182 | GMNA |
| 0520100 | Locking Gas Cap Package Replacement | R700200 | Holden New Zealand |
| 0520130 | Spare Tire Replacement | R9185 | GMNA |
| 0520130 | Spare Tire Replacement | 3021620 | GMK Domestic |
| 0520160 | Wheel Lock Package Replacement | R9186 | GMNA |
| 0520190 | Vehicle Protective Cover/Lock/Stowage Bag Package Replacement | R9187 | GMNA |
| 0520220 | Interior Storage Box Package Replacement | R9188 | GMNA |
| 0520250 | Engine Performance Data Plate Package Replacement | | |
| 0520270 | Engine Replacement | | |
| 0520280 | Personal Audio Link Module Package Replacement | R9191 | GMNA |
| 0520290 | Engine Wiring Harness Assembly Replacement | | |
| 0520310 | Rear Parking Assist Alarm Sensor Package Replacement | R9192 | GMNA |
| 0520340 | Toolbox Package Replacement | R9193 | GMNA |
| 0520370 | Ambient Lighting Package Replacement | R9194 | GMNA |
| 0520400 | Engine Oil Heater Package Replacement | R9195 | GMNA |
| 0520430 | Liftgate Applique Package Replacement | R9196 | GMNA |
| 0520460 | Battery/Charger/Heater Package Replacement | R9197 | GMNA |
| 0520490 | License Plate Frame Package Replacement | R9198 | GMNA |
| 0520520 | Exhaust Tail Pipe Extension Package Replacement | R9199 | GMNA |
| 0520550 | Intake Manifold Replacement | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0520580 | Turbocharger Replacement | | |
| 0520610 | Performance Muffler Exhaust Package Replacement | R9227 | GMNA |
| 0520640 | Front Stabilizer Shaft Package Replacement | R9228 | GMNA |
| 0520640 | Front Stabilizer Shaft Package Replacement | 8511200 | GMK Domestic |
| 0520640 | Front Stabilizer Shaft Package Replacement | N1567 | Holden New Zealand |
| 0520670 | Audio/XM Radio Package Replacement | R0125 | GMNA |
| 0520670 | Audio/XM Radio Package Replacement | R0130 | GMNA |
| 0520670 | Audio/XM Radio Package Replacement | R0710 | GMNA |
| 0520670 | Audio/XM Radio Package Replacement | R0747 | GMNA |
| 0520670 | Audio/XM Radio Package Replacement | R0748 | GMNA |
| 0520670 | Audio/XM Radio Package Replacement | R0790 | GMNA |
| 0520670 | Audio/XM Radio Package Replacement | R0795 | GMNA |
| 0520670 | Audio/XM Radio Package Replacement | R9230 | GMNA |
| 0520670 | Audio/XM Radio Package Replacement | R9703 | GMNA |
| 0520670 | Audio/XM Radio Package Replacement | R9737 | GMNA |
| 0520670 | Audio/XM Radio Package Replacement | R9740 | GMNA |
| 0520670 | Audio/XM Radio Package Replacement | R9776 | GMNA |
| 0520670 | Audio/XM Radio Package Replacement | R9799 | GMNA |
| 0520670 | Audio/XM Radio Package Replacement | N999019 | Holden Australia |
| 0520670 | Audio/XM Radio Package Replacement | N999020 | Holden Australia |
| 0520670 | Audio/XM Radio Package Replacement | N999023 | Holden Australia |
| 0520670 | Audio/XM Radio Package Replacement | N999028 | Holden Australia |
| 0520670 | Audio/XM Radio Package Replacement | N999029 | Holden Australia |
| 0520670 | Audio/XM Radio Package Replacement | N999037 | Holden Australia |
| 0520670 | Audio/XM Radio Package Replacement | N999038 | Holden Australia |
| 0520670 | Audio/XM Radio Package Replacement | N999039 | Holden Australia |
| 0520670 | Audio/XM Radio Package Replacement | N999045 | Holden Australia |
| 0520670 | Audio/XM Radio Package Replacement | N999047 | Holden Australia |
| 0520670 | Audio/XM Radio Package Replacement | N999048 | Holden Australia |
| 0520670 | Audio/XM Radio Package Replacement | N999049 | Holden Australia |
| 0520670 | Audio/XM Radio Package Replacement | N999057 | Holden Australia |
| 0520670 | Audio/XM Radio Package Replacement | N999058 | Holden Australia |
| 0520670 | Audio/XM Radio Package Replacement | N999059 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0520670 | Audio/XM Radio Package Replacement | N999121 | Holden Australia |
| 0520670 | Audio/XM Radio Package Replacement | R205520 | Holden Australia |
| 0520670 | Audio/XM Radio Package Replacement | R205700 | Holden Australia |
| 0520670 | Audio/XM Radio Package Replacement | N999010 | Holden New Zealand |
| 0520670 | Audio/XM Radio Package Replacement | N999019 | Holden New Zealand |
| 0520670 | Audio/XM Radio Package Replacement | N999020 | Holden New Zealand |
| 0520670 | Audio/XM Radio Package Replacement | N999023 | Holden New Zealand |
| 0520670 | Audio/XM Radio Package Replacement | N999027 | Holden New Zealand |
| 0520670 | Audio/XM Radio Package Replacement | N999035 | Holden New Zealand |
| 0520670 | Audio/XM Radio Package Replacement | N999039 | Holden New Zealand |
| 0520670 | Audio/XM Radio Package Replacement | N999049 | Holden New Zealand |
| 0520670 | Audio/XM Radio Package Replacement | R000281 | Holden New Zealand |
| 0520670 | Audio/XM Radio Package Replacement | R200100 | Holden New Zealand |
| 0520670 | Audio/XM Radio Package Replacement | R205510 | Holden New Zealand |
| 0520670 | Audio/XM Radio Package Replacement | R205520 | Holden New Zealand |
| 0520730 | Engine Control Module Replacement | R9220 | GMNA |
| 0520740 | Transmission Fluid Auxiliary Cooler Kit Replacement | 2422500 | GMK Domestic |
| 0520760 | Bumper/Bumper Protector Replacement | R9235 | GMNA |
| 0520820 | Engine Coolant Heater Replacement | | |
| 0520850 | Engine Cover Replacement | | |
| 0520880 | Underhood Appearance Package Replacement | I9225 | GMNA |
| 0520910 | Wheel Opening Flare/Liner Package Replacement | R9245 | GMNA |
| 0520940 | Floor Mat Package Replacement | R9250 | GMNA |
| 0520940 | Floor Mat Package Replacement | 8523800 | GMK Domestic |
| 0520970 | Front Fog Lamp Replacement | | |
| 0521000 | Headlamp Replacement | W200800 | Holden Australia |
| 0521000 | Headlamp Replacement | W200850 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N8519 | GMNA |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | R9260 | GMNA |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | R9701 | GMNA |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | T2720 | GMNA |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999012 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999018 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999021 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999022 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999024 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999026 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999030 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999031 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999032 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999033 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999034 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999036 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999040 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999041 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999042 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999043 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999044 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999046 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999051 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999052 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999053 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999054 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999056 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999061 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999063 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999064 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999065 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999066 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999067 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999068 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999069 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999072 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999075 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999076 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999077 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999078 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999081 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999083 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999084 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999085 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999087 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999088 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999089 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999091 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999092 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999093 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999094 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999095 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999099 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999110 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999167 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999168 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | R000061 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | R000064 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | R000085 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | R076000 | Holden Australia |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999022 | Holden New Zealand |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999024 | Holden New Zealand |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999037 | Holden New Zealand |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999038 | Holden New Zealand |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999044 | Holden New Zealand |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999046 | Holden New Zealand |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999048 | Holden New Zealand |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999063 | Holden New Zealand |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999069 | Holden New Zealand |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999073 | Holden New Zealand |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999092 | Holden New Zealand |
| 0521030 | Front End Cover/Molded Hood Protector Replacement | N999093 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0521030 | Front End Cover/Molded Hood Protector Replacement | R202100 | Holden New Zealand |
| 0521060 | Hood, Hood Insert, or Hood Louver Replacement | R9231 | GMNA |
| 0521060 | Hood, Hood Insert, or Hood Louver Replacement | R9261 | GMNA |
| 0521090 | Garage Door Opener Transmitter Replacement | | |
| 0521100 | Instrument Panel Ashtray Replacement | | |
| 0521120 | Body Decal Kit Replacement | R9270 | GMNA |
| 0521130 | Body Side Decal Package Replacement | R9271 | GMNA |
| 0521150 | Passenger Compartment Screen Air Deflector Package Replacement | R9273 | GMNA |
| 0521180 | Cigarette Lighter Replacement | R9240 | GMNA |
| 0521210 | Rear Compartment Floor Stowage Compartment Tray Replacement | R9241 | GMNA |
| 0521240 | Multifunction Auxiliary Gauge Replacement | | |
| 0521270 | Shifter/Parking Brake Handle Replacement | R9277 | GMNA |
| 0521300 | Accelerator Pedal Cover Package Replacement | R9278 | GMNA |
| 0521300 | Accelerator Pedal Cover Package Replacement | J815600 | Holden Australia |
| 0521330 | Cargo Organizer Package Replacement | R9255 | GMNA |
| 0521330 | Cargo Organizer Package Replacement | R9279 | GMNA |
| 0521360 | Outside Rearview Mirror/Cover Replacement | R9256 | GMNA |
| 0521360 | Outside Rearview Mirror/Cover Replacement | R9280 | GMNA |
| 0521390 | Body Side Molding Insert Package Replacement | R9281 | GMNA |
| 0521420 | Body Exterior Molding Package Replacement | A0413 | GMNA |
| 0521420 | Body Exterior Molding Package Replacement | A0416 | GMNA |
| 0521420 | Body Exterior Molding Package Replacement | R9285 | GMNA |
| 0521450 | Exterior Latch, Handle, or Fuel Door Replacement | R9265 | GMNA |
| 0521450 | Exterior Latch, Handle, or Fuel Door Replacement | R9286 | GMNA |
| 0521480 | Front Grill/Guard Replacement | R9287 | GMNA |
| 0521510 | Tail Lamp Guard Replacement | | |
| 0521540 | Oil Pan Skid Plate Replacement | | |
| 0521570 | Navigation/Information Package Replacement | R9274 | GMNA |
| 0521570 | Navigation/Information Package Replacement | R9290 | GMNA |
| 0521570 | Navigation/Information Package Replacement | N712326 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N712529 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N732131 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999009 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0521570 | Navigation/Information Package Replacement | N999010 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999011 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999016 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999025 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999035 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999055 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999101 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999140 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999147 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999155 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999164 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999184 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999201 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999202 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999203 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999204 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999240 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999243 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999244 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999245 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999248 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999249 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999271 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999325 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999330 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999335 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999340 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999401 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999423 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999462 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999464 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999484 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999924 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0521570 | Navigation/Information Package Replacement | N999926 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999927 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999996 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999997 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999998 | Holden Australia |
| 0521570 | Navigation/Information Package Replacement | N999011 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999055 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999101 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999121 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999140 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999155 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999164 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999184 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999201 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999203 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999243 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999244 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999248 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999249 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999271 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999325 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999330 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999423 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999462 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999924 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | N999997 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | R000251 | Holden New Zealand |
| 0521570 | Navigation/Information Package Replacement | R000257 | Holden New Zealand |
| 0521600 | Remote Start/Keyless Entry Transmitter Replacement | R3010 | GMNA |
| 0521600 | Remote Start/Keyless Entry Transmitter Replacement | R3011 | GMNA |
| 0521600 | Remote Start/Keyless Entry Transmitter Replacement | R9275 | GMNA |
| 0521600 | Remote Start/Keyless Entry Transmitter Replacement | R9291 | GMNA |
| 0521600 | Remote Start/Keyless Entry Transmitter Replacement | N313600 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0521600 | Remote Start/Keyless Entry Transmitter Replacement | N501600 | Holden Australia |
| 0521600 | Remote Start/Keyless Entry Transmitter Replacement | N501610 | Holden Australia |
| 0521600 | Remote Start/Keyless Entry Transmitter Replacement | N313600 | Holden New Zealand |
| 0521600 | Remote Start/Keyless Entry Transmitter Replacement | N501600 | Holden New Zealand |
| 0521600 | Remote Start/Keyless Entry Transmitter Replacement | N501610 | Holden New Zealand |
| 0521630 | Windshield Washer Solvent Heater Replacement | R9276 | GMNA |
| 0521660 | Multimedia Player Interface Module Replacement | | |
| 0521720 | Cellular Telephone Replacement | R9295 | GMNA |
| 0521750 | Roof Rack/Rail/Panel Replacement | R9300 | GMNA |
| 0521780 | Air Deflector Replacement | J7920 | GMNA |
| 0521810 | Rear Sliding Window Replacement | | |
| 0521840 | Ski Carrier Recreation Package Replacement | R9307 | GMNA |
| 0521870 | Running Board Step Replacement | R9310 | GMNA |
| 0521900 | Tubular Assist Step Replacement | R9288 | GMNA |
| 0521900 | Tubular Assist Step Replacement | R9311 | GMNA |
| 0521930 | Highway Emergency Package Replacement | R9289 | GMNA |
| 0521930 | Highway Emergency Package Replacement | R9315 | GMNA |
| 0521960 | Front and Rear Seat Cover Package Replacement | C6865 | GMNA |
| 0521960 | Front and Rear Seat Cover Package Replacement | C6869 | GMNA |
| 0521960 | Front and Rear Seat Cover Package Replacement | C7141 | GMNA |
| 0521960 | Front and Rear Seat Cover Package Replacement | C9864 | GMNA |
| 0521960 | Front and Rear Seat Cover Package Replacement | R9320 | GMNA |
| 0521960 | Front and Rear Seat Cover Package Replacement | C552100 | Holden Australia |
| 0521960 | Front and Rear Seat Cover Package Replacement | N999013 | Holden Australia |
| 0521960 | Front and Rear Seat Cover Package Replacement | N999014 | Holden Australia |
| 0521960 | Front and Rear Seat Cover Package Replacement | N999015 | Holden Australia |
| 0521960 | Front and Rear Seat Cover Package Replacement | N999017 | Holden Australia |
| 0521960 | Front and Rear Seat Cover Package Replacement | N999171 | Holden Australia |
| 0521960 | Front and Rear Seat Cover Package Replacement | N999173 | Holden Australia |
| 0521960 | Front and Rear Seat Cover Package Replacement | R000251 | Holden Australia |
| 0521960 | Front and Rear Seat Cover Package Replacement | R000254 | Holden Australia |
| 0521960 | Front and Rear Seat Cover Package Replacement | R000257 | Holden Australia |
| 0521960 | Front and Rear Seat Cover Package Replacement | R000260 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0521960 | Front and Rear Seat Cover Package Replacement | R000263 | Holden Australia |
| 0521960 | Front and Rear Seat Cover Package Replacement | R000266 | Holden Australia |
| 0521960 | Front and Rear Seat Cover Package Replacement | C552100 | Holden New Zealand |
| 0521960 | Front and Rear Seat Cover Package Replacement | N999017 | Holden New Zealand |
| 0521960 | Front and Rear Seat Cover Package Replacement | N999021 | Holden New Zealand |
| 0521960 | Front and Rear Seat Cover Package Replacement | N999031 | Holden New Zealand |
| 0521960 | Front and Rear Seat Cover Package Replacement | N999033 | Holden New Zealand |
| 0521960 | Front and Rear Seat Cover Package Replacement | N999052 | Holden New Zealand |
| 0521960 | Front and Rear Seat Cover Package Replacement | N999087 | Holden New Zealand |
| 0521990 | Driver or Passenger Seat Cushion Heater Replacement | N000291 | Holden Australia |
| 0521990 | Driver or Passenger Seat Cushion Heater Replacement | N000312 | Holden Australia |
| 0521990 | Driver or Passenger Seat Cushion Heater Replacement | N501675 | Holden Australia |
| 0521990 | Driver or Passenger Seat Cushion Heater Replacement | R905500 | Holden Australia |
| 0521990 | Driver or Passenger Seat Cushion Heater Replacement | N000291 | Holden New Zealand |
| 0521990 | Driver or Passenger Seat Cushion Heater Replacement | N501675 | Holden New Zealand |
| 0521990 | Driver or Passenger Seat Cushion Heater Replacement | N501900 | Holden New Zealand |
| 0521990 | Driver or Passenger Seat Cushion Heater Replacement | R905500 | Holden New Zealand |
| 0522020 | Steering Wheel Replacement | A7318 | GMNA |
| 0522020 | Steering Wheel Replacement | R9292 | GMNA |
| 0522050 | Rear Window Inside Sunshade Replacement | R9293 | GMNA |
| 0522080 | Vehicle Remote Security Package Replacement | R9294 | GMNA |
| 0522080 | Vehicle Remote Security Package Replacement | R9325 | GMNA |
| 0522080 | Vehicle Remote Security Package Replacement | N311500 | Holden Australia |
| 0522090 | Front Floor Illumination Lamp Package Replacement | | |
| 0522110 | Front and Rear Side Door Sill Trim Plate Replacement | | |
| 0522120 | Instrument Panel and Steering Wheel Accessory Trim Package Replacement | R9332 | GMNA |
| 0522140 | Spare Wheel Cover Package Replacement | | |
| 0522170 | Mud Flap Guard Replacement | R9340 | GMNA |
| 0522200 | Vehicle Appearance Ground Effects Replacement | R9305 | GMNA |
| 0522200 | Vehicle Appearance Ground Effects Replacement | R9345 | GMNA |
| 0522210 | Rear End Spoiler Replacement | | |
| 0522230 | Pickup Box Tonneau Cover Replacement | B9711 | GMNA |
| 0522230 | Pickup Box Tonneau Cover Replacement | B9713 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0522230 | Pickup Box Tonneau Cover Replacement | B9726 | GMNA |
| 0522230 | Pickup Box Tonneau Cover Replacement | B9968 | GMNA |
| 0522230 | Pickup Box Tonneau Cover Replacement | C9943 | GMNA |
| 0522230 | Pickup Box Tonneau Cover Replacement | R2470 | GMNA |
| 0522230 | Pickup Box Tonneau Cover Replacement | R9350 | GMNA |
| 0522230 | Pickup Box Tonneau Cover Replacement | R9352 | GMNA |
| 0522230 | Pickup Box Tonneau Cover Replacement | R9741 | GMNA |
| 0522230 | Pickup Box Tonneau Cover Replacement | B077770 | Holden Australia |
| 0522230 | Pickup Box Tonneau Cover Replacement | R000227 | Holden Australia |
| 0522230 | Pickup Box Tonneau Cover Replacement | R000284 | Holden Australia |
| 0522230 | Pickup Box Tonneau Cover Replacement | R000287 | Holden Australia |
| 0522230 | Pickup Box Tonneau Cover Replacement | R407200 | Holden Australia |
| 0522230 | Pickup Box Tonneau Cover Replacement | R407250 | Holden Australia |
| 0522230 | Pickup Box Tonneau Cover Replacement | B077770 | Holden New Zealand |
| 0522230 | Pickup Box Tonneau Cover Replacement | R000284 | Holden New Zealand |
| 0522230 | Pickup Box Tonneau Cover Replacement | R407200 | Holden New Zealand |
| 0522230 | Pickup Box Tonneau Cover Replacement | R407250 | Holden New Zealand |
| 0522260 | Pickup Box Cover Replacement | | |
| 0522290 | Roof Panel Storage Bag Package Replacement | R9355 | GMNA |
| 0522350 | Pickup Box Liner Replacement | C000352 | Holden Australia |
| 0522380 | Pickup Box Platform Extension Package Replacement | C7339 | GMNA |
| 0522380 | Pickup Box Platform Extension Package Replacement | R9321 | GMNA |
| 0522380 | Pickup Box Platform Extension Package Replacement | R9370 | GMNA |
| 0522410 | Endgate Spoiler Package Replacement | E7015 | GMNA |
| 0522410 | Endgate Spoiler Package Replacement | E7101 | GMNA |
| 0522410 | Endgate Spoiler Package Replacement | R9322 | GMNA |
| 0522410 | Endgate Spoiler Package Replacement | R9371 | GMNA |
| 0522410 | Endgate Spoiler Package Replacement | E7020 | Holden Australia |
| 0522410 | Endgate Spoiler Package Replacement | E702000 | Holden Australia |
| 0522410 | Endgate Spoiler Package Replacement | E7237 | Holden Australia |
| 0522410 | Endgate Spoiler Package Replacement | M001500 | Holden Australia |
| 0522410 | Endgate Spoiler Package Replacement | E7020 | Holden New Zealand |
| 0522410 | Endgate Spoiler Package Replacement | E702000 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0522410 | Endgate Spoiler Package Replacement | M001500 | Holden New Zealand |
| 0522440 | Truck Bed - Bike Chock/Stake Hook/Tie Down Replacement | R9323 | GMNA |
| 0522440 | Truck Bed - Bike Chock/Stake Hook/Tie Down Replacement | R9372 | GMNA |
| 0522470 | Rear Cargo Organizer/Cargo Net Replacement | R9374 | GMNA |
| 0522500 | Cargo Box Side Rail Replacement | R9331 | GMNA |
| 0522500 | Cargo Box Side Rail Replacement | R9375 | GMNA |
| 0522530 | Daytime Running Lamp Replacement | | |
| 0522560 | Folding Top Cover Replacement | | |
| 0522590 | Body Side Window Replacement | | |
| 0522620 | Video Disc Player Replacement | B5352 | GMNA |
| 0522620 | Video Disc Player Replacement | B9712 | GMNA |
| 0522620 | Video Disc Player Replacement | C000502 | Holden Australia |
| 0522620 | Video Disc Player Replacement | F000206 | Holden Australia |
| 0522620 | Video Disc Player Replacement | R000290 | Holden Australia |
| 0522620 | Video Disc Player Replacement | R9350 | Holden Australia |
| 0522620 | Video Disc Player Replacement | R9351 | Holden Australia |
| 0522620 | Video Disc Player Replacement | R000227 | Holden New Zealand |
| 0522620 | Video Disc Player Replacement | R000290 | Holden New Zealand |
| 0522620 | Video Disc Player Replacement | R9350 | Holden New Zealand |
| 0522650 | Wheel/Wheel Cover Replacement | R9351 | GMNA |
| 0523000 | Wheel Wrench Replacement | R0100 | GMNA |
| 0523000 | Wheel Wrench Replacement | E001600 | Holden Australia |
| 0523000 | Wheel Wrench Replacement | E001600 | Holden New Zealand |
| 0523010 | Automatic Transmission Replacement | R5153 | GMNA |
| 0523010 | Automatic Transmission Replacement | R5525 | GMNA |
| 0523010 | Automatic Transmission Replacement | R5541 | GMNA |
| 0523010 | Automatic Transmission Replacement | R5542 | GMNA |
| 0523010 | Automatic Transmission Replacement | R5543 | GMNA |
| 0523010 | Automatic Transmission Replacement | R5551 | GMNA |
| 0523010 | Automatic Transmission Replacement | R5552 | GMNA |
| 0523010 | Automatic Transmission Replacement | R5553 | GMNA |
| 0523010 | Automatic Transmission Replacement | R5555 | GMNA |
| 0523010 | Automatic Transmission Replacement | R5556 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0523010 | Automatic Transmission Replacement | R5564 | GMNA |
| 0523010 | Automatic Transmission Replacement | R5566 | GMNA |
| 0523010 | Automatic Transmission Replacement | R9392 | GMNA |
| 0523010 | Automatic Transmission Replacement | R9739 | GMNA |
| 0523300 | Fire Extinguisher Bracket Replacement | | |
| 0523320 | Fire Extinguisher Replacement | R700300 | Holden New Zealand |
| 0523350 | Disabled Vehicle Warning Triangle Reflector Replacement | R700200 | Holden Australia |
| 0530010 | Door Lock and Ignition Lock Key Replacement | B6814 | GMNA |
| 0530010 | Door Lock and Ignition Lock Key Replacement | E7005 | GMNA |
| 0530010 | Door Lock and Ignition Lock Key Replacement | N501650 | Holden Australia |
| 0530010 | Door Lock and Ignition Lock Key Replacement | S0011 | Holden Australia |
| 0530010 | Door Lock and Ignition Lock Key Replacement | N501650 | Holden New Zealand |
| 0560012 | Roof Stationary Window Resealing | B2179 | GMNA |
| 560012 | Roof Stationary Window Resealing | | |
| 0560032 | Body Joint Resealing | B4805 | GMNA |
| 0560032 | Body Joint Resealing | B5295 | GMNA |
| 0560032 | Body Joint Resealing | B5410 | GMNA |
| 0560032 | Body Joint Resealing | B9809 | GMNA |
| 0560032 | Body Joint Resealing | B9811 | GMNA |
| 0560032 | Body Joint Resealing | B9878 | GMNA |
| 0560032 | Body Joint Resealing | B9937 | GMNA |
| 0560032 | Body Joint Resealing | B9986 | GMNA |
| 0560032 | Body Joint Resealing | C0010 | GMNA |
| 0560032 | Body Joint Resealing | C0990 | GMNA |
| 0560032 | Body Joint Resealing | C9809 | GMNA |
| 0560032 | Body Joint Resealing | C9810 | GMNA |
| 0560032 | Body Joint Resealing | C9812 | GMNA |
| 0560032 | Body Joint Resealing | J7527 | GMNA |
| 0560032 | Body Joint Resealing | T6644 | GMNA |
| 0560032 | Body Joint Resealing | T6740 | GMNA |
| 0560032 | Body Joint Resealing | T6741 | GMNA |
| 0560032 | Body Joint Resealing | T6742 | GMNA |
| 0560032 | Body Joint Resealing | T6743 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0560032 | Body Joint Resealing | T6744 | GMNA |
| 0560032 | Body Joint Resealing | T6745 | GMNA |
| 0560032 | Body Joint Resealing | A000318 | Holden Australia |
| 0560032 | Body Joint Resealing | A000336 | Holden Australia |
| 0560032 | Body Joint Resealing | A000342 | Holden Australia |
| 0560032 | Body Joint Resealing | A201598 | Holden Australia |
| 0560032 | Body Joint Resealing | A202100 | Holden Australia |
| 0560032 | Body Joint Resealing | A202200 | Holden Australia |
| 0560032 | Body Joint Resealing | A202300 | Holden Australia |
| 0560032 | Body Joint Resealing | A202400 | Holden Australia |
| 0560032 | Body Joint Resealing | A202500 | Holden Australia |
| 0560032 | Body Joint Resealing | A202600 | Holden Australia |
| 0560032 | Body Joint Resealing | A202700 | Holden Australia |
| 0560032 | Body Joint Resealing | A202800 | Holden Australia |
| 0560032 | Body Joint Resealing | A202900 | Holden Australia |
| 0560032 | Body Joint Resealing | A203098 | Holden Australia |
| 0560032 | Body Joint Resealing | A205199 | Holden Australia |
| 0560032 | Body Joint Resealing | A206098 | Holden Australia |
| 0560032 | Body Joint Resealing | A210198 | Holden Australia |
| 0560032 | Body Joint Resealing | A210298 | Holden Australia |
| 0560032 | Body Joint Resealing | B5410 | Holden Australia |
| 0560032 | Body Joint Resealing | C0010 | Holden Australia |
| 0560032 | Body Joint Resealing | C061000 | Holden Australia |
| 0560032 | Body Joint Resealing | C061100 | Holden Australia |
| 0560032 | Body Joint Resealing | C065000 | Holden Australia |
| 0560032 | Body Joint Resealing | A000318 | Holden New Zealand |
| 0560032 | Body Joint Resealing | A000336 | Holden New Zealand |
| 0560032 | Body Joint Resealing | A000342 | Holden New Zealand |
| 0560032 | Body Joint Resealing | A201598 | Holden New Zealand |
| 0560032 | Body Joint Resealing | A202100 | Holden New Zealand |
| 0560032 | Body Joint Resealing | A202200 | Holden New Zealand |
| 0560032 | Body Joint Resealing | A202400 | Holden New Zealand |
| 0560032 | Body Joint Resealing | A202500 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0560032 | Body Joint Resealing | A202600 | Holden New Zealand |
| 0560032 | Body Joint Resealing | A202700 | Holden New Zealand |
| 0560032 | Body Joint Resealing | A202800 | Holden New Zealand |
| 0560032 | Body Joint Resealing | A202900 | Holden New Zealand |
| 0560032 | Body Joint Resealing | A203098 | Holden New Zealand |
| 0560032 | Body Joint Resealing | A205199 | Holden New Zealand |
| 0560032 | Body Joint Resealing | A206098 | Holden New Zealand |
| 0560032 | Body Joint Resealing | A210198 | Holden New Zealand |
| 0560032 | Body Joint Resealing | A210298 | Holden New Zealand |
| 0560032 | Body Joint Resealing | A216598 | Holden New Zealand |
| 0560052 | Plenum Panel Resealing | | |
| 0560072 | Windshield Resealing | C0018 | GMNA |
| 0560072 | Windshield Resealing | C0020 | GMNA |
| 0560072 | Windshield Resealing | C0673 | GMNA |
| 0560072 | Windshield Resealing | R146040 | GMNA |
| 0560072 | Windshield Resealing | T6350 | GMNA |
| 0560072 | Windshield Resealing | T6354 | GMNA |
| 0560072 | Windshield Resealing | C001200 | Holden Australia |
| 0560072 | Windshield Resealing | C0020 | Holden Australia |
| 0560072 | Windshield Resealing | C002000 | Holden Australia |
| 0560072 | Windshield Resealing | C001200 | Holden New Zealand |
| 0560072 | Windshield Resealing | C002000 | Holden New Zealand |
| 0560092 | Body Side Window Resealing | C0450 | GMNA |
| 0560092 | Body Side Window Resealing | C0500 | GMNA |
| 0560092 | Body Side Window Resealing | C0501 | GMNA |
| 0560092 | Body Side Window Resealing | T6650 | GMNA |
| 0560092 | Body Side Window Resealing | C004110 | Holden Australia |
| 0560092 | Body Side Window Resealing | C004210 | Holden Australia |
| 0560092 | Body Side Window Resealing | C0450 | Holden Australia |
| 0560092 | Body Side Window Resealing | C004110 | Holden New Zealand |
| 0560092 | Body Side Window Resealing | C004210 | Holden New Zealand |
| 0560112 | Rear Window Resealing | C0650 | GMNA |
| 0560112 | Rear Window Resealing | C002500 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 0560112 | Rear Window Resealing | C0650 | Holden Australia |
| 0560112 | Rear Window Resealing | C002500 | Holden New Zealand |
| 0590019 | Towing | T2020 | GMNA |
| 0590032 | PDI - Dealer Installed - Factory Invoiced Options | Z6998 | GMNA |
| 0590052 | PDI Related Fluid Adds | Z6999 | GMNA |
| 0590072 | Pre-Delivery Inspection - Base Time | P0124 | GMNA |
| 0590072 | Pre-Delivery Inspection - Base Time | Z7000 | GMNA |
| 0590072 | Pre-Delivery Inspection - Base Time | M000187 | Holden Australia |
| 0590072 | Pre-Delivery Inspection - Base Time | M000187 | Holden New Zealand |
| 1010010 | Front End Fascia Emblem Replacement | B0031 | GMNA |
| 1010030 | Front License Plate Bracket Replacement | B0135 | GMNA |
| 1010030 | Front License Plate Bracket Replacement | B0140 | GMNA |
| 1010030 | Front License Plate Bracket Replacement | B9860 | GMNA |
| 1010030 | Front License Plate Bracket Replacement | 8441100 | GMK Domestic |
| 1010030 | Front License Plate Bracket Replacement | B0140 | Holden Australia |
| 1010030 | Front License Plate Bracket Replacement | 9561400 | GMK Overseas |
| 1010050 | Front Bumper Fascia Outer Molding Replacement | B0306 | GMNA |
| 1010070 | Front Bumper Fascia Upper Molding Replacement | B0309 | GMNA |
| 1010070 | Front Bumper Fascia Upper Molding Replacement | B0310 | GMNA |
| 1010070 | Front Bumper Fascia Upper Molding Replacement | B0312 | GMNA |
| 1010070 | Front Bumper Fascia Upper Molding Replacement | B0309 | Holden Australia |
| 1010080 | Front Bumper Fascia Outer Insert Molding Replacement | B0316 | GMNA |
| 1010090 | Front Bumper Lower Fascia Center Grille Replacement | B0446 | GMNA |
| 1010090 | Front Bumper Lower Fascia Center Grille Replacement | 8639200 | GMK Domestic |
| 1010110 | Front Bumper Lower Fascia Side Grille Replacement | B0481 | GMNA |
| 1010110 | Front Bumper Lower Fascia Side Grille Replacement | 8639100 | GMK Domestic |
| 1010130 | Rear Bumper Fascia Protector Replacement | B0606 | GMNA |
| 1010170 | Front Fender Inner Panel Access Opening Cover Replacement | B0777 | GMNA |
| 1010190 | Tail Lamp Closeout Filler Replacement | B1093 | GMNA |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B1295 | GMNA |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B7080 | GMNA |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B7100 | GMNA |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B7400 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B7401 | GMNA |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B7600 | GMNA |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B7601 | GMNA |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B8100 | GMNA |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B8101 | GMNA |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B8605 | GMNA |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B8610 | GMNA |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B8700 | GMNA |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B8705 | GMNA |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B8900 | GMNA |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B1295 | Holden Australia |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B710000 | Holden Australia |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | C891500 | Holden Australia |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B7100 | Holden New Zealand |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | B710000 | Holden New Zealand |
| 1010300 | Radiator Grille Emblem/Nameplate Replacement | C891500 | Holden New Zealand |
| 1010320 | Radiator Grille Molding Replacement | B0482 | GMNA |
| 1010320 | Radiator Grille Molding Replacement | B1296 | GMNA |
| 1010320 | Radiator Grille Molding Replacement | B1312 | GMNA |
| 1010320 | Radiator Grille Molding Replacement | B7142 | GMNA |
| 1010320 | Radiator Grille Molding Replacement | B7143 | GMNA |
| 1010340 | Front Outer Grille Replacement | | |
| 1010420 | Radiator Upper Grille Replacement | B1302 | GMNA |
| 1010420 | Radiator Upper Grille Replacement | B1302 | Holden Australia |
| 1010420 | Radiator Upper Grille Replacement | 9770200 | GMK Overseas |
| 1010440 | Front Lower Grille Replacement | B1303 | GMNA |
| 1010440 | Front Lower Grille Replacement | B1303 | Holden Australia |
| 1010440 | Front Lower Grille Replacement | 9770500 | GMK Overseas |
| 1010520 | Radiator Center Grille Replacement | B1306 | GMNA |
| 1010570 | Front Grille Replacement | B1308 | GMNA |
| 1010570 | Front Grille Replacement | 8637100 | GMK Domestic |
| 1010570 | Front Grille Replacement | 8637200 | GMK Domestic |
| 1010570 | Front Grille Replacement | A550000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1010570 | Front Grille Replacement | A550000 | Holden New Zealand |
| 1010590 | Front Lower Outer Grille Replacement | B1309 | GMNA |
| 1010610 | Radiator Grille Opening Bezel Replacement | | |
| 1010650 | Radiator Grille Upper Insert Replacement | B1314 | GMNA |
| 1010670 | Radiator Grille Lower Insert Replacement | | |
| 1010690 | Radiator Grille Opening Cover Replacement | B1316 | GMNA |
| 1010710 | Radiator Grille Retainer Replacement | | |
| 1010730 | Radiator Grille Opening Bezel Replacement - Upper | B1319 | GMNA |
| 1010830 | Hood Air Scoop Replacement | B1497 | GMNA |
| 1010830 | Hood Air Scoop Replacement | A015000 | Holden Australia |
| 1010830 | Hood Air Scoop Replacement | A015100 | Holden Australia |
| 1010830 | Hood Air Scoop Replacement | A015200 | Holden Australia |
| 1010850 | Hood Air Grille Replacement | B1498 | GMNA |
| 1010850 | Hood Air Grille Replacement | B1498 | Holden Australia |
| 1010870 | Hood Ornament Replacement | B1499 | GMNA |
| 1010920 | Body Side Outside Assist Handle Replacement | B4140 | GMNA |
| 1011060 | Pickup Box Outer Side Panel Rear Step Replacement | B5322 | GMNA |
| 1011290 | Rear End Spoiler Replacement | B5608 | GMNA |
| 1011290 | Rear End Spoiler Replacement | 8642200 | GMK Domestic |
| 1011290 | Rear End Spoiler Replacement | A506500 | Holden Australia |
| 1011290 | Rear End Spoiler Replacement | 9783300 | GMK Overseas |
| 1011290 | Rear End Spoiler Replacement | 9783350 | GMK Overseas |
| 1011290 | Rear End Spoiler Replacement | T697005 | GMK Overseas |
| 1011310 | Rear Compartment Lid Applique Replacement | B5609 | GMNA |
| 1011310 | Rear Compartment Lid Applique Replacement | 9781810 | GMK Overseas |
| 1011390 | Pickup Box Endgate Latch Handle Bezel Replacement | B5795 | GMNA |
| 1011390 | Pickup Box Endgate Latch Handle Bezel Replacement | B5795 | Holden Australia |
| 1011390 | Pickup Box Endgate Latch Handle Bezel Replacement | C613100 | Holden Australia |
| 1011390 | Pickup Box Endgate Latch Handle Bezel Replacement | C613100 | Holden New Zealand |
| 1011410 | Cargo Box Stowage Box Handle Replacement | B6043 | GMNA |
| 1011520 | Emblem/Nameplate Replacement | B7010 | GMNA |
| 1011520 | Emblem/Nameplate Replacement | B7010 | Holden Australia |
| 1011520 | Emblem/Nameplate Replacement | C882200 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1011520 | Emblem/Nameplate Replacement | 9510100 | GMK Overseas |
| 1011540 | Decal or Stripe Replacement | A3710 | GMNA |
| 1011540 | Decal or Stripe Replacement | A3730 | GMNA |
| 1011540 | Decal or Stripe Replacement | A4900 | GMNA |
| 1011540 | Decal or Stripe Replacement | A4910 | GMNA |
| 1011540 | Decal or Stripe Replacement | A4920 | GMNA |
| 1011540 | Decal or Stripe Replacement | A4923 | GMNA |
| 1011540 | Decal or Stripe Replacement | A9923 | GMNA |
| 1011540 | Decal or Stripe Replacement | B7011 | GMNA |
| 1011540 | Decal or Stripe Replacement | B9834 | GMNA |
| 1011540 | Decal or Stripe Replacement | B9933 | GMNA |
| 1011540 | Decal or Stripe Replacement | B069099 | Holden Australia |
| 1011540 | Decal or Stripe Replacement | B069099 | Holden New Zealand |
| 1011560 | Body Panel Paint Protector Replacement | B7012 | GMNA |
| 1011580 | Rear Compartment Lid Emblem/Nameplate Replacement | B7013 | GMNA |
| 1011580 | Rear Compartment Lid Emblem/Nameplate Replacement | C870900 | Holden Australia |
| 1011580 | Rear Compartment Lid Emblem/Nameplate Replacement | C870900 | Holden New Zealand |
| 1011580 | Rear Compartment Lid Emblem/Nameplate Replacement | 9510300 | GMK Overseas |
| 1011580 | Rear Compartment Lid Emblem/Nameplate Replacement | 951030A | GMK Overseas |
| 1011600 | Radiator Grille Upper Molding Replacement | 9772300 | GMK Overseas |
| 1011620 | Headlamp Bezel Replacement | B7240 | GMNA |
| 1011620 | Headlamp Bezel Replacement | B7286 | GMNA |
| 1011620 | Headlamp Bezel Replacement | B8600 | GMNA |
| 1011620 | Headlamp Bezel Replacement | B8601 | GMNA |
| 1011620 | Headlamp Bezel Replacement | B8646 | GMNA |
| 1011620 | Headlamp Bezel Replacement | N0231 | GMNA |
| 1011620 | Headlamp Bezel Replacement | N104470 | Holden Australia |
| 1011690 | Front Fog Lamp Bezel Replacement | B7245 | GMNA |
| 1011690 | Front Fog Lamp Bezel Replacement | 9770600 | GMK Overseas |
| 1011690 | Front Fog Lamp Bezel Replacement | 9770700 | GMK Overseas |
| 1011690 | Front Fog Lamp Bezel Replacement | 9770800 | GMK Overseas |
| 1011690 | Front Fog Lamp Bezel Replacement | 9771300 | GMK Overseas |
| 1011690 | Front Fog Lamp Bezel Replacement | 9771400 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1011700 | Front Bumper Fascia Front Tow Eye Access Hole Cover Replacement | B7246 | GMNA |
| 1011700 | Front Bumper Fascia Front Tow Eye Access Hole Cover Replacement | A561520 | Holden Australia |
| 1011700 | Front Bumper Fascia Front Tow Eye Access Hole Cover Replacement | A561520 | Holden New Zealand |
| 1011700 | Front Bumper Fascia Front Tow Eye Access Hole Cover Replacement | 9561700 | GMK Overseas |
| 1011710 | Rear Bumper Fascia Rear Tow Eye Access Hole Cover Replacement | B7247 | GMNA |
| 1011710 | Rear Bumper Fascia Rear Tow Eye Access Hole Cover Replacement | 8514500 | GMK Domestic |
| 1011710 | Rear Bumper Fascia Rear Tow Eye Access Hole Cover Replacement | A571520 | Holden Australia |
| 1011710 | Rear Bumper Fascia Rear Tow Eye Access Hole Cover Replacement | A571520 | Holden New Zealand |
| 1011720 | Rear Bumper Filler Replacement | | |
| 1011730 | Hood Side Molding Replacement | B7338 | GMNA |
| 1011730 | Hood Side Molding Replacement | A015250 | Holden Australia |
| 1011750 | Hood Front Molding Replacement | B7339 | GMNA |
| 1011750 | Hood Front Molding Replacement | A015250 | Holden New Zealand |
| 1011750 | Hood Front Molding Replacement | 9730400 | GMK Overseas |
| 1011770 | Hood Rear Molding Replacement | B7332 | GMNA |
| 1011770 | Hood Rear Molding Replacement | B7340 | GMNA |
| 1011790 | Hood Center Molding Replacement | B7341 | GMNA |
| 1011840 | Front Intake Air Duct Hole Cover Replacement | | |
| 1011860 | Front Bumper Impact Bar Fog Lamp Access Hole Cover Replacement | B7354 | GMNA |
| 1011940 | Body Hinge Pillar Filler Replacement | B7442 | GMNA |
| 1011960 | Front Fender Lower Rear Molding Replacement | B7465 | GMNA |
| 1012010 | Body Side Upper Front Applique Replacement | B7471 | GMNA |
| 1012010 | Body Side Upper Front Applique Replacement | 9526100 | GMK Overseas |
| 1012010 | Body Side Upper Front Applique Replacement | 9526200 | GMK Overseas |
| 1012010 | Body Side Upper Front Applique Replacement | 9526300 | GMK Overseas |
| 1012030 | Front Fender Upper Rear Molding Replacement | B7472 | GMNA |
| 1012030 | Front Fender Upper Rear Molding Replacement | B7474 | GMNA |
| 1012030 | Front Fender Upper Rear Molding Replacement | B7479 | GMNA |
| 1012030 | Front Fender Upper Rear Molding Replacement | 8430302 | GMK Domestic |
| 1012030 | Front Fender Upper Rear Molding Replacement | 8430400 | GMK Domestic |
| 1012110 | Front Fender Wheel Opening Molding Replacement | B7480 | GMNA |
| 1012110 | Front Fender Wheel Opening Molding Replacement | C838300 | Holden Australia |
| 1012110 | Front Fender Wheel Opening Molding Replacement | C838400 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1012110 | Front Fender Wheel Opening Molding Replacement | C882100 | Holden Australia |
| 1012110 | Front Fender Wheel Opening Molding Replacement | C883100 | Holden Australia |
| 1012110 | Front Fender Wheel Opening Molding Replacement | C884100 | Holden Australia |
| 1012110 | Front Fender Wheel Opening Molding Replacement | C884200 | Holden Australia |
| 1012110 | Front Fender Wheel Opening Molding Replacement | C838300 | Holden New Zealand |
| 1012110 | Front Fender Wheel Opening Molding Replacement | C882100 | Holden New Zealand |
| 1012110 | Front Fender Wheel Opening Molding Replacement | C883100 | Holden New Zealand |
| 1012110 | Front Fender Wheel Opening Molding Replacement | C884100 | Holden New Zealand |
| 1012110 | Front Fender Wheel Opening Molding Replacement | C884200 | Holden New Zealand |
| 1012110 | Front Fender Wheel Opening Molding Replacement | 9521100 | GMK Overseas |
| 1012110 | Front Fender Wheel Opening Molding Replacement | 9521200 | GMK Overseas |
| 1012110 | Front Fender Wheel Opening Molding Replacement | 9521300 | GMK Overseas |
| 1012180 | Front Fender Ornament Replacement | B7485 | GMNA |
| 1012200 | Front Fender Center Rear Upper Molding Insert Replacement | B7486 | GMNA |
| 1012200 | Front Fender Center Rear Upper Molding Insert Replacement | B9958 | GMNA |
| 1012220 | Front Fender Center Molding Replacement | B7487 | GMNA |
| 1012240 | Front Wheel Opening Flare Replacement | B7490 | GMNA |
| 1012240 | Front Wheel Opening Flare Replacement | B7490 | Holden Australia |
| 1012250 | Windshield Frame Filler Panel Replacement | B7568 | GMNA |
| 1012350 | Windshield Frame Filler Panel Applique Replacement | B7569 | GMNA |
| 1012400 | Body Side Window Reveal Molding Replacement | | |
| 1012420 | Center Pillar Molding Replacement | B7579 | GMNA |
| 1012420 | Center Pillar Molding Replacement | C000625 | Holden Australia |
| 1012420 | Center Pillar Molding Replacement | C896800 | Holden Australia |
| 1012420 | Center Pillar Molding Replacement | C896700 | Holden New Zealand |
| 1012420 | Center Pillar Molding Replacement | C896800 | Holden New Zealand |
| 1012560 | Roof Front Drip Molding Replacement | B7612 | GMNA |
| 1012600 | Roof Drip Scalp Molding Replacement | B7616 | GMNA |
| 1012620 | Front and Rear Side Door Outer Opening Frame Upper Reveal Molding Replacement | | |
| 1012700 | Roof Center Drip Front Molding Replacement | | |
| 1012720 | Roof Center Drip Rear Molding Replacement | B7623 | GMNA |
| 1012860 | Roof Panel Joint Front Finish Molding Replacement | B7790 | GMNA |
| 1012860 | Roof Panel Joint Front Finish Molding Replacement | C825150 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1012860 | Roof Panel Joint Front Finish Molding Replacement | C896700 | Holden Australia |
| 1012860 | Roof Panel Joint Front Finish Molding Replacement | C825150 | Holden New Zealand |
| 1012860 | Roof Panel Joint Front Finish Molding Replacement | C825200 | Holden New Zealand |
| 1012860 | Roof Panel Joint Front Finish Molding Replacement | C827000 | Holden New Zealand |
| 1012880 | Roof Panel Joint Rear Finish Molding Replacement | | |
| 1012900 | Roof Panel Joint Finish Molding Clip Replacement | B7679 | GMNA |
| 1012900 | Roof Panel Joint Finish Molding Clip Replacement | T6353 | GMNA |
| 1012920 | Roof Panel Joint Finish Molding Replacement | B7680 | GMNA |
| 1012920 | Roof Panel Joint Finish Molding Replacement | B7680 | Holden Australia |
| 1012920 | Roof Panel Joint Finish Molding Replacement | C825100 | Holden Australia |
| 1012920 | Roof Panel Joint Finish Molding Replacement | C825200 | Holden Australia |
| 1012920 | Roof Panel Joint Finish Molding Replacement | C825100 | Holden New Zealand |
| 1012970 | Roof Panel Molding Replacement | B7682 | GMNA |
| 1012970 | Roof Panel Molding Replacement | 9711100 | GMK Overseas |
| 1012970 | Roof Panel Molding Replacement | 9711200 | GMK Overseas |
| 1012970 | Roof Panel Molding Replacement | 9711300 | GMK Overseas |
| 1012990 | Roof Panel Front Molding Replacement | B7683 | GMNA |
| 1013060 | Center Pillar Applique Replacement | B7720 | GMNA |
| 1013060 | Center Pillar Applique Replacement | B7721 | GMNA |
| 1013100 | Front and Rear Side Door Sill Trim Plate Replacement | B7754 | GMNA |
| 1013100 | Front and Rear Side Door Sill Trim Plate Replacement | B7962 | GMNA |
| 1013100 | Front and Rear Side Door Sill Trim Plate Replacement | B8603 | GMNA |
| 1013120 | Side Door Sill Trim Plate Decal Replacement | B7755 | GMNA |
| 1013140 | Rocker Panel Extension Molding Replacement | B7758 | GMNA |
| 1013160 | Rocker Panel Molding Rear End Cap Replacement | B7759 | GMNA |
| 1013180 | Rocker Panel Molding Replacement | B7756 | GMNA |
| 1013180 | Rocker Panel Molding Replacement | B7757 | GMNA |
| 1013180 | Rocker Panel Molding Replacement | B7760 | GMNA |
| 1013180 | Rocker Panel Molding Replacement | B7775 | GMNA |
| 1013180 | Rocker Panel Molding Replacement | B7776 | GMNA |
| 1013180 | Rocker Panel Molding Replacement | B9850 | GMNA |
| 1013180 | Rocker Panel Molding Replacement | B9930 | GMNA |
| 1013180 | Rocker Panel Molding Replacement | A000291 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1013180 | Rocker Panel Molding Replacement | A000294 | Holden Australia |
| 1013180 | Rocker Panel Molding Replacement | A506100 | Holden Australia |
| 1013180 | Rocker Panel Molding Replacement | A506200 | Holden Australia |
| 1013180 | Rocker Panel Molding Replacement | A506250 | Holden Australia |
| 1013180 | Rocker Panel Molding Replacement | A506300 | Holden Australia |
| 1013180 | Rocker Panel Molding Replacement | A506400 | Holden Australia |
| 1013180 | Rocker Panel Molding Replacement | B7760 | Holden Australia |
| 1013180 | Rocker Panel Molding Replacement | B776400 | Holden Australia |
| 1013180 | Rocker Panel Molding Replacement | B776500 | Holden Australia |
| 1013180 | Rocker Panel Molding Replacement | C621630 | Holden Australia |
| 1013180 | Rocker Panel Molding Replacement | C621640 | Holden Australia |
| 1013180 | Rocker Panel Molding Replacement | C621730 | Holden Australia |
| 1013180 | Rocker Panel Molding Replacement | C621740 | Holden Australia |
| 1013180 | Rocker Panel Molding Replacement | C888000 | Holden Australia |
| 1013180 | Rocker Panel Molding Replacement | C888600 | Holden Australia |
| 1013180 | Rocker Panel Molding Replacement | A000291 | Holden New Zealand |
| 1013180 | Rocker Panel Molding Replacement | A000294 | Holden New Zealand |
| 1013180 | Rocker Panel Molding Replacement | A506100 | Holden New Zealand |
| 1013180 | Rocker Panel Molding Replacement | A506200 | Holden New Zealand |
| 1013180 | Rocker Panel Molding Replacement | A506250 | Holden New Zealand |
| 1013180 | Rocker Panel Molding Replacement | A506300 | Holden New Zealand |
| 1013180 | Rocker Panel Molding Replacement | A506400 | Holden New Zealand |
| 1013180 | Rocker Panel Molding Replacement | B776400 | Holden New Zealand |
| 1013180 | Rocker Panel Molding Replacement | C621640 | Holden New Zealand |
| 1013180 | Rocker Panel Molding Replacement | C621730 | Holden New Zealand |
| 1013180 | Rocker Panel Molding Replacement | C621740 | Holden New Zealand |
| 1013180 | Rocker Panel Molding Replacement | C888000 | Holden New Zealand |
| 1013180 | Rocker Panel Molding Replacement | C888200 | Holden New Zealand |
| 1013180 | Rocker Panel Molding Replacement | C888600 | Holden New Zealand |
| 1013230 | Rocker Panel Front Molding Replacement | B7762 | GMNA |
| 1013340 | Rocker Panel Rear Molding Replacement | B7766 | GMNA |
| 1013480 | Body Side Window Rear Panel Replacement | | |
| 1013510 | Body Side Lower Rear Molding Replacement | B7772 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1013560 | Front Fender Mud Flap Guard Replacement | 8646500 | GMK Domestic |
| 1013560 | Front Fender Mud Flap Guard Replacement | 8646600 | GMK Domestic |
| 1013560 | Front Fender Mud Flap Guard Replacement | 9520100 | GMK Overseas |
| 1013560 | Front Fender Mud Flap Guard Replacement | 9520200 | GMK Overseas |
| 1013560 | Front Fender Mud Flap Guard Replacement | 9520300 | GMK Overseas |
| 1013570 | Door Latch Release Actuator Bezel Replacement | B7795 | GMNA |
| 1013590 | Front and Rear Side Door Opening Frame Reveal Molding Replacement | R005300 | Holden Australia |
| 1013590 | Front and Rear Side Door Opening Frame Reveal Molding Replacement | R005400 | Holden Australia |
| 1013590 | Front and Rear Side Door Opening Frame Reveal Molding Replacement | R005300 | Holden New Zealand |
| 1013590 | Front and Rear Side Door Opening Frame Reveal Molding Replacement | R005400 | Holden New Zealand |
| 1013600 | Front Side Door Window Frame Rear Applique Replacement | 9518500 | GMK Overseas |
| 1013600 | Front Side Door Window Frame Rear Applique Replacement | 9618500 | GMK Overseas |
| 1013600 | Front Side Door Window Frame Rear Applique Replacement | 9618510 | GMK Overseas |
| 1013600 | Front Side Door Window Frame Rear Applique Replacement | 9618520 | GMK Overseas |
| 1013790 | Front Side Door Window Outer Weatherstrip Stripe Replacement | B4807 | GMNA |
| 1013790 | Front Side Door Window Outer Weatherstrip Stripe Replacement | B4808 | GMNA |
| 1013790 | Front Side Door Window Outer Weatherstrip Stripe Replacement | B7830 | GMNA |
| 1013930 | Front Side Door Lower Molding Replacement | B7863 | GMNA |
| 1013930 | Front Side Door Lower Molding Replacement | 9520900 | GMK Overseas |
| 1013930 | Front Side Door Lower Molding Replacement | 9520910 | GMK Overseas |
| 1013930 | Front Side Door Lower Molding Replacement | 9520920 | GMK Overseas |
| 1013930 | Front Side Door Lower Molding Replacement | 9900600 | GMK Overseas |
| 1013950 | Body Side Molding Replacement | B7430 | GMNA |
| 1013950 | Body Side Molding Replacement | B7431 | GMNA |
| 1013950 | Body Side Molding Replacement | B7866 | GMNA |
| 1013950 | Body Side Molding Replacement | B7868 | GMNA |
| 1013950 | Body Side Molding Replacement | C830100 | Holden Australia |
| 1013950 | Body Side Molding Replacement | 9619350 | GMK Overseas |
| 1014120 | Rear Side Door Window Frame Front Cover Replacement | B7924 | GMNA |
| 1014120 | Rear Side Door Window Frame Front Cover Replacement | 9522100 | GMK Overseas |
| 1014120 | Rear Side Door Window Frame Front Cover Replacement | 9522200 | GMK Overseas |
| 1014120 | Rear Side Door Window Frame Front Cover Replacement | 9522300 | GMK Overseas |
| 1014120 | Rear Side Door Window Frame Front Cover Replacement | 9636510 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1014120 | Rear Side Door Window Frame Front Cover Replacement | 9636520 | GMK Overseas |
| 1014120 | Rear Side Door Window Frame Front Cover Replacement | 9638500 | GMK Overseas |
| 1014120 | Rear Side Door Window Frame Front Cover Replacement | 9638510 | GMK Overseas |
| 1014120 | Rear Side Door Window Frame Front Cover Replacement | 9638520 | GMK Overseas |
| 1014140 | Rear Side Door Window Outer Weatherstrip Stripe Replacement | B7925 | GMNA |
| 1014160 | Rear Side Door Window Frame Rear Cover Replacement | 9526400 | GMK Overseas |
| 1014160 | Rear Side Door Window Frame Rear Cover Replacement | 9526500 | GMK Overseas |
| 1014160 | Rear Side Door Window Frame Rear Cover Replacement | 9526600 | GMK Overseas |
| 1014180 | Rear Side Door Window Frame Filler Replacement | C004200 | Holden New Zealand |
| 1014200 | Rear Side Door Lower Molding Replacement | B7963 | GMNA |
| 1014210 | Rear Side Door Window Frame Rear Applique Replacement | 9639600 | GMK Overseas |
| 1014210 | Rear Side Door Window Frame Rear Applique Replacement | 9639610 | GMK Overseas |
| 1014210 | Rear Side Door Window Frame Rear Applique Replacement | 9639620 | GMK Overseas |
| 1014220 | Rear Side Door Molding Replacement | B7966 | GMNA |
| 1014220 | Rear Side Door Molding Replacement | C838200 | Holden Australia |
| 1014220 | Rear Side Door Molding Replacement | C838200 | Holden New Zealand |
| 1014220 | Rear Side Door Molding Replacement | 9639300 | GMK Overseas |
| 1014220 | Rear Side Door Molding Replacement | 9639500 | GMK Overseas |
| 1014220 | Rear Side Door Molding Replacement | 9639510 | GMK Overseas |
| 1014230 | Rear Side Door Window Frame Front Applique Replacement | | |
| 1014630 | Rear Door Outer Extension Panel Replacement | B8125 | GMNA |
| 1014630 | Rear Door Outer Extension Panel Replacement | C127750 | Holden Australia |
| 1014630 | Rear Door Outer Extension Panel Replacement | C127850 | Holden Australia |
| 1014630 | Rear Door Outer Extension Panel Replacement | C127850 | Holden New Zealand |
| 1014650 | Body Lock Pillar Reveal Molding Replacement | B8126 | GMNA |
| 1015010 | Quarter Panel Upper Rear Molding Replacement | B8269 | GMNA |
| 1015120 | Rear Wheel Opening Molding Replacement | B8280 | GMNA |
| 1015120 | Rear Wheel Opening Molding Replacement | B8310 | GMNA |
| 1015120 | Rear Wheel Opening Molding Replacement | B8280 | Holden Australia |
| 1015120 | Rear Wheel Opening Molding Replacement | C847100 | Holden Australia |
| 1015120 | Rear Wheel Opening Molding Replacement | C847200 | Holden Australia |
| 1015120 | Rear Wheel Opening Molding Replacement | C847100 | Holden New Zealand |
| 1015120 | Rear Wheel Opening Molding Replacement | C847200 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1015120 | Rear Wheel Opening Molding Replacement | 9522500 | GMK Overseas |
| 1015120 | Rear Wheel Opening Molding Replacement | 9522600 | GMK Overseas |
| 1015120 | Rear Wheel Opening Molding Replacement | 9522700 | GMK Overseas |
| 1015170 | Rear Wheel Opening Front Flare Replacement | B8289 | GMNA |
| 1015190 | Rear Wheel Opening Flare Replacement | B8290 | GMNA |
| 1015190 | Rear Wheel Opening Flare Replacement | B8290 | Holden Australia |
| 1015470 | Rear Door Lower Molding Replacement | B8550 | GMNA |
| 1015550 | Pickup Box Endgate Latch Cover Replacement | B8622 | GMNA |
| 1015570 | Pickup Box Cargo Tie Down Hook Replacement | | |
| 1015590 | Pickup Box Liner Replacement | B5290 | GMNA |
| 1015590 | Pickup Box Liner Replacement | B8627 | GMNA |
| 1015590 | Pickup Box Liner Replacement | A590500 | Holden Australia |
| 1015590 | Pickup Box Liner Replacement | R407100 | Holden Australia |
| 1015590 | Pickup Box Liner Replacement | R407350 | Holden Australia |
| 1015590 | Pickup Box Liner Replacement | R9365 | Holden Australia |
| 1015590 | Pickup Box Liner Replacement | A590500 | Holden New Zealand |
| 1015590 | Pickup Box Liner Replacement | R407100 | Holden New Zealand |
| 1015610 | Pickup Box Liner Replacement - Front | B8628 | GMNA |
| 1015630 | Pickup Box Liner Replacement - Side | B8629 | GMNA |
| 1015650 | Pickup Box Front Upper Molding Replacement | B8630 | GMNA |
| 1015670 | Pickup Box Side Upper Molding Replacement | B8631 | GMNA |
| 1015670 | Pickup Box Side Upper Molding Replacement | R2423 | GMNA |
| 1015670 | Pickup Box Side Upper Molding Replacement | R2427 | GMNA |
| 1015690 | Endgate Upper Finish Molding End Cap Replacement | B8632 | GMNA |
| 1015710 | Pickup Box Cover Replacement | B8633 | GMNA |
| 1015750 | Cargo Carrier Pickup Box Front Cap Replacement | B8635 | GMNA |
| 1015770 | Cargo Carrier Pickup Box Front Rail Replacement | B8636 | GMNA |
| 1015790 | Cargo Carrier Pickup Box Side Rail Replacement | B8637 | GMNA |
| 1015790 | Cargo Carrier Pickup Box Side Rail Replacement | R603800 | Holden Australia |
| 1015790 | Cargo Carrier Pickup Box Side Rail Replacement | R603800 | Holden New Zealand |
| 1015840 | Rear Compartment Lid Lower Molding Replacement | B8639 | GMNA |
| 1015840 | Rear Compartment Lid Lower Molding Replacement | C847500 | Holden Australia |
| 1015840 | Rear Compartment Lid Lower Molding Replacement | C847500 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1015950 | Quarter Panel Tail Lamp Upper Molding Replacement | B8678 | GMNA |
| 1015960 | Tail Lamp Bezel Replacement | B8688 | GMNA |
| 1015970 | Body Side Upper Rear Applique Replacement | B8689 | GMNA |
| 1015990 | Quarter Panel Upper Applique Replacement | B8690 | GMNA |
| 1015990 | Quarter Panel Upper Applique Replacement | C000598 | Holden Australia |
| 1015990 | Quarter Panel Upper Applique Replacement | C403000 | Holden Australia |
| 1015990 | Quarter Panel Upper Applique Replacement | C403100 | Holden Australia |
| 1015990 | Quarter Panel Upper Applique Replacement | C897400 | Holden New Zealand |
| 1016070 | Liftgate Side Applique Replacement | B8822 | GMNA |
| 1016070 | Liftgate Side Applique Replacement | 8643000 | GMK Domestic |
| 1016090 | Liftgate Center Applique Replacement | B8823 | GMNA |
| 1016090 | Liftgate Center Applique Replacement | 9671710 | GMK Overseas |
| 1016110 | Liftgate Upper Applique Replacement | B8824 | GMNA |
| 1016130 | Liftgate Applique Replacement | B8825 | GMNA |
| 1016130 | Liftgate Applique Replacement | A506600 | Holden Australia |
| 1016130 | Liftgate Applique Replacement | C000583 | Holden Australia |
| 1016130 | Liftgate Applique Replacement | A506600 | Holden New Zealand |
| 1016150 | Endgate Applique Replacement | B8826 | GMNA |
| 1016190 | Back Body Opening Side Applique Replacement | | |
| 1016240 | Back Body Opening Upper Applique Replacement | B8832 | GMNA |
| 1016260 | Liftgate Upper Molding Replacement | B8962 | GMNA |
| 1016280 | Liftgate Lower Molding Replacement | B8963 | GMNA |
| 1016330 | Pickup Box Endgate Molding Replacement | B8969 | GMNA |
| 1016410 | Endgate Upper Molding Replacement | B8972 | GMNA |
| 1016410 | Endgate Upper Molding Replacement | C614000 | Holden Australia |
| 1016410 | Endgate Upper Molding Replacement | C614100 | Holden Australia |
| 1016410 | Endgate Upper Molding Replacement | C614200 | Holden Australia |
| 1016410 | Endgate Upper Molding Replacement | C614000 | Holden New Zealand |
| 1016410 | Endgate Upper Molding Replacement | C614100 | Holden New Zealand |
| 1016460 | Rear License Plate Lamp Bezel Replacement | B8989 | GMNA |
| 1016480 | Rear License Plate Pocket Replacement | B8990 | GMNA |
| 1016520 | Spare Wheel Stowage Outer Cover Replacement | 9390500 | GMK Overseas |
| 1020020 | Driver Footrest Replacement | C2926 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1020020 | Driver Footrest Replacement | C001100 | Holden Australia |
| 1020020 | Driver Footrest Replacement | C001100 | Holden New Zealand |
| 1020020 | Driver Footrest Replacement | 9391600 | GMK Overseas |
| 1020090 | Sunroof Panel Trim Panel Replacement | B2862 | GMNA |
| 1020090 | Sunroof Panel Trim Panel Replacement | B2899 | GMNA |
| 1020090 | Sunroof Panel Trim Panel Replacement | C3121 | GMNA |
| 1020110 | Headlining Front Trim Panel Replacement | C3122 | GMNA |
| 1020110 | Headlining Front Trim Panel Replacement | C440100 | Holden Australia |
| 1020110 | Headlining Front Trim Panel Replacement | C440100 | Holden New Zealand |
| 1020110 | Headlining Front Trim Panel Replacement | C449010 | Holden New Zealand |
| 1020130 | Headlining Rear Trim Panel Replacement | C3123 | GMNA |
| 1020130 | Headlining Rear Trim Panel Replacement | C000719 | Holden Australia |
| 1020130 | Headlining Rear Trim Panel Replacement | C623800 | Holden Australia |
| 1020130 | Headlining Rear Trim Panel Replacement | C000719 | Holden New Zealand |
| 1020150 | Folding Top Headlining Trim Panel Replacement | C3124 | GMNA |
| 1020170 | Roof Lift Off Panel Headlining Trim Panel Replacement | C3125 | GMNA |
| 1020170 | Roof Lift Off Panel Headlining Trim Panel Replacement | C9948 | GMNA |
| 1020170 | Roof Lift Off Panel Headlining Trim Panel Replacement | C400130 | Holden Australia |
| 1020170 | Roof Lift Off Panel Headlining Trim Panel Replacement | C400150 | Holden Australia |
| 1020170 | Roof Lift Off Panel Headlining Trim Panel Replacement | C400130 | Holden New Zealand |
| 1020170 | Roof Lift Off Panel Headlining Trim Panel Replacement | C400150 | Holden New Zealand |
| 1020210 | Headlining Trim Panel Replacement | C3098 | GMNA |
| 1020210 | Headlining Trim Panel Replacement | C3108 | GMNA |
| 1020210 | Headlining Trim Panel Replacement | C3128 | GMNA |
| 1020210 | Headlining Trim Panel Replacement | C9504 | GMNA |
| 1020210 | Headlining Trim Panel Replacement | C9506 | GMNA |
| 1020210 | Headlining Trim Panel Replacement | C9947 | GMNA |
| 1020210 | Headlining Trim Panel Replacement | C9966 | GMNA |
| 1020210 | Headlining Trim Panel Replacement | C9972 | GMNA |
| 1020210 | Headlining Trim Panel Replacement | C309800 | Holden Australia |
| 1020210 | Headlining Trim Panel Replacement | C310800 | Holden Australia |
| 1020210 | Headlining Trim Panel Replacement | C3128 | Holden Australia |
| 1020210 | Headlining Trim Panel Replacement | C313000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1020210 | Headlining Trim Panel Replacement | C400100 | Holden Australia |
| 1020210 | Headlining Trim Panel Replacement | C3098 | Holden New Zealand |
| 1020210 | Headlining Trim Panel Replacement | C309800 | Holden New Zealand |
| 1020210 | Headlining Trim Panel Replacement | C310800 | Holden New Zealand |
| 1020210 | Headlining Trim Panel Replacement | C400100 | Holden New Zealand |
| 1020210 | Headlining Trim Panel Replacement | 9710100 | GMK Overseas |
| 1020260 | Floor Mat Replacement | C4175 | GMNA |
| 1020260 | Floor Mat Replacement | R100200 | Holden Australia |
| 1020260 | Floor Mat Replacement | R100200 | Holden New Zealand |
| 1020260 | Floor Mat Replacement | 9390350 | GMK Overseas |
| 1020260 | Floor Mat Replacement | 9390360 | GMK Overseas |
| 1020280 | Front Side Door Opening Floor Carpet Retainer Replacement | C4176 | GMNA |
| 1020280 | Front Side Door Opening Floor Carpet Retainer Replacement | C4180 | GMNA |
| 1020280 | Front Side Door Opening Floor Carpet Retainer Replacement | C4181 | GMNA |
| 1020280 | Front Side Door Opening Floor Carpet Retainer Replacement | R000272 | Holden New Zealand |
| 1020300 | Rear Side Door Opening Floor Carpet Retainer Replacement | C4177 | GMNA |
| 1020300 | Rear Side Door Opening Floor Carpet Retainer Replacement | C4182 | GMNA |
| 1020300 | Rear Side Door Opening Floor Carpet Retainer Replacement | C4183 | GMNA |
| 1020320 | Rear Side Door Step Mat Replacement | C4179 | GMNA |
| 1020520 | Front Floor Panel Carpet Replacement - Right Side | C4200 | GMNA |
| 1020540 | Front Floor Panel Carpet Replacement - Left Side | C4201 | GMNA |
| 1020560 | Front Floor Panel Carpet Replacement | C4202 | GMNA |
| 1020560 | Front Floor Panel Carpet Replacement | C4493 | GMNA |
| 1020560 | Front Floor Panel Carpet Replacement | C4494 | GMNA |
| 1020560 | Front Floor Panel Carpet Replacement | C4495 | GMNA |
| 1020560 | Front Floor Panel Carpet Replacement | C9824 | GMNA |
| 1020560 | Front Floor Panel Carpet Replacement | C9825 | GMNA |
| 1020560 | Front Floor Panel Carpet Replacement | C4202 | Holden Australia |
| 1020560 | Front Floor Panel Carpet Replacement | C449100 | Holden Australia |
| 1020560 | Front Floor Panel Carpet Replacement | 9390100 | GMK Overseas |
| 1020580 | Rear Floor Panel Carpet Replacement | C4203 | GMNA |
| 1020580 | Rear Floor Panel Carpet Replacement | C449500 | Holden Australia |
| 1020580 | Rear Floor Panel Carpet Replacement | C449500 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1020580 | Rear Floor Panel Carpet Replacement | C451010 | Holden New Zealand |
| 1020580 | Rear Floor Panel Carpet Replacement | C451040 | Holden New Zealand |
| 1020670 | Floor Panel Carpet Replacement | C4208 | GMNA |
| 1020690 | Floor Carpet Retainer Replacement | C4216 | GMNA |
| 1020690 | Floor Carpet Retainer Replacement | C9872 | GMNA |
| 1020690 | Floor Carpet Retainer Replacement | C9886 | GMNA |
| 1020710 | Floor Carpet Auxiliary Mat Retainer Replacement | C4217 | GMNA |
| 1020710 | Floor Carpet Auxiliary Mat Retainer Replacement | C9517 | GMNA |
| 1020710 | Floor Carpet Auxiliary Mat Retainer Replacement | C449200 | Holden Australia |
| 1020710 | Floor Carpet Auxiliary Mat Retainer Replacement | C449100 | Holden New Zealand |
| 1020710 | Floor Carpet Auxiliary Mat Retainer Replacement | C449200 | Holden New Zealand |
| 1020710 | Floor Carpet Auxiliary Mat Retainer Replacement | C449200A1 | Holden New Zealand |
| 1020730 | Front Floor Panel Carpet Hook Replacement | C4218 | GMNA |
| 1020780 | Front Seat Back Body Panel Carpet Replacement | C4220 | GMNA |
| 1020780 | Front Seat Back Body Panel Carpet Replacement | C9881 | GMNA |
| 1020800 | Front Floor Panel Mat Replacement | C4222 | GMNA |
| 1020800 | Front Floor Panel Mat Replacement | R000272 | Holden Australia |
| 1020820 | Rear Floor Mat Replacement | C4223 | GMNA |
| 1020820 | Rear Floor Mat Replacement | C432650 | Holden Australia |
| 1020820 | Rear Floor Mat Replacement | C431150 | Holden New Zealand |
| 1020820 | Rear Floor Mat Replacement | C432650 | Holden New Zealand |
| 1020840 | Floor Panel Mat Replacement | C4224 | GMNA |
| 1020840 | Floor Panel Mat Replacement | C4226 | GMNA |
| 1020860 | Body Rear Inner Panel Carpet Replacement | C4506 | GMNA |
| 1020890 | Load Floor Carpet Replacement | C4619 | GMNA |
| 1021040 | Rear Compartment Floor Panel Carpet Replacement | | |
| 1030010 | Instrument Panel Compartment Door Pad Replacement | | |
| 1030020 | Instrument Panel Compartment Door Latch Actuator Replacement | | |
| 1030030 | Instrument Panel Upper Compartment Door Latch Replacement | C2093 | GMNA |
| 1030040 | Instrument Panel Compartment Door Latch Release Handle Replacement | C2090 | GMNA |
| 1030040 | Instrument Panel Compartment Door Latch Release Handle Replacement | C9889 | GMNA |
| 1030070 | Instrument Panel Compartment Door Latch Replacement | C2095 | GMNA |
| 1030070 | Instrument Panel Compartment Door Latch Replacement | C9817 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1030070 | Instrument Panel Compartment Door Latch Replacement | C2095 | Holden Australia |
| 1030090 | Instrument Panel Compartment Door Latch Trim Cover Replacement | C2096 | GMNA |
| 1030110 | Instrument Panel Compartment Door Lock Cylinder Replacement | C2097 | GMNA |
| 1030110 | Instrument Panel Compartment Door Lock Cylinder Replacement | C459110 | Holden Australia |
| 1030110 | Instrument Panel Compartment Door Lock Cylinder Replacement | C459700 | Holden Australia |
| 1030110 | Instrument Panel Compartment Door Lock Cylinder Replacement | C459110 | Holden New Zealand |
| 1030110 | Instrument Panel Compartment Door Lock Cylinder Replacement | C459700 | Holden New Zealand |
| 1030130 | Instrument Panel Compartment Door Compartment Replacement | C2098 | GMNA |
| 1030130 | Instrument Panel Compartment Door Compartment Replacement | C2153 | GMNA |
| 1030130 | Instrument Panel Compartment Door Compartment Replacement | C9926 | GMNA |
| 1030130 | Instrument Panel Compartment Door Compartment Replacement | C000656 | Holden Australia |
| 1030130 | Instrument Panel Compartment Door Compartment Replacement | C459300 | Holden Australia |
| 1030130 | Instrument Panel Compartment Door Compartment Replacement | C000656 | Holden New Zealand |
| 1030130 | Instrument Panel Compartment Door Compartment Replacement | C214000 | Holden New Zealand |
| 1030130 | Instrument Panel Compartment Door Compartment Replacement | C459300 | Holden New Zealand |
| 1030150 | Instrument Panel Compartment Door Emblem Replacement | C2099 | GMNA |
| 1030160 | Instrument Panel Compartment Door Lock Replacement | C2100 | GMNA |
| 1030160 | Instrument Panel Compartment Door Lock Replacement | 8522100 | GMK Domestic |
| 1030160 | Instrument Panel Compartment Door Lock Replacement | C210000 | Holden Australia |
| 1030160 | Instrument Panel Compartment Door Lock Replacement | C2100 | Holden New Zealand |
| 1030160 | Instrument Panel Compartment Door Lock Replacement | 9310100 | GMK Overseas |
| 1030170 | Instrument Panel Compartment Housing Replacement | C2101 | GMNA |
| 1030190 | Instrument Panel Upper Compartment Door Replacement | | |
| 1030210 | Instrument Panel Upper Center Compartment Replacement | C2103 | GMNA |
| 1030230 | Instrument Panel Compartment Lamp Switch Actuator Replacement | C2104 | GMNA |
| 1030230 | Instrument Panel Compartment Lamp Switch Actuator Replacement | N214600 | Holden Australia |
| 1030230 | Instrument Panel Compartment Lamp Switch Actuator Replacement | N214600 | Holden New Zealand |
| 1030270 | Instrument Panel Compartment Door Lock Striker Replacement | C2106 | GMNA |
| 1030270 | Instrument Panel Compartment Door Lock Striker Replacement | 8522500 | GMK Domestic |
| 1030270 | Instrument Panel Compartment Door Lock Striker Replacement | 9313500 | GMK Overseas |
| 1030272 | Instrument Panel Compartment Door Lock Striker Adjustment | C2105 | GMNA |
| 1030290 | Instrument Panel Compartment Door Spring Replacement | | |
| 1030310 | Instrument Panel Compartment Door Dampener Replacement | C2109 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1030320 | Instrument Panel Cup Holder Replacement | C2085 | GMNA |
| 1030320 | Instrument Panel Cup Holder Replacement | 8614500 | GMK Domestic |
| 1030320 | Instrument Panel Cup Holder Replacement | 9330300 | GMK Overseas |
| 1030390 | Instrument Panel Outer Compartment Replacement | C2138 | GMNA |
| 1030410 | Instrument Panel Compartment Door Replacement | C2140 | GMNA |
| 1030410 | Instrument Panel Compartment Door Replacement | C2140 | Holden Australia |
| 1030410 | Instrument Panel Compartment Door Replacement | C214000 | Holden Australia |
| 1030410 | Instrument Panel Compartment Door Replacement | C2140 | Holden New Zealand |
| 1030430 | Instrument Panel Compartment Replacement | C2141 | GMNA |
| 1030430 | Instrument Panel Compartment Replacement | C459100 | Holden Australia |
| 1030430 | Instrument Panel Compartment Replacement | C459100 | Holden New Zealand |
| 1030430 | Instrument Panel Compartment Replacement | 9310300 | GMK Overseas |
| 1030430 | Instrument Panel Compartment Replacement | 9310700 | GMK Overseas |
| 1030450 | Instrument Panel Upper Compartment Replacement | C2142 | GMNA |
| 1030450 | Instrument Panel Upper Compartment Replacement | N300700 | Holden New Zealand |
| 1030450 | Instrument Panel Upper Compartment Replacement | 9311500 | GMK Overseas |
| 1030450 | Instrument Panel Upper Compartment Replacement | 9322700 | GMK Overseas |
| 1030470 | Instrument Panel Cluster Lower Compartment Replacement | C2143 | GMNA |
| 1030490 | Instrument Panel Lower Compartment Replacement | C2144 | GMNA |
| 1030510 | Instrument Panel Lower Extension Compartment Replacement | | |
| 1030530 | Instrument Panel Compartment Door Foundation Replacement | C2159 | GMNA |
| 1030610 | Instrument Panel Stowage Tray Replacement | C2080 | GMNA |
| 1030610 | Instrument Panel Stowage Tray Replacement | C2656 | GMNA |
| 1030610 | Instrument Panel Stowage Tray Replacement | C9724 | GMNA |
| 1030610 | Instrument Panel Stowage Tray Replacement | C9752 | GMNA |
| 1030610 | Instrument Panel Stowage Tray Replacement | C402300 | Holden Australia |
| 1030620 | Instrument Panel Compartment Pen Holder Replacement | | |
| 1030630 | Instrument Panel Fuse Block Access Hole Cover Replacement | C2150 | GMNA |
| 1030630 | Instrument Panel Fuse Block Access Hole Cover Replacement | C2190 | GMNA |
| 1030630 | Instrument Panel Fuse Block Access Hole Cover Replacement | 8720102 | GMK Domestic |
| 1030650 | Instrument Panel Ashtray Replacement | C2200 | GMNA |
| 1030650 | Instrument Panel Ashtray Replacement | C2201 | GMNA |
| 1030650 | Instrument Panel Ashtray Replacement | C9908 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1030650 | Instrument Panel Ashtray Replacement | C220000 | Holden Australia |
| 1030650 | Instrument Panel Ashtray Replacement | C457100 | Holden Australia |
| 1030650 | Instrument Panel Ashtray Replacement | C220000 | Holden New Zealand |
| 1030650 | Instrument Panel Ashtray Replacement | C457100 | Holden New Zealand |
| 1030650 | Instrument Panel Ashtray Replacement | 9330500 | GMK Overseas |
| 1030670 | Instrument Panel Air Outlet Bezel Replacement - Right Side | C2202 | GMNA |
| 1030670 | Instrument Panel Air Outlet Bezel Replacement - Right Side | 7110600 | GMK Overseas |
| 1030670 | Instrument Panel Air Outlet Bezel Replacement - Right Side | 7110630 | GMK Overseas |
| 1030670 | Instrument Panel Air Outlet Bezel Replacement - Right Side | 7110640 | GMK Overseas |
| 1030690 | Instrument Panel Air Outlet Bezel Replacement - Left Side | 7110610 | GMK Overseas |
| 1030710 | Instrument Panel Center Air Outlet Bezel Replacement | D1472 | GMNA |
| 1030710 | Instrument Panel Center Air Outlet Bezel Replacement | 7110620 | GMK Overseas |
| 1030730 | Instrument Panel Accessory Bezel Replacement | C2205 | GMNA |
| 1030730 | Instrument Panel Accessory Bezel Replacement | 9320700 | GMK Overseas |
| 1030750 | Instrument Panel Accessory Trim Plate Replacement - Left Side | C2208 | GMNA |
| 1030770 | Instrument Cluster Trim Panel Replacement | C2209 | GMNA |
| 1030790 | Instrument Panel Center Trim Panel Replacement | C2210 | GMNA |
| 1030810 | Instrument Panel Cluster Trim Plate Cover Replacement | C2211 | GMNA |
| 1030830 | Instrument Panel Trim Plate Applique Replacement - Right Side | C2212 | GMNA |
| 1030830 | Instrument Panel Trim Plate Applique Replacement - Right Side | C461410 | Holden Australia |
| 1030830 | Instrument Panel Trim Plate Applique Replacement - Right Side | C461410 | Holden New Zealand |
| 1030850 | Instrument Panel Trim Plate Applique Replacement - Left Side | C2213 | GMNA |
| 1030850 | Instrument Panel Trim Plate Applique Replacement - Left Side | C461420 | Holden Australia |
| 1030850 | Instrument Panel Trim Plate Applique Replacement - Left Side | C462100 | Holden Australia |
| 1030850 | Instrument Panel Trim Plate Applique Replacement - Left Side | C461420 | Holden New Zealand |
| 1030850 | Instrument Panel Trim Plate Applique Replacement - Left Side | C462100 | Holden New Zealand |
| 1030870 | Instrument Panel Center Trim Plate Applique Replacement | C2214 | GMNA |
| 1030890 | Instrument Panel Emblem Replacement | C2040 | GMNA |
| 1030890 | Instrument Panel Emblem Replacement | C2215 | GMNA |
| 1030890 | Instrument Panel Emblem Replacement | C204000 | Holden Australia |
| 1030890 | Instrument Panel Emblem Replacement | C461700 | Holden Australia |
| 1030890 | Instrument Panel Emblem Replacement | C2040 | Holden New Zealand |
| 1030890 | Instrument Panel Emblem Replacement | C461700 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1030910 | Instrument Panel Center Molding Replacement | C2216 | GMNA |
| 1030910 | Instrument Panel Center Molding Replacement | 9324300 | GMK Overseas |
| 1030930 | Instrument Panel Molding Replacement | C2217 | GMNA |
| 1030930 | Instrument Panel Molding Replacement | 9323000 | GMK Overseas |
| 1030950 | Instrument Panel Lower Center Trim Panel Replacement | C2218 | GMNA |
| 1030970 | Instrument Panel Center Compartment Replacement | C2219 | GMNA |
| 1030970 | Instrument Panel Center Compartment Replacement | 9313600 | GMK Overseas |
| 1030980 | Instrument Panel Lower Trim Panel Replacement - Left Side | C2398 | GMNA |
| 1030990 | Instrument Panel Lower Trim Panel Replacement - Right Side | C2397 | GMNA |
| 1031020 | Instrument Panel Trim Plate Retainer Replacement - Right Side | C2221 | GMNA |
| 1031040 | Instrument Panel Trim Plate Retainer Replacement - Left Side | | |
| 1031060 | Instrument Panel Upper Molding Replacement | C2223 | GMNA |
| 1031060 | Instrument Panel Upper Molding Replacement | 9324700 | GMK Overseas |
| 1031080 | Instrument Panel Molding Replacement - Passenger Side | C2224 | GMNA |
| 1031100 | Instrument Panel Molding Replacement - Driver Side | C2225 | GMNA |
| 1031120 | Instrument Panel Lower Molding Replacement | | |
| 1031140 | Instrument Panel Trim Plate Applique Replacement | C2227 | GMNA |
| 1031160 | Instrument Panel Accessory Molding Replacement | C2228 | GMNA |
| 1031180 | Instrument Panel Accessory Upper Trim Plate Replacement | C2230 | GMNA |
| 1031220 | Instrument Panel Accessory Center Trim Plate Replacement | C2232 | GMNA |
| 1031240 | Instrument Panel Lower Extension Accessory Bezel Replacement | C2233 | GMNA |
| 1031250 | Instrument Panel Accessory Trim Pad Replacement | | |
| 1031260 | Instrument Panel Lower Trim Panel Outer Filler Replacement | C2297 | GMNA |
| 1031280 | Instrument Panel Lower Filler Replacement - Right Side | C2298 | GMNA |
| 1031300 | Instrument Panel Lower Filler Replacement - Left Side | C2299 | GMNA |
| 1031320 | Instrument Panel Assist Handle Replacement | C2300 | GMNA |
| 1031340 | Steering Column Opening Lower Filler Replacement | C2306 | GMNA |
| 1031350 | Steering Column Lower Trim Cover Replacement | | |
| 1031360 | Clock Bezel Replacement | C2307 | GMNA |
| 1031380 | Headlamp Switch Bezel Replacement | C2308 | GMNA |
| 1031400 | Headlamp Switch Molding Replacement | C2309 | GMNA |
| 1031450 | Steering Column Opening Filler Replacement | C2311 | GMNA |
| 1031470 | Steering Column Housing Cover Replacement | C2312 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1031470 | Steering Column Housing Cover Replacement | E7025 | GMNA |
| 1031490 | Instrument Panel Cluster Trim Plate Bezel Replacement | C2313 | GMNA |
| 1031510 | Instrument Cluster Housing Replacement | C2314 | GMNA |
| 1031510 | Instrument Cluster Housing Replacement | 6220200 | GMK Domestic |
| 1031560 | Instrument Panel Compartment Trim Plate Replacement | C2316 | GMNA |
| 1031620 | Instrument Panel Accessory Trim Plate Replacement | C2319 | GMNA |
| 1031640 | Instrument Panel Trim Plate Replacement - Right Side | C2320 | GMNA |
| 1031660 | Instrument Panel Trim Plate Replacement - Left Side | C2321 | GMNA |
| 1031680 | Instrument Panel Trim Plate Replacement | C2322 | GMNA |
| 1031690 | Instrument Panel Lower Trim Plate Replacement | C2323 | GMNA |
| 1031700 | Instrument Panel Center Trim Plate Replacement | C2326 | GMNA |
| 1031700 | Instrument Panel Center Trim Plate Replacement | 9330100 | GMK Overseas |
| 1031750 | Instrument Panel Cluster Trim Plate Replacement | C2328 | GMNA |
| 1031750 | Instrument Panel Cluster Trim Plate Replacement | 6141700 | GMK Domestic |
| 1031750 | Instrument Panel Cluster Trim Plate Replacement | C2328 | Holden Australia |
| 1031750 | Instrument Panel Cluster Trim Plate Replacement | 9251300 | GMK Overseas |
| 1031830 | Instrument Panel Cluster Lower Trim Plate Replacement | C2332 | GMNA |
| 1031830 | Instrument Panel Cluster Lower Trim Plate Replacement | 9322600 | GMK Overseas |
| 1031850 | Driver Information Display Bezel Replacement | C2334 | GMNA |
| 1031870 | Instrument Panel Center Upper Molding Replacement | C2335 | GMNA |
| 1031870 | Instrument Panel Center Upper Molding Replacement | 9322800 | GMK Overseas |
| 1031890 | Instrument Panel Upper Molding Replacement - Right Side | C2336 | GMNA |
| 1031910 | Instrument Panel Upper Molding Replacement - Left Side | C2337 | GMNA |
| 1031930 | Instrument Panel Trim Panel Replacement | C2338 | GMNA |
| 1031930 | Instrument Panel Trim Panel Replacement | 9314700 | GMK Overseas |
| 1031950 | Instrument Panel Accessory Trim Plate Switch Hole Cover Replacement | 9321100 | GMK Overseas |
| 1031970 | Radio Opening Cover Replacement | C2329 | GMNA |
| 1031970 | Radio Opening Cover Replacement | C2340 | GMNA |
| 1031970 | Radio Opening Cover Replacement | C9973 | GMNA |
| 1031970 | Radio Opening Cover Replacement | R0720 | GMNA |
| 1031970 | Radio Opening Cover Replacement | C461120 | Holden Australia |
| 1031970 | Radio Opening Cover Replacement | C500500 | Holden Australia |
| 1031970 | Radio Opening Cover Replacement | C500700 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1031970 | Radio Opening Cover Replacement | C500800 | Holden Australia |
| 1031970 | Radio Opening Cover Replacement | D333150 | Holden Australia |
| 1031970 | Radio Opening Cover Replacement | C461120 | Holden New Zealand |
| 1031970 | Radio Opening Cover Replacement | C500500 | Holden New Zealand |
| 1031970 | Radio Opening Cover Replacement | C500700 | Holden New Zealand |
| 1031970 | Radio Opening Cover Replacement | C500800 | Holden New Zealand |
| 1031970 | Radio Opening Cover Replacement | D333150 | Holden New Zealand |
| 1031970 | Radio Opening Cover Replacement | 9283110 | GMK Overseas |
| 1031980 | Audio Disc Player and USB Receptacle Opening Cover Replacement | | |
| 1031990 | Instrument Panel Upper Trim Panel Replacement - Left Side | C2341 | GMNA |
| 1031990 | Instrument Panel Upper Trim Panel Replacement - Left Side | 8713200 | GMK Domestic |
| 1031990 | Instrument Panel Upper Trim Panel Replacement - Left Side | 9322400 | GMK Overseas |
| 1032010 | Instrument Panel Upper Trim Panel Replacement - Right Side | C2342 | GMNA |
| 1032030 | Instrument Panel Cluster Trim Plate Applique Replacement | C2343 | GMNA |
| 1032050 | Instrument Panel Upper Trim Plate Replacement | | |
| 1032070 | Instrument Panel Accessory Trim Plate Grille Replacement | | |
| 1032090 | Instrument Panel Upper Trim Pad Insert Replacement | C2347 | GMNA |
| 1032090 | Instrument Panel Upper Trim Pad Insert Replacement | 8661300 | GMK Domestic |
| 1032110 | Instrument Panel Upper Outer Trim Panel Replacement - Right Side | C2352 | GMNA |
| 1032130 | Instrument Panel Upper Outer Trim Panel Replacement - Left Side | C2353 | GMNA |
| 1032150 | Instrument Panel Upper Outer Trim Panel Replacement | C2354 | GMNA |
| 1032170 | Instrument Panel Outer Trim Cover Replacement | A7359 | GMNA |
| 1032170 | Instrument Panel Outer Trim Cover Replacement | A7419 | GMNA |
| 1032170 | Instrument Panel Outer Trim Cover Replacement | A7420 | GMNA |
| 1032170 | Instrument Panel Outer Trim Cover Replacement | C2355 | GMNA |
| 1032170 | Instrument Panel Outer Trim Cover Replacement | C9790 | GMNA |
| 1032190 | Instrument Panel Side Trim Panel Replacement | C2356 | GMNA |
| 1032190 | Instrument Panel Side Trim Panel Replacement | 9311100 | GMK Overseas |
| 1032190 | Instrument Panel Side Trim Panel Replacement | 9311200 | GMK Overseas |
| 1032210 | Instrument Panel Compartment Access Hole Cover Replacement | C2357 | GMNA |
| 1032230 | Instrument Panel Outer Trim Cover Replacement - Left Side | C2358 | GMNA |
| 1032230 | Instrument Panel Outer Trim Cover Replacement - Left Side | C461300 | Holden Australia |
| 1032230 | Instrument Panel Outer Trim Cover Replacement - Left Side | C461300 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1032250 | Instrument Panel Outer Trim Cover Replacement - Right Side | C2359 | GMNA |
| 1032250 | Instrument Panel Outer Trim Cover Replacement - Right Side | C461200 | Holden Australia |
| 1032250 | Instrument Panel Outer Trim Cover Replacement - Right Side | C461200 | Holden New Zealand |
| 1032270 | Instrument Panel Lower Trim Panel Replacement | C2360 | GMNA |
| 1032270 | Instrument Panel Lower Trim Panel Replacement | R993074 | Holden New Zealand |
| 1032290 | Instrument Panel Upper Center Trim Panel Replacement | C2363 | GMNA |
| 1032310 | Instrument Panel Upper Trim Cover Replacement | C2361 | GMNA |
| 1032310 | Instrument Panel Upper Trim Cover Replacement | C2364 | GMNA |
| 1032310 | Instrument Panel Upper Trim Cover Replacement | C9884 | GMNA |
| 1032310 | Instrument Panel Upper Trim Cover Replacement | C236100 | Holden Australia |
| 1032310 | Instrument Panel Upper Trim Cover Replacement | C461600 | Holden Australia |
| 1032310 | Instrument Panel Upper Trim Cover Replacement | C236100 | Holden New Zealand |
| 1032310 | Instrument Panel Upper Trim Cover Replacement | C461600 | Holden New Zealand |
| 1032330 | Head-Up Display Bezel Replacement | C2365 | GMNA |
| 1032380 | Instrument Panel Upper Trim Panel with Windshield Defroster Nozzle Grille Replacement | C2369 | GMNA |
| 1032380 | Instrument Panel Upper Trim Panel with Windshield Defroster Nozzle Grille Replacement | D1407 | GMNA |
| 1032380 | Instrument Panel Upper Trim Panel with Windshield Defroster Nozzle Grille Replacement | D1408 | GMNA |
| 1032390 | Windshield Defroster Nozzle Grille Replacement | 9312100 | GMK Overseas |
| 1032390 | Windshield Defroster Nozzle Grille Replacement | 9312200 | GMK Overseas |
| 1032390 | Windshield Defroster Nozzle Grille Replacement | 9312300 | GMK Overseas |
| 1032390 | Windshield Defroster Nozzle Grille Replacement | 9312600 | GMK Overseas |
| 1032390 | Windshield Defroster Nozzle Grille Replacement | 9312700 | GMK Overseas |
| 1032390 | Windshield Defroster Nozzle Grille Replacement | 9314200 | GMK Overseas |
| 1032400 | Inflatable Restraint Instrument Panel Module Trim Cover Replacement | C2376 | GMNA |
| 1032400 | Inflatable Restraint Instrument Panel Module Trim Cover Replacement | 9313200 | GMK Overseas |
| 1032420 | Instrument Panel Trim Panel Replacement - Left Side | C2393 | GMNA |
| 1032440 | Instrument Panel Trim Panel Replacement - Right Side | C2394 | GMNA |
| 1032460 | Instrument Panel Lower Extension Side Trim Panel Replacement | C2395 | GMNA |
| 1032460 | Instrument Panel Lower Extension Side Trim Panel Replacement | 9324100 | GMK Overseas |
| 1032460 | Instrument Panel Lower Extension Side Trim Panel Replacement | 9324200 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1032480 | Instrument Panel Lower Extension Compartment Panel Replacement | C2396 | GMNA |
| 1032540 | Instrument Panel Lower Extension Replacement | C2399 | GMNA |
| 1032590 | Instrument Panel Extension Replacement | C2401 | GMNA |
| 1032610 | Instrument Panel Lower Extension Tray Replacement | C2402 | GMNA |
| 1032630 | Instrument Panel Lower Center Compartment Replacement | | |
| 1032640 | Instrument Panel Lower Center Compartment Liner Replacement | | |
| 1032650 | Instrument Panel Lower Extension Trim Panel Replacement | C2404 | GMNA |
| 1032650 | Instrument Panel Lower Extension Trim Panel Replacement | 9315200 | GMK Overseas |
| 1032670 | Instrument Panel Lower Trim Panel Insulator Replacement | C2419 | GMNA |
| 1032670 | Instrument Panel Lower Trim Panel Insulator Replacement | C2420 | GMNA |
| 1032710 | Instrument Panel Insulator Panel Replacement - Left Side | C2421 | GMNA |
| 1032730 | Instrument Panel Insulator Panel Replacement | C2427 | GMNA |
| 1032740 | Instrument Panel Knee Bolster Compartment Replacement | | |
| 1032860 | Instrument Panel Insulator Seal Replacement | C2433 | GMNA |
| 1032860 | Instrument Panel Insulator Seal Replacement | 9314500 | GMK Overseas |
| 1032910 | Instrument Cluster Upper Bezel Replacement | C2457 | GMNA |
| 1032930 | Instrument Panel Instrument Cluster Hood Replacement | C2458 | GMNA |
| 1032950 | Instrument Cluster Housing Hood Replacement | C2459 | GMNA |
| 1032970 | Instrument Panel Compartment Inner Panel Replacement | C2461 | GMNA |
| 1032990 | Instrument Panel Carrier Replacement | C2465 | GMNA |
| 1032990 | Instrument Panel Carrier Replacement | C2550 | GMNA |
| 1032990 | Instrument Panel Carrier Replacement | C000689 | Holden Australia |
| 1033010 | Lower Trim Pad Retainer Replacement | C2466 | GMNA |
| 1033030 | Instrument Panel Retainer Replacement | C2467 | GMNA |
| 1033030 | Instrument Panel Retainer Replacement | 9314800 | GMK Overseas |
| 1033050 | Upper Trim Pad Retainer Replacement | C2468 | GMNA |
| 1033060 | Instrument Panel Knee Bolster Replacement | C8830 | GMNA |
| 1033070 | Instrument Panel Lower Trim Pad Cover Replacement | C2480 | GMNA |
| 1033070 | Instrument Panel Lower Trim Pad Cover Replacement | C2481 | GMNA |
| 1033070 | Instrument Panel Lower Trim Pad Cover Replacement | J7927 | GMNA |
| 1033070 | Instrument Panel Lower Trim Pad Cover Replacement | N2967 | GMNA |
| 1033070 | Instrument Panel Lower Trim Pad Cover Replacement | C456700 | Holden Australia |
| 1033070 | Instrument Panel Lower Trim Pad Cover Replacement | C456800 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1033070 | Instrument Panel Lower Trim Pad Cover Replacement | C461800 | Holden Australia |
| 1033070 | Instrument Panel Lower Trim Pad Cover Replacement | C461810 | Holden Australia |
| 1033070 | Instrument Panel Lower Trim Pad Cover Replacement | C456700 | Holden New Zealand |
| 1033070 | Instrument Panel Lower Trim Pad Cover Replacement | C456800 | Holden New Zealand |
| 1033070 | Instrument Panel Lower Trim Pad Cover Replacement | C461800 | Holden New Zealand |
| 1033070 | Instrument Panel Lower Trim Pad Cover Replacement | C461810 | Holden New Zealand |
| 1033070 | Instrument Panel Lower Trim Pad Cover Replacement | C462720 | Holden New Zealand |
| 1033070 | Instrument Panel Lower Trim Pad Cover Replacement | C463100 | Holden New Zealand |
| 1033080 | Instrument Panel Trim Panel Replacement - Center | | |
| 1033090 | Instrument Panel Lower Trim Pad Replacement | A7360 | GMNA |
| 1033090 | Instrument Panel Lower Trim Pad Replacement | A7430 | GMNA |
| 1033090 | Instrument Panel Lower Trim Pad Replacement | C2499 | GMNA |
| 1033090 | Instrument Panel Lower Trim Pad Replacement | C9841 | GMNA |
| 1033090 | Instrument Panel Lower Trim Pad Replacement | C9887 | GMNA |
| 1033090 | Instrument Panel Lower Trim Pad Replacement | R9807 | GMNA |
| 1033090 | Instrument Panel Lower Trim Pad Replacement | T6716 | GMNA |
| 1033090 | Instrument Panel Lower Trim Pad Replacement | C464100 | Holden Australia |
| 1033090 | Instrument Panel Lower Trim Pad Replacement | C464100 | Holden New Zealand |
| 1033090 | Instrument Panel Lower Trim Pad Replacement | 9311400 | GMK Overseas |
| 1033110 | Instrument Panel Trim Pad Replacement | C2500 | GMNA |
| 1033110 | Instrument Panel Trim Pad Replacement | C247500 | Holden Australia |
| 1033110 | Instrument Panel Trim Pad Replacement | C250000 | Holden Australia |
| 1033110 | Instrument Panel Trim Pad Replacement | C2475 | Holden New Zealand |
| 1033110 | Instrument Panel Trim Pad Replacement | C247500 | Holden New Zealand |
| 1033110 | Instrument Panel Trim Pad Replacement | C248000 | Holden New Zealand |
| 1033110 | Instrument Panel Trim Pad Replacement | C2500 | Holden New Zealand |
| 1033110 | Instrument Panel Trim Pad Replacement | C250000 | Holden New Zealand |
| 1033130 | Instrument Panel Upper Trim Pad Replacement | C2501 | GMNA |
| 1033150 | Instrument Panel Cluster Trim Pad Replacement | C2502 | GMNA |
| 1033170 | Instrument Panel Upper Trim Pad Bezel Replacement | C2503 | GMNA |
| 1033190 | Instrument Panel Trim Pad Radio Center Speaker Opening Cover Replacement | | |
| 1033250 | Instrument Panel Assembly Replacement | C2460 | GMNA |
| 1033250 | Instrument Panel Assembly Replacement | C2512 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1033250 | Instrument Panel Assembly Replacement | C2520 | GMNA |
| 1033250 | Instrument Panel Assembly Replacement | C2539 | GMNA |
| 1033250 | Instrument Panel Assembly Replacement | C2545 | GMNA |
| 1033250 | Instrument Panel Assembly Replacement | C9713 | GMNA |
| 1033250 | Instrument Panel Assembly Replacement | C9757 | GMNA |
| 1033250 | Instrument Panel Assembly Replacement | C9783 | GMNA |
| 1033250 | Instrument Panel Assembly Replacement | C9931 | GMNA |
| 1033250 | Instrument Panel Assembly Replacement | C9936 | GMNA |
| 1033250 | Instrument Panel Assembly Replacement | 8661100 | GMK Domestic |
| 1033250 | Instrument Panel Assembly Replacement | A000276 | Holden Australia |
| 1033250 | Instrument Panel Assembly Replacement | C2539 | Holden Australia |
| 1033250 | Instrument Panel Assembly Replacement | C461100 | Holden Australia |
| 1033250 | Instrument Panel Assembly Replacement | S531000 | Holden Australia |
| 1033250 | Instrument Panel Assembly Replacement | A000276 | Holden New Zealand |
| 1033250 | Instrument Panel Assembly Replacement | C461100 | Holden New Zealand |
| 1033250 | Instrument Panel Assembly Replacement | S531000 | Holden New Zealand |
| 1033250 | Instrument Panel Assembly Replacement | 9310900 | GMK Overseas |
| 1033250 | Instrument Panel Assembly Replacement | 931090A | GMK Overseas |
| 1033260 | Passenger Knee Bolster Replacement | C2542 | GMNA |
| 1033260 | Passenger Knee Bolster Replacement | C8833 | GMNA |
| 1033270 | Instrument Panel Upper Trim Panel Replacement | C2362 | GMNA |
| 1033270 | Instrument Panel Upper Trim Panel Replacement | 9321200 | GMK Overseas |
| 1033280 | Driver Knee Bolster Replacement | C2543 | GMNA |
| 1033300 | Driver Knee Bolster Panel Replacement | C2544 | GMNA |
| 1033300 | Driver Knee Bolster Panel Replacement | 9312400 | GMK Overseas |
| 1033300 | Driver Knee Bolster Panel Replacement | 9312500 | GMK Overseas |
| 1033320 | Automatic or Manual Transmission Control Lever Trim Cover Replacement | C2546 | GMNA |
| 1033320 | Automatic or Manual Transmission Control Lever Trim Cover Replacement | C9782 | GMNA |
| 1033320 | Automatic or Manual Transmission Control Lever Trim Cover Replacement | 9342100 | GMK Overseas |
| 1033320 | Automatic or Manual Transmission Control Lever Trim Cover Replacement | 9342400 | GMK Overseas |
| 1033360 | Front Floor Console Armrest Hinge Cover Replacement | C2698 | GMNA |
| 1033370 | Instrument Panel Compartment Door Opening Frame Replacement | C2699 | GMNA |
| 1033370 | Instrument Panel Compartment Door Opening Frame Replacement | 9314100 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1033390 | Front Floor Console Compartment Door Lock Replacement | C2700 | GMNA |
| 1033390 | Front Floor Console Compartment Door Lock Replacement | C000728 | Holden New Zealand |
| 1033410 | Front Floor Console Armrest Compartment Replacement | C2701 | GMNA |
| 1033430 | Front Floor Console Armrest with Support Replacement | C2702 | GMNA |
| 1033520 | Front Floor Console Compartment Door Panel Replacement | C2706 | GMNA |
| 1033540 | Folding Top Stowage Compartment Lid Replacement | C2707 | GMNA |
| 1033560 | Front Floor Rear Console Armrest Latch Replacement | C2708 | GMNA |
| 1033580 | Front Floor Console Armrest Latch Replacement | C2709 | GMNA |
| 1033580 | Front Floor Console Armrest Latch Replacement | C9836 | GMNA |
| 1033580 | Front Floor Console Armrest Latch Replacement | C9935 | GMNA |
| 1033630 | Front Floor Console Compartment Door Latch Replacement | C2711 | GMNA |
| 1033630 | Front Floor Console Compartment Door Latch Replacement | C9702 | GMNA |
| 1033630 | Front Floor Console Compartment Door Latch Replacement | C9760 | GMNA |
| 1033630 | Front Floor Console Compartment Door Latch Replacement | C9952 | GMNA |
| 1033630 | Front Floor Console Compartment Door Latch Replacement | 9331200 | GMK Overseas |
| 1033650 | Front Floor Console Armrest Hinge Replacement | C2712 | GMNA |
| 1033670 | Front Floor Console Compartment Door Replacement | C2713 | GMNA |
| 1033710 | Front Floor Console Front Compartment Replacement | C2719 | GMNA |
| 1033730 | Front Floor Console Compartment Door Hinge Replacement | C2720 | GMNA |
| 1033730 | Front Floor Console Compartment Door Hinge Replacement | C2720 | Holden Australia |
| 1033730 | Front Floor Console Compartment Door Hinge Replacement | 9331400 | GMK Overseas |
| 1033750 | Front Floor Console Rear Cover Replacement | C2721 | GMNA |
| 1033750 | Front Floor Console Rear Cover Replacement | 8712600 | GMK Domestic |
| 1033750 | Front Floor Console Rear Cover Replacement | C474100 | Holden Australia |
| 1033750 | Front Floor Console Rear Cover Replacement | C474200 | Holden Australia |
| 1033750 | Front Floor Console Rear Cover Replacement | C474100 | Holden New Zealand |
| 1033750 | Front Floor Console Rear Cover Replacement | C474200 | Holden New Zealand |
| 1033750 | Front Floor Console Rear Cover Replacement | 9342700 | GMK Overseas |
| 1033770 | Front Floor Console Accessory Trim Plate Applique Replacement | C2722 | GMNA |
| 1033790 | Front Floor Console Cover Replacement | C2723 | GMNA |
| 1033790 | Front Floor Console Cover Replacement | 8712400 | GMK Domestic |
| 1033800 | Front Floor Console Bolt Access Hole Cover Replacement | | |
| 1033810 | Front Floor Console Transmission Shift Opening Trim Plate Replacement | C2724 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1033830 | Front Floor Console Trim Plate Replacement | C2725 | GMNA |
| 1033850 | Front Floor Console Applique Replacement | C2726 | GMNA |
| 1033850 | Front Floor Console Applique Replacement | C2780 | GMNA |
| 1033870 | Front Floor Console Cover Trim Plate Replacement - Left Side | C2727 | GMNA |
| 1033890 | Front Floor Console Cover Trim Plate Replacement - Right Side | C2728 | GMNA |
| 1033890 | Front Floor Console Cover Trim Plate Replacement - Right Side | 9331600 | GMK Overseas |
| 1033910 | Front Floor Console Rear Trim Panel Replacement - Upper | C2729 | GMNA |
| 1033930 | Front Floor Console Rear Trim Panel Replacement - Lower | C2730 | GMNA |
| 1033970 | Front Floor Lower Console Side Finish Cover Replacement - Right Side | C2732 | GMNA |
| 1033970 | Front Floor Lower Console Side Finish Cover Replacement - Right Side | C2733 | GMNA |
| 1033990 | Front Floor Lower Console Side Finish Cover Replacement - Left Side | | |
| 1034010 | Front Floor Console Extension Accessory Upper Bezel Replacement | C2734 | GMNA |
| 1034030 | Front Floor Console Filler Replacement | C2735 | GMNA |
| 1034050 | Front Floor Console Extension Panel Replacement | C2736 | GMNA |
| 1034070 | Front Floor Console Side Trim Panel Replacement - Right Side | C2738 | GMNA |
| 1034090 | Front Floor Console Side Trim Panel Replacement - Left Side | C2739 | GMNA |
| 1034290 | Front Floor Console Cup Holder Latch Replacement | C2748 | GMNA |
| 1034290 | Front Floor Console Cup Holder Latch Replacement | 9331700 | GMK Overseas |
| 1034310 | Instrument Panel Cup Holder Track Replacement | C2749 | GMNA |
| 1034330 | Front Floor Console Armrest Replacement | C2750 | GMNA |
| 1034330 | Front Floor Console Armrest Replacement | C474400 | Holden Australia |
| 1034330 | Front Floor Console Armrest Replacement | C474400 | Holden New Zealand |
| 1034330 | Front Floor Console Armrest Replacement | 9342600 | GMK Overseas |
| 1034340 | Front Floor Console Cup Holder Replacement | C2751 | GMNA |
| 1034350 | Front Floor Console Cup Holder Housing Replacement | C2754 | GMNA |
| 1034350 | Front Floor Console Cup Holder Housing Replacement | 9343900 | GMK Overseas |
| 1034360 | Front Floor Console Cup Holder Insert Replacement | | |
| 1034400 | Front Floor Console Accessory Housing Replacement | C2756 | GMNA |
| 1034420 | Front Floor Console Rear Cup Holder Replacement | C2757 | GMNA |
| 1034420 | Front Floor Console Rear Cup Holder Replacement | C457400 | Holden Australia |
| 1034480 | Front Floor Console Front Cup Holder Replacement | C2761 | GMNA |
| 1034540 | Front Floor Console Stowage Tray Replacement | C2765 | GMNA |
| 1034540 | Front Floor Console Stowage Tray Replacement | 9314600 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1034560 | Instrument Panel Ashtray Housing Replacement | C2767 | GMNA |
| 1034560 | Instrument Panel Ashtray Housing Replacement | 9341440 | GMK Overseas |
| 1034610 | Ashtray Side Panel Replacement | C2769 | GMNA |
| 1034630 | Front Floor Console Front Ashtray Replacement | C2770 | GMNA |
| 1034630 | Front Floor Console Front Ashtray Replacement | C9838 | GMNA |
| 1034630 | Front Floor Console Front Ashtray Replacement | 8670600 | GMK Domestic |
| 1034630 | Front Floor Console Front Ashtray Replacement | C457200 | Holden Australia |
| 1034630 | Front Floor Console Front Ashtray Replacement | C457200 | Holden New Zealand |
| 1034630 | Front Floor Console Front Ashtray Replacement | 9313100 | GMK Overseas |
| 1034630 | Front Floor Console Front Ashtray Replacement | 9341400 | GMK Overseas |
| 1034650 | Front Floor Console Cup Holder Door Replacement | C2771 | GMNA |
| 1034670 | Front Floor Console Cup Holder Cover Track Replacement | C2772 | GMNA |
| 1034690 | Front Floor Console Rear Ashtray Replacement | C2773 | GMNA |
| 1034690 | Front Floor Console Rear Ashtray Replacement | 8670800 | GMK Domestic |
| 1034690 | Front Floor Console Rear Ashtray Replacement | 9341300 | GMK Overseas |
| 1034710 | Front Floor Console Rail Replacement | S5110 | GMNA |
| 1034710 | Front Floor Console Rail Replacement | S5111 | GMNA |
| 1034710 | Front Floor Console Rail Replacement | A500300 | Holden Australia |
| 1034730 | Front Floor Console Extension Replacement - Center | C2776 | GMNA |
| 1034750 | Front Floor Console Extension Replacement - Side | C2777 | GMNA |
| 1034770 | Front Floor Console Extension Replacement | C2778 | GMNA |
| 1034770 | Front Floor Console Extension Replacement | C474500 | Holden Australia |
| 1034770 | Front Floor Console Extension Replacement | C474600 | Holden Australia |
| 1034770 | Front Floor Console Extension Replacement | C474500 | Holden New Zealand |
| 1034770 | Front Floor Console Extension Replacement | C474600 | Holden New Zealand |
| 1034790 | Automatic Transmission Control Indicator Opening Cover Replacement | C2779 | GMNA |
| 1034810 | Front Floor Console Armrest Stowage Tray Replacement | C2781 | GMNA |
| 1034830 | Front Floor Console Transmission Shift Opening Bezel Replacement | C2782 | GMNA |
| 1034830 | Front Floor Console Transmission Shift Opening Bezel Replacement | 5191100 | GMK Overseas |
| 1034830 | Front Floor Console Transmission Shift Opening Bezel Replacement | 5270500 | GMK Overseas |
| 1034850 | Automatic Transmission Control Opening Cover Bezel Replacement | C2783 | GMNA |
| 1034870 | Floor Panel Transmission Control Opening Cover Replacement | C2784 | GMNA |
| 1034920 | Front Floor Console Accessory Trim Plate Replacement | C2786 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1034940 | Front Floor Front Console Accessory Trim Bezel Replacement | C2787 | GMNA |
| 1034960 | Front Floor Upper Console Trim Plate Replacement | C2789 | GMNA |
| 1034960 | Front Floor Upper Console Trim Plate Replacement | C9915 | GMNA |
| 1034960 | Front Floor Upper Console Trim Plate Replacement | C000653 | Holden Australia |
| 1034960 | Front Floor Upper Console Trim Plate Replacement | C000653 | Holden New Zealand |
| 1034980 | Front Floor Console Trim Panel Replacement | C2790 | GMNA |
| 1034980 | Front Floor Console Trim Panel Replacement | 9340100 | GMK Overseas |
| 1034980 | Front Floor Console Trim Panel Replacement | 9340200 | GMK Overseas |
| 1035000 | Front Floor Console Compartment Bezel Replacement | C2791 | GMNA |
| 1035040 | Parking Brake Lever Boot Replacement | C2795 | GMNA |
| 1035060 | Front Floor Console Side Cover Replacement | C2819 | GMNA |
| 1035080 | Front Floor Console Side Cover Replacement - Right Side | C2820 | GMNA |
| 1035080 | Front Floor Console Side Cover Replacement - Right Side | 8617600 | GMK Domestic |
| 1035080 | Front Floor Console Side Cover Replacement - Right Side | 8713002 | GMK Domestic |
| 1035080 | Front Floor Console Side Cover Replacement - Right Side | C474510 | Holden Australia |
| 1035080 | Front Floor Console Side Cover Replacement - Right Side | 9341600 | GMK Overseas |
| 1035080 | Front Floor Console Side Cover Replacement - Right Side | 9341610 | GMK Overseas |
| 1035080 | Front Floor Console Side Cover Replacement - Right Side | 9341620 | GMK Overseas |
| 1035080 | Front Floor Console Side Cover Replacement - Right Side | 9341800 | GMK Overseas |
| 1035100 | Front Floor Console Side Cover Replacement - Left Side | C2821 | GMNA |
| 1035100 | Front Floor Console Side Cover Replacement - Left Side | C474520 | Holden Australia |
| 1035120 | Front Floor Console Side Rear Cover Replacement - Right Side | C2824 | GMNA |
| 1035140 | Front Floor Console Side Rear Cover Replacement - Left Side | C2825 | GMNA |
| 1035160 | Front Floor Console Side Trim Front Panel Replacement - Right Side | C2826 | GMNA |
| 1035180 | Front Floor Console Side Trim Front Panel Replacement - Left Side | C2827 | GMNA |
| 1035200 | Front Floor Console Front Cover Replacement | C2841 | GMNA |
| 1035250 | Front Floor Console Rear Trim Panel Replacement | C2843 | GMNA |
| 1035270 | Front Floor Rear Upper Console Replacement | C2844 | GMNA |
| 1035290 | Front Floor Lower Console Replacement | C2845 | GMNA |
| 1035310 | Front Floor Front Console Replacement | C2846 | GMNA |
| 1035330 | Front Floor Console Carrier Replacement | C2847 | GMNA |
| 1035350 | Front Floor Rear Console Replacement | C2848 | GMNA |
| 1035370 | Front Floor Rear Console Front Cover Replacement | C2763 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1035370 | Front Floor Rear Console Front Cover Replacement | C2849 | GMNA |
| 1035380 | Front Floor Console Center Compartment Replacement | | |
| 1035390 | Front Floor Console Rear Compartment Door Replacement | C2857 | GMNA |
| 1035410 | Front Floor Console Rear Compartment Replacement | C2858 | GMNA |
| 1035430 | Front Floor Console Compartment Replacement | C2743 | GMNA |
| 1035430 | Front Floor Console Compartment Replacement | C2859 | GMNA |
| 1035430 | Front Floor Console Compartment Replacement | 8711800 | GMK Domestic |
| 1035430 | Front Floor Console Compartment Replacement | C457250 | Holden Australia |
| 1035430 | Front Floor Console Compartment Replacement | C457500 | Holden Australia |
| 1035430 | Front Floor Console Compartment Replacement | C457500 | Holden New Zealand |
| 1035430 | Front Floor Console Compartment Replacement | 9342500 | GMK Overseas |
| 1035440 | Front Floor Console Compartment Trim Plate Replacement | | |
| 1035450 | Front Floor Console Replacement | C2042 | GMNA |
| 1035450 | Front Floor Console Replacement | C2744 | GMNA |
| 1035450 | Front Floor Console Replacement | C2860 | GMNA |
| 1035450 | Front Floor Console Replacement | R5500 | GMNA |
| 1035450 | Front Floor Console Replacement | C2860 | Holden Australia |
| 1035450 | Front Floor Console Replacement | C286000 | Holden Australia |
| 1035450 | Front Floor Console Replacement | C474000 | Holden Australia |
| 1035450 | Front Floor Console Replacement | C2860 | Holden New Zealand |
| 1035450 | Front Floor Console Replacement | C286000 | Holden New Zealand |
| 1035450 | Front Floor Console Replacement | C474000 | Holden New Zealand |
| 1035450 | Front Floor Console Replacement | 5370700 | GMK Overseas |
| 1035450 | Front Floor Console Replacement | 9341100 | GMK Overseas |
| 1035470 | Front Side Door Window and Rear Side Door Window Switch Bezel Replacement | C2861 | GMNA |
| 1035580 | Roof Console Replacement | C2870 | GMNA |
| 1035580 | Roof Console Replacement | 5321600 | GMK Domestic |
| 1035580 | Roof Console Replacement | 9720700 | GMK Overseas |
| 1035600 | Roof Console Reading Lamp Bezel Replacement | C2872 | GMNA |
| 1035610 | Roof Console Accessory Switch Trim Plate Replacement | | |
| 1035620 | Roof Rear Console Replacement | C2877 | GMNA |
| 1035630 | Roof Console Opening Trim Plate Replacement | | |
| 1035640 | Roof Rail Front Stowage Compartment Replacement | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1035650 | Rear Floor Console Replacement | C2823 | GMNA |
| 1035650 | Rear Floor Console Replacement | C3580 | GMNA |
| 1035650 | Rear Floor Console Replacement | C3955 | GMNA |
| 1035650 | Rear Floor Console Replacement | C474050 | Holden Australia |
| 1035650 | Rear Floor Console Replacement | C474050 | Holden New Zealand |
| 1035650 | Rear Floor Console Replacement | 5040100 | GMK Overseas |
| 1035650 | Rear Floor Console Replacement | 9340400 | GMK Overseas |
| 1035650 | Rear Floor Console Replacement | 9340500 | GMK Overseas |
| 1035660 | Rear Floor Lower Console Replacement | | |
| 1035680 | Rear Floor Console Front Trim Panel Replacement | C3956 | GMNA |
| 1035690 | Rear Floor Console Armrest Latch Replacement | C3963 | GMNA |
| 1035700 | Rear Floor Console Latch Cover Replacement | C3957 | GMNA |
| 1035720 | Rear Floor Console Rear Release Latch Replacement | C3958 | GMNA |
| 1035730 | Rear Floor Console Side Trim Panel Replacement - Right Side | C3965 | GMNA |
| 1035750 | Rear Floor Console Side Trim Panel Replacement - Left Side | C3966 | GMNA |
| 1035770 | Rear Floor Console Armrest Replacement | C2800 | GMNA |
| 1035770 | Rear Floor Console Armrest Replacement | C3967 | GMNA |
| 1035770 | Rear Floor Console Armrest Replacement | C000559 | Holden Australia |
| 1035770 | Rear Floor Console Armrest Replacement | C000559 | Holden New Zealand |
| 1035790 | Rear Floor Console Rear Trim Upper Panel Replacement | C3968 | GMNA |
| 1035800 | Rear Floor Console Cover Replacement | C3959 | GMNA |
| 1035800 | Rear Floor Console Cover Replacement | 8700120 | GMK Domestic |
| 1035800 | Rear Floor Console Cover Replacement | 8711100 | GMK Domestic |
| 1035800 | Rear Floor Console Cover Replacement | C474510 | Holden New Zealand |
| 1035800 | Rear Floor Console Cover Replacement | C474520 | Holden New Zealand |
| 1035800 | Rear Floor Console Cover Replacement | 9331100 | GMK Overseas |
| 1035810 | Rear Floor Console Stowage Tray Replacement | C3969 | GMNA |
| 1035810 | Rear Floor Console Stowage Tray Replacement | C401110 | Holden Australia |
| 1035830 | Rear Floor Console Front Trim Upper Panel Replacement | C3970 | GMNA |
| 1035850 | Rear Floor Console Cup Holder Trim Upper Panel Replacement | C3971 | GMNA |
| 1035870 | Rear Floor Console Rear Trim Lower Panel Replacement | C3972 | GMNA |
| 1035890 | Rear Floor Console Cup Holder Bezel Replacement | C3973 | GMNA |
| 1035890 | Rear Floor Console Cup Holder Bezel Replacement | C9781 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1035910 | Rear Floor Console Release Latch Replacement | C3974 | GMNA |
| 1035930 | Automatic Transmission Control Indicator Bezel Replacement | K5102 | GMNA |
| 1035930 | Automatic Transmission Control Indicator Bezel Replacement | 2613700 | GMK Domestic |
| 1035930 | Automatic Transmission Control Indicator Bezel Replacement | 5490500 | GMK Overseas |
| 1040010 | Body Side Air Outlet Deflector Replacement | B6303 | GMNA |
| 1040030 | Pressure Relief Valve Replacement | | |
| 1040080 | Quarter Outer Panel Pressure Relief Valve Replacement | 9573200 | GMK Overseas |
| 1040080 | Quarter Outer Panel Pressure Relief Valve Replacement | 9575200 | GMK Overseas |
| 1040150 | Windshield Side Garnish Molding Replacement | C2000 | GMNA |
| 1040150 | Windshield Side Garnish Molding Replacement | C2000 | Holden Australia |
| 1040150 | Windshield Side Garnish Molding Replacement | C623400 | Holden Australia |
| 1040150 | Windshield Side Garnish Molding Replacement | C623400 | Holden New Zealand |
| 1040150 | Windshield Side Garnish Molding Replacement | 9381600 | GMK Overseas |
| 1040150 | Windshield Side Garnish Molding Replacement | 9383600 | GMK Overseas |
| 1040150 | Windshield Side Garnish Molding Replacement | 9383700 | GMK Overseas |
| 1040200 | Windshield Garnish Molding Replacement | C9879 | GMNA |
| 1040200 | Windshield Garnish Molding Replacement | C9885 | GMNA |
| 1040200 | Windshield Garnish Molding Replacement | C623450 | Holden Australia |
| 1040200 | Windshield Garnish Molding Replacement | C623450 | Holden New Zealand |
| 1040200 | Windshield Garnish Molding Replacement | 9381620 | GMK Overseas |
| 1040200 | Windshield Garnish Molding Replacement | 9381630 | GMK Overseas |
| 1040220 | Windshield Upper Garnish Molding Replacement | C2006 | GMNA |
| 1040330 | Inside Rearview Mirror Mount Plate Cover Replacement | 9721200 | GMK Overseas |
| 1040350 | Roof Front Header Garnish Molding Replacement - Upper | C2013 | GMNA |
| 1040370 | Roof Front Header Garnish Molding Replacement - Lower | C2014 | GMNA |
| 1040390 | Sunshade Replacement | C2020 | GMNA |
| 1040390 | Sunshade Replacement | C2028 | GMNA |
| 1040390 | Sunshade Replacement | C2029 | GMNA |
| 1040390 | Sunshade Replacement | 8648800 | GMK Domestic |
| 1040390 | Sunshade Replacement | C2020 | Holden Australia |
| 1040390 | Sunshade Replacement | C402100 | Holden Australia |
| 1040390 | Sunshade Replacement | C402100 | Holden New Zealand |
| 1040390 | Sunshade Replacement | 9720100 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1040390 | Sunshade Replacement | 9720200 | GMK Overseas |
| 1040410 | Sunshade Support Replacement | C2030 | GMNA |
| 1040410 | Sunshade Support Replacement | C402200 | Holden Australia |
| 1040410 | Sunshade Support Replacement | 9720300 | GMK Overseas |
| 1040410 | Sunshade Support Replacement | 9720400 | GMK Overseas |
| 1040410 | Sunshade Support Replacement | 9720500 | GMK Overseas |
| 1040570 | Body Hinge Pillar Trim Panel Replacement | C2600 | GMNA |
| 1040570 | Body Hinge Pillar Trim Panel Replacement | 8641200 | GMK Domestic |
| 1040570 | Body Hinge Pillar Trim Panel Replacement | 9382100 | GMK Overseas |
| 1040570 | Body Hinge Pillar Trim Panel Replacement | 9382200 | GMK Overseas |
| 1040570 | Body Hinge Pillar Trim Panel Replacement | 9382300 | GMK Overseas |
| 1040640 | Cowl Side Panel Replacement | C2603 | GMNA |
| 1040640 | Cowl Side Panel Replacement | C456100 | Holden Australia |
| 1040640 | Cowl Side Panel Replacement | C456200 | Holden Australia |
| 1040640 | Cowl Side Panel Replacement | C456100 | Holden New Zealand |
| 1040640 | Cowl Side Panel Replacement | C456200 | Holden New Zealand |
| 1040700 | Driver Seat Cup Holder Replacement | C2752 | GMNA |
| 1040700 | Driver Seat Cup Holder Replacement | C6696 | GMNA |
| 1040720 | Rear Seat Cup Holder Replacement | C2753 | GMNA |
| 1040720 | Rear Seat Cup Holder Replacement | C7211 | GMNA |
| 1040720 | Rear Seat Cup Holder Replacement | C457300 | Holden Australia |
| 1040720 | Rear Seat Cup Holder Replacement | C7211 | Holden Australia |
| 1040720 | Rear Seat Cup Holder Replacement | C457300 | Holden New Zealand |
| 1040760 | Front Seat Armrest Cup Holder Replacement | C2764 | GMNA |
| 1040810 | Engine Cover Replacement | C2885 | GMNA |
| 1040810 | Engine Cover Replacement | C2886 | GMNA |
| 1040810 | Engine Cover Replacement | C2887 | GMNA |
| 1040810 | Engine Cover Replacement | C2890 | GMNA |
| 1041030 | Theft Deterrent Sensor Opening Trim Plate Replacement | | |
| 1041050 | Theft Deterrent Sensor Opening Cover Replacement | C3004 | GMNA |
| 1041070 | Rear Side Door Upper Track Garnish Molding Replacement | C3024 | GMNA |
| 1041090 | Roof Side Rail Garnish Molding Replacement - Right Side | C3028 | GMNA |
| 1041090 | Roof Side Rail Garnish Molding Replacement - Right Side | C322000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1041090 | Roof Side Rail Garnish Molding Replacement - Right Side | C623425 | Holden Australia |
| 1041110 | Roof Side Rail Garnish Molding Replacement - Left Side | C3038 | GMNA |
| 1041130 | Roof Rail Front Stowage Compartment Replacement | C3039 | GMNA |
| 1041130 | Roof Rail Front Stowage Compartment Replacement | 9712400 | GMK Overseas |
| 1041180 | Roof Panel Bow Replacement | | |
| 1041200 | Coat Hook Replacement | C3140 | GMNA |
| 1041280 | Body Lock Pillar Upper Trim Panel Replacement | C3158 | GMNA |
| 1041300 | Body Lock Pillar Lower Trim Panel Replacement | C3160 | GMNA |
| 1041300 | Body Lock Pillar Lower Trim Panel Replacement | C3161 | GMNA |
| 1041300 | Body Lock Pillar Lower Trim Panel Replacement | 8424500 | GMK Domestic |
| 1041300 | Body Lock Pillar Lower Trim Panel Replacement | 9380200 | GMK Overseas |
| 1041300 | Body Lock Pillar Lower Trim Panel Replacement | 9380500 | GMK Overseas |
| 1041350 | Body Lock Pillar Trim Panel Replacement | C3162 | GMNA |
| 1041350 | Body Lock Pillar Trim Panel Replacement | C3289 | GMNA |
| 1041350 | Body Lock Pillar Trim Panel Replacement | C410310 | Holden Australia |
| 1041350 | Body Lock Pillar Trim Panel Replacement | C410100 | Holden New Zealand |
| 1041350 | Body Lock Pillar Trim Panel Replacement | C410300 | Holden New Zealand |
| 1041350 | Body Lock Pillar Trim Panel Replacement | C410310 | Holden New Zealand |
| 1041370 | Body Lock Pillar Garnish Molding Replacement - Upper | C3163 | GMNA |
| 1041390 | Body Lock Pillar Garnish Lower Molding Replacement | C3164 | GMNA |
| 1041430 | Body Lock Pillar Garnish Molding Replacement | C3166 | GMNA |
| 1041450 | Body Side Rear Garnish Molding Replacement | C3167 | GMNA |
| 1041460 | Body Side Rear Window Garnish Molding Replacement | | |
| 1041470 | Center Pillar Garnish Molding Replacement | C3179 | GMNA |
| 1041490 | Center Pillar Upper Garnish Molding Replacement | C3180 | GMNA |
| 1041490 | Center Pillar Upper Garnish Molding Replacement | C3181 | GMNA |
| 1041490 | Center Pillar Upper Garnish Molding Replacement | 9380100 | GMK Overseas |
| 1041490 | Center Pillar Upper Garnish Molding Replacement | 9380400 | GMK Overseas |
| 1041490 | Center Pillar Upper Garnish Molding Replacement | 9380640 | GMK Overseas |
| 1041590 | Center Pillar Trim Panel Replacement | C3184 | GMNA |
| 1041590 | Center Pillar Trim Panel Replacement | C411150 | Holden Australia |
| 1041590 | Center Pillar Trim Panel Replacement | C411250 | Holden Australia |
| 1041590 | Center Pillar Trim Panel Replacement | C411150 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1041590 | Center Pillar Trim Panel Replacement | C411250 | Holden New Zealand |
| 1041590 | Center Pillar Trim Panel Replacement | 9380310 | GMK Overseas |
| 1041590 | Center Pillar Trim Panel Replacement | 9380320 | GMK Overseas |
| 1041640 | Center Pillar Upper Trim Panel Replacement | C4047 | GMNA |
| 1041640 | Center Pillar Upper Trim Panel Replacement | C622200 | Holden Australia |
| 1041640 | Center Pillar Upper Trim Panel Replacement | C622250 | Holden Australia |
| 1041640 | Center Pillar Upper Trim Panel Replacement | C622200 | Holden New Zealand |
| 1041640 | Center Pillar Upper Trim Panel Replacement | C622250 | Holden New Zealand |
| 1041660 | Center Pillar Lower Trim Panel Replacement | C3191 | GMNA |
| 1041660 | Center Pillar Lower Trim Panel Replacement | C4048 | GMNA |
| 1041660 | Center Pillar Lower Trim Panel Replacement | C412100 | Holden Australia |
| 1041660 | Center Pillar Lower Trim Panel Replacement | C623500 | Holden Australia |
| 1041660 | Center Pillar Lower Trim Panel Replacement | C623550 | Holden Australia |
| 1041660 | Center Pillar Lower Trim Panel Replacement | C623500 | Holden New Zealand |
| 1041660 | Center Pillar Lower Trim Panel Replacement | C623550 | Holden New Zealand |
| 1041860 | Front Side Door Front Garnish Molding Replacement | C3208 | GMNA |
| 1041880 | Front Side Door Rear Garnish Molding Replacement | C3209 | GMNA |
| 1042030 | Front Side Door Garnish Molding Replacement | C3217 | GMNA |
| 1042060 | Front Side Door Inside Handle Bezel Replacement | C3230 | GMNA |
| 1042060 | Front Side Door Inside Handle Bezel Replacement | C3230 | Holden Australia |
| 1042100 | Front or Rear Side Door Locking Rod Knob Trim Cover Replacement | B4350 | GMNA |
| 1042100 | Front or Rear Side Door Locking Rod Knob Trim Cover Replacement | B4351 | GMNA |
| 1042100 | Front or Rear Side Door Locking Rod Knob Trim Cover Replacement | B4358 | GMNA |
| 1042100 | Front or Rear Side Door Locking Rod Knob Trim Cover Replacement | C3234 | GMNA |
| 1042100 | Front or Rear Side Door Locking Rod Knob Trim Cover Replacement | C3235 | GMNA |
| 1042100 | Front or Rear Side Door Locking Rod Knob Trim Cover Replacement | 9353900 | GMK Overseas |
| 1042120 | Front Side Door Pull Handle Replacement | C3240 | GMNA |
| 1042120 | Front Side Door Pull Handle Replacement | 9352700 | GMK Overseas |
| 1042120 | Front Side Door Pull Handle Replacement | 9352800 | GMK Overseas |
| 1042120 | Front Side Door Pull Handle Replacement | 9352810 | GMK Overseas |
| 1042170 | Front Side Door Warning Reflector Replacement | C3254 | GMNA |
| 1042170 | Front Side Door Warning Reflector Replacement | C3524 | GMNA |
| 1042190 | Front Side Door Upper Trim Cover Replacement | C3260 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1042190 | Front Side Door Upper Trim Cover Replacement | C3261 | GMNA |
| 1042190 | Front Side Door Upper Trim Cover Replacement | 9465600 | GMK Overseas |
| 1042190 | Front Side Door Upper Trim Cover Replacement | 9465700 | GMK Overseas |
| 1042190 | Front Side Door Upper Trim Cover Replacement | 9465800 | GMK Overseas |
| 1042290 | Front Side Door Inside Handle Trim Plate Replacement | C3280 | GMNA |
| 1042290 | Front Side Door Inside Handle Trim Plate Replacement | C3280 | Holden Australia |
| 1042340 | Front Side Door Trim Panel Insert Replacement | C3282 | GMNA |
| 1042340 | Front Side Door Trim Panel Insert Replacement | C9920 | GMNA |
| 1042340 | Front Side Door Trim Panel Insert Replacement | 8612500 | GMK Domestic |
| 1042340 | Front Side Door Trim Panel Insert Replacement | 8612600 | GMK Domestic |
| 1042350 | Driver Seat Adjuster Memory Switch Bezel Replacement | | |
| 1042410 | Front Side Door Armrest Switch Mount Plate Replacement | | |
| 1042420 | Front Side Door Window Switch Bezel Replacement | C3292 | GMNA |
| 1042420 | Front Side Door Window Switch Bezel Replacement | 9354500 | GMK Overseas |
| 1042420 | Front Side Door Window Switch Bezel Replacement | 9354600 | GMK Overseas |
| 1042440 | Front Side Door Accessory Switch Mount Plate Replacement | B9964 | GMNA |
| 1042440 | Front Side Door Accessory Switch Mount Plate Replacement | C3293 | GMNA |
| 1042460 | Front Side Door Window Switch Opening Cover Replacement | C3294 | GMNA |
| 1042480 | Door Latch Release Switch Bezel Replacement | C3295 | GMNA |
| 1042500 | Front Side Door Armrest Lower Finish Cover Replacement | C3296 | GMNA |
| 1042580 | Front Side Door Trim Panel Finish Panel Applique Replacement | C3314 | GMNA |
| 1042600 | Front Side Door Armrest Pull Cup Replacement | C3315 | GMNA |
| 1042650 | Front Side Door Pull Handle Cover Replacement | C3317 | GMNA |
| 1042650 | Front Side Door Pull Handle Cover Replacement | 8613000 | GMK Domestic |
| 1042670 | Armrest Replacement | C3319 | GMNA |
| 1042690 | Front Side Door Armrest Replacement | C3320 | GMNA |
| 1042690 | Front Side Door Armrest Replacement | C9940 | GMNA |
| 1042690 | Front Side Door Armrest Replacement | 8613100 | GMK Domestic |
| 1042690 | Front Side Door Armrest Replacement | 8613400 | GMK Domestic |
| 1042690 | Front Side Door Armrest Replacement | 8613500 | GMK Domestic |
| 1042690 | Front Side Door Armrest Replacement | C3320 | Holden Australia |
| 1042690 | Front Side Door Armrest Replacement | C332000 | Holden Australia |
| 1042690 | Front Side Door Armrest Replacement | C406150 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1042690 | Front Side Door Armrest Replacement | C406250 | Holden Australia |
| 1042690 | Front Side Door Armrest Replacement | C414150 | Holden Australia |
| 1042690 | Front Side Door Armrest Replacement | C414250 | Holden Australia |
| 1042690 | Front Side Door Armrest Replacement | C406150 | Holden New Zealand |
| 1042690 | Front Side Door Armrest Replacement | C406250 | Holden New Zealand |
| 1042690 | Front Side Door Armrest Replacement | C407100 | Holden New Zealand |
| 1042690 | Front Side Door Armrest Replacement | C414150 | Holden New Zealand |
| 1042690 | Front Side Door Armrest Replacement | C414250 | Holden New Zealand |
| 1042690 | Front Side Door Armrest Replacement | 9352100 | GMK Overseas |
| 1042690 | Front Side Door Armrest Replacement | 9352200 | GMK Overseas |
| 1042690 | Front Side Door Armrest Replacement | 9352300 | GMK Overseas |
| 1042740 | Front Side Door Outside Rearview Mirror Filler Replacement | B9960 | GMNA |
| 1042740 | Front Side Door Outside Rearview Mirror Filler Replacement | C3329 | GMNA |
| 1042740 | Front Side Door Outside Rearview Mirror Filler Replacement | 9462800 | GMK Overseas |
| 1042740 | Front Side Door Outside Rearview Mirror Filler Replacement | 9462900 | GMK Overseas |
| 1042760 | Front Side Door Window Frame Front Cover Replacement | | |
| 1042810 | Front Side Door Map Pocket Replacement | C3335 | GMNA |
| 1042810 | Front Side Door Map Pocket Replacement | C3336 | GMNA |
| 1042810 | Front Side Door Map Pocket Replacement | C3462 | GMNA |
| 1042810 | Front Side Door Map Pocket Replacement | C407300 | Holden Australia |
| 1042810 | Front Side Door Map Pocket Replacement | C407400 | Holden Australia |
| 1042810 | Front Side Door Map Pocket Replacement | C407500 | Holden Australia |
| 1042810 | Front Side Door Map Pocket Replacement | C407600 | Holden Australia |
| 1042810 | Front Side Door Map Pocket Replacement | C407300 | Holden New Zealand |
| 1042810 | Front Side Door Map Pocket Replacement | C407400 | Holden New Zealand |
| 1042850 | Radio Front Side Door Speaker Grille Bezel Replacement | C3338 | GMNA |
| 1042850 | Radio Front Side Door Speaker Grille Bezel Replacement | R211200 | Holden Australia |
| 1042850 | Radio Front Side Door Speaker Grille Bezel Replacement | R211300 | Holden Australia |
| 1042850 | Radio Front Side Door Speaker Grille Bezel Replacement | R211200 | Holden New Zealand |
| 1042850 | Radio Front Side Door Speaker Grille Bezel Replacement | R211300 | Holden New Zealand |
| 1042870 | Front Side Door Trim Panel Applique Replacement | C3339 | GMNA |
| 1042870 | Front Side Door Trim Panel Applique Replacement | 8616200 | GMK Domestic |
| 1042870 | Front Side Door Trim Panel Applique Replacement | 9353500 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1042870 | Front Side Door Trim Panel Applique Replacement | 9353510 | GMK Overseas |
| 1042870 | Front Side Door Trim Panel Applique Replacement | 9353520 | GMK Overseas |
| 1042870 | Front Side Door Trim Panel Applique Replacement | 9355100 | GMK Overseas |
| 1042870 | Front Side Door Trim Panel Applique Replacement | 9355200 | GMK Overseas |
| 1042870 | Front Side Door Trim Panel Applique Replacement | 9617100 | GMK Overseas |
| 1042870 | Front Side Door Trim Panel Applique Replacement | 9617200 | GMK Overseas |
| 1042870 | Front Side Door Trim Panel Applique Replacement | 9617300 | GMK Overseas |
| 1042890 | Front Side Door Window and Rear Side Door Window Switch Opening Cover Replacement | C3340 | GMNA |
| 1042910 | Front Side Door Upper Front Trim Panel Replacement | | |
| 1042930 | Front Side Door Upper Trim Panel Replacement | C3342 | GMNA |
| 1042930 | Front Side Door Upper Trim Panel Replacement | C3342 | Holden New Zealand |
| 1042980 | Front Side Door Trim Panel Replacement | C3348 | GMNA |
| 1042980 | Front Side Door Trim Panel Replacement | 8612300 | GMK Domestic |
| 1042980 | Front Side Door Trim Panel Replacement | C3348 | Holden Australia |
| 1042980 | Front Side Door Trim Panel Replacement | C334800 | Holden Australia |
| 1042980 | Front Side Door Trim Panel Replacement | C406100 | Holden Australia |
| 1042980 | Front Side Door Trim Panel Replacement | C406200 | Holden Australia |
| 1042980 | Front Side Door Trim Panel Replacement | C3348 | Holden New Zealand |
| 1042980 | Front Side Door Trim Panel Replacement | C334800 | Holden New Zealand |
| 1042980 | Front Side Door Trim Panel Replacement | C406100 | Holden New Zealand |
| 1042980 | Front Side Door Trim Panel Replacement | C406200 | Holden New Zealand |
| 1042980 | Front Side Door Trim Panel Replacement | 9350100 | GMK Overseas |
| 1042980 | Front Side Door Trim Panel Replacement | 9350200 | GMK Overseas |
| 1042980 | Front Side Door Trim Panel Replacement | 9350300 | GMK Overseas |
| 1042980 | Front Side Door Trim Panel Replacement | 9350400 | GMK Overseas |
| 1043090 | Front Side Door Sill Trim Plate Replacement | C3359 | GMNA |
| 1043090 | Front Side Door Sill Trim Plate Replacement | C3361 | GMNA |
| 1043090 | Front Side Door Sill Trim Plate Replacement | C106700 | Holden Australia |
| 1043090 | Front Side Door Sill Trim Plate Replacement | C336100 | Holden Australia |
| 1043090 | Front Side Door Sill Trim Plate Replacement | C106700 | Holden New Zealand |
| 1043090 | Front Side Door Sill Trim Plate Replacement | C106800 | Holden New Zealand |
| 1043090 | Front Side Door Sill Trim Plate Replacement | 9380700 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1043190 | Front Side Door Water Deflector Replacement | C3364 | GMNA |
| 1043190 | Front Side Door Water Deflector Replacement | C3365 | GMNA |
| 1043190 | Front Side Door Water Deflector Replacement | C9869 | GMNA |
| 1043190 | Front Side Door Water Deflector Replacement | 8424220 | GMK Domestic |
| 1043190 | Front Side Door Water Deflector Replacement | 8612620 | GMK Domestic |
| 1043190 | Front Side Door Water Deflector Replacement | 8612700 | GMK Domestic |
| 1043190 | Front Side Door Water Deflector Replacement | C000616 | Holden Australia |
| 1043190 | Front Side Door Water Deflector Replacement | C406700 | Holden Australia |
| 1043190 | Front Side Door Water Deflector Replacement | C406800 | Holden Australia |
| 1043190 | Front Side Door Water Deflector Replacement | C000616 | Holden New Zealand |
| 1043190 | Front Side Door Water Deflector Replacement | C406700 | Holden New Zealand |
| 1043190 | Front Side Door Water Deflector Replacement | C406800 | Holden New Zealand |
| 1043190 | Front Side Door Water Deflector Replacement | 9350800 | GMK Overseas |
| 1043190 | Front Side Door Water Deflector Replacement | 9350900 | GMK Overseas |
| 1043210 | Side Door Sill Nameplate Replacement | C3370 | GMNA |
| 1043290 | Rear Side Door Window Frame Garnish Molding Replacement | C3400 | GMNA |
| 1043400 | Rear Side Door Window Garnish Molding Replacement | C3404 | GMNA |
| 1043400 | Rear Side Door Window Garnish Molding Replacement | 9640100 | GMK Overseas |
| 1043400 | Rear Side Door Window Garnish Molding Replacement | 9640200 | GMK Overseas |
| 1043450 | Rear Side Door Garnish Molding Replacement | C3407 | GMNA |
| 1043450 | Rear Side Door Garnish Molding Replacement | 9636810 | GMK Overseas |
| 1043450 | Rear Side Door Garnish Molding Replacement | 9636820 | GMK Overseas |
| 1043450 | Rear Side Door Garnish Molding Replacement | 9636830 | GMK Overseas |
| 1043450 | Rear Side Door Garnish Molding Replacement | 9637100 | GMK Overseas |
| 1043450 | Rear Side Door Garnish Molding Replacement | 9637110 | GMK Overseas |
| 1043450 | Rear Side Door Garnish Molding Replacement | 9637120 | GMK Overseas |
| 1043450 | Rear Side Door Garnish Molding Replacement | 9637130 | GMK Overseas |
| 1043450 | Rear Side Door Garnish Molding Replacement | 9637300 | GMK Overseas |
| 1043470 | Rear Side Door Upper Garnish Molding Replacement | C3408 | GMNA |
| 1043490 | Back Body Opening Garnish Molding Replacement | C3409 | GMNA |
| 1043490 | Back Body Opening Garnish Molding Replacement | C4520 | GMNA |
| 1043570 | Rear Side Door Latch Striker Cover Replacement | | |
| 1043610 | Rear Side Door Upper Molding Replacement | C3414 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1043620 | Rear Side Door Window Inside Sunshade Replacement | C3437 | GMNA |
| 1043630 | Rear Side Door Pull Handle Trim Finish Panel Replacement | | |
| 1043650 | Rear Side Door Pull Handle Cover Replacement | C3439 | GMNA |
| 1043670 | Rear Side Door Pull Handle Replacement | C3440 | GMNA |
| 1043670 | Rear Side Door Pull Handle Replacement | C3441 | GMNA |
| 1043670 | Rear Side Door Pull Handle Replacement | 9363800 | GMK Overseas |
| 1043670 | Rear Side Door Pull Handle Replacement | 9363810 | GMK Overseas |
| 1043670 | Rear Side Door Pull Handle Replacement | 9363820 | GMK Overseas |
| 1043720 | Rear Side Door Trim Panel Applique Replacement | C3447 | GMNA |
| 1043720 | Rear Side Door Trim Panel Applique Replacement | C3448 | GMNA |
| 1043720 | Rear Side Door Trim Panel Applique Replacement | 8625020 | GMK Domestic |
| 1043720 | Rear Side Door Trim Panel Applique Replacement | 9363400 | GMK Overseas |
| 1043720 | Rear Side Door Trim Panel Applique Replacement | 9363410 | GMK Overseas |
| 1043720 | Rear Side Door Trim Panel Applique Replacement | 9363420 | GMK Overseas |
| 1043930 | Rear Side Door Accessory Switch Mount Plate Replacement | | |
| 1044000 | Rear Side Door Armrest Pull Cup Replacement | C3515 | GMNA |
| 1044010 | Rear Side Door Armrest Switch Mount Plate Replacement | | |
| 1044020 | Rear Side Door Window Switch Bezel Replacement | C3502 | GMNA |
| 1044020 | Rear Side Door Window Switch Bezel Replacement | 9364100 | GMK Overseas |
| 1044020 | Rear Side Door Window Switch Bezel Replacement | 9364200 | GMK Overseas |
| 1044050 | Rear Side Door Armrest Replacement | C3520 | GMNA |
| 1044050 | Rear Side Door Armrest Replacement | 8620500 | GMK Domestic |
| 1044050 | Rear Side Door Armrest Replacement | 8624600 | GMK Domestic |
| 1044050 | Rear Side Door Armrest Replacement | C352000 | Holden Australia |
| 1044050 | Rear Side Door Armrest Replacement | C352200 | Holden Australia |
| 1044050 | Rear Side Door Armrest Replacement | 9362600 | GMK Overseas |
| 1044050 | Rear Side Door Armrest Replacement | 9362700 | GMK Overseas |
| 1044100 | Rear Side Door Map Pocket Replacement | C3326 | GMNA |
| 1044100 | Rear Side Door Map Pocket Replacement | C3526 | GMNA |
| 1044100 | Rear Side Door Map Pocket Replacement | C4879 | GMNA |
| 1044100 | Rear Side Door Map Pocket Replacement | C417300 | Holden Australia |
| 1044100 | Rear Side Door Map Pocket Replacement | C417400 | Holden Australia |
| 1044120 | Radio Rear Side Door Speaker Grille Bezel Replacement | C3528 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1044200 | Rear Side Door Upper Rear Trim Panel Replacement | C3534 | GMNA |
| 1044200 | Rear Side Door Upper Rear Trim Panel Replacement | C3535 | GMNA |
| 1044200 | Rear Side Door Upper Rear Trim Panel Replacement | 9365100 | GMK Overseas |
| 1044200 | Rear Side Door Upper Rear Trim Panel Replacement | 9365200 | GMK Overseas |
| 1044260 | Rear Side Door Trim Panel Replacement | C3540 | GMNA |
| 1044260 | Rear Side Door Trim Panel Replacement | 8454000 | GMK Domestic |
| 1044260 | Rear Side Door Trim Panel Replacement | 8623900 | GMK Domestic |
| 1044260 | Rear Side Door Trim Panel Replacement | 8624200 | GMK Domestic |
| 1044260 | Rear Side Door Trim Panel Replacement | C354000 | Holden Australia |
| 1044260 | Rear Side Door Trim Panel Replacement | C354000 | Holden New Zealand |
| 1044260 | Rear Side Door Trim Panel Replacement | 9360300 | GMK Overseas |
| 1044260 | Rear Side Door Trim Panel Replacement | 9360400 | GMK Overseas |
| 1044260 | Rear Side Door Trim Panel Replacement | 9360500 | GMK Overseas |
| 1044310 | Rear Door Inside Handle Bezel Replacement | C3544 | GMNA |
| 1044310 | Rear Door Inside Handle Bezel Replacement | 8622500 | GMK Domestic |
| 1044350 | Rear Side Door Sill Garnish Molding Replacement | | |
| 1044360 | Rear Side Door Sill Trim Plate Replacement | C3559 | GMNA |
| 1044360 | Rear Side Door Sill Trim Plate Replacement | C3560 | GMNA |
| 1044360 | Rear Side Door Sill Trim Plate Replacement | C3561 | GMNA |
| 1044360 | Rear Side Door Sill Trim Plate Replacement | C356000 | Holden Australia |
| 1044360 | Rear Side Door Sill Trim Plate Replacement | C356100 | Holden Australia |
| 1044360 | Rear Side Door Sill Trim Plate Replacement | C356000 | Holden New Zealand |
| 1044360 | Rear Side Door Sill Trim Plate Replacement | 9381100 | GMK Overseas |
| 1044440 | Rear Side Door Water Deflector Replacement | C3565 | GMNA |
| 1044440 | Rear Side Door Water Deflector Replacement | C3566 | GMNA |
| 1044440 | Rear Side Door Water Deflector Replacement | 8624220 | GMK Domestic |
| 1044440 | Rear Side Door Water Deflector Replacement | C417100 | Holden Australia |
| 1044440 | Rear Side Door Water Deflector Replacement | C417200 | Holden Australia |
| 1044440 | Rear Side Door Water Deflector Replacement | C897350 | Holden Australia |
| 1044440 | Rear Side Door Water Deflector Replacement | C417100 | Holden New Zealand |
| 1044440 | Rear Side Door Water Deflector Replacement | C417200 | Holden New Zealand |
| 1044440 | Rear Side Door Water Deflector Replacement | C897350 | Holden New Zealand |
| 1044440 | Rear Side Door Water Deflector Replacement | 9361000 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1044440 | Rear Side Door Water Deflector Replacement | 9361100 | GMK Overseas |
| 1044580 | Intermediate Side Door Trim Panel Replacement | C3764 | GMNA |
| 1044580 | Intermediate Side Door Trim Panel Replacement | C3767 | GMNA |
| 1044660 | Roof Rail Rear Assist Handle Replacement | C3900 | GMNA |
| 1044660 | Roof Rail Rear Assist Handle Replacement | C3900 | Holden Australia |
| 1044660 | Roof Rail Rear Assist Handle Replacement | 9710400 | GMK Overseas |
| 1044660 | Roof Rail Rear Assist Handle Replacement | 9710500 | GMK Overseas |
| 1044710 | Windshield Pillar Assist Handle Replacement | | |
| 1044720 | Roof Rail Assist Handle Replacement | | |
| 1044730 | Roof Rail Front Assist Handle Replacement | | |
| 1044780 | Center Pillar Assist Handle Replacement | C3906 | GMNA |
| 1044800 | Assist Handle Replacement | 9710200 | GMK Overseas |
| 1044800 | Assist Handle Replacement | 9710300 | GMK Overseas |
| 1044840 | Quarter Window Garnish Molding Replacement | C3920 | GMNA |
| 1044840 | Quarter Window Garnish Molding Replacement | 9382400 | GMK Overseas |
| 1044840 | Quarter Window Garnish Molding Replacement | 9382810 | GMK Overseas |
| 1044840 | Quarter Window Garnish Molding Replacement | 9382820 | GMK Overseas |
| 1044840 | Quarter Window Garnish Molding Replacement | 9382830 | GMK Overseas |
| 1044840 | Quarter Window Garnish Molding Replacement | 9383800 | GMK Overseas |
| 1044840 | Quarter Window Garnish Molding Replacement | 9383900 | GMK Overseas |
| 1045050 | Quarter Trim Panel Insert Replacement | C3977 | GMNA |
| 1045070 | Quarter Stowage Pocket Door Replacement | C3982 | GMNA |
| 1045070 | Quarter Stowage Pocket Door Replacement | C457110 | Holden Australia |
| 1045070 | Quarter Stowage Pocket Door Replacement | C457120 | Holden Australia |
| 1045070 | Quarter Stowage Pocket Door Replacement | C457110 | Holden New Zealand |
| 1045090 | Rear Compartment Floor Stowage Compartment Tray Replacement | C3983 | GMNA |
| 1045110 | Rear Floor Panel Stowage Compartment Door Replacement | C3984 | GMNA |
| 1045160 | Body Side Rear Stowage Compartment Replacement | C3986 | GMNA |
| 1045160 | Body Side Rear Stowage Compartment Replacement | 9391100 | GMK Overseas |
| 1045210 | Quarter Inner Panel Access Hole Cover Replacement | S1381 | GMNA |
| 1045230 | Cargo Stowage Tray Replacement | C3992 | GMNA |
| 1045250 | Cargo Partition Track Slide Replacement | C3993 | GMNA |
| 1045270 | Cargo Partition Replacement | C3994 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1045290 | Body Side Trim Panel Stowage Pocket Replacement | C3997 | GMNA |
| 1045310 | Quarter Inner Trim Finish Panel Replacement - Right Side | | |
| 1045330 | Quarter Inner Trim Finish Panel Replacement - Left Side | | |
| 1045410 | Quarter Upper Trim Panel Replacement - Right Side | C4002 | GMNA |
| 1045410 | Quarter Upper Trim Panel Replacement - Right Side | C400200 | Holden Australia |
| 1045410 | Quarter Upper Trim Panel Replacement - Right Side | C624400 | Holden Australia |
| 1045410 | Quarter Upper Trim Panel Replacement - Right Side | C400200 | Holden New Zealand |
| 1045410 | Quarter Upper Trim Panel Replacement - Right Side | C624400 | Holden New Zealand |
| 1045430 | Quarter Upper Trim Panel Replacement - Left Side | C4003 | GMNA |
| 1045430 | Quarter Upper Trim Panel Replacement - Left Side | C624450 | Holden Australia |
| 1045430 | Quarter Upper Trim Panel Replacement - Left Side | C624450 | Holden New Zealand |
| 1045450 | Body Side Upper Trim Panel Replacement | C4004 | GMNA |
| 1045470 | Body Side Trim Panel Replacement - Left Side | C4005 | GMNA |
| 1045470 | Body Side Trim Panel Replacement - Left Side | C410410 | Holden Australia |
| 1045470 | Body Side Trim Panel Replacement - Left Side | C410420 | Holden Australia |
| 1045470 | Body Side Trim Panel Replacement - Left Side | C410410 | Holden New Zealand |
| 1045470 | Body Side Trim Panel Replacement - Left Side | C410420 | Holden New Zealand |
| 1045490 | Body Side Trim Panel Replacement | C4006 | GMNA |
| 1045490 | Body Side Trim Panel Replacement | C4006 | Holden Australia |
| 1045490 | Body Side Trim Panel Replacement | C00653 | Holden New Zealand |
| 1045490 | Body Side Trim Panel Replacement | 9382600 | GMK Overseas |
| 1045490 | Body Side Trim Panel Replacement | 9384500 | GMK Overseas |
| 1045510 | Body Side Rear Trim Panel Replacement | C4007 | GMNA |
| 1045560 | Body Side Front Trim Panel Replacement - Left Side | C4009 | GMNA |
| 1045640 | Body Side Rear Lower Trim Panel Replacement | C4012 | GMNA |
| 1045660 | Body Side Front Lower Trim Panel Replacement | C2172 | GMNA |
| 1045660 | Body Side Front Lower Trim Panel Replacement | C4013 | GMNA |
| 1045680 | Quarter Inner Trim Finish Panel Replacement | C4014 | GMNA |
| 1045680 | Quarter Inner Trim Finish Panel Replacement | 9384200 | GMK Overseas |
| 1045700 | Body Side Lower Trim Panel Replacement | C4017 | GMNA |
| 1045720 | Body Side Rear Upper Trim Panel Replacement | | |
| 1045740 | Body Side Trim Panel Replacement - Right Side | C4019 | GMNA |
| 1045740 | Body Side Trim Panel Replacement - Right Side | C410320 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1045740 | Body Side Trim Panel Replacement - Right Side | C410320 | Holden New Zealand |
| 1045760 | Quarter Trim Panel Replacement | C4020 | GMNA |
| 1045810 | Quarter Upper Trim Panel Replacement | C4022 | GMNA |
| 1045830 | Quarter Lower Rear Trim Panel Replacement | C3978 | GMNA |
| 1045830 | Quarter Lower Rear Trim Panel Replacement | C3979 | GMNA |
| 1045830 | Quarter Lower Rear Trim Panel Replacement | C3980 | GMNA |
| 1045830 | Quarter Lower Rear Trim Panel Replacement | C3981 | GMNA |
| 1045830 | Quarter Lower Rear Trim Panel Replacement | C3995 | GMNA |
| 1045830 | Quarter Lower Rear Trim Panel Replacement | C3996 | GMNA |
| 1045830 | Quarter Lower Rear Trim Panel Replacement | C4023 | GMNA |
| 1045910 | Quarter Upper Rear Trim Panel Replacement | C4026 | GMNA |
| 1046010 | Body Side Window Front Garnish Molding Replacement | C4030 | GMNA |
| 1046030 | Body Side Window Rear Garnish Molding Replacement | C4031 | GMNA |
| 1046050 | Quarter Window Trim Finish Panel Replacement | C4032 | GMNA |
| 1046050 | Quarter Window Trim Finish Panel Replacement | C000713 | Holden Australia |
| 1046090 | Quarter Window Lower Trim Finish Panel Replacement | C4034 | GMNA |
| 1046110 | Quarter Lower Trim Replacement | C4035 | GMNA |
| 1046110 | Quarter Lower Trim Replacement | C9795 | GMNA |
| 1046110 | Quarter Lower Trim Replacement | C9888 | GMNA |
| 1046110 | Quarter Lower Trim Replacement | C411600 | Holden Australia |
| 1046110 | Quarter Lower Trim Replacement | C411700 | Holden Australia |
| 1046110 | Quarter Lower Trim Replacement | C421100 | Holden Australia |
| 1046110 | Quarter Lower Trim Replacement | C421200 | Holden Australia |
| 1046110 | Quarter Lower Trim Replacement | C434200 | Holden Australia |
| 1046110 | Quarter Lower Trim Replacement | C421200 | Holden New Zealand |
| 1046110 | Quarter Lower Trim Replacement | C434200 | Holden New Zealand |
| 1046110 | Quarter Lower Trim Replacement | 9382840 | GMK Overseas |
| 1046110 | Quarter Lower Trim Replacement | 9382850 | GMK Overseas |
| 1046110 | Quarter Lower Trim Replacement | 9382860 | GMK Overseas |
| 1046130 | Quarter Stowage Box Replacement | | |
| 1046140 | Body Side Trim Panel Armrest Replacement | | |
| 1046150 | Quarter Inner Trim Finish Panel Cover Replacement | C4036 | GMNA |
| 1046270 | Rear Wheelhouse Trim Finish Panel Replacement | C434100 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1046270 | Rear Wheelhouse Trim Finish Panel Replacement | C434100 | Holden New Zealand |
| 1046290 | Front Side Door Step Mat Replacement | C4178 | GMNA |
| 1046370 | Multifunction Accessory Module Lower Carrier Replacement | C4238 | GMNA |
| 1046390 | Rear Window Panel Trim Replacement | C4239 | GMNA |
| 1046390 | Rear Window Panel Trim Replacement | C9946 | GMNA |
| 1046390 | Rear Window Panel Trim Replacement | C9976 | GMNA |
| 1046390 | Rear Window Panel Trim Replacement | C427100 | Holden Australia |
| 1046390 | Rear Window Panel Trim Replacement | C427100 | Holden New Zealand |
| 1046390 | Rear Window Panel Trim Replacement | C427110 | Holden New Zealand |
| 1046390 | Rear Window Panel Trim Replacement | C427120 | Holden New Zealand |
| 1046390 | Rear Window Panel Trim Replacement | C427210 | Holden New Zealand |
| 1046390 | Rear Window Panel Trim Replacement | C427220 | Holden New Zealand |
| 1046390 | Rear Window Panel Trim Replacement | 9390700 | GMK Overseas |
| 1046390 | Rear Window Panel Trim Replacement | 9710700 | GMK Overseas |
| 1046390 | Rear Window Panel Trim Replacement | 9711700 | GMK Overseas |
| 1046390 | Rear Window Panel Trim Replacement | 9711900 | GMK Overseas |
| 1046470 | Rear Compartment Access Door Cover Replacement | C4251 | GMNA |
| 1046470 | Rear Compartment Access Door Cover Replacement | C623600 | Holden Australia |
| 1046470 | Rear Compartment Access Door Cover Replacement | C623600 | Holden New Zealand |
| 1046490 | Rear Compartment Stowage Shelf Replacement | C4252 | GMNA |
| 1046490 | Rear Compartment Stowage Shelf Replacement | C9871 | GMNA |
| 1046490 | Rear Compartment Stowage Shelf Replacement | C860760 | Holden Australia |
| 1046490 | Rear Compartment Stowage Shelf Replacement | C860770 | Holden Australia |
| 1046500 | Rear Compartment Rear Window Lower Trim Replacement | | |
| 1046510 | Luggage Shade Replacement | C2797 | GMNA |
| 1046510 | Luggage Shade Replacement | C4260 | GMNA |
| 1046510 | Luggage Shade Replacement | C4260 | Holden Australia |
| 1046510 | Luggage Shade Replacement | C426000 | Holden Australia |
| 1046510 | Luggage Shade Replacement | R609100 | Holden Australia |
| 1046510 | Luggage Shade Replacement | C426000 | Holden New Zealand |
| 1046510 | Luggage Shade Replacement | C427010 | Holden New Zealand |
| 1046510 | Luggage Shade Replacement | R609100 | Holden New Zealand |
| 1046530 | Luggage Shade Strap Replacement | C4261 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1046550 | Luggage Shade Retainer Replacement | C4263 | GMNA |
| 1046570 | Sunshade Retainer Replacement | C4264 | GMNA |
| 1046590 | Luggage Shade Pivot Replacement | C4265 | GMNA |
| 1046750 | Rear Window Lower Garnish Molding Replacement | C4283 | GMNA |
| 1046880 | Rear Window Trim Finish Panel Replacement | B6805 | GMNA |
| 1046880 | Rear Window Trim Finish Panel Replacement | C4289 | GMNA |
| 1046900 | Rear Window Trim Panel Speaker Opening Cover Replacement | C4290 | GMNA |
| 1046920 | Rear Window Panel Stowage Compartment Cover Replacement | C4291 | GMNA |
| 1046940 | Removable Midgate Hinge Finish Cover Replacement | C4320 | GMNA |
| 1047140 | Rear Window Inside Sunshade Replacement | C4369 | GMNA |
| 1047140 | Rear Window Inside Sunshade Replacement | C4370 | GMNA |
| 1047140 | Rear Window Inside Sunshade Replacement | R603000 | Holden Australia |
| 1047140 | Rear Window Inside Sunshade Replacement | R603100 | Holden Australia |
| 1047190 | Rear Window Inside Sunshade Control Module Replacement | C4378 | GMNA |
| 1047200 | Rear Wheelhouse Front Trim Replacement | | |
| 1047240 | Body Rear Corner Trim Panel Replacement | C4499 | GMNA |
| 1047320 | Back Body Pillar Inner Panel Trim Panel Replacement | C4502 | GMNA |
| 1047330 | Rear End Trim Finish Panel Replacement | C4503 | GMNA |
| 1047340 | Body Rear Corner Trim Panel Replacement - Right Side | C4504 | GMNA |
| 1047360 | Body Rear Corner Trim Panel Replacement - Left Side | C4505 | GMNA |
| 1047380 | Body Rear Trim Panel Replacement | C4507 | GMNA |
| 1047400 | Body Rear Panel Insulator Replacement | B9947 | GMNA |
| 1047400 | Body Rear Panel Insulator Replacement | C4508 | GMNA |
| 1047400 | Body Rear Panel Insulator Replacement | C9941 | GMNA |
| 1047400 | Body Rear Panel Insulator Replacement | 8641900 | GMK Domestic |
| 1047400 | Body Rear Panel Insulator Replacement | 8642502 | GMK Domestic |
| 1047420 | Liftgate Window Upper Garnish Molding Replacement | C4509 | GMNA |
| 1047440 | Liftgate Window Side Garnish Molding Replacement | C4510 | GMNA |
| 1047440 | Liftgate Window Side Garnish Molding Replacement | 9523600 | GMK Overseas |
| 1047440 | Liftgate Window Side Garnish Molding Replacement | 9523700 | GMK Overseas |
| 1047440 | Liftgate Window Side Garnish Molding Replacement | 9523800 | GMK Overseas |
| 1047460 | Body Rear Corner Garnish Molding Replacement | C4511 | GMNA |
| 1047480 | Body Rear Corner Upper Garnish Molding Replacement | C4512 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1047590 | Back Body Opening Garnish Molding Replacement | | |
| 1047670 | Rear Door Opening Upper Trim Panel Replacement | C4532 | GMNA |
| 1047750 | Rear Compartment Sill Trim Plate Replacement | C4541 | GMNA |
| 1047770 | Rear Floor Rear Trim Plate Replacement | C4542 | GMNA |
| 1047790 | Liftgate Sill Trim Plate Replacement | C4543 | GMNA |
| 1047900 | Rear End Trim Finish Upper Panel Replacement | C4580 | GMNA |
| 1047920 | Rear Compartment Front Trim Panel Replacement | C4585 | GMNA |
| 1047940 | Rear Compartment Side Trim Panel Replacement | C4586 | GMNA |
| 1047940 | Rear Compartment Side Trim Panel Replacement | 8641800 | GMK Domestic |
| 1047940 | Rear Compartment Side Trim Panel Replacement | 9380620 | GMK Overseas |
| 1047940 | Rear Compartment Side Trim Panel Replacement | 9380650 | GMK Overseas |
| 1047940 | Rear Compartment Side Trim Panel Replacement | 9381800 | GMK Overseas |
| 1047940 | Rear Compartment Side Trim Panel Replacement | 9381900 | GMK Overseas |
| 1047940 | Rear Compartment Side Trim Panel Replacement | 9382700 | GMK Overseas |
| 1047940 | Rear Compartment Side Trim Panel Replacement | 9384600 | GMK Overseas |
| 1047960 | Rear Compartment Side Trim Panel Access Hole Cover Replacement | C4587 | GMNA |
| 1047960 | Rear Compartment Side Trim Panel Access Hole Cover Replacement | C9974 | GMNA |
| 1047980 | Rear Compartment Floor Stowage Compartment Door Pull Strap Replacement | C4588 | GMNA |
| 1047980 | Rear Compartment Floor Stowage Compartment Door Pull Strap Replacement | C000668 | Holden Australia |
| 1047980 | Rear Compartment Floor Stowage Compartment Door Pull Strap Replacement | C000668 | Holden New Zealand |
| 1048000 | Convenience Net Replacement | C2403 | GMNA |
| 1048000 | Convenience Net Replacement | C754400 | Holden Australia |
| 1048000 | Convenience Net Replacement | C754400 | Holden New Zealand |
| 1048000 | Convenience Net Replacement | 9390950 | GMK Overseas |
| 1048020 | Rear Compartment Lid Inner Panel Trim Replacement | C4600 | GMNA |
| 1048020 | Rear Compartment Lid Inner Panel Trim Replacement | 9382900 | GMK Overseas |
| 1048040 | Rear Compartment Lid Carpet Replacement | C4601 | GMNA |
| 1048060 | Rear Compartment Lid Latch Cover Replacement | C4602 | GMNA |
| 1048080 | Rear Compartment Lid Pull Strap Replacement | C4604 | GMNA |
| 1048100 | Rear Compartment Floor Stowage Compartment Replacement | C4608 | GMNA |
| 1048100 | Rear Compartment Floor Stowage Compartment Replacement | 8511000 | GMK Domestic |
| 1048100 | Rear Compartment Floor Stowage Compartment Replacement | C474300 | Holden Australia |
| 1048100 | Rear Compartment Floor Stowage Compartment Replacement | C474300 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1048100 | Rear Compartment Floor Stowage Compartment Replacement | 9391200 | GMK Overseas |
| 1048100 | Rear Compartment Floor Stowage Compartment Replacement | 9392900 | GMK Overseas |
| 1048120 | Rear Compartment Floor Stowage Compartment Cover Replacement | C4609 | GMNA |
| 1048140 | Rear Compartment Stowage Tray Net Replacement | C4610 | GMNA |
| 1048140 | Rear Compartment Stowage Tray Net Replacement | C100770 | Holden Australia |
| 1048140 | Rear Compartment Stowage Tray Net Replacement | C4610 | Holden Australia |
| 1048160 | Rear Compartment Floor Stowage Compartment Door Frame Replacement | C4611 | GMNA |
| 1048160 | Rear Compartment Floor Stowage Compartment Door Frame Replacement | C9513 | GMNA |
| 1048180 | Load Floor Panel Frame Replacement | C4612 | GMNA |
| 1048180 | Load Floor Panel Frame Replacement | S0650 | GMNA |
| 1048180 | Load Floor Panel Frame Replacement | L000281 | Holden New Zealand |
| 1048200 | Rear Compartment Panel Stowage Pocket Cover Latch Replacement | C4613 | GMNA |
| 1048220 | Rear Compartment Floor Panel Track Partition Slide Replacement | C4614 | GMNA |
| 1048240 | Rear Compartment Floor Stowage Trim Compartment Replacement | C4615 | GMNA |
| 1048260 | Load Floor Rear Compartment Cover Handle Replacement | C4617 | GMNA |
| 1048260 | Load Floor Rear Compartment Cover Handle Replacement | 9390310 | GMK Overseas |
| 1048330 | Load Floor Panel Rear Extension Panel Replacement | C4621 | GMNA |
| 1048350 | Load Floor Rear Compartment Cover Replacement | C4622 | GMNA |
| 1048350 | Load Floor Rear Compartment Cover Replacement | 9392100 | GMK Overseas |
| 1048360 | Rear Compartment Floor Panel Trim Replacement | C4640 | GMNA |
| 1048360 | Rear Compartment Floor Panel Trim Replacement | C431600 | Holden Australia |
| 1048360 | Rear Compartment Floor Panel Trim Replacement | C431600 | Holden New Zealand |
| 1048370 | Rear Compartment Floor Panel Rail Replacement | C4653 | GMNA |
| 1048370 | Rear Compartment Floor Panel Rail Replacement | C432700 | Holden Australia |
| 1048370 | Rear Compartment Floor Panel Rail Replacement | C432700 | Holden New Zealand |
| 1048380 | Rear Compartment Floor Panel Trim Support Replacement | | |
| 1048390 | Rear Compartment Convenience Hook Replacement | C4654 | GMNA |
| 1048410 | Cargo Tie Down Hook Replacement | C4657 | GMNA |
| 1048410 | Cargo Tie Down Hook Replacement | 9384100 | GMK Overseas |
| 1048500 | Rear Compartment Side Trim Replacement - Right Side | C4684 | GMNA |
| 1048500 | Rear Compartment Side Trim Replacement - Right Side | C424100 | Holden Australia |
| 1048500 | Rear Compartment Side Trim Replacement - Right Side | C424100 | Holden New Zealand |
| 1048520 | Rear Compartment Side Trim Replacement - Left Side | C4685 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1048520 | Rear Compartment Side Trim Replacement - Left Side | C424200 | Holden Australia |
| 1048520 | Rear Compartment Side Trim Replacement - Left Side | C424200 | Holden New Zealand |
| 1048540 | Jack Stowage Cover Replacement | C4710 | GMNA |
| 1048540 | Jack Stowage Cover Replacement | C4710 | Holden Australia |
| 1048560 | Tool Stowage Compartment Replacement | C4711 | GMNA |
| 1048730 | Rear Door Trim Panel Replacement | C4830 | GMNA |
| 1048730 | Rear Door Trim Panel Replacement | 8627100 | GMK Domestic |
| 1048730 | Rear Door Trim Panel Replacement | C414100 | Holden Australia |
| 1048730 | Rear Door Trim Panel Replacement | C414200 | Holden Australia |
| 1048730 | Rear Door Trim Panel Replacement | C414100 | Holden New Zealand |
| 1048730 | Rear Door Trim Panel Replacement | C414200 | Holden New Zealand |
| 1048730 | Rear Door Trim Panel Replacement | 9783500 | GMK Overseas |
| 1048780 | Liftgate Close Switch Bezel Replacement | C4859 | GMNA |
| 1048800 | Liftgate Trim Panel Replacement | C4860 | GMNA |
| 1048820 | Endgate Trim Panel Replacement | C4861 | GMNA |
| 1048820 | Endgate Trim Panel Replacement | C4861 | Holden Australia |
| 1048840 | Liftgate Garnish Molding Replacement | C4870 | GMNA |
| 1048860 | Liftgate Trim Finish Panel Replacement | C4871 | GMNA |
| 1048860 | Liftgate Trim Finish Panel Replacement | C621600 | Holden Australia |
| 1048860 | Liftgate Trim Finish Panel Replacement | C621700 | Holden Australia |
| 1048860 | Liftgate Trim Finish Panel Replacement | C621800 | Holden Australia |
| 1048860 | Liftgate Trim Finish Panel Replacement | C621850 | Holden Australia |
| 1048860 | Liftgate Trim Finish Panel Replacement | C621900 | Holden Australia |
| 1048860 | Liftgate Trim Finish Panel Replacement | C621950 | Holden Australia |
| 1048860 | Liftgate Trim Finish Panel Replacement | C621600 | Holden New Zealand |
| 1048860 | Liftgate Trim Finish Panel Replacement | C621700 | Holden New Zealand |
| 1048860 | Liftgate Trim Finish Panel Replacement | C621800 | Holden New Zealand |
| 1048860 | Liftgate Trim Finish Panel Replacement | C621850 | Holden New Zealand |
| 1048860 | Liftgate Trim Finish Panel Replacement | C621900 | Holden New Zealand |
| 1048860 | Liftgate Trim Finish Panel Replacement | C621950 | Holden New Zealand |
| 1048860 | Liftgate Trim Finish Panel Replacement | 9383400 | GMK Overseas |
| 1048880 | Liftgate Lower Trim Finish Panel Replacement | C4872 | GMNA |
| 1048880 | Liftgate Lower Trim Finish Panel Replacement | 9381500 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1048900 | Liftgate Upper Trim Finish Panel Replacement | C4873 | GMNA |
| 1048900 | Liftgate Upper Trim Finish Panel Replacement | 9381700 | GMK Overseas |
| 1048910 | Liftgate Upper Side Trim Finish Panel Replacement | | |
| 1048920 | Liftgate Trim Finish Access Hole Cover Replacement | 9672200 | GMK Overseas |
| 1048940 | Liftgate Inside Pull Handle Replacement | C4880 | GMNA |
| 1048940 | Liftgate Inside Pull Handle Replacement | 9672100 | GMK Overseas |
| 1049020 | Rear Window Inside Sunshade Switch Replacement | N2464 | GMNA |
| 1049030 | Fire Extinguisher Bracket Replacement | | |
| 1049070 | Radio Front Side Door Lower Speaker Grille Replacement | | |
| 1049090 | Radio Rear Side Door Lower Speaker Grille Replacement | | |
| 1410010 | Front Compartment Side Sight Shield Replacement | B1228 | GMNA |
| 1410020 | Radiator Opening Upper Cover Replacement | | |
| 1410030 | Front Compartment Front Sight Shield Replacement | | |
| 1410040 | Hood Air Scoop Replacement | | |
| 1410052 | Hood Adjustment | B1500 | GMNA |
| 1410052 | Hood Adjustment | B1536 | GMNA |
| 1410052 | Hood Adjustment | S0285 | GMNA |
| 1410052 | Hood Adjustment | B150000 | Holden Australia |
| 1410052 | Hood Adjustment | P003100 | Holden Australia |
| 1410052 | Hood Adjustment | B150000 | Holden New Zealand |
| 1410052 | Hood Adjustment | P003100 | Holden New Zealand |
| 1410052 | Hood Adjustment | 9730800 | GMK Overseas |
| 1410070 | Hood Rear Corner Seal Replacement | | |
| 1410090 | Hood Rear Seal Replacement | B1529 | GMNA |
| 1410090 | Hood Rear Seal Replacement | C1035 | GMNA |
| 1410090 | Hood Rear Seal Replacement | C107700 | Holden Australia |
| 1410090 | Hood Rear Seal Replacement | C107700 | Holden New Zealand |
| 1410090 | Hood Rear Seal Replacement | 9733000 | GMK Overseas |
| 1410090 | Hood Rear Seal Replacement | 9733500 | GMK Overseas |
| 1410090 | Hood Rear Seal Replacement | 9733600 | GMK Overseas |
| 1410110 | Hood Insulator Replacement | B1530 | GMNA |
| 1410110 | Hood Insulator Replacement | R9242 | GMNA |
| 1410110 | Hood Insulator Replacement | A505500 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1410110 | Hood Insulator Replacement | B151000 | Holden Australia |
| 1410110 | Hood Insulator Replacement | A505500 | Holden New Zealand |
| 1410110 | Hood Insulator Replacement | B1510 | Holden New Zealand |
| 1410110 | Hood Insulator Replacement | 9731700 | GMK Overseas |
| 1410160 | Hood Front Seal Replacement | B1531 | GMNA |
| 1410160 | Hood Front Seal Replacement | B1532 | GMNA |
| 1410160 | Hood Front Seal Replacement | B1535 | GMNA |
| 1410160 | Hood Front Seal Replacement | C1034 | GMNA |
| 1410160 | Hood Front Seal Replacement | 9731900 | GMK Overseas |
| 1410160 | Hood Front Seal Replacement | 9733100 | GMK Overseas |
| 1410180 | Hood Side Seal Replacement | B1533 | GMNA |
| 1410180 | Hood Side Seal Replacement | B1534 | GMNA |
| 1410180 | Hood Side Seal Replacement | 9733200 | GMK Overseas |
| 1410180 | Hood Side Seal Replacement | 9733300 | GMK Overseas |
| 1410260 | Hood Primary Latch Replacement | B1540 | GMNA |
| 1410260 | Hood Primary Latch Replacement | B1550 | GMNA |
| 1410260 | Hood Primary Latch Replacement | B1580 | GMNA |
| 1410260 | Hood Primary Latch Replacement | B1640 | GMNA |
| 1410260 | Hood Primary Latch Replacement | C9921 | GMNA |
| 1410260 | Hood Primary Latch Replacement | 8630900 | GMK Domestic |
| 1410260 | Hood Primary Latch Replacement | 8631200 | GMK Domestic |
| 1410260 | Hood Primary Latch Replacement | 8633100 | GMK Domestic |
| 1410260 | Hood Primary Latch Replacement | 8635100 | GMK Domestic |
| 1410260 | Hood Primary Latch Replacement | 8635300 | GMK Domestic |
| 1410260 | Hood Primary Latch Replacement | A511500 | Holden Australia |
| 1410260 | Hood Primary Latch Replacement | A513500 | Holden Australia |
| 1410260 | Hood Primary Latch Replacement | A517600 | Holden Australia |
| 1410260 | Hood Primary Latch Replacement | A519500 | Holden Australia |
| 1410260 | Hood Primary Latch Replacement | B1500 | Holden Australia |
| 1410260 | Hood Primary Latch Replacement | B154000 | Holden Australia |
| 1410260 | Hood Primary Latch Replacement | B155000 | Holden Australia |
| 1410260 | Hood Primary Latch Replacement | B158000 | Holden Australia |
| 1410260 | Hood Primary Latch Replacement | A511500 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1410260 | Hood Primary Latch Replacement | A513500 | Holden New Zealand |
| 1410260 | Hood Primary Latch Replacement | A517600 | Holden New Zealand |
| 1410260 | Hood Primary Latch Replacement | A519500 | Holden New Zealand |
| 1410260 | Hood Primary Latch Replacement | B1505 | Holden New Zealand |
| 1410260 | Hood Primary Latch Replacement | B154000 | Holden New Zealand |
| 1410260 | Hood Primary Latch Replacement | 9740100 | GMK Overseas |
| 1410260 | Hood Primary Latch Replacement | 9741700 | GMK Overseas |
| 1410280 | Hood Primary and Secondary Latch Replacement | B1541 | GMNA |
| 1410280 | Hood Primary and Secondary Latch Replacement | B1542 | GMNA |
| 1410300 | Hood Secondary Latch Replacement | H0042 | Holden Australia |
| 1410320 | Hood Primary Latch Striker Replacement | B1545 | GMNA |
| 1410320 | Hood Primary Latch Striker Replacement | 8633000 | GMK Domestic |
| 1410340 | Hood Open Assist Spring Replacement | | |
| 1410450 | Hood Hold-Open Rod Replacement | B1600 | GMNA |
| 1410450 | Hood Hold-Open Rod Replacement | B1600 | Holden New Zealand |
| 1410470 | Hood Primary Latch Release Cable Replacement | B1630 | GMNA |
| 1410470 | Hood Primary Latch Release Cable Replacement | B1720 | GMNA |
| 1410470 | Hood Primary Latch Release Cable Replacement | B1721 | GMNA |
| 1410470 | Hood Primary Latch Release Cable Replacement | B1727 | GMNA |
| 1410470 | Hood Primary Latch Release Cable Replacement | B9880 | GMNA |
| 1410470 | Hood Primary Latch Release Cable Replacement | A517500 | Holden Australia |
| 1410470 | Hood Primary Latch Release Cable Replacement | B163000 | Holden Australia |
| 1410470 | Hood Primary Latch Release Cable Replacement | A517500 | Holden New Zealand |
| 1410470 | Hood Primary Latch Release Cable Replacement | B1630 | Holden New Zealand |
| 1410470 | Hood Primary Latch Release Cable Replacement | B163000 | Holden New Zealand |
| 1410470 | Hood Primary Latch Release Cable Replacement | 9730500 | GMK Overseas |
| 1410490 | Hood Primary Latch Release Cable Handle Replacement | B1634 | GMNA |
| 1410490 | Hood Primary Latch Release Cable Handle Replacement | B1635 | GMNA |
| 1410490 | Hood Primary Latch Release Cable Handle Replacement | 8631500 | GMK Domestic |
| 1410490 | Hood Primary Latch Release Cable Handle Replacement | A000345 | Holden Australia |
| 1410490 | Hood Primary Latch Release Cable Handle Replacement | 9730600 | GMK Overseas |
| 1410490 | Hood Primary Latch Release Cable Handle Replacement | 9740200 | GMK Overseas |
| 1410570 | Hood Stop Bumper Replacement | B1650 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1410570 | Hood Stop Bumper Replacement | B9881 | GMNA |
| 1410570 | Hood Stop Bumper Replacement | B1650 | Holden Australia |
| 1410570 | Hood Stop Bumper Replacement | R603900 | Holden Australia |
| 1410570 | Hood Stop Bumper Replacement | 9731500 | GMK Overseas |
| 1410570 | Hood Stop Bumper Replacement | 9740500 | GMK Overseas |
| 1410620 | Hood Strut Replacement | B1670 | GMNA |
| 1410620 | Hood Strut Replacement | B1671 | GMNA |
| 1410620 | Hood Strut Replacement | B1677 | GMNA |
| 1410620 | Hood Strut Replacement | A502400 | Holden Australia |
| 1410620 | Hood Strut Replacement | A502500 | Holden Australia |
| 1410620 | Hood Strut Replacement | A502400 | Holden New Zealand |
| 1410620 | Hood Strut Replacement | A502500 | Holden New Zealand |
| 1410620 | Hood Strut Replacement | 9732100 | GMK Overseas |
| 1410620 | Hood Strut Replacement | 9732110 | GMK Overseas |
| 1410620 | Hood Strut Replacement | 9732120 | GMK Overseas |
| 1410640 | Hood Open Assist Rod Replacement | B1672 | GMNA |
| 1410640 | Hood Open Assist Rod Replacement | A502300 | Holden Australia |
| 1410640 | Hood Open Assist Rod Replacement | A502300 | Holden New Zealand |
| 1410640 | Hood Open Assist Rod Replacement | 9740300 | GMK Overseas |
| 1410780 | Hood Hinge Replacement | B1560 | GMNA |
| 1410780 | Hood Hinge Replacement | B1660 | GMNA |
| 1410780 | Hood Hinge Replacement | B1700 | GMNA |
| 1410780 | Hood Hinge Replacement | B1710 | GMNA |
| 1410780 | Hood Hinge Replacement | B1711 | GMNA |
| 1410780 | Hood Hinge Replacement | B1712 | GMNA |
| 1410780 | Hood Hinge Replacement | B1717 | GMNA |
| 1410780 | Hood Hinge Replacement | B1953 | GMNA |
| 1410780 | Hood Hinge Replacement | B1954 | GMNA |
| 1410780 | Hood Hinge Replacement | 8431000 | GMK Domestic |
| 1410780 | Hood Hinge Replacement | A501100 | Holden Australia |
| 1410780 | Hood Hinge Replacement | A501200 | Holden Australia |
| 1410780 | Hood Hinge Replacement | B171000 | Holden Australia |
| 1410780 | Hood Hinge Replacement | B1711 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1410780 | Hood Hinge Replacement | B171100 | Holden Australia |
| 1410780 | Hood Hinge Replacement | B1712 | Holden Australia |
| 1410780 | Hood Hinge Replacement | B171700 | Holden Australia |
| 1410780 | Hood Hinge Replacement | A501100 | Holden New Zealand |
| 1410780 | Hood Hinge Replacement | A501200 | Holden New Zealand |
| 1410780 | Hood Hinge Replacement | 9730900 | GMK Overseas |
| 1410780 | Hood Hinge Replacement | 9731100 | GMK Overseas |
| 1410780 | Hood Hinge Replacement | 9731200 | GMK Overseas |
| 1410780 | Hood Hinge Replacement | 9731300 | GMK Overseas |
| 1410780 | Hood Hinge Replacement | 9740700 | GMK Overseas |
| 1410790 | Plenum Front Panel Replacement | | |
| 1410890 | Plenum Lower Panel Replacement | A9100 | GMNA |
| 1410890 | Plenum Lower Panel Replacement | B1749 | GMNA |
| 1410890 | Plenum Lower Panel Replacement | D907400 | Holden Australia |
| 1410890 | Plenum Lower Panel Replacement | D907400 | Holden New Zealand |
| 1411182 | Front Fender Alignment | A0682 | GMNA |
| 1411182 | Front Fender Alignment | B1880 | GMNA |
| 1411182 | Front Fender Alignment | B1881 | GMNA |
| 1411182 | Front Fender Alignment | 8211720 | GMK Domestic |
| 1411182 | Front Fender Alignment | 8426800 | GMK Domestic |
| 1411182 | Front Fender Alignment | A068000 | Holden Australia |
| 1411182 | Front Fender Alignment | A068100 | Holden Australia |
| 1411182 | Front Fender Alignment | B188000 | Holden Australia |
| 1411182 | Front Fender Alignment | B188100 | Holden Australia |
| 1411182 | Front Fender Alignment | B188000 | Holden New Zealand |
| 1411182 | Front Fender Alignment | 9750700 | GMK Overseas |
| 1411232 | Front Side Door Adjustment | B2026 | GMNA |
| 1411232 | Front Side Door Adjustment | B4000 | GMNA |
| 1411232 | Front Side Door Adjustment | B4001 | GMNA |
| 1411232 | Front Side Door Adjustment | B4210 | GMNA |
| 1411232 | Front Side Door Adjustment | B4211 | GMNA |
| 1411232 | Front Side Door Adjustment | B4380 | GMNA |
| 1411232 | Front Side Door Adjustment | B5002 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1411232 | Front Side Door Adjustment | B5003 | GMNA |
| 1411232 | Front Side Door Adjustment | B5004 | GMNA |
| 1411232 | Front Side Door Adjustment | B5005 | GMNA |
| 1411232 | Front Side Door Adjustment | B5006 | GMNA |
| 1411232 | Front Side Door Adjustment | B5008 | GMNA |
| 1411232 | Front Side Door Adjustment | B9777 | GMNA |
| 1411232 | Front Side Door Adjustment | C9758 | GMNA |
| 1411232 | Front Side Door Adjustment | C9759 | GMNA |
| 1411232 | Front Side Door Adjustment | C9772 | GMNA |
| 1411232 | Front Side Door Adjustment | C9773 | GMNA |
| 1411232 | Front Side Door Adjustment | C9845 | GMNA |
| 1411232 | Front Side Door Adjustment | B4000 | Holden Australia |
| 1411232 | Front Side Door Adjustment | B400000 | Holden Australia |
| 1411232 | Front Side Door Adjustment | B400100 | Holden Australia |
| 1411232 | Front Side Door Adjustment | C000313 | Holden Australia |
| 1411232 | Front Side Door Adjustment | C000316 | Holden Australia |
| 1411232 | Front Side Door Adjustment | C030000 | Holden Australia |
| 1411232 | Front Side Door Adjustment | C030100 | Holden Australia |
| 1411232 | Front Side Door Adjustment | C161000 | Holden Australia |
| 1411232 | Front Side Door Adjustment | C161100 | Holden Australia |
| 1411232 | Front Side Door Adjustment | P001120 | Holden Australia |
| 1411232 | Front Side Door Adjustment | B4000 | Holden New Zealand |
| 1411232 | Front Side Door Adjustment | B400000 | Holden New Zealand |
| 1411232 | Front Side Door Adjustment | B4001 | Holden New Zealand |
| 1411232 | Front Side Door Adjustment | B400100 | Holden New Zealand |
| 1411232 | Front Side Door Adjustment | C000313 | Holden New Zealand |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | A3060 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4010 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4012 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4013 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4014 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4015 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4018 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4019 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4022 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4023 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4024 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4025 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4032 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4033 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4034 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4035 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4042 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4043 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4044 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4045 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4052 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4053 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4060 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4061 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4062 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4082 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B9920 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | S0720 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | S0721 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | S0740 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | S0741 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | S0780 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | S0781 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | S0970 | GMNA |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | 8420700 | GMK Domestic |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4010 | Holden Australia |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B401200 | Holden Australia |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B401300 | Holden Australia |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B401400 | Holden Australia |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B401500 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | C625100 | Holden Australia |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | C625150 | Holden Australia |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | C625200 | Holden Australia |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | C625250 | Holden Australia |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4010 | Holden New Zealand |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B4012 | Holden New Zealand |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | B401200 | Holden New Zealand |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | C625100 | Holden New Zealand |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | C625150 | Holden New Zealand |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | C625200 | Holden New Zealand |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | C625250 | Holden New Zealand |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | 9611200 | GMK Overseas |
| 1411340 | Front Side Door Upper Hinge and Lower Hinge Replacement | 9611300 | GMK Overseas |
| 1411780 | Front Side Door Hinge Spring Replacement | B4050 | GMNA |
| 1412150 | Front Side Door Check Link Replacement | B4072 | GMNA |
| 1412150 | Front Side Door Check Link Replacement | B407200 | Holden Australia |
| 1412150 | Front Side Door Check Link Replacement | C000556 | Holden Australia |
| 1412150 | Front Side Door Check Link Replacement | C634000 | Holden Australia |
| 1412150 | Front Side Door Check Link Replacement | C634050 | Holden Australia |
| 1412150 | Front Side Door Check Link Replacement | C634100 | Holden Australia |
| 1412150 | Front Side Door Check Link Replacement | C634150 | Holden Australia |
| 1412150 | Front Side Door Check Link Replacement | C634200 | Holden Australia |
| 1412150 | Front Side Door Check Link Replacement | C634250 | Holden Australia |
| 1412150 | Front Side Door Check Link Replacement | B407200 | Holden New Zealand |
| 1412150 | Front Side Door Check Link Replacement | C626100 | Holden New Zealand |
| 1412150 | Front Side Door Check Link Replacement | C634000 | Holden New Zealand |
| 1412150 | Front Side Door Check Link Replacement | C634050 | Holden New Zealand |
| 1412150 | Front Side Door Check Link Replacement | C634100 | Holden New Zealand |
| 1412150 | Front Side Door Check Link Replacement | C634150 | Holden New Zealand |
| 1412150 | Front Side Door Check Link Replacement | C634200 | Holden New Zealand |
| 1412150 | Front Side Door Check Link Replacement | C634250 | Holden New Zealand |
| 1412170 | Front Side Door Wiring Conduit Replacement - Right Side | B4100 | GMNA |
| 1412190 | Front Side Door Wiring Conduit Replacement - Left Side | B4101 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1412330 | Front Side Door Upper Auxiliary Sealing Strip Replacement | B4375 | GMNA |
| 1412350 | Front Side Door Bottom Auxiliary Sealing Strip Replacement | B4376 | GMNA |
| 1412512 | Rear Side Door Adjustment | B4400 | Holden Australia |
| 1412512 | Rear Side Door Adjustment | B4400 | Holden New Zealand |
| 1412560 | Rear Side Door Hinge Cover Replacement | B4406 | GMNA |
| 1412580 | Rear Side Door Hinge Pin and Bushing Replacement | B4409 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4407 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4410 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4412 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4413 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4414 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4415 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4418 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4419 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4422 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4423 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4424 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4425 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4432 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4433 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4434 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4435 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4442 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4443 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4444 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4445 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4452 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4461 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4812 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B5010 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B5011 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B5015 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B5016 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B5017 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B5018 | GMNA |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B4410 | Holden Australia |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B441200 | Holden Australia |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B441300 | Holden Australia |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B441400 | Holden Australia |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B441500 | Holden Australia |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B611200 | Holden Australia |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B611300 | Holden Australia |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B633000 | Holden Australia |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B633100 | Holden Australia |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B640100 | Holden Australia |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B660000 | Holden Australia |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | B660100 | Holden Australia |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | C644100 | Holden Australia |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | C644150 | Holden Australia |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | C644200 | Holden Australia |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | C644250 | Holden Australia |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | C644100 | Holden New Zealand |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | C644150 | Holden New Zealand |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | C644250 | Holden New Zealand |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | 9631200 | GMK Overseas |
| 1412600 | Rear Side Door Upper Hinge and Lower Hinge Replacement | 9631300 | GMK Overseas |
| 1413270 | Rear Side Door Check Link Replacement | B4472 | GMNA |
| 1413270 | Rear Side Door Check Link Replacement | B4480 | GMNA |
| 1413270 | Rear Side Door Check Link Replacement | B4481 | GMNA |
| 1413270 | Rear Side Door Check Link Replacement | B5024 | GMNA |
| 1413270 | Rear Side Door Check Link Replacement | B6140 | GMNA |
| 1413270 | Rear Side Door Check Link Replacement | B6141 | GMNA |
| 1413270 | Rear Side Door Check Link Replacement | B6143 | GMNA |
| 1413270 | Rear Side Door Check Link Replacement | B9870 | GMNA |
| 1413270 | Rear Side Door Check Link Replacement | B434100 | Holden Australia |
| 1413270 | Rear Side Door Check Link Replacement | C636100 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1413270 | Rear Side Door Check Link Replacement | C636150 | Holden Australia |
| 1413270 | Rear Side Door Check Link Replacement | C636200 | Holden Australia |
| 1413270 | Rear Side Door Check Link Replacement | C636250 | Holden Australia |
| 1413270 | Rear Side Door Check Link Replacement | C646700 | Holden Australia |
| 1413270 | Rear Side Door Check Link Replacement | C636100 | Holden New Zealand |
| 1413270 | Rear Side Door Check Link Replacement | C636150 | Holden New Zealand |
| 1413270 | Rear Side Door Check Link Replacement | C636200 | Holden New Zealand |
| 1413270 | Rear Side Door Check Link Replacement | C636250 | Holden New Zealand |
| 1413270 | Rear Side Door Check Link Replacement | C646700 | Holden New Zealand |
| 1413270 | Rear Side Door Check Link Replacement | 9631500 | GMK Overseas |
| 1413270 | Rear Side Door Check Link Replacement | 9631600 | GMK Overseas |
| 1413350 | Rear Side Door Wiring Conduit Replacement - Right Side | B4500 | GMNA |
| 1413370 | Rear Side Door Wiring Conduit Replacement - Left Side | B4501 | GMNA |
| 1413420 | Rear Side Door Wedge Replacement - Door Side | B4649 | GMNA |
| 1413430 | Rear Side Door Bottom Auxiliary Sealing Strip Replacement | B4750 | GMNA |
| 1413440 | Rear Side Door Lower Rear Auxiliary Sealing Strip Replacement | B4752 | GMNA |
| 1413440 | Rear Side Door Lower Rear Auxiliary Sealing Strip Replacement | 8625600 | GMK Domestic |
| 1413640 | Intermediate Side Door Hinge Replacement - Body Side | | |
| 1413780 | Intermediate Side Door Check Strap Replacement | B5022 | GMNA |
| 1413830 | Rear Side Door Upper Track Replacement | B5021 | GMNA |
| 1413830 | Rear Side Door Upper Track Replacement | B5025 | GMNA |
| 1413830 | Rear Side Door Upper Track Replacement | B5026 | GMNA |
| 1413830 | Rear Side Door Upper Track Replacement | B5029 | GMNA |
| 1413880 | Rear Side Door Lower Track Replacement | B5027 | GMNA |
| 1413900 | Rear Side Door Upper Roller Bracket Replacement | | |
| 1413920 | Rear Side Door Lower Roller Bracket Replacement | | |
| 1413940 | Rear Side Door Center Roller Bracket Replacement | B5020 | GMNA |
| 1413940 | Rear Side Door Center Roller Bracket Replacement | B5033 | GMNA |
| 1413940 | Rear Side Door Center Roller Bracket Replacement | B5034 | GMNA |
| 1413940 | Rear Side Door Center Roller Bracket Replacement | B5035 | GMNA |
| 1413940 | Rear Side Door Center Roller Bracket Replacement | B5037 | GMNA |
| 1413940 | Rear Side Door Center Roller Bracket Replacement | B5038 | GMNA |
| 1413940 | Rear Side Door Center Roller Bracket Replacement | B5039 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1414050 | Pickup Box Endgate Liner Replacement | B5291 | GMNA |
| 1414072 | Rear Compartment Lift Window Panel Adjustment | B5390 | GMNA |
| 1414072 | Rear Compartment Lift Window Panel Adjustment | B5393 | GMNA |
| 1414092 | Rear Compartment Lid Adjustment | A9580 | GMNA |
| 1414092 | Rear Compartment Lid Adjustment | B5400 | GMNA |
| 1414092 | Rear Compartment Lid Adjustment | B5405 | GMNA |
| 1414092 | Rear Compartment Lid Adjustment | B9844 | GMNA |
| 1414092 | Rear Compartment Lid Adjustment | R4040 | GMNA |
| 1414092 | Rear Compartment Lid Adjustment | T1787 | GMNA |
| 1414092 | Rear Compartment Lid Adjustment | C000391 | Holden Australia |
| 1414092 | Rear Compartment Lid Adjustment | P002100 | Holden Australia |
| 1414092 | Rear Compartment Lid Adjustment | P003900 | Holden Australia |
| 1414092 | Rear Compartment Lid Adjustment | P002100 | Holden New Zealand |
| 1414092 | Rear Compartment Lid Adjustment | P003900 | Holden New Zealand |
| 1414110 | Rear Compartment Lid Bumper Replacement | 8643500 | GMK Domestic |
| 1414110 | Rear Compartment Lid Bumper Replacement | 8643600 | GMK Domestic |
| 1414130 | Rear Compartment Lid Hinge Replacement | B5419 | GMNA |
| 1414130 | Rear Compartment Lid Hinge Replacement | B5420 | GMNA |
| 1414130 | Rear Compartment Lid Hinge Replacement | B5421 | GMNA |
| 1414130 | Rear Compartment Lid Hinge Replacement | B5427 | GMNA |
| 1414130 | Rear Compartment Lid Hinge Replacement | B5430 | GMNA |
| 1414130 | Rear Compartment Lid Hinge Replacement | B5431 | GMNA |
| 1414130 | Rear Compartment Lid Hinge Replacement | B5437 | GMNA |
| 1414130 | Rear Compartment Lid Hinge Replacement | B5440 | GMNA |
| 1414130 | Rear Compartment Lid Hinge Replacement | B5441 | GMNA |
| 1414130 | Rear Compartment Lid Hinge Replacement | B5447 | GMNA |
| 1414130 | Rear Compartment Lid Hinge Replacement | A320100 | Holden Australia |
| 1414130 | Rear Compartment Lid Hinge Replacement | A320300 | Holden Australia |
| 1414130 | Rear Compartment Lid Hinge Replacement | C701300 | Holden Australia |
| 1414130 | Rear Compartment Lid Hinge Replacement | C701400 | Holden Australia |
| 1414130 | Rear Compartment Lid Hinge Replacement | A320100 | Holden New Zealand |
| 1414130 | Rear Compartment Lid Hinge Replacement | A320300 | Holden New Zealand |
| 1414130 | Rear Compartment Lid Hinge Replacement | C701300 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1414130 | Rear Compartment Lid Hinge Replacement | C701400 | Holden New Zealand |
| 1414130 | Rear Compartment Lid Hinge Replacement | 9780100 | GMK Overseas |
| 1414130 | Rear Compartment Lid Hinge Replacement | 9780200 | GMK Overseas |
| 1414130 | Rear Compartment Lid Hinge Replacement | 9780600 | GMK Overseas |
| 1414130 | Rear Compartment Lid Hinge Replacement | 9786100 | GMK Overseas |
| 1414130 | Rear Compartment Lid Hinge Replacement | 9786200 | GMK Overseas |
| 1414130 | Rear Compartment Lid Hinge Replacement | 9786300 | GMK Overseas |
| 1414390 | Rear Compartment Lid Strut Replacement | B5452 | GMNA |
| 1414390 | Rear Compartment Lid Strut Replacement | 8640800 | GMK Domestic |
| 1414390 | Rear Compartment Lid Strut Replacement | C756000 | Holden Australia |
| 1414390 | Rear Compartment Lid Strut Replacement | C756200 | Holden Australia |
| 1414390 | Rear Compartment Lid Strut Replacement | C702600 | Holden New Zealand |
| 1414390 | Rear Compartment Lid Strut Replacement | C756000 | Holden New Zealand |
| 1414390 | Rear Compartment Lid Strut Replacement | C756100 | Holden New Zealand |
| 1414390 | Rear Compartment Lid Strut Replacement | C756200 | Holden New Zealand |
| 1414390 | Rear Compartment Lid Strut Replacement | 9781400 | GMK Overseas |
| 1414390 | Rear Compartment Lid Strut Replacement | 9781410 | GMK Overseas |
| 1414390 | Rear Compartment Lid Strut Replacement | 9781420 | GMK Overseas |
| 1414460 | Rear Compartment Lid Hinge Torque Rod Replacement | B5459 | GMNA |
| 1414460 | Rear Compartment Lid Hinge Torque Rod Replacement | B5460 | GMNA |
| 1414460 | Rear Compartment Lid Hinge Torque Rod Replacement | B5461 | GMNA |
| 1414460 | Rear Compartment Lid Hinge Torque Rod Replacement | B5462 | GMNA |
| 1414460 | Rear Compartment Lid Hinge Torque Rod Replacement | R4045 | GMNA |
| 1414460 | Rear Compartment Lid Hinge Torque Rod Replacement | 9780500 | GMK Overseas |
| 1414460 | Rear Compartment Lid Hinge Torque Rod Replacement | 9780700 | GMK Overseas |
| 1414462 | Rear Compartment Lid Hinge Torque Rod Adjustment | B5458 | GMNA |
| 1414462 | Rear Compartment Lid Hinge Torque Rod Adjustment | B5463 | GMNA |
| 1414462 | Rear Compartment Lid Hinge Torque Rod Adjustment | B5464 | GMNA |
| 1414462 | Rear Compartment Lid Hinge Torque Rod Adjustment | 8640500 | GMK Domestic |
| 1414570 | Rear Compartment Lid Lock Cylinder Rod Replacement | B5481 | GMNA |
| 1414590 | Roof Panel Replacement | A9200 | GMNA |
| 1414590 | Roof Panel Replacement | A9201 | GMNA |
| 1414590 | Roof Panel Replacement | A9220 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1414590 | Roof Panel Replacement | A9221 | GMNA |
| 1414590 | Roof Panel Replacement | B5654 | GMNA |
| 1414590 | Roof Panel Replacement | S5170 | GMNA |
| 1414590 | Roof Panel Replacement | A9220 | Holden New Zealand |
| 1414590 | Roof Panel Replacement | 9712500 | GMK Overseas |
| 1414610 | Roof Panel Rear Extension Replacement | B5655 | GMNA |
| 1414632 | Liftgate Adjustment | B5700 | GMNA |
| 1414632 | Liftgate Adjustment | B570000 | Holden Australia |
| 1414632 | Liftgate Adjustment | B5700 | Holden New Zealand |
| 1414632 | Liftgate Adjustment | B570000 | Holden New Zealand |
| 1414652 | Endgate Adjustment | B5701 | GMNA |
| 1414700 | Liftgate Adjust Bumper Replacement | B1595 | GMNA |
| 1414700 | Liftgate Adjust Bumper Replacement | B5703 | GMNA |
| 1414720 | Liftgate Hinge Replacement | A9912 | GMNA |
| 1414720 | Liftgate Hinge Replacement | B5710 | GMNA |
| 1414720 | Liftgate Hinge Replacement | B5711 | GMNA |
| 1414720 | Liftgate Hinge Replacement | B5712 | GMNA |
| 1414720 | Liftgate Hinge Replacement | B571000 | Holden Australia |
| 1414720 | Liftgate Hinge Replacement | B571100 | Holden Australia |
| 1414720 | Liftgate Hinge Replacement | C701110 | Holden Australia |
| 1414720 | Liftgate Hinge Replacement | C701210 | Holden Australia |
| 1414720 | Liftgate Hinge Replacement | B571000 | Holden New Zealand |
| 1414720 | Liftgate Hinge Replacement | C701110 | Holden New Zealand |
| 1414720 | Liftgate Hinge Replacement | C701210 | Holden New Zealand |
| 1414720 | Liftgate Hinge Replacement | 9788900 | GMK Overseas |
| 1414770 | Endgate Lower Hinge Replacement - Body Side | B5719 | GMNA |
| 1414790 | Endgate Hinge Replacement | B5720 | GMNA |
| 1414790 | Endgate Hinge Replacement | B5721 | GMNA |
| 1414790 | Endgate Hinge Replacement | B5730 | GMNA |
| 1414790 | Endgate Hinge Replacement | B5731 | GMNA |
| 1414950 | Endgate Cable Replacement | B5752 | GMNA |
| 1414990 | Liftgate Wedge Replacement | B5785 | GMNA |
| 1415010 | Endgate Torque Rod Replacement | B5790 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1415030 | Liftgate Strut Replacement | B5933 | GMNA |
| 1415030 | Liftgate Strut Replacement | 8626300 | GMK Domestic |
| 1415030 | Liftgate Strut Replacement | 8626400 | GMK Domestic |
| 1415030 | Liftgate Strut Replacement | 8626600 | GMK Domestic |
| 1415030 | Liftgate Strut Replacement | 8626800 | GMK Domestic |
| 1415030 | Liftgate Strut Replacement | 8643700 | GMK Domestic |
| 1415030 | Liftgate Strut Replacement | 8643900 | GMK Domestic |
| 1415030 | Liftgate Strut Replacement | 9781100 | GMK Overseas |
| 1415110 | Liftgate Strut Ball Stud Replacement | B5845 | GMNA |
| 1415110 | Liftgate Strut Ball Stud Replacement | B5937 | GMNA |
| 1415160 | Fuel Tank Filler Door Replacement | B6000 | GMNA |
| 1415160 | Fuel Tank Filler Door Replacement | L9718 | GMNA |
| 1415160 | Fuel Tank Filler Door Replacement | T9701 | GMNA |
| 1415160 | Fuel Tank Filler Door Replacement | T9702 | GMNA |
| 1415160 | Fuel Tank Filler Door Replacement | B6000 | Holden Australia |
| 1415160 | Fuel Tank Filler Door Replacement | B670100 | Holden Australia |
| 1415160 | Fuel Tank Filler Door Replacement | L006200 | Holden Australia |
| 1415160 | Fuel Tank Filler Door Replacement | L006200 | Holden New Zealand |
| 1415160 | Fuel Tank Filler Door Replacement | 9660100 | GMK Overseas |
| 1415180 | Fuel Tank Filler Door Hinge Replacement | B6005 | GMNA |
| 1415230 | Fuel Tank Filler Pipe Housing Replacement | B6007 | GMNA |
| 1415230 | Fuel Tank Filler Pipe Housing Replacement | B9975 | GMNA |
| 1415230 | Fuel Tank Filler Pipe Housing Replacement | 1451000 | GMK Domestic |
| 1415230 | Fuel Tank Filler Pipe Housing Replacement | 1451600 | GMK Domestic |
| 1415230 | Fuel Tank Filler Pipe Housing Replacement | 1711400 | GMK Overseas |
| 1415230 | Fuel Tank Filler Pipe Housing Replacement | 9662100 | GMK Overseas |
| 1415250 | Fuel Tank Filler Valve Housing Replacement | B6008 | GMNA |
| 1415250 | Fuel Tank Filler Valve Housing Replacement | 9662300 | GMK Overseas |
| 1415270 | Fuel Tank Filler Door Spring Replacement | B6009 | GMNA |
| 1415320 | Fuel Tank Filler Door Latch Housing Replacement | B6011 | GMNA |
| 1415370 | Fuel Filler Door Latch Striker Replacement | B6030 | GMNA |
| 1415390 | Fuel Tank Filler Door Latch Replacement | B6035 | GMNA |
| 1415440 | Cargo Box Cover Latch Replacement | B6038 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1415460 | Cargo Box Front Cover, Center Cover, and Rear Cover Replacement | B6039 | GMNA |
| 1415480 | Cargo Box Stowage Box Lid Replacement | B6040 | GMNA |
| 1415560 | Midgate Inner Panel Replacement | B6050 | GMNA |
| 1415580 | Midgate Outer Panel Replacement | B6051 | GMNA |
| 1415600 | Midgate Hinge Replacement | B6052 | GMNA |
| 1415650 | Cargo Box Stowage Box Replacement | B6070 | GMNA |
| 1415650 | Cargo Box Stowage Box Replacement | B6071 | GMNA |
| 1415650 | Cargo Box Stowage Box Replacement | B8834 | GMNA |
| 1415650 | Cargo Box Stowage Box Replacement | B8835 | GMNA |
| 1415700 | Cargo Box Side Drain Gutter Replacement | B6082 | GMNA |
| 1415700 | Cargo Box Side Drain Gutter Replacement | 9710800 | GMK Overseas |
| 1415722 | Rear Door Adjustment | B6100 | GMNA |
| 1415722 | Rear Door Adjustment | B6101 | GMNA |
| 1415722 | Rear Door Adjustment | B610000 | Holden Australia |
| 1415722 | Rear Door Adjustment | B610100 | Holden Australia |
| 1415740 | Rear Door Hinge Replacement | B6112 | GMNA |
| 1415850 | Rear Compartment Front Panel Replacement | B6249 | GMNA |
| 1415990 | Front Fender Insulator Replacement | B1950 | GMNA |
| 1415990 | Front Fender Insulator Replacement | B1951 | GMNA |
| 1415990 | Front Fender Insulator Replacement | B7505 | GMNA |
| 1415990 | Front Fender Insulator Replacement | B7506 | GMNA |
| 1415990 | Front Fender Insulator Replacement | 9750800 | GMK Overseas |
| 1416000 | Rear Side Door Window Frame Rear Applique Replacement | | |
| 1416100 | Quarter Panel Lower Rear Molding Replacement | B8268 | GMNA |
| 1416230 | Cargo Box Bridge Cross Bar Replacement | B8833 | GMNA |
| 1416250 | Cargo Box Bridge Side Outer Panel Replacement | | |
| 1416270 | Cargo Box Bridge Side Inner Panel Replacement | | |
| 1416290 | Liftgate Hinge Seal Replacement | C0732 | GMNA |
| 1416300 | Liftgate Window Strut Replacement | C756100 | Holden Australia |
| 1416400 | Front Side Door Roof Drip Weatherstrip Replacement | C1022 | GMNA |
| 1416480 | Hood Front Weatherstrip Replacement | 9732900 | GMK Overseas |
| 1416500 | Hood Rear Weatherstrip Replacement | 9760900 | GMK Overseas |
| 1416580 | Front Side Door Upper Auxiliary Weatherstrip Replacement | C1052 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1416580 | Front Side Door Upper Auxiliary Weatherstrip Replacement | C1095 | Holden Australia |
| 1416580 | Front Side Door Upper Auxiliary Weatherstrip Replacement | C134100 | Holden Australia |
| 1416580 | Front Side Door Upper Auxiliary Weatherstrip Replacement | C134200 | Holden Australia |
| 1416580 | Front Side Door Upper Auxiliary Weatherstrip Replacement | C134100 | Holden New Zealand |
| 1416580 | Front Side Door Upper Auxiliary Weatherstrip Replacement | C134200 | Holden New Zealand |
| 1416630 | Front Side Door Lower Auxiliary Weatherstrip Replacement | C1054 | GMNA |
| 1416640 | Front Side Door Front Auxiliary Weatherstrip Replacement | | |
| 1416650 | Front Side Door Weatherstrip Replacement - Door Side | C1059 | GMNA |
| 1416650 | Front Side Door Weatherstrip Replacement - Door Side | 8614200 | GMK Domestic |
| 1416650 | Front Side Door Weatherstrip Replacement - Door Side | 9618100 | GMK Overseas |
| 1416650 | Front Side Door Weatherstrip Replacement - Door Side | 9618200 | GMK Overseas |
| 1416670 | Front Side Door Weatherstrip Replacement | B6807 | GMNA |
| 1416670 | Front Side Door Weatherstrip Replacement | B9901 | GMNA |
| 1416670 | Front Side Door Weatherstrip Replacement | B9948 | GMNA |
| 1416670 | Front Side Door Weatherstrip Replacement | C1051 | GMNA |
| 1416670 | Front Side Door Weatherstrip Replacement | C1060 | GMNA |
| 1416670 | Front Side Door Weatherstrip Replacement | C1062 | GMNA |
| 1416670 | Front Side Door Weatherstrip Replacement | C9903 | GMNA |
| 1416670 | Front Side Door Weatherstrip Replacement | C9975 | GMNA |
| 1416670 | Front Side Door Weatherstrip Replacement | C000322 | Holden Australia |
| 1416670 | Front Side Door Weatherstrip Replacement | C000707 | Holden Australia |
| 1416670 | Front Side Door Weatherstrip Replacement | C013110 | Holden Australia |
| 1416670 | Front Side Door Weatherstrip Replacement | C013210 | Holden Australia |
| 1416670 | Front Side Door Weatherstrip Replacement | C105100 | Holden Australia |
| 1416670 | Front Side Door Weatherstrip Replacement | C105200 | Holden Australia |
| 1416670 | Front Side Door Weatherstrip Replacement | C1059 | Holden Australia |
| 1416670 | Front Side Door Weatherstrip Replacement | C1060 | Holden Australia |
| 1416670 | Front Side Door Weatherstrip Replacement | C106000 | Holden Australia |
| 1416670 | Front Side Door Weatherstrip Replacement | C106200 | Holden Australia |
| 1416670 | Front Side Door Weatherstrip Replacement | C000322 | Holden New Zealand |
| 1416670 | Front Side Door Weatherstrip Replacement | C000707 | Holden New Zealand |
| 1416670 | Front Side Door Weatherstrip Replacement | C105100 | Holden New Zealand |
| 1416670 | Front Side Door Weatherstrip Replacement | C105200 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1416670 | Front Side Door Weatherstrip Replacement | C1060 | Holden New Zealand |
| 1416670 | Front Side Door Weatherstrip Replacement | C106000 | Holden New Zealand |
| 1416670 | Front Side Door Weatherstrip Replacement | C106200 | Holden New Zealand |
| 1416680 | Front Side Door Front Lower Weatherstrip Replacement | | |
| 1416720 | Front Side Door Rear Weatherstrip Replacement | C1070 | GMNA |
| 1416740 | Front Side Door Weatherstrip Replacement - Body Side | C1080 | GMNA |
| 1416740 | Front Side Door Weatherstrip Replacement - Body Side | 8614300 | GMK Domestic |
| 1416740 | Front Side Door Weatherstrip Replacement - Body Side | 8614400 | GMK Domestic |
| 1416740 | Front Side Door Weatherstrip Replacement - Body Side | 9618250 | GMK Overseas |
| 1416740 | Front Side Door Weatherstrip Replacement - Body Side | 9618260 | GMK Overseas |
| 1416740 | Front Side Door Weatherstrip Replacement - Body Side | 9618900 | GMK Overseas |
| 1416740 | Front Side Door Weatherstrip Replacement - Body Side | 9619000 | GMK Overseas |
| 1416850 | Front Side Door Auxiliary Weatherstrip Replacement | C1095 | GMNA |
| 1416850 | Front Side Door Auxiliary Weatherstrip Replacement | C000674 | Holden Australia |
| 1416850 | Front Side Door Auxiliary Weatherstrip Replacement | C000674 | Holden New Zealand |
| 1416960 | Front or Rear Side Door Upper Auxiliary Weatherstrip Replacement | C1105 | GMNA |
| 1416960 | Front or Rear Side Door Upper Auxiliary Weatherstrip Replacement | C1106 | GMNA |
| 1417010 | Front or Rear Side Door Upper Weatherstrip Replacement | C1107 | GMNA |
| 1417030 | Front or Rear Side Door Lower Weatherstrip Replacement | 8614700 | GMK Domestic |
| 1417080 | Rear Side Door Weatherstrip Replacement - Door Side | C1119 | GMNA |
| 1417100 | Rear Side Door Weatherstrip Replacement | C1120 | GMNA |
| 1417100 | Rear Side Door Weatherstrip Replacement | 8433700 | GMK Domestic |
| 1417100 | Rear Side Door Weatherstrip Replacement | 8433702 | GMK Domestic |
| 1417100 | Rear Side Door Weatherstrip Replacement | 8455000 | GMK Domestic |
| 1417100 | Rear Side Door Weatherstrip Replacement | 8623500 | GMK Domestic |
| 1417100 | Rear Side Door Weatherstrip Replacement | 8628900 | GMK Domestic |
| 1417110 | Rear Side Door Lower Auxiliary Weatherstrip Replacement | | |
| 1417150 | Rear Side Door Upper Auxiliary Weatherstrip Replacement | C1124 | GMNA |
| 1417170 | Rear Side Door Front Auxiliary Weatherstrip Replacement | C1127 | GMNA |
| 1417170 | Rear Side Door Front Auxiliary Weatherstrip Replacement | 8625100 | GMK Domestic |
| 1417190 | Rear Side Door Weatherstrip Replacement - Body Side | C1130 | GMNA |
| 1417190 | Rear Side Door Weatherstrip Replacement - Body Side | 9638100 | GMK Overseas |
| 1417190 | Rear Side Door Weatherstrip Replacement - Body Side | 9638200 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1417190 | Rear Side Door Weatherstrip Replacement - Body Side | 9638800 | GMK Overseas |
| 1417190 | Rear Side Door Weatherstrip Replacement - Body Side | 9638900 | GMK Overseas |
| 1417240 | Rear Side Door Auxiliary Weatherstrip Replacement | C1136 | GMNA |
| 1417410 | Rear Side Door Lower Weatherstrip Replacement | C1164 | GMNA |
| 1417410 | Rear Side Door Lower Weatherstrip Replacement | 8625400 | GMK Domestic |
| 1417410 | Rear Side Door Lower Weatherstrip Replacement | 8625500 | GMK Domestic |
| 1417410 | Rear Side Door Lower Weatherstrip Replacement | 9639400 | GMK Overseas |
| 1417410 | Rear Side Door Lower Weatherstrip Replacement | 9639410 | GMK Overseas |
| 1417410 | Rear Side Door Lower Weatherstrip Replacement | 9639420 | GMK Overseas |
| 1417520 | Intermediate Side Door Weatherstrip Replacement | C1182 | GMNA |
| 1417570 | Rear Compartment Lid Weatherstrip Replacement | C1270 | GMNA |
| 1417570 | Rear Compartment Lid Weatherstrip Replacement | 8642000 | GMK Domestic |
| 1417570 | Rear Compartment Lid Weatherstrip Replacement | C125500 | Holden Australia |
| 1417570 | Rear Compartment Lid Weatherstrip Replacement | C125500 | Holden New Zealand |
| 1417570 | Rear Compartment Lid Weatherstrip Replacement | 9781500 | GMK Overseas |
| 1417570 | Rear Compartment Lid Weatherstrip Replacement | 9783200 | GMK Overseas |
| 1417620 | Midgate Window Weatherstrip Replacement | C1281 | GMNA |
| 1417640 | Cargo Box Stowage and Midgate Window Opening Weatherstrip Replacement | C1282 | GMNA |
| 1417660 | Rear Compartment Access Door Weatherstrip Replacement | | |
| 1417700 | Pickup Box Endgate Weatherstrip Replacement | C1327 | GMNA |
| 1417720 | Endgate Weatherstrip Replacement | C1328 | GMNA |
| 1417740 | Body Side Upper Front and Rear Access Panel Weatherstrip Replacement | C1329 | GMNA |
| 1417790 | Liftgate Weatherstrip Replacement | C1335 | GMNA |
| 1417790 | Liftgate Weatherstrip Replacement | 8627200 | GMK Domestic |
| 1417790 | Liftgate Weatherstrip Replacement | C126000 | Holden Australia |
| 1417790 | Liftgate Weatherstrip Replacement | C1328 | Holden Australia |
| 1417790 | Liftgate Weatherstrip Replacement | C126000 | Holden New Zealand |
| 1417790 | Liftgate Weatherstrip Replacement | 9783100 | GMK Overseas |
| 1417810 | Liftgate Upper Weatherstrip Replacement | C1336 | GMNA |
| 1417860 | Rear Door Weatherstrip Replacement | C1340 | GMNA |
| 1417860 | Rear Door Weatherstrip Replacement | C1341 | GMNA |
| 1417860 | Rear Door Weatherstrip Replacement | C126120 | Holden Australia |
| 1417860 | Rear Door Weatherstrip Replacement | C126220 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1417910 | Rear Door Weatherstrip Replacement - Left Side Lower | C1342 | GMNA |
| 1417930 | Rear Side Door Upper Weatherstrip Replacement - Left Side | C1343 | GMNA |
| 1418110 | Front or Rear Side Door Window Garnish Molding Replacement | C3406 | GMNA |
| 1418150 | Rear Compartment Lid Hinge Cover Replacement | C4605 | GMNA |
| 1418150 | Rear Compartment Lid Hinge Cover Replacement | C4606 | GMNA |
| 1418150 | Rear Compartment Lid Hinge Cover Replacement | C4607 | GMNA |
| 1418150 | Rear Compartment Lid Hinge Cover Replacement | C4607 | Holden Australia |
| 1420060 | Front Bumper Upper Fascia Replacement | B0042 | GMNA |
| 1420060 | Front Bumper Upper Fascia Replacement | 9563500 | GMK Overseas |
| 1420080 | Front Bumper Lower Fascia Replacement | B0043 | GMNA |
| 1420080 | Front Bumper Lower Fascia Replacement | 9563600 | GMK Overseas |
| 1420100 | Front Bumper Fascia Extension Replacement | B0044 | GMNA |
| 1420120 | Front Bumper Fascia Replacement | B0048 | GMNA |
| 1420120 | Front Bumper Fascia Replacement | B1318 | GMNA |
| 1420120 | Front Bumper Fascia Replacement | 8431200 | GMK Domestic |
| 1420120 | Front Bumper Fascia Replacement | 8431300 | GMK Domestic |
| 1420120 | Front Bumper Fascia Replacement | 8431400 | GMK Domestic |
| 1420120 | Front Bumper Fascia Replacement | B0048 | Holden Australia |
| 1420120 | Front Bumper Fascia Replacement | B0048 | Holden New Zealand |
| 1420120 | Front Bumper Fascia Replacement | 9560100 | GMK Overseas |
| 1420120 | Front Bumper Fascia Replacement | 956010A | GMK Overseas |
| 1420120 | Front Bumper Fascia Replacement | 956010B | GMK Overseas |
| 1420120 | Front Bumper Fascia Replacement | 956010E | GMK Overseas |
| 1420120 | Front Bumper Fascia Replacement | 956010F | GMK Overseas |
| 1420120 | Front Bumper Fascia Replacement | 956010G | GMK Overseas |
| 1420120 | Front Bumper Fascia Replacement | 956010I | GMK Overseas |
| 1420120 | Front Bumper Fascia Replacement | 9560700 | GMK Overseas |
| 1420122 | Front Bumper Fascia Alignment | B0020 | GMNA |
| 1420122 | Front Bumper Fascia Alignment | T6654 | GMNA |
| 1420122 | Front Bumper Fascia Alignment | 8431500 | GMK Domestic |
| 1420122 | Front Bumper Fascia Alignment | 8431600 | GMK Domestic |
| 1420122 | Front Bumper Fascia Alignment | A000330 | Holden Australia |
| 1420122 | Front Bumper Fascia Alignment | A000330 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1420140 | Front Bumper Fascia Inner Guide Replacement | B0049 | GMNA |
| 1420160 | Front Bumper Fascia Guide Replacement | B0050 | GMNA |
| 1420160 | Front Bumper Fascia Guide Replacement | A000357 | Holden Australia |
| 1420160 | Front Bumper Fascia Guide Replacement | A000357 | Holden New Zealand |
| 1420160 | Front Bumper Fascia Guide Replacement | 9560600 | GMK Overseas |
| 1420260 | Front Bumper Fascia Lower Stiffener Replacement | B0194 | GMNA |
| 1420260 | Front Bumper Fascia Lower Stiffener Replacement | B0210 | GMNA |
| 1420260 | Front Bumper Fascia Lower Stiffener Replacement | B0214 | GMNA |
| 1420260 | Front Bumper Fascia Lower Stiffener Replacement | B0216 | GMNA |
| 1420260 | Front Bumper Fascia Lower Stiffener Replacement | B0320 | GMNA |
| 1420260 | Front Bumper Fascia Lower Stiffener Replacement | B0321 | GMNA |
| 1420260 | Front Bumper Fascia Lower Stiffener Replacement | B0327 | GMNA |
| 1420260 | Front Bumper Fascia Lower Stiffener Replacement | B0360 | GMNA |
| 1420260 | Front Bumper Fascia Lower Stiffener Replacement | B0920 | GMNA |
| 1420260 | Front Bumper Fascia Lower Stiffener Replacement | B0921 | GMNA |
| 1420260 | Front Bumper Fascia Lower Stiffener Replacement | B021000 | Holden Australia |
| 1420260 | Front Bumper Fascia Lower Stiffener Replacement | B0210 | Holden New Zealand |
| 1420260 | Front Bumper Fascia Lower Stiffener Replacement | B021000 | Holden New Zealand |
| 1420280 | Front Bumper Fascia Support Replacement | B0195 | GMNA |
| 1420300 | Front Bumper Impact Bar Replacement | B0218 | GMNA |
| 1420300 | Front Bumper Impact Bar Replacement | 8431700 | GMK Domestic |
| 1420300 | Front Bumper Impact Bar Replacement | A560500 | Holden Australia |
| 1420300 | Front Bumper Impact Bar Replacement | A561500 | Holden Australia |
| 1420300 | Front Bumper Impact Bar Replacement | A561510 | Holden Australia |
| 1420300 | Front Bumper Impact Bar Replacement | B0218 | Holden Australia |
| 1420300 | Front Bumper Impact Bar Replacement | P006100 | Holden Australia |
| 1420300 | Front Bumper Impact Bar Replacement | A560500 | Holden New Zealand |
| 1420300 | Front Bumper Impact Bar Replacement | A561500 | Holden New Zealand |
| 1420300 | Front Bumper Impact Bar Replacement | A561510 | Holden New Zealand |
| 1420300 | Front Bumper Impact Bar Replacement | B0218 | Holden New Zealand |
| 1420300 | Front Bumper Impact Bar Replacement | B021800 | Holden New Zealand |
| 1420300 | Front Bumper Impact Bar Replacement | P006100 | Holden New Zealand |
| 1420300 | Front Bumper Impact Bar Replacement | 2154100 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1420300 | Front Bumper Impact Bar Replacement | 2154200 | GMK Overseas |
| 1420300 | Front Bumper Impact Bar Replacement | 9560300 | GMK Overseas |
| 1420300 | Front Bumper Impact Bar Replacement | 956030G | GMK Overseas |
| 1420320 | Front Bumper End Cap Replacement | B0240 | GMNA |
| 1420400 | Front Bumper Step Pad Replacement | B0243 | GMNA |
| 1420400 | Front Bumper Step Pad Replacement | B0350 | GMNA |
| 1420452 | Front Bumper Alignment | B0260 | GMNA |
| 1420510 | Front Bumper Fascia Molding Replacement | B0307 | GMNA |
| 1420510 | Front Bumper Fascia Molding Replacement | B0308 | GMNA |
| 1420510 | Front Bumper Fascia Molding Replacement | B0311 | GMNA |
| 1420510 | Front Bumper Fascia Molding Replacement | B0315 | GMNA |
| 1420510 | Front Bumper Fascia Molding Replacement | B9560 | GMNA |
| 1420510 | Front Bumper Fascia Molding Replacement | C734510 | Holden Australia |
| 1420510 | Front Bumper Fascia Molding Replacement | C734510 | Holden New Zealand |
| 1420610 | Front Bumper Fascia Energy Absorber Replacement | B0366 | GMNA |
| 1420610 | Front Bumper Fascia Energy Absorber Replacement | B0367 | GMNA |
| 1420610 | Front Bumper Fascia Energy Absorber Replacement | 9560500 | GMK Overseas |
| 1420720 | Front Bumper Fascia Skid Plate Replacement | B0393 | GMNA |
| 1420720 | Front Bumper Fascia Skid Plate Replacement | 9562000 | GMK Overseas |
| 1420730 | Front Bumper Outer Valance Panel Replacement | | |
| 1420740 | Front Bumper Valance Panel Replacement | B0400 | GMNA |
| 1420760 | Front Bumper Fascia Seal Replacement | B0401 | GMNA |
| 1420780 | Radiator Opening Upper Cover Replacement | 9770400 | GMK Overseas |
| 1420800 | Front Bumper Fascia Opening Lower Cover Replacement | B0448 | GMNA |
| 1420800 | Front Bumper Fascia Opening Lower Cover Replacement | 9563100 | GMK Overseas |
| 1420820 | Front Bumper Fascia Opening Cover Replacement | B0449 | GMNA |
| 1420920 | Front Bumper Lower Fascia Trim Insert Grille Replacement | | |
| 1420940 | Front Bumper Fascia Lower Deflector Replacement | B0483 | GMNA |
| 1420960 | Radiator Air Lower Deflector Replacement | B0484 | GMNA |
| 1420960 | Radiator Air Lower Deflector Replacement | 1430500 | GMK Overseas |
| 1420980 | Front Air Deflector Replacement | B0485 | GMNA |
| 1420980 | Front Air Deflector Replacement | 9772200 | GMK Overseas |
| 1421000 | Front Air Deflector Extension Replacement | B0486 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1421020 | Front Bumper Fascia Air Deflector Replacement | B0487 | GMNA |
| 1421020 | Front Bumper Fascia Air Deflector Replacement | B062600 | Holden Australia |
| 1421020 | Front Bumper Fascia Air Deflector Replacement | B062610 | Holden Australia |
| 1421020 | Front Bumper Fascia Air Deflector Replacement | B062620 | Holden Australia |
| 1421020 | Front Bumper Fascia Air Deflector Replacement | B062600 | Holden New Zealand |
| 1421020 | Front Bumper Fascia Air Deflector Replacement | B062610 | Holden New Zealand |
| 1421020 | Front Bumper Fascia Air Deflector Replacement | 9560800 | GMK Overseas |
| 1421040 | Front Bumper Fascia Air Deflector Replacement - Center | B0488 | GMNA |
| 1421060 | Front Bumper Fascia Air Deflector Replacement - Outer | B0489 | GMNA |
| 1421080 | Aero Shutter Front Bumper Fascia Air Deflector Replacement | B0491 | GMNA |
| 1421080 | Aero Shutter Front Bumper Fascia Air Deflector Replacement | B6801 | GMNA |
| 1421100 | Front Bumper Fascia Air Deflector Replacement - Right Side | B0492 | GMNA |
| 1421120 | Front Bumper Fascia Air Deflector Replacement - Left Side | 9561300 | GMK Overseas |
| 1421140 | Front Bumper Lower Shutter Grille Replacement | B0495 | GMNA |
| 1421160 | Front Bumper Center Filler Replacement | | |
| 1421180 | Front Bumper Filler Replacement | B0506 | GMNA |
| 1421180 | Front Bumper Filler Replacement | B0508 | GMNA |
| 1421250 | Rear Bumper Upper Fascia Replacement | B0602 | GMNA |
| 1421270 | Rear Bumper Lower Fascia Replacement | B0603 | GMNA |
| 1421270 | Rear Bumper Lower Fascia Replacement | 9573100 | GMK Overseas |
| 1421290 | Rear Bumper Fascia Extension Replacement | B0604 | GMNA |
| 1421340 | Rear Bumper Fascia Replacement | B0608 | GMNA |
| 1421340 | Rear Bumper Fascia Replacement | B0624 | GMNA |
| 1421340 | Rear Bumper Fascia Replacement | B9912 | GMNA |
| 1421340 | Rear Bumper Fascia Replacement | B9918 | GMNA |
| 1421340 | Rear Bumper Fascia Replacement | 8320110 | GMK Domestic |
| 1421340 | Rear Bumper Fascia Replacement | 8512900 | GMK Domestic |
| 1421340 | Rear Bumper Fascia Replacement | 8514000 | GMK Domestic |
| 1421340 | Rear Bumper Fascia Replacement | B089100 | Holden Australia |
| 1421340 | Rear Bumper Fascia Replacement | B089200 | Holden Australia |
| 1421340 | Rear Bumper Fascia Replacement | A571500 | Holden New Zealand |
| 1421340 | Rear Bumper Fascia Replacement | A571510 | Holden New Zealand |
| 1421340 | Rear Bumper Fascia Replacement | 9570100 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1421340 | Rear Bumper Fascia Replacement | 957010A | GMK Overseas |
| 1421340 | Rear Bumper Fascia Replacement | 9570400 | GMK Overseas |
| 1421342 | Rear Bumper Fascia Alignment | B0598 | GMNA |
| 1421342 | Rear Bumper Fascia Alignment | 8512700 | GMK Domestic |
| 1421342 | Rear Bumper Fascia Alignment | B0598 | Holden Australia |
| 1421342 | Rear Bumper Fascia Alignment | 957020A | GMK Overseas |
| 1421342 | Rear Bumper Fascia Alignment | 957020B | GMK Overseas |
| 1421342 | Rear Bumper Fascia Alignment | 957020C | GMK Overseas |
| 1421342 | Rear Bumper Fascia Alignment | 957020D | GMK Overseas |
| 1421342 | Rear Bumper Fascia Alignment | 957020E | GMK Overseas |
| 1421342 | Rear Bumper Fascia Alignment | 9571100 | GMK Overseas |
| 1421360 | Rear Bumper Fascia Outer Guide Replacement | B0611 | GMNA |
| 1421360 | Rear Bumper Fascia Outer Guide Replacement | 9574400 | GMK Overseas |
| 1421380 | Rear Bumper Fascia Guide Replacement | B0612 | GMNA |
| 1421380 | Rear Bumper Fascia Guide Replacement | 8513500 | GMK Domestic |
| 1421380 | Rear Bumper Fascia Guide Replacement | 8513700 | GMK Domestic |
| 1421380 | Rear Bumper Fascia Guide Replacement | 8513800 | GMK Domestic |
| 1421380 | Rear Bumper Fascia Guide Replacement | 9571300 | GMK Overseas |
| 1421400 | Rear Bumper Fascia Inner Guide Replacement | B0613 | GMNA |
| 1421410 | Rear Bumper Fascia Heat Shield Replacement | | |
| 1421420 | Rear Bumper Fascia Bumper Guard Pad Replacement | B0618 | GMNA |
| 1421440 | Rear Bumper Fascia Lower Skid Plate Replacement | B0619 | GMNA |
| 1421440 | Rear Bumper Fascia Lower Skid Plate Replacement | 8520100 | GMK Domestic |
| 1421440 | Rear Bumper Fascia Lower Skid Plate Replacement | 9573400 | GMK Overseas |
| 1421460 | Rear Bumper Fascia Support Replacement | B0620 | GMNA |
| 1421480 | Rear Bumper Step Pad Replacement | B0720 | GMNA |
| 1421480 | Rear Bumper Step Pad Replacement | 8320000 | GMK Domestic |
| 1421480 | Rear Bumper Step Pad Replacement | 8514200 | GMK Domestic |
| 1421480 | Rear Bumper Step Pad Replacement | B0720 | Holden Australia |
| 1421480 | Rear Bumper Step Pad Replacement | 9570500 | GMK Overseas |
| 1421500 | Rear Bumper Step Pad Extension Replacement | B0721 | GMNA |
| 1421520 | Rear Bumper Step Center Pad Replacement | B0722 | GMNA |
| 1421540 | Rear Bumper Step Outer Pad Replacement | B0723 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1421550 | Rear Bumper Fascia Splash Shield Replacement | | |
| 1421580 | Rear Bumper Fascia Reflector Replacement | B0740 | GMNA |
| 1421580 | Rear Bumper Fascia Reflector Replacement | 8514100 | GMK Domestic |
| 1421580 | Rear Bumper Fascia Reflector Replacement | 9182800 | GMK Overseas |
| 1421580 | Rear Bumper Fascia Reflector Replacement | 9573500 | GMK Overseas |
| 1421710 | Rear Bumper Impact Bar Replacement | B0800 | GMNA |
| 1421710 | Rear Bumper Impact Bar Replacement | A570500 | Holden Australia |
| 1421710 | Rear Bumper Impact Bar Replacement | A571500 | Holden Australia |
| 1421710 | Rear Bumper Impact Bar Replacement | B0800 | Holden Australia |
| 1421710 | Rear Bumper Impact Bar Replacement | B080000 | Holden Australia |
| 1421710 | Rear Bumper Impact Bar Replacement | P006900 | Holden Australia |
| 1421710 | Rear Bumper Impact Bar Replacement | A570500 | Holden New Zealand |
| 1421710 | Rear Bumper Impact Bar Replacement | B080000 | Holden New Zealand |
| 1421710 | Rear Bumper Impact Bar Replacement | P006900 | Holden New Zealand |
| 1421710 | Rear Bumper Impact Bar Replacement | 9570600 | GMK Overseas |
| 1421730 | Rear Bumper Fascia Step Pad Replacement | B0820 | GMNA |
| 1421730 | Rear Bumper Fascia Step Pad Replacement | A569510 | Holden Australia |
| 1421730 | Rear Bumper Fascia Step Pad Replacement | A569510 | Holden New Zealand |
| 1421750 | Rear Bumper Fascia Trailer Hitch Access Hole Cover Replacement | B0821 | GMNA |
| 1421760 | Rear Bumper Fascia Access Hole Cover Replacement | | |
| 1421770 | Rear Bumper Impact Bar End Cap Replacement | B0840 | GMNA |
| 1421770 | Rear Bumper Impact Bar End Cap Replacement | B9983 | GMNA |
| 1421790 | Rear Bumper Impact Bar Extension Replacement | B0825 | GMNA |
| 1421790 | Rear Bumper Impact Bar Extension Replacement | B0825 | Holden Australia |
| 1421820 | Front Bumper Fascia Trim Cap Replacement | B0842 | GMNA |
| 1421842 | Rear Bumper Alignment | B0860 | GMNA |
| 1421842 | Rear Bumper Alignment | B0860 | Holden Australia |
| 1421890 | Rear Bumper Fascia Molding Replacement | B0909 | GMNA |
| 1421890 | Rear Bumper Fascia Molding Replacement | A571600 | Holden Australia |
| 1421890 | Rear Bumper Fascia Molding Replacement | A571600 | Holden New Zealand |
| 1421910 | Rear Bumper Fascia Insert Replacement | B0922 | GMNA |
| 1421930 | Rear Bumper Energy Absorber Replacement | B0966 | GMNA |
| 1421930 | Rear Bumper Energy Absorber Replacement | 8514800 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1421930 | Rear Bumper Energy Absorber Replacement | 9570800 | GMK Overseas |
| 1421980 | Rear Bumper Filler Panel Replacement | B1100 | GMNA |
| 1421980 | Rear Bumper Filler Panel Replacement | B1107 | GMNA |
| 1421980 | Rear Bumper Filler Panel Replacement | B9714 | GMNA |
| 1422000 | Radiator Grille Lower Molding Replacement | 9770100 | GMK Overseas |
| 1422000 | Radiator Grille Lower Molding Replacement | 9772400 | GMK Overseas |
| 1422040 | Front Bumper Fascia Air Deflector Actuator Replacement | N3232 | GMNA |
| 1422060 | Front Bumper Lower Shutter Actuator Replacement | N3233 | GMNA |
| 1430010 | Front Brake Caliper Cooling Duct Replacement | B0064 | GMNA |
| 1430030 | Rear Brake Caliper Cooling Air Scoop Replacement | B0065 | GMNA |
| 1430050 | Front Tow Hook Replacement | B0342 | GMNA |
| 1430050 | Front Tow Hook Replacement | R603500 | Holden Australia |
| 1430050 | Front Tow Hook Replacement | R603510 | Holden Australia |
| 1430050 | Front Tow Hook Replacement | R603520 | Holden Australia |
| 1430050 | Front Tow Hook Replacement | R603500 | Holden New Zealand |
| 1430050 | Front Tow Hook Replacement | R603500A | Holden New Zealand |
| 1430050 | Front Tow Hook Replacement | R603510 | Holden New Zealand |
| 1430050 | Front Tow Hook Replacement | R603520 | Holden New Zealand |
| 1430070 | Rear Tow Hook Replacement | B0343 | GMNA |
| 1430070 | Rear Tow Hook Replacement | B0347 | GMNA |
| 1430070 | Rear Tow Hook Replacement | B0348 | GMNA |
| 1430070 | Rear Tow Hook Replacement | B0349 | GMNA |
| 1430070 | Rear Tow Hook Replacement | R9236 | GMNA |
| 1430270 | Front Wheelhouse Liner Inner Front Extension Replacement | B0756 | GMNA |
| 1430270 | Front Wheelhouse Liner Inner Front Extension Replacement | B9851 | GMNA |
| 1430270 | Front Wheelhouse Liner Inner Front Extension Replacement | 9563800 | GMK Overseas |
| 1430270 | Front Wheelhouse Liner Inner Front Extension Replacement | 9563900 | GMK Overseas |
| 1430270 | Front Wheelhouse Liner Inner Front Extension Replacement | 9753100 | GMK Overseas |
| 1430270 | Front Wheelhouse Liner Inner Front Extension Replacement | 9753300 | GMK Overseas |
| 1430290 | Front Wheelhouse Lower Center Panel Replacement | B0757 | GMNA |
| 1430290 | Front Wheelhouse Lower Center Panel Replacement | S0320 | GMNA |
| 1430290 | Front Wheelhouse Lower Center Panel Replacement | S0321 | GMNA |
| 1430300 | Front Compartment Air Deflector Replacement | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1430300 | Loss of Isolation in the High Voltage System | | |
| 1430310 | Front Compartment Splash Shield Replacement | 9751700 | GMK Overseas |
| 1430330 | Engine Splash Shield Replacement | B0758 | GMNA |
| 1430330 | Engine Splash Shield Replacement | B0759 | GMNA |
| 1430330 | Engine Splash Shield Replacement | B0760 | GMNA |
| 1430330 | Engine Splash Shield Replacement | B0761 | GMNA |
| 1430330 | Engine Splash Shield Replacement | E1688 | GMNA |
| 1430330 | Engine Splash Shield Replacement | E1689 | GMNA |
| 1430330 | Engine Splash Shield Replacement | E1690 | GMNA |
| 1430330 | Engine Splash Shield Replacement | J3234 | GMNA |
| 1430330 | Engine Splash Shield Replacement | J3235 | GMNA |
| 1430330 | Engine Splash Shield Replacement | J3236 | GMNA |
| 1430330 | Engine Splash Shield Replacement | J3413 | GMNA |
| 1430330 | Engine Splash Shield Replacement | J3414 | GMNA |
| 1430330 | Engine Splash Shield Replacement | 8637600 | GMK Domestic |
| 1430330 | Engine Splash Shield Replacement | 1382300 | GMK Overseas |
| 1430330 | Engine Splash Shield Replacement | 1382400 | GMK Overseas |
| 1430330 | Engine Splash Shield Replacement | 1382800 | GMK Overseas |
| 1430330 | Engine Splash Shield Replacement | 5710800 | GMK Overseas |
| 1430350 | Engine Splash Shield Replacement - Right Side | 1382100 | GMK Overseas |
| 1430370 | Engine Splash Shield Replacement - Left Side | 1382200 | GMK Overseas |
| 1430370 | Engine Splash Shield Replacement - Left Side | 5010500 | GMK Overseas |
| 1430370 | Engine Splash Shield Replacement - Left Side | 9751800 | GMK Overseas |
| 1430450 | Front Wheelhouse Liner Replacement - Right Side | B0764 | GMNA |
| 1430450 | Front Wheelhouse Liner Replacement - Right Side | A531100 | Holden Australia |
| 1430450 | Front Wheelhouse Liner Replacement - Right Side | A531400 | Holden Australia |
| 1430450 | Front Wheelhouse Liner Replacement - Right Side | B0764 | Holden Australia |
| 1430450 | Front Wheelhouse Liner Replacement - Right Side | A531100 | Holden New Zealand |
| 1430450 | Front Wheelhouse Liner Replacement - Right Side | A531400 | Holden New Zealand |
| 1430470 | Front Wheelhouse Liner Replacement - Left Side | B0765 | GMNA |
| 1430470 | Front Wheelhouse Liner Replacement - Left Side | A531200 | Holden Australia |
| 1430470 | Front Wheelhouse Liner Replacement - Left Side | A531200 | Holden New Zealand |
| 1430490 | Front Wheelhouse Liner Replacement | B0766 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1430490 | Front Wheelhouse Liner Replacement | B9923 | GMNA |
| 1430490 | Front Wheelhouse Liner Replacement | B9971 | GMNA |
| 1430490 | Front Wheelhouse Liner Replacement | 8637800 | GMK Domestic |
| 1430490 | Front Wheelhouse Liner Replacement | 8637900 | GMK Domestic |
| 1430490 | Front Wheelhouse Liner Replacement | B0766 | Holden Australia |
| 1430490 | Front Wheelhouse Liner Replacement | B0766 | Holden New Zealand |
| 1430490 | Front Wheelhouse Liner Replacement | 9750100 | GMK Overseas |
| 1430490 | Front Wheelhouse Liner Replacement | 9750200 | GMK Overseas |
| 1430490 | Front Wheelhouse Liner Replacement | 9750300 | GMK Overseas |
| 1430510 | Rear Wheelhouse Panel Liner Replacement | B0769 | GMNA |
| 1430510 | Rear Wheelhouse Panel Liner Replacement | B9987 | GMNA |
| 1430510 | Rear Wheelhouse Panel Liner Replacement | A531300 | Holden Australia |
| 1430510 | Rear Wheelhouse Panel Liner Replacement | A531300 | Holden New Zealand |
| 1430510 | Rear Wheelhouse Panel Liner Replacement | 9786500 | GMK Overseas |
| 1430510 | Rear Wheelhouse Panel Liner Replacement | 9786600 | GMK Overseas |
| 1430510 | Rear Wheelhouse Panel Liner Replacement | 9786700 | GMK Overseas |
| 1430530 | Front Wheelhouse Front Liner Replacement | B0773 | GMNA |
| 1430550 | Front Wheelhouse Rear Liner Replacement | B0774 | GMNA |
| 1430550 | Front Wheelhouse Rear Liner Replacement | B9925 | GMNA |
| 1430570 | Front Wheelhouse Splash Shield Replacement | B0775 | GMNA |
| 1430590 | Front Wheelhouse Panel Extension Replacement | B0776 | GMNA |
| 1430590 | Front Wheelhouse Panel Extension Replacement | B001635 | Holden Australia |
| 1430590 | Front Wheelhouse Panel Extension Replacement | B062225 | Holden Australia |
| 1430590 | Front Wheelhouse Panel Extension Replacement | B062325 | Holden Australia |
| 1430590 | Front Wheelhouse Panel Extension Replacement | B189000 | Holden Australia |
| 1430590 | Front Wheelhouse Panel Extension Replacement | B189100 | Holden Australia |
| 1430590 | Front Wheelhouse Panel Extension Replacement | B189700 | Holden Australia |
| 1430590 | Front Wheelhouse Panel Extension Replacement | B189000 | Holden New Zealand |
| 1430610 | Front Wheelhouse Front Panel Hole Cover Replacement | B0778 | GMNA |
| 1430610 | Front Wheelhouse Front Panel Hole Cover Replacement | B077810 | Holden New Zealand |
| 1430630 | Rear Wheelhouse Panel Extension Replacement | | |
| 1430640 | Rear Wheelhouse Panel Liner Replacement - Right Side | | |
| 1430650 | Rear Wheelhouse Panel Liner Replacement - Left Side | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1430670 | Trailer Hitch Replacement | B1160 | GMNA |
| 1430670 | Trailer Hitch Replacement | B6813 | GMNA |
| 1430670 | Trailer Hitch Replacement | B1160 | Holden Australia |
| 1430670 | Trailer Hitch Replacement | C451110A | Holden New Zealand |
| 1430770 | Assist Step Replacement | B7777 | GMNA |
| 1430770 | Assist Step Replacement | B7777 | Holden Australia |
| 1430770 | Assist Step Replacement | 9523100 | GMK Overseas |
| 1430770 | Assist Step Replacement | 9523200 | GMK Overseas |
| 1430770 | Assist Step Replacement | 9523300 | GMK Overseas |
| 1430850 | Assist Step Pad Replacement | B7780 | GMNA |
| 1430870 | Assist Step Front Bracket Replacement | B7781 | GMNA |
| 1430870 | Assist Step Front Bracket Replacement | R000275 | Holden Australia |
| 1430870 | Assist Step Front Bracket Replacement | R906000 | Holden Australia |
| 1430870 | Assist Step Front Bracket Replacement | R906100 | Holden Australia |
| 1430870 | Assist Step Front Bracket Replacement | R906200 | Holden Australia |
| 1430870 | Assist Step Front Bracket Replacement | R000275 | Holden New Zealand |
| 1430870 | Assist Step Front Bracket Replacement | R906000 | Holden New Zealand |
| 1430870 | Assist Step Front Bracket Replacement | R906100 | Holden New Zealand |
| 1430870 | Assist Step Front Bracket Replacement | R906200 | Holden New Zealand |
| 1430890 | Assist Step Rear Bracket Replacement | B7782 | GMNA |
| 1430910 | Assist Step Finish Cover Replacement | B7783 | GMNA |
| 1430930 | Front Fender Mud Flap Guard Replacement | B7786 | GMNA |
| 1430930 | Front Fender Mud Flap Guard Replacement | R000121 | Holden Australia |
| 1430930 | Front Fender Mud Flap Guard Replacement | R506000 | Holden Australia |
| 1430930 | Front Fender Mud Flap Guard Replacement | R000121 | Holden New Zealand |
| 1430930 | Front Fender Mud Flap Guard Replacement | R506000 | Holden New Zealand |
| 1430950 | Rear Mud Flap Guard Replacement | B7787 | GMNA |
| 1430950 | Rear Mud Flap Guard Replacement | 8647300 | GMK Domestic |
| 1430950 | Rear Mud Flap Guard Replacement | R506200 | Holden Australia |
| 1430950 | Rear Mud Flap Guard Replacement | R506200 | Holden New Zealand |
| 1430950 | Rear Mud Flap Guard Replacement | 9520600 | GMK Overseas |
| 1430950 | Rear Mud Flap Guard Replacement | 9520700 | GMK Overseas |
| 1430950 | Rear Mud Flap Guard Replacement | 9520800 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1430970 | Body Bolt Lower Cushion Replacement | E1040 | GMNA |
| 1430970 | Body Bolt Lower Cushion Replacement | E1040 | Holden Australia |
| 1430970 | Body Bolt Lower Cushion Replacement | E110600 | Holden Australia |
| 1430990 | Oil Pan Skid Plate Replacement | | |
| 1431010 | Front Compartment Lower Noise Shield Replacement | E1051 | GMNA |
| 1431010 | Front Compartment Lower Noise Shield Replacement | R9793 | GMNA |
| 1431030 | Engine Shield Replacement | E1050 | GMNA |
| 1431030 | Engine Shield Replacement | E1052 | GMNA |
| 1431030 | Engine Shield Replacement | E1054 | GMNA |
| 1431050 | Electronic Brake Control Module Splash Shield Replacement | E1053 | GMNA |
| 1431070 | Engine Lower Front Splash Shield Replacement | | |
| 1431090 | Fuel Tank Shield Replacement | E1070 | GMNA |
| 1431090 | Fuel Tank Shield Replacement | R606500 | Holden Australia |
| 1431090 | Fuel Tank Shield Replacement | R606500 | Holden New Zealand |
| 1431090 | Fuel Tank Shield Replacement | 1962600 | GMK Overseas |
| 1431090 | Fuel Tank Shield Replacement | 196260A | GMK Overseas |
| 1431110 | Drivetrain and Front Suspension Frame Insulator Replacement | E1095 | GMNA |
| 1431110 | Drivetrain and Front Suspension Frame Insulator Replacement | E9476 | GMNA |
| 1431110 | Drivetrain and Front Suspension Frame Insulator Replacement | E9491 | GMNA |
| 1431110 | Drivetrain and Front Suspension Frame Insulator Replacement | E9500 | GMNA |
| 1431110 | Drivetrain and Front Suspension Frame Insulator Replacement | E9503 | GMNA |
| 1431130 | Drivetrain and Front Suspension Frame Front Insulator Replacement | E1096 | GMNA |
| 1431150 | Drivetrain and Front Suspension Frame Rear Insulator Replacement | E1097 | GMNA |
| 1431170 | Body Bolt Upper Cushion Replacement | E1103 | GMNA |
| 1431290 | Rear Suspension Support Lower Mount Replacement - Front | E1115 | GMNA |
| 1431310 | Rear Suspension Support Lower Mount Replacement - Rear | E1116 | GMNA |
| 1431540 | Body Cable Replacement | E1601 | GMNA |
| 1431540 | Body Cable Replacement | E9506 | GMNA |
| 1431550 | Front Compartment Front Center Insulator Replacement | | |
| 1431580 | Underbody Front Air Deflector Replacement - Right Side | | |
| 1431600 | Underbody Rear Air Deflector Replacement | N5868 | GMNA |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1300 | GMNA |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1325 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1330 | GMNA |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1410 | GMNA |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1411 | GMNA |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1417 | GMNA |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1563 | GMNA |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1600 | GMNA |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1700 | GMNA |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1707 | GMNA |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | 1141200 | GMK Domestic |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | 8434000 | GMK Domestic |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130010 | Holden Australia |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130020 | Holden Australia |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130030 | Holden Australia |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130040 | Holden Australia |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130110 | Holden Australia |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130120 | Holden Australia |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130210 | Holden Australia |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130220 | Holden Australia |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E117600 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E119200 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1300 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130000 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130010 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130010ST | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130020 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130030 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130040 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130100 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130110 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130120 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130210 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E130220 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1330 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E133000 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1352 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E135200 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1357 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E135700 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1358 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1400 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1410 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E141000 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1411 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1417 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1420 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E142000 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1421 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E142100 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1431 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1432 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1500 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1502 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1510 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1511 | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1512NZ | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1522NZ | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | E1545NZ | Holden New Zealand |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | 2153200 | GMK Overseas |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | 215320A | GMK Overseas |
| 1431640 | Drivetrain and Front Suspension Frame Replacement | 2153300 | GMK Overseas |
| 1431660 | Transmission Support Replacement | E1720 | GMNA |
| 1431660 | Transmission Support Replacement | 1113100 | GMK Domestic |
| 1431662 | Transmission Support Adjustment | E1721 | GMNA |
| 1431700 | Front Suspension Crossmember Replacement | E1701 | GMNA |
| 1431700 | Front Suspension Crossmember Replacement | E1730 | GMNA |
| 1431700 | Front Suspension Crossmember Replacement | E3508 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1431700 | Front Suspension Crossmember Replacement | E3510 | GMNA |
| 1431700 | Front Suspension Crossmember Replacement | T6142 | GMNA |
| 1431700 | Front Suspension Crossmember Replacement | 1141600 | GMK Domestic |
| 1431700 | Front Suspension Crossmember Replacement | E1730 | Holden Australia |
| 1431700 | Front Suspension Crossmember Replacement | E400400 | Holden Australia |
| 1431700 | Front Suspension Crossmember Replacement | E400400 | Holden New Zealand |
| 1431700 | Front Suspension Crossmember Replacement | 2153100 | GMK Overseas |
| 1431700 | Front Suspension Crossmember Replacement | E333333 | GMK Overseas |
| 1431720 | Drivetrain and Front Suspension Frame Front Crossmember Replacement | E1731 | GMNA |
| 1431720 | Drivetrain and Front Suspension Frame Front Crossmember Replacement | E1780 | GMNA |
| 1431720 | Drivetrain and Front Suspension Frame Front Crossmember Replacement | E1855 | GMNA |
| 1431720 | Drivetrain and Front Suspension Frame Front Crossmember Replacement | E1720 | Holden Australia |
| 1431720 | Drivetrain and Front Suspension Frame Front Crossmember Replacement | E176000 | Holden Australia |
| 1431720 | Drivetrain and Front Suspension Frame Front Crossmember Replacement | E177000 | Holden Australia |
| 1431720 | Drivetrain and Front Suspension Frame Front Crossmember Replacement | E186000 | Holden Australia |
| 1431720 | Drivetrain and Front Suspension Frame Front Crossmember Replacement | E176000 | Holden New Zealand |
| 1431720 | Drivetrain and Front Suspension Frame Front Crossmember Replacement | E1770 | Holden New Zealand |
| 1431720 | Drivetrain and Front Suspension Frame Front Crossmember Replacement | E177000 | Holden New Zealand |
| 1431720 | Drivetrain and Front Suspension Frame Front Crossmember Replacement | E1860 | Holden New Zealand |
| 1431720 | Drivetrain and Front Suspension Frame Front Crossmember Replacement | E186000 | Holden New Zealand |
| 1431720 | Drivetrain and Front Suspension Frame Front Crossmember Replacement | 1382500 | GMK Overseas |
| 1431731 | Rear Suspension Support Bushing Replacement | 2313300 | GMK Overseas |
| 1431800 | Rear Suspension Support Crossmember Replacement | E1889 | GMNA |
| 1431800 | Rear Suspension Support Crossmember Replacement | E2022 | GMNA |
| 1431800 | Rear Suspension Support Crossmember Replacement | E2360 | GMNA |
| 1431800 | Rear Suspension Support Crossmember Replacement | E2361 | GMNA |
| 1431800 | Rear Suspension Support Crossmember Replacement | E2367 | GMNA |
| 1431800 | Rear Suspension Support Crossmember Replacement | E2740 | GMNA |
| 1431800 | Rear Suspension Support Crossmember Replacement | E2741 | GMNA |
| 1431800 | Rear Suspension Support Crossmember Replacement | E3650 | GMNA |
| 1431800 | Rear Suspension Support Crossmember Replacement | 4410500 | GMK Domestic |
| 1431800 | Rear Suspension Support Crossmember Replacement | A202000 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E222000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1431800 | Rear Suspension Support Crossmember Replacement | E222100 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E222700 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E223000 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E223100 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E223700 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E224700 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E224800 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E225700 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E225800 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E226700 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E226800 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E228000 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E228100 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E228200 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E228300 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E228700 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E229100 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E2320 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E232000 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E2321 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E232100 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E2327 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E232700 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E236000 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E236100 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E236700 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E255100 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E255200 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E255700 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | E313700 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | F000179 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | F110300 | Holden Australia |
| 1431800 | Rear Suspension Support Crossmember Replacement | A202000 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1431800 | Rear Suspension Support Crossmember Replacement | E000427 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E222000 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E222700 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E2230 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E223000 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E223100 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E2237 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E223700 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E224700 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E224800 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E2250 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E226700 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E2280 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E228000 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E228100 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E228700 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E232000 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E236000 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | E236700 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | F000179 | Holden New Zealand |
| 1431800 | Rear Suspension Support Crossmember Replacement | 231610A | GMK Overseas |
| 1431810 | Rear Suspension Support Replacement | E5305 | GMNA |
| 1431880 | Assist Step Motor Replacement | N3370 | GMNA |
| 1431900 | Assist Step Controller Replacement | B9956 | GMNA |
| 1431900 | Assist Step Controller Replacement | N5525 | GMNA |
| 1440054 | Front Bumper Upper Fascia Partial Refinish Color/Clear Coat | | |
| 1440144 | Front Bumper Lower Fascia Partial Color/Clear Coat | | |
| 1440154 | Front Bumper Lower Fascia Partial Refinish Color/Clear Coat | | |
| 1440244 | Front Bumper Fascia Partial Color/Clear Coat | 9837080 | GMK Overseas |
| 1440254 | Front Bumper Fascia Partial Refinish Color/Clear Coat | 9837060 | GMK Overseas |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0002 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0003 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0007 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0008 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0012 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0013 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0020 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0040 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0051 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0080 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0081 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0086 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0087 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0088 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0090 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0101 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0105 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A0157 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A9915 | GMNA |
| 1440344 | Front Bumper Impact Bar Partial Color/Clear Coat | A002000 | Holden Australia |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0016 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0017 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0018 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0030 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0050 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0052 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0096 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0097 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0098 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0102 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0106 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0120 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0130 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0139 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0142 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0143 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0147 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0154 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A5262 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A5263 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A5342 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A5343 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A9914 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A9933 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | B0451 | GMNA |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A002100 | Holden Australia |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A002600 | Holden Australia |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A002800 | Holden Australia |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A014200 | Holden Australia |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | B076520 | Holden Australia |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A002800 | Holden New Zealand |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | A0030 | Holden New Zealand |
| 1440354 | Front Bumper Impact Bar Partial Refinish Color/Clear Coat | B076520 | Holden New Zealand |
| 1440444 | Front Bumper Fascia Extension Partial Color/Clear Coat | | |
| 1440454 | Front Bumper Fascia Extension Partial Refinish Color/Clear Coat | | |
| 1440544 | Front Bumper Fascia Trim Cap Partial Color/Clear Coat | | |
| 1440554 | Front Bumper Fascia Trim Cap Partial Refinish Color/Clear Coat | | |
| 1440644 | Front Bumper End Cap Partial Color/Clear Coat | | |
| 1440654 | Front Bumper End Cap Partial Refinish Color/Clear Coat | B9974 | GMNA |
| 1440744 | Front Grille Partial Color/Clear Coat | A0235 | GMNA |
| 1440744 | Front Grille Partial Color/Clear Coat | A0236 | GMNA |
| 1440744 | Front Grille Partial Color/Clear Coat | A0260 | GMNA |
| 1440744 | Front Grille Partial Color/Clear Coat | A026000 | Holden Australia |
| 1440744 | Front Grille Partial Color/Clear Coat | 9850080 | GMK Overseas |
| 1440754 | Front Grille Partial Refinish Color/Clear Coat | A0270 | GMNA |
| 1441144 | Hood Partial Color/Clear Coat | A0347 | GMNA |
| 1441144 | Hood Partial Color/Clear Coat | A0347 | Holden Australia |
| 1441144 | Hood Partial Color/Clear Coat | A034700 | Holden Australia |
| 1441144 | Hood Partial Color/Clear Coat | A0357 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1441144 | Hood Partial Color/Clear Coat | A0347 | Holden New Zealand |
| 1441144 | Hood Partial Color/Clear Coat | A034700 | Holden New Zealand |
| 1441144 | Hood Partial Color/Clear Coat | B062120 | Holden New Zealand |
| 1441144 | Hood Partial Color/Clear Coat | B062129 | Holden New Zealand |
| 1441144 | Hood Partial Color/Clear Coat | 9836080 | GMK Overseas |
| 1441154 | Hood Partial Refinish Color/Clear Coat | A0357 | GMNA |
| 1441154 | Hood Partial Refinish Color/Clear Coat | 9214070 | GMK Domestic |
| 1441154 | Hood Partial Refinish Color/Clear Coat | A0357 | Holden New Zealand |
| 1441154 | Hood Partial Refinish Color/Clear Coat | B062110 | Holden New Zealand |
| 1441154 | Hood Partial Refinish Color/Clear Coat | 9836060 | GMK Overseas |
| 1441244 | Front Intake Air Duct Hole Cover Partial Color/Clear Coat | A0431 | GMNA |
| 1441254 | Front Intake Air Duct Hole Cover Partial Refinish Color/Clear Coat | | |
| 1441344 | Front Fender Partial Color/Clear Coat | A0630 | GMNA |
| 1441344 | Front Fender Partial Color/Clear Coat | A0631 | GMNA |
| 1441344 | Front Fender Partial Color/Clear Coat | A0634 | GMNA |
| 1441344 | Front Fender Partial Color/Clear Coat | A0635 | GMNA |
| 1441344 | Front Fender Partial Color/Clear Coat | A0636 | GMNA |
| 1441344 | Front Fender Partial Color/Clear Coat | A0637 | GMNA |
| 1441344 | Front Fender Partial Color/Clear Coat | A0680 | GMNA |
| 1441344 | Front Fender Partial Color/Clear Coat | A0680 | Holden Australia |
| 1441344 | Front Fender Partial Color/Clear Coat | A0681 | Holden Australia |
| 1441344 | Front Fender Partial Color/Clear Coat | A0680 | Holden New Zealand |
| 1441344 | Front Fender Partial Color/Clear Coat | A0681 | Holden New Zealand |
| 1441344 | Front Fender Partial Color/Clear Coat | B062300 | Holden New Zealand |
| 1441344 | Front Fender Partial Color/Clear Coat | 9834080 | GMK Overseas |
| 1441344 | Front Fender Partial Color/Clear Coat | 9835080 | GMK Overseas |
| 1441344 | Front Fender Partial Color/Clear Coat | 9841060 | GMK Overseas |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | A0690 | GMNA |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | A2580 | GMNA |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | A2581 | GMNA |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | A2590 | GMNA |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | A2591 | GMNA |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | A0690 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | B062200 | Holden Australia |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | B062210 | Holden Australia |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | B062220 | Holden Australia |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | B062300 | Holden Australia |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | B062310 | Holden Australia |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | B062320 | Holden Australia |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | B062200 | Holden New Zealand |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | B062210 | Holden New Zealand |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | B062220 | Holden New Zealand |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | B062310 | Holden New Zealand |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | B062320 | Holden New Zealand |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | 9834060 | GMK Overseas |
| 1441354 | Front Fender Partial Refinish Color/Clear Coat | 9835060 | GMK Overseas |
| 1441444 | Front Wheel Opening Flare Partial Flare Color/Clear Coat | A0760 | GMNA |
| 1441454 | Front Wheel Opening Flare Partial Refinish Color/Clear Coat | A0770 | GMNA |
| 1441544 | Roof Panel Partial Color/Clear Coat | A0880 | GMNA |
| 1441544 | Roof Panel Partial Color/Clear Coat | 9808080 | GMK Overseas |
| 1441554 | Roof Panel Partial Refinish Color/Clear Coat | A0890 | GMNA |
| 1441554 | Roof Panel Partial Refinish Color/Clear Coat | 9808060 | GMK Overseas |
| 1441644 | Roof Lift Off Panel Partial Color/Clear Coat | A0927 | GMNA |
| 1441654 | Roof Lift Off Panel Partial Refinish Color/Clear Coat | A0937 | GMNA |
| 1441844 | Rocker Panel Front Molding Partial Color/Clear Coat | A1043 | GMNA |
| 1441854 | Rocker Panel Front Molding Partial Refinish Color/Clear Coat | A1053 | GMNA |
| 1441944 | Rocker Panel Rear Molding Partial Color/Clear Coat | A1044 | GMNA |
| 1441954 | Rocker Panel Rear Molding Partial Refinish Color/Clear Coat | A1054 | GMNA |
| 1442154 | Front Side Door Outside Handle Full Color/Clear Coat | A1117 | GMNA |
| 1442154 | Front Side Door Outside Handle Full Color/Clear Coat | A2682 | GMNA |
| 1442154 | Front Side Door Outside Handle Full Color/Clear Coat | B081250 | Holden Australia |
| 1442154 | Front Side Door Outside Handle Full Color/Clear Coat | B081250 | Holden New Zealand |
| 1442154 | Front Side Door Outside Handle Full Color/Clear Coat | B081300 | Holden New Zealand |
| 1442154 | Front Side Door Outside Handle Full Color/Clear Coat | 9857080 | GMK Overseas |
| 1442154 | Front Side Door Outside Handle Full Color/Clear Coat | 9858080 | GMK Overseas |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | A1220 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | A1222 | GMNA |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | A1224 | GMNA |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | A1225 | GMNA |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | A7679 | GMNA |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | A7680 | GMNA |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | A7681 | GMNA |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | A7689 | GMNA |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | A7690 | GMNA |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | A7691 | GMNA |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | T7949 | GMNA |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | 9142060 | GMK Domestic |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | 9142560 | GMK Domestic |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | A1220 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | A122000 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | A1221 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | A122100 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | A768100 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B001110 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B001119 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B001120 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B001199 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B001210 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B001219 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B001220 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B014510 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B014520 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B014610 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B014620 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B100300 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B100310 | Holden Australia |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | A122000 | Holden New Zealand |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B001110 | Holden New Zealand |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B001119 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B001120 | Holden New Zealand |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B001210 | Holden New Zealand |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B014610 | Holden New Zealand |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B100300 | Holden New Zealand |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | B100310 | Holden New Zealand |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | 9813060 | GMK Overseas |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | 9814060 | GMK Overseas |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | 9815080 | GMK Overseas |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | 9816080 | GMK Overseas |
| 1442244 | Front Side Door Outer Panel Partial Color/Clear Coat | 981M2FA | GMK Overseas |
| 1442254 | Front Side Door Outer Panel Partial Refinish Color/Clear Coat | A1230 | GMNA |
| 1442254 | Front Side Door Outer Panel Partial Refinish Color/Clear Coat | 9142070 | GMK Domestic |
| 1442254 | Front Side Door Outer Panel Partial Refinish Color/Clear Coat | 9142570 | GMK Domestic |
| 1442254 | Front Side Door Outer Panel Partial Refinish Color/Clear Coat | A1230 | Holden Australia |
| 1442254 | Front Side Door Outer Panel Partial Refinish Color/Clear Coat | 9813080 | GMK Overseas |
| 1442254 | Front Side Door Outer Panel Partial Refinish Color/Clear Coat | 9814080 | GMK Overseas |
| 1442254 | Front Side Door Outer Panel Partial Refinish Color/Clear Coat | 9815060 | GMK Overseas |
| 1442254 | Front Side Door Outer Panel Partial Refinish Color/Clear Coat | 9816060 | GMK Overseas |
| 1442354 | Outside Rearview Mirror Full Color/Clear Coat | | |
| 1442444 | Quarter Panel Upper Applique Partial Color/Clear Coat | A1260 | GMNA |
| 1442454 | Quarter Panel Upper Applique Partial Refinish Color/Clear Coat | A1264 | GMNA |
| 1442854 | Rear Side Door Outside Handle Full Color/Clear Coat | | |
| 1442944 | Rear Side Door Outer Panel Partial Color/Clear Coat | A1520 | GMNA |
| 1442944 | Rear Side Door Outer Panel Partial Color/Clear Coat | A1529 | GMNA |
| 1442944 | Rear Side Door Outer Panel Partial Color/Clear Coat | 9144060 | GMK Domestic |
| 1442944 | Rear Side Door Outer Panel Partial Color/Clear Coat | 9146360 | GMK Domestic |
| 1442944 | Rear Side Door Outer Panel Partial Color/Clear Coat | A1520 | Holden Australia |
| 1442944 | Rear Side Door Outer Panel Partial Color/Clear Coat | A152000 | Holden Australia |
| 1442944 | Rear Side Door Outer Panel Partial Color/Clear Coat | A152100 | Holden Australia |
| 1442944 | Rear Side Door Outer Panel Partial Color/Clear Coat | B001320 | Holden Australia |
| 1442944 | Rear Side Door Outer Panel Partial Color/Clear Coat | B001420 | Holden Australia |
| 1442944 | Rear Side Door Outer Panel Partial Color/Clear Coat | 9817080 | GMK Overseas |
| 1442944 | Rear Side Door Outer Panel Partial Color/Clear Coat | 9818080 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1442954 | Rear Side Door Outer Panel Partial Refinish Color/Clear Coat | A1530 | GMNA |
| 1442954 | Rear Side Door Outer Panel Partial Refinish Color/Clear Coat | 9144070 | GMK Domestic |
| 1442954 | Rear Side Door Outer Panel Partial Refinish Color/Clear Coat | 9146370 | GMK Domestic |
| 1442954 | Rear Side Door Outer Panel Partial Refinish Color/Clear Coat | A1530 | Holden Australia |
| 1442954 | Rear Side Door Outer Panel Partial Refinish Color/Clear Coat | A1530 | Holden New Zealand |
| 1442954 | Rear Side Door Outer Panel Partial Refinish Color/Clear Coat | 9817060 | GMK Overseas |
| 1442954 | Rear Side Door Outer Panel Partial Refinish Color/Clear Coat | 9818060 | GMK Overseas |
| 1443044 | Intermediate Side Door Outer Panel Partial Color/Clear Coat | A1942 | GMNA |
| 1443054 | Intermediate Side Door Outer Panel Partial Refinish Color/Clear Coat | A1952 | GMNA |
| 1443144 | Body Side Outer Panel Partial Color/Clear Coat | A2180 | GMNA |
| 1443144 | Body Side Outer Panel Partial Color/Clear Coat | A5540 | GMNA |
| 1443144 | Body Side Outer Panel Partial Color/Clear Coat | A9909 | GMNA |
| 1443144 | Body Side Outer Panel Partial Color/Clear Coat | A218000 | Holden Australia |
| 1443144 | Body Side Outer Panel Partial Color/Clear Coat | B077710 | Holden Australia |
| 1443144 | Body Side Outer Panel Partial Color/Clear Coat | B078520 | Holden Australia |
| 1443144 | Body Side Outer Panel Partial Color/Clear Coat | C895200 | Holden Australia |
| 1443144 | Body Side Outer Panel Partial Color/Clear Coat | B047120 | Holden New Zealand |
| 1443144 | Body Side Outer Panel Partial Color/Clear Coat | B078520 | Holden New Zealand |
| 1443144 | Body Side Outer Panel Partial Color/Clear Coat | C895200 | Holden New Zealand |
| 1443154 | Body Side Outer Panel Partial Refinish Color/Clear Coat | A2179 | GMNA |
| 1443154 | Body Side Outer Panel Partial Refinish Color/Clear Coat | A2189 | GMNA |
| 1443154 | Body Side Outer Panel Partial Refinish Color/Clear Coat | A2190 | GMNA |
| 1443154 | Body Side Outer Panel Partial Refinish Color/Clear Coat | A5800 | GMNA |
| 1443154 | Body Side Outer Panel Partial Refinish Color/Clear Coat | B8687 | GMNA |
| 1443154 | Body Side Outer Panel Partial Refinish Color/Clear Coat | A5435 | Holden Australia |
| 1443154 | Body Side Outer Panel Partial Refinish Color/Clear Coat | A5440 | Holden Australia |
| 1443154 | Body Side Outer Panel Partial Refinish Color/Clear Coat | B001100 | Holden Australia |
| 1443154 | Body Side Outer Panel Partial Refinish Color/Clear Coat | C895100 | Holden Australia |
| 1443154 | Body Side Outer Panel Partial Refinish Color/Clear Coat | B000910 | Holden New Zealand |
| 1443154 | Body Side Outer Panel Partial Refinish Color/Clear Coat | C895100 | Holden New Zealand |
| 1443244 | Rear Wheel Opening Flare Partial Color/Clear Coat | A2200 | GMNA |
| 1443254 | Rear Wheel Opening Flare Partial Refinish Color/Clear Coat | A2210 | GMNA |
| 1443344 | Fuel Tank Filler Door Partial Color/Clear Coat | A2240 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1443354 | Fuel Tank Filler Door Full Color/Clear Coat | A2250 | GMNA |
| 1443354 | Fuel Tank Filler Door Full Color/Clear Coat | 9148170 | GMK Domestic |
| 1443354 | Fuel Tank Filler Door Full Color/Clear Coat | B081199 | Holden Australia |
| 1443354 | Fuel Tank Filler Door Full Color/Clear Coat | 9856060 | GMK Overseas |
| 1443444 | Load Floor Panel Partial Color/Clear Coat | A2410 | GMNA |
| 1443444 | Load Floor Panel Partial Color/Clear Coat | A241000 | Holden Australia |
| 1443444 | Load Floor Panel Partial Color/Clear Coat | A2410 | Holden New Zealand |
| 1443444 | Load Floor Panel Partial Color/Clear Coat | B001100 | Holden New Zealand |
| 1443454 | Load Floor Panel Partial Refinish Color/Clear Coat | A1080 | GMNA |
| 1443454 | Load Floor Panel Partial Refinish Color/Clear Coat | A1081 | GMNA |
| 1443454 | Load Floor Panel Partial Refinish Color/Clear Coat | A2420 | GMNA |
| 1443544 | Pickup Box Outer Side Panel Partial Color/Clear Coat | A2501 | GMNA |
| 1443544 | Pickup Box Outer Side Panel Partial Color/Clear Coat | A2510 | GMNA |
| 1443544 | Pickup Box Outer Side Panel Partial Color/Clear Coat | A2511 | GMNA |
| 1443544 | Pickup Box Outer Side Panel Partial Color/Clear Coat | A2520 | GMNA |
| 1443544 | Pickup Box Outer Side Panel Partial Color/Clear Coat | A2521 | GMNA |
| 1443544 | Pickup Box Outer Side Panel Partial Color/Clear Coat | A2530 | GMNA |
| 1443544 | Pickup Box Outer Side Panel Partial Color/Clear Coat | A2531 | GMNA |
| 1443544 | Pickup Box Outer Side Panel Partial Color/Clear Coat | A2540 | GMNA |
| 1443544 | Pickup Box Outer Side Panel Partial Color/Clear Coat | A2541 | GMNA |
| 1443544 | Pickup Box Outer Side Panel Partial Color/Clear Coat | A2544 | GMNA |
| 1443544 | Pickup Box Outer Side Panel Partial Color/Clear Coat | A2545 | GMNA |
| 1443544 | Pickup Box Outer Side Panel Partial Color/Clear Coat | A2560 | GMNA |
| 1443544 | Pickup Box Outer Side Panel Partial Color/Clear Coat | A250100 | Holden Australia |
| 1443554 | Pickup Box Outer Side Panel Partial Refinish Color/Clear Coat | A2570 | GMNA |
| 1443644 | Pickup Box Front End Panel Partial Color/Clear Coat - Interior | A2600 | GMNA |
| 1443654 | Pickup Box Front End Panel Partial Refinish Color/Clear Coat - Interior | A2610 | GMNA |
| 1443744 | Pickup Box Inner Side Panel Partial Color/Clear Coat | A2620 | GMNA |
| 1443744 | Pickup Box Inner Side Panel Partial Color/Clear Coat | A2620 | Holden Australia |
| 1443754 | Pickup Box Inner Side Panel Partial Refinish Color/Clear Coat | A2630 | GMNA |
| 1443844 | Pickup Box Endgate Partial Color/Clear Coat - Exterior | A2658 | GMNA |
| 1443844 | Pickup Box Endgate Partial Color/Clear Coat - Exterior | A2676 | Holden Australia |
| 1443854 | Pickup Box Endgate Partial Refinish Color/Clear Coat - Exterior | A2659 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1443944 | Pickup Box Endgate Partial Color/Clear Coat - Interior | A2660 | GMNA |
| 1443954 | Pickup Box Endgate Partial Refinish Color/Clear Coat - Interior | A2670 | GMNA |
| 1444044 | Pickup Box Assembly and Endgate Full Color/Clear Coat - Exterior | A2675 | GMNA |
| 1444054 | Pickup Box Assembly and Endgate Full Refinish Color/Clear Coat - Exterior | A2676 | GMNA |
| 1444144 | Rear Compartment Lid Partial Color/Clear Coat | A2720 | GMNA |
| 1444144 | Rear Compartment Lid Partial Color/Clear Coat | 9315060 | GMK Domestic |
| 1444144 | Rear Compartment Lid Partial Color/Clear Coat | B001710 | Holden Australia |
| 1444144 | Rear Compartment Lid Partial Color/Clear Coat | B001719 | Holden Australia |
| 1444144 | Rear Compartment Lid Partial Color/Clear Coat | B001720 | Holden Australia |
| 1444144 | Rear Compartment Lid Partial Color/Clear Coat | B100350 | Holden Australia |
| 1444144 | Rear Compartment Lid Partial Color/Clear Coat | B001710 | Holden New Zealand |
| 1444144 | Rear Compartment Lid Partial Color/Clear Coat | B001719 | Holden New Zealand |
| 1444144 | Rear Compartment Lid Partial Color/Clear Coat | B001720 | Holden New Zealand |
| 1444144 | Rear Compartment Lid Partial Color/Clear Coat | B100350 | Holden New Zealand |
| 1444144 | Rear Compartment Lid Partial Color/Clear Coat | 9847080 | GMK Overseas |
| 1444154 | Rear Compartment Lid Partial Refinish Color/Clear Coat | A2730 | GMNA |
| 1444154 | Rear Compartment Lid Partial Refinish Color/Clear Coat | S1820 | GMNA |
| 1444154 | Rear Compartment Lid Partial Refinish Color/Clear Coat | 9315070 | GMK Domestic |
| 1444154 | Rear Compartment Lid Partial Refinish Color/Clear Coat | 9847060 | GMK Overseas |
| 1444244 | Rear Compartment Lid Applique Partial Color/Clear Coat | A2758 | GMNA |
| 1444344 | Rear End Spoiler Partial Color/Clear Coat | A2760 | GMNA |
| 1444344 | Rear End Spoiler Partial Color/Clear Coat | A2761 | GMNA |
| 1444344 | Rear End Spoiler Partial Color/Clear Coat | A2766 | GMNA |
| 1444344 | Rear End Spoiler Partial Color/Clear Coat | A2767 | GMNA |
| 1444344 | Rear End Spoiler Partial Color/Clear Coat | A2768 | GMNA |
| 1444354 | Rear End Spoiler Partial Refinish Color/Clear Coat | A2770 | GMNA |
| 1444354 | Rear End Spoiler Partial Refinish Color/Clear Coat | A2771 | GMNA |
| 1444354 | Rear End Spoiler Partial Refinish Color/Clear Coat | A2776 | GMNA |
| 1444354 | Rear End Spoiler Partial Refinish Color/Clear Coat | A2777 | GMNA |
| 1444354 | Rear End Spoiler Partial Refinish Color/Clear Coat | A2778 | GMNA |
| 1444354 | Rear End Spoiler Partial Refinish Color/Clear Coat | 9862060 | GMK Overseas |
| 1444444 | Liftgate Upper Applique Partial Color/Clear Coat | A2954 | GMNA |
| 1444454 | Liftgate Upper Applique Partial Refinish Color/Clear Coat | A2955 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1444544 | Liftgate Upper Panel Partial Color/Clear Coat | A2956 | GMNA |
| 1444554 | Liftgate Upper Panel Partial Refinish Color/Clear Coat | A2957 | GMNA |
| 1444644 | Liftgate Lower Panel Partial Color/Clear Coat | A2958 | GMNA |
| 1444654 | Liftgate Lower Panel Partial Refinish Color/Clear Coat | A2959 | GMNA |
| 1444744 | Liftgate Panel Partial Color/Clear Coat | A2948 | GMNA |
| 1444744 | Liftgate Panel Partial Color/Clear Coat | A2960 | GMNA |
| 1444744 | Liftgate Panel Partial Color/Clear Coat | 9849080 | GMK Overseas |
| 1444744 | Liftgate Panel Partial Color/Clear Coat | 9853080 | GMK Overseas |
| 1444754 | Liftgate Panel Partial Refinish Color/Clear Coat | A2961 | GMNA |
| 1444754 | Liftgate Panel Partial Refinish Color/Clear Coat | 9849060 | GMK Overseas |
| 1444754 | Liftgate Panel Partial Refinish Color/Clear Coat | 9853060 | GMK Overseas |
| 1444844 | Liftgate Outside Handle Partial Color/Clear Coat | A2962 | GMNA |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | A1431 | GMNA |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | A3120 | GMNA |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | A7640 | GMNA |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | A7641 | GMNA |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | A140100 | Holden Australia |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | B001310 | Holden Australia |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | B001410 | Holden Australia |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | B001419 | Holden Australia |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | B020510 | Holden Australia |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | B020520 | Holden Australia |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | B020610 | Holden Australia |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | B020620 | Holden Australia |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | B001219 | Holden New Zealand |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | B001310 | Holden New Zealand |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | B001315 | Holden New Zealand |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | B001399 | Holden New Zealand |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | B001410 | Holden New Zealand |
| 1444944 | Rear Door Outer Panel Partial Color/Clear Coat | B001420 | Holden New Zealand |
| 1444954 | Rear Door Outer Panel Partial Refinish Color/Clear Coat | A3130 | GMNA |
| 1444954 | Rear Door Outer Panel Partial Refinish Color/Clear Coat | A250000 | Holden Australia |
| 1444954 | Rear Door Outer Panel Partial Refinish Color/Clear Coat | B001499 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1444954 | Rear Door Outer Panel Partial Refinish Color/Clear Coat | B043510 | Holden Australia |
| 1444954 | Rear Door Outer Panel Partial Refinish Color/Clear Coat | B043520 | Holden Australia |
| 1444954 | Rear Door Outer Panel Partial Refinish Color/Clear Coat | B043610 | Holden Australia |
| 1444954 | Rear Door Outer Panel Partial Refinish Color/Clear Coat | B043620 | Holden Australia |
| 1444954 | Rear Door Outer Panel Partial Refinish Color/Clear Coat | B100320 | Holden Australia |
| 1444954 | Rear Door Outer Panel Partial Refinish Color/Clear Coat | B100330 | Holden Australia |
| 1444954 | Rear Door Outer Panel Partial Refinish Color/Clear Coat | B001499 | Holden New Zealand |
| 1444954 | Rear Door Outer Panel Partial Refinish Color/Clear Coat | B100320 | Holden New Zealand |
| 1444954 | Rear Door Outer Panel Partial Refinish Color/Clear Coat | B100330 | Holden New Zealand |
| 1445044 | Rear Bumper Fascia Extension Partial Color/Clear Coat | | |
| 1445054 | Rear Bumper Fascia Extension Partial Refinish Color/Clear Coat | | |
| 1445144 | Rear Bumper Fascia Trailer Hitch Access Hole Cover Partial Color/Clear Coat | | |
| 1445154 | Rear Bumper Fascia Trailer Hitch Access Hole Cover Full Color/Clear Coat | A3203 | GMNA |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | A3198 | GMNA |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | A3200 | GMNA |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | A3201 | GMNA |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | A3206 | GMNA |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | A3240 | GMNA |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | A3255 | GMNA |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | A3256 | GMNA |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | A3262 | GMNA |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | A3263 | GMNA |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | A3266 | GMNA |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | A3267 | GMNA |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | A3268 | GMNA |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | A324000 | Holden Australia |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | B077520 | Holden Australia |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | B077600 | Holden Australia |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | B077620 | Holden Australia |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | B077520 | Holden New Zealand |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | B077600 | Holden New Zealand |
| 1445244 | Rear Bumper Impact Bar Partial Color/Clear Coat | B077620 | Holden New Zealand |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A2780 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A2783 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A2790 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A2791 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A2793 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A3199 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A3202 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A3207 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A3210 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A3211 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A3216 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A3217 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A3250 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A3272 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A3273 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A3276 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A3277 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A3278 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A5226 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A5227 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | A9920 | GMNA |
| 1445254 | Rear Bumper Impact Bar Partial Refinish Color/Clear Coat | 9320170 | GMK Domestic |
| 1445444 | Rear Bumper Upper Fascia Partial Color/Clear Coat | | |
| 1445454 | Rear Bumper Upper Fascia Partial Refinish Color/Clear Coat | | |
| 1445544 | Rear Bumper Lower Fascia Partial Color/Clear Coat | | |
| 1445554 | Rear Bumper Lower Fascia Partial Refinish Color/Clear Coat | | |
| 1445654 | Rear Bumper Fascia Partial Refinish Color/Clear Coat | 9848060 | GMK Overseas |
| 1445654 | Rear Bumper Fascia Partial Refinish Color/Clear Coat | 9848080 | GMK Overseas |
| 1445754 | Steel Wheel Refinish Color/Clear Coat | | |
| 1445854 | Aluminum Wheel Refinish Color/Clear Coat | A2181 | GMNA |
| 1445854 | Aluminum Wheel Refinish Color/Clear Coat | B001530 | Holden Australia |
| 1445954 | Body Side Molding Full Color/Clear Coat | A2201 | GMNA |
| 1446044 | Front Fender Lower Rear Molding Partial Color/Clear Coat | A5230 | GMNA |
| 1446044 | Front Fender Lower Rear Molding Partial Color/Clear Coat | A5272 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 1446044 | Front Fender Lower Rear Molding Partial Color/Clear Coat | A5273 | GMNA |
| 1446044 | Front Fender Lower Rear Molding Partial Color/Clear Coat | A5274 | GMNA |
| 1446044 | Front Fender Lower Rear Molding Partial Color/Clear Coat | A5275 | GMNA |
| 1446044 | Front Fender Lower Rear Molding Partial Color/Clear Coat | A5276 | GMNA |
| 1446044 | Front Fender Lower Rear Molding Partial Color/Clear Coat | A5277 | GMNA |
| 1446044 | Front Fender Lower Rear Molding Partial Color/Clear Coat | A5377 | GMNA |
| 1446044 | Front Fender Lower Rear Molding Partial Color/Clear Coat | A5380 | GMNA |
| 1446044 | Front Fender Lower Rear Molding Partial Color/Clear Coat | A5381 | GMNA |
| 1446054 | Front Fender Lower Rear Molding Partial Refinish Color/Clear Coat | A5330 | GMNA |
| 1446054 | Front Fender Lower Rear Molding Partial Refinish Color/Clear Coat | A5360 | GMNA |
| 1446054 | Front Fender Lower Rear Molding Partial Refinish Color/Clear Coat | A5361 | GMNA |
| 1446054 | Front Fender Lower Rear Molding Partial Refinish Color/Clear Coat | A5362 | GMNA |
| 1446054 | Front Fender Lower Rear Molding Partial Refinish Color/Clear Coat | A5363 | GMNA |
| 1446054 | Front Fender Lower Rear Molding Partial Refinish Color/Clear Coat | A5364 | GMNA |
| 1446054 | Front Fender Lower Rear Molding Partial Refinish Color/Clear Coat | A5365 | GMNA |
| 1446054 | Front Fender Lower Rear Molding Partial Refinish Color/Clear Coat | A5379 | GMNA |
| 1446054 | Front Fender Lower Rear Molding Partial Refinish Color/Clear Coat | A5382 | GMNA |
| 1446054 | Front Fender Lower Rear Molding Partial Refinish Color/Clear Coat | A5383 | GMNA |
| 1446144 | Front Side Door Lower Molding Partial Color/Clear Coat | A5250 | GMNA |
| 1446154 | Front Side Door Lower Molding Partial Refinish Color/Clear Coat | A5350 | GMNA |
| 1446244 | Rear Side Door Lower Molding Partial Color/Clear Coat | A5254 | GMNA |
| 1446254 | Rear Side Door Lower Molding Partial Refinish Color/Clear Coat | A5354 | GMNA |
| 1446344 | Rocker Panel Molding Partial Color/Clear Coat | A5270 | GMNA |
| 1446344 | Rocker Panel Molding Partial Color/Clear Coat | 9867560 | GMK Overseas |
| 1446344 | Rocker Panel Molding Partial Color/Clear Coat | 9867660 | GMK Overseas |
| 1446354 | Rocker Panel Molding Refinish Color/Clear Coat | A5370 | GMNA |
| 1446444 | Quarter Panel Lower Rear Molding Partial Color/Clear Coat | A5372 | GMNA |
| 1446454 | Quarter Panel Lower Rear Molding Partial Refinish Color/Clear Coat | A5374 | GMNA |
| 1446664 | Complete Body Full Color/Clear Coat | A5435 | GMNA |
| 1446664 | Complete Body Full Color/Clear Coat | 9802080 | GMK Overseas |
| 1446674 | Complete Body Full Refinish Color/Clear Coat | A5440 | GMNA |
| 1446674 | Complete Body Full Refinish Color/Clear Coat | 9802060 | GMK Overseas |
| 2000010 | Brake and Accelerator Pedal Adjuster Switch Replacement | H2643 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2000010 | Brake and Accelerator Pedal Adjuster Switch Replacement | N2370 | Holden New Zealand |
| 2000010 | Brake and Accelerator Pedal Adjuster Switch Replacement | N237000 | Holden New Zealand |
| 2000020 | Brake Pedal Assembly Replacement | 4110100 | GMK Domestic |
| 2000030 | Brake and Accelerator Pedal Adjuster Actuator Motor Replacement | H2646 | GMNA |
| 2000050 | Accelerator Pedal Adjuster Actuator Replacement | H2647 | GMNA |
| 2000070 | Accelerator Pedal Assembly Replacement | H2648 | GMNA |
| 2000070 | Accelerator Pedal Assembly Replacement | J5327 | GMNA |
| 2000090 | Brake Pedal Adjuster Actuator Cable Replacement | H2649 | GMNA |
| 2000090 | Brake Pedal Adjuster Actuator Cable Replacement | H3240 | GMNA |
| 2000090 | Brake Pedal Adjuster Actuator Cable Replacement | H3245 | GMNA |
| 2000090 | Brake Pedal Adjuster Actuator Cable Replacement | H3315 | GMNA |
| 2000110 | Brake and Accelerator Pedal Adjuster Position Sensor Replacement | H2650 | GMNA |
| 2000110 | Brake and Accelerator Pedal Adjuster Position Sensor Replacement | N221330 | Holden Australia |
| 2000110 | Brake and Accelerator Pedal Adjuster Position Sensor Replacement | N221330 | Holden New Zealand |
| 2010010 | Auxiliary Air Compressor Replacement | N0140 | GMNA |
| 2020010 | Hood Window Replacement | B1492 | GMNA |
| 2020010 | Hood Window Replacement | B1496 | GMNA |
| 2020020 | Liftgate Window Latch Replacement | | |
| 2020080 | Windshield Lower Reveal Molding Replacement | B7560 | GMNA |
| 2020100 | Windshield Upper Reveal Molding Replacement | 8743400 | GMK Domestic |
| 2020100 | Windshield Upper Reveal Molding Replacement | C820500 | Holden Australia |
| 2020100 | Windshield Upper Reveal Molding Replacement | C820600 | Holden Australia |
| 2020100 | Windshield Upper Reveal Molding Replacement | C897300 | Holden Australia |
| 2020100 | Windshield Upper Reveal Molding Replacement | C897400 | Holden Australia |
| 2020100 | Windshield Upper Reveal Molding Replacement | C897500 | Holden Australia |
| 2020100 | Windshield Upper Reveal Molding Replacement | C820500 | Holden New Zealand |
| 2020100 | Windshield Upper Reveal Molding Replacement | C820600 | Holden New Zealand |
| 2020100 | Windshield Upper Reveal Molding Replacement | C897300 | Holden New Zealand |
| 2020100 | Windshield Upper Reveal Molding Replacement | C897500 | Holden New Zealand |
| 2020100 | Windshield Upper Reveal Molding Replacement | 9460600 | GMK Overseas |
| 2020120 | Windshield Side Reveal Molding Replacement | B7540 | GMNA |
| 2020120 | Windshield Side Reveal Molding Replacement | B7565 | GMNA |
| 2020120 | Windshield Side Reveal Molding Replacement | B7570 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2020120 | Windshield Side Reveal Molding Replacement | B7571 | GMNA |
| 2020120 | Windshield Side Reveal Molding Replacement | B7610 | GMNA |
| 2020120 | Windshield Side Reveal Molding Replacement | B7611 | GMNA |
| 2020120 | Windshield Side Reveal Molding Replacement | B7570 | Holden Australia |
| 2020120 | Windshield Side Reveal Molding Replacement | B7571 | Holden Australia |
| 2020120 | Windshield Side Reveal Molding Replacement | C820700 | Holden Australia |
| 2020120 | Windshield Side Reveal Molding Replacement | C820700 | Holden New Zealand |
| 2020120 | Windshield Side Reveal Molding Replacement | 9462100 | GMK Overseas |
| 2020120 | Windshield Side Reveal Molding Replacement | 9462200 | GMK Overseas |
| 2020140 | Front Side Door Window Frame Rear Applique Replacement | C896850 | Holden Australia |
| 2020140 | Front Side Door Window Frame Rear Applique Replacement | C896850 | Holden New Zealand |
| 2020140 | Front Side Door Window Frame Rear Applique Replacement | 9620100 | GMK Overseas |
| 2020140 | Front Side Door Window Frame Rear Applique Replacement | 9620200 | GMK Overseas |
| 2020160 | Front Side Door Window Upper Reveal Molding Replacement | B7843 | GMNA |
| 2020160 | Front Side Door Window Upper Reveal Molding Replacement | B7845 | GMNA |
| 2020160 | Front Side Door Window Upper Reveal Molding Replacement | B7919 | GMNA |
| 2020180 | Front Side Door Window Reveal Molding Replacement | B7846 | GMNA |
| 2020180 | Front Side Door Window Reveal Molding Replacement | C832100 | Holden Australia |
| 2020180 | Front Side Door Window Reveal Molding Replacement | C832100 | Holden New Zealand |
| 2020180 | Front Side Door Window Reveal Molding Replacement | C832200 | Holden New Zealand |
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | B7578 | GMNA |
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | B7800 | GMNA |
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | B7840 | GMNA |
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | B7841 | GMNA |
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | B7844 | GMNA |
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | B7848 | GMNA |
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | B7849 | GMNA |
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | B7850 | GMNA |
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | B7851 | GMNA |
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | B8140 | GMNA |
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | B8141 | GMNA |
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | B8160 | GMNA |
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | B8161 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | B8180 | GMNA |
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | B8181 | GMNA |
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | B8190 | GMNA |
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | B8191 | GMNA |
| 2020200 | Front Side Door Window Belt Reveal Molding Replacement | C832200 | Holden Australia |
| 2020220 | Rear Side Door Window Belt Reveal Molding Replacement | B7890 | GMNA |
| 2020240 | Rear Side Door Window Rear Reveal Molding Replacement | B7918 | GMNA |
| 2020280 | Rear Side Door Window Reveal Molding Replacement | B7926 | GMNA |
| 2020300 | Rear Side Door Window Frame Rear Applique Replacement | B7930 | GMNA |
| 2020300 | Rear Side Door Window Frame Rear Applique Replacement | B7931 | GMNA |
| 2020300 | Rear Side Door Window Frame Rear Applique Replacement | B7961 | GMNA |
| 2020300 | Rear Side Door Window Frame Rear Applique Replacement | B7992 | GMNA |
| 2020320 | Rear Side Door Window Frame Front Applique Replacement | B7994 | GMNA |
| 2020340 | Rear Window Reveal Molding Replacement | B8520 | GMNA |
| 2020340 | Rear Window Reveal Molding Replacement | B8540 | GMNA |
| 2020340 | Rear Window Reveal Molding Replacement | B8760 | GMNA |
| 2020340 | Rear Window Reveal Molding Replacement | B8761 | GMNA |
| 2020340 | Rear Window Reveal Molding Replacement | B8768 | GMNA |
| 2020340 | Rear Window Reveal Molding Replacement | B8920 | GMNA |
| 2020340 | Rear Window Reveal Molding Replacement | B9700 | GMNA |
| 2020340 | Rear Window Reveal Molding Replacement | C860500 | Holden Australia |
| 2020340 | Rear Window Reveal Molding Replacement | C868100 | Holden Australia |
| 2020340 | Rear Window Reveal Molding Replacement | C868100 | Holden New Zealand |
| 2020340 | Rear Window Reveal Molding Replacement | 9461900 | GMK Overseas |
| 2020360 | Rear Window Upper Reveal Molding Replacement | B8521 | GMNA |
| 2020380 | Windshield Replacement | B9882 | GMNA |
| 2020380 | Windshield Replacement | B9909 | GMNA |
| 2020380 | Windshield Replacement | C0034 | GMNA |
| 2020380 | Windshield Replacement | C0037 | GMNA |
| 2020380 | Windshield Replacement | C9939 | GMNA |
| 2020380 | Windshield Replacement | C001000 | Holden Australia |
| 2020380 | Windshield Replacement | C001010 | Holden Australia |
| 2020380 | Windshield Replacement | C0034 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2020380 | Windshield Replacement | C003400 | Holden Australia |
| 2020380 | Windshield Replacement | W201000 | Holden Australia |
| 2020380 | Windshield Replacement | C001000 | Holden New Zealand |
| 2020380 | Windshield Replacement | C001010 | Holden New Zealand |
| 2020380 | Windshield Replacement | C0034 | Holden New Zealand |
| 2020380 | Windshield Replacement | 9460100 | GMK Overseas |
| 2020400 | Front Side Door Stationary Window Replacement | B8130 | GMNA |
| 2020400 | Front Side Door Stationary Window Replacement | B8131 | GMNA |
| 2020400 | Front Side Door Stationary Window Replacement | C0064 | GMNA |
| 2020400 | Front Side Door Stationary Window Replacement | C0065 | GMNA |
| 2020400 | Front Side Door Stationary Window Replacement | C0462 | GMNA |
| 2020400 | Front Side Door Stationary Window Replacement | C0507 | GMNA |
| 2020400 | Front Side Door Stationary Window Replacement | 9465300 | GMK Overseas |
| 2020400 | Front Side Door Stationary Window Replacement | 9465400 | GMK Overseas |
| 2020680 | Front Side Door Window Replacement | C0110 | GMNA |
| 2020680 | Front Side Door Window Replacement | C0111 | GMNA |
| 2020680 | Front Side Door Window Replacement | C0114 | GMNA |
| 2020680 | Front Side Door Window Replacement | C0115 | GMNA |
| 2020680 | Front Side Door Window Replacement | C0200 | GMNA |
| 2020680 | Front Side Door Window Replacement | C011000 | Holden Australia |
| 2020680 | Front Side Door Window Replacement | C011100 | Holden Australia |
| 2020680 | Front Side Door Window Replacement | C0114 | Holden Australia |
| 2020680 | Front Side Door Window Replacement | C011400 | Holden Australia |
| 2020680 | Front Side Door Window Replacement | C011500 | Holden Australia |
| 2020680 | Front Side Door Window Replacement | C0110 | Holden New Zealand |
| 2020680 | Front Side Door Window Replacement | C011000 | Holden New Zealand |
| 2020680 | Front Side Door Window Replacement | C0111 | Holden New Zealand |
| 2020680 | Front Side Door Window Replacement | C0114 | Holden New Zealand |
| 2020680 | Front Side Door Window Replacement | C011400 | Holden New Zealand |
| 2020680 | Front Side Door Window Replacement | C011500 | Holden New Zealand |
| 2020680 | Front Side Door Window Replacement | 9461100 | GMK Overseas |
| 2020680 | Front Side Door Window Replacement | 9461200 | GMK Overseas |
| 2020680 | Front Side Door Window Replacement | 9461201 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2020682 | Front Side Door Window Adjustment | B9928 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0100 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0101 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0116 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0117 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0152 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0153 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0230 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0300 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0301 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0310 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0311 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0316 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0317 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0318 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0319 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0342 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0343 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0390 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0391 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0431 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0671 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C0681 | GMNA |
| 2020682 | Front Side Door Window Adjustment | C000376 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C000662 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C005100 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C005200 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C010000 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C0101 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C010100 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C011600 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C011700 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C013100 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2020682 | Front Side Door Window Adjustment | C013200 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C013235 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C0314 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C0315 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C043000 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C043100 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C049400 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C049500 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C066100 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C066400 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C066500 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C066600 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C067000 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C068000 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C068100 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C068700 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C085000 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C085100 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C086000 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C086100 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C086200 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | P008100 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | P008200 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | P008500 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | P008600 | Holden Australia |
| 2020682 | Front Side Door Window Adjustment | C000376 | Holden New Zealand |
| 2020682 | Front Side Door Window Adjustment | C000662 | Holden New Zealand |
| 2020682 | Front Side Door Window Adjustment | C005100 | Holden New Zealand |
| 2020682 | Front Side Door Window Adjustment | C005200 | Holden New Zealand |
| 2020682 | Front Side Door Window Adjustment | C010000 | Holden New Zealand |
| 2020682 | Front Side Door Window Adjustment | C010100 | Holden New Zealand |
| 2020682 | Front Side Door Window Adjustment | C011600 | Holden New Zealand |
| 2020682 | Front Side Door Window Adjustment | C011700 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2020682 | Front Side Door Window Adjustment | C013100 | Holden New Zealand |
| 2020682 | Front Side Door Window Adjustment | C013200 | Holden New Zealand |
| 2020682 | Front Side Door Window Adjustment | C013235 | Holden New Zealand |
| 2020682 | Front Side Door Window Adjustment | C0310 | Holden New Zealand |
| 2020682 | Front Side Door Window Adjustment | C085100 | Holden New Zealand |
| 2020682 | Front Side Door Window Adjustment | P008100 | Holden New Zealand |
| 2020682 | Front Side Door Window Adjustment | P008200 | Holden New Zealand |
| 2020682 | Front Side Door Window Adjustment | P008500 | Holden New Zealand |
| 2020682 | Front Side Door Window Adjustment | P008600 | Holden New Zealand |
| 2020682 | Front Side Door Window Adjustment | 9467100 | GMK Overseas |
| 2020682 | Front Side Door Window Adjustment | 9467200 | GMK Overseas |
| 2020790 | Front Side Door Window Inner Sealing Strip Replacement | C0121 | GMNA |
| 2020790 | Front Side Door Window Inner Sealing Strip Replacement | C0122 | GMNA |
| 2020790 | Front Side Door Window Inner Sealing Strip Replacement | C0204 | GMNA |
| 2020790 | Front Side Door Window Inner Sealing Strip Replacement | C0205 | GMNA |
| 2020790 | Front Side Door Window Inner Sealing Strip Replacement | 8614800 | GMK Domestic |
| 2020790 | Front Side Door Window Inner Sealing Strip Replacement | 8615100 | GMK Domestic |
| 2020790 | Front Side Door Window Inner Sealing Strip Replacement | C012100 | Holden Australia |
| 2020790 | Front Side Door Window Inner Sealing Strip Replacement | C0122 | Holden Australia |
| 2020790 | Front Side Door Window Inner Sealing Strip Replacement | C0121 | Holden New Zealand |
| 2020790 | Front Side Door Window Inner Sealing Strip Replacement | C012100 | Holden New Zealand |
| 2020810 | Front Side Door Window Outer Sealing Strip Replacement | C0123 | GMNA |
| 2020810 | Front Side Door Window Outer Sealing Strip Replacement | 8425400 | GMK Domestic |
| 2020910 | Front Side Door Window Channel Retainer Replacement | C0133 | GMNA |
| 2020910 | Front Side Door Window Channel Retainer Replacement | C0134 | GMNA |
| 2020910 | Front Side Door Window Channel Retainer Replacement | C0135 | GMNA |
| 2020990 | Front Side Door Window Front Channel Replacement | C0140 | GMNA |
| 2020990 | Front Side Door Window Front Channel Replacement | C008130 | Holden Australia |
| 2020990 | Front Side Door Window Front Channel Replacement | C008150 | Holden Australia |
| 2020990 | Front Side Door Window Front Channel Replacement | C008240 | Holden Australia |
| 2020990 | Front Side Door Window Front Channel Replacement | C008250 | Holden Australia |
| 2020990 | Front Side Door Window Front Channel Replacement | C008300 | Holden Australia |
| 2020990 | Front Side Door Window Front Channel Replacement | C008350 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2020990 | Front Side Door Window Front Channel Replacement | C127400 | Holden Australia |
| 2020990 | Front Side Door Window Front Channel Replacement | C826000 | Holden Australia |
| 2020990 | Front Side Door Window Front Channel Replacement | C827000 | Holden Australia |
| 2020990 | Front Side Door Window Front Channel Replacement | C896500 | Holden Australia |
| 2020990 | Front Side Door Window Front Channel Replacement | C008130 | Holden New Zealand |
| 2020990 | Front Side Door Window Front Channel Replacement | C008150 | Holden New Zealand |
| 2020990 | Front Side Door Window Front Channel Replacement | C008240 | Holden New Zealand |
| 2020990 | Front Side Door Window Front Channel Replacement | C008250 | Holden New Zealand |
| 2020990 | Front Side Door Window Front Channel Replacement | C009120 | Holden New Zealand |
| 2020990 | Front Side Door Window Front Channel Replacement | C009220 | Holden New Zealand |
| 2020990 | Front Side Door Window Front Channel Replacement | C127100 | Holden New Zealand |
| 2020990 | Front Side Door Window Front Channel Replacement | C127300 | Holden New Zealand |
| 2020990 | Front Side Door Window Front Channel Replacement | C127400 | Holden New Zealand |
| 2020990 | Front Side Door Window Front Channel Replacement | C826000 | Holden New Zealand |
| 2020990 | Front Side Door Window Front Channel Replacement | C896500 | Holden New Zealand |
| 2020990 | Front Side Door Window Front Channel Replacement | 9620500 | GMK Overseas |
| 2020990 | Front Side Door Window Front Channel Replacement | 9620600 | GMK Overseas |
| 2021040 | Front Side Door Window Rear Channel Retainer Replacement | C0143 | GMNA |
| 2021090 | Front Side Door Window Channel Replacement | B6817 | GMNA |
| 2021090 | Front Side Door Window Channel Replacement | C0141 | GMNA |
| 2021090 | Front Side Door Window Channel Replacement | C0142 | GMNA |
| 2021090 | Front Side Door Window Channel Replacement | C0145 | GMNA |
| 2021090 | Front Side Door Window Channel Replacement | C0160 | GMNA |
| 2021090 | Front Side Door Window Channel Replacement | C0161 | GMNA |
| 2021090 | Front Side Door Window Channel Replacement | C1040 | GMNA |
| 2021090 | Front Side Door Window Channel Replacement | C1041 | GMNA |
| 2021090 | Front Side Door Window Channel Replacement | C9980 | GMNA |
| 2021090 | Front Side Door Window Channel Replacement | C008230 | Holden Australia |
| 2021090 | Front Side Door Window Channel Replacement | C014000 | Holden Australia |
| 2021090 | Front Side Door Window Channel Replacement | C014100 | Holden Australia |
| 2021090 | Front Side Door Window Channel Replacement | C016000 | Holden Australia |
| 2021090 | Front Side Door Window Channel Replacement | C016100 | Holden Australia |
| 2021090 | Front Side Door Window Channel Replacement | C118900 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2021090 | Front Side Door Window Channel Replacement | C119000 | Holden Australia |
| 2021090 | Front Side Door Window Channel Replacement | C127100 | Holden Australia |
| 2021090 | Front Side Door Window Channel Replacement | C127200 | Holden Australia |
| 2021090 | Front Side Door Window Channel Replacement | C127300 | Holden Australia |
| 2021090 | Front Side Door Window Channel Replacement | C008230 | Holden New Zealand |
| 2021090 | Front Side Door Window Channel Replacement | C013110 | Holden New Zealand |
| 2021090 | Front Side Door Window Channel Replacement | C013210 | Holden New Zealand |
| 2021090 | Front Side Door Window Channel Replacement | C0140 | Holden New Zealand |
| 2021090 | Front Side Door Window Channel Replacement | C014000 | Holden New Zealand |
| 2021090 | Front Side Door Window Channel Replacement | C0141 | Holden New Zealand |
| 2021090 | Front Side Door Window Channel Replacement | C014100 | Holden New Zealand |
| 2021090 | Front Side Door Window Channel Replacement | C119000 | Holden New Zealand |
| 2021090 | Front Side Door Window Channel Replacement | C127200 | Holden New Zealand |
| 2021110 | Front Side Door Window Rear Channel Replacement | C0146 | GMNA |
| 2021150 | Front Side Door Window Regulator Guide Replacement | 9617400 | GMK Overseas |
| 2021150 | Front Side Door Window Regulator Guide Replacement | 9617500 | GMK Overseas |
| 2021230 | Front Side Door Window Stabilizer Replacement | C0164 | GMNA |
| 2021280 | Front Side Door Window Module Replacement | C0167 | GMNA |
| 2021300 | Front or Rear Side Door Window Regulator Handle Replacement | 8610500 | GMK Domestic |
| 2021300 | Front or Rear Side Door Window Regulator Handle Replacement | 8610600 | GMK Domestic |
| 2021300 | Front or Rear Side Door Window Regulator Handle Replacement | 9351500 | GMK Overseas |
| 2021300 | Front or Rear Side Door Window Regulator Handle Replacement | 9351600 | GMK Overseas |
| 2021300 | Front or Rear Side Door Window Regulator Handle Replacement | 9351700 | GMK Overseas |
| 2021410 | Front Side Door Window Regulator Replacement | C0182 | GMNA |
| 2021410 | Front Side Door Window Regulator Replacement | 8610400 | GMK Domestic |
| 2021410 | Front Side Door Window Regulator Replacement | C0182 | Holden Australia |
| 2021410 | Front Side Door Window Regulator Replacement | C0182 | Holden New Zealand |
| 2021410 | Front Side Door Window Regulator Replacement | 9616100 | GMK Overseas |
| 2021410 | Front Side Door Window Regulator Replacement | 9616200 | GMK Overseas |
| 2021410 | Front Side Door Window Regulator Replacement | 9616300 | GMK Overseas |
| 2021410 | Front Side Door Window Regulator Replacement | 9616400 | GMK Overseas |
| 2021410 | Front Side Door Window Regulator Replacement | 9616500 | GMK Overseas |
| 2021410 | Front Side Door Window Regulator Replacement | 9616600 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2021690 | Rear Side Door Window Replacement | C0314 | GMNA |
| 2021690 | Rear Side Door Window Replacement | 9461400 | GMK Overseas |
| 2021690 | Rear Side Door Window Replacement | 9461500 | GMK Overseas |
| 2021692 | Rear Side Door Window Adjustment | B9990 | GMNA |
| 2021692 | Rear Side Door Window Adjustment | 9467300 | GMK Overseas |
| 2021692 | Rear Side Door Window Adjustment | 9467400 | GMK Overseas |
| 2021800 | Rear Side Door Window Inner Sealing Strip Replacement | C0322 | GMNA |
| 2021800 | Rear Side Door Window Inner Sealing Strip Replacement | C032000 | Holden Australia |
| 2021800 | Rear Side Door Window Inner Sealing Strip Replacement | C032100 | Holden Australia |
| 2021800 | Rear Side Door Window Inner Sealing Strip Replacement | 9363100 | GMK Overseas |
| 2021800 | Rear Side Door Window Inner Sealing Strip Replacement | 9363200 | GMK Overseas |
| 2021800 | Rear Side Door Window Inner Sealing Strip Replacement | 9363300 | GMK Overseas |
| 2021820 | Rear Side Door Window Outer Sealing Strip Replacement | C0323 | GMNA |
| 2021820 | Rear Side Door Window Outer Sealing Strip Replacement | 9635400 | GMK Overseas |
| 2021820 | Rear Side Door Window Outer Sealing Strip Replacement | 9635500 | GMK Overseas |
| 2021820 | Rear Side Door Window Outer Sealing Strip Replacement | 9635600 | GMK Overseas |
| 2021820 | Rear Side Door Window Outer Sealing Strip Replacement | 9638600 | GMK Overseas |
| 2021820 | Rear Side Door Window Outer Sealing Strip Replacement | 9638700 | GMK Overseas |
| 2021900 | Rear Side Door Window Channel Retainer Replacement | C0335 | GMNA |
| 2021900 | Rear Side Door Window Channel Retainer Replacement | 9638300 | GMK Overseas |
| 2021900 | Rear Side Door Window Channel Retainer Replacement | 9638400 | GMK Overseas |
| 2021970 | Rear Side Door Window Channel Replacement | C0340 | GMNA |
| 2021970 | Rear Side Door Window Channel Replacement | C0341 | GMNA |
| 2021970 | Rear Side Door Window Channel Replacement | C9508 | GMNA |
| 2021970 | Rear Side Door Window Channel Replacement | C018100 | Holden Australia |
| 2021970 | Rear Side Door Window Channel Replacement | C018200 | Holden Australia |
| 2021970 | Rear Side Door Window Channel Replacement | C034000 | Holden Australia |
| 2021970 | Rear Side Door Window Channel Replacement | C034100 | Holden Australia |
| 2021970 | Rear Side Door Window Channel Replacement | C118700 | Holden Australia |
| 2021970 | Rear Side Door Window Channel Replacement | C118800 | Holden Australia |
| 2021970 | Rear Side Door Window Channel Replacement | C127500 | Holden Australia |
| 2021970 | Rear Side Door Window Channel Replacement | C127700 | Holden Australia |
| 2021970 | Rear Side Door Window Channel Replacement | C127800 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2021970 | Rear Side Door Window Channel Replacement | C836100 | Holden Australia |
| 2021970 | Rear Side Door Window Channel Replacement | C836200 | Holden Australia |
| 2021970 | Rear Side Door Window Channel Replacement | C018100 | Holden New Zealand |
| 2021970 | Rear Side Door Window Channel Replacement | C018200 | Holden New Zealand |
| 2021970 | Rear Side Door Window Channel Replacement | C034000 | Holden New Zealand |
| 2021970 | Rear Side Door Window Channel Replacement | C034100 | Holden New Zealand |
| 2021970 | Rear Side Door Window Channel Replacement | C118700 | Holden New Zealand |
| 2021970 | Rear Side Door Window Channel Replacement | C118800 | Holden New Zealand |
| 2021970 | Rear Side Door Window Channel Replacement | C127500 | Holden New Zealand |
| 2021970 | Rear Side Door Window Channel Replacement | C127600 | Holden New Zealand |
| 2021970 | Rear Side Door Window Channel Replacement | C127700 | Holden New Zealand |
| 2021970 | Rear Side Door Window Channel Replacement | C127800 | Holden New Zealand |
| 2021970 | Rear Side Door Window Channel Replacement | C836100 | Holden New Zealand |
| 2021970 | Rear Side Door Window Channel Replacement | C836200 | Holden New Zealand |
| 2022050 | Rear Side Door Window Rear Channel Replacement | C0350 | GMNA |
| 2022100 | Rear Side Door Window Rear Guide Replacement | C0184 | GMNA |
| 2022100 | Rear Side Door Window Rear Guide Replacement | C0220 | GMNA |
| 2022100 | Rear Side Door Window Rear Guide Replacement | C0221 | GMNA |
| 2022100 | Rear Side Door Window Rear Guide Replacement | C0352 | GMNA |
| 2022100 | Rear Side Door Window Rear Guide Replacement | C9751 | GMNA |
| 2022100 | Rear Side Door Window Rear Guide Replacement | 8622000 | GMK Domestic |
| 2022100 | Rear Side Door Window Rear Guide Replacement | C008260 | Holden Australia |
| 2022100 | Rear Side Door Window Rear Guide Replacement | C013170 | Holden Australia |
| 2022100 | Rear Side Door Window Rear Guide Replacement | C013270 | Holden Australia |
| 2022100 | Rear Side Door Window Rear Guide Replacement | C017100 | Holden Australia |
| 2022100 | Rear Side Door Window Rear Guide Replacement | C017200 | Holden Australia |
| 2022100 | Rear Side Door Window Rear Guide Replacement | C008260 | Holden New Zealand |
| 2022100 | Rear Side Door Window Rear Guide Replacement | C013170 | Holden New Zealand |
| 2022100 | Rear Side Door Window Rear Guide Replacement | C013270 | Holden New Zealand |
| 2022100 | Rear Side Door Window Rear Guide Replacement | C017100 | Holden New Zealand |
| 2022100 | Rear Side Door Window Rear Guide Replacement | C017200 | Holden New Zealand |
| 2022100 | Rear Side Door Window Rear Guide Replacement | 9636910 | GMK Overseas |
| 2022100 | Rear Side Door Window Rear Guide Replacement | 9636920 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2022100 | Rear Side Door Window Rear Guide Replacement | 9636930 | GMK Overseas |
| 2022120 | Rear Side Door Window Front Channel Replacement | C0354 | GMNA |
| 2022120 | Rear Side Door Window Front Channel Replacement | C0355 | GMNA |
| 2022310 | Rear Side Door Window Regulator Replacement | C0370 | GMNA |
| 2022310 | Rear Side Door Window Regulator Replacement | C0371 | GMNA |
| 2022310 | Rear Side Door Window Regulator Replacement | C0382 | GMNA |
| 2022310 | Rear Side Door Window Regulator Replacement | 8622100 | GMK Domestic |
| 2022310 | Rear Side Door Window Regulator Replacement | 8622200 | GMK Domestic |
| 2022310 | Rear Side Door Window Regulator Replacement | C013130 | Holden Australia |
| 2022310 | Rear Side Door Window Regulator Replacement | C013230 | Holden Australia |
| 2022310 | Rear Side Door Window Regulator Replacement | C038000 | Holden Australia |
| 2022310 | Rear Side Door Window Regulator Replacement | C038100 | Holden Australia |
| 2022310 | Rear Side Door Window Regulator Replacement | C038200 | Holden Australia |
| 2022310 | Rear Side Door Window Regulator Replacement | C038300 | Holden Australia |
| 2022310 | Rear Side Door Window Regulator Replacement | C332200 | Holden Australia |
| 2022310 | Rear Side Door Window Regulator Replacement | C013230 | Holden New Zealand |
| 2022310 | Rear Side Door Window Regulator Replacement | 9636100 | GMK Overseas |
| 2022310 | Rear Side Door Window Regulator Replacement | 9636200 | GMK Overseas |
| 2022310 | Rear Side Door Window Regulator Replacement | 9636300 | GMK Overseas |
| 2022310 | Rear Side Door Window Regulator Replacement | 9636400 | GMK Overseas |
| 2022310 | Rear Side Door Window Regulator Replacement | 9636500 | GMK Overseas |
| 2022480 | Rear Side Door Stationary Window Replacement | C0402 | GMNA |
| 2022480 | Rear Side Door Stationary Window Replacement | 9463100 | GMK Overseas |
| 2022480 | Rear Side Door Stationary Window Replacement | 9463200 | GMK Overseas |
| 2022500 | Rear Side Door Stationary Window Sealing Strip Replacement | | |
| 2022520 | Rear Side Door Window Channel Insulator Replacement | C0409 | GMNA |
| 2022520 | Rear Side Door Window Channel Insulator Replacement | 9640300 | GMK Overseas |
| 2022520 | Rear Side Door Window Channel Insulator Replacement | 9640400 | GMK Overseas |
| 2022540 | Rear Side Door Stationary Window Divider Channel Replacement | C0410 | GMNA |
| 2022540 | Rear Side Door Stationary Window Divider Channel Replacement | C0411 | GMNA |
| 2022640 | Midgate Window Replacement | C0436 | GMNA |
| 2022640 | Midgate Window Replacement | C0438 | GMNA |
| 2022640 | Midgate Window Replacement | C0439 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2022640 | Midgate Window Replacement | N3332 | GMNA |
| 2022642 | Midgate Window Adjustment | C0435 | GMNA |
| 2022660 | Midgate Window Outer Sealing Strip Replacement | | |
| 2022890 | Quarter Window Regulator Replacement | C0480 | GMNA |
| 2022890 | Quarter Window Regulator Replacement | C000725 | Holden New Zealand |
| 2022970 | Body Side Front Window Replacement | | |
| 2022990 | Body Side Rear Window Replacement | C0508 | GMNA |
| 2023010 | Quarter Window Replacement | C0509 | GMNA |
| 2023010 | Quarter Window Replacement | 9464100 | GMK Overseas |
| 2023010 | Quarter Window Replacement | 9464200 | GMK Overseas |
| 2023010 | Quarter Window Replacement | 9465100 | GMK Overseas |
| 2023010 | Quarter Window Replacement | 9465200 | GMK Overseas |
| 2023030 | Body Side Window Replacement | C0510 | GMNA |
| 2023030 | Body Side Window Replacement | C004100 | Holden Australia |
| 2023030 | Body Side Window Replacement | C004200 | Holden Australia |
| 2023030 | Body Side Window Replacement | C004100 | Holden New Zealand |
| 2023450 | Quarter Window Outer Belt Sealing Strip Replacement | C0557 | GMNA |
| 2023490 | Quarter Window Reveal Molding Replacement | C0559 | GMNA |
| 2023490 | Quarter Window Reveal Molding Replacement | C0600 | GMNA |
| 2023570 | Rear Window Defogger Switch Replacement | C0630 | GMNA |
| 2023570 | Rear Window Defogger Switch Replacement | R2020 | GMNA |
| 2023570 | Rear Window Defogger Switch Replacement | R2110 | GMNA |
| 2023570 | Rear Window Defogger Switch Replacement | D200100 | Holden Australia |
| 2023570 | Rear Window Defogger Switch Replacement | N224300 | Holden Australia |
| 2023570 | Rear Window Defogger Switch Replacement | 7323300 | GMK Overseas |
| 2023570 | Rear Window Defogger Switch Replacement | 9321600 | GMK Overseas |
| 2023570 | Rear Window Defogger Switch Replacement | 9322500 | GMK Overseas |
| 2023590 | Rear Window Replacement | C0631 | GMNA |
| 2023590 | Rear Window Replacement | C0660 | GMNA |
| 2023590 | Rear Window Replacement | C9873 | GMNA |
| 2023590 | Rear Window Replacement | C066000 | Holden Australia |
| 2023590 | Rear Window Replacement | C0660 | Holden New Zealand |
| 2023590 | Rear Window Replacement | 9461700 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2023610 | Rear Sliding Window Replacement | C0684 | GMNA |
| 2023630 | Rear Sliding Window Regulator Replacement | C0685 | GMNA |
| 2023850 | Liftgate Window Hinge Replacement | C0730 | GMNA |
| 2023850 | Liftgate Window Hinge Replacement | 8627400 | GMK Domestic |
| 2023850 | Liftgate Window Hinge Replacement | 9784700 | GMK Overseas |
| 2023850 | Liftgate Window Hinge Replacement | 9784800 | GMK Overseas |
| 2023850 | Liftgate Window Hinge Replacement | 9784900 | GMK Overseas |
| 2023900 | Liftgate Window Strut Replacement | B9790 | GMNA |
| 2023900 | Liftgate Window Strut Replacement | C0740 | GMNA |
| 2023900 | Liftgate Window Strut Replacement | 8627500 | GMK Domestic |
| 2023900 | Liftgate Window Strut Replacement | 9785100 | GMK Overseas |
| 2023900 | Liftgate Window Strut Replacement | 9785200 | GMK Overseas |
| 2023900 | Liftgate Window Strut Replacement | 9785300 | GMK Overseas |
| 2023920 | Rear Compartment Lift Window Strut Replacement | C0742 | GMNA |
| 2023940 | Rear Compartment Lift Window Latch Replacement | C0743 | GMNA |
| 2024010 | Liftgate Window Weatherstrip Replacement | C0809 | GMNA |
| 2024010 | Liftgate Window Weatherstrip Replacement | 9463800 | GMK Overseas |
| 2024010 | Liftgate Window Weatherstrip Replacement | 9464000 | GMK Overseas |
| 2024010 | Liftgate Window Weatherstrip Replacement | 9465900 | GMK Overseas |
| 2024010 | Liftgate Window Weatherstrip Replacement | 9465910 | GMK Overseas |
| 2024030 | Liftgate Window Replacement | C0710 | GMNA |
| 2024030 | Liftgate Window Replacement | C0810 | GMNA |
| 2024030 | Liftgate Window Replacement | 8831100 | GMK Domestic |
| 2024030 | Liftgate Window Replacement | C002100 | Holden Australia |
| 2024030 | Liftgate Window Replacement | C020000 | Holden Australia |
| 2024030 | Liftgate Window Replacement | C020010 | Holden Australia |
| 2024030 | Liftgate Window Replacement | C020500 | Holden Australia |
| 2024030 | Liftgate Window Replacement | D906199 | Holden Australia |
| 2024030 | Liftgate Window Replacement | C020000 | Holden New Zealand |
| 2024030 | Liftgate Window Replacement | C020010 | Holden New Zealand |
| 2024030 | Liftgate Window Replacement | D906199 | Holden New Zealand |
| 2024030 | Liftgate Window Replacement | 9463700 | GMK Overseas |
| 2024030 | Liftgate Window Replacement | 946370A | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2024030 | Liftgate Window Replacement | 9463900 | GMK Overseas |
| 2024050 | Rear Compartment Lift Window Replacement | C0811 | GMNA |
| 2024070 | Liftgate Upper Window Replacement | C0812 | GMNA |
| 2024090 | Liftgate Lower Window Replacement | C0813 | GMNA |
| 2024090 | Liftgate Lower Window Replacement | 9467900 | GMK Overseas |
| 2024270 | Windshield Frame Weatherstrip Replacement | C1000 | GMNA |
| 2024270 | Windshield Frame Weatherstrip Replacement | C1005 | GMNA |
| 2024410 | Front Side Door Window Weatherstrip Replacement | C1044 | GMNA |
| 2024410 | Front Side Door Window Weatherstrip Replacement | 8615400 | GMK Domestic |
| 2024410 | Front Side Door Window Weatherstrip Replacement | 8615700 | GMK Domestic |
| 2024410 | Front Side Door Window Weatherstrip Replacement | C118300 | Holden Australia |
| 2024410 | Front Side Door Window Weatherstrip Replacement | C118400 | Holden Australia |
| 2024410 | Front Side Door Window Weatherstrip Replacement | C118300 | Holden New Zealand |
| 2024410 | Front Side Door Window Weatherstrip Replacement | C118400 | Holden New Zealand |
| 2024410 | Front Side Door Window Weatherstrip Replacement | 9615100 | GMK Overseas |
| 2024410 | Front Side Door Window Weatherstrip Replacement | 9615200 | GMK Overseas |
| 2024410 | Front Side Door Window Weatherstrip Replacement | 9615400 | GMK Overseas |
| 2024410 | Front Side Door Window Weatherstrip Replacement | 9615500 | GMK Overseas |
| 2024410 | Front Side Door Window Weatherstrip Replacement | 9615600 | GMK Overseas |
| 2024430 | Front Side Door Window Inner Weatherstrip Replacement | C1045 | GMNA |
| 2024450 | Front Side Door Window Outer Weatherstrip Replacement | C1046 | GMNA |
| 2024530 | Rear Side Door Window Inner Weatherstrip Replacement | C1133 | GMNA |
| 2024550 | Rear Side Door Window Outer Weatherstrip Replacement | C1134 | GMNA |
| 2024550 | Rear Side Door Window Outer Weatherstrip Replacement | C1290 | GMNA |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | B9935 | GMNA |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | C1135 | GMNA |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | C1160 | GMNA |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | C1161 | GMNA |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | 8625300 | GMK Domestic |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | C110100 | Holden Australia |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | C110200 | Holden Australia |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | C1120 | Holden Australia |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | C1121 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2024570 | Rear Side Door Window Weatherstrip Replacement | C1138 | Holden Australia |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | C118500 | Holden Australia |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | C118600 | Holden Australia |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | C127600 | Holden Australia |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | C110100 | Holden New Zealand |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | C110200 | Holden New Zealand |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | C118500 | Holden New Zealand |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | C118600 | Holden New Zealand |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | 9635100 | GMK Overseas |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | 9635200 | GMK Overseas |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | 9639100 | GMK Overseas |
| 2024570 | Rear Side Door Window Weatherstrip Replacement | 9639200 | GMK Overseas |
| 2024650 | Intermediate Side Door Window Weatherstrip Replacement | C1202 | GMNA |
| 2024650 | Intermediate Side Door Window Weatherstrip Replacement | C1203 | GMNA |
| 2024820 | Rear Window Weatherstrip Replacement | C1259 | GMNA |
| 2024820 | Rear Window Weatherstrip Replacement | C9916 | GMNA |
| 2024930 | Roof Lift Off Panel/Window Rear Weatherstrip Replacement | C1424 | GMNA |
| 2024950 | Front Side Door Window and Multifunction Switch Replacement | N2118 | GMNA |
| 2024950 | Front Side Door Window and Multifunction Switch Replacement | N226000 | Holden Australia |
| 2024950 | Front Side Door Window and Multifunction Switch Replacement | N226000 | Holden New Zealand |
| 2024970 | Front Side Door Window and Rear Side Door Window Switch Replacement | N2119 | GMNA |
| 2024980 | Front Side Door Window, Rear Side Door Window, and Multifunction Switch Replacement | N2130 | GMNA |
| 2025110 | Front Side Door Window Switch Replacement | N2010 | GMNA |
| 2025110 | Front Side Door Window Switch Replacement | N2015 | GMNA |
| 2025110 | Front Side Door Window Switch Replacement | N2070 | GMNA |
| 2025110 | Front Side Door Window Switch Replacement | N2144 | GMNA |
| 2025110 | Front Side Door Window Switch Replacement | N2985 | GMNA |
| 2025110 | Front Side Door Window Switch Replacement | N2144 | Holden Australia |
| 2025110 | Front Side Door Window Switch Replacement | N214400 | Holden Australia |
| 2025110 | Front Side Door Window Switch Replacement | N226100 | Holden Australia |
| 2025110 | Front Side Door Window Switch Replacement | N2144 | Holden New Zealand |
| 2025110 | Front Side Door Window Switch Replacement | N214400 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2025110 | Front Side Door Window Switch Replacement | N226100 | Holden New Zealand |
| 2025110 | Front Side Door Window Switch Replacement | N226500 | Holden New Zealand |
| 2025110 | Front Side Door Window Switch Replacement | N228300 | Holden New Zealand |
| 2025160 | Rear Side Door Window Switch Replacement | N2154 | GMNA |
| 2025160 | Rear Side Door Window Switch Replacement | 8622620 | GMK Domestic |
| 2025160 | Rear Side Door Window Switch Replacement | 8622700 | GMK Domestic |
| 2025160 | Rear Side Door Window Switch Replacement | 8622800 | GMK Domestic |
| 2025160 | Rear Side Door Window Switch Replacement | N2154 | Holden Australia |
| 2025160 | Rear Side Door Window Switch Replacement | N215400 | Holden Australia |
| 2025160 | Rear Side Door Window Switch Replacement | N230100 | Holden Australia |
| 2025160 | Rear Side Door Window Switch Replacement | N230200 | Holden Australia |
| 2025160 | Rear Side Door Window Switch Replacement | N2154 | Holden New Zealand |
| 2025160 | Rear Side Door Window Switch Replacement | N215400 | Holden New Zealand |
| 2025160 | Rear Side Door Window Switch Replacement | N228100 | Holden New Zealand |
| 2025160 | Rear Side Door Window Switch Replacement | N230100 | Holden New Zealand |
| 2025160 | Rear Side Door Window Switch Replacement | 9361700 | GMK Overseas |
| 2025160 | Rear Side Door Window Switch Replacement | 9361800 | GMK Overseas |
| 2025160 | Rear Side Door Window Switch Replacement | 9361900 | GMK Overseas |
| 2025210 | Quarter Window Switch Replacement | N2164 | GMNA |
| 2025290 | Rear Window Defogger Relay Replacement | N2987 | GMNA |
| 2025310 | Front Side Door Window Regulator Motor Replacement | B4307 | GMNA |
| 2025310 | Front Side Door Window Regulator Motor Replacement | B4308 | GMNA |
| 2025310 | Front Side Door Window Regulator Motor Replacement | B6822 | GMNA |
| 2025310 | Front Side Door Window Regulator Motor Replacement | B9885 | GMNA |
| 2025310 | Front Side Door Window Regulator Motor Replacement | B9886 | GMNA |
| 2025310 | Front Side Door Window Regulator Motor Replacement | B9899 | GMNA |
| 2025310 | Front Side Door Window Regulator Motor Replacement | C0166 | GMNA |
| 2025310 | Front Side Door Window Regulator Motor Replacement | C0170 | GMNA |
| 2025310 | Front Side Door Window Regulator Motor Replacement | C0171 | GMNA |
| 2025310 | Front Side Door Window Regulator Motor Replacement | C9831 | GMNA |
| 2025310 | Front Side Door Window Regulator Motor Replacement | C9890 | GMNA |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N3312 | GMNA |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N3314 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2025310 | Front Side Door Window Regulator Motor Replacement | N3315 | GMNA |
| 2025310 | Front Side Door Window Regulator Motor Replacement | 8610900 | GMK Domestic |
| 2025310 | Front Side Door Window Regulator Motor Replacement | 8610902 | GMK Domestic |
| 2025310 | Front Side Door Window Regulator Motor Replacement | 8611000 | GMK Domestic |
| 2025310 | Front Side Door Window Regulator Motor Replacement | 8611100 | GMK Domestic |
| 2025310 | Front Side Door Window Regulator Motor Replacement | C000725 | Holden Australia |
| 2025310 | Front Side Door Window Regulator Motor Replacement | C006100 | Holden Australia |
| 2025310 | Front Side Door Window Regulator Motor Replacement | C006200 | Holden Australia |
| 2025310 | Front Side Door Window Regulator Motor Replacement | C332100 | Holden Australia |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N227100 | Holden Australia |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N227150 | Holden Australia |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N227200 | Holden Australia |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N227250 | Holden Australia |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N331000 | Holden Australia |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N331100 | Holden Australia |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N3314 | Holden Australia |
| 2025310 | Front Side Door Window Regulator Motor Replacement | C006100 | Holden New Zealand |
| 2025310 | Front Side Door Window Regulator Motor Replacement | C006200 | Holden New Zealand |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N227100 | Holden New Zealand |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N227150 | Holden New Zealand |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N227200 | Holden New Zealand |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N227250 | Holden New Zealand |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N3310 | Holden New Zealand |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N331000 | Holden New Zealand |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N3311 | Holden New Zealand |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N331100 | Holden New Zealand |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N3314 | Holden New Zealand |
| 2025310 | Front Side Door Window Regulator Motor Replacement | N3315 | Holden New Zealand |
| 2025310 | Front Side Door Window Regulator Motor Replacement | 9616700 | GMK Overseas |
| 2025310 | Front Side Door Window Regulator Motor Replacement | 9616800 | GMK Overseas |
| 2025310 | Front Side Door Window Regulator Motor Replacement | 9616900 | GMK Overseas |
| 2025360 | Rear Side Door Window Regulator Motor Replacement | N3324 | GMNA |
| 2025360 | Rear Side Door Window Regulator Motor Replacement | N229100 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2025360 | Rear Side Door Window Regulator Motor Replacement | N229150 | Holden Australia |
| 2025360 | Rear Side Door Window Regulator Motor Replacement | N229250 | Holden Australia |
| 2025360 | Rear Side Door Window Regulator Motor Replacement | 9636600 | GMK Overseas |
| 2025360 | Rear Side Door Window Regulator Motor Replacement | 9636700 | GMK Overseas |
| 2025410 | Quarter Window Regulator Motor Replacement | N3320 | GMNA |
| 2025410 | Quarter Window Regulator Motor Replacement | N332400 | Holden Australia |
| 2025410 | Quarter Window Regulator Motor Replacement | N332500 | Holden Australia |
| 2025410 | Quarter Window Regulator Motor Replacement | N332700 | Holden Australia |
| 2025410 | Quarter Window Regulator Motor Replacement | N332400 | Holden New Zealand |
| 2025410 | Quarter Window Regulator Motor Replacement | N332500 | Holden New Zealand |
| 2025460 | Midgate Window Regulator Module Motor Replacement | | |
| 2025480 | Rear Sliding Window Module Replacement | N4890 | GMNA |
| 2025500 | Front Side Door Window Control Module Replacement | | |
| 2029939 | Customer Concerned Not Duplicated (CCND) - Electronics/Safety/Seat/Lighting/Keyless Entry/Theft Alarm | N9993 | GMNA |
| 2030010 | Steering Wheel Horn Contact Replacement | E7100 | GMNA |
| 2030010 | Steering Wheel Horn Contact Replacement | 6423400 | GMK Domestic |
| 2030010 | Steering Wheel Horn Contact Replacement | 6423500 | GMK Domestic |
| 2030010 | Steering Wheel Horn Contact Replacement | E710000 | Holden Australia |
| 2030010 | Steering Wheel Horn Contact Replacement | E710000 | Holden New Zealand |
| 2030010 | Steering Wheel Horn Contact Replacement | 6410300 | GMK Overseas |
| 2030010 | Steering Wheel Horn Contact Replacement | 641030A | GMK Overseas |
| 2030020 | Steering Wheel Horn Switch Replacement | E7110 | GMNA |
| 2030020 | Steering Wheel Horn Switch Replacement | N204500 | Holden New Zealand |
| 2030030 | Horn Replacement | N0200 | GMNA |
| 2030030 | Horn Replacement | N0201 | GMNA |
| 2030030 | Horn Replacement | N0210 | GMNA |
| 2030030 | Horn Replacement | 6422900 | GMK Domestic |
| 2030030 | Horn Replacement | 6423000 | GMK Domestic |
| 2030030 | Horn Replacement | N0200 | Holden Australia |
| 2030030 | Horn Replacement | N200500 | Holden Australia |
| 2030030 | Horn Replacement | N200550 | Holden Australia |
| 2030030 | Horn Replacement | N203500 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2030030 | Horn Replacement | N0200 | Holden New Zealand |
| 2030030 | Horn Replacement | N200500 | Holden New Zealand |
| 2030030 | Horn Replacement | N200550 | Holden New Zealand |
| 2030030 | Horn Replacement | 9281100 | GMK Overseas |
| 2030030 | Horn Replacement | 928110A | GMK Overseas |
| 2040150 | Front Fog Lamp Bracket Replacement | B1334 | GMNA |
| 2040260 | Outside Rearview Mirror Courtesy Lamp Replacement | B4158 | GMNA |
| 2040300 | Front Fog Lamp Cover Replacement | B7248 | GMNA |
| 2040510 | Headlamp Replacement | B7294 | GMNA |
| 2040510 | Headlamp Replacement | N0250 | GMNA |
| 2040510 | Headlamp Replacement | N0251 | GMNA |
| 2040510 | Headlamp Replacement | N025000 | Holden Australia |
| 2040510 | Headlamp Replacement | N104100 | Holden Australia |
| 2040510 | Headlamp Replacement | N104200 | Holden Australia |
| 2040510 | Headlamp Replacement | N0250 | Holden New Zealand |
| 2040510 | Headlamp Replacement | N025000 | Holden New Zealand |
| 2040510 | Headlamp Replacement | N0253 | Holden New Zealand |
| 2040510 | Headlamp Replacement | N102000 | Holden New Zealand |
| 2040510 | Headlamp Replacement | N102100 | Holden New Zealand |
| 2040510 | Headlamp Replacement | N102200 | Holden New Zealand |
| 2040510 | Headlamp Replacement | N104100 | Holden New Zealand |
| 2040510 | Headlamp Replacement | N104200 | Holden New Zealand |
| 2040510 | Headlamp Replacement | 9160100 | GMK Overseas |
| 2040510 | Headlamp Replacement | 916010A | GMK Overseas |
| 2040510 | Headlamp Replacement | 9160200 | GMK Overseas |
| 2040510 | Headlamp Replacement | 9160300 | GMK Overseas |
| 2040512 | Headlamp Aiming | B7280 | GMNA |
| 2040512 | Headlamp Aiming | N0225 | GMNA |
| 2040512 | Headlamp Aiming | B7280 | Holden Australia |
| 2040512 | Headlamp Aiming | 9163100 | GMK Overseas |
| 2040560 | Headlamp Capsule Replacement | B7296 | GMNA |
| 2040560 | Headlamp Capsule Replacement | B7298 | GMNA |
| 2040560 | Headlamp Capsule Replacement | N0230 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2040670 | Backup Lamp Applique Replacement | B8669 | GMNA |
| 2040690 | Tail Lamp Applique Replacement | B8670 | GMNA |
| 2040740 | Tail Lamp Guard Replacement | | |
| 2040870 | Rear Reflector Replacement | B5510 | GMNA |
| 2040870 | Rear Reflector Replacement | B8988 | GMNA |
| 2040920 | Daytime Running Lamp Replacement | | |
| 2040970 | Cornering Lamp Replacement | B9604 | GMNA |
| 2041020 | Front Parking and Turn Signal and Fog Lamp Assembly Replacement | B9606 | GMNA |
| 2041020 | Front Parking and Turn Signal and Fog Lamp Assembly Replacement | N118100 | Holden New Zealand |
| 2041040 | Front Fog Lamp Replacement | B9612 | GMNA |
| 2041040 | Front Fog Lamp Replacement | N0515 | GMNA |
| 2041040 | Front Fog Lamp Replacement | N1462 | GMNA |
| 2041040 | Front Fog Lamp Replacement | N1463 | GMNA |
| 2041040 | Front Fog Lamp Replacement | N1465 | GMNA |
| 2041040 | Front Fog Lamp Replacement | N1466 | GMNA |
| 2041040 | Front Fog Lamp Replacement | N1467 | GMNA |
| 2041040 | Front Fog Lamp Replacement | A506000 | Holden Australia |
| 2041040 | Front Fog Lamp Replacement | B9612 | Holden Australia |
| 2041040 | Front Fog Lamp Replacement | N008000 | Holden Australia |
| 2041040 | Front Fog Lamp Replacement | N008010 | Holden Australia |
| 2041040 | Front Fog Lamp Replacement | N008020 | Holden Australia |
| 2041040 | Front Fog Lamp Replacement | N146600 | Holden Australia |
| 2041040 | Front Fog Lamp Replacement | N146700 | Holden Australia |
| 2041040 | Front Fog Lamp Replacement | A506000 | Holden New Zealand |
| 2041040 | Front Fog Lamp Replacement | N008000 | Holden New Zealand |
| 2041040 | Front Fog Lamp Replacement | N008010 | Holden New Zealand |
| 2041040 | Front Fog Lamp Replacement | N008020 | Holden New Zealand |
| 2041040 | Front Fog Lamp Replacement | N146600 | Holden New Zealand |
| 2041040 | Front Fog Lamp Replacement | N146700 | Holden New Zealand |
| 2041040 | Front Fog Lamp Replacement | R104000 | Holden New Zealand |
| 2041040 | Front Fog Lamp Replacement | 9161500 | GMK Overseas |
| 2041040 | Front Fog Lamp Replacement | 9161520 | GMK Overseas |
| 2041040 | Front Fog Lamp Replacement | 9161600 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2041040 | Front Fog Lamp Replacement | 9170500 | GMK Overseas |
| 2041040 | Front Fog Lamp Replacement | 9170600 | GMK Overseas |
| 2041042 | Fog Lamp Aiming | B7282 | GMNA |
| 2041042 | Fog Lamp Aiming | N0227 | GMNA |
| 2041090 | Parking and Turn Signal Lamp Replacement | B9616 | GMNA |
| 2041090 | Parking and Turn Signal Lamp Replacement | B9616 | Holden Australia |
| 2041090 | Parking and Turn Signal Lamp Replacement | T881501 | Holden New Zealand |
| 2041090 | Parking and Turn Signal Lamp Replacement | 9162100 | GMK Overseas |
| 2041140 | Spot Lamp Replacement | B9620 | GMNA |
| 2041160 | Outside Rearview Mirror Turn Signal Lamp Replacement | B9621 | GMNA |
| 2041160 | Outside Rearview Mirror Turn Signal Lamp Replacement | N0555 | GMNA |
| 2041160 | Outside Rearview Mirror Turn Signal Lamp Replacement | R005610 | Holden Australia |
| 2041160 | Outside Rearview Mirror Turn Signal Lamp Replacement | 9171900 | GMK Overseas |
| 2041160 | Outside Rearview Mirror Turn Signal Lamp Replacement | 9172000 | GMK Overseas |
| 2041210 | Front Side Turn Signal Lamp Replacement | B9625 | GMNA |
| 2041210 | Front Side Turn Signal Lamp Replacement | 5540400 | GMK Domestic |
| 2041210 | Front Side Turn Signal Lamp Replacement | N0682 | Holden Australia |
| 2041210 | Front Side Turn Signal Lamp Replacement | N104230 | Holden Australia |
| 2041210 | Front Side Turn Signal Lamp Replacement | N118300 | Holden Australia |
| 2041210 | Front Side Turn Signal Lamp Replacement | N118400 | Holden Australia |
| 2041210 | Front Side Turn Signal Lamp Replacement | N104230 | Holden New Zealand |
| 2041210 | Front Side Turn Signal Lamp Replacement | N104240 | Holden New Zealand |
| 2041210 | Front Side Turn Signal Lamp Replacement | 9163500 | GMK Overseas |
| 2041210 | Front Side Turn Signal Lamp Replacement | 916350A | GMK Overseas |
| 2041210 | Front Side Turn Signal Lamp Replacement | 9163600 | GMK Overseas |
| 2041210 | Front Side Turn Signal Lamp Replacement | 9163700 | GMK Overseas |
| 2041210 | Front Side Turn Signal Lamp Replacement | 9171200 | GMK Overseas |
| 2041210 | Front Side Turn Signal Lamp Replacement | 9171300 | GMK Overseas |
| 2041230 | Front Side Marker Lamp Replacement | B9626 | GMNA |
| 2041230 | Front Side Marker Lamp Replacement | 5621100 | GMK Domestic |
| 2041230 | Front Side Marker Lamp Replacement | B9626 | Holden Australia |
| 2041230 | Front Side Marker Lamp Replacement | 9162400 | GMK Overseas |
| 2041230 | Front Side Marker Lamp Replacement | 9162500 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2041280 | Rear Side Marker Lamp Replacement | B9630 | GMNA |
| 2041280 | Rear Side Marker Lamp Replacement | 9182100 | GMK Overseas |
| 2041280 | Rear Side Marker Lamp Replacement | 9182200 | GMK Overseas |
| 2041330 | Roof Clearance Center Lamp Replacement | B9633 | GMNA |
| 2041350 | Roof Clearance Outer Lamp Replacement | B9634 | GMNA |
| 2041370 | Rear Fender Clearance Lamp Replacement | B9635 | GMNA |
| 2041390 | Emergency Vehicle Rear Lamp Replacement | B9638 | GMNA |
| 2041410 | Emergency Vehicle Rear Compartment Lid Lamp Replacement | B9639 | GMNA |
| 2041490 | Tail Lamp Replacement | B9643 | GMNA |
| 2041490 | Tail Lamp Replacement | 5610100 | GMK Domestic |
| 2041490 | Tail Lamp Replacement | 5610120 | GMK Domestic |
| 2041490 | Tail Lamp Replacement | N122100 | Holden Australia |
| 2041490 | Tail Lamp Replacement | N122200 | Holden Australia |
| 2041490 | Tail Lamp Replacement | 9180100 | GMK Overseas |
| 2041490 | Tail Lamp Replacement | 9180200 | GMK Overseas |
| 2041490 | Tail Lamp Replacement | 9180300 | GMK Overseas |
| 2041490 | Tail Lamp Replacement | 9180410 | GMK Overseas |
| 2041490 | Tail Lamp Replacement | 9180420 | GMK Overseas |
| 2041490 | Tail Lamp Replacement | 9180430 | GMK Overseas |
| 2041510 | Tail Lamp Replacement - Inboard | B9644 | GMNA |
| 2041510 | Tail Lamp Replacement - Inboard | 5620300 | GMK Domestic |
| 2041510 | Tail Lamp Replacement - Inboard | 9183700 | GMK Overseas |
| 2041510 | Tail Lamp Replacement - Inboard | 9183800 | GMK Overseas |
| 2041530 | Tail Lamp Replacement - Outboard | B9645 | GMNA |
| 2041530 | Tail Lamp Replacement - Outboard | 5621000 | GMK Domestic |
| 2041530 | Tail Lamp Replacement - Outboard | 9183900 | GMK Overseas |
| 2041530 | Tail Lamp Replacement - Outboard | 9184000 | GMK Overseas |
| 2041610 | Backup Lamp Replacement | B9648 | GMNA |
| 2041610 | Backup Lamp Replacement | 5613500 | GMK Domestic |
| 2041610 | Backup Lamp Replacement | 9181000 | GMK Overseas |
| 2041610 | Backup Lamp Replacement | 9183400 | GMK Overseas |
| 2041610 | Backup Lamp Replacement | 9183500 | GMK Overseas |
| 2041610 | Backup Lamp Replacement | 9183600 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2041630 | Rear Auxiliary Turn Signal Lamp Replacement | B9649 | GMNA |
| 2041650 | High Mount Stop Lamp Replacement | B9650 | GMNA |
| 2041650 | High Mount Stop Lamp Replacement | N1600 | GMNA |
| 2041650 | High Mount Stop Lamp Replacement | N2865 | GMNA |
| 2041650 | High Mount Stop Lamp Replacement | N9645 | GMNA |
| 2041650 | High Mount Stop Lamp Replacement | 5341101 | GMK Domestic |
| 2041650 | High Mount Stop Lamp Replacement | 5611000 | GMK Domestic |
| 2041650 | High Mount Stop Lamp Replacement | B9650 | Holden Australia |
| 2041650 | High Mount Stop Lamp Replacement | N104280 | Holden Australia |
| 2041650 | High Mount Stop Lamp Replacement | N104285 | Holden Australia |
| 2041650 | High Mount Stop Lamp Replacement | N112510 | Holden Australia |
| 2041650 | High Mount Stop Lamp Replacement | N159900 | Holden Australia |
| 2041650 | High Mount Stop Lamp Replacement | R902400 | Holden Australia |
| 2041650 | High Mount Stop Lamp Replacement | N104280 | Holden New Zealand |
| 2041650 | High Mount Stop Lamp Replacement | N104285 | Holden New Zealand |
| 2041650 | High Mount Stop Lamp Replacement | N159900 | Holden New Zealand |
| 2041650 | High Mount Stop Lamp Replacement | R902400 | Holden New Zealand |
| 2041650 | High Mount Stop Lamp Replacement | 9181600 | GMK Overseas |
| 2041650 | High Mount Stop Lamp Replacement | 9181700 | GMK Overseas |
| 2041670 | Rear Fog Lamp Replacement | B9651 | GMNA |
| 2041670 | Rear Fog Lamp Replacement | 5334200 | GMK Domestic |
| 2041670 | Rear Fog Lamp Replacement | 9181300 | GMK Overseas |
| 2041670 | Rear Fog Lamp Replacement | 9181320 | GMK Overseas |
| 2041710 | Pickup Box Identification Lamp Replacement | B9653 | GMNA |
| 2041760 | Rear License Plate Lamp Replacement | B9655 | GMNA |
| 2041760 | Rear License Plate Lamp Replacement | N126500 | Holden Australia |
| 2041770 | Tail Lamp Mount Plate Replacement | | |
| 2041780 | Tail Lamp Housing Replacement | B9642 | GMNA |
| 2041780 | Tail Lamp Housing Replacement | B9656 | GMNA |
| 2041800 | Underhood Lamp Replacement | B9660 | GMNA |
| 2041800 | Underhood Lamp Replacement | N1290 | GMNA |
| 2041800 | Underhood Lamp Replacement | N1610 | GMNA |
| 2041800 | Underhood Lamp Replacement | B9660 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2041820 | Backup and Rear Fog Lamp Replacement | B9661 | GMNA |
| 2041820 | Backup and Rear Fog Lamp Replacement | N217700 | Holden Australia |
| 2041820 | Backup and Rear Fog Lamp Replacement | 9182900 | GMK Overseas |
| 2041860 | Sunshade Illuminated Mirror Lamp Lens Replacement | C2019 | GMNA |
| 2041880 | Inside Rearview Mirror Lamp Replacement | | |
| 2041900 | Front Floor Flood Lamp Replacement | C2081 | GMNA |
| 2041920 | Headlamp Automatic Control Ambient Light Sensor Bezel Replacement | | |
| 2041940 | Headlamp Automatic Control Ambient Light Sensor Opening Cover Replacement | | |
| 2041960 | Luminescent Lamp Replacement - Instrument Panel | | |
| 2041980 | Instrument Panel Compartment Lamp Replacement | C2139 | GMNA |
| 2041980 | Instrument Panel Compartment Lamp Replacement | N1165 | GMNA |
| 2041980 | Instrument Panel Compartment Lamp Replacement | N1470 | GMNA |
| 2041980 | Instrument Panel Compartment Lamp Replacement | N1474 | GMNA |
| 2041980 | Instrument Panel Compartment Lamp Replacement | 5321000 | GMK Domestic |
| 2041980 | Instrument Panel Compartment Lamp Replacement | N000414 | Holden Australia |
| 2041980 | Instrument Panel Compartment Lamp Replacement | N214500 | Holden Australia |
| 2041980 | Instrument Panel Compartment Lamp Replacement | N000414 | Holden New Zealand |
| 2041980 | Instrument Panel Compartment Lamp Replacement | N214500 | Holden New Zealand |
| 2041980 | Instrument Panel Compartment Lamp Replacement | 9281900 | GMK Overseas |
| 2042000 | Instrument Panel Courtesy Lamp Replacement - Right Side | C2422 | GMNA |
| 2042020 | Instrument Panel Courtesy Lamp Replacement - Left Side | C2423 | GMNA |
| 2042100 | Front Floor Console Flood Lamp Replacement | C2715 | GMNA |
| 2042120 | Front Floor Console Cup Holder Illumination Lamp Replacement | C2716 | GMNA |
| 2042140 | Front Floor Console Compartment Lamp Replacement | C2717 | GMNA |
| 2042140 | Front Floor Console Compartment Lamp Replacement | N0524 | GMNA |
| 2042140 | Front Floor Console Compartment Lamp Replacement | N1425 | GMNA |
| 2042160 | Front Floor Console Armrest Compartment Lamp Replacement | C2718 | GMNA |
| 2042180 | Roof Rail Courtesy and Reading Lamp Replacement | C3066 | GMNA |
| 2042200 | Roof Rail Rear Courtesy Lamp Replacement | C3068 | GMNA |
| 2042210 | Roof Rail Rear Seat Position Reading and Courtesy Lamp Replacement | | |
| 2042220 | Dome Lamp Replacement | 9281500 | GMK Overseas |
| 2042270 | Dome and Reading Lamp Replacement | C3069 | GMNA |
| 2042270 | Dome and Reading Lamp Replacement | C3071 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2042270 | Dome and Reading Lamp Replacement | N1440 | GMNA |
| 2042270 | Dome and Reading Lamp Replacement | N1456 | GMNA |
| 2042270 | Dome and Reading Lamp Replacement | 5521100 | GMK Domestic |
| 2042270 | Dome and Reading Lamp Replacement | 5521300 | GMK Domestic |
| 2042270 | Dome and Reading Lamp Replacement | 5521600 | GMK Domestic |
| 2042270 | Dome and Reading Lamp Replacement | 5521700 | GMK Domestic |
| 2042270 | Dome and Reading Lamp Replacement | N145600 | Holden Australia |
| 2042270 | Dome and Reading Lamp Replacement | N1456 | Holden New Zealand |
| 2042270 | Dome and Reading Lamp Replacement | 9282700 | GMK Overseas |
| 2042290 | Dome and Reading Lamp Replacement - Front | C3072 | GMNA |
| 2042290 | Dome and Reading Lamp Replacement - Front | C9799 | GMNA |
| 2042290 | Dome and Reading Lamp Replacement - Front | N1441 | GMNA |
| 2042290 | Dome and Reading Lamp Replacement - Front | N112400 | Holden Australia |
| 2042290 | Dome and Reading Lamp Replacement - Front | N112500 | Holden Australia |
| 2042290 | Dome and Reading Lamp Replacement - Front | N112400 | Holden New Zealand |
| 2042290 | Dome and Reading Lamp Replacement - Front | N112500 | Holden New Zealand |
| 2042310 | Dome and Reading Lamp Replacement - Rear | C3073 | GMNA |
| 2042320 | Center Reading and Courtesy Lamp Lens Replacement | | |
| 2042330 | Reading Lamp Replacement | C3074 | GMNA |
| 2042330 | Reading Lamp Replacement | N1487 | GMNA |
| 2042330 | Reading Lamp Replacement | N1490 | GMNA |
| 2042330 | Reading Lamp Replacement | 9281700 | GMK Overseas |
| 2042340 | Center Reading and Courtesy Lamp Replacement | | |
| 2042350 | Dome Lamp Lens Replacement | C3075 | GMNA |
| 2042360 | Center Reading Lamp Replacement | | |
| 2042370 | Dome Lamp Bezel Replacement | C3076 | GMNA |
| 2042370 | Dome Lamp Bezel Replacement | 9282800 | GMK Overseas |
| 2042390 | Luminescent Lamp Replacement - Roof Console | C3077 | GMNA |
| 2042410 | Dome Lamp Housing Replacement | C3078 | GMNA |
| 2042430 | Front Side Door Courtesy Lamp Lens Replacement | C3327 | GMNA |
| 2042450 | Front Side Door Courtesy Lamp Replacement | C3328 | GMNA |
| 2042470 | Front Side Door Warning Lamp Replacement | C3332 | GMNA |
| 2042490 | Front Side Door Inside Handle Illumination Lamp Replacement | C3333 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2042510 | Front Side Door Map Pocket Illumination Lamp Replacement | C3334 | GMNA |
| 2042530 | Front Side Door Sill Courtesy Lamp Replacement | C3368 | GMNA |
| 2042550 | Stepwell Lamp Replacement | 5622300 | GMK Domestic |
| 2042550 | Stepwell Lamp Replacement | 5622400 | GMK Domestic |
| 2042550 | Stepwell Lamp Replacement | 9281400 | GMK Overseas |
| 2042570 | Rear Side Door Inside Handle Illumination Lamp Replacement | C3503 | GMNA |
| 2042570 | Rear Side Door Inside Handle Illumination Lamp Replacement | 9641600 | GMK Overseas |
| 2042570 | Rear Side Door Inside Handle Illumination Lamp Replacement | 9641700 | GMK Overseas |
| 2042590 | Rear Side Door Warning Lamp Replacement | C3504 | GMNA |
| 2042600 | Rear Side Door Pocket Illumination Lamp Replacement | | |
| 2042610 | Rear Side Door Courtesy Lamp Replacement | C3505 | GMNA |
| 2042610 | Rear Side Door Courtesy Lamp Replacement | N1445 | GMNA |
| 2042610 | Rear Side Door Courtesy Lamp Replacement | N144200 | Holden Australia |
| 2042610 | Rear Side Door Courtesy Lamp Replacement | N144300 | Holden Australia |
| 2042610 | Rear Side Door Courtesy Lamp Replacement | N319200 | Holden Australia |
| 2042610 | Rear Side Door Courtesy Lamp Replacement | N319300 | Holden Australia |
| 2042610 | Rear Side Door Courtesy Lamp Replacement | N319200 | Holden New Zealand |
| 2042610 | Rear Side Door Courtesy Lamp Replacement | N319300 | Holden New Zealand |
| 2042620 | Rear Floor Flood Lamp Replacement | H0120 | Holden Australia |
| 2042630 | Cargo Lamp Replacement | C3989 | GMNA |
| 2042650 | Rear Compartment Courtesy Lamp Replacement | N2315 | GMNA |
| 2042650 | Rear Compartment Courtesy Lamp Replacement | N2591 | GMNA |
| 2042650 | Rear Compartment Courtesy Lamp Replacement | 5620000 | GMK Domestic |
| 2042650 | Rear Compartment Courtesy Lamp Replacement | N144500 | Holden Australia |
| 2042650 | Rear Compartment Courtesy Lamp Replacement | 9281300 | GMK Overseas |
| 2042670 | Liftgate Courtesy Lamp Replacement | C4858 | GMNA |
| 2042690 | Front Seat Back Courtesy Lamp Replacement | | |
| 2042700 | Sun Load Temperature and Headlamp Automatic Control Ambient Light Sensor Replacement | | |
| 2042710 | Brake Pedal Position Sensor Replacement | H2642 | GMNA |
| 2042710 | Brake Pedal Position Sensor Replacement | H9732 | GMNA |
| 2042710 | Brake Pedal Position Sensor Replacement | H9754 | GMNA |
| 2042710 | Brake Pedal Position Sensor Replacement | N207500 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2042710 | Brake Pedal Position Sensor Replacement | N207500 | Holden Australia |
| 2042710 | Brake Pedal Position Sensor Replacement | N207500 | Holden New Zealand |
| 2042710 | Brake Pedal Position Sensor Replacement | 4280700 | GMK Overseas |
| 2042730 | Headlamp Ballast Replacement | N0280 | GMNA |
| 2042900 | Headlamp Ignitor Replacement | N0286 | GMNA |
| 2042980 | Headlamp Leveling Front Suspension Height Sensor Replacement | N0310 | GMNA |
| 2042980 | Headlamp Leveling Front Suspension Height Sensor Replacement | 9164300 | GMK Overseas |
| 2043000 | Headlamp Leveling Rear Suspension Height Sensor Replacement | N0311 | GMNA |
| 2043000 | Headlamp Leveling Rear Suspension Height Sensor Replacement | 6420100 | GMK Domestic |
| 2043000 | Headlamp Leveling Rear Suspension Height Sensor Replacement | 9161800 | GMK Overseas |
| 2043080 | Daytime Running Lamp (DRL) Diode Replacement | N0360 | GMNA |
| 2043100 | Daytime Running Lamp Control Module Replacement | N0363 | GMNA |
| 2043100 | Daytime Running Lamp Control Module Replacement | 1584500 | GMK Overseas |
| 2043100 | Daytime Running Lamp Control Module Replacement | 1584600 | GMK Overseas |
| 2043120 | Daytime Running Lamp (DRL) Ambient Light Sensor Replacement | | |
| 2043140 | Sun Load Temperature and Daytime Running Lamp Ambient Light Sensor Replacement | | |
| 2043190 | Windshield Outside Moisture and Headlamp Automatic Control Ambient Light Sensor Replacement | N0368 | GMNA |
| 2043240 | Ashtray Lamp Bulb Replacement | N0400 | GMNA |
| 2043240 | Ashtray Lamp Bulb Replacement | 5320800 | GMK Domestic |
| 2043240 | Ashtray Lamp Bulb Replacement | 9341650 | GMK Overseas |
| 2043260 | Backup Lamp Bulb Replacement | N0410 | GMNA |
| 2043260 | Backup Lamp Bulb Replacement | N0414 | GMNA |
| 2043260 | Backup Lamp Bulb Replacement | N0416 | GMNA |
| 2043260 | Backup Lamp Bulb Replacement | N0417 | GMNA |
| 2043260 | Backup Lamp Bulb Replacement | N0418 | GMNA |
| 2043260 | Backup Lamp Bulb Replacement | 5615000 | GMK Domestic |
| 2043260 | Backup Lamp Bulb Replacement | N0410 | Holden Australia |
| 2043260 | Backup Lamp Bulb Replacement | N104380 | Holden Australia |
| 2043260 | Backup Lamp Bulb Replacement | N104380 | Holden New Zealand |
| 2043260 | Backup Lamp Bulb Replacement | 9181100 | GMK Overseas |
| 2043310 | Cargo Center Courtesy Lamp Bulb Replacement | N0420 | GMNA |
| 2043350 | Headlamp Bulb Replacement | N0440 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2043350 | Headlamp Bulb Replacement | N0442 | GMNA |
| 2043350 | Headlamp Bulb Replacement | N0443 | GMNA |
| 2043350 | Headlamp Bulb Replacement | N9666 | GMNA |
| 2043350 | Headlamp Bulb Replacement | 5330400 | GMK Domestic |
| 2043350 | Headlamp Bulb Replacement | 5330500 | GMK Domestic |
| 2043350 | Headlamp Bulb Replacement | 5530200 | GMK Domestic |
| 2043350 | Headlamp Bulb Replacement | N0441 | Holden Australia |
| 2043350 | Headlamp Bulb Replacement | N044200 | Holden Australia |
| 2043350 | Headlamp Bulb Replacement | N044300 | Holden Australia |
| 2043350 | Headlamp Bulb Replacement | N044400 | Holden Australia |
| 2043350 | Headlamp Bulb Replacement | N104340 | Holden Australia |
| 2043350 | Headlamp Bulb Replacement | N104345 | Holden Australia |
| 2043350 | Headlamp Bulb Replacement | N104440 | Holden Australia |
| 2043350 | Headlamp Bulb Replacement | N104445 | Holden Australia |
| 2043350 | Headlamp Bulb Replacement | N104460 | Holden Australia |
| 2043350 | Headlamp Bulb Replacement | N104480 | Holden Australia |
| 2043350 | Headlamp Bulb Replacement | N104490 | Holden Australia |
| 2043350 | Headlamp Bulb Replacement | N0442 | Holden New Zealand |
| 2043350 | Headlamp Bulb Replacement | N044200 | Holden New Zealand |
| 2043350 | Headlamp Bulb Replacement | N104340 | Holden New Zealand |
| 2043350 | Headlamp Bulb Replacement | N104440 | Holden New Zealand |
| 2043350 | Headlamp Bulb Replacement | N104460 | Holden New Zealand |
| 2043350 | Headlamp Bulb Replacement | N104470 | Holden New Zealand |
| 2043350 | Headlamp Bulb Replacement | N115500 | Holden New Zealand |
| 2043350 | Headlamp Bulb Replacement | 9160400 | GMK Overseas |
| 2043350 | Headlamp Bulb Replacement | 916040A | GMK Overseas |
| 2043350 | Headlamp Bulb Replacement | 9160500 | GMK Overseas |
| 2043350 | Headlamp Bulb Replacement | 9160600 | GMK Overseas |
| 2043400 | Cornering Lamp Bulb Replacement | N0476 | GMNA |
| 2043400 | Cornering Lamp Bulb Replacement | N104425 | Holden Australia |
| 2043400 | Cornering Lamp Bulb Replacement | N104425 | Holden New Zealand |
| 2043420 | Courtesy Lamp Bulb Replacement | N0480 | GMNA |
| 2043440 | Daytime Running Lamp Bulb Replacement | N0495 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2043440 | Daytime Running Lamp Bulb Replacement | N0496 | GMNA |
| 2043440 | Daytime Running Lamp Bulb Replacement | N104310 | Holden Australia |
| 2043440 | Daytime Running Lamp Bulb Replacement | N104320 | Holden Australia |
| 2043440 | Daytime Running Lamp Bulb Replacement | N104310 | Holden New Zealand |
| 2043440 | Daytime Running Lamp Bulb Replacement | N104320 | Holden New Zealand |
| 2043450 | Roof Console Lamp Bulb Replacement | | |
| 2043490 | Dome Lamp Bulb Replacement | N0507 | GMNA |
| 2043490 | Dome Lamp Bulb Replacement | 5321800 | GMK Domestic |
| 2043490 | Dome Lamp Bulb Replacement | N050700 | Holden Australia |
| 2043490 | Dome Lamp Bulb Replacement | N104420 | Holden Australia |
| 2043490 | Dome Lamp Bulb Replacement | N104420 | Holden New Zealand |
| 2043490 | Dome Lamp Bulb Replacement | 9281600 | GMK Overseas |
| 2043510 | Front Position Lamp Bulb Replacement | N0519 | GMNA |
| 2043510 | Front Position Lamp Bulb Replacement | 9161300 | GMK Overseas |
| 2043510 | Front Position Lamp Bulb Replacement | 9170300 | GMK Overseas |
| 2043510 | Front Position Lamp Bulb Replacement | 9170400 | GMK Overseas |
| 2043530 | Reading Lamp Bulb Replacement | N0520 | GMNA |
| 2043530 | Reading Lamp Bulb Replacement | N0670 | GMNA |
| 2043530 | Reading Lamp Bulb Replacement | N0520 | Holden Australia |
| 2043530 | Reading Lamp Bulb Replacement | 9281800 | GMK Overseas |
| 2043580 | Instrument Panel Compartment Lamp Bulb Replacement | N0560 | GMNA |
| 2043580 | Instrument Panel Compartment Lamp Bulb Replacement | 5321100 | GMK Domestic |
| 2043580 | Instrument Panel Compartment Lamp Bulb Replacement | 5523200 | GMK Domestic |
| 2043580 | Instrument Panel Compartment Lamp Bulb Replacement | 9282000 | GMK Overseas |
| 2043630 | Instrument Panel Courtesy Lamp Bulb Replacement | N0610 | GMNA |
| 2043650 | Front Floor Console Extension Flexible Light Tube Replacement | | |
| 2043660 | Front Side Door Courtesy Bulb Replacement | | |
| 2043670 | Instrument Panel Flexible Light Tube Replacement | 5523000 | GMK Domestic |
| 2043680 | Front Side Door Trim Flexible Light Tube Replacement | | |
| 2043690 | Rear License Plate Lamp Bulb Replacement | N0657 | GMNA |
| 2043690 | Rear License Plate Lamp Bulb Replacement | N0657 | Holden Australia |
| 2043690 | Rear License Plate Lamp Bulb Replacement | N065700 | Holden Australia |
| 2043690 | Rear License Plate Lamp Bulb Replacement | N104290 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2043690 | Rear License Plate Lamp Bulb Replacement | N104295 | Holden Australia |
| 2043690 | Rear License Plate Lamp Bulb Replacement | N0657 | Holden New Zealand |
| 2043690 | Rear License Plate Lamp Bulb Replacement | N065700 | Holden New Zealand |
| 2043690 | Rear License Plate Lamp Bulb Replacement | N104290 | Holden New Zealand |
| 2043690 | Rear License Plate Lamp Bulb Replacement | N104295 | Holden New Zealand |
| 2043690 | Rear License Plate Lamp Bulb Replacement | 9180900 | GMK Overseas |
| 2043700 | Rear Side Door Trim Flexible Light Tube Replacement | | |
| 2043710 | Outside Rearview Mirror Turn Signal Lamp Bulb Replacement | | |
| 2043730 | Luminescent Lamp Bulb Replacement - Outside Mirror | N0672 | GMNA |
| 2043730 | Luminescent Lamp Bulb Replacement - Outside Mirror | R005510 | Holden Australia |
| 2043780 | Parking and Turn Signal Lamp Bulb Replacement | N0680 | GMNA |
| 2043780 | Parking and Turn Signal Lamp Bulb Replacement | N0680 | Holden Australia |
| 2043830 | Front Turn Signal Lamp Bulb Replacement | N0682 | GMNA |
| 2043830 | Front Turn Signal Lamp Bulb Replacement | 5540600 | GMK Domestic |
| 2043830 | Front Turn Signal Lamp Bulb Replacement | 5540700 | GMK Domestic |
| 2043830 | Front Turn Signal Lamp Bulb Replacement | N104330 | Holden Australia |
| 2043830 | Front Turn Signal Lamp Bulb Replacement | N104350 | Holden Australia |
| 2043830 | Front Turn Signal Lamp Bulb Replacement | N104350 | Holden New Zealand |
| 2043830 | Front Turn Signal Lamp Bulb Replacement | 9161100 | GMK Overseas |
| 2043830 | Front Turn Signal Lamp Bulb Replacement | 916110A | GMK Overseas |
| 2043830 | Front Turn Signal Lamp Bulb Replacement | 9161110 | GMK Overseas |
| 2043830 | Front Turn Signal Lamp Bulb Replacement | 9162200 | GMK Overseas |
| 2043830 | Front Turn Signal Lamp Bulb Replacement | 9170100 | GMK Overseas |
| 2043830 | Front Turn Signal Lamp Bulb Replacement | 9170200 | GMK Overseas |
| 2043850 | Front Side Turn Signal Lamp Bulb Replacement | N0687 | GMNA |
| 2043850 | Front Side Turn Signal Lamp Bulb Replacement | N152500 | Holden Australia |
| 2043850 | Front Side Turn Signal Lamp Bulb Replacement | 9171400 | GMK Overseas |
| 2043850 | Front Side Turn Signal Lamp Bulb Replacement | 9171500 | GMK Overseas |
| 2043850 | Front Side Turn Signal Lamp Bulb Replacement | 9181200 | GMK Overseas |
| 2043870 | Rear Compartment Courtesy Lamp Bulb Replacement | N0695 | GMNA |
| 2043870 | Rear Compartment Courtesy Lamp Bulb Replacement | 9281310 | GMK Overseas |
| 2043890 | Roof Clearance Lamp Bulb Replacement | N0700 | GMNA |
| 2043890 | Roof Clearance Lamp Bulb Replacement | N0700 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2043940 | Transmission Control Position Indicator Bulb Replacement | N0406 | GMNA |
| 2043940 | Transmission Control Position Indicator Bulb Replacement | N0725 | GMNA |
| 2043940 | Transmission Control Position Indicator Bulb Replacement | N221000 | Holden Australia |
| 2043940 | Transmission Control Position Indicator Bulb Replacement | N221005 | Holden Australia |
| 2043940 | Transmission Control Position Indicator Bulb Replacement | N221000 | Holden New Zealand |
| 2043940 | Transmission Control Position Indicator Bulb Replacement | N221005 | Holden New Zealand |
| 2043960 | Front Side Marker Lamp Bulb Replacement | N0734 | GMNA |
| 2043960 | Front Side Marker Lamp Bulb Replacement | 5621200 | GMK Domestic |
| 2043960 | Front Side Marker Lamp Bulb Replacement | 9162700 | GMK Overseas |
| 2043960 | Front Side Marker Lamp Bulb Replacement | 9162800 | GMK Overseas |
| 2043960 | Front Side Marker Lamp Bulb Replacement | 9182500 | GMK Overseas |
| 2044010 | Rear Side Marker Lamp Bulb Replacement | N0737 | GMNA |
| 2044010 | Rear Side Marker Lamp Bulb Replacement | N0744 | GMNA |
| 2044010 | Rear Side Marker Lamp Bulb Replacement | 9182400 | GMK Overseas |
| 2044060 | Spot Lamp Bulb Replacement | N0748 | GMNA |
| 2044080 | Tail Lamp Bulb Replacement | N0760 | GMNA |
| 2044080 | Tail Lamp Bulb Replacement | 5610800 | GMK Domestic |
| 2044080 | Tail Lamp Bulb Replacement | N104300 | Holden Australia |
| 2044080 | Tail Lamp Bulb Replacement | N104370 | Holden Australia |
| 2044080 | Tail Lamp Bulb Replacement | 9180500 | GMK Overseas |
| 2044080 | Tail Lamp Bulb Replacement | 9180600 | GMK Overseas |
| 2044080 | Tail Lamp Bulb Replacement | 9180700 | GMK Overseas |
| 2044130 | Stop and Tail Lamp Bulb Replacement | N0762 | GMNA |
| 2044130 | Stop and Tail Lamp Bulb Replacement | N104400 | Holden Australia |
| 2044130 | Stop and Tail Lamp Bulb Replacement | N104405 | Holden Australia |
| 2044130 | Stop and Tail Lamp Bulb Replacement | N104500 | Holden Australia |
| 2044130 | Stop and Tail Lamp Bulb Replacement | N104505 | Holden Australia |
| 2044150 | Stop and Turn Signal Lamp Bulb Replacement | N0766 | GMNA |
| 2044170 | High Mount Stop Lamp Bulb Replacement | N0768 | GMNA |
| 2044170 | High Mount Stop Lamp Bulb Replacement | 5611300 | GMK Domestic |
| 2044170 | High Mount Stop Lamp Bulb Replacement | 9181610 | GMK Overseas |
| 2044190 | Emergency Vehicle Rear Lamp Lens and Bulb Replacement | N0769 | GMNA |
| 2044210 | Rear Turn Signal Lamp Bulb Replacement | N0780 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2044210 | Rear Turn Signal Lamp Bulb Replacement | N0807 | GMNA |
| 2044230 | Sunshade Illuminated Mirror Lamp Bulb Replacement | C2036 | GMNA |
| 2044230 | Sunshade Illuminated Mirror Lamp Bulb Replacement | N0820 | GMNA |
| 2044230 | Sunshade Illuminated Mirror Lamp Bulb Replacement | N0821 | GMNA |
| 2044230 | Sunshade Illuminated Mirror Lamp Bulb Replacement | N1310 | GMNA |
| 2044230 | Sunshade Illuminated Mirror Lamp Bulb Replacement | N1311 | GMNA |
| 2044230 | Sunshade Illuminated Mirror Lamp Bulb Replacement | N1620 | GMNA |
| 2044230 | Sunshade Illuminated Mirror Lamp Bulb Replacement | N1621 | GMNA |
| 2044230 | Sunshade Illuminated Mirror Lamp Bulb Replacement | 5321200 | GMK Domestic |
| 2044250 | Front Fog Lamp Bulb Replacement | N0850 | GMNA |
| 2044250 | Front Fog Lamp Bulb Replacement | N104415 | Holden Australia |
| 2044250 | Front Fog Lamp Bulb Replacement | N104415 | Holden New Zealand |
| 2044250 | Front Fog Lamp Bulb Replacement | 9161700 | GMK Overseas |
| 2044250 | Front Fog Lamp Bulb Replacement | 9170700 | GMK Overseas |
| 2044250 | Front Fog Lamp Bulb Replacement | 9170800 | GMK Overseas |
| 2044300 | Rear Fog Lamp Bulb Replacement | N0852 | GMNA |
| 2044300 | Rear Fog Lamp Bulb Replacement | 5322000 | GMK Domestic |
| 2044300 | Rear Fog Lamp Bulb Replacement | N128150 | Holden Australia |
| 2044300 | Rear Fog Lamp Bulb Replacement | 9181310 | GMK Overseas |
| 2044300 | Rear Fog Lamp Bulb Replacement | 9182700 | GMK Overseas |
| 2044320 | Interior Lamp Bulb Socket Replacement | N0900 | GMNA |
| 2044320 | Interior Lamp Bulb Socket Replacement | N0910 | GMNA |
| 2044340 | Exterior Lamp Bulb Socket Replacement | N0912 | GMNA |
| 2044340 | Exterior Lamp Bulb Socket Replacement | N0916 | GMNA |
| 2044340 | Exterior Lamp Bulb Socket Replacement | N0966 | GMNA |
| 2044340 | Exterior Lamp Bulb Socket Replacement | N0967 | GMNA |
| 2044340 | Exterior Lamp Bulb Socket Replacement | N0977 | GMNA |
| 2044340 | Exterior Lamp Bulb Socket Replacement | N0996 | GMNA |
| 2044340 | Exterior Lamp Bulb Socket Replacement | N1395 | GMNA |
| 2044340 | Exterior Lamp Bulb Socket Replacement | N1396 | GMNA |
| 2044340 | Exterior Lamp Bulb Socket Replacement | N0912 | Holden Australia |
| 2044340 | Exterior Lamp Bulb Socket Replacement | N104240 | Holden Australia |
| 2044340 | Exterior Lamp Bulb Socket Replacement | N104360 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2044340 | Exterior Lamp Bulb Socket Replacement | N104450 | Holden Australia |
| 2044340 | Exterior Lamp Bulb Socket Replacement | N104360 | Holden New Zealand |
| 2044340 | Exterior Lamp Bulb Socket Replacement | N104450 | Holden New Zealand |
| 2044360 | LED Circuit Board Replacement | N0913 | GMNA |
| 2044440 | Instrument Panel Flood Lamp Replacement - Left Side | N1436 | GMNA |
| 2044460 | Instrument Panel Flood Lamp Replacement - Right Side | N1437 | GMNA |
| 2044480 | Interior Lamp and Multifunction Switch Replacement | | |
| 2044520 | Luminescent Lamp Replacement - Driver or Passenger Seat | C6608 | GMNA |
| 2044520 | Luminescent Lamp Replacement - Driver or Passenger Seat | N1442 | GMNA |
| 2044540 | Roof Console Courtesy Lamp Replacement | | |
| 2044590 | Tail Lamp Circuit Board Replacement | N1590 | GMNA |
| 2044590 | Tail Lamp Circuit Board Replacement | N1591 | GMNA |
| 2044590 | Tail Lamp Circuit Board Replacement | N1592 | GMNA |
| 2044590 | Tail Lamp Circuit Board Replacement | N5180 | GMNA |
| 2044590 | Tail Lamp Circuit Board Replacement | N217800 | Holden Australia |
| 2044590 | Tail Lamp Circuit Board Replacement | N217800 | Holden New Zealand |
| 2044630 | Tail Lamp Control Module with Bulb Replacement | N1594 | GMNA |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N1596 | GMNA |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N6180 | GMNA |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N6272 | GMNA |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N6288 | GMNA |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N6290 | GMNA |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N9566 | GMNA |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N913986 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N913987 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N913991 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N913996 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N914685 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N914686 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N914687 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N914688 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N914689 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N914691 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N914692 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N914693 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N914694 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N914696 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N914697 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N914698 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N922902 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N932987 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N932990 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N932991 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N932992 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N932996 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N932997 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N944188 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N953186 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N953187 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N953188 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N953191 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N953192 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N953194 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N953195 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N953196 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N964285 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N964286 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N964287 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N964288 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N964289 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N964292 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N964293 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N964294 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N964296 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N964297 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N973386 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N973387 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N973389 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N973392 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N973394 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N973396 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N973397 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N983987 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N983988 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N983996 | Holden Australia |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N453599R | Holden New Zealand |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N618000 | Holden New Zealand |
| 2044650 | Rear License Plate Lamp Wiring Harness Replacement | N629000 | Holden New Zealand |
| 2044670 | Hazard Lamp Flasher Replacement | N1750 | GMNA |
| 2044670 | Hazard Lamp Flasher Replacement | N175000 | Holden Australia |
| 2044670 | Hazard Lamp Flasher Replacement | N1750 | Holden New Zealand |
| 2044690 | Hazard Lamp and Turn Signal Lamp Flasher Replacement | N1755 | GMNA |
| 2044770 | Cargo Lamp Switch Replacement | N2060 | GMNA |
| 2044820 | Dome and Reading Lamp Switch Replacement | N2101 | GMNA |
| 2044820 | Dome and Reading Lamp Switch Replacement | N9592 | GMNA |
| 2044820 | Dome and Reading Lamp Switch Replacement | 9286200 | GMK Overseas |
| 2044840 | Dome Lamp Switch Replacement | N2102 | GMNA |
| 2044840 | Dome Lamp Switch Replacement | 5810600 | GMK Domestic |
| 2044860 | Front Side Door Jamb Switch Replacement | N2174 | GMNA |
| 2044860 | Front Side Door Jamb Switch Replacement | N6204 | GMNA |
| 2044860 | Front Side Door Jamb Switch Replacement | N2174 | Holden Australia |
| 2044860 | Front Side Door Jamb Switch Replacement | N217400 | Holden Australia |
| 2044860 | Front Side Door Jamb Switch Replacement | N217400 | Holden New Zealand |
| 2044910 | Rear Side Door Jamb Switch Replacement | B4510 | GMNA |
| 2044910 | Rear Side Door Jamb Switch Replacement | N2184 | GMNA |
| 2044910 | Rear Side Door Jamb Switch Replacement | N2184 | Holden Australia |
| 2044980 | Rear Fog Lamp Switch Replacement | N2231 | GMNA |
| 2044980 | Rear Fog Lamp Switch Replacement | N105600 | Holden Australia |
| 2045000 | Fog Lamp Switch Replacement | N2232 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2045000 | Fog Lamp Switch Replacement | 5721100 | GMK Domestic |
| 2045000 | Fog Lamp Switch Replacement | 5721200 | GMK Domestic |
| 2045000 | Fog Lamp Switch Replacement | 5721300 | GMK Domestic |
| 2045000 | Fog Lamp Switch Replacement | N761700 | Holden Australia |
| 2045000 | Fog Lamp Switch Replacement | N2244 | Holden New Zealand |
| 2045000 | Fog Lamp Switch Replacement | 9320400 | GMK Overseas |
| 2045020 | Instrument Panel Compartment Lamp Switch Replacement | N2280 | GMNA |
| 2045020 | Instrument Panel Compartment Lamp Switch Replacement | 9282100 | GMK Overseas |
| 2045090 | Headlamp Switch Replacement | N0580 | GMNA |
| 2045090 | Headlamp Switch Replacement | N1980 | GMNA |
| 2045090 | Headlamp Switch Replacement | N2290 | GMNA |
| 2045090 | Headlamp Switch Replacement | N218500 | Holden Australia |
| 2045090 | Headlamp Switch Replacement | N2290 | Holden Australia |
| 2045090 | Headlamp Switch Replacement | N229000 | Holden Australia |
| 2045090 | Headlamp Switch Replacement | N712309 | Holden Australia |
| 2045090 | Headlamp Switch Replacement | N712507 | Holden Australia |
| 2045090 | Headlamp Switch Replacement | N712527 | Holden Australia |
| 2045090 | Headlamp Switch Replacement | N218500 | Holden New Zealand |
| 2045090 | Headlamp Switch Replacement | N2290 | Holden New Zealand |
| 2045090 | Headlamp Switch Replacement | N229000 | Holden New Zealand |
| 2045090 | Headlamp Switch Replacement | 9321500 | GMK Overseas |
| 2045110 | Headlamp, Instrument Panel Lamp Dimmer, and Fog Lamp Switch Replacement | N2291 | GMNA |
| 2045160 | Headlamp Leveling Actuator Replacement | N2301 | GMNA |
| 2045160 | Headlamp Leveling Actuator Replacement | N3400 | GMNA |
| 2045160 | Headlamp Leveling Actuator Replacement | 5712800 | GMK Domestic |
| 2045160 | Headlamp Leveling Actuator Replacement | 6420000 | GMK Domestic |
| 2045160 | Headlamp Leveling Actuator Replacement | N238000 | Holden Australia |
| 2045160 | Headlamp Leveling Actuator Replacement | N238100 | Holden Australia |
| 2045160 | Headlamp Leveling Actuator Replacement | N238200 | Holden Australia |
| 2045160 | Headlamp Leveling Actuator Replacement | N238100 | Holden New Zealand |
| 2045160 | Headlamp Leveling Actuator Replacement | 9164400 | GMK Overseas |
| 2045180 | Headlamp Leveling Control Module Replacement | N506410 | Holden Australia |
| 2045180 | Headlamp Leveling Control Module Replacement | N506410 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2045200 | Headlamp Leveling Actuator Switch Replacement | | |
| 2045250 | Interior Lamp Switch Replacement | N2314 | GMNA |
| 2045250 | Interior Lamp Switch Replacement | N2831 | GMNA |
| 2045250 | Interior Lamp Switch Replacement | N231500 | Holden Australia |
| 2045300 | Dimmer Switch Replacement | N2318 | GMNA |
| 2045300 | Dimmer Switch Replacement | 6230200 | GMK Domestic |
| 2045300 | Dimmer Switch Replacement | 9322900 | GMK Overseas |
| 2045310 | Map Lamp Switch Replacement | | |
| 2045320 | Reading Lamp Switch Pushbutton Replacement | N2350 | GMNA |
| 2045340 | Rear Compartment Courtesy Lamp Switch Replacement | | |
| 2045350 | Instrument Panel Multifunction Switch Replacement | | |
| 2045420 | Stop Lamp Switch Replacement | H9722 | GMNA |
| 2045420 | Stop Lamp Switch Replacement | K5322 | GMNA |
| 2045420 | Stop Lamp Switch Replacement | N2440 | GMNA |
| 2045420 | Stop Lamp Switch Replacement | N2440 | Holden Australia |
| 2045420 | Stop Lamp Switch Replacement | N2440 | Holden New Zealand |
| 2045420 | Stop Lamp Switch Replacement | N244000 | Holden New Zealand |
| 2045420 | Stop Lamp Switch Replacement | 4450420 | GMK Overseas |
| 2045422 | Stop Lamp Switch Adjustment | N2700 | GMNA |
| 2045440 | Hazard Warning Switch Replacement | N1987 | GMNA |
| 2045440 | Hazard Warning Switch Replacement | N2540 | GMNA |
| 2045440 | Hazard Warning Switch Replacement | 5810800 | GMK Domestic |
| 2045440 | Hazard Warning Switch Replacement | N000330 | Holden Australia |
| 2045440 | Hazard Warning Switch Replacement | N220600 | Holden Australia |
| 2045440 | Hazard Warning Switch Replacement | N224700 | Holden Australia |
| 2045440 | Hazard Warning Switch Replacement | N732122 | Holden Australia |
| 2045440 | Hazard Warning Switch Replacement | N732124 | Holden Australia |
| 2045440 | Hazard Warning Switch Replacement | N732125 | Holden Australia |
| 2045440 | Hazard Warning Switch Replacement | N732126 | Holden Australia |
| 2045440 | Hazard Warning Switch Replacement | N732127 | Holden Australia |
| 2045440 | Hazard Warning Switch Replacement | N220600 | Holden New Zealand |
| 2045440 | Hazard Warning Switch Replacement | N2247 | Holden New Zealand |
| 2045440 | Hazard Warning Switch Replacement | N224700 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2045440 | Hazard Warning Switch Replacement | N2451 | Holden New Zealand |
| 2045440 | Hazard Warning Switch Replacement | N2710 | Holden New Zealand |
| 2045440 | Hazard Warning Switch Replacement | 9320300 | GMK Overseas |
| 2045460 | Hazard Warning and Accessory Switch Replacement | J000926 | Holden Australia |
| 2045680 | Headlamp Control Module Replacement | N4828 | GMNA |
| 2045680 | Headlamp Control Module Replacement | N4848 | GMNA |
| 2045680 | Headlamp Control Module Replacement | N9650 | GMNA |
| 2045680 | Headlamp Control Module Replacement | N9657 | GMNA |
| 2045680 | Headlamp Control Module Replacement | 5711000 | GMK Domestic |
| 2045680 | Headlamp Control Module Replacement | N506400 | Holden Australia |
| 2045680 | Headlamp Control Module Replacement | 9293800 | GMK Overseas |
| 2045700 | Trailer Lamp Control Module Replacement | N4894 | GMNA |
| 2045780 | Headlamp Automatic Control Ambient Light Sensor Replacement | R4229 | GMNA |
| 2045780 | Headlamp Automatic Control Ambient Light Sensor Replacement | 6410900 | GMK Domestic |
| 2045780 | Headlamp Automatic Control Ambient Light Sensor Replacement | 9164000 | GMK Overseas |
| 2050010 | Outside Rearview Mirror Bracket Cover Replacement | 8646400 | GMK Domestic |
| 2050010 | Outside Rearview Mirror Bracket Cover Replacement | 8648300 | GMK Domestic |
| 2050010 | Outside Rearview Mirror Bracket Cover Replacement | H0615 | Holden Australia |
| 2050030 | Outside Rearview Mirror Applique Replacement | B4146 | GMNA |
| 2050050 | Outside Rearview Mirror Housing Cover Replacement | B4147 | GMNA |
| 2050050 | Outside Rearview Mirror Housing Cover Replacement | R3325 | GMNA |
| 2050050 | Outside Rearview Mirror Housing Cover Replacement | 8645200 | GMK Domestic |
| 2050050 | Outside Rearview Mirror Housing Cover Replacement | 8645300 | GMK Domestic |
| 2050050 | Outside Rearview Mirror Housing Cover Replacement | 8645900 | GMK Domestic |
| 2050050 | Outside Rearview Mirror Housing Cover Replacement | 9467800 | GMK Overseas |
| 2050070 | Outside Rearview Mirror Housing Bezel Replacement | B4148 | GMNA |
| 2050070 | Outside Rearview Mirror Housing Bezel Replacement | C340000 | Holden Australia |
| 2050070 | Outside Rearview Mirror Housing Bezel Replacement | C340100 | Holden Australia |
| 2050070 | Outside Rearview Mirror Housing Bezel Replacement | R3391 | Holden New Zealand |
| 2050090 | Outside Rearview Mirror Remote Control Knob Replacement | | |
| 2050110 | Outside Rearview Mirror Glass Replacement | B4150 | GMNA |
| 2050110 | Outside Rearview Mirror Glass Replacement | R3390 | GMNA |
| 2050110 | Outside Rearview Mirror Glass Replacement | R3391 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2050110 | Outside Rearview Mirror Glass Replacement | 8644600 | GMK Domestic |
| 2050110 | Outside Rearview Mirror Glass Replacement | R006120 | Holden Australia |
| 2050110 | Outside Rearview Mirror Glass Replacement | R006220 | Holden Australia |
| 2050110 | Outside Rearview Mirror Glass Replacement | R339000 | Holden Australia |
| 2050110 | Outside Rearview Mirror Glass Replacement | R339100 | Holden Australia |
| 2050110 | Outside Rearview Mirror Glass Replacement | R339500 | Holden Australia |
| 2050110 | Outside Rearview Mirror Glass Replacement | R006120 | Holden New Zealand |
| 2050110 | Outside Rearview Mirror Glass Replacement | R006220 | Holden New Zealand |
| 2050110 | Outside Rearview Mirror Glass Replacement | R3390 | Holden New Zealand |
| 2050110 | Outside Rearview Mirror Glass Replacement | R339000 | Holden New Zealand |
| 2050110 | Outside Rearview Mirror Glass Replacement | R339100 | Holden New Zealand |
| 2050110 | Outside Rearview Mirror Glass Replacement | 9462600 | GMK Overseas |
| 2050110 | Outside Rearview Mirror Glass Replacement | 9462700 | GMK Overseas |
| 2050160 | Outside Rearview Mirror Housing Replacement | B4152 | GMNA |
| 2050160 | Outside Rearview Mirror Housing Replacement | 9466600 | GMK Overseas |
| 2050160 | Outside Rearview Mirror Housing Replacement | 9466700 | GMK Overseas |
| 2050200 | Outside Rearview Mirror Opening Applique Replacement | B4154 | GMNA |
| 2050200 | Outside Rearview Mirror Opening Applique Replacement | B4155 | Holden Australia |
| 2050220 | Outside Rearview Mirror Replacement | B4155 | GMNA |
| 2050220 | Outside Rearview Mirror Replacement | B6804 | GMNA |
| 2050220 | Outside Rearview Mirror Replacement | B9782 | GMNA |
| 2050220 | Outside Rearview Mirror Replacement | B9961 | GMNA |
| 2050220 | Outside Rearview Mirror Replacement | 8644700 | GMK Domestic |
| 2050220 | Outside Rearview Mirror Replacement | 8644800 | GMK Domestic |
| 2050220 | Outside Rearview Mirror Replacement | 8645000 | GMK Domestic |
| 2050220 | Outside Rearview Mirror Replacement | 8645100 | GMK Domestic |
| 2050220 | Outside Rearview Mirror Replacement | B4155 | Holden New Zealand |
| 2050220 | Outside Rearview Mirror Replacement | C000716 | Holden New Zealand |
| 2050220 | Outside Rearview Mirror Replacement | 1584800 | GMK Overseas |
| 2050220 | Outside Rearview Mirror Replacement | 9284600 | GMK Overseas |
| 2050220 | Outside Rearview Mirror Replacement | 9462300 | GMK Overseas |
| 2050220 | Outside Rearview Mirror Replacement | 9462400 | GMK Overseas |
| 2050220 | Outside Rearview Mirror Replacement | 9462500 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2050270 | Outside Rearview Mirror Seal Replacement | B4157 | GMNA |
| 2050270 | Outside Rearview Mirror Seal Replacement | B9904 | GMNA |
| 2050270 | Outside Rearview Mirror Seal Replacement | B9955 | GMNA |
| 2050270 | Outside Rearview Mirror Seal Replacement | C342000 | Holden Australia |
| 2050270 | Outside Rearview Mirror Seal Replacement | C342100 | Holden Australia |
| 2050270 | Outside Rearview Mirror Seal Replacement | C345000 | Holden Australia |
| 2050270 | Outside Rearview Mirror Seal Replacement | C345100 | Holden Australia |
| 2050290 | Outside Rearview Mirror Inner Actuator Replacement | B4159 | GMNA |
| 2050310 | Outside Rearview Mirror Motor Replacement | B4160 | GMNA |
| 2050310 | Outside Rearview Mirror Motor Replacement | 8648900 | GMK Domestic |
| 2050310 | Outside Rearview Mirror Motor Replacement | N006130 | Holden Australia |
| 2050310 | Outside Rearview Mirror Motor Replacement | N006230 | Holden Australia |
| 2050310 | Outside Rearview Mirror Motor Replacement | N411310 | Holden Australia |
| 2050310 | Outside Rearview Mirror Motor Replacement | N411320 | Holden Australia |
| 2050310 | Outside Rearview Mirror Motor Replacement | 9466800 | GMK Overseas |
| 2050310 | Outside Rearview Mirror Motor Replacement | 9466900 | GMK Overseas |
| 2050320 | Outside Rearview Mirror Gasket Replacement | | |
| 2050330 | Outside Rearview Mirror Housing Lower Cover Replacement | | |
| 2050340 | Outside Rearview Mirror Housing Upper Cover Replacement | B4161 | GMNA |
| 2050360 | Inside Rearview Mirror Replacement | C0040 | GMNA |
| 2050360 | Inside Rearview Mirror Replacement | 5524700 | GMK Domestic |
| 2050360 | Inside Rearview Mirror Replacement | C004000 | Holden Australia |
| 2050360 | Inside Rearview Mirror Replacement | C315500 | Holden Australia |
| 2050360 | Inside Rearview Mirror Replacement | C0040 | Holden New Zealand |
| 2050360 | Inside Rearview Mirror Replacement | C004000 | Holden New Zealand |
| 2050360 | Inside Rearview Mirror Replacement | 9720600 | GMK Overseas |
| 2050370 | Inside Rearview Mirror Wiring Harness Lower Cover Replacement | C2015 | GMNA |
| 2050370 | Inside Rearview Mirror Wiring Harness Lower Cover Replacement | N964886 | Holden Australia |
| 2050370 | Inside Rearview Mirror Wiring Harness Lower Cover Replacement | N964887 | Holden Australia |
| 2050370 | Inside Rearview Mirror Wiring Harness Lower Cover Replacement | N964889 | Holden Australia |
| 2050370 | Inside Rearview Mirror Wiring Harness Lower Cover Replacement | N964890 | Holden Australia |
| 2050370 | Inside Rearview Mirror Wiring Harness Lower Cover Replacement | N964891 | Holden Australia |
| 2050410 | Inside Rearview Mirror Bracket Replacement | C0050 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2050410 | Inside Rearview Mirror Bracket Replacement | C0050 | Holden Australia |
| 2050410 | Inside Rearview Mirror Bracket Replacement | C005000 | Holden Australia |
| 2050410 | Inside Rearview Mirror Bracket Replacement | C315510 | Holden Australia |
| 2050410 | Inside Rearview Mirror Bracket Replacement | C005000 | Holden New Zealand |
| 2050410 | Inside Rearview Mirror Bracket Replacement | C315510 | Holden New Zealand |
| 2050410 | Inside Rearview Mirror Bracket Replacement | 9465500 | GMK Overseas |
| 2050420 | Inside Rearview Mirror Mount Plate Cover Replacement | | |
| 2050430 | Rear Seat Roof Illuminated Mirror Replacement | | |
| 2050470 | Outside Rearview Mirror Remote Control Switch Replacement | N2157 | GMNA |
| 2050470 | Outside Rearview Mirror Remote Control Switch Replacement | R1910 | GMNA |
| 2050470 | Outside Rearview Mirror Remote Control Switch Replacement | R3310 | GMNA |
| 2050470 | Outside Rearview Mirror Remote Control Switch Replacement | R3311 | GMNA |
| 2050470 | Outside Rearview Mirror Remote Control Switch Replacement | R3314 | GMNA |
| 2050470 | Outside Rearview Mirror Remote Control Switch Replacement | R3318 | GMNA |
| 2050470 | Outside Rearview Mirror Remote Control Switch Replacement | 8646100 | GMK Domestic |
| 2050470 | Outside Rearview Mirror Remote Control Switch Replacement | N2157 | Holden Australia |
| 2050470 | Outside Rearview Mirror Remote Control Switch Replacement | N240200 | Holden Australia |
| 2050470 | Outside Rearview Mirror Remote Control Switch Replacement | N914118 | Holden Australia |
| 2050470 | Outside Rearview Mirror Remote Control Switch Replacement | R331800 | Holden Australia |
| 2050470 | Outside Rearview Mirror Remote Control Switch Replacement | N2040200 | Holden New Zealand |
| 2050470 | Outside Rearview Mirror Remote Control Switch Replacement | R006300 | Holden New Zealand |
| 2050490 | Outside Rearview Mirror Folding Switch Replacement | N2158 | GMNA |
| 2050490 | Outside Rearview Mirror Folding Switch Replacement | 5811000 | GMK Domestic |
| 2050490 | Outside Rearview Mirror Folding Switch Replacement | 9320800 | GMK Overseas |
| 2050540 | Outside Rearview Mirror Folding Control Module Replacement | B9798 | GMNA |
| 2050540 | Outside Rearview Mirror Folding Control Module Replacement | N4827 | GMNA |
| 2050540 | Outside Rearview Mirror Folding Control Module Replacement | R3396 | GMNA |
| 2050560 | Outside Rearview Mirror Memory Module Replacement | N4855 | GMNA |
| 2060010 | Rear Compartment Lid Release Switch Replacement - Rear Compartment Lid Hinge | B3746 | GMNA |
| 2060030 | Rear Compartment Lid Release Switch Replacement - Front Hinge Side | B3747 | GMNA |
| 2060050 | Rear Compartment Lid Release Switch Replacement - Hinge Bracket | B3748 | GMNA |
| 2060060 | Front Side Door Outside Handle Insert Replacement | B4119 | GMNA |
| 2060070 | Front Side Door Outside Handle Replacement | B4120 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2060070 | Front Side Door Outside Handle Replacement | B4121 | GMNA |
| 2060070 | Front Side Door Outside Handle Replacement | B4141 | GMNA |
| 2060070 | Front Side Door Outside Handle Replacement | 8531600 | GMK Domestic |
| 2060070 | Front Side Door Outside Handle Replacement | B4120 | Holden Australia |
| 2060070 | Front Side Door Outside Handle Replacement | B412000 | Holden Australia |
| 2060070 | Front Side Door Outside Handle Replacement | B4121 | Holden Australia |
| 2060070 | Front Side Door Outside Handle Replacement | B412100 | Holden Australia |
| 2060070 | Front Side Door Outside Handle Replacement | C621100 | Holden Australia |
| 2060070 | Front Side Door Outside Handle Replacement | C621200 | Holden Australia |
| 2060070 | Front Side Door Outside Handle Replacement | C621300 | Holden Australia |
| 2060070 | Front Side Door Outside Handle Replacement | C621400 | Holden Australia |
| 2060070 | Front Side Door Outside Handle Replacement | C641220 | Holden Australia |
| 2060070 | Front Side Door Outside Handle Replacement | B4120 | Holden New Zealand |
| 2060070 | Front Side Door Outside Handle Replacement | B412000 | Holden New Zealand |
| 2060070 | Front Side Door Outside Handle Replacement | B4121 | Holden New Zealand |
| 2060070 | Front Side Door Outside Handle Replacement | B412100 | Holden New Zealand |
| 2060070 | Front Side Door Outside Handle Replacement | C621100 | Holden New Zealand |
| 2060070 | Front Side Door Outside Handle Replacement | C621200 | Holden New Zealand |
| 2060070 | Front Side Door Outside Handle Replacement | C621200A1 | Holden New Zealand |
| 2060070 | Front Side Door Outside Handle Replacement | C621300 | Holden New Zealand |
| 2060070 | Front Side Door Outside Handle Replacement | C621400 | Holden New Zealand |
| 2060070 | Front Side Door Outside Handle Replacement | C641220 | Holden New Zealand |
| 2060070 | Front Side Door Outside Handle Replacement | 9612100 | GMK Overseas |
| 2060070 | Front Side Door Outside Handle Replacement | 9612200 | GMK Overseas |
| 2060070 | Front Side Door Outside Handle Replacement | 9612300 | GMK Overseas |
| 2060120 | Front Side Door Outside Handle Bracket Replacement | B4122 | GMNA |
| 2060120 | Front Side Door Outside Handle Bracket Replacement | B4123 | GMNA |
| 2060200 | Front Side Door Outside Handle Housing Replacement | 8617500 | GMK Domestic |
| 2060200 | Front Side Door Outside Handle Housing Replacement | 9613700 | GMK Overseas |
| 2060200 | Front Side Door Outside Handle Housing Replacement | 9613800 | GMK Overseas |
| 2060220 | Front Side Door Lock Cylinder Replacement | B4170 | GMNA |
| 2060220 | Front Side Door Lock Cylinder Replacement | B4171 | GMNA |
| 2060220 | Front Side Door Lock Cylinder Replacement | B4180 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2060220 | Front Side Door Lock Cylinder Replacement | B4181 | GMNA |
| 2060220 | Front Side Door Lock Cylinder Replacement | B4182 | GMNA |
| 2060220 | Front Side Door Lock Cylinder Replacement | B4190 | GMNA |
| 2060220 | Front Side Door Lock Cylinder Replacement | 8521400 | GMK Domestic |
| 2060220 | Front Side Door Lock Cylinder Replacement | B418000 | Holden Australia |
| 2060220 | Front Side Door Lock Cylinder Replacement | B418100 | Holden Australia |
| 2060220 | Front Side Door Lock Cylinder Replacement | C622000 | Holden Australia |
| 2060220 | Front Side Door Lock Cylinder Replacement | C622100 | Holden Australia |
| 2060220 | Front Side Door Lock Cylinder Replacement | C623100 | Holden Australia |
| 2060220 | Front Side Door Lock Cylinder Replacement | B418000 | Holden New Zealand |
| 2060220 | Front Side Door Lock Cylinder Replacement | B418100 | Holden New Zealand |
| 2060220 | Front Side Door Lock Cylinder Replacement | C622000 | Holden New Zealand |
| 2060220 | Front Side Door Lock Cylinder Replacement | C622100 | Holden New Zealand |
| 2060220 | Front Side Door Lock Cylinder Replacement | C623100 | Holden New Zealand |
| 2060220 | Front Side Door Lock Cylinder Replacement | 9680100 | GMK Overseas |
| 2060220 | Front Side Door Lock Cylinder Replacement | 9680200 | GMK Overseas |
| 2060220 | Front Side Door Lock Cylinder Replacement | 9680300 | GMK Overseas |
| 2060300 | Front Side Door Lock Cover Replacement | B4183 | GMNA |
| 2060300 | Front Side Door Lock Cover Replacement | B4184 | GMNA |
| 2060300 | Front Side Door Lock Cover Replacement | B4185 | GMNA |
| 2060300 | Front Side Door Lock Cover Replacement | B4186 | GMNA |
| 2060300 | Front Side Door Lock Cover Replacement | C9883 | GMNA |
| 2060300 | Front Side Door Lock Cover Replacement | 8617200 | GMK Domestic |
| 2060320 | Front Side Door Lock Cylinder Bezel Replacement | | |
| 2060360 | Front Side Door Lock Opening Cover Replacement | | |
| 2060380 | Door Latch Release Switch Outside Bezel Replacement | B4187 | GMNA |
| 2060520 | Front Side Door Lock Replacement | B9929 | GMNA |
| 2060520 | Front Side Door Lock Replacement | B9931 | GMNA |
| 2060520 | Front Side Door Lock Replacement | B9946 | GMNA |
| 2060570 | Front Side Door Locking System Module Replacement | B4270 | GMNA |
| 2060570 | Front Side Door Locking System Module Replacement | N764100 | Holden Australia |
| 2060620 | Front Side Door Inside Handle Replacement | B4280 | GMNA |
| 2060620 | Front Side Door Inside Handle Replacement | B4281 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2060620 | Front Side Door Inside Handle Replacement | 8531700 | GMK Domestic |
| 2060620 | Front Side Door Inside Handle Replacement | 8532000 | GMK Domestic |
| 2060620 | Front Side Door Inside Handle Replacement | B428000 | Holden Australia |
| 2060620 | Front Side Door Inside Handle Replacement | B428100 | Holden Australia |
| 2060620 | Front Side Door Inside Handle Replacement | B4280 | Holden New Zealand |
| 2060620 | Front Side Door Inside Handle Replacement | B428000 | Holden New Zealand |
| 2060620 | Front Side Door Inside Handle Replacement | B4281 | Holden New Zealand |
| 2060620 | Front Side Door Inside Handle Replacement | B428100 | Holden New Zealand |
| 2060620 | Front Side Door Inside Handle Replacement | 9350500 | GMK Overseas |
| 2060620 | Front Side Door Inside Handle Replacement | 9350600 | GMK Overseas |
| 2060620 | Front Side Door Inside Handle Replacement | 9350700 | GMK Overseas |
| 2060730 | Front Side Door Latch Replacement | B4260 | GMNA |
| 2060730 | Front Side Door Latch Replacement | B4261 | GMNA |
| 2060730 | Front Side Door Latch Replacement | B4310 | GMNA |
| 2060730 | Front Side Door Latch Replacement | B4311 | GMNA |
| 2060730 | Front Side Door Latch Replacement | 8530100 | GMK Domestic |
| 2060730 | Front Side Door Latch Replacement | 8530102 | GMK Domestic |
| 2060730 | Front Side Door Latch Replacement | B4260 | Holden Australia |
| 2060730 | Front Side Door Latch Replacement | B426000 | Holden Australia |
| 2060730 | Front Side Door Latch Replacement | B426100 | Holden Australia |
| 2060730 | Front Side Door Latch Replacement | B4260 | Holden New Zealand |
| 2060730 | Front Side Door Latch Replacement | B426000 | Holden New Zealand |
| 2060730 | Front Side Door Latch Replacement | B4261 | Holden New Zealand |
| 2060730 | Front Side Door Latch Replacement | B426100 | Holden New Zealand |
| 2060730 | Front Side Door Latch Replacement | B4379 | Holden New Zealand |
| 2060730 | Front Side Door Latch Replacement | 9612800 | GMK Overseas |
| 2060730 | Front Side Door Latch Replacement | 9612900 | GMK Overseas |
| 2060730 | Front Side Door Latch Replacement | 9613000 | GMK Overseas |
| 2060780 | Front Side Door Locking Rod Replacement | B4330 | GMNA |
| 2060780 | Front Side Door Locking Rod Replacement | B4331 | GMNA |
| 2060780 | Front Side Door Locking Rod Replacement | B4360 | GMNA |
| 2060780 | Front Side Door Locking Rod Replacement | B4361 | GMNA |
| 2060780 | Front Side Door Locking Rod Replacement | 8530120 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2060780 | Front Side Door Locking Rod Replacement | 8530200 | GMK Domestic |
| 2060780 | Front Side Door Locking Rod Replacement | 8616700 | GMK Domestic |
| 2060780 | Front Side Door Locking Rod Replacement | 8616800 | GMK Domestic |
| 2060780 | Front Side Door Locking Rod Replacement | C622300 | Holden Australia |
| 2060780 | Front Side Door Locking Rod Replacement | C622330 | Holden Australia |
| 2060780 | Front Side Door Locking Rod Replacement | C622300 | Holden New Zealand |
| 2060780 | Front Side Door Locking Rod Replacement | C622330 | Holden New Zealand |
| 2060780 | Front Side Door Locking Rod Replacement | C641200 | Holden New Zealand |
| 2060780 | Front Side Door Locking Rod Replacement | 9614300 | GMK Overseas |
| 2061010 | Front Side Door Inside Handle Cable Replacement | 8532600 | GMK Domestic |
| 2061010 | Front Side Door Inside Handle Cable Replacement | 8616900 | GMK Domestic |
| 2061010 | Front Side Door Inside Handle Cable Replacement | 8617100 | GMK Domestic |
| 2061010 | Front Side Door Inside Handle Cable Replacement | 9614900 | GMK Overseas |
| 2061010 | Front Side Door Inside Handle Cable Replacement | 9615000 | GMK Overseas |
| 2061020 | Front Side Door Outside Handle Cable Replacement | | |
| 2061110 | Front Side Door Lock Cylinder Rod Replacement | B4364 | GMNA |
| 2061110 | Front Side Door Lock Cylinder Rod Replacement | B4365 | GMNA |
| 2061110 | Front Side Door Lock Cylinder Rod Replacement | B4366 | GMNA |
| 2061110 | Front Side Door Lock Cylinder Rod Replacement | B4367 | GMNA |
| 2061110 | Front Side Door Lock Cylinder Rod Replacement | B4368 | GMNA |
| 2061110 | Front Side Door Lock Cylinder Rod Replacement | B4369 | GMNA |
| 2061110 | Front Side Door Lock Cylinder Rod Replacement | C622350 | Holden Australia |
| 2061110 | Front Side Door Lock Cylinder Rod Replacement | C622350 | Holden New Zealand |
| 2061110 | Front Side Door Lock Cylinder Rod Replacement | 9614400 | GMK Overseas |
| 2061110 | Front Side Door Lock Cylinder Rod Replacement | 9614500 | GMK Overseas |
| 2061160 | Front Side Door Outside Handle Rod Replacement | B4268 | GMNA |
| 2061160 | Front Side Door Outside Handle Rod Replacement | B4269 | GMNA |
| 2061160 | Front Side Door Outside Handle Rod Replacement | 8530300 | GMK Domestic |
| 2061160 | Front Side Door Outside Handle Rod Replacement | 8532300 | GMK Domestic |
| 2061160 | Front Side Door Outside Handle Rod Replacement | C622500 | Holden Australia |
| 2061160 | Front Side Door Outside Handle Rod Replacement | C622600 | Holden Australia |
| 2061160 | Front Side Door Outside Handle Rod Replacement | C622500 | Holden New Zealand |
| 2061160 | Front Side Door Outside Handle Rod Replacement | C622600 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2061160 | Front Side Door Outside Handle Rod Replacement | 9614700 | GMK Overseas |
| 2061160 | Front Side Door Outside Handle Rod Replacement | 9614800 | GMK Overseas |
| 2061162 | Front Side Door Outside Handle Rod Adjustment | B4363 | GMNA |
| 2061210 | Front Side Door Inside Handle Rod Replacement | 8621100 | GMK Domestic |
| 2061210 | Front Side Door Inside Handle Rod Replacement | 8621200 | GMK Domestic |
| 2061210 | Front Side Door Inside Handle Rod Replacement | 9613100 | GMK Overseas |
| 2061210 | Front Side Door Inside Handle Rod Replacement | 9613200 | GMK Overseas |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B3366 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B3367 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B4240 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B4241 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B4256 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B4265 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B4266 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B4379 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B4640 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B4641 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B4642 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B4643 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B4644 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B4645 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B4665 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B4666 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | C3412 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | C9722 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | N3214 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | N3215 | GMNA |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | 8531500 | GMK Domestic |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B424000 | Holden Australia |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B424100 | Holden Australia |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B464000 | Holden Australia |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B464100 | Holden Australia |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | C000529 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | C623000 | Holden Australia |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | C624100 | Holden Australia |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | C624200 | Holden Australia |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | C643100 | Holden Australia |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | C643200 | Holden Australia |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | N242100 | Holden Australia |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | N242200 | Holden Australia |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | N331400 | Holden Australia |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | N331500 | Holden Australia |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B4240 | Holden New Zealand |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B424000 | Holden New Zealand |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | B424100 | Holden New Zealand |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | C000529 | Holden New Zealand |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | C623000 | Holden New Zealand |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | C624100 | Holden New Zealand |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | C624200 | Holden New Zealand |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | C643100 | Holden New Zealand |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | C643200 | Holden New Zealand |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | N242100 | Holden New Zealand |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | N242200 | Holden New Zealand |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | N3214 | Holden New Zealand |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | N3215 | Holden New Zealand |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | N331400 | Holden New Zealand |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | 9612500 | GMK Overseas |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | 9612600 | GMK Overseas |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | 9612700 | GMK Overseas |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | 9632100 | GMK Overseas |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | 9632200 | GMK Overseas |
| 2061260 | Front or Rear Side Door Latch Striker or Lock Striker Replacement | 9632300 | GMK Overseas |
| 2061370 | Rear Side Door Outside Handle Replacement | B4520 | GMNA |
| 2061370 | Rear Side Door Outside Handle Replacement | B4521 | GMNA |
| 2061370 | Rear Side Door Outside Handle Replacement | 8620700 | GMK Domestic |
| 2061370 | Rear Side Door Outside Handle Replacement | B4520 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2061370 | Rear Side Door Outside Handle Replacement | B452000 | Holden Australia |
| 2061370 | Rear Side Door Outside Handle Replacement | B4521 | Holden Australia |
| 2061370 | Rear Side Door Outside Handle Replacement | B452100 | Holden Australia |
| 2061370 | Rear Side Door Outside Handle Replacement | C640100 | Holden Australia |
| 2061370 | Rear Side Door Outside Handle Replacement | C640200 | Holden Australia |
| 2061370 | Rear Side Door Outside Handle Replacement | B452000 | Holden New Zealand |
| 2061370 | Rear Side Door Outside Handle Replacement | B452100 | Holden New Zealand |
| 2061370 | Rear Side Door Outside Handle Replacement | 9631800 | GMK Overseas |
| 2061370 | Rear Side Door Outside Handle Replacement | 9631900 | GMK Overseas |
| 2061370 | Rear Side Door Outside Handle Replacement | 9632000 | GMK Overseas |
| 2061380 | Front or Rear Side Door Inside Handle Lever Replacement | | |
| 2061420 | Rear Side Door Outside Handle Bracket Replacement | 9635000 | GMK Overseas |
| 2061430 | Rear Side Door Outside Handle Insert Replacement | | |
| 2061500 | Rear Side Door Outside Handle Housing Replacement | 8623400 | GMK Domestic |
| 2061500 | Rear Side Door Outside Handle Housing Replacement | 9633500 | GMK Overseas |
| 2061570 | Rear Side Door Lower Latch Replacement | | |
| 2061650 | Rear Side Door Rear Lock Replacement | B4659 | GMNA |
| 2061670 | Rear Side Door Lock Replacement | B6803 | GMNA |
| 2061670 | Rear Side Door Lock Replacement | 8618900 | GMK Domestic |
| 2061670 | Rear Side Door Lock Replacement | C641000 | Holden Australia |
| 2061670 | Rear Side Door Lock Replacement | C642000 | Holden Australia |
| 2061670 | Rear Side Door Lock Replacement | 9632400 | GMK Overseas |
| 2061670 | Rear Side Door Lock Replacement | 9632500 | GMK Overseas |
| 2061670 | Rear Side Door Lock Replacement | 9632600 | GMK Overseas |
| 2061720 | Rear Side Door Latch Replacement | B4660 | GMNA |
| 2061720 | Rear Side Door Latch Replacement | B4661 | GMNA |
| 2061720 | Rear Side Door Latch Replacement | B4662 | GMNA |
| 2061720 | Rear Side Door Latch Replacement | B4660 | Holden Australia |
| 2061720 | Rear Side Door Latch Replacement | B466000 | Holden Australia |
| 2061720 | Rear Side Door Latch Replacement | B4661 | Holden Australia |
| 2061720 | Rear Side Door Latch Replacement | B466100 | Holden Australia |
| 2061720 | Rear Side Door Latch Replacement | B4660 | Holden New Zealand |
| 2061720 | Rear Side Door Latch Replacement | B466000 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2061720 | Rear Side Door Latch Replacement | B466100 | Holden New Zealand |
| 2061740 | Rear Side Door Lock Cylinder Opening Cover Replacement | B4663 | GMNA |
| 2061760 | Rear Side Door Outside Handle End Cap Replacement | 8623300 | GMK Domestic |
| 2061840 | Rear Side Door Inside Handle Replacement | B4359 | GMNA |
| 2061840 | Rear Side Door Inside Handle Replacement | B4517 | GMNA |
| 2061840 | Rear Side Door Inside Handle Replacement | B4518 | GMNA |
| 2061840 | Rear Side Door Inside Handle Replacement | B4680 | GMNA |
| 2061840 | Rear Side Door Inside Handle Replacement | B4727 | GMNA |
| 2061840 | Rear Side Door Inside Handle Replacement | B6150 | GMNA |
| 2061840 | Rear Side Door Inside Handle Replacement | B6800 | GMNA |
| 2061840 | Rear Side Door Inside Handle Replacement | C2222 | GMNA |
| 2061840 | Rear Side Door Inside Handle Replacement | C3337 | GMNA |
| 2061840 | Rear Side Door Inside Handle Replacement | C3482 | GMNA |
| 2061840 | Rear Side Door Inside Handle Replacement | N9638 | GMNA |
| 2061840 | Rear Side Door Inside Handle Replacement | T5285 | GMNA |
| 2061840 | Rear Side Door Inside Handle Replacement | 8620900 | GMK Domestic |
| 2061840 | Rear Side Door Inside Handle Replacement | 8628700 | GMK Domestic |
| 2061840 | Rear Side Door Inside Handle Replacement | C000634 | Holden Australia |
| 2061840 | Rear Side Door Inside Handle Replacement | C000637 | Holden Australia |
| 2061840 | Rear Side Door Inside Handle Replacement | C000640 | Holden Australia |
| 2061840 | Rear Side Door Inside Handle Replacement | C000634 | Holden New Zealand |
| 2061840 | Rear Side Door Inside Handle Replacement | C000637 | Holden New Zealand |
| 2061840 | Rear Side Door Inside Handle Replacement | C000640 | Holden New Zealand |
| 2061840 | Rear Side Door Inside Handle Replacement | 9360700 | GMK Overseas |
| 2061840 | Rear Side Door Inside Handle Replacement | 9360800 | GMK Overseas |
| 2061840 | Rear Side Door Inside Handle Replacement | 9360900 | GMK Overseas |
| 2061850 | Rear Side Door Outside Handle Cable Replacement | | |
| 2062070 | Rear Side Door Locking Rod Bellcrank Replacement | B4725 | GMNA |
| 2062070 | Rear Side Door Locking Rod Bellcrank Replacement | 8629000 | GMK Domestic |
| 2062120 | Rear Side Door Inside Handle Cable Replacement | 9633600 | GMK Overseas |
| 2062120 | Rear Side Door Inside Handle Cable Replacement | 9633700 | GMK Overseas |
| 2062120 | Rear Side Door Inside Handle Cable Replacement | 9634400 | GMK Overseas |
| 2062160 | Rear Side Door Locking Rod Replacement | B4730 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2062160 | Rear Side Door Locking Rod Replacement | B4731 | GMNA |
| 2062160 | Rear Side Door Locking Rod Replacement | 8620020 | GMK Domestic |
| 2062160 | Rear Side Door Locking Rod Replacement | 8622900 | GMK Domestic |
| 2062160 | Rear Side Door Locking Rod Replacement | C624700 | Holden Australia |
| 2062160 | Rear Side Door Locking Rod Replacement | C624800 | Holden Australia |
| 2062160 | Rear Side Door Locking Rod Replacement | C641300 | Holden Australia |
| 2062160 | Rear Side Door Locking Rod Replacement | B473100 | Holden New Zealand |
| 2062160 | Rear Side Door Locking Rod Replacement | C624700 | Holden New Zealand |
| 2062160 | Rear Side Door Locking Rod Replacement | C624800 | Holden New Zealand |
| 2062160 | Rear Side Door Locking Rod Replacement | 9632700 | GMK Overseas |
| 2062160 | Rear Side Door Locking Rod Replacement | 9632800 | GMK Overseas |
| 2062210 | Rear Side Door Outside Handle Rod Replacement | 8621202 | GMK Domestic |
| 2062210 | Rear Side Door Outside Handle Rod Replacement | 8621300 | GMK Domestic |
| 2062212 | Rear Side Door Outside Handle Rod Adjustment | C641300 | Holden New Zealand |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | B4700 | GMNA |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | B4701 | GMNA |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | B4740 | GMNA |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | B4741 | GMNA |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | B4947 | GMNA |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | B4992 | GMNA |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | B4993 | GMNA |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | B4996 | GMNA |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | B5082 | GMNA |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | B5083 | GMNA |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C3480 | GMNA |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C3481 | GMNA |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | B4700 | Holden Australia |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | B4701 | Holden Australia |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C334000 | Holden Australia |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C334100 | Holden Australia |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C334200 | Holden Australia |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C623200 | Holden Australia |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C623300 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C624500 | Holden Australia |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C624600 | Holden Australia |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C641200 | Holden Australia |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C641210 | Holden Australia |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C334100 | Holden New Zealand |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C334200 | Holden New Zealand |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C623200 | Holden New Zealand |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C623300 | Holden New Zealand |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C624500 | Holden New Zealand |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C624600 | Holden New Zealand |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C641100 | Holden New Zealand |
| 2062320 | Rear Side Door Inside Handle Rod Replacement | C641210 | Holden New Zealand |
| 2062370 | Rear Side Door Locking Rod Bellcrank Rod Replacement | B4742 | GMNA |
| 2062370 | Rear Side Door Locking Rod Bellcrank Rod Replacement | B4743 | GMNA |
| 2062440 | Rear Compartment Lid Inside Handle Replacement | B4804 | GMNA |
| 2062490 | Rear Side Door Latch Control Replacement | | |
| 2062690 | Intermediate Side Door Outside Handle Replacement | B5032 | GMNA |
| 2062770 | Intermediate Side Door Lock Replacement | B5059 | GMNA |
| 2062910 | Intermediate Side Door Inside Handle Replacement | B5079 | GMNA |
| 2063050 | Rear Compartment Lid Hinge Spring Replacement | B5468 | GMNA |
| 2063050 | Rear Compartment Lid Hinge Spring Replacement | B5469 | GMNA |
| 2063050 | Rear Compartment Lid Hinge Spring Replacement | 8640600 | GMK Domestic |
| 2063050 | Rear Compartment Lid Hinge Spring Replacement | 8640601 | GMK Domestic |
| 2063050 | Rear Compartment Lid Hinge Spring Replacement | C754100 | Holden Australia |
| 2063050 | Rear Compartment Lid Hinge Spring Replacement | C754200 | Holden Australia |
| 2063050 | Rear Compartment Lid Hinge Spring Replacement | C754100 | Holden New Zealand |
| 2063050 | Rear Compartment Lid Hinge Spring Replacement | C754200 | Holden New Zealand |
| 2063070 | Rear Compartment Lid Latch Release Cable Replacement | B5470 | GMNA |
| 2063070 | Rear Compartment Lid Latch Release Cable Replacement | 8625900 | GMK Domestic |
| 2063070 | Rear Compartment Lid Latch Release Cable Replacement | C456000 | Holden Australia |
| 2063070 | Rear Compartment Lid Latch Release Cable Replacement | C732610 | Holden Australia |
| 2063070 | Rear Compartment Lid Latch Release Cable Replacement | C732620 | Holden Australia |
| 2063070 | Rear Compartment Lid Latch Release Cable Replacement | C456000 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2063070 | Rear Compartment Lid Latch Release Cable Replacement | C732610 | Holden New Zealand |
| 2063070 | Rear Compartment Lid Latch Release Cable Replacement | 9670100 | GMK Overseas |
| 2063110 | Rear Compartment Access Door Latch Release Cable Replacement | | |
| 2063130 | Rear Compartment Lid Latch Release Cable Handle Replacement | B5474 | GMNA |
| 2063130 | Rear Compartment Lid Latch Release Cable Handle Replacement | B5475 | GMNA |
| 2063130 | Rear Compartment Lid Latch Release Cable Handle Replacement | 8625800 | GMK Domestic |
| 2063130 | Rear Compartment Lid Latch Release Cable Handle Replacement | 9670900 | GMK Overseas |
| 2063150 | Rear Compartment Lid Outside Handle Replacement | B5476 | GMNA |
| 2063150 | Rear Compartment Lid Outside Handle Replacement | C753500 | Holden Australia |
| 2063150 | Rear Compartment Lid Outside Handle Replacement | C753500 | Holden New Zealand |
| 2063170 | Rear Compartment Lid Lock Cylinder Replacement | B3233 | GMNA |
| 2063170 | Rear Compartment Lid Lock Cylinder Replacement | B4935 | GMNA |
| 2063170 | Rear Compartment Lid Lock Cylinder Replacement | B5472 | GMNA |
| 2063170 | Rear Compartment Lid Lock Cylinder Replacement | B5480 | GMNA |
| 2063170 | Rear Compartment Lid Lock Cylinder Replacement | B5500 | GMNA |
| 2063170 | Rear Compartment Lid Lock Cylinder Replacement | C5810 | GMNA |
| 2063170 | Rear Compartment Lid Lock Cylinder Replacement | R2840 | GMNA |
| 2063170 | Rear Compartment Lid Lock Cylinder Replacement | 8522200 | GMK Domestic |
| 2063170 | Rear Compartment Lid Lock Cylinder Replacement | C733500 | Holden Australia |
| 2063170 | Rear Compartment Lid Lock Cylinder Replacement | C733510 | Holden Australia |
| 2063170 | Rear Compartment Lid Lock Cylinder Replacement | C752100 | Holden Australia |
| 2063170 | Rear Compartment Lid Lock Cylinder Replacement | C720000 | Holden New Zealand |
| 2063170 | Rear Compartment Lid Lock Cylinder Replacement | C733500 | Holden New Zealand |
| 2063170 | Rear Compartment Lid Lock Cylinder Replacement | C733510 | Holden New Zealand |
| 2063170 | Rear Compartment Lid Lock Cylinder Replacement | C752100 | Holden New Zealand |
| 2063170 | Rear Compartment Lid Lock Cylinder Replacement | 9680400 | GMK Overseas |
| 2063190 | Rear Compartment Lid Latch Striker Replacement | B5490 | GMNA |
| 2063190 | Rear Compartment Lid Latch Striker Replacement | 8626100 | GMK Domestic |
| 2063190 | Rear Compartment Lid Latch Striker Replacement | 8641300 | GMK Domestic |
| 2063190 | Rear Compartment Lid Latch Striker Replacement | C719100 | Holden Australia |
| 2063190 | Rear Compartment Lid Latch Striker Replacement | C719200 | Holden Australia |
| 2063190 | Rear Compartment Lid Latch Striker Replacement | C731200 | Holden Australia |
| 2063190 | Rear Compartment Lid Latch Striker Replacement | C731300 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2063190 | Rear Compartment Lid Latch Striker Replacement | C719100 | Holden New Zealand |
| 2063190 | Rear Compartment Lid Latch Striker Replacement | C731200 | Holden New Zealand |
| 2063190 | Rear Compartment Lid Latch Striker Replacement | 9670300 | GMK Overseas |
| 2063240 | Rear Compartment Lid Latch Replacement | B5499 | GMNA |
| 2063240 | Rear Compartment Lid Latch Replacement | B6802 | GMNA |
| 2063240 | Rear Compartment Lid Latch Replacement | 8640100 | GMK Domestic |
| 2063240 | Rear Compartment Lid Latch Replacement | C752000 | Holden Australia |
| 2063240 | Rear Compartment Lid Latch Replacement | C752000 | Holden New Zealand |
| 2063240 | Rear Compartment Lid Latch Replacement | 9670500 | GMK Overseas |
| 2063310 | Endgate Handle Rod Replacement | B5802 | GMNA |
| 2063310 | Endgate Handle Rod Replacement | 9671500 | GMK Overseas |
| 2063380 | Endgate Lock Striker Replacement | B5820 | GMNA |
| 2063380 | Endgate Lock Striker Replacement | B5821 | GMNA |
| 2063380 | Endgate Lock Striker Replacement | B5826 | GMNA |
| 2063380 | Endgate Lock Striker Replacement | C613500 | Holden Australia |
| 2063380 | Endgate Lock Striker Replacement | C613550 | Holden Australia |
| 2063380 | Endgate Lock Striker Replacement | C613500 | Holden New Zealand |
| 2063380 | Endgate Lock Striker Replacement | C613550 | Holden New Zealand |
| 2063430 | Endgate Latch Replacement - Left Side Upper | B5831 | GMNA |
| 2063500 | Endgate Latch Replacement | B5832 | GMNA |
| 2063500 | Endgate Latch Replacement | B5837 | GMNA |
| 2063500 | Endgate Latch Replacement | C000671 | Holden New Zealand |
| 2063550 | Pickup Box Endgate Latch Rod Replacement | B5880 | GMNA |
| 2063550 | Pickup Box Endgate Latch Rod Replacement | B9772 | GMNA |
| 2063550 | Pickup Box Endgate Latch Rod Replacement | B9919 | GMNA |
| 2063600 | Liftgate Outside Handle Replacement | B5910 | GMNA |
| 2063600 | Liftgate Outside Handle Replacement | 8626200 | GMK Domestic |
| 2063600 | Liftgate Outside Handle Replacement | 8630000 | GMK Domestic |
| 2063600 | Liftgate Outside Handle Replacement | C734500 | Holden Australia |
| 2063600 | Liftgate Outside Handle Replacement | C734500 | Holden New Zealand |
| 2063600 | Liftgate Outside Handle Replacement | 9671700 | GMK Overseas |
| 2063600 | Liftgate Outside Handle Replacement | 9781820 | GMK Overseas |
| 2063600 | Liftgate Outside Handle Replacement | 9781850 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2063620 | Liftgate Latch Cover Replacement | B5918 | GMNA |
| 2063640 | Liftgate Lock Replacement | | |
| 2063720 | Liftgate Latch Replacement | B5922 | GMNA |
| 2063720 | Liftgate Latch Replacement | 9671600 | GMK Overseas |
| 2063740 | Liftgate Window Latch Replacement | B5924 | GMNA |
| 2063740 | Liftgate Window Latch Replacement | 9671400 | GMK Overseas |
| 2063760 | Liftgate Actuator Rod Replacement | B5926 | GMNA |
| 2063760 | Liftgate Actuator Rod Replacement | B5930 | GMNA |
| 2063760 | Liftgate Actuator Rod Replacement | 8441400 | GMK Domestic |
| 2063760 | Liftgate Actuator Rod Replacement | 8626900 | GMK Domestic |
| 2063760 | Liftgate Actuator Rod Replacement | 9670700 | GMK Overseas |
| 2063760 | Liftgate Actuator Rod Replacement | 9671300 | GMK Overseas |
| 2063780 | Liftgate Close Actuator Motor Control Module Replacement | B5927 | GMNA |
| 2063780 | Liftgate Close Actuator Motor Control Module Replacement | N312720 | Holden Australia |
| 2063780 | Liftgate Close Actuator Motor Control Module Replacement | N312720 | Holden New Zealand |
| 2063800 | Liftgate Latch Striker Replacement | B582000 | Holden Australia |
| 2063800 | Liftgate Latch Striker Replacement | B582100 | Holden Australia |
| 2063800 | Liftgate Latch Striker Replacement | B582700 | Holden Australia |
| 2063800 | Liftgate Latch Striker Replacement | C753100 | Holden Australia |
| 2063800 | Liftgate Latch Striker Replacement | B582700 | Holden New Zealand |
| 2063800 | Liftgate Latch Striker Replacement | C753100 | Holden New Zealand |
| 2063820 | Liftgate Hydraulic Actuator Replacement | B5942 | GMNA |
| 2063820 | Liftgate Hydraulic Actuator Replacement | 9785900 | GMK Overseas |
| 2063860 | Liftgate Hydraulic Pump Replacement | B5944 | GMNA |
| 2063900 | Liftgate Hydraulic Pump Insulator Replacement | B5946 | GMNA |
| 2063920 | Liftgate Hydraulic Pump Cover Replacement | B5947 | GMNA |
| 2063960 | Fuel Tank Filler Door Latch Release Cable Replacement | B6004 | GMNA |
| 2063960 | Fuel Tank Filler Door Latch Release Cable Replacement | 1452300 | GMK Domestic |
| 2063960 | Fuel Tank Filler Door Latch Release Cable Replacement | 1460100 | GMK Domestic |
| 2064040 | Midgate Latch Replacement | B6053 | GMNA |
| 2064040 | Midgate Latch Replacement | B6054 | GMNA |
| 2064040 | Midgate Latch Replacement | B6055 | GMNA |
| 2064040 | Midgate Latch Replacement | B6056 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2064100 | Liftgate Lock Cylinder Rod Replacement | | |
| 2064110 | Rear Door Outside Handle Replacement | B6160 | GMNA |
| 2064160 | Cargo Box Stowage Box Lid Lock Cylinder Replacement | B6041 | GMNA |
| 2064160 | Cargo Box Stowage Box Lid Lock Cylinder Replacement | B6170 | GMNA |
| 2064160 | Cargo Box Stowage Box Lid Lock Cylinder Replacement | B6171 | GMNA |
| 2064210 | Rear Door Lock Cylinder Replacement | B619800 | Holden Australia |
| 2064230 | Liftgate Lock Cylinder Replacement | B5810 | GMNA |
| 2064230 | Liftgate Lock Cylinder Replacement | B5812 | GMNA |
| 2064230 | Liftgate Lock Cylinder Replacement | B5919 | GMNA |
| 2064230 | Liftgate Lock Cylinder Replacement | B6180 | GMNA |
| 2064230 | Liftgate Lock Cylinder Replacement | B6181 | GMNA |
| 2064230 | Liftgate Lock Cylinder Replacement | C9816 | GMNA |
| 2064230 | Liftgate Lock Cylinder Replacement | B583000 | Holden Australia |
| 2064230 | Liftgate Lock Cylinder Replacement | B583000 | Holden New Zealand |
| 2064230 | Liftgate Lock Cylinder Replacement | C720300 | Holden New Zealand |
| 2064250 | Rear Door Lock Striker Replacement | 8430920 | GMK Domestic |
| 2064250 | Rear Door Lock Striker Replacement | 8620600 | GMK Domestic |
| 2064290 | Rear Door Latch Control Replacement | B6200 | GMNA |
| 2064310 | Liftgate Lock Release Cable Replacement | B6220 | GMNA |
| 2064310 | Liftgate Lock Release Cable Replacement | 8640400 | GMK Domestic |
| 2064310 | Liftgate Lock Release Cable Replacement | 9671900 | GMK Overseas |
| 2064330 | Rear Door Latch Replacement - Upper | B6232 | GMNA |
| 2064350 | Rear Door Latch Replacement - Lower | B6234 | GMNA |
| 2064430 | Body Side Upper Front and Rear Access Panel Strut Replacement | | |
| 2064470 | Rear Compartment Lid Interior Release Latch Handle Replacement | C4603 | GMNA |
| 2064490 | Door Lock Switch Replacement - Front | N2106 | GMNA |
| 2064490 | Door Lock Switch Replacement - Front | N2107 | GMNA |
| 2064490 | Door Lock Switch Replacement - Front | N2133 | GMNA |
| 2064490 | Door Lock Switch Replacement - Front | N228300 | Holden Australia |
| 2064490 | Door Lock Switch Replacement - Front | 9650500 | GMK Overseas |
| 2064510 | Door Lock Switch Replacement | N2114 | GMNA |
| 2064510 | Door Lock Switch Replacement | N2126 | GMNA |
| 2064510 | Door Lock Switch Replacement | N211400 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2064510 | Door Lock Switch Replacement | N240100 | Holden Australia |
| 2064510 | Door Lock Switch Replacement | N240150 | Holden Australia |
| 2064510 | Door Lock Switch Replacement | N2114 | Holden New Zealand |
| 2064510 | Door Lock Switch Replacement | N240100 | Holden New Zealand |
| 2064510 | Door Lock Switch Replacement | N240150 | Holden New Zealand |
| 2064510 | Door Lock Switch Replacement | 9650600 | GMK Overseas |
| 2064620 | Front Side Door Handle Switch Replacement | N2120 | GMNA |
| 2064620 | Front Side Door Handle Switch Replacement | C000577 | Holden Australia |
| 2064620 | Front Side Door Handle Switch Replacement | C000577 | Holden New Zealand |
| 2064670 | Door Lock Switch Replacement - Passenger Front | N2122 | GMNA |
| 2064690 | Door Lock Switch Replacement - Driver Side | N2123 | GMNA |
| 2064690 | Door Lock Switch Replacement - Driver Side | N2124 | GMNA |
| 2064690 | Door Lock Switch Replacement - Driver Side | N2125 | GMNA |
| 2064730 | Door Lock and Side Window Switch Replacement - Driver Side | N2131 | GMNA |
| 2064750 | Door Lock and Side Window Switch Replacement - Passenger Side | N2132 | GMNA |
| 2064800 | Rear Compartment Lid and Fuel Filler Door Release Switch Replacement | N2236 | GMNA |
| 2064800 | Rear Compartment Lid and Fuel Filler Door Release Switch Replacement | 9322000 | GMK Overseas |
| 2064820 | Door Lock Status Indicator Replacement | N2270 | GMNA |
| 2064840 | Liftgate Actuator Control Switch Replacement | N2331 | GMNA |
| 2064860 | Liftgate Release Switch Replacement | N2335 | GMNA |
| 2064860 | Liftgate Release Switch Replacement | N2336 | GMNA |
| 2064860 | Liftgate Release Switch Replacement | N2520 | GMNA |
| 2064860 | Liftgate Release Switch Replacement | N9672 | GMNA |
| 2064880 | Liftgate Close Switch Replacement | N2337 | GMNA |
| 2064900 | Liftgate Angle Sensor Replacement | N2338 | GMNA |
| 2064940 | Rear Compartment Lid Ajar Indicator Switch Replacement | N2386 | GMNA |
| 2064960 | Rear Compartment Lid Release Switch Replacement | N2387 | GMNA |
| 2064960 | Rear Compartment Lid Release Switch Replacement | N2388 | GMNA |
| 2064960 | Rear Compartment Lid Release Switch Replacement | N2389 | GMNA |
| 2064960 | Rear Compartment Lid Release Switch Replacement | N4020 | GMNA |
| 2064960 | Rear Compartment Lid Release Switch Replacement | 5720100 | GMK Domestic |
| 2064960 | Rear Compartment Lid Release Switch Replacement | 8626000 | GMK Domestic |
| 2064960 | Rear Compartment Lid Release Switch Replacement | 8641400 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2064960 | Rear Compartment Lid Release Switch Replacement | 8641500 | GMK Domestic |
| 2064960 | Rear Compartment Lid Release Switch Replacement | N253300 | Holden Australia |
| 2064960 | Rear Compartment Lid Release Switch Replacement | N253300 | Holden New Zealand |
| 2064960 | Rear Compartment Lid Release Switch Replacement | 9353400 | GMK Overseas |
| 2064980 | Rear Compartment Lid Door Lock Switch Enable Switch Replacement | N2587 | GMNA |
| 2065030 | Door Lock Harness Contact Replacement | N3010 | GMNA |
| 2065030 | Door Lock Harness Contact Replacement | N914184 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N914185 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N914186 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N914187 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N914188 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N914189 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N914190 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N914191 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N914192 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N914193 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N914194 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N914195 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N914196 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N914197 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N933285 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N933286 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N933287 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N933288 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N933290 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N933292 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N933295 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N933296 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N933297 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N943684 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N943685 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N943686 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N943687 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2065030 | Door Lock Harness Contact Replacement | N943688 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N943690 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N943691 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N943695 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N943696 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N943698 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N953284 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N953285 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N953286 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N953287 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N953288 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N953290 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N953291 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N953292 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N953293 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N953295 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N953296 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N953297 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N953298 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N963784 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N963785 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N963786 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N963787 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N963788 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N963789 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N963790 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N963791 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N963792 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N963793 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N963794 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N963795 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N963796 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N963797 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2065030 | Door Lock Harness Contact Replacement | N963798 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N973085 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N973086 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N973087 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N973088 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N973089 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N973093 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N973094 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N973095 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N983484 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N983485 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N983486 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N983487 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N983488 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N983494 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N983495 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N983496 | Holden Australia |
| 2065030 | Door Lock Harness Contact Replacement | N622400 | Holden New Zealand |
| 2065030 | Door Lock Harness Contact Replacement | N622500 | Holden New Zealand |
| 2065030 | Door Lock Harness Contact Replacement | N623400 | Holden New Zealand |
| 2065030 | Door Lock Harness Contact Replacement | N623800 | Holden New Zealand |
| 2065030 | Door Lock Harness Contact Replacement | N625400 | Holden New Zealand |
| 2065030 | Door Lock Harness Contact Replacement | N625500 | Holden New Zealand |
| 2065030 | Door Lock Harness Contact Replacement | N626500 | Holden New Zealand |
| 2065030 | Door Lock Harness Contact Replacement | N706600 | Holden New Zealand |
| 2065110 | Front Side Door Lock Actuator Replacement | 8531000 | GMK Domestic |
| 2065110 | Front Side Door Lock Actuator Replacement | 9650100 | GMK Overseas |
| 2065110 | Front Side Door Lock Actuator Replacement | 9650200 | GMK Overseas |
| 2065160 | Rear Side Door Lock Actuator Replacement | N3224 | GMNA |
| 2065160 | Rear Side Door Lock Actuator Replacement | 8620200 | GMK Domestic |
| 2065160 | Rear Side Door Lock Actuator Replacement | B619900 | Holden Australia |
| 2065160 | Rear Side Door Lock Actuator Replacement | N243100 | Holden Australia |
| 2065160 | Rear Side Door Lock Actuator Replacement | B619900 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2065160 | Rear Side Door Lock Actuator Replacement | N243100 | Holden New Zealand |
| 2065160 | Rear Side Door Lock Actuator Replacement | 9650300 | GMK Overseas |
| 2065270 | Liftgate Lock Actuator Replacement | B3270 | GMNA |
| 2065270 | Liftgate Lock Actuator Replacement | B5727 | GMNA |
| 2065270 | Liftgate Lock Actuator Replacement | B5834 | GMNA |
| 2065270 | Liftgate Lock Actuator Replacement | B5850 | GMNA |
| 2065270 | Liftgate Lock Actuator Replacement | B5860 | GMNA |
| 2065270 | Liftgate Lock Actuator Replacement | B5939 | GMNA |
| 2065270 | Liftgate Lock Actuator Replacement | B6258 | GMNA |
| 2065270 | Liftgate Lock Actuator Replacement | B9917 | GMNA |
| 2065270 | Liftgate Lock Actuator Replacement | B9934 | GMNA |
| 2065270 | Liftgate Lock Actuator Replacement | C0720 | GMNA |
| 2065270 | Liftgate Lock Actuator Replacement | N3252 | GMNA |
| 2065270 | Liftgate Lock Actuator Replacement | N3260 | GMNA |
| 2065270 | Liftgate Lock Actuator Replacement | N3265 | GMNA |
| 2065270 | Liftgate Lock Actuator Replacement | C613000 | Holden Australia |
| 2065270 | Liftgate Lock Actuator Replacement | C613200 | Holden Australia |
| 2065270 | Liftgate Lock Actuator Replacement | C613250 | Holden Australia |
| 2065270 | Liftgate Lock Actuator Replacement | C613300 | Holden Australia |
| 2065270 | Liftgate Lock Actuator Replacement | C613350 | Holden Australia |
| 2065270 | Liftgate Lock Actuator Replacement | C613000 | Holden New Zealand |
| 2065270 | Liftgate Lock Actuator Replacement | C613200 | Holden New Zealand |
| 2065270 | Liftgate Lock Actuator Replacement | C613250 | Holden New Zealand |
| 2065270 | Liftgate Lock Actuator Replacement | C613300 | Holden New Zealand |
| 2065270 | Liftgate Lock Actuator Replacement | C613350 | Holden New Zealand |
| 2065290 | Fuel Tank Filler Door Lock Release Switch Replacement | N3268 | GMNA |
| 2065310 | Fuel Tank Filler Door Lock Actuator Replacement | N3228 | GMNA |
| 2065310 | Fuel Tank Filler Door Lock Actuator Replacement | N3269 | GMNA |
| 2065310 | Fuel Tank Filler Door Lock Actuator Replacement | 1451400 | GMK Domestic |
| 2065310 | Fuel Tank Filler Door Lock Actuator Replacement | 1451500 | GMK Domestic |
| 2065310 | Fuel Tank Filler Door Lock Actuator Replacement | L000263 | Holden Australia |
| 2065310 | Fuel Tank Filler Door Lock Actuator Replacement | L006220 | Holden Australia |
| 2065310 | Fuel Tank Filler Door Lock Actuator Replacement | N328000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2065310 | Fuel Tank Filler Door Lock Actuator Replacement | L000263 | Holden New Zealand |
| 2065310 | Fuel Tank Filler Door Lock Actuator Replacement | L006220 | Holden New Zealand |
| 2065310 | Fuel Tank Filler Door Lock Actuator Replacement | N243400 | Holden New Zealand |
| 2065310 | Fuel Tank Filler Door Lock Actuator Replacement | 9660700 | GMK Overseas |
| 2065310 | Fuel Tank Filler Door Lock Actuator Replacement | 9661900 | GMK Overseas |
| 2065360 | Liftgate Actuator Replacement | B9939 | GMNA |
| 2065360 | Liftgate Actuator Replacement | N3271 | GMNA |
| 2065360 | Liftgate Actuator Replacement | N411400 | Holden Australia |
| 2065360 | Liftgate Actuator Replacement | N411410 | Holden Australia |
| 2065380 | Liftgate Close Actuator Motor Replacement | N3335 | GMNA |
| 2065490 | Accessory and Liftgate Control Module Replacement | N4867 | GMNA |
| 2065690 | Charger Door Release Switch Replacement | J4270 | GMNA |
| 2065690 | Charger Door Release Switch Replacement | N5350 | GMNA |
| 2065690 | Charger Door Release Switch Replacement | 9355300 | GMK Overseas |
| 2065710 | Liftgate Side Upper Sensor Replacement | N5513 | GMNA |
| 2069939 | Customer Concerned Not Duplicated (CCND) - Electronics/Safety/Seat/Lighting/Keyless Entry/Theft Alarm | 5612620 | GMK Domestic |
| 2069939 | Customer Concerned Not Duplicated (CCND) - Electronics/Safety/Seat/Lighting/Keyless Entry/Theft Alarm | 5823520 | GMK Domestic |
| 2069939 | Customer Concerned Not Duplicated (CCND) - Electronics/Safety/Seat/Lighting/Keyless Entry/Theft Alarm | 6230100 | GMK Domestic |
| 2070010 | Plenum Drain Tube Replacement | | |
| 2070030 | Plenum Upper Panel Insulator Replacement | B1539 | GMNA |
| 2070030 | Plenum Upper Panel Insulator Replacement | 9761100 | GMK Overseas |
| 2070050 | Plenum Water Deflector Replacement - Left Side | B1751 | GMNA |
| 2070090 | Dash Upper Extension Panel Opening Cover Replacement | B1753 | GMNA |
| 2070090 | Dash Upper Extension Panel Opening Cover Replacement | 9760100 | GMK Overseas |
| 2070100 | Plenum Water Deflector Support Replacement | | |
| 2070110 | Plenum Water Deflector Replacement | B1758 | GMNA |
| 2070110 | Plenum Water Deflector Replacement | 8638700 | GMK Domestic |
| 2070240 | Rear Window Wiper Blade Replacement | B1781 | GMNA |
| 2070240 | Rear Window Wiper Blade Replacement | N3616 | GMNA |
| 2070240 | Rear Window Wiper Blade Replacement | N3621 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2070240 | Rear Window Wiper Blade Replacement | 6420700 | GMK Domestic |
| 2070240 | Rear Window Wiper Blade Replacement | N361600 | Holden Australia |
| 2070240 | Rear Window Wiper Blade Replacement | N362100 | Holden Australia |
| 2070240 | Rear Window Wiper Blade Replacement | N362200 | Holden Australia |
| 2070240 | Rear Window Wiper Blade Replacement | N752200 | Holden Australia |
| 2070240 | Rear Window Wiper Blade Replacement | 9210710 | GMK Overseas |
| 2070260 | Windshield Wiper Blade Replacement | B1783 | GMNA |
| 2070260 | Windshield Wiper Blade Replacement | N3615 | GMNA |
| 2070260 | Windshield Wiper Blade Replacement | B1783 | Holden Australia |
| 2070260 | Windshield Wiper Blade Replacement | N356000 | Holden Australia |
| 2070260 | Windshield Wiper Blade Replacement | N361500 | Holden Australia |
| 2070260 | Windshield Wiper Blade Replacement | W200100 | Holden Australia |
| 2070260 | Windshield Wiper Blade Replacement | B1783 | Holden New Zealand |
| 2070260 | Windshield Wiper Blade Replacement | N356000 | Holden New Zealand |
| 2070260 | Windshield Wiper Blade Replacement | N356200 | Holden New Zealand |
| 2070260 | Windshield Wiper Blade Replacement | N356500 | Holden New Zealand |
| 2070260 | Windshield Wiper Blade Replacement | N361500 | Holden New Zealand |
| 2070260 | Windshield Wiper Blade Replacement | 9210700 | GMK Overseas |
| 2070260 | Windshield Wiper Blade Replacement | 9222900 | GMK Overseas |
| 2070280 | Windshield Wiper Arm Replacement | B1784 | GMNA |
| 2070280 | Windshield Wiper Arm Replacement | B9770 | GMNA |
| 2070280 | Windshield Wiper Arm Replacement | N3588 | GMNA |
| 2070280 | Windshield Wiper Arm Replacement | N3595 | GMNA |
| 2070280 | Windshield Wiper Arm Replacement | N3620 | GMNA |
| 2070280 | Windshield Wiper Arm Replacement | T2557 | GMNA |
| 2070280 | Windshield Wiper Arm Replacement | 6320900 | GMK Domestic |
| 2070280 | Windshield Wiper Arm Replacement | B1784 | Holden Australia |
| 2070280 | Windshield Wiper Arm Replacement | N356100 | Holden Australia |
| 2070280 | Windshield Wiper Arm Replacement | N362000 | Holden Australia |
| 2070280 | Windshield Wiper Arm Replacement | B1784 | Holden New Zealand |
| 2070280 | Windshield Wiper Arm Replacement | N353000 | Holden New Zealand |
| 2070280 | Windshield Wiper Arm Replacement | N356100 | Holden New Zealand |
| 2070280 | Windshield Wiper Arm Replacement | N356600 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2070280 | Windshield Wiper Arm Replacement | N362000 | Holden New Zealand |
| 2070280 | Windshield Wiper Arm Replacement | 9210800 | GMK Overseas |
| 2070282 | Windshield Wiper Arm Adjustment | 5710520 | GMK Domestic |
| 2070282 | Windshield Wiper Arm Adjustment | 9210900 | GMK Overseas |
| 2070300 | Rear Window Wiper Arm Replacement | B1785 | GMNA |
| 2070300 | Rear Window Wiper Arm Replacement | 6420400 | GMK Domestic |
| 2070300 | Rear Window Wiper Arm Replacement | N752100 | Holden Australia |
| 2070300 | Rear Window Wiper Arm Replacement | N752100 | Holden New Zealand |
| 2070300 | Rear Window Wiper Arm Replacement | 9210930 | GMK Overseas |
| 2070300 | Rear Window Wiper Arm Replacement | 9211000 | GMK Overseas |
| 2070380 | Windshield Wiper Transmission Replacement | B1788 | GMNA |
| 2070380 | Windshield Wiper Transmission Replacement | N3610 | GMNA |
| 2070380 | Windshield Wiper Transmission Replacement | N3628 | GMNA |
| 2070380 | Windshield Wiper Transmission Replacement | N3630 | GMNA |
| 2070380 | Windshield Wiper Transmission Replacement | N3631 | GMNA |
| 2070380 | Windshield Wiper Transmission Replacement | N3660 | GMNA |
| 2070380 | Windshield Wiper Transmission Replacement | N3661 | GMNA |
| 2070380 | Windshield Wiper Transmission Replacement | N3667 | GMNA |
| 2070380 | Windshield Wiper Transmission Replacement | N351000 | Holden Australia |
| 2070380 | Windshield Wiper Transmission Replacement | N351100 | Holden Australia |
| 2070380 | Windshield Wiper Transmission Replacement | N351200 | Holden Australia |
| 2070380 | Windshield Wiper Transmission Replacement | N363000 | Holden Australia |
| 2070380 | Windshield Wiper Transmission Replacement | N363100 | Holden Australia |
| 2070380 | Windshield Wiper Transmission Replacement | N363700 | Holden Australia |
| 2070380 | Windshield Wiper Transmission Replacement | N351000 | Holden New Zealand |
| 2070380 | Windshield Wiper Transmission Replacement | N351100 | Holden New Zealand |
| 2070380 | Windshield Wiper Transmission Replacement | N351200 | Holden New Zealand |
| 2070380 | Windshield Wiper Transmission Replacement | N3630 | Holden New Zealand |
| 2070380 | Windshield Wiper Transmission Replacement | N363000 | Holden New Zealand |
| 2070380 | Windshield Wiper Transmission Replacement | N363700 | Holden New Zealand |
| 2070380 | Windshield Wiper Transmission Replacement | 9211100 | GMK Overseas |
| 2070460 | Rear Window Washer Nozzle Replacement | B1791 | GMNA |
| 2070460 | Rear Window Washer Nozzle Replacement | N3775 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2070460 | Rear Window Washer Nozzle Replacement | N755000 | Holden Australia |
| 2070460 | Rear Window Washer Nozzle Replacement | N755000 | Holden New Zealand |
| 2070460 | Rear Window Washer Nozzle Replacement | 9231100 | GMK Overseas |
| 2070462 | Rear Window Washer Nozzle Adjustment | B1809 | GMNA |
| 2070470 | Air Inlet Grille Panel Air Deflector Opening Cover Replacement | | |
| 2070480 | Air Inlet Grille Panel Air Deflector Replacement | | |
| 2070510 | Windshield Washer Nozzle Replacement | B1793 | GMNA |
| 2070510 | Windshield Washer Nozzle Replacement | 6410200 | GMK Domestic |
| 2070510 | Windshield Washer Nozzle Replacement | 6410300 | GMK Domestic |
| 2070510 | Windshield Washer Nozzle Replacement | N357000 | Holden Australia |
| 2070510 | Windshield Washer Nozzle Replacement | N705000 | Holden Australia |
| 2070510 | Windshield Washer Nozzle Replacement | N357000 | Holden New Zealand |
| 2070510 | Windshield Washer Nozzle Replacement | N705000 | Holden New Zealand |
| 2070510 | Windshield Washer Nozzle Replacement | 9230200 | GMK Overseas |
| 2070512 | Windshield Washer Nozzle Adjustment | B1808 | GMNA |
| 2070512 | Windshield Washer Nozzle Adjustment | 5711420 | GMK Domestic |
| 2070530 | Windshield Washer Solvent Container Replacement | B1794 | GMNA |
| 2070530 | Windshield Washer Solvent Container Replacement | B9941 | GMNA |
| 2070530 | Windshield Washer Solvent Container Replacement | B9945 | GMNA |
| 2070530 | Windshield Washer Solvent Container Replacement | N3671 | GMNA |
| 2070530 | Windshield Washer Solvent Container Replacement | N3750 | GMNA |
| 2070530 | Windshield Washer Solvent Container Replacement | N3765 | GMNA |
| 2070530 | Windshield Washer Solvent Container Replacement | 6330700 | GMK Domestic |
| 2070530 | Windshield Washer Solvent Container Replacement | 6330800 | GMK Domestic |
| 2070530 | Windshield Washer Solvent Container Replacement | B1794 | Holden Australia |
| 2070530 | Windshield Washer Solvent Container Replacement | B1801 | Holden Australia |
| 2070530 | Windshield Washer Solvent Container Replacement | N358500 | Holden Australia |
| 2070530 | Windshield Washer Solvent Container Replacement | B1794 | Holden New Zealand |
| 2070530 | Windshield Washer Solvent Container Replacement | 9230100 | GMK Overseas |
| 2070580 | Windshield Washer Solvent Container Grommet Replacement | B1796 | GMNA |
| 2070580 | Windshield Washer Solvent Container Grommet Replacement | 5715300 | GMK Domestic |
| 2070580 | Windshield Washer Solvent Container Grommet Replacement | 6422500 | GMK Domestic |
| 2070580 | Windshield Washer Solvent Container Grommet Replacement | 9231400 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2070630 | Windshield Wiper System Module Replacement | B1799 | GMNA |
| 2070630 | Windshield Wiper System Module Replacement | 6320500 | GMK Domestic |
| 2070650 | Windshield Washer Solvent Container Cap Replacement | B1800 | GMNA |
| 2070650 | Windshield Washer Solvent Container Cap Replacement | 9231800 | GMK Overseas |
| 2070670 | Windshield Washer Solvent Container Filler Tube Replacement | B1801 | GMNA |
| 2070670 | Windshield Washer Solvent Container Filler Tube Replacement | 6330600 | GMK Domestic |
| 2070670 | Windshield Washer Solvent Container Filler Tube Replacement | N358520 | Holden Australia |
| 2070670 | Windshield Washer Solvent Container Filler Tube Replacement | N358520 | Holden New Zealand |
| 2070670 | Windshield Washer Solvent Container Filler Tube Replacement | 9231500 | GMK Overseas |
| 2070690 | Headlamp Washer Nozzle Replacement | B1802 | GMNA |
| 2070690 | Headlamp Washer Nozzle Replacement | 5531800 | GMK Domestic |
| 2070690 | Headlamp Washer Nozzle Replacement | 6412300 | GMK Domestic |
| 2070690 | Headlamp Washer Nozzle Replacement | 6412400 | GMK Domestic |
| 2070690 | Headlamp Washer Nozzle Replacement | N705010 | Holden Australia |
| 2070690 | Headlamp Washer Nozzle Replacement | N705010 | Holden New Zealand |
| 2070710 | Headlamp Washer Nozzle Hole Cover Replacement | B1803 | GMNA |
| 2070710 | Headlamp Washer Nozzle Hole Cover Replacement | 6412000 | GMK Domestic |
| 2070730 | Headlamp Washer Solvent Container Replacement | B1804 | GMNA |
| 2070772 | Washer Hose Repair | B1807 | GMNA |
| 2070772 | Washer Hose Repair | N357100 | Holden Australia |
| 2070772 | Washer Hose Repair | N357200 | Holden Australia |
| 2070772 | Washer Hose Repair | 9230410 | GMK Overseas |
| 2070830 | Air Inlet Grille Panel Extension Replacement | B6809 | GMNA |
| 2070830 | Air Inlet Grille Panel Extension Replacement | B7348 | GMNA |
| 2070830 | Air Inlet Grille Panel Extension Replacement | B7348 | Holden New Zealand |
| 2070850 | Air Inlet Grille Panel Seal Replacement | B1338 | GMNA |
| 2070850 | Air Inlet Grille Panel Seal Replacement | B7349 | GMNA |
| 2070850 | Air Inlet Grille Panel Seal Replacement | B9927 | GMNA |
| 2070850 | Air Inlet Grille Panel Seal Replacement | C1037 | GMNA |
| 2070850 | Air Inlet Grille Panel Seal Replacement | J7913 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | B1229 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | B1538 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | B1748 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2070870 | Air Inlet Grille Panel Replacement | B1760 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | B1761 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | B1766 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | B7350 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | B7351 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | B7352 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | B7353 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | B9745 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | B9814 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | C9701 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | D1350 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | D1351 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | D1352 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | D1353 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | D2000 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | S0350 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | S5130 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | Y0136 | GMNA |
| 2070870 | Air Inlet Grille Panel Replacement | 8638100 | GMK Domestic |
| 2070870 | Air Inlet Grille Panel Replacement | 8638200 | GMK Domestic |
| 2070870 | Air Inlet Grille Panel Replacement | B7350 | Holden Australia |
| 2070870 | Air Inlet Grille Panel Replacement | D907200 | Holden Australia |
| 2070870 | Air Inlet Grille Panel Replacement | D907500 | Holden Australia |
| 2070870 | Air Inlet Grille Panel Replacement | S513000 | Holden Australia |
| 2070870 | Air Inlet Grille Panel Replacement | B7350 | Holden New Zealand |
| 2070870 | Air Inlet Grille Panel Replacement | D907200 | Holden New Zealand |
| 2070870 | Air Inlet Grille Panel Replacement | D907500 | Holden New Zealand |
| 2070870 | Air Inlet Grille Panel Replacement | 9732400 | GMK Overseas |
| 2070890 | Air Inlet Screen Replacement | | |
| 2070940 | Windshield Washer Solvent Level Sensor Replacement | N2590 | GMNA |
| 2070940 | Windshield Washer Solvent Level Sensor Replacement | 6320100 | GMK Domestic |
| 2070940 | Windshield Washer Solvent Level Sensor Replacement | 9231200 | GMK Overseas |
| 2070960 | Rear Window Wiper and Washer Switch Replacement | N2609 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2070960 | Rear Window Wiper and Washer Switch Replacement | 6422200 | GMK Domestic |
| 2070980 | Windshield Wiper and Washer Switch Replacement | N2610 | GMNA |
| 2070980 | Windshield Wiper and Washer Switch Replacement | N2620 | GMNA |
| 2070980 | Windshield Wiper and Washer Switch Replacement | N3505 | GMNA |
| 2070980 | Windshield Wiper and Washer Switch Replacement | 6410800 | GMK Domestic |
| 2070980 | Windshield Wiper and Washer Switch Replacement | N203000 | Holden Australia |
| 2070980 | Windshield Wiper and Washer Switch Replacement | N261000 | Holden Australia |
| 2070980 | Windshield Wiper and Washer Switch Replacement | N203000 | Holden New Zealand |
| 2070980 | Windshield Wiper and Washer Switch Replacement | N2610 | Holden New Zealand |
| 2070980 | Windshield Wiper and Washer Switch Replacement | N261000 | Holden New Zealand |
| 2070980 | Windshield Wiper and Washer Switch Replacement | N350500 | Holden New Zealand |
| 2070980 | Windshield Wiper and Washer Switch Replacement | 6410600 | GMK Overseas |
| 2071090 | Windshield Wiper Motor Replacement | B9747 | GMNA |
| 2071090 | Windshield Wiper Motor Replacement | N3510 | GMNA |
| 2071090 | Windshield Wiper Motor Replacement | N3512 | GMNA |
| 2071090 | Windshield Wiper Motor Replacement | N3520 | GMNA |
| 2071090 | Windshield Wiper Motor Replacement | N3540 | GMNA |
| 2071090 | Windshield Wiper Motor Replacement | N3541 | GMNA |
| 2071090 | Windshield Wiper Motor Replacement | N3550 | GMNA |
| 2071090 | Windshield Wiper Motor Replacement | N3551 | GMNA |
| 2071090 | Windshield Wiper Motor Replacement | N3598 | GMNA |
| 2071090 | Windshield Wiper Motor Replacement | N3640 | GMNA |
| 2071090 | Windshield Wiper Motor Replacement | N3641 | GMNA |
| 2071090 | Windshield Wiper Motor Replacement | N3647 | GMNA |
| 2071090 | Windshield Wiper Motor Replacement | N3648 | GMNA |
| 2071090 | Windshield Wiper Motor Replacement | N9532 | GMNA |
| 2071090 | Windshield Wiper Motor Replacement | N9572 | GMNA |
| 2071090 | Windshield Wiper Motor Replacement | 6320600 | GMK Domestic |
| 2071090 | Windshield Wiper Motor Replacement | 6320700 | GMK Domestic |
| 2071090 | Windshield Wiper Motor Replacement | N351500 | Holden Australia |
| 2071090 | Windshield Wiper Motor Replacement | N3520 | Holden Australia |
| 2071090 | Windshield Wiper Motor Replacement | N352000 | Holden Australia |
| 2071090 | Windshield Wiper Motor Replacement | N351500 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2071090 | Windshield Wiper Motor Replacement | N3520 | Holden New Zealand |
| 2071090 | Windshield Wiper Motor Replacement | N352000 | Holden New Zealand |
| 2071090 | Windshield Wiper Motor Replacement | N3540 | Holden New Zealand |
| 2071090 | Windshield Wiper Motor Replacement | N3550 | Holden New Zealand |
| 2071090 | Windshield Wiper Motor Replacement | 9210100 | GMK Overseas |
| 2071090 | Windshield Wiper Motor Replacement | 9210100R | GMK Overseas |
| 2071090 | Windshield Wiper Motor Replacement | 9210200 | GMK Overseas |
| 2071090 | Windshield Wiper Motor Replacement | 9210210 | GMK Overseas |
| 2071090 | Windshield Wiper Motor Replacement | 92102200 | GMK Overseas |
| 2071110 | Rear Window Wiper Motor Replacement | N3511 | GMNA |
| 2071110 | Rear Window Wiper Motor Replacement | N3521 | GMNA |
| 2071110 | Rear Window Wiper Motor Replacement | 6420300 | GMK Domestic |
| 2071110 | Rear Window Wiper Motor Replacement | N3521 | Holden Australia |
| 2071110 | Rear Window Wiper Motor Replacement | N352100 | Holden Australia |
| 2071110 | Rear Window Wiper Motor Replacement | N752000 | Holden Australia |
| 2071110 | Rear Window Wiper Motor Replacement | N752050 | Holden Australia |
| 2071110 | Rear Window Wiper Motor Replacement | N752000 | Holden New Zealand |
| 2071110 | Rear Window Wiper Motor Replacement | N752050 | Holden New Zealand |
| 2071110 | Rear Window Wiper Motor Replacement | 9210300 | GMK Overseas |
| 2071130 | Windshield Wiper Motor Cover Replacement | N3565 | GMNA |
| 2071150 | Rear Window Wiper Control Module Replacement | 9211600 | GMK Overseas |
| 2071230 | Windshield Outside Moisture Sensor Replacement | N3573 | GMNA |
| 2071240 | Windshield Outside Moisture Sensor Lens Replacement | | |
| 2071250 | Windshield Outside Moisture Sensor Lens Replacement | N3575 | GMNA |
| 2071270 | Windshield Outside Moisture Sensor Cover Replacement | N3577 | GMNA |
| 2071270 | Windshield Outside Moisture Sensor Cover Replacement | 6320300 | GMK Domestic |
| 2071350 | Windshield Washer Solvent Level Switch Replacement | N3822 | GMNA |
| 2071350 | Windshield Washer Solvent Level Switch Replacement | 9231000 | GMK Overseas |
| 2071370 | Windshield Washer Solvent Level Indicator Replacement | N3823 | GMNA |
| 2071390 | Windshield Washer Solvent Heater Replacement | 9232300 | GMK Overseas |
| 2071410 | Windshield Washer Pump Replacement | N3860 | GMNA |
| 2071410 | Windshield Washer Pump Replacement | 6330900 | GMK Domestic |
| 2071410 | Windshield Washer Pump Replacement | N354500 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2071410 | Windshield Washer Pump Replacement | N354500 | Holden New Zealand |
| 2071410 | Windshield Washer Pump Replacement | 9230700 | GMK Overseas |
| 2071410 | Windshield Washer Pump Replacement | 9230710 | GMK Overseas |
| 2071430 | Rear Window Washer Pump Replacement | N3861 | GMNA |
| 2071430 | Rear Window Washer Pump Replacement | N757500 | Holden Australia |
| 2071430 | Rear Window Washer Pump Replacement | N757500 | Holden New Zealand |
| 2071430 | Rear Window Washer Pump Replacement | 9231600 | GMK Overseas |
| 2071450 | Headlamp Washer Pump Replacement | N3865 | GMNA |
| 2071450 | Headlamp Washer Pump Replacement | N3860 | Holden Australia |
| 2071450 | Headlamp Washer Pump Replacement | N3861 | Holden Australia |
| 2071450 | Headlamp Washer Pump Replacement | N3860 | Holden New Zealand |
| 2071450 | Headlamp Washer Pump Replacement | 9232400 | GMK Overseas |
| 2071470 | Headlamp Washer Nozzle Actuator Replacement | N3866 | GMNA |
| 2071470 | Headlamp Washer Nozzle Actuator Replacement | 9232500 | GMK Overseas |
| 2410010 | Brake Master Cylinder with Power Brake Booster and Chassis Control Module Replacement | H0639 | GMNA |
| 2410020 | Front Wheel Speed Sensor Replacement | H2410 | GMNA |
| 2410020 | Front Wheel Speed Sensor Replacement | H2410 | Holden Australia |
| 2410020 | Front Wheel Speed Sensor Replacement | H901340 | Holden Australia |
| 2410020 | Front Wheel Speed Sensor Replacement | 4620100 | GMK Overseas |
| 2410020 | Front Wheel Speed Sensor Replacement | 4620200 | GMK Overseas |
| 2410022 | Front Wheel Speed Sensor Replacement - Both Sides | H2412 | GMNA |
| 2410022 | Front Wheel Speed Sensor Replacement - Both Sides | H9714 | GMNA |
| 2410022 | Front Wheel Speed Sensor Replacement - Both Sides | H9734 | GMNA |
| 2410022 | Front Wheel Speed Sensor Replacement - Both Sides | 5330100 | GMK Domestic |
| 2410022 | Front Wheel Speed Sensor Replacement - Both Sides | H901300 | Holden Australia |
| 2410022 | Front Wheel Speed Sensor Replacement - Both Sides | H901300 | Holden New Zealand |
| 2410022 | Front Wheel Speed Sensor Replacement - Both Sides | 4620300 | GMK Overseas |
| 2410060 | Front Wheel Speed Sensor Reluctor Wheel Replacement | H2413 | GMNA |
| 2410060 | Front Wheel Speed Sensor Reluctor Wheel Replacement | F506300 | Holden Australia |
| 2410060 | Front Wheel Speed Sensor Reluctor Wheel Replacement | F506400 | Holden Australia |
| 2410060 | Front Wheel Speed Sensor Reluctor Wheel Replacement | F506500 | Holden Australia |
| 2410060 | Front Wheel Speed Sensor Reluctor Wheel Replacement | F506400 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2410080 | Rear Wheel Speed Sensor Replacement | H2414 | GMNA |
| 2410080 | Rear Wheel Speed Sensor Replacement | H2435 | GMNA |
| 2410080 | Rear Wheel Speed Sensor Replacement | H2450 | GMNA |
| 2410080 | Rear Wheel Speed Sensor Replacement | H2414 | Holden Australia |
| 2410080 | Rear Wheel Speed Sensor Replacement | H241400 | Holden Australia |
| 2410080 | Rear Wheel Speed Sensor Replacement | H901320 | Holden Australia |
| 2410080 | Rear Wheel Speed Sensor Replacement | H901440 | Holden Australia |
| 2410080 | Rear Wheel Speed Sensor Replacement | H2414 | Holden New Zealand |
| 2410080 | Rear Wheel Speed Sensor Replacement | H2440 | Holden New Zealand |
| 2410080 | Rear Wheel Speed Sensor Replacement | H2442 | Holden New Zealand |
| 2410080 | Rear Wheel Speed Sensor Replacement | H2444 | Holden New Zealand |
| 2410080 | Rear Wheel Speed Sensor Replacement | H2445 | Holden New Zealand |
| 2410080 | Rear Wheel Speed Sensor Replacement | H702000 | Holden New Zealand |
| 2410080 | Rear Wheel Speed Sensor Replacement | H901320 | Holden New Zealand |
| 2410080 | Rear Wheel Speed Sensor Replacement | 4620400 | GMK Overseas |
| 2410080 | Rear Wheel Speed Sensor Replacement | 462040A | GMK Overseas |
| 2410080 | Rear Wheel Speed Sensor Replacement | 4620500 | GMK Overseas |
| 2410080 | Rear Wheel Speed Sensor Replacement | 462050A | GMK Overseas |
| 2410081 | Rear Wheel Speed Sensor Replacement - Both Sides | H2417 | GMNA |
| 2410081 | Rear Wheel Speed Sensor Replacement - Both Sides | 4711202 | GMK Domestic |
| 2410081 | Rear Wheel Speed Sensor Replacement - Both Sides | H2417 | Holden Australia |
| 2410081 | Rear Wheel Speed Sensor Replacement - Both Sides | H241700 | Holden Australia |
| 2410081 | Rear Wheel Speed Sensor Replacement - Both Sides | H901400 | Holden Australia |
| 2410081 | Rear Wheel Speed Sensor Replacement - Both Sides | H241700 | Holden New Zealand |
| 2410081 | Rear Wheel Speed Sensor Replacement - Both Sides | H702200 | Holden New Zealand |
| 2410081 | Rear Wheel Speed Sensor Replacement - Both Sides | H901400 | Holden New Zealand |
| 2410081 | Rear Wheel Speed Sensor Replacement - Both Sides | 4620600 | GMK Overseas |
| 2410081 | Rear Wheel Speed Sensor Replacement - Both Sides | 462060A | GMK Overseas |
| 2410170 | Brake Pressure Modulator Valve Replacement | H2480 | GMNA |
| 2410170 | Brake Pressure Modulator Valve Replacement | H9741 | GMNA |
| 2410170 | Brake Pressure Modulator Valve Replacement | H2480 | Holden New Zealand |
| 2410170 | Brake Pressure Modulator Valve Replacement | 4620900 | GMK Overseas |
| 2410230 | Brake Pipe Manifold Replacement | H2486 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2410310 | Brake Pressure Modulator Valve Pressure Sensor Replacement | H2496 | GMNA |
| 2410310 | Brake Pressure Modulator Valve Pressure Sensor Replacement | H2550 | GMNA |
| 2410330 | Electronic Brake Control Module with Brake Pressure Modulator Valve Replacement | H2501 | GMNA |
| 2410330 | Electronic Brake Control Module with Brake Pressure Modulator Valve Replacement | L1245 | GMNA |
| 2410330 | Electronic Brake Control Module with Brake Pressure Modulator Valve Replacement | H000299 | Holden Australia |
| 2410330 | Electronic Brake Control Module with Brake Pressure Modulator Valve Replacement | H2501 | Holden Australia |
| 2410330 | Electronic Brake Control Module with Brake Pressure Modulator Valve Replacement | H000299 | Holden New Zealand |
| 2410350 | Electronic Brake and Traction Control Module with Brake Pressure Modulator Valve Replacement | H2500 | GMNA |
| 2410350 | Electronic Brake and Traction Control Module with Brake Pressure Modulator Valve Replacement | H2502 | GMNA |
| 2410350 | Electronic Brake and Traction Control Module with Brake Pressure Modulator Valve Replacement | H2505 | Holden Australia |
| 2410350 | Electronic Brake and Traction Control Module with Brake Pressure Modulator Valve Replacement | H250500 | Holden Australia |
| 2410350 | Electronic Brake and Traction Control Module with Brake Pressure Modulator Valve Replacement | H900354 | Holden Australia |
| 2410350 | Electronic Brake and Traction Control Module with Brake Pressure Modulator Valve Replacement | H902745 | Holden Australia |
| 2410350 | Electronic Brake and Traction Control Module with Brake Pressure Modulator Valve Replacement | H250500 | Holden New Zealand |
| 2410350 | Electronic Brake and Traction Control Module with Brake Pressure Modulator Valve Replacement | H900275 | Holden New Zealand |
| 2410350 | Electronic Brake and Traction Control Module with Brake Pressure Modulator Valve Replacement | H900292 | Holden New Zealand |
| 2410370 | Electronic Brake Control Module Replacement | H2105 | GMNA |
| 2410370 | Electronic Brake Control Module Replacement | H2479 | GMNA |
| 2410370 | Electronic Brake Control Module Replacement | H2491 | GMNA |
| 2410370 | Electronic Brake Control Module Replacement | H2503 | GMNA |
| 2410370 | Electronic Brake Control Module Replacement | H2504 | GMNA |
| 2410370 | Electronic Brake Control Module Replacement | H2506 | GMNA |
| 2410370 | Electronic Brake Control Module Replacement | H3320 | GMNA |
| 2410370 | Electronic Brake Control Module Replacement | H9740 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2410370 | Electronic Brake Control Module Replacement | 5110300 | GMK Domestic |
| 2410370 | Electronic Brake Control Module Replacement | 5330920 | GMK Domestic |
| 2410370 | Electronic Brake Control Module Replacement | H245000 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H245100 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H245200 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H250600 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H900166 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H900222 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H900231 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H900235 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H900287 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H900500 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H900710 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H900750 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H900800 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H901100 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H901200 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H901203 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H901204 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H901206 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H901207 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H901208 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H901209 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | N506700 | Holden Australia |
| 2410370 | Electronic Brake Control Module Replacement | H2105 | Holden New Zealand |
| 2410370 | Electronic Brake Control Module Replacement | H2490 | Holden New Zealand |
| 2410370 | Electronic Brake Control Module Replacement | H2506 | Holden New Zealand |
| 2410370 | Electronic Brake Control Module Replacement | H901100 | Holden New Zealand |
| 2410370 | Electronic Brake Control Module Replacement | N506700 | Holden New Zealand |
| 2410370 | Electronic Brake Control Module Replacement | 4620700 | GMK Overseas |
| 2410370 | Electronic Brake Control Module Replacement | 4620800 | GMK Overseas |
| 2410370 | Electronic Brake Control Module Replacement | 4621100 | GMK Overseas |
| 2410370 | Electronic Brake Control Module Replacement | 4627100 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2410370 | Electronic Brake Control Module Replacement | 4663500 | GMK Overseas |
| 2410370 | Electronic Brake Control Module Replacement | 4783000 | GMK Overseas |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H2505 | GMNA |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H9715 | GMNA |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900010 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900012 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900013 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900014 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900016 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900018 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900019 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900021 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900022 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900023 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900024 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900025 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900027 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900028 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900031 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900032 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900033 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900035 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900036 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900037 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900039 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900040 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900041 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900042 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900043 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900044 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900045 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900046 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900047 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900048 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900050 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900051 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900052 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900054 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900055 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900056 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900058 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900059 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900060 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900061 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900062 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900063 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900064 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900065 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900066 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900067 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900068 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900070 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900071 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900072 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900073 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900074 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900075 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900078 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900080 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900085 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900090 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900095 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900100 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900101 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900104 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900105 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900110 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900121 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900126 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900131 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900140 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900141 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900143 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900146 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900151 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900155 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900156 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900161 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900186 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900191 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900192 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900196 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900221 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900223 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900225 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900226 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900227 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900232 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900236 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900240 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900241 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900242 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900244 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900245 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900252 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900253 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900256 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900260 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900267 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900271 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900273 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900274 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900275 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900276 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900277 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900280 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900281 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900282 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900285 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900292 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900297 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900454 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900460 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900475 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900501 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900506 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900550 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900551 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900558 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900561 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900565 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900569 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900730 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900751 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900755 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900760 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900895 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900896 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900899 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900900 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901012 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901020 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901041 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901051 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901052 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901055 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901102 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901201 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901202 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901205 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901210 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901211 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901390 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901395 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901571 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901611 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901612 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901650 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901711 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901712 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H902100 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H902103 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H902104 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H902105 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H902106 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H902108 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H902112 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H902139 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H902143 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H902160 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H902402 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H902459 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H902795 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H906236 | Holden Australia |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900013 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900017 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900021 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900023 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900025 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900027 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900031 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900033 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900035 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900037 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900040 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900041 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900044 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900045 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900046 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900050 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900051 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900052 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900056 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900058 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900062 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900063 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900064 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900067 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900070 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900071 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900072 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900073 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900074 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900085 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900100 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900101 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900110 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900121 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900151 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900155 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900156 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900161 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900166 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900186 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900189 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900221 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900222 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900231 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900241 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900245 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900267 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900282 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900287 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900460 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900500 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900550 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900551 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900561 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900565 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900569 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900710 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900750 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900800 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900896 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900899 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H900900 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901200 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901201 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901203 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901206 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901209 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901210 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901395 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901503 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H901612 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H902106 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H902108 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | H902139 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | K506710 | Holden New Zealand |
| 2410390 | Electronic Brake and Traction Control Module Replacement | 4621700 | GMK Overseas |
| 2410440 | Front Wheel Speed Sensor Wiring Harness Replacement | H2530 | GMNA |
| 2410440 | Front Wheel Speed Sensor Wiring Harness Replacement | H000272 | Holden New Zealand |
| 2410440 | Front Wheel Speed Sensor Wiring Harness Replacement | H000275 | Holden New Zealand |
| 2410440 | Front Wheel Speed Sensor Wiring Harness Replacement | H000278 | Holden New Zealand |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | H2532 | GMNA |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | H4050 | GMNA |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | H6551 | GMNA |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N6035 | GMNA |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | H000272 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | H000275 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | H000278 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N914484 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N914485 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N914486 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N914487 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N914491 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N914492 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N914493 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N914494 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N914496 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N914497 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N916991 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N933491 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N933492 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N933493 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N933494 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N933496 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N933497 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N943986 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N943996 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N943997 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N944095 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N953591 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N953592 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N953593 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N953595 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N953596 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N953597 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N964084 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N964085 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N964086 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N964087 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N964088 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N964091 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N964092 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N964093 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N964094 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N964095 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N964096 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N964097 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N973185 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N973186 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N973188 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N973193 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N973194 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N973196 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N973197 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N973295 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N983786 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N983792 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N983793 | Holden Australia |
| 2410441 | Front Wheel Speed Sensor Wiring Harness Replacement - Both Sides | N983794 | Holden Australia |
| 2410510 | Rear Wheel Speed Sensor Wiring Harness Replacement | H2534 | GMNA |
| 2410511 | Rear Wheel Speed Sensor Wiring Harness Replacement - Both Sides | H2537 | GMNA |
| 2410520 | Vehicle Pitch Brake Control and Stability Control System Switch Replacement | | |
| 2410600 | Vehicle Yaw Sensor with Vehicle Lateral and Longitudinal Accelerometer Replacement | H2580 | GMNA |
| 2410620 | Vehicle Yaw Sensor with Vehicle Lateral Accelerometer Replacement | H2581 | GMNA |
| 2410640 | Vehicle Yaw Sensor Replacement | H2582 | GMNA |
| 2410640 | Vehicle Yaw Sensor Replacement | K5528 | GMNA |
| 2410640 | Vehicle Yaw Sensor Replacement | N221320 | Holden Australia |
| 2410640 | Vehicle Yaw Sensor Replacement | N221320 | Holden New Zealand |
| 2410640 | Vehicle Yaw Sensor Replacement | 4622300 | GMK Overseas |
| 2410740 | Electronic Brake Control Position Sensor Replacement | H2587 | GMNA |
| 2410760 | Brake Control Brake Pedal Position Sensor Replacement | H2588 | GMNA |
| 2410780 | Wheel Speed Sensor Reluctor Ring Replacement - Rear Right Side | H2726 | GMNA |
| 2410780 | Wheel Speed Sensor Reluctor Ring Replacement - Rear Right Side | H901420 | Holden Australia |
| 2410780 | Wheel Speed Sensor Reluctor Ring Replacement - Rear Right Side | H901420 | Holden New Zealand |
| 2410800 | Wheel Speed Sensor Reluctor Ring Replacement - Rear Left Side | H2728 | GMNA |
| 2410850 | Electronic Traction Control Switch Replacement | N2583 | GMNA |
| 2410850 | Electronic Traction Control Switch Replacement | N220900 | Holden Australia |
| 2410850 | Electronic Traction Control Switch Replacement | N220900 | Holden New Zealand |
| 2410850 | Electronic Traction Control Switch Replacement | 4622700 | GMK Overseas |
| 2410850 | Electronic Traction Control Switch Replacement | 5270900 | GMK Overseas |
| 2410900 | Vehicle Stability Control System Switch Replacement | N526050 | Holden Australia |
| 2410900 | Vehicle Stability Control System Switch Replacement | N526050 | Holden New Zealand |
| 2410920 | Electronic Traction Control and Vehicle Stability Control Switch Replacement | N5629 | GMNA |
| 2410940 | Vehicle Stability Control Module Replacement | H9747 | GMNA |
| 2410940 | Vehicle Stability Control Module Replacement | H9763 | GMNA |
| 2410940 | Vehicle Stability Control Module Replacement | N5645 | GMNA |
| 2419919 | Customer Concern Not Duplicated (CCND) - Brakes | 4521000 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2420010 | Front Brake Caliper Hardware Replacement | H0030 | GMNA |
| 2420010 | Front Brake Caliper Hardware Replacement | 4122000 | GMK Domestic |
| 2420010 | Front Brake Caliper Hardware Replacement | 4451100 | GMK Overseas |
| 2420010 | Front Brake Caliper Hardware Replacement | 4451200 | GMK Overseas |
| 2420010 | Front Brake Caliper Hardware Replacement | 4565500 | GMK Overseas |
| 2420010 | Front Brake Caliper Hardware Replacement | R445030 | GMK Overseas |
| 2420011 | Front Brake Caliper Hardware Replacement - Both Sides | H0032 | GMNA |
| 2420011 | Front Brake Caliper Hardware Replacement - Both Sides | H9773 | GMNA |
| 2420011 | Front Brake Caliper Hardware Replacement - Both Sides | 4450900 | GMK Overseas |
| 2420011 | Front Brake Caliper Hardware Replacement - Both Sides | 4451000 | GMK Overseas |
| 2420011 | Front Brake Caliper Hardware Replacement - Both Sides | T545018 | GMK Overseas |
| 2420080 | Rear Brake Caliper Hardware Replacement | H0035 | GMNA |
| 2420080 | Rear Brake Caliper Hardware Replacement | H0075 | GMNA |
| 2420080 | Rear Brake Caliper Hardware Replacement | H0076 | GMNA |
| 2420080 | Rear Brake Caliper Hardware Replacement | H0077 | GMNA |
| 2420080 | Rear Brake Caliper Hardware Replacement | H9701 | GMNA |
| 2420080 | Rear Brake Caliper Hardware Replacement | 5290120 | GMK Domestic |
| 2420080 | Rear Brake Caliper Hardware Replacement | 4564800 | GMK Overseas |
| 2420080 | Rear Brake Caliper Hardware Replacement | 4564900 | GMK Overseas |
| 2420080 | Rear Brake Caliper Hardware Replacement | 4566000 | GMK Overseas |
| 2420080 | Rear Brake Caliper Hardware Replacement | 4566200 | GMK Overseas |
| 2420080 | Rear Brake Caliper Hardware Replacement | 4568700 | GMK Overseas |
| 2420081 | Rear Brake Caliper Hardware Replacement - Both Sides | H0037 | GMNA |
| 2420081 | Rear Brake Caliper Hardware Replacement - Both Sides | H9739 | GMNA |
| 2420081 | Rear Brake Caliper Hardware Replacement - Both Sides | H9761 | GMNA |
| 2420150 | Front Disc Brake Pads Replacement | H0042 | GMNA |
| 2420150 | Front Disc Brake Pads Replacement | H9724 | GMNA |
| 2420150 | Front Disc Brake Pads Replacement | H9728 | GMNA |
| 2420150 | Front Disc Brake Pads Replacement | H9730 | GMNA |
| 2420150 | Front Disc Brake Pads Replacement | H9745 | GMNA |
| 2420150 | Front Disc Brake Pads Replacement | L2286 | GMNA |
| 2420150 | Front Disc Brake Pads Replacement | R9229 | GMNA |
| 2420150 | Front Disc Brake Pads Replacement | 5222400 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2420150 | Front Disc Brake Pads Replacement | 5222800 | GMK Domestic |
| 2420150 | Front Disc Brake Pads Replacement | H000171 | Holden Australia |
| 2420150 | Front Disc Brake Pads Replacement | H000222 | Holden Australia |
| 2420150 | Front Disc Brake Pads Replacement | H000225 | Holden Australia |
| 2420150 | Front Disc Brake Pads Replacement | H000231 | Holden Australia |
| 2420150 | Front Disc Brake Pads Replacement | H000234 | Holden Australia |
| 2420150 | Front Disc Brake Pads Replacement | H000251 | Holden Australia |
| 2420150 | Front Disc Brake Pads Replacement | H000263 | Holden Australia |
| 2420150 | Front Disc Brake Pads Replacement | H000290 | Holden Australia |
| 2420150 | Front Disc Brake Pads Replacement | H004200 | Holden Australia |
| 2420150 | Front Disc Brake Pads Replacement | H004300 | Holden Australia |
| 2420150 | Front Disc Brake Pads Replacement | H105000 | Holden Australia |
| 2420150 | Front Disc Brake Pads Replacement | H000222 | Holden New Zealand |
| 2420150 | Front Disc Brake Pads Replacement | H000225 | Holden New Zealand |
| 2420150 | Front Disc Brake Pads Replacement | H000290 | Holden New Zealand |
| 2420150 | Front Disc Brake Pads Replacement | H0042 | Holden New Zealand |
| 2420150 | Front Disc Brake Pads Replacement | H004200 | Holden New Zealand |
| 2420150 | Front Disc Brake Pads Replacement | H004700 | Holden New Zealand |
| 2420150 | Front Disc Brake Pads Replacement | H105000 | Holden New Zealand |
| 2420150 | Front Disc Brake Pads Replacement | 4450100 | GMK Overseas |
| 2420150 | Front Disc Brake Pads Replacement | 4450110 | GMK Overseas |
| 2420150 | Front Disc Brake Pads Replacement | 4450120 | GMK Overseas |
| 2420150 | Front Disc Brake Pads Replacement | 4450200 | GMK Overseas |
| 2420150 | Front Disc Brake Pads Replacement | 4452000 | GMK Overseas |
| 2420170 | Rear Disc Brake Pads Replacement | H0043 | GMNA |
| 2420170 | Rear Disc Brake Pads Replacement | H9713 | GMNA |
| 2420170 | Rear Disc Brake Pads Replacement | H0043 | Holden Australia |
| 2420170 | Rear Disc Brake Pads Replacement | H125000 | Holden Australia |
| 2420170 | Rear Disc Brake Pads Replacement | W200900 | Holden Australia |
| 2420170 | Rear Disc Brake Pads Replacement | H125000 | Holden New Zealand |
| 2420170 | Rear Disc Brake Pads Replacement | 4566300 | GMK Overseas |
| 2420170 | Rear Disc Brake Pads Replacement | 4566400 | GMK Overseas |
| 2420170 | Rear Disc Brake Pads Replacement | 4566500 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2420530 | Front Brake Caliper Replacement | H0070 | GMNA |
| 2420530 | Front Brake Caliper Replacement | H0071 | GMNA |
| 2420530 | Front Brake Caliper Replacement | H0072 | GMNA |
| 2420530 | Front Brake Caliper Replacement | H0100 | GMNA |
| 2420530 | Front Brake Caliper Replacement | H0875 | GMNA |
| 2420530 | Front Brake Caliper Replacement | H0876 | GMNA |
| 2420530 | Front Brake Caliper Replacement | H9749 | GMNA |
| 2420530 | Front Brake Caliper Replacement | 5220400 | GMK Domestic |
| 2420530 | Front Brake Caliper Replacement | H000284 | Holden Australia |
| 2420530 | Front Brake Caliper Replacement | H000287 | Holden Australia |
| 2420530 | Front Brake Caliper Replacement | H000284 | Holden New Zealand |
| 2420530 | Front Brake Caliper Replacement | H000317 | Holden New Zealand |
| 2420530 | Front Brake Caliper Replacement | 4450300 | GMK Overseas |
| 2420530 | Front Brake Caliper Replacement | 445030A | GMK Overseas |
| 2420530 | Front Brake Caliper Replacement | 4450400 | GMK Overseas |
| 2420530 | Front Brake Caliper Replacement | 445040A | GMK Overseas |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H0107 | GMNA |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H0150 | GMNA |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H0151 | GMNA |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H0152 | GMNA |
| 2420531 | Front Brake Caliper Replacement - Both Sides | 4310202 | GMK Domestic |
| 2420531 | Front Brake Caliper Replacement - Both Sides | 5220500 | GMK Domestic |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H008000 | Holden Australia |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H008100 | Holden Australia |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H008700 | Holden Australia |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H0090 | Holden Australia |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H009000 | Holden Australia |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H009100 | Holden Australia |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H009700 | Holden Australia |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H010000 | Holden Australia |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H010100 | Holden Australia |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H0107 | Holden Australia |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H010700 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2420531 | Front Brake Caliper Replacement - Both Sides | H011000 | Holden Australia |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H011100 | Holden Australia |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H107000 | Holden Australia |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H107100 | Holden Australia |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H107200 | Holden Australia |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H0080 | Holden New Zealand |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H008000 | Holden New Zealand |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H008100 | Holden New Zealand |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H008700 | Holden New Zealand |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H010000 | Holden New Zealand |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H010100 | Holden New Zealand |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H107000 | Holden New Zealand |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H107010 | Holden New Zealand |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H107100 | Holden New Zealand |
| 2420531 | Front Brake Caliper Replacement - Both Sides | H107200 | Holden New Zealand |
| 2420531 | Front Brake Caliper Replacement - Both Sides | 4450500 | GMK Overseas |
| 2420531 | Front Brake Caliper Replacement - Both Sides | 445050A | GMK Overseas |
| 2420532 | Front Brake Caliper Overhaul | H0080 | GMNA |
| 2420532 | Front Brake Caliper Overhaul | H9702 | GMNA |
| 2420532 | Front Brake Caliper Overhaul | H9703 | GMNA |
| 2420532 | Front Brake Caliper Overhaul | 5220600 | GMK Domestic |
| 2420532 | Front Brake Caliper Overhaul | H127010 | Holden New Zealand |
| 2420532 | Front Brake Caliper Overhaul | 4450310 | GMK Overseas |
| 2420532 | Front Brake Caliper Overhaul | 4450320 | GMK Overseas |
| 2420532 | Front Brake Caliper Overhaul | 4450510 | GMK Overseas |
| 2420532 | Front Brake Caliper Overhaul | 4450520 | GMK Overseas |
| 2420532 | Front Brake Caliper Overhaul | 4450600 | GMK Overseas |
| 2420532 | Front Brake Caliper Overhaul | 4450610 | GMK Overseas |
| 2420532 | Front Brake Caliper Overhaul | 4450620 | GMK Overseas |
| 2420532 | Front Brake Caliper Overhaul | 4451300 | GMK Overseas |
| 2420532 | Front Brake Caliper Overhaul | 4565900 | GMK Overseas |
| 2420600 | Rear Brake Caliper Replacement | H0110 | GMNA |
| 2420600 | Rear Brake Caliper Replacement | H0147 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2420600 | Rear Brake Caliper Replacement | 5240300 | GMK Domestic |
| 2420600 | Rear Brake Caliper Replacement | 4564300 | GMK Overseas |
| 2420600 | Rear Brake Caliper Replacement | 456430A | GMK Overseas |
| 2420600 | Rear Brake Caliper Replacement | 4564400 | GMK Overseas |
| 2420600 | Rear Brake Caliper Replacement | 456440A | GMK Overseas |
| 2420601 | Rear Brake Caliper Replacement - Both Sides | H0117 | GMNA |
| 2420601 | Rear Brake Caliper Replacement - Both Sides | 4410202 | GMK Domestic |
| 2420601 | Rear Brake Caliper Replacement - Both Sides | 5240400 | GMK Domestic |
| 2420601 | Rear Brake Caliper Replacement - Both Sides | H0117 | Holden Australia |
| 2420601 | Rear Brake Caliper Replacement - Both Sides | H127000 | Holden Australia |
| 2420601 | Rear Brake Caliper Replacement - Both Sides | H127100 | Holden Australia |
| 2420601 | Rear Brake Caliper Replacement - Both Sides | H127200 | Holden Australia |
| 2420601 | Rear Brake Caliper Replacement - Both Sides | H127000 | Holden New Zealand |
| 2420601 | Rear Brake Caliper Replacement - Both Sides | H127100 | Holden New Zealand |
| 2420601 | Rear Brake Caliper Replacement - Both Sides | H127200 | Holden New Zealand |
| 2420601 | Rear Brake Caliper Replacement - Both Sides | 4564500 | GMK Overseas |
| 2420601 | Rear Brake Caliper Replacement - Both Sides | 456450A | GMK Overseas |
| 2420602 | Rear Brake Caliper Overhaul | H0090 | GMNA |
| 2420602 | Rear Brake Caliper Overhaul | 4410210 | GMK Domestic |
| 2420602 | Rear Brake Caliper Overhaul | 5240500 | GMK Domestic |
| 2420602 | Rear Brake Caliper Overhaul | 4564700 | GMK Overseas |
| 2420602 | Rear Brake Caliper Overhaul | 4565600 | GMK Overseas |
| 2420602 | Rear Brake Caliper Overhaul | 4565700 | GMK Overseas |
| 2420670 | Front Brake Rotor Replacement | H0120 | GMNA |
| 2420670 | Front Brake Rotor Replacement | L2593 | GMNA |
| 2420670 | Front Brake Rotor Replacement | 5221520 | GMK Domestic |
| 2420670 | Front Brake Rotor Replacement | H106000 | Holden Australia |
| 2420670 | Front Brake Rotor Replacement | H106100 | Holden Australia |
| 2420670 | Front Brake Rotor Replacement | H106200 | Holden Australia |
| 2420670 | Front Brake Rotor Replacement | H000251 | Holden New Zealand |
| 2420670 | Front Brake Rotor Replacement | H106000 | Holden New Zealand |
| 2420670 | Front Brake Rotor Replacement | H106000A1 | Holden New Zealand |
| 2420670 | Front Brake Rotor Replacement | H106010 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2420670 | Front Brake Rotor Replacement | H106100 | Holden New Zealand |
| 2420670 | Front Brake Rotor Replacement | H106200 | Holden New Zealand |
| 2420670 | Front Brake Rotor Replacement | 2131500 | GMK Overseas |
| 2420670 | Front Brake Rotor Replacement | 2131600 | GMK Overseas |
| 2420670 | Front Brake Rotor Replacement | H106000 | GMK Overseas |
| 2420671 | Front Brake Rotor Replacement - Both Sides | H0127 | GMNA |
| 2420671 | Front Brake Rotor Replacement - Both Sides | H9766 | GMNA |
| 2420671 | Front Brake Rotor Replacement - Both Sides | T5834 | GMNA |
| 2420671 | Front Brake Rotor Replacement - Both Sides | 4320102 | GMK Domestic |
| 2420671 | Front Brake Rotor Replacement - Both Sides | 2131700 | GMK Overseas |
| 2420672 | Front Brake Rotor Refinishing | H0122 | GMNA |
| 2420672 | Front Brake Rotor Refinishing | H9709 | GMNA |
| 2420672 | Front Brake Rotor Refinishing | 4320250 | GMK Domestic |
| 2420672 | Front Brake Rotor Refinishing | H000198 | Holden Australia |
| 2420672 | Front Brake Rotor Refinishing | H000201 | Holden Australia |
| 2420672 | Front Brake Rotor Refinishing | H000207 | Holden Australia |
| 2420672 | Front Brake Rotor Refinishing | H000210 | Holden Australia |
| 2420672 | Front Brake Rotor Refinishing | H0122 | Holden Australia |
| 2420672 | Front Brake Rotor Refinishing | H000195 | Holden New Zealand |
| 2420672 | Front Brake Rotor Refinishing | H000198 | Holden New Zealand |
| 2420672 | Front Brake Rotor Refinishing | H0030005 | Holden New Zealand |
| 2420672 | Front Brake Rotor Refinishing | H0030037 | Holden New Zealand |
| 2420672 | Front Brake Rotor Refinishing | H0030072 | Holden New Zealand |
| 2420672 | Front Brake Rotor Refinishing | H003010 | Holden New Zealand |
| 2420672 | Front Brake Rotor Refinishing | H003020 | Holden New Zealand |
| 2420672 | Front Brake Rotor Refinishing | H003020005 | Holden New Zealand |
| 2420672 | Front Brake Rotor Refinishing | H0250 | Holden New Zealand |
| 2420672 | Front Brake Rotor Refinishing | H126010 | Holden New Zealand |
| 2420672 | Front Brake Rotor Refinishing | H67023 | Holden New Zealand |
| 2420672 | Front Brake Rotor Refinishing | 2131510 | GMK Overseas |
| 2420672 | Front Brake Rotor Refinishing | 2131610 | GMK Overseas |
| 2420672 | Front Brake Rotor Refinishing | 2131710 | GMK Overseas |
| 2420760 | Rear Brake Rotor Replacement | H0130 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2420760 | Rear Brake Rotor Replacement | H9705 | GMNA |
| 2420760 | Rear Brake Rotor Replacement | H9706 | GMNA |
| 2420760 | Rear Brake Rotor Replacement | 5250900 | GMK Domestic |
| 2420760 | Rear Brake Rotor Replacement | H000228 | Holden Australia |
| 2420760 | Rear Brake Rotor Replacement | H000243 | Holden Australia |
| 2420760 | Rear Brake Rotor Replacement | H000254 | Holden Australia |
| 2420760 | Rear Brake Rotor Replacement | H126000 | Holden Australia |
| 2420760 | Rear Brake Rotor Replacement | H126100 | Holden Australia |
| 2420760 | Rear Brake Rotor Replacement | H126200 | Holden Australia |
| 2420760 | Rear Brake Rotor Replacement | H000228 | Holden New Zealand |
| 2420760 | Rear Brake Rotor Replacement | H000243 | Holden New Zealand |
| 2420760 | Rear Brake Rotor Replacement | H126000 | Holden New Zealand |
| 2420760 | Rear Brake Rotor Replacement | H126100 | Holden New Zealand |
| 2420760 | Rear Brake Rotor Replacement | H126200 | Holden New Zealand |
| 2420760 | Rear Brake Rotor Replacement | 4565100 | GMK Overseas |
| 2420760 | Rear Brake Rotor Replacement | 4565200 | GMK Overseas |
| 2420760 | Rear Brake Rotor Replacement | 4565210 | GMK Overseas |
| 2420761 | Rear Brake Rotor Replacement - Both Sides | H0137 | GMNA |
| 2420761 | Rear Brake Rotor Replacement - Both Sides | 4420102 | GMK Domestic |
| 2420761 | Rear Brake Rotor Replacement - Both Sides | 4565300 | GMK Overseas |
| 2420762 | Rear Brake Rotor Refinishing | H0132 | GMNA |
| 2420762 | Rear Brake Rotor Refinishing | H000195 | Holden Australia |
| 2420762 | Rear Brake Rotor Refinishing | H000204 | Holden Australia |
| 2420762 | Rear Brake Rotor Refinishing | H000257 | Holden Australia |
| 2420762 | Rear Brake Rotor Refinishing | H013000 | Holden Australia |
| 2420762 | Rear Brake Rotor Refinishing | H013100 | Holden Australia |
| 2420762 | Rear Brake Rotor Refinishing | H0132 | Holden Australia |
| 2420762 | Rear Brake Rotor Refinishing | H013700 | Holden Australia |
| 2420762 | Rear Brake Rotor Refinishing | H000201 | Holden New Zealand |
| 2420762 | Rear Brake Rotor Refinishing | H000204 | Holden New Zealand |
| 2420762 | Rear Brake Rotor Refinishing | H000207 | Holden New Zealand |
| 2420762 | Rear Brake Rotor Refinishing | H000210 | Holden New Zealand |
| 2420762 | Rear Brake Rotor Refinishing | H000257 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2420762 | Rear Brake Rotor Refinishing | H125010 | Holden New Zealand |
| 2420762 | Rear Brake Rotor Refinishing | 2131900 | GMK Overseas |
| 2420762 | Rear Brake Rotor Refinishing | 213190A | GMK Overseas |
| 2420762 | Rear Brake Rotor Refinishing | 4565310 | GMK Overseas |
| 2420940 | Front Brake Shield Replacement | H0162 | GMNA |
| 2420940 | Front Brake Shield Replacement | H1100 | GMNA |
| 2420940 | Front Brake Shield Replacement | A338260 | Holden Australia |
| 2420940 | Front Brake Shield Replacement | H0160 | Holden Australia |
| 2420940 | Front Brake Shield Replacement | H016000 | Holden Australia |
| 2420940 | Front Brake Shield Replacement | H016100 | Holden Australia |
| 2420940 | Front Brake Shield Replacement | H016700 | Holden Australia |
| 2420940 | Front Brake Shield Replacement | H108000 | Holden Australia |
| 2420940 | Front Brake Shield Replacement | H108100 | Holden Australia |
| 2420940 | Front Brake Shield Replacement | H108200 | Holden Australia |
| 2420940 | Front Brake Shield Replacement | H108000 | Holden New Zealand |
| 2420940 | Front Brake Shield Replacement | H108100 | Holden New Zealand |
| 2420940 | Front Brake Shield Replacement | H108200 | Holden New Zealand |
| 2420940 | Front Brake Shield Replacement | 2132100 | GMK Overseas |
| 2420940 | Front Brake Shield Replacement | 2132200 | GMK Overseas |
| 2420941 | Front Brake Shield Replacement - Both Sides | H0167 | GMNA |
| 2420941 | Front Brake Shield Replacement - Both Sides | H9725 | GMNA |
| 2420941 | Front Brake Shield Replacement - Both Sides | H9755 | GMNA |
| 2420941 | Front Brake Shield Replacement - Both Sides | 2132300 | GMK Overseas |
| 2421040 | Rear Brake Shield Replacement | H0172 | GMNA |
| 2421040 | Rear Brake Shield Replacement | H0400 | GMNA |
| 2421040 | Rear Brake Shield Replacement | H040000 | Holden Australia |
| 2421040 | Rear Brake Shield Replacement | H040100 | Holden Australia |
| 2421040 | Rear Brake Shield Replacement | H040700 | Holden Australia |
| 2421040 | Rear Brake Shield Replacement | H128100 | Holden Australia |
| 2421040 | Rear Brake Shield Replacement | H128200 | Holden Australia |
| 2421040 | Rear Brake Shield Replacement | H128100 | Holden New Zealand |
| 2421040 | Rear Brake Shield Replacement | 4568400 | GMK Overseas |
| 2421040 | Rear Brake Shield Replacement | 4568500 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2421041 | Rear Brake Shield Replacement - Both Sides | H0177 | GMNA |
| 2421041 | Rear Brake Shield Replacement - Both Sides | 4568600 | GMK Overseas |
| 2421050 | Rear Brake Backing Plate Replacement | | |
| 2421052 | Rear Brake Backing Plate Replacement - Both Sides | | |
| 2421110 | Front Disc Brake Pad Wear Sensor Replacement | H0764 | GMNA |
| 2421110 | Front Disc Brake Pad Wear Sensor Replacement | H0768 | GMNA |
| 2421110 | Front Disc Brake Pad Wear Sensor Replacement | H0769 | GMNA |
| 2421110 | Front Disc Brake Pad Wear Sensor Replacement | N221920 | Holden Australia |
| 2421110 | Front Disc Brake Pad Wear Sensor Replacement | N221920 | Holden New Zealand |
| 2429919 | Customer Concern Not Duplicated (CCND) - Brakes | | |
| 2430032 | Front Brake Drum Refinishing | H0190 | GMNA |
| 2430032 | Front Brake Drum Refinishing | H0191 | GMNA |
| 2430032 | Front Brake Drum Refinishing | H0192 | GMNA |
| 2430032 | Front Brake Drum Refinishing | H0197 | GMNA |
| 2430032 | Front Brake Drum Refinishing | H0197 | Holden New Zealand |
| 2430050 | Brake Drum Replacement | H0200 | GMNA |
| 2430050 | Brake Drum Replacement | 4420400 | GMK Domestic |
| 2430050 | Brake Drum Replacement | 5261000 | GMK Domestic |
| 2430050 | Brake Drum Replacement | H3070 | Holden New Zealand |
| 2430050 | Brake Drum Replacement | H3300 | Holden New Zealand |
| 2430050 | Brake Drum Replacement | 4560100 | GMK Overseas |
| 2430050 | Brake Drum Replacement | 4560200 | GMK Overseas |
| 2430050 | Brake Drum Replacement | 4560500 | GMK Overseas |
| 2430050 | Brake Drum Replacement | 4560600 | GMK Overseas |
| 2430050 | Brake Drum Replacement | 4560700 | GMK Overseas |
| 2430050 | Brake Drum Replacement | 4561110 | GMK Overseas |
| 2430050 | Brake Drum Replacement | 4561120 | GMK Overseas |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H0207 | GMNA |
| 2430051 | Rear Brake Drum Replacement - Both Sides | 5261300 | GMK Domestic |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H020000 | Holden Australia |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H020100 | Holden Australia |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H020700 | Holden Australia |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H026000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2430051 | Rear Brake Drum Replacement - Both Sides | H026100 | Holden Australia |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H026200 | Holden Australia |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H020000 | Holden New Zealand |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H020100 | Holden New Zealand |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H0202 | Holden New Zealand |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H0203 | Holden New Zealand |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H0204 | Holden New Zealand |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H0205 | Holden New Zealand |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H0207 | Holden New Zealand |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H020700 | Holden New Zealand |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H020800 | Holden New Zealand |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H026000 | Holden New Zealand |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H026100 | Holden New Zealand |
| 2430051 | Rear Brake Drum Replacement - Both Sides | H026200 | Holden New Zealand |
| 2430051 | Rear Brake Drum Replacement - Both Sides | 4560300 | GMK Overseas |
| 2430051 | Rear Brake Drum Replacement - Both Sides | 4560710 | GMK Overseas |
| 2430052 | Rear Brake Drum Refinishing | H0202 | GMNA |
| 2430052 | Rear Brake Drum Refinishing | H0211 | GMNA |
| 2430052 | Rear Brake Drum Refinishing | H0212 | GMNA |
| 2430052 | Rear Brake Drum Refinishing | H000296 | Holden Australia |
| 2430052 | Rear Brake Drum Refinishing | H000296 | Holden New Zealand |
| 2430052 | Rear Brake Drum Refinishing | 4560400 | GMK Overseas |
| 2430052 | Rear Brake Drum Refinishing | 4560410 | GMK Overseas |
| 2430052 | Rear Brake Drum Refinishing | 4560420 | GMK Overseas |
| 2430052 | Rear Brake Drum Refinishing | T345002 | GMK Overseas |
| 2430201 | Front Brake Shoe Replacement - Both Sides | H0247 | GMNA |
| 2430220 | Brake Shoe Replacement | H0250 | GMNA |
| 2430220 | Brake Shoe Replacement | 5261500 | GMK Domestic |
| 2430220 | Brake Shoe Replacement | 5263300 | GMK Domestic |
| 2430220 | Brake Shoe Replacement | H0250 | Holden Australia |
| 2430220 | Brake Shoe Replacement | H024800 | Holden New Zealand |
| 2430220 | Brake Shoe Replacement | 4560900 | GMK Overseas |
| 2430220 | Brake Shoe Replacement | 4560910 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2430220 | Brake Shoe Replacement | 4560920 | GMK Overseas |
| 2430221 | Rear Brake Shoe Replacement - Both Sides | H0257 | GMNA |
| 2430221 | Rear Brake Shoe Replacement - Both Sides | 4420702 | GMK Domestic |
| 2430221 | Rear Brake Shoe Replacement - Both Sides | 5263200 | GMK Domestic |
| 2430221 | Rear Brake Shoe Replacement - Both Sides | 4561100 | GMK Overseas |
| 2430222 | Drum Brake Adjustment | H0180 | GMNA |
| 2430222 | Drum Brake Adjustment | H9727 | GMNA |
| 2430290 | Drum Brake Hardware Replacement | H0290 | GMNA |
| 2430370 | Drum Brake Adjusting Hardware Replacement | H0340 | GMNA |
| 2430450 | Rear Brake Cylinder Replacement | H0370 | GMNA |
| 2430450 | Rear Brake Cylinder Replacement | H0377 | GMNA |
| 2430450 | Rear Brake Cylinder Replacement | 4410600 | GMK Domestic |
| 2430450 | Rear Brake Cylinder Replacement | 5241300 | GMK Domestic |
| 2430450 | Rear Brake Cylinder Replacement | 5241400 | GMK Domestic |
| 2430450 | Rear Brake Cylinder Replacement | H0370 | Holden New Zealand |
| 2430450 | Rear Brake Cylinder Replacement | H037500 | Holden New Zealand |
| 2430450 | Rear Brake Cylinder Replacement | H0377 | Holden New Zealand |
| 2430450 | Rear Brake Cylinder Replacement | 4562900 | GMK Overseas |
| 2430450 | Rear Brake Cylinder Replacement | 4563100 | GMK Overseas |
| 2430450 | Rear Brake Cylinder Replacement | 4563400 | GMK Overseas |
| 2430450 | Rear Brake Cylinder Replacement | 4563500 | GMK Overseas |
| 2430451 | Rear Brake Cylinder Replacement - Both Sides | 4410502 | GMK Domestic |
| 2430451 | Rear Brake Cylinder Replacement - Both Sides | 5250100 | GMK Domestic |
| 2430451 | Rear Brake Cylinder Replacement - Both Sides | 4563200 | GMK Overseas |
| 2430451 | Rear Brake Cylinder Replacement - Both Sides | 4563600 | GMK Overseas |
| 2430610 | Rear Brake Backing Plate Replacement | H0430 | GMNA |
| 2430610 | Rear Brake Backing Plate Replacement | 5291200 | GMK Domestic |
| 2430610 | Rear Brake Backing Plate Replacement | 4563800 | GMK Overseas |
| 2430610 | Rear Brake Backing Plate Replacement | 4563900 | GMK Overseas |
| 2430611 | Rear Brake Backing Plate Replacement - Both Sides | H0437 | GMNA |
| 2430611 | Rear Brake Backing Plate Replacement - Both Sides | 4430602 | GMK Domestic |
| 2430611 | Rear Brake Backing Plate Replacement - Both Sides | 5291120 | GMK Domestic |
| 2430611 | Rear Brake Backing Plate Replacement - Both Sides | 4564100 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2439919 | Customer Concern Not Duplicated (CCND) - Brakes | | |
| 2440010 | Brake Master Cylinder Reservoir Cap Replacement | H0610 | GMNA |
| 2440010 | Brake Master Cylinder Reservoir Cap Replacement | 5120300 | GMK Domestic |
| 2440010 | Brake Master Cylinder Reservoir Cap Replacement | H400250 | Holden Australia |
| 2440010 | Brake Master Cylinder Reservoir Cap Replacement | H400250 | Holden New Zealand |
| 2440030 | Master Cylinder Reservoir Replacement | H0615 | GMNA |
| 2440030 | Master Cylinder Reservoir Replacement | H2477 | GMNA |
| 2440030 | Master Cylinder Reservoir Replacement | H2522 | GMNA |
| 2440030 | Master Cylinder Reservoir Replacement | J0233 | GMNA |
| 2440030 | Master Cylinder Reservoir Replacement | H0610 | Holden Australia |
| 2440030 | Master Cylinder Reservoir Replacement | H061500 | Holden Australia |
| 2440030 | Master Cylinder Reservoir Replacement | H400200 | Holden Australia |
| 2440030 | Master Cylinder Reservoir Replacement | H400200 | Holden New Zealand |
| 2440030 | Master Cylinder Reservoir Replacement | 4310800 | GMK Overseas |
| 2440050 | Brake Master Cylinder Reservoir Hose Replacement | H0616 | GMNA |
| 2440050 | Brake Master Cylinder Reservoir Hose Replacement | 4010300 | GMK Domestic |
| 2440050 | Brake Master Cylinder Reservoir Hose Replacement | H403210 | Holden Australia |
| 2440100 | Master Cylinder Replacement | H0520 | GMNA |
| 2440100 | Master Cylinder Replacement | H0640 | GMNA |
| 2440100 | Master Cylinder Replacement | H9767 | GMNA |
| 2440100 | Master Cylinder Replacement | 5121000 | GMK Domestic |
| 2440100 | Master Cylinder Replacement | H037100 | Holden Australia |
| 2440100 | Master Cylinder Replacement | H062000 | Holden Australia |
| 2440100 | Master Cylinder Replacement | H0640 | Holden Australia |
| 2440100 | Master Cylinder Replacement | H064000 | Holden Australia |
| 2440100 | Master Cylinder Replacement | H400100 | Holden Australia |
| 2440100 | Master Cylinder Replacement | H400110 | Holden Australia |
| 2440100 | Master Cylinder Replacement | H0371 | Holden New Zealand |
| 2440100 | Master Cylinder Replacement | H037100 | Holden New Zealand |
| 2440100 | Master Cylinder Replacement | H0372 | Holden New Zealand |
| 2440100 | Master Cylinder Replacement | H037200 | Holden New Zealand |
| 2440100 | Master Cylinder Replacement | H0373 | Holden New Zealand |
| 2440100 | Master Cylinder Replacement | H037300 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2440100 | Master Cylinder Replacement | H037400 | Holden New Zealand |
| 2440100 | Master Cylinder Replacement | H0375 | Holden New Zealand |
| 2440100 | Master Cylinder Replacement | H0620 | Holden New Zealand |
| 2440100 | Master Cylinder Replacement | H062000 | Holden New Zealand |
| 2440100 | Master Cylinder Replacement | H064000 | Holden New Zealand |
| 2440100 | Master Cylinder Replacement | H400100 | Holden New Zealand |
| 2440100 | Master Cylinder Replacement | H400110 | Holden New Zealand |
| 2440100 | Master Cylinder Replacement | 4310100 | GMK Overseas |
| 2440100 | Master Cylinder Replacement | 4310200 | GMK Overseas |
| 2440100 | Master Cylinder Replacement | 4310210 | GMK Overseas |
| 2440100 | Master Cylinder Replacement | 4310300 | GMK Overseas |
| 2440100 | Master Cylinder Replacement | 4311500 | GMK Overseas |
| 2440100 | Master Cylinder Replacement | 431150C | GMK Overseas |
| 2440100 | Master Cylinder Replacement | 431150D | GMK Overseas |
| 2440100 | Master Cylinder Replacement | 4311600 | GMK Overseas |
| 2440122 | Hydraulic Brake System Bleeding | H0700 | GMNA |
| 2440122 | Hydraulic Brake System Bleeding | H9733 | GMNA |
| 2440122 | Hydraulic Brake System Bleeding | H0700 | Holden Australia |
| 2440122 | Hydraulic Brake System Bleeding | H902500 | Holden Australia |
| 2440122 | Hydraulic Brake System Bleeding | H0700 | Holden New Zealand |
| 2440122 | Hydraulic Brake System Bleeding | H902500 | Holden New Zealand |
| 2440122 | Hydraulic Brake System Bleeding | 4310400 | GMK Overseas |
| 2440122 | Hydraulic Brake System Bleeding | 4311200 | GMK Overseas |
| 2440140 | Front Brake Hose Replacement | H0720 | GMNA |
| 2440140 | Front Brake Hose Replacement | T5835 | GMNA |
| 2440140 | Front Brake Hose Replacement | 5110100 | GMK Domestic |
| 2440140 | Front Brake Hose Replacement | H0720 | Holden Australia |
| 2440140 | Front Brake Hose Replacement | H072000 | Holden Australia |
| 2440140 | Front Brake Hose Replacement | H0721 | Holden Australia |
| 2440140 | Front Brake Hose Replacement | H402000 | Holden Australia |
| 2440140 | Front Brake Hose Replacement | H402100 | Holden Australia |
| 2440140 | Front Brake Hose Replacement | H402200 | Holden Australia |
| 2440140 | Front Brake Hose Replacement | H412000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2440140 | Front Brake Hose Replacement | H412100 | Holden Australia |
| 2440140 | Front Brake Hose Replacement | H412200 | Holden Australia |
| 2440140 | Front Brake Hose Replacement | H0720 | Holden New Zealand |
| 2440140 | Front Brake Hose Replacement | H0721 | Holden New Zealand |
| 2440140 | Front Brake Hose Replacement | H402000 | Holden New Zealand |
| 2440140 | Front Brake Hose Replacement | H402100 | Holden New Zealand |
| 2440140 | Front Brake Hose Replacement | H402200 | Holden New Zealand |
| 2440140 | Front Brake Hose Replacement | 4250100 | GMK Overseas |
| 2440140 | Front Brake Hose Replacement | 4250200 | GMK Overseas |
| 2440220 | Rear Brake Hose Replacement | H0730 | GMNA |
| 2440220 | Rear Brake Hose Replacement | 4122400 | GMK Domestic |
| 2440220 | Rear Brake Hose Replacement | 5110200 | GMK Domestic |
| 2440220 | Rear Brake Hose Replacement | H072100 | Holden Australia |
| 2440220 | Rear Brake Hose Replacement | H073700 | Holden Australia |
| 2440220 | Rear Brake Hose Replacement | H0737 | Holden New Zealand |
| 2440220 | Rear Brake Hose Replacement | H073700 | Holden New Zealand |
| 2440220 | Rear Brake Hose Replacement | H412100 | Holden New Zealand |
| 2440220 | Rear Brake Hose Replacement | 4250400 | GMK Overseas |
| 2440220 | Rear Brake Hose Replacement | 4250500 | GMK Overseas |
| 2440220 | Rear Brake Hose Replacement | 4253100 | GMK Overseas |
| 2440220 | Rear Brake Hose Replacement | 4254100 | GMK Overseas |
| 2440220 | Rear Brake Hose Replacement | 4254200 | GMK Overseas |
| 2440450 | Brake Combination Valve Replacement | H0780 | GMNA |
| 2440450 | Brake Combination Valve Replacement | H078000 | Holden Australia |
| 2440450 | Brake Combination Valve Replacement | H078000 | Holden New Zealand |
| 2440470 | Brake Delay Valve Replacement | | |
| 2440520 | Brake Fluid Level Indicator Switch Replacement | H0786 | GMNA |
| 2440520 | Brake Fluid Level Indicator Switch Replacement | H078500 | Holden Australia |
| 2440520 | Brake Fluid Level Indicator Switch Replacement | H078500 | Holden New Zealand |
| 2440520 | Brake Fluid Level Indicator Switch Replacement | 4311100 | GMK Overseas |
| 2440540 | Brake Proportion Valve Replacement | H0771 | GMNA |
| 2440540 | Brake Proportion Valve Replacement | H0775 | GMNA |
| 2440540 | Brake Proportion Valve Replacement | H0776 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2440540 | Brake Proportion Valve Replacement | H0777 | GMNA |
| 2440540 | Brake Proportion Valve Replacement | H0787 | GMNA |
| 2440540 | Brake Proportion Valve Replacement | H0790 | GMNA |
| 2440540 | Brake Proportion Valve Replacement | H2517 | GMNA |
| 2440540 | Brake Proportion Valve Replacement | H2710 | GMNA |
| 2440540 | Brake Proportion Valve Replacement | 4121000 | GMK Domestic |
| 2440540 | Brake Proportion Valve Replacement | 5210100 | GMK Domestic |
| 2440540 | Brake Proportion Valve Replacement | H077500 | Holden Australia |
| 2440540 | Brake Proportion Valve Replacement | H077700 | Holden Australia |
| 2440540 | Brake Proportion Valve Replacement | H408500 | Holden Australia |
| 2440540 | Brake Proportion Valve Replacement | H077500 | Holden New Zealand |
| 2440540 | Brake Proportion Valve Replacement | H408500 | Holden New Zealand |
| 2440540 | Brake Proportion Valve Replacement | H409130 | Holden New Zealand |
| 2440540 | Brake Proportion Valve Replacement | 4311300 | GMK Overseas |
| 2440550 | Brake Pipe Replacement | | |
| 2440550 | Wheel Removal | | |
| 2441460 | Brake Master Cylinder Pressure Sensor Replacement | | |
| 2441480 | Brake Master Cylinder Primary Piston Position Sensor Replacement | | |
| 2441500 | Power Brake Booster Vacuum Sensor Replacement | H1150 | GMNA |
| 2441500 | Power Brake Booster Vacuum Sensor Replacement | H1151 | GMNA |
| 2441500 | Power Brake Booster Vacuum Sensor Replacement | H1152 | GMNA |
| 2441500 | Power Brake Booster Vacuum Sensor Replacement | H1182 | GMNA |
| 2441500 | Power Brake Booster Vacuum Sensor Replacement | N002020 | Holden New Zealand |
| 2441580 | Power Vacuum Brake Booster Replacement | H1210 | GMNA |
| 2441580 | Power Vacuum Brake Booster Replacement | H1220 | GMNA |
| 2441580 | Power Vacuum Brake Booster Replacement | H9716 | GMNA |
| 2441580 | Power Vacuum Brake Booster Replacement | 4310600 | GMK Overseas |
| 2441580 | Power Vacuum Brake Booster Replacement | 431060C | GMK Overseas |
| 2441580 | Power Vacuum Brake Booster Replacement | 4310700 | GMK Overseas |
| 2441580 | Power Vacuum Brake Booster Replacement | 4310710 | GMK Overseas |
| 2441600 | Power Brake Booster Pump Replacement | H1224 | GMNA |
| 2441600 | Power Brake Booster Pump Replacement | H9726 | GMNA |
| 2441600 | Power Brake Booster Pump Replacement | J0672 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2441600 | Power Brake Booster Pump Replacement | 4313100 | GMK Overseas |
| 2441620 | Power Brake Booster Auxiliary Pump Replacement | H1225 | GMNA |
| 2441620 | Power Brake Booster Auxiliary Pump Replacement | N002020 | Holden Australia |
| 2441640 | Power Brake Booster Vacuum Pipe Replacement | H0525 | GMNA |
| 2441640 | Power Brake Booster Vacuum Pipe Replacement | H1200 | GMNA |
| 2441640 | Power Brake Booster Vacuum Pipe Replacement | H1239 | GMNA |
| 2441640 | Power Brake Booster Vacuum Pipe Replacement | H9771 | GMNA |
| 2441640 | Power Brake Booster Vacuum Pipe Replacement | H9772 | GMNA |
| 2441640 | Power Brake Booster Vacuum Pipe Replacement | 5210200 | GMK Domestic |
| 2441640 | Power Brake Booster Vacuum Pipe Replacement | 5210300 | GMK Domestic |
| 2441640 | Power Brake Booster Vacuum Pipe Replacement | H1120 | Holden New Zealand |
| 2441640 | Power Brake Booster Vacuum Pipe Replacement | 4312110 | GMK Overseas |
| 2441660 | Power Brake Booster Vacuum Check Valve and Hose Replacement | H1240 | GMNA |
| 2441660 | Power Brake Booster Vacuum Check Valve and Hose Replacement | 5201120 | GMK Domestic |
| 2441660 | Power Brake Booster Vacuum Check Valve and Hose Replacement | H124000 | Holden Australia |
| 2441660 | Power Brake Booster Vacuum Check Valve and Hose Replacement | H503100 | Holden Australia |
| 2441660 | Power Brake Booster Vacuum Check Valve and Hose Replacement | H504100 | Holden Australia |
| 2441660 | Power Brake Booster Vacuum Check Valve and Hose Replacement | H124000 | Holden New Zealand |
| 2441660 | Power Brake Booster Vacuum Check Valve and Hose Replacement | H503100 | Holden New Zealand |
| 2441660 | Power Brake Booster Vacuum Check Valve and Hose Replacement | H504100 | Holden New Zealand |
| 2441660 | Power Brake Booster Vacuum Check Valve and Hose Replacement | 4312100 | GMK Overseas |
| 2441660 | Power Brake Booster Vacuum Check Valve and Hose Replacement | 4312200 | GMK Overseas |
| 2441660 | Power Brake Booster Vacuum Check Valve and Hose Replacement | 4312300 | GMK Overseas |
| 2441680 | Power Brake Booster Vacuum Rear Pipe Replacement | H1241 | GMNA |
| 2441730 | Power Brake Booster Replacement | H1320 | GMNA |
| 2441730 | Power Brake Booster Replacement | 4220100 | GMK Domestic |
| 2441730 | Power Brake Booster Replacement | 4220200 | GMK Domestic |
| 2441730 | Power Brake Booster Replacement | 4221300 | GMK Domestic |
| 2441730 | Power Brake Booster Replacement | 4221400 | GMK Domestic |
| 2441730 | Power Brake Booster Replacement | H502500 | Holden Australia |
| 2441730 | Power Brake Booster Replacement | H502500 | Holden New Zealand |
| 2441730 | Power Brake Booster Replacement | 4310610 | GMK Overseas |
| 2441750 | Power Brake Booster Pump Fluid Accumulator Replacement | H1360 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2441750 | Power Brake Booster Pump Fluid Accumulator Replacement | H1380 | GMNA |
| 2441770 | Brake Pressure Modulator Valve Primary Pipe Replacement | H2487 | GMNA |
| 2441770 | Brake Pressure Modulator Valve Primary Pipe Replacement | 4711400 | GMK Domestic |
| 2441770 | Brake Pressure Modulator Valve Primary Pipe Replacement | 4711500 | GMK Domestic |
| 2441770 | Brake Pressure Modulator Valve Primary Pipe Replacement | H2487 | Holden New Zealand |
| 2441790 | Brake Pressure Modulator Valve Secondary Pipe Replacement | H2488 | GMNA |
| 2441930 | Brake, Accelerator, and Clutch Pedal Replacement | H2639 | GMNA |
| 2441930 | Brake, Accelerator, and Clutch Pedal Replacement | K0061 | GMNA |
| 2441930 | Brake, Accelerator, and Clutch Pedal Replacement | 4534400 | GMK Domestic |
| 2441930 | Brake, Accelerator, and Clutch Pedal Replacement | 4281400 | GMK Overseas |
| 2441930 | Brake, Accelerator, and Clutch Pedal Replacement | 4281500 | GMK Overseas |
| 2441980 | Brake Pedal Assembly Replacement | H2641 | GMNA |
| 2441980 | Brake Pedal Assembly Replacement | H301000 | Holden Australia |
| 2441980 | Brake Pedal Assembly Replacement | H301100 | Holden Australia |
| 2441980 | Brake Pedal Assembly Replacement | H301000 | Holden New Zealand |
| 2441980 | Brake Pedal Assembly Replacement | 4280100 | GMK Overseas |
| 2441980 | Brake Pedal Assembly Replacement | 4280200 | GMK Overseas |
| 2441980 | Brake Pedal Assembly Replacement | 4280900 | GMK Overseas |
| 2442000 | Brake and Accelerator Pedal Assembly Replacement | H2661 | GMNA |
| 2449919 | Customer Concern Not Duplicated (CCND) - Brakes | H9991 | GMNA |
| 2449919 | Customer Concern Not Duplicated (CCND) - Brakes | H9995 | GMNA |
| 2449919 | Customer Concern Not Duplicated (CCND) - Brakes | H9999 | GMNA |
| 2449919 | Customer Concern Not Duplicated (CCND) - Brakes | H9991 | Holden Australia |
| 2450130 | Parking Brake Lever Boot Replacement | H2815 | GMNA |
| 2450130 | Parking Brake Lever Boot Replacement | 5293000 | GMK Domestic |
| 2450210 | Parking Brake Control Module Replacement | H2841 | GMNA |
| 2450260 | Parking Brake Release Handle Assembly Replacement | H2861 | GMNA |
| 2450260 | Parking Brake Release Handle Assembly Replacement | H9737 | GMNA |
| 2450260 | Parking Brake Release Handle Assembly Replacement | 4780200 | GMK Overseas |
| 2450280 | Parking Brake Lever Pedal Assembly Replacement | H2862 | GMNA |
| 2450300 | Parking Brake Lever Replacement | H2863 | GMNA |
| 2450300 | Parking Brake Lever Replacement | H2910 | GMNA |
| 2450300 | Parking Brake Lever Replacement | 2613800 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2450300 | Parking Brake Lever Replacement | H325100 | Holden Australia |
| 2450300 | Parking Brake Lever Replacement | 4780300 | GMK Overseas |
| 2450310 | Parking Brake Lever Opening Cover Replacement | C474700 | Holden Australia |
| 2450310 | Parking Brake Lever Opening Cover Replacement | C474700 | Holden New Zealand |
| 2450320 | Parking Brake Lever Handle Replacement | H2864 | GMNA |
| 2450340 | Parking Brake Cable Replacement | H2879 | GMNA |
| 2450340 | Parking Brake Cable Replacement | H3250 | GMNA |
| 2450340 | Parking Brake Cable Replacement | H3317 | GMNA |
| 2450340 | Parking Brake Cable Replacement | H6555 | GMNA |
| 2450340 | Parking Brake Cable Replacement | H9712 | GMNA |
| 2450340 | Parking Brake Cable Replacement | H9718 | GMNA |
| 2450340 | Parking Brake Cable Replacement | H9719 | GMNA |
| 2450340 | Parking Brake Cable Replacement | H9720 | GMNA |
| 2450340 | Parking Brake Cable Replacement | H9721 | GMNA |
| 2450340 | Parking Brake Cable Replacement | H9723 | GMNA |
| 2450340 | Parking Brake Cable Replacement | H9750 | GMNA |
| 2450340 | Parking Brake Cable Replacement | H9762 | GMNA |
| 2450340 | Parking Brake Cable Replacement | 5310200 | GMK Domestic |
| 2450340 | Parking Brake Cable Replacement | H000237 | Holden Australia |
| 2450340 | Parking Brake Cable Replacement | H2882 | Holden Australia |
| 2450340 | Parking Brake Cable Replacement | H288600 | Holden Australia |
| 2450340 | Parking Brake Cable Replacement | H321000 | Holden Australia |
| 2450340 | Parking Brake Cable Replacement | H321100 | Holden Australia |
| 2450340 | Parking Brake Cable Replacement | H321200 | Holden Australia |
| 2450340 | Parking Brake Cable Replacement | H327300 | Holden Australia |
| 2450340 | Parking Brake Cable Replacement | H000237 | Holden New Zealand |
| 2450340 | Parking Brake Cable Replacement | H321000 | Holden New Zealand |
| 2450340 | Parking Brake Cable Replacement | H321100 | Holden New Zealand |
| 2450340 | Parking Brake Cable Replacement | H321200 | Holden New Zealand |
| 2450340 | Parking Brake Cable Replacement | H321500 | Holden New Zealand |
| 2450340 | Parking Brake Cable Replacement | H321700 | Holden New Zealand |
| 2450340 | Parking Brake Cable Replacement | H327300 | Holden New Zealand |
| 2450340 | Parking Brake Cable Replacement | 4780500 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2450342 | Parking Brake Adjustment | H2800 | GMNA |
| 2450342 | Parking Brake Adjustment | H2800 | Holden Australia |
| 2450360 | Parking Brake Rear Cable Replacement - Right Side | H2880 | GMNA |
| 2450360 | Parking Brake Rear Cable Replacement - Right Side | 4780600 | GMK Overseas |
| 2450380 | Parking Brake Rear Cable Replacement - Left Side | H2881 | GMNA |
| 2450380 | Parking Brake Rear Cable Replacement - Left Side | H288100 | Holden Australia |
| 2450380 | Parking Brake Rear Cable Replacement - Left Side | H288100 | Holden New Zealand |
| 2450400 | Parking Brake Front Cable Replacement | H2882 | GMNA |
| 2450400 | Parking Brake Front Cable Replacement | 2450400 | GMK Domestic |
| 2450400 | Parking Brake Front Cable Replacement | H000189 | Holden Australia |
| 2450420 | Parking Brake Release Cable Replacement | H2883 | GMNA |
| 2450470 | Parking Brake Rear Cable Replacement | H2888 | GMNA |
| 2450470 | Parking Brake Rear Cable Replacement | 4780700 | GMK Overseas |
| 2450490 | Parking Brake Intermediate Cable Replacement | H2889 | GMNA |
| 2450510 | Parking Brake Cable Guide Replacement | H2890 | GMNA |
| 2450560 | Parking Brake Cable Equalizer Replacement | H2900 | GMNA |
| 2450560 | Parking Brake Cable Equalizer Replacement | 4521500 | GMK Domestic |
| 2450560 | Parking Brake Cable Equalizer Replacement | H2900 | Holden Australia |
| 2450570 | Park Brake Hardware Replacement | H9736 | GMNA |
| 2450670 | Parking Brake Shoe Replacement | H2947 | GMNA |
| 2450670 | Parking Brake Shoe Replacement | 5320100 | GMK Domestic |
| 2450670 | Parking Brake Shoe Replacement | H000248 | Holden Australia |
| 2450670 | Parking Brake Shoe Replacement | H025000 | Holden Australia |
| 2450670 | Parking Brake Shoe Replacement | H000248 | Holden New Zealand |
| 2450670 | Parking Brake Shoe Replacement | H025000 | Holden New Zealand |
| 2450670 | Parking Brake Shoe Replacement | 4781100 | GMK Overseas |
| 2450670 | Parking Brake Shoe Replacement | 4781300 | GMK Overseas |
| 2450900 | Rear Parking Brake Anchor Backing Plate Replacement | H3056 | GMNA |
| 2450900 | Rear Parking Brake Anchor Backing Plate Replacement | 5320200 | GMK Domestic |
| 2450901 | Rear Parking Brake Anchor Backing Plate Replacement - Both Sides | H3057 | GMNA |
| 2450940 | Parking Brake Actuator Replacement | H3060 | GMNA |
| 2450940 | Parking Brake Actuator Replacement | H3319 | GMNA |
| 2450940 | Parking Brake Actuator Replacement | H3335 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2451050 | Parking Brake Actuator Switch Replacement | H3220 | GMNA |
| 2451050 | Parking Brake Actuator Switch Replacement | H3303 | GMNA |
| 2451050 | Parking Brake Actuator Switch Replacement | H3305 | GMNA |
| 2451050 | Parking Brake Actuator Switch Replacement | H3307 | GMNA |
| 2451050 | Parking Brake Actuator Switch Replacement | H3330 | GMNA |
| 2451050 | Parking Brake Actuator Switch Replacement | N2378 | GMNA |
| 2451070 | Parking Brake Switch Replacement | H2830 | GMNA |
| 2451070 | Parking Brake Switch Replacement | H3322 | GMNA |
| 2451070 | Parking Brake Switch Replacement | H3324 | GMNA |
| 2451070 | Parking Brake Switch Replacement | N2379 | GMNA |
| 2451070 | Parking Brake Switch Replacement | N2380 | Holden New Zealand |
| 2451090 | Parking Brake Indicator Switch Replacement | N2380 | GMNA |
| 2451090 | Parking Brake Indicator Switch Replacement | N6416 | GMNA |
| 2451090 | Parking Brake Indicator Switch Replacement | 5721500 | GMK Domestic |
| 2451090 | Parking Brake Indicator Switch Replacement | N208500 | Holden Australia |
| 2451090 | Parking Brake Indicator Switch Replacement | N237900 | Holden Australia |
| 2451090 | Parking Brake Indicator Switch Replacement | N2380 | Holden Australia |
| 2451090 | Parking Brake Indicator Switch Replacement | N208500 | Holden New Zealand |
| 2451090 | Parking Brake Indicator Switch Replacement | 4780800 | GMK Overseas |
| 2451110 | Electronic Parking Brake Control Module Replacement | N5644 | GMNA |
| 2451110 | Electronic Parking Brake Control Module Replacement | 4712120 | GMK Domestic |
| 2451110 | Electronic Parking Brake Control Module Replacement | N564400 | Holden Australia |
| 2451110 | Electronic Parking Brake Control Module Replacement | T981501 | Holden New Zealand |
| 2460010 | Trailer Brake Control Switch Replacement | N2582 | GMNA |
| 2460030 | Trailer Brake Control Relay Replacement | N2919 | GMNA |
| 2460050 | Trailer Brake Power Control Module Replacement | N4895 | GMNA |
| 2460050 | Trailer Brake Power Control Module Replacement | H1800 | Holden New Zealand |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D4707 | GMNA |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D9705 | GMNA |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D9711 | GMNA |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D9712 | GMNA |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D9713 | GMNA |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D9733 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2810015 | HVAC System Control Module Reprogramming with SPS | D9740 | GMNA |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D9748 | GMNA |
| 2810015 | HVAC System Control Module Reprogramming with SPS | N9591 | GMNA |
| 2810015 | HVAC System Control Module Reprogramming with SPS | R173017 | GMNA |
| 2810015 | HVAC System Control Module Reprogramming with SPS | T8515 | GMNA |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D333120 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900140 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900155 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900158 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900164 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900168 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900183 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900184 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900223 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900228 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900238 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900253 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900260 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900418 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900428 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D901325 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D901501 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D903531 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D903933 | Holden Australia |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D000357 | Holden New Zealand |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900140 | Holden New Zealand |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900155 | Holden New Zealand |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900164 | Holden New Zealand |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900184 | Holden New Zealand |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900228 | Holden New Zealand |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900238 | Holden New Zealand |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900253 | Holden New Zealand |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900418 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2810015 | HVAC System Control Module Reprogramming with SPS | D900428 | Holden New Zealand |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D901325 | Holden New Zealand |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D903531 | Holden New Zealand |
| 2810015 | HVAC System Control Module Reprogramming with SPS | D903933 | Holden New Zealand |
| 2810015 | HVAC System Control Module Reprogramming with SPS | 7352000 | GMK Overseas |
| 2810035 | Electronic Brake Control Module Reprogramming with SPS | H2508 | GMNA |
| 2810035 | Electronic Brake Control Module Reprogramming with SPS | H2512 | GMNA |
| 2810035 | Electronic Brake Control Module Reprogramming with SPS | H9731 | GMNA |
| 2810035 | Electronic Brake Control Module Reprogramming with SPS | H9735 | GMNA |
| 2810035 | Electronic Brake Control Module Reprogramming with SPS | H9743 | GMNA |
| 2810035 | Electronic Brake Control Module Reprogramming with SPS | R104086 | GMNA |
| 2810035 | Electronic Brake Control Module Reprogramming with SPS | V2466 | GMNA |
| 2810035 | Electronic Brake Control Module Reprogramming with SPS | H2508 | Holden Australia |
| 2810035 | Electronic Brake Control Module Reprogramming with SPS | N506710 | Holden Australia |
| 2810035 | Electronic Brake Control Module Reprogramming with SPS | N506710 | Holden New Zealand |
| 2810035 | Electronic Brake Control Module Reprogramming with SPS | T546013 | GMK Overseas |
| 2810055 | Glow Plug Control Module Reprogramming with SPS | J4821 | GMNA |
| 2810075 | Engine Control Module Reprogramming with SPS | J6350 | GMNA |
| 2810075 | Engine Control Module Reprogramming with SPS | J6364 | GMNA |
| 2810075 | Engine Control Module Reprogramming with SPS | J7716 | GMNA |
| 2810075 | Engine Control Module Reprogramming with SPS | J7919 | GMNA |
| 2810075 | Engine Control Module Reprogramming with SPS | J7947 | GMNA |
| 2810075 | Engine Control Module Reprogramming with SPS | T9738 | GMNA |
| 2810075 | Engine Control Module Reprogramming with SPS | T9758 | GMNA |
| 2810075 | Engine Control Module Reprogramming with SPS | D000366 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | J000669 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | J000672 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | J000809 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | J000812 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | J000818 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | J000821 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | J000914 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | J635900 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2810075 | Engine Control Module Reprogramming with SPS | J987700 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | J987710 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | K000330 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | N000447 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | N000533 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | N000561 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | N000568 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | N000592 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | N000595 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | N000598 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | N000710 | Holden Australia |
| 2810075 | Engine Control Module Reprogramming with SPS | D000366 | Holden New Zealand |
| 2810075 | Engine Control Module Reprogramming with SPS | J000669 | Holden New Zealand |
| 2810075 | Engine Control Module Reprogramming with SPS | J000809 | Holden New Zealand |
| 2810075 | Engine Control Module Reprogramming with SPS | J000812 | Holden New Zealand |
| 2810075 | Engine Control Module Reprogramming with SPS | J000818 | Holden New Zealand |
| 2810075 | Engine Control Module Reprogramming with SPS | J000914 | Holden New Zealand |
| 2810075 | Engine Control Module Reprogramming with SPS | J6358 | Holden New Zealand |
| 2810075 | Engine Control Module Reprogramming with SPS | J987700 | Holden New Zealand |
| 2810075 | Engine Control Module Reprogramming with SPS | J987710 | Holden New Zealand |
| 2810075 | Engine Control Module Reprogramming with SPS | K000330 | Holden New Zealand |
| 2810075 | Engine Control Module Reprogramming with SPS | N000568 | Holden New Zealand |
| 2810075 | Engine Control Module Reprogramming with SPS | N000598 | Holden New Zealand |
| 2810075 | Engine Control Module Reprogramming with SPS | R918065 | Holden New Zealand |
| 2810075 | Engine Control Module Reprogramming with SPS | 1860300 | GMK Overseas |
| 2810075 | Engine Control Module Reprogramming with SPS | 1860600 | GMK Overseas |
| 2810075 | Engine Control Module Reprogramming with SPS | F118026 | GMK Overseas |
| 2810075 | Engine Control Module Reprogramming with SPS | T218015 | GMK Overseas |
| 2810095 | Powertrain Control Module Engine Reprogramming with SPS | J6352 | GMNA |
| 2810095 | Powertrain Control Module Engine Reprogramming with SPS | J6353 | GMNA |
| 2810095 | Powertrain Control Module Engine Reprogramming with SPS | J6354 | GMNA |
| 2810095 | Powertrain Control Module Engine Reprogramming with SPS | J6379 | GMNA |
| 2810095 | Powertrain Control Module Engine Reprogramming with SPS | J6381 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2810095 | Powertrain Control Module Engine Reprogramming with SPS | J7538 | GMNA |
| 2810095 | Powertrain Control Module Engine Reprogramming with SPS | J7941 | GMNA |
| 2810095 | Powertrain Control Module Engine Reprogramming with SPS | J6354 | Holden Australia |
| 2810115 | Powertrain Control Module Transmission Reprogramming with SPS | J6355 | GMNA |
| 2810115 | Powertrain Control Module Transmission Reprogramming with SPS | J7915 | GMNA |
| 2810115 | Powertrain Control Module Transmission Reprogramming with SPS | J6355 | Holden Australia |
| 2810135 | Transfer Case Shift Control Module Reprogramming with SPS | K4121 | GMNA |
| 2810135 | Transfer Case Shift Control Module Reprogramming with SPS | K9814 | GMNA |
| 2810155 | Control Solenoid Valve and Transmission Control Module Assembly Reprogramming with SPS | K5363 | GMNA |
| 2810155 | Control Solenoid Valve and Transmission Control Module Assembly Reprogramming with SPS | K9550 | GMNA |
| 2810155 | Control Solenoid Valve and Transmission Control Module Assembly Reprogramming with SPS | K2490 | Holden New Zealand |
| 2810175 | Transmission Control Module Reprogramming with SPS | K5364 | GMNA |
| 2810175 | Transmission Control Module Reprogramming with SPS | K5634 | GMNA |
| 2810175 | Transmission Control Module Reprogramming with SPS | K9504 | GMNA |
| 2810175 | Transmission Control Module Reprogramming with SPS | K9509 | GMNA |
| 2810175 | Transmission Control Module Reprogramming with SPS | K9532 | GMNA |
| 2810175 | Transmission Control Module Reprogramming with SPS | K9535 | GMNA |
| 2810175 | Transmission Control Module Reprogramming with SPS | K9556 | GMNA |
| 2810175 | Transmission Control Module Reprogramming with SPS | K9557 | GMNA |
| 2810175 | Transmission Control Module Reprogramming with SPS | 2717800 | GMK Domestic |
| 2810175 | Transmission Control Module Reprogramming with SPS | K000318 | Holden Australia |
| 2810175 | Transmission Control Module Reprogramming with SPS | K000321 | Holden Australia |
| 2810175 | Transmission Control Module Reprogramming with SPS | K000333 | Holden Australia |
| 2810175 | Transmission Control Module Reprogramming with SPS | K000348 | Holden Australia |
| 2810175 | Transmission Control Module Reprogramming with SPS | K509610 | Holden Australia |
| 2810175 | Transmission Control Module Reprogramming with SPS | K000318 | Holden New Zealand |
| 2810175 | Transmission Control Module Reprogramming with SPS | K000321 | Holden New Zealand |
| 2810175 | Transmission Control Module Reprogramming with SPS | K000333 | Holden New Zealand |
| 2810175 | Transmission Control Module Reprogramming with SPS | K000348 | Holden New Zealand |
| 2810175 | Transmission Control Module Reprogramming with SPS | K509610 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2810175 | Transmission Control Module Reprogramming with SPS | R718014 | Holden New Zealand |
| 2810195 | Instrument Cluster Reprogramming with SPS | N4199 | GMNA |
| 2810195 | Instrument Cluster Reprogramming with SPS | N9580 | GMNA |
| 2810195 | Instrument Cluster Reprogramming with SPS | N9583 | GMNA |
| 2810195 | Instrument Cluster Reprogramming with SPS | N9633 | GMNA |
| 2810195 | Instrument Cluster Reprogramming with SPS | N9679 | GMNA |
| 2810195 | Instrument Cluster Reprogramming with SPS | N000417 | Holden Australia |
| 2810195 | Instrument Cluster Reprogramming with SPS | N000481 | Holden Australia |
| 2810195 | Instrument Cluster Reprogramming with SPS | N000586 | Holden Australia |
| 2810195 | Instrument Cluster Reprogramming with SPS | N000722 | Holden Australia |
| 2810195 | Instrument Cluster Reprogramming with SPS | N000725 | Holden Australia |
| 2810195 | Instrument Cluster Reprogramming with SPS | N000771 | Holden Australia |
| 2810195 | Instrument Cluster Reprogramming with SPS | N000774 | Holden Australia |
| 2810195 | Instrument Cluster Reprogramming with SPS | N000789 | Holden Australia |
| 2810195 | Instrument Cluster Reprogramming with SPS | N312700 | Holden Australia |
| 2810195 | Instrument Cluster Reprogramming with SPS | N312750 | Holden Australia |
| 2810195 | Instrument Cluster Reprogramming with SPS | N4199 | Holden Australia |
| 2810195 | Instrument Cluster Reprogramming with SPS | N000417 | Holden New Zealand |
| 2810195 | Instrument Cluster Reprogramming with SPS | N000481 | Holden New Zealand |
| 2810195 | Instrument Cluster Reprogramming with SPS | N000586 | Holden New Zealand |
| 2810195 | Instrument Cluster Reprogramming with SPS | N000592 | Holden New Zealand |
| 2810195 | Instrument Cluster Reprogramming with SPS | N000725 | Holden New Zealand |
| 2810195 | Instrument Cluster Reprogramming with SPS | N000774 | Holden New Zealand |
| 2810195 | Instrument Cluster Reprogramming with SPS | N000789 | Holden New Zealand |
| 2810195 | Instrument Cluster Reprogramming with SPS | N312700 | Holden New Zealand |
| 2810195 | Instrument Cluster Reprogramming with SPS | N312750 | Holden New Zealand |
| 2810195 | Instrument Cluster Reprogramming with SPS | 9250800 | GMK Overseas |
| 2810215 | Body Control Module Reprogramming with SPS | N4808 | GMNA |
| 2810215 | Body Control Module Reprogramming with SPS | N9518 | GMNA |
| 2810215 | Body Control Module Reprogramming with SPS | N9535 | GMNA |
| 2810215 | Body Control Module Reprogramming with SPS | N9574 | GMNA |
| 2810215 | Body Control Module Reprogramming with SPS | N9640 | GMNA |
| 2810215 | Body Control Module Reprogramming with SPS | 5711100 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2810215 | Body Control Module Reprogramming with SPS | 5711600 | GMK Domestic |
| 2810215 | Body Control Module Reprogramming with SPS | 5714700 | GMK Domestic |
| 2810215 | Body Control Module Reprogramming with SPS | 5714900 | GMK Domestic |
| 2810215 | Body Control Module Reprogramming with SPS | N000530 | Holden Australia |
| 2810215 | Body Control Module Reprogramming with SPS | N000716 | Holden Australia |
| 2810215 | Body Control Module Reprogramming with SPS | N000719 | Holden Australia |
| 2810215 | Body Control Module Reprogramming with SPS | N000728 | Holden Australia |
| 2810215 | Body Control Module Reprogramming with SPS | N000731 | Holden Australia |
| 2810215 | Body Control Module Reprogramming with SPS | N4808 | Holden Australia |
| 2810215 | Body Control Module Reprogramming with SPS | N506590 | Holden Australia |
| 2810215 | Body Control Module Reprogramming with SPS | N506650 | Holden Australia |
| 2810215 | Body Control Module Reprogramming with SPS | R000245 | Holden Australia |
| 2810215 | Body Control Module Reprogramming with SPS | M000253 | Holden New Zealand |
| 2810215 | Body Control Module Reprogramming with SPS | M000254 | Holden New Zealand |
| 2810215 | Body Control Module Reprogramming with SPS | N000508 | Holden New Zealand |
| 2810215 | Body Control Module Reprogramming with SPS | N000530 | Holden New Zealand |
| 2810215 | Body Control Module Reprogramming with SPS | N000716 | Holden New Zealand |
| 2810215 | Body Control Module Reprogramming with SPS | N000728 | Holden New Zealand |
| 2810215 | Body Control Module Reprogramming with SPS | N000731 | Holden New Zealand |
| 2810215 | Body Control Module Reprogramming with SPS | N506590 | Holden New Zealand |
| 2810215 | Body Control Module Reprogramming with SPS | N5066001 | Holden New Zealand |
| 2810215 | Body Control Module Reprogramming with SPS | N506650 | Holden New Zealand |
| 2810215 | Body Control Module Reprogramming with SPS | R000245 | Holden New Zealand |
| 2810215 | Body Control Module Reprogramming with SPS | R179018 | Holden New Zealand |
| 2810215 | Body Control Module Reprogramming with SPS | R918041 | Holden New Zealand |
| 2810215 | Body Control Module Reprogramming with SPS | R918093 | Holden New Zealand |
| 2810215 | Body Control Module Reprogramming with SPS | T681301 | Holden New Zealand |
| 2810215 | Body Control Module Reprogramming with SPS | T881401 | Holden New Zealand |
| 2810215 | Body Control Module Reprogramming with SPS | 9292900 | GMK Overseas |
| 2810215 | Body Control Module Reprogramming with SPS | R964094 | GMK Overseas |
| 2810235 | Door Lock and Side Window Switch Reprogramming with SPS | N4879 | GMNA |
| 2810235 | Door Lock and Side Window Switch Reprogramming with SPS | N8520 | GMNA |
| 2810235 | Door Lock and Side Window Switch Reprogramming with SPS | N9512 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2810235 | Door Lock and Side Window Switch Reprogramming with SPS | N9569 | GMNA |
| 2810255 | Trailer Brake Control Module Reprogramming with SPS | N4896 | GMNA |
| 2810265 | Hybrid Powertrain Control Module 2 Reprogramming with SPS | | |
| 2810275 | Serial Data Gateway Module Reprogramming with SPS | N5897 | GMNA |
| 2810295 | Drive Motor Generator Power Inverter Module Reprogramming with SPS | N5898 | GMNA |
| 2810315 | Drive Motor Generator Battery Control Module Reprogramming with SPS | N5899 | GMNA |
| 2810335 | Radio Reprogramming with SPS | R0759 | GMNA |
| 2810335 | Radio Reprogramming with SPS | R9809 | GMNA |
| 2810335 | Radio Reprogramming with SPS | 5815100 | GMK Domestic |
| 2810335 | Radio Reprogramming with SPS | R205570 | Holden Australia |
| 2810335 | Radio Reprogramming with SPS | R201800 | Holden New Zealand |
| 2810335 | Radio Reprogramming with SPS | 9296200 | GMK Overseas |
| 2810345 | Human Machine Interface Control Module Reprogramming with SPS | | |
| 2810355 | Remote Control Door Lock Receiver Reprogramming with SPS | R4481 | GMNA |
| 2810355 | Remote Control Door Lock Receiver Reprogramming with SPS | R9716 | GMNA |
| 2810355 | Remote Control Door Lock Receiver Reprogramming with SPS | R9718 | GMNA |
| 2810355 | Remote Control Door Lock Receiver Reprogramming with SPS | R9727 | GMNA |
| 2810355 | Remote Control Door Lock Receiver Reprogramming with SPS | R9728 | GMNA |
| 2810355 | Remote Control Door Lock Receiver Reprogramming with SPS | R9729 | GMNA |
| 2810355 | Remote Control Door Lock Receiver Reprogramming with SPS | R9730 | GMNA |
| 2810355 | Remote Control Door Lock Receiver Reprogramming with SPS | R9731 | GMNA |
| 2810355 | Remote Control Door Lock Receiver Reprogramming with SPS | R9732 | GMNA |
| 2810355 | Remote Control Door Lock Receiver Reprogramming with SPS | R9753 | GMNA |
| 2810355 | Remote Control Door Lock Receiver Reprogramming with SPS | R9757 | GMNA |
| 2810355 | Remote Control Door Lock Receiver Reprogramming with SPS | R9771 | GMNA |
| 2810355 | Remote Control Door Lock Receiver Reprogramming with SPS | 8525000 | GMK Domestic |
| 2810355 | Remote Control Door Lock Receiver Reprogramming with SPS | N317710 | Holden Australia |
| 2810355 | Remote Control Door Lock Receiver Reprogramming with SPS | N317720 | Holden Australia |
| 2810355 | Remote Control Door Lock Receiver Reprogramming with SPS | N317710 | Holden New Zealand |
| 2810415 | Communication Interface Module Reprogramming with SPS | N4807 | GMNA |
| 2810415 | Communication Interface Module Reprogramming with SPS | R4806 | GMNA |
| 2810415 | Communication Interface Module Reprogramming with SPS | R4807 | GMNA |
| 2810415 | Communication Interface Module Reprogramming with SPS | 6111000 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 2810415 | Communication Interface Module Reprogramming with SPS | J902000 | Holden Australia |
| 2810415 | Communication Interface Module Reprogramming with SPS | N446010 | Holden Australia |
| 2810415 | Communication Interface Module Reprogramming with SPS | R4807 | Holden Australia |
| 2810415 | Communication Interface Module Reprogramming with SPS | N446010 | Holden New Zealand |
| 3010060 | Front Drive Axle Actuator Replacement | F0025 | GMNA |
| 3010060 | Front Drive Axle Actuator Replacement | N9668 | GMNA |
| 3010110 | Output Shaft Seal Replacement - Right Side | F1440 | GMNA |
| 3010130 | Output Shaft Seal Replacement - Left Side | F1441 | GMNA |
| 3010130 | Output Shaft Seal Replacement - Left Side | F1441 | Holden Australia |
| 3010140 | Front Wheel Drive Intermediate Shaft Bearing Replacement | 2610900 | GMK Domestic |
| 3010160 | Front Drive Axle Inner Shaft Replacement | F1470 | GMNA |
| 3010160 | Front Drive Axle Inner Shaft Replacement | F1527 | Holden New Zealand |
| 3010180 | Front Drive Axle Inner Shaft Bearing Replacement - Right Side | | |
| 3010190 | Front Drive Axle Inner Shaft Seal Replacement - Right Side | E9547 | GMNA |
| 3010190 | Front Drive Axle Inner Shaft Seal Replacement - Right Side | F1427 | GMNA |
| 3010190 | Front Drive Axle Inner Shaft Seal Replacement - Right Side | F1600 | GMNA |
| 3010190 | Front Drive Axle Inner Shaft Seal Replacement - Right Side | F9716 | GMNA |
| 3010190 | Front Drive Axle Inner Shaft Seal Replacement - Right Side | F9722 | GMNA |
| 3010190 | Front Drive Axle Inner Shaft Seal Replacement - Right Side | E303100 | Holden Australia |
| 3010190 | Front Drive Axle Inner Shaft Seal Replacement - Right Side | E303150 | Holden Australia |
| 3010190 | Front Drive Axle Inner Shaft Seal Replacement - Right Side | E303200 | Holden Australia |
| 3010190 | Front Drive Axle Inner Shaft Seal Replacement - Right Side | F142000 | Holden Australia |
| 3010190 | Front Drive Axle Inner Shaft Seal Replacement - Right Side | F1421 | Holden Australia |
| 3010190 | Front Drive Axle Inner Shaft Seal Replacement - Right Side | F142100 | Holden Australia |
| 3010190 | Front Drive Axle Inner Shaft Seal Replacement - Right Side | E303100 | Holden New Zealand |
| 3010190 | Front Drive Axle Inner Shaft Seal Replacement - Right Side | E303150 | Holden New Zealand |
| 3010190 | Front Drive Axle Inner Shaft Seal Replacement - Right Side | E303200 | Holden New Zealand |
| 3010190 | Front Drive Axle Inner Shaft Seal Replacement - Right Side | F142000 | Holden New Zealand |
| 3010190 | Front Drive Axle Inner Shaft Seal Replacement - Right Side | F142100 | Holden New Zealand |
| 3010190 | Front Drive Axle Inner Shaft Seal Replacement - Right Side | F160000 | Holden New Zealand |
| 3010210 | Front Drive Axle Inner Shaft Seal Replacement - Left Side | F1521 | GMNA |
| 3010210 | Front Drive Axle Inner Shaft Seal Replacement - Left Side | F1527 | GMNA |
| 3010210 | Front Drive Axle Inner Shaft Seal Replacement - Left Side | F1601 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3010210 | Front Drive Axle Inner Shaft Seal Replacement - Left Side | F152700 | Holden Australia |
| 3010230 | Front Drive Axle Inner Shaft Seal and Inner Shaft Bearing Replacement | F1602 | GMNA |
| 3010250 | Front Drive Axle Inner Shaft Housing Replacement | F1603 | GMNA |
| 3010270 | Front Drive Axle Clutch Shaft Bearing Replacement | F1604 | GMNA |
| 3010290 | Front Drive Axle Clutch Fork Replacement | F1605 | GMNA |
| 3010360 | Front Drive Axle Clutch Gear Replacement | | |
| 3010380 | Front Differential Carrier Oil Drain or Filler Plug Replacement | F2001 | GMNA |
| 3010400 | Front Differential Carrier Cover Gasket Replacement | F2002 | GMNA |
| 3010400 | Front Differential Carrier Cover Gasket Replacement | K204110 | Holden Australia |
| 3010400 | Front Differential Carrier Cover Gasket Replacement | 3311100 | GMK Overseas |
| 3010420 | Front Differential Carrier Flange Replacement | | |
| 3010440 | Front Differential Drive Pinion Gear Yoke Replacement | F2019 | GMNA |
| 3010460 | Differential Drive Pinion Gear Seal Replacement | F2022 | GMNA |
| 3010460 | Differential Drive Pinion Gear Seal Replacement | F2024 | GMNA |
| 3010460 | Differential Drive Pinion Gear Seal Replacement | F2025 | GMNA |
| 3010460 | Differential Drive Pinion Gear Seal Replacement | F2027 | GMNA |
| 3010460 | Differential Drive Pinion Gear Seal Replacement | F2022 | Holden Australia |
| 3010460 | Differential Drive Pinion Gear Seal Replacement | F502100 | Holden Australia |
| 3010460 | Differential Drive Pinion Gear Seal Replacement | F202800 | Holden New Zealand |
| 3010460 | Differential Drive Pinion Gear Seal Replacement | F501100 | Holden New Zealand |
| 3010460 | Differential Drive Pinion Gear Seal Replacement | F502100 | Holden New Zealand |
| 3010460 | Differential Drive Pinion Gear Seal Replacement | 3310500 | GMK Overseas |
| 3010460 | Differential Drive Pinion Gear Seal Replacement | 5011600 | GMK Overseas |
| 3010560 | Differential Carrier Assembly Replacement | F2124 | GMNA |
| 3010560 | Differential Carrier Assembly Replacement | F2142 | GMNA |
| 3010560 | Differential Carrier Assembly Replacement | F2122 | Holden Australia |
| 3010560 | Differential Carrier Assembly Replacement | F2142 | Holden Australia |
| 3010560 | Differential Carrier Assembly Replacement | F212600 | Holden New Zealand |
| 3010560 | Differential Carrier Assembly Replacement | F213100 | Holden New Zealand |
| 3010560 | Differential Carrier Assembly Replacement | F2132 | Holden New Zealand |
| 3010560 | Differential Carrier Assembly Replacement | F213300 | Holden New Zealand |
| 3010560 | Differential Carrier Assembly Replacement | F213400 | Holden New Zealand |
| 3010560 | Differential Carrier Assembly Replacement | 5431300 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3010562 | Differential Carrier Overhaul | F0035 | GMNA |
| 3010562 | Differential Carrier Overhaul | F2122 | GMNA |
| 3010562 | Differential Carrier Overhaul | F2025 | Holden New Zealand |
| 3010562 | Differential Carrier Overhaul | F212300F | Holden New Zealand |
| 3010580 | Differential Carrier Bushing Replacement | F2157 | GMNA |
| 3010580 | Differential Carrier Bushing Replacement | 3310900 | GMK Overseas |
| 3010600 | Front Differential Carrier Bracket Replacement | F2161 | GMNA |
| 3010600 | Front Differential Carrier Bracket Replacement | F2161 | Holden Australia |
| 3010620 | Differential Drive Pinion Gear Bearing Replacement | F2282 | GMNA |
| 3010620 | Differential Drive Pinion Gear Bearing Replacement | 5740400 | GMK Overseas |
| 3010640 | Drive Pinion and Ring Gear Replacement | F2042 | GMNA |
| 3010640 | Drive Pinion and Ring Gear Replacement | F2115 | GMNA |
| 3010640 | Drive Pinion and Ring Gear Replacement | F2382 | GMNA |
| 3010640 | Drive Pinion and Ring Gear Replacement | F204200 | Holden Australia |
| 3010640 | Drive Pinion and Ring Gear Replacement | F2382 | Holden Australia |
| 3010660 | Vent Hose Replacement | F3269 | GMNA |
| 3010660 | Vent Hose Replacement | 3120300 | GMK Domestic |
| 3010660 | Vent Hose Replacement | 3141200 | GMK Domestic |
| 3010810 | Front Wheel Drive Shaft Joint Boot Shield Replacement | L2412 | GMNA |
| 3019959 | Customer Concern Not Duplicated (CCND) - Driveline/Axle | F9710 | GMNA |
| 3019959 | Customer Concern Not Duplicated (CCND) - Driveline/Axle | F9719 | GMNA |
| 3020010 | Propeller Shaft Center Support Bearing Replacement | F0040 | GMNA |
| 3020010 | Propeller Shaft Center Support Bearing Replacement | F9735 | GMNA |
| 3020010 | Propeller Shaft Center Support Bearing Replacement | F9736 | GMNA |
| 3020010 | Propeller Shaft Center Support Bearing Replacement | F004000 | Holden Australia |
| 3020010 | Propeller Shaft Center Support Bearing Replacement | F912100 | Holden Australia |
| 3020010 | Propeller Shaft Center Support Bearing Replacement | F0040 | Holden New Zealand |
| 3020010 | Propeller Shaft Center Support Bearing Replacement | F004000 | Holden New Zealand |
| 3020010 | Propeller Shaft Center Support Bearing Replacement | F912100 | Holden New Zealand |
| 3020030 | Propeller Shaft Slip Yoke Replacement | F0060 | GMNA |
| 3020030 | Propeller Shaft Slip Yoke Replacement | 3230500 | GMK Overseas |
| 3020040 | Front Propeller Shaft Coupling Replacement | | |
| 3020050 | Flexible Rear Plate Replacement | F0070 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3020070 | Universal Joint Replacement | F0091 | GMNA |
| 3020070 | Universal Joint Replacement | F1690 | GMNA |
| 3020070 | Universal Joint Replacement | F1691 | GMNA |
| 3020070 | Universal Joint Replacement | 4321300 | GMK Domestic |
| 3020090 | Front Propeller Shaft Front Universal Joint Replacement | F0092 | GMNA |
| 3020090 | Front Propeller Shaft Front Universal Joint Replacement | F1575 | GMNA |
| 3020090 | Front Propeller Shaft Front Universal Joint Replacement | E303110 | Holden Australia |
| 3020090 | Front Propeller Shaft Front Universal Joint Replacement | E303210 | Holden Australia |
| 3020090 | Front Propeller Shaft Front Universal Joint Replacement | E303410 | Holden Australia |
| 3020090 | Front Propeller Shaft Front Universal Joint Replacement | F504110 | Holden Australia |
| 3020090 | Front Propeller Shaft Front Universal Joint Replacement | F504210 | Holden Australia |
| 3020090 | Front Propeller Shaft Front Universal Joint Replacement | F908100 | Holden Australia |
| 3020090 | Front Propeller Shaft Front Universal Joint Replacement | F911100 | Holden Australia |
| 3020090 | Front Propeller Shaft Front Universal Joint Replacement | E303110 | Holden New Zealand |
| 3020090 | Front Propeller Shaft Front Universal Joint Replacement | E303210 | Holden New Zealand |
| 3020090 | Front Propeller Shaft Front Universal Joint Replacement | E303410 | Holden New Zealand |
| 3020090 | Front Propeller Shaft Front Universal Joint Replacement | F504210 | Holden New Zealand |
| 3020090 | Front Propeller Shaft Front Universal Joint Replacement | F908100 | Holden New Zealand |
| 3020110 | Front Propeller Shaft Rear Universal Joint Replacement | F0093 | GMNA |
| 3020110 | Front Propeller Shaft Rear Universal Joint Replacement | F910100 | Holden New Zealand |
| 3020160 | Rear Propeller Shaft Front Universal Joint Replacement | F1002 | GMNA |
| 3020160 | Rear Propeller Shaft Front Universal Joint Replacement | F1002 | Holden New Zealand |
| 3020160 | Rear Propeller Shaft Front Universal Joint Replacement | 3230300 | GMK Overseas |
| 3020180 | Rear Propeller Shaft Rear Universal Joint Replacement | F1003 | GMNA |
| 3020180 | Rear Propeller Shaft Rear Universal Joint Replacement | F910100 | Holden Australia |
| 3020200 | Rear Propeller Shaft Intermediate Universal Joint Replacement | F1006 | GMNA |
| 3020200 | Rear Propeller Shaft Intermediate Universal Joint Replacement | F1007 | GMNA |
| 3020200 | Rear Propeller Shaft Intermediate Universal Joint Replacement | F1006 | Holden New Zealand |
| 3020280 | Front Propeller Shaft Replacement | F1200 | GMNA |
| 3020280 | Front Propeller Shaft Replacement | F1201 | GMNA |
| 3020280 | Front Propeller Shaft Replacement | F9725 | GMNA |
| 3020280 | Front Propeller Shaft Replacement | F1200 | Holden Australia |
| 3020280 | Front Propeller Shaft Replacement | F1280 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3020280 | Front Propeller Shaft Replacement | F905100 | Holden Australia |
| 3020280 | Front Propeller Shaft Replacement | F1200 | Holden New Zealand |
| 3020280 | Front Propeller Shaft Replacement | F126000 | Holden New Zealand |
| 3020280 | Front Propeller Shaft Replacement | F905100 | Holden New Zealand |
| 3020300 | Two-Piece Propeller Shaft Replacement | F1202 | GMNA |
| 3020320 | Propeller Shaft Slip Yoke Boot Replacement | F1203 | GMNA |
| 3020320 | Propeller Shaft Slip Yoke Boot Replacement | F9723 | GMNA |
| 3020320 | Propeller Shaft Slip Yoke Boot Replacement | F9726 | GMNA |
| 3020340 | Rear Propeller Shaft Replacement | F1204 | GMNA |
| 3020340 | Rear Propeller Shaft Replacement | F9721 | GMNA |
| 3020360 | Rear Propeller Shaft Coupling Replacement | | |
| 3020410 | Propeller Shaft Replacement | F1240 | GMNA |
| 3020410 | Propeller Shaft Replacement | F1260 | GMNA |
| 3020410 | Propeller Shaft Replacement | F1280 | GMNA |
| 3020410 | Propeller Shaft Replacement | F128000 | Holden Australia |
| 3020410 | Propeller Shaft Replacement | F907100 | Holden Australia |
| 3020410 | Propeller Shaft Replacement | F1240 | Holden New Zealand |
| 3020410 | Propeller Shaft Replacement | F124000 | Holden New Zealand |
| 3020410 | Propeller Shaft Replacement | F907100 | Holden New Zealand |
| 3020410 | Propeller Shaft Replacement | 3230100 | GMK Overseas |
| 3020410 | Propeller Shaft Replacement | 3320100 | GMK Overseas |
| 3020550 | Driveline Support Replacement | F1295 | GMNA |
| 3020550 | Driveline Support Replacement | F1298 | GMNA |
| 3020550 | Driveline Support Replacement | F1300 | GMNA |
| 3029959 | Customer Concern Not Duplicated (CCND) - Driveline/Axle | | |
| 3030010 | Driveline Torque Tube Replacement | F1305 | GMNA |
| 3030010 | Driveline Torque Tube Replacement | F4001 | GMNA |
| 3030030 | Rear Axle Shaft Replacement | F1530 | GMNA |
| 3030030 | Rear Axle Shaft Replacement | F1531 | GMNA |
| 3030030 | Rear Axle Shaft Replacement | F1537 | GMNA |
| 3030030 | Rear Axle Shaft Replacement | F9729 | GMNA |
| 3030030 | Rear Axle Shaft Replacement | F9732 | GMNA |
| 3030030 | Rear Axle Shaft Replacement | 4420500 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3030030 | Rear Axle Shaft Replacement | F153100 | Holden Australia |
| 3030030 | Rear Axle Shaft Replacement | F155000 | Holden Australia |
| 3030030 | Rear Axle Shaft Replacement | F153100 | Holden New Zealand |
| 3030030 | Rear Axle Shaft Replacement | F1537 | Holden New Zealand |
| 3030050 | Rear Axle Shaft Seal Replacement - Inner | F1594 | GMNA |
| 3030050 | Rear Axle Shaft Seal Replacement - Inner | 4410700 | GMK Domestic |
| 3030050 | Rear Axle Shaft Seal Replacement - Inner | 4420100 | GMK Domestic |
| 3030070 | Output Shaft Seal Replacement | F1609 | GMNA |
| 3030070 | Output Shaft Seal Replacement | F2681 | Holden New Zealand |
| 3030090 | Rear Axle Shaft Seal Replacement - Right Side | F1610 | GMNA |
| 3030090 | Rear Axle Shaft Seal Replacement - Right Side | F1610 | Holden Australia |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F1447 | GMNA |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F1468 | GMNA |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F1595 | GMNA |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F1597 | GMNA |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F1607 | GMNA |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F1611 | GMNA |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F2006 | GMNA |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F2680 | GMNA |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F2684 | GMNA |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F9734 | GMNA |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | E200500 | Holden Australia |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | E302010 | Holden Australia |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | E302110 | Holden Australia |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | E302120 | Holden Australia |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F505000 | Holden Australia |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F505100 | Holden Australia |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F505200 | Holden Australia |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F505300 | Holden Australia |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F505400 | Holden Australia |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F505500 | Holden Australia |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | E200500 | Holden New Zealand |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | E302010 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | E302110 | Holden New Zealand |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | E302120 | Holden New Zealand |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F160100 | Holden New Zealand |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F160700 | Holden New Zealand |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F1611 | Holden New Zealand |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F505100 | Holden New Zealand |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F505300 | Holden New Zealand |
| 3030110 | Rear Axle Shaft Seal Replacement - Left Side | F505400 | Holden New Zealand |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | F1540 | GMNA |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | F1541 | GMNA |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | F1550 | GMNA |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | F1551 | GMNA |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | F1615 | GMNA |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | F3023 | GMNA |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | 4321400 | GMK Domestic |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | F201350 | Holden Australia |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | F201450 | Holden Australia |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | F504000 | Holden Australia |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | F504100 | Holden Australia |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | F504200 | Holden Australia |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | F651100 | Holden Australia |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | F1551 | Holden New Zealand |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | F201350 | Holden New Zealand |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | F201450 | Holden New Zealand |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | F504100 | Holden New Zealand |
| 3030130 | Rear Axle Shaft Seal and Rear Wheel Drive Shaft Flange Replacement | F504200 | Holden New Zealand |
| 3030180 | Rear Wheel Bearing Replacement | F1640 | GMNA |
| 3030260 | Rear Wheel Inner or Outer Bearing Replacement | F1660 | GMNA |
| 3030340 | Rear Wheel Bearing and Hub Replacement | F1664 | GMNA |
| 3030340 | Rear Wheel Bearing and Hub Replacement | 3540200 | GMK Domestic |
| 3030340 | Rear Wheel Bearing and Hub Replacement | 4420200 | GMK Domestic |
| 3030340 | Rear Wheel Bearing and Hub Replacement | 4422100 | GMK Domestic |
| 3030340 | Rear Wheel Bearing and Hub Replacement | 2318400 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3030340 | Rear Wheel Bearing and Hub Replacement | 231840A | GMK Overseas |
| 3030340 | Rear Wheel Bearing and Hub Replacement | 2318500 | GMK Overseas |
| 3030340 | Rear Wheel Bearing and Hub Replacement | 231850A | GMK Overseas |
| 3030340 | Rear Wheel Bearing and Hub Replacement | 2318600 | GMK Overseas |
| 3030360 | Rear Wheel Hub Replacement | F1665 | GMNA |
| 3030440 | Rear Axle Shaft Seal Replacement | F1617 | GMNA |
| 3030440 | Rear Axle Shaft Seal Replacement | F1670 | GMNA |
| 3030440 | Rear Axle Shaft Seal Replacement | F1671 | GMNA |
| 3030440 | Rear Axle Shaft Seal Replacement | F1672 | GMNA |
| 3030440 | Rear Axle Shaft Seal Replacement | F9714 | GMNA |
| 3030440 | Rear Axle Shaft Seal Replacement | F161100 | Holden New Zealand |
| 3030440 | Rear Axle Shaft Seal Replacement | F161700 | Holden New Zealand |
| 3030440 | Rear Axle Shaft Seal Replacement | 3311500 | GMK Overseas |
| 3030440 | Rear Axle Shaft Seal Replacement | 3311700 | GMK Overseas |
| 3030520 | Rear Axle Shaft Gasket Replacement | F1675 | GMNA |
| 3030640 | Differential Oil Cooler Inlet Hose Replacement | F1680 | GMNA |
| 3030660 | Differential Oil Pump Inlet Hose Replacement | F1681 | GMNA |
| 3030660 | Differential Oil Pump Inlet Hose Replacement | F9706 | GMNA |
| 3030660 | Differential Oil Pump Inlet Hose Replacement | F9707 | GMNA |
| 3030660 | Differential Oil Pump Inlet Hose Replacement | F9713 | GMNA |
| 3030680 | Differential Oil Cooler Replacement | F1683 | GMNA |
| 3030700 | Differential Carrier Coolant Inlet Pipe Replacement | F1684 | GMNA |
| 3030720 | Differential Oil Cooler Adapter Replacement | | |
| 3030740 | Differential Oil Cooler Outlet Hose Replacement | F1686 | GMNA |
| 3030760 | Rear Axle Housing Cover and Gasket Replacement | F2003 | GMNA |
| 3030760 | Rear Axle Housing Cover and Gasket Replacement | 3312000 | GMK Overseas |
| 3030780 | Differential Carrier Cover and Seal Replacement - Right Side | F2004 | GMNA |
| 3030780 | Differential Carrier Cover and Seal Replacement - Right Side | R753036 | GMK Overseas |
| 3030800 | Differential Carrier Cover and Seal Replacement - Left Side | F2005 | GMNA |
| 3030850 | Differential Drive Pinion Gear Yoke Replacement | F2020 | GMNA |
| 3030870 | Differential Drive Pinion Gear Seal Replacement | F2023 | GMNA |
| 3030870 | Differential Drive Pinion Gear Seal Replacement | F2023 | Holden Australia |
| 3030870 | Differential Drive Pinion Gear Seal Replacement | 5011500 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3030980 | Rear Wheel Drive Shaft Flange Replacement | F2043 | GMNA |
| 3030980 | Rear Wheel Drive Shaft Flange Replacement | 3521200 | GMK Domestic |
| 3030980 | Rear Wheel Drive Shaft Flange Replacement | F501100 | Holden Australia |
| 3031000 | Propeller Shaft Flange Replacement | F2044 | GMNA |
| 3031000 | Propeller Shaft Flange Replacement | K6263 | GMNA |
| 3031000 | Propeller Shaft Flange Replacement | K9559 | GMNA |
| 3031160 | Differential Carrier Assembly Replacement | F2143 | GMNA |
| 3031160 | Differential Carrier Assembly Replacement | K6902 | GMNA |
| 3031160 | Differential Carrier Assembly Replacement | 4420700 | GMK Domestic |
| 3031160 | Differential Carrier Assembly Replacement | E200100 | Holden Australia |
| 3031160 | Differential Carrier Assembly Replacement | F502600 | Holden Australia |
| 3031160 | Differential Carrier Assembly Replacement | E200100 | Holden New Zealand |
| 3031160 | Differential Carrier Assembly Replacement | 3310100 | GMK Overseas |
| 3031162 | Differential Carrier Overhaul | F2123 | GMNA |
| 3031162 | Differential Carrier Overhaul | F2125 | GMNA |
| 3031162 | Differential Carrier Overhaul | F2134 | GMNA |
| 3031162 | Differential Carrier Overhaul | F2135 | GMNA |
| 3031162 | Differential Carrier Overhaul | F9718 | GMNA |
| 3031162 | Differential Carrier Overhaul | F710100 | Holden Australia |
| 3031162 | Differential Carrier Overhaul | F212400 | Holden New Zealand |
| 3031162 | Differential Carrier Overhaul | F710100 | Holden New Zealand |
| 3031170 | Rear Wheel Drive Module Differential Clutch Control Module Replacement | | |
| 3031180 | Differential Carrier Bushing Replacement | F2154 | GMNA |
| 3031180 | Differential Carrier Bushing Replacement | F2240 | GMNA |
| 3031200 | Rear Differential Clutch Control Module Replacement | F2155 | GMNA |
| 3031200 | Rear Differential Clutch Control Module Replacement | F9733 | GMNA |
| 3031240 | Differential Carrier Bushing Replacement - Front | F2158 | GMNA |
| 3031260 | Differential Carrier Bushing Replacement - Rear | F2159 | GMNA |
| 3031300 | Differential Clutch Drum Assembly Replacement | F2165 | GMNA |
| 3031320 | Rear Wheel Drive Module Clutch Housing Replacement | F2166 | GMNA |
| 3031320 | Rear Wheel Drive Module Clutch Housing Replacement | 3311300 | GMK Overseas |
| 3031320 | Rear Wheel Drive Module Clutch Housing Replacement | 3316100 | GMK Overseas |
| 3031320 | Rear Wheel Drive Module Clutch Housing Replacement | 3317100 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3031340 | Limited Slip Differential Clutch Valve Replacement | F2167 | GMNA |
| 3031340 | Limited Slip Differential Clutch Valve Replacement | F2710 | GMNA |
| 3031360 | Limited Slip Differential Clutch Replacement | F2168 | GMNA |
| 3031360 | Limited Slip Differential Clutch Replacement | F502600 | Holden New Zealand |
| 3031380 | Intermediate Axle Differential Lubricant Pump Replacement | F2174 | GMNA |
| 3031400 | Differential Clutch Replacement | F2175 | GMNA |
| 3031420 | Differential Clutch Pump Replacement | F2176 | GMNA |
| 3031440 | Differential Clutch Seal Replacement | F2177 | GMNA |
| 3031460 | Differential Clutch Oil Filter Replacement | F2178 | GMNA |
| 3031460 | Differential Clutch Oil Filter Replacement | F9731 | GMNA |
| 3031510 | Locking Differential Clutch Disc Replacement | F2184 | GMNA |
| 3031560 | Electronic Locking Differential Coil Lock Replacement | F2186 | GMNA |
| 3031580 | Vehicle Speed Sensor Replacement | F2187 | GMNA |
| 3031580 | Vehicle Speed Sensor Replacement | 2611300 | GMK Domestic |
| 3031580 | Vehicle Speed Sensor Replacement | H241900 | Holden Australia |
| 3031580 | Vehicle Speed Sensor Replacement | 5812300 | GMK Overseas |
| 3031600 | Differential Case Replacement | F2223 | GMNA |
| 3031600 | Differential Case Replacement | F2223 | Holden Australia |
| 3031650 | Differential Bearing Replacement | F2263 | GMNA |
| 3031650 | Differential Bearing Replacement | 2511200 | GMK Domestic |
| 3031650 | Differential Bearing Replacement | 2511800 | GMK Domestic |
| 3031670 | Differential Drive Pinion Gear Bearing Replacement | F1651 | GMNA |
| 3031670 | Differential Drive Pinion Gear Bearing Replacement | F1657 | GMNA |
| 3031670 | Differential Drive Pinion Gear Bearing Replacement | F1661 | GMNA |
| 3031670 | Differential Drive Pinion Gear Bearing Replacement | F1662 | GMNA |
| 3031670 | Differential Drive Pinion Gear Bearing Replacement | F2183 | GMNA |
| 3031670 | Differential Drive Pinion Gear Bearing Replacement | F2283 | GMNA |
| 3031670 | Differential Drive Pinion Gear Bearing Replacement | F3030 | GMNA |
| 3031670 | Differential Drive Pinion Gear Bearing Replacement | K7650 | GMNA |
| 3031670 | Differential Drive Pinion Gear Bearing Replacement | K009820 | Holden Australia |
| 3031690 | Drive Pinion and Ring Gear Replacement | F2383 | GMNA |
| 3031890 | Differential Lock Control Valve Replacement | F2700 | GMNA |
| 3032120 | Differential Lock Switch Replacement | F2840 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3032120 | Differential Lock Switch Replacement | F2860 | GMNA |
| 3032230 | Transmission Mount Replacement | F3017 | GMNA |
| 3032310 | Rear Axle Housing Replacement | F1676 | GMNA |
| 3032310 | Rear Axle Housing Replacement | F1677 | GMNA |
| 3032310 | Rear Axle Housing Replacement | F3062 | GMNA |
| 3032310 | Rear Axle Housing Replacement | F654510 | Holden Australia |
| 3032360 | Differential Replacement | F3200 | GMNA |
| 3032360 | Differential Replacement | F9709 | GMNA |
| 3032360 | Differential Replacement | F3200 | Holden Australia |
| 3032400 | Rear Axle Replacement | F3063 | GMNA |
| 3032400 | Rear Axle Replacement | F3262 | GMNA |
| 3032400 | Rear Axle Replacement | F3263 | GMNA |
| 3032400 | Rear Axle Replacement | F9720 | GMNA |
| 3032400 | Rear Axle Replacement | 4410200 | GMK Domestic |
| 3032400 | Rear Axle Replacement | E200300 | Holden Australia |
| 3032400 | Rear Axle Replacement | F204300 | Holden Australia |
| 3032400 | Rear Axle Replacement | F650100 | Holden Australia |
| 3032400 | Rear Axle Replacement | F2043 | Holden New Zealand |
| 3032400 | Rear Axle Replacement | F204300 | Holden New Zealand |
| 3032450 | Rear Axle Vent Replacement | F3270 | GMNA |
| 3032450 | Rear Axle Vent Replacement | F327000 | Holden Australia |
| 3032450 | Rear Axle Vent Replacement | F3270 | Holden New Zealand |
| 3032450 | Rear Axle Vent Replacement | F327000 | Holden New Zealand |
| 3032470 | Differential Carrier Drain or Fill Plug Replacement | F3272 | GMNA |
| 3032470 | Differential Carrier Drain or Fill Plug Replacement | F3273 | GMNA |
| 3032550 | Limited Slip Differential Clutch High Pressure Pipe Replacement | F3280 | GMNA |
| 3032550 | Limited Slip Differential Clutch High Pressure Pipe Replacement | F654500 | Holden Australia |
| 3032550 | Limited Slip Differential Clutch High Pressure Pipe Replacement | F650100 | Holden New Zealand |
| 3032570 | Limited Slip Differential Clutch Low Pressure Pipe Replacement | C9771 | GMNA |
| 3032570 | Limited Slip Differential Clutch Low Pressure Pipe Replacement | F3281 | GMNA |
| 3032590 | Differential Temperature Sensor Replacement | N4588 | GMNA |
| 3032610 | Differential Oil Cooler Temperature Sensor Replacement | N4589 | GMNA |
| 3039959 | Customer Concern Not Duplicated (CCND) - Driveline/Axle | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3040120 | Front Wheel Drive Intermediate Shaft Replacement | F1465 | GMNA |
| 3040120 | Front Wheel Drive Intermediate Shaft Replacement | 3211600 | GMK Overseas |
| 3040170 | Front Wheel Drive Intermediate Shaft Bearing Replacement | F1469 | GMNA |
| 3040170 | Front Wheel Drive Intermediate Shaft Bearing Replacement | 5911100 | GMK Overseas |
| 3040190 | Front Wheel Drive Shaft Replacement - Right Side | F1475 | GMNA |
| 3040190 | Front Wheel Drive Shaft Replacement - Right Side | 3211100 | GMK Overseas |
| 3040190 | Front Wheel Drive Shaft Replacement - Right Side | 3211300 | GMK Overseas |
| 3040190 | Front Wheel Drive Shaft Replacement - Right Side | 3211400 | GMK Overseas |
| 3040190 | Front Wheel Drive Shaft Replacement - Right Side | 3211500 | GMK Overseas |
| 3040210 | Front Wheel Drive Shaft Replacement - Left Side | F1420 | GMNA |
| 3040210 | Front Wheel Drive Shaft Replacement - Left Side | F1421 | GMNA |
| 3040210 | Front Wheel Drive Shaft Replacement - Left Side | F1476 | GMNA |
| 3040210 | Front Wheel Drive Shaft Replacement - Left Side | F1521 | Holden New Zealand |
| 3040210 | Front Wheel Drive Shaft Replacement - Left Side | 3211200 | GMK Overseas |
| 3040210 | Front Wheel Drive Shaft Replacement - Left Side | 3211410 | GMK Overseas |
| 3040210 | Front Wheel Drive Shaft Replacement - Left Side | 3211420 | GMK Overseas |
| 3040210 | Front Wheel Drive Shaft Replacement - Left Side | 3211700 | GMK Overseas |
| 3040210 | Front Wheel Drive Shaft Replacement - Left Side | 3214300 | GMK Overseas |
| 3040210 | Front Wheel Drive Shaft Replacement - Left Side | R832016 | GMK Overseas |
| 3040210 | Front Wheel Drive Shaft Replacement - Left Side | R837037 | GMK Overseas |
| 3040210 | Front Wheel Drive Shaft Replacement - Left Side | T213430 | GMK Overseas |
| 3040230 | Rear Wheel Drive Shaft and Rear Axle Shaft Seal Replacement | F1480 | GMNA |
| 3040250 | Rear Wheel Drive Shaft Replacement | F1485 | GMNA |
| 3040250 | Rear Wheel Drive Shaft Replacement | 3221100 | GMK Overseas |
| 3040250 | Rear Wheel Drive Shaft Replacement | 3221200 | GMK Overseas |
| 3040250 | Rear Wheel Drive Shaft Replacement | 3221300 | GMK Overseas |
| 3040250 | Rear Wheel Drive Shaft Replacement | 3221500 | GMK Overseas |
| 3040630 | Intermediate Shaft Replacement | F1523 | GMNA |
| 3040630 | Intermediate Shaft Replacement | K3137 | GMNA |
| 3040630 | Intermediate Shaft Replacement | K9803 | GMNA |
| 3040830 | Front Wheel Drive Shaft Outer Joint Replacement | 4223100 | GMK Domestic |
| 3040830 | Front Wheel Drive Shaft Outer Joint Replacement | 4223200 | GMK Domestic |
| 3040850 | Front Wheel Drive Shaft Inner Joint Replacement | 3213100 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3040850 | Front Wheel Drive Shaft Inner Joint Replacement | 3213110 | GMK Overseas |
| 3040850 | Front Wheel Drive Shaft Inner Joint Replacement | 3213200 | GMK Overseas |
| 3040850 | Front Wheel Drive Shaft Inner Joint Replacement | 3213210 | GMK Overseas |
| 3040850 | Front Wheel Drive Shaft Inner Joint Replacement | 3213220 | GMK Overseas |
| 3040870 | Front Wheel Drive Shaft Seal Protector Replacement | F1565 | GMNA |
| 3040890 | Front Wheel Drive Shaft Inner Joint Boot Replacement | F1566 | GMNA |
| 3040890 | Front Wheel Drive Shaft Inner Joint Boot Replacement | 3212400 | GMK Overseas |
| 3040890 | Front Wheel Drive Shaft Inner Joint Boot Replacement | 3212410 | GMK Overseas |
| 3040890 | Front Wheel Drive Shaft Inner Joint Boot Replacement | 3212500 | GMK Overseas |
| 3040890 | Front Wheel Drive Shaft Inner Joint Boot Replacement | 3212510 | GMK Overseas |
| 3040890 | Front Wheel Drive Shaft Inner Joint Boot Replacement | 3212520 | GMK Overseas |
| 3040910 | Front Wheel Drive Shaft Outer Joint Boot Replacement | F1567 | GMNA |
| 3040910 | Front Wheel Drive Shaft Outer Joint Boot Replacement | 3212600 | GMK Overseas |
| 3040910 | Front Wheel Drive Shaft Outer Joint Boot Replacement | 3212610 | GMK Overseas |
| 3040910 | Front Wheel Drive Shaft Outer Joint Boot Replacement | 3212700 | GMK Overseas |
| 3040910 | Front Wheel Drive Shaft Outer Joint Boot Replacement | 3212710 | GMK Overseas |
| 3040910 | Front Wheel Drive Shaft Outer Joint Boot Replacement | 3212720 | GMK Overseas |
| 3040910 | Front Wheel Drive Shaft Outer Joint Boot Replacement | 3212800 | GMK Overseas |
| 3040910 | Front Wheel Drive Shaft Outer Joint Boot Replacement | 3212810 | GMK Overseas |
| 3040910 | Front Wheel Drive Shaft Outer Joint Boot Replacement | 3212900 | GMK Overseas |
| 3040910 | Front Wheel Drive Shaft Outer Joint Boot Replacement | 3212910 | GMK Overseas |
| 3040930 | Rear Wheel Drive Shaft Inner Joint Boot Replacement | F1568 | GMNA |
| 3040950 | Rear Wheel Drive Shaft Outer Joint Boot Replacement | F1569 | GMNA |
| 3040950 | Rear Wheel Drive Shaft Outer Joint Boot Replacement | F1570 | GMNA |
| 3041000 | Front Wheel Drive Shaft Inner Joint and Boot Replacement | F1576 | GMNA |
| 3041000 | Front Wheel Drive Shaft Inner Joint and Boot Replacement | F1580 | GMNA |
| 3041020 | Front Wheel Drive Shaft Outer Joint and Boot Replacement | F1581 | GMNA |
| 3041020 | Front Wheel Drive Shaft Outer Joint and Boot Replacement | 3210600 | GMK Overseas |
| 3041020 | Front Wheel Drive Shaft Outer Joint and Boot Replacement | 3210700 | GMK Overseas |
| 3041020 | Front Wheel Drive Shaft Outer Joint and Boot Replacement | 3210800 | GMK Overseas |
| 3041020 | Front Wheel Drive Shaft Outer Joint and Boot Replacement | 3210900 | GMK Overseas |
| 3041040 | Rear Wheel Drive Shaft Inner Joint and Boot Replacement | F1582 | GMNA |
| 3041040 | Rear Wheel Drive Shaft Inner Joint and Boot Replacement | F504110 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3041060 | Rear Wheel Drive Shaft Outer Joint and Boot Replacement | F1583 | GMNA |
| 3049959 | Customer Concern Not Duplicated (CCND) - Driveline/Axle | F9995 | GMNA |
| 3410010 | Active Noise Cancellation Module Replacement | R0150 | GMNA |
| 3420020 | Heater and Air Conditioning and Radio Control Module Replacement | D0369 | GMNA |
| 3420160 | Radio Antenna Replacement | R0239 | GMNA |
| 3420160 | Radio Antenna Replacement | 6120500 | GMK Domestic |
| 3420160 | Radio Antenna Replacement | 6120700 | GMK Domestic |
| 3420160 | Radio Antenna Replacement | 6122400 | GMK Domestic |
| 3420160 | Radio Antenna Replacement | R200200 | Holden Australia |
| 3420160 | Radio Antenna Replacement | R022000 | Holden New Zealand |
| 3420160 | Radio Antenna Replacement | 9290900 | GMK Overseas |
| 3420160 | Radio Antenna Replacement | 9291500 | GMK Overseas |
| 3420170 | Radio, Mobile Telephone, and Vehicle Location Antenna Cable Replacement | | |
| 3420180 | Radio Antenna Base Replacement | R0240 | GMNA |
| 3420180 | Radio Antenna Base Replacement | R200210 | Holden Australia |
| 3420180 | Radio Antenna Base Replacement | R200210 | Holden New Zealand |
| 3420180 | Radio Antenna Base Replacement | 9291000 | GMK Overseas |
| 3420180 | Radio Antenna Base Replacement | 9291600 | GMK Overseas |
| 3420180 | Radio Antenna Base Replacement | 9291700 | GMK Overseas |
| 3420180 | Radio Antenna Base Replacement | 9292300 | GMK Overseas |
| 3420180 | Radio Antenna Base Replacement | F192025 | GMK Overseas |
| 3420200 | Radio Antenna Coil Replacement | N9696 | GMNA |
| 3420200 | Radio Antenna Coil Replacement | R0245 | GMNA |
| 3420220 | Radio Antenna Coil Replacement - High Side | R0246 | GMNA |
| 3420220 | Radio Antenna Coil Replacement - High Side | 6130200 | GMK Domestic |
| 3420240 | Radio Antenna Coil Replacement - Ground Side | R0247 | GMNA |
| 3420410 | Radio Antenna Cable Replacement | R0441 | GMNA |
| 3420410 | Radio Antenna Cable Replacement | R200202 | Holden New Zealand |
| 3420410 | Radio Antenna Cable Replacement | R201505 | Holden New Zealand |
| 3420410 | Radio Antenna Cable Replacement | 9292200 | GMK Overseas |
| 3420460 | Radio Antenna Cable Extension Radio End Cable Replacement | R0508 | GMNA |
| 3420460 | Radio Antenna Cable Extension Radio End Cable Replacement | 9290400 | GMK Overseas |
| 3420480 | Radio Antenna Cable Extension Cable Connector Replacement | R0509 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3420560 | Radio Antenna Cable Extension Cable Replacement | R0514 | GMNA |
| 3420560 | Radio Antenna Cable Extension Cable Replacement | R5141 | GMNA |
| 3420560 | Radio Antenna Cable Extension Cable Replacement | 9290300 | GMK Overseas |
| 3420560 | Radio Antenna Cable Extension Cable Replacement | 9290500 | GMK Overseas |
| 3420580 | Radio Antenna Module Replacement | R0520 | GMNA |
| 3420580 | Radio Antenna Module Replacement | 6130400 | GMK Domestic |
| 3420580 | Radio Antenna Module Replacement | R0520 | Holden Australia |
| 3420580 | Radio Antenna Module Replacement | R200100 | Holden Australia |
| 3420580 | Radio Antenna Module Replacement | R200180 | Holden Australia |
| 3420580 | Radio Antenna Module Replacement | R200180 | Holden New Zealand |
| 3420580 | Radio Antenna Module Replacement | 9291800 | GMK Overseas |
| 3420600 | Radio Antenna Amplifier Replacement | R0521 | GMNA |
| 3420600 | Radio Antenna Amplifier Replacement | R5137 | GMNA |
| 3420600 | Radio Antenna Amplifier Replacement | 5822100 | GMK Domestic |
| 3420600 | Radio Antenna Amplifier Replacement | R201000 | Holden Australia |
| 3420600 | Radio Antenna Amplifier Replacement | R201000 | Holden New Zealand |
| 3420620 | Radio Antenna Diversity Module Replacement | R0522 | GMNA |
| 3420630 | Active Noise Cancellation Microphone Grille Replacement | | |
| 3420640 | Radio Volume Compensator Interior Noise Microphone Replacement | R0715 | GMNA |
| 3420660 | Communication Interface Module Microphone Replacement | R0716 | GMNA |
| 3420680 | Radio Control Switch Replacement | R0732 | GMNA |
| 3420680 | Radio Control Switch Replacement | 5822400 | GMK Domestic |
| 3420680 | Radio Control Switch Replacement | 9284900 | GMK Overseas |
| 3420700 | Radio Control Assembly Replacement | R0733 | GMNA |
| 3420700 | Radio Control Assembly Replacement | R9761 | GMNA |
| 3420700 | Radio Control Assembly Replacement | T5745 | GMNA |
| 3420700 | Radio Control Assembly Replacement | T5746 | GMNA |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | R0734 | GMNA |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | R9707 | GMNA |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | R9758 | GMNA |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | R9786 | GMNA |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | R9792 | GMNA |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | 5822500 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | N780200 | Holden Australia |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | N780250 | Holden Australia |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | N780300 | Holden Australia |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | N780350 | Holden Australia |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | N780550 | Holden Australia |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | R000281 | Holden Australia |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | R205560 | Holden Australia |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | R205670 | Holden Australia |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | R604100 | Holden Australia |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | R604200 | Holden Australia |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | N780200 | Holden New Zealand |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | N780250 | Holden New Zealand |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | N780300 | Holden New Zealand |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | N780550 | Holden New Zealand |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | R000233 | Holden New Zealand |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | R205560 | Holden New Zealand |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | R205670 | Holden New Zealand |
| 3420720 | Radio, Video, Audio Disc Player, and Navigation Information Display Replacement | R604200 | Holden New Zealand |
| 3420770 | Radio and Telephone Control Switch Replacement | R0739 | GMNA |
| 3420820 | Cruise Control and Mobile Telephone Switch Replacement | 5813600 | GMK Domestic |
| 3420820 | Cruise Control and Mobile Telephone Switch Replacement | 1821300 | GMK Overseas |
| 3420820 | Cruise Control and Mobile Telephone Switch Replacement | 6410900 | GMK Overseas |
| 3420840 | Radio Replacement | R0760 | GMNA |
| 3420840 | Radio Replacement | 5814620 | GMK Domestic |
| 3420840 | Radio Replacement | 5814700 | GMK Domestic |
| 3420840 | Radio Replacement | R0760 | Holden Australia |
| 3420840 | Radio Replacement | R03176 | Holden New Zealand |
| 3420840 | Radio Replacement | R0760 | Holden New Zealand |
| 3420840 | Radio Replacement | R201500 | Holden New Zealand |
| 3420840 | Radio Replacement | R202100A | Holden New Zealand |
| 3420840 | Radio Replacement | R205505 | Holden New Zealand |
| 3420860 | Navigation Map Data Storage Device Replacement | R0761 | GMNA |
| 3420860 | Navigation Map Data Storage Device Replacement | R5151 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3420860 | Navigation Map Data Storage Device Replacement | R9710 | GMNA |
| 3420860 | Navigation Map Data Storage Device Replacement | R9711 | GMNA |
| 3420860 | Navigation Map Data Storage Device Replacement | R9714 | GMNA |
| 3420860 | Navigation Map Data Storage Device Replacement | R9735 | GMNA |
| 3420860 | Navigation Map Data Storage Device Replacement | R9738 | GMNA |
| 3420860 | Navigation Map Data Storage Device Replacement | 6112800 | GMK Domestic |
| 3420860 | Navigation Map Data Storage Device Replacement | R000236 | Holden Australia |
| 3420860 | Navigation Map Data Storage Device Replacement | R000239 | Holden Australia |
| 3420860 | Navigation Map Data Storage Device Replacement | R000242 | Holden Australia |
| 3420860 | Navigation Map Data Storage Device Replacement | R000236 | Holden New Zealand |
| 3420860 | Navigation Map Data Storage Device Replacement | R000242 | Holden New Zealand |
| 3420860 | Navigation Map Data Storage Device Replacement | R0761 | Holden New Zealand |
| 3420880 | Radio Control Switch Replacement - Rear | R0764 | GMNA |
| 3420970 | Radio Control Module Replacement | R0799 | GMNA |
| 3420970 | Radio Control Module Replacement | R9779 | GMNA |
| 3420970 | Radio Control Module Replacement | 5822200 | GMK Domestic |
| 3420970 | Radio Control Module Replacement | 9286300 | GMK Overseas |
| 3420990 | Audio System Transceiver Module Replacement | R0800 | GMNA |
| 3421030 | Audio Disc Player Receptacle Replacement | R0802 | GMNA |
| 3421030 | Audio Disc Player Receptacle Replacement | NZE5517 | Holden New Zealand |
| 3421030 | Audio Disc Player Receptacle Replacement | 9284000 | GMK Overseas |
| 3421050 | Audio Multifunction Control Replacement | R0803 | GMNA |
| 3421050 | Audio Multifunction Control Replacement | R9767 | GMNA |
| 3421050 | Audio Multifunction Control Replacement | R9780 | GMNA |
| 3421050 | Audio Multifunction Control Replacement | 5822600 | GMK Domestic |
| 3421050 | Audio Multifunction Control Replacement | R205565 | Holden Australia |
| 3421060 | Human Machine Interface Control Module Replacement | | |
| 3421120 | Remote Compact Disc Player Replacement | R0780 | GMNA |
| 3421120 | Remote Compact Disc Player Replacement | R0833 | GMNA |
| 3421120 | Remote Compact Disc Player Replacement | R0840 | GMNA |
| 3421120 | Remote Compact Disc Player Replacement | R0842 | GMNA |
| 3421120 | Remote Compact Disc Player Replacement | R0843 | GMNA |
| 3421120 | Remote Compact Disc Player Replacement | N780600 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3421120 | Remote Compact Disc Player Replacement | N780650 | Holden Australia |
| 3421120 | Remote Compact Disc Player Replacement | N780650 | Holden New Zealand |
| 3421200 | Radio Speaker Amplifier Replacement | R0810 | GMNA |
| 3421200 | Radio Speaker Amplifier Replacement | R0865 | GMNA |
| 3421200 | Radio Speaker Amplifier Replacement | R0870 | GMNA |
| 3421200 | Radio Speaker Amplifier Replacement | R0880 | GMNA |
| 3421200 | Radio Speaker Amplifier Replacement | R0881 | GMNA |
| 3421200 | Radio Speaker Amplifier Replacement | R0883 | GMNA |
| 3421200 | Radio Speaker Amplifier Replacement | R0884 | GMNA |
| 3421200 | Radio Speaker Amplifier Replacement | R0885 | GMNA |
| 3421200 | Radio Speaker Amplifier Replacement | R0889 | GMNA |
| 3421200 | Radio Speaker Amplifier Replacement | R0890 | GMNA |
| 3421200 | Radio Speaker Amplifier Replacement | R0891 | GMNA |
| 3421200 | Radio Speaker Amplifier Replacement | R0894 | GMNA |
| 3421200 | Radio Speaker Amplifier Replacement | R0895 | GMNA |
| 3421200 | Radio Speaker Amplifier Replacement | R0896 | GMNA |
| 3421200 | Radio Speaker Amplifier Replacement | J000806 | Holden Australia |
| 3421200 | Radio Speaker Amplifier Replacement | R0883 | Holden Australia |
| 3421200 | Radio Speaker Amplifier Replacement | J000806 | Holden New Zealand |
| 3421200 | Radio Speaker Amplifier Replacement | R205700 | Holden New Zealand |
| 3421200 | Radio Speaker Amplifier Replacement | 9280810 | GMK Overseas |
| 3421200 | Radio Speaker Amplifier Replacement | 9285300 | GMK Overseas |
| 3421280 | Radio Front Side Door Upper Speaker Grille Replacement | C3271 | GMNA |
| 3421280 | Radio Front Side Door Upper Speaker Grille Replacement | R0900 | GMNA |
| 3421280 | Radio Front Side Door Upper Speaker Grille Replacement | R0901 | GMNA |
| 3421300 | Radio Front Speaker Grille Replacement | C2084 | GMNA |
| 3421300 | Radio Front Speaker Grille Replacement | R0902 | GMNA |
| 3421300 | Radio Front Speaker Grille Replacement | R0912 | GMNA |
| 3421300 | Radio Front Speaker Grille Replacement | R0918 | GMNA |
| 3421320 | Radio Front Side Door Speaker Grille Replacement | R0910 | GMNA |
| 3421320 | Radio Front Side Door Speaker Grille Replacement | R0911 | GMNA |
| 3421320 | Radio Front Side Door Speaker Grille Replacement | 8613600 | GMK Domestic |
| 3421320 | Radio Front Side Door Speaker Grille Replacement | 8613700 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3421320 | Radio Front Side Door Speaker Grille Replacement | 9351800 | GMK Overseas |
| 3421320 | Radio Front Side Door Speaker Grille Replacement | 9351900 | GMK Overseas |
| 3421320 | Radio Front Side Door Speaker Grille Replacement | 9352000 | GMK Overseas |
| 3421340 | Radio Front Center Speaker Grille Replacement | R0905 | GMNA |
| 3421340 | Radio Front Center Speaker Grille Replacement | R0906 | GMNA |
| 3421340 | Radio Front Center Speaker Grille Replacement | R0916 | GMNA |
| 3421340 | Radio Front Center Speaker Grille Replacement | R092100 | Holden Australia |
| 3421360 | Radio Rear Speaker Grille Bezel Replacement | R0917 | GMNA |
| 3421360 | Radio Rear Speaker Grille Bezel Replacement | 9361210 | GMK Overseas |
| 3421380 | Radio Body Rear Corner Upper Garnish Molding Speaker Grille Replacement | R0919 | GMNA |
| 3421400 | Radio Rear Speaker Grille Replacement | C2367 | GMNA |
| 3421400 | Radio Rear Speaker Grille Replacement | R0920 | GMNA |
| 3421400 | Radio Rear Speaker Grille Replacement | R0921 | GMNA |
| 3421400 | Radio Rear Speaker Grille Replacement | 8624900 | GMK Domestic |
| 3421400 | Radio Rear Speaker Grille Replacement | 8625000 | GMK Domestic |
| 3421400 | Radio Rear Speaker Grille Replacement | 8650100 | GMK Domestic |
| 3421400 | Radio Rear Speaker Grille Replacement | C212000 | Holden Australia |
| 3421400 | Radio Rear Speaker Grille Replacement | C212100 | Holden Australia |
| 3421400 | Radio Rear Speaker Grille Replacement | C461400 | Holden Australia |
| 3421400 | Radio Rear Speaker Grille Replacement | R092000 | Holden Australia |
| 3421400 | Radio Rear Speaker Grille Replacement | C212000 | Holden New Zealand |
| 3421400 | Radio Rear Speaker Grille Replacement | C212100 | Holden New Zealand |
| 3421400 | Radio Rear Speaker Grille Replacement | C461400 | Holden New Zealand |
| 3421400 | Radio Rear Speaker Grille Replacement | 9361200 | GMK Overseas |
| 3421400 | Radio Rear Speaker Grille Replacement | 9361220 | GMK Overseas |
| 3421400 | Radio Rear Speaker Grille Replacement | 9712100 | GMK Overseas |
| 3421400 | Radio Rear Speaker Grille Replacement | 9712200 | GMK Overseas |
| 3421400 | Radio Rear Speaker Grille Replacement | 9712300 | GMK Overseas |
| 3421420 | Radio Front Center Speaker Replacement | R0927 | GMNA |
| 3421420 | Radio Front Center Speaker Replacement | R0939 | GMNA |
| 3421420 | Radio Front Center Speaker Replacement | 8111000 | GMK Domestic |
| 3421420 | Radio Front Center Speaker Replacement | N446200 | Holden Australia |
| 3421420 | Radio Front Center Speaker Replacement | N770200 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3421420 | Radio Front Center Speaker Replacement | R211160 | Holden Australia |
| 3421420 | Radio Front Center Speaker Replacement | R211400 | Holden Australia |
| 3421420 | Radio Front Center Speaker Replacement | R211520 | Holden Australia |
| 3421420 | Radio Front Center Speaker Replacement | N770200 | Holden New Zealand |
| 3421420 | Radio Front Center Speaker Replacement | R211160 | Holden New Zealand |
| 3421440 | Radio Windshield Side Garnish Molding Speaker Replacement | R0934 | GMNA |
| 3421440 | Radio Windshield Side Garnish Molding Speaker Replacement | 6131100 | GMK Domestic |
| 3421440 | Radio Windshield Side Garnish Molding Speaker Replacement | N000589 | Holden Australia |
| 3421440 | Radio Windshield Side Garnish Molding Speaker Replacement | N000589 | Holden New Zealand |
| 3421440 | Radio Windshield Side Garnish Molding Speaker Replacement | 9283600 | GMK Overseas |
| 3421440 | Radio Windshield Side Garnish Molding Speaker Replacement | 9283700 | GMK Overseas |
| 3421440 | Radio Windshield Side Garnish Molding Speaker Replacement | 9353600 | GMK Overseas |
| 3421440 | Radio Windshield Side Garnish Molding Speaker Replacement | 9353700 | GMK Overseas |
| 3421440 | Radio Windshield Side Garnish Molding Speaker Replacement | 9353800 | GMK Overseas |
| 3421460 | Radio Front Side Door Upper Speaker Replacement | R0937 | GMNA |
| 3421540 | Radio Front Side Door Speaker Replacement | R0930 | GMNA |
| 3421540 | Radio Front Side Door Speaker Replacement | R0942 | GMNA |
| 3421540 | Radio Front Side Door Speaker Replacement | R0968 | GMNA |
| 3421540 | Radio Front Side Door Speaker Replacement | R0937 | Holden Australia |
| 3421540 | Radio Front Side Door Speaker Replacement | R211600 | Holden Australia |
| 3421540 | Radio Front Side Door Speaker Replacement | R211700 | Holden Australia |
| 3421540 | Radio Front Side Door Speaker Replacement | R0937 | Holden New Zealand |
| 3421540 | Radio Front Side Door Speaker Replacement | R094100 | Holden New Zealand |
| 3421540 | Radio Front Side Door Speaker Replacement | R211600 | Holden New Zealand |
| 3421540 | Radio Front Side Door Speaker Replacement | R212320 | Holden New Zealand |
| 3421540 | Radio Front Side Door Speaker Replacement | 9280300 | GMK Overseas |
| 3421540 | Radio Front Side Door Speaker Replacement | 9280400 | GMK Overseas |
| 3421540 | Radio Front Side Door Speaker Replacement | 9280500 | GMK Overseas |
| 3421590 | Radio Front Side Door Lower Speaker Replacement | R0944 | GMNA |
| 3421640 | Radio Front Speaker Replacement | N6285 | GMNA |
| 3421640 | Radio Front Speaker Replacement | R0946 | GMNA |
| 3421640 | Radio Front Speaker Replacement | R5125 | GMNA |
| 3421640 | Radio Front Speaker Replacement | R9747 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3421640 | Radio Front Speaker Replacement | R9760 | GMNA |
| 3421640 | Radio Front Speaker Replacement | R9764 | GMNA |
| 3421640 | Radio Front Speaker Replacement | R9766 | GMNA |
| 3421640 | Radio Front Speaker Replacement | R9773 | GMNA |
| 3421640 | Radio Front Speaker Replacement | 6130800 | GMK Domestic |
| 3421640 | Radio Front Speaker Replacement | R211100 | Holden Australia |
| 3421640 | Radio Front Speaker Replacement | R211150 | Holden Australia |
| 3421640 | Radio Front Speaker Replacement | R211100 | Holden New Zealand |
| 3421640 | Radio Front Speaker Replacement | R211150 | Holden New Zealand |
| 3421640 | Radio Front Speaker Replacement | 9280200 | GMK Overseas |
| 3421660 | Radio Front Floor Console Speaker Replacement | R0947 | GMNA |
| 3421740 | Radio Rear Side Door Speaker Replacement | R0950 | GMNA |
| 3421740 | Radio Rear Side Door Speaker Replacement | 6132100 | GMK Domestic |
| 3421740 | Radio Rear Side Door Speaker Replacement | N000801 | Holden Australia |
| 3421740 | Radio Rear Side Door Speaker Replacement | R0950 | Holden Australia |
| 3421740 | Radio Rear Side Door Speaker Replacement | R211650 | Holden Australia |
| 3421740 | Radio Rear Side Door Speaker Replacement | R213300 | Holden Australia |
| 3421740 | Radio Rear Side Door Speaker Replacement | R0752 | Holden New Zealand |
| 3421740 | Radio Rear Side Door Speaker Replacement | R095000 | Holden New Zealand |
| 3421740 | Radio Rear Side Door Speaker Replacement | R095100 | Holden New Zealand |
| 3421740 | Radio Rear Side Door Speaker Replacement | R211650 | Holden New Zealand |
| 3421740 | Radio Rear Side Door Speaker Replacement | R213300 | Holden New Zealand |
| 3421740 | Radio Rear Side Door Speaker Replacement | 9282400 | GMK Overseas |
| 3421740 | Radio Rear Side Door Speaker Replacement | 9282500 | GMK Overseas |
| 3421740 | Radio Rear Side Door Speaker Replacement | 9282600 | GMK Overseas |
| 3421790 | Radio Rear Compartment Speaker Replacement | R0935 | GMNA |
| 3421790 | Radio Rear Compartment Speaker Replacement | R0952 | GMNA |
| 3421790 | Radio Rear Compartment Speaker Replacement | 9280600 | GMK Overseas |
| 3421790 | Radio Rear Compartment Speaker Replacement | 9280700 | GMK Overseas |
| 3421790 | Radio Rear Compartment Speaker Replacement | 9280800 | GMK Overseas |
| 3421790 | Radio Rear Compartment Speaker Replacement | 9281200 | GMK Overseas |
| 3421840 | Rear Liftgate Speaker Replacement | R0954 | GMNA |
| 3421890 | Driver or Passenger Seat Head Restraint Speaker Replacement | R0956 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3422030 | Radio Rear Speaker Replacement | R0958 | GMNA |
| 3422030 | Radio Rear Speaker Replacement | R0959 | GMNA |
| 3422030 | Radio Rear Speaker Replacement | R0964 | GMNA |
| 3422030 | Radio Rear Speaker Replacement | R9709 | GMNA |
| 3422030 | Radio Rear Speaker Replacement | 6132200 | GMK Domestic |
| 3422030 | Radio Rear Speaker Replacement | 6132300 | GMK Domestic |
| 3422030 | Radio Rear Speaker Replacement | R211750 | Holden Australia |
| 3422030 | Radio Rear Speaker Replacement | 9280900 | GMK Overseas |
| 3422030 | Radio Rear Speaker Replacement | 9281000 | GMK Overseas |
| 3422050 | Radio Rear Side Door Upper Speaker Replacement | R0965 | GMNA |
| 3422050 | Radio Rear Side Door Upper Speaker Replacement | 9361600 | GMK Overseas |
| 3422050 | Radio Rear Side Door Upper Speaker Replacement | 9361610 | GMK Overseas |
| 3422050 | Radio Rear Side Door Upper Speaker Replacement | 9361620 | GMK Overseas |
| 3422070 | Radio Rear Side Door Lower Speaker Replacement | R0966 | GMNA |
| 3422090 | Radio Rear Corner Upper Garnish Molding Speaker Replacement | R0967 | GMNA |
| 3422110 | Radio Rear Quarter Trim Panel Speaker Replacement | R0971 | GMNA |
| 3422130 | Radio Roof Speaker Replacement | C9803 | GMNA |
| 3422130 | Radio Roof Speaker Replacement | R0973 | GMNA |
| 3422130 | Radio Roof Speaker Replacement | R9782 | GMNA |
| 3422130 | Radio Roof Speaker Replacement | R9784 | GMNA |
| 3422130 | Radio Roof Speaker Replacement | R9789 | GMNA |
| 3422130 | Radio Roof Speaker Replacement | R9791 | GMNA |
| 3422130 | Radio Roof Speaker Replacement | R9800 | GMNA |
| 3422130 | Radio Roof Speaker Replacement | R9804 | GMNA |
| 3422130 | Radio Roof Speaker Replacement | R9806 | GMNA |
| 3422130 | Radio Roof Speaker Replacement | 5540300 | GMK Domestic |
| 3422190 | Personal Message Player/Recorder Replacement | R4660 | GMNA |
| 3422230 | Mobile Telephone and Navigation Power Supply Transformer Replacement | R5090 | GMNA |
| 3422250 | Traffic Information Receiver Replacement | R5104 | GMNA |
| 3422270 | Navigation Interface Module Replacement | 6110600 | GMK Domestic |
| 3422270 | Navigation Interface Module Replacement | 9283500 | GMK Overseas |
| 3422290 | Navigation Antenna Coaxial Cable Replacement | R5106 | GMNA |
| 3422310 | Navigation and Traffic Data Antenna Replacement | R5107 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3422310 | Navigation and Traffic Data Antenna Replacement | R9176 | GMNA |
| 3422310 | Navigation and Traffic Data Antenna Replacement | R9177 | GMNA |
| 3422310 | Navigation and Traffic Data Antenna Replacement | R9178 | GMNA |
| 3422310 | Navigation and Traffic Data Antenna Replacement | N735202 | Holden Australia |
| 3422310 | Navigation and Traffic Data Antenna Replacement | N934902 | Holden Australia |
| 3422310 | Navigation and Traffic Data Antenna Replacement | R604150 | Holden Australia |
| 3422310 | Navigation and Traffic Data Antenna Replacement | R604150 | Holden New Zealand |
| 3422330 | Television Antenna Cable Replacement | R5108 | GMNA |
| 3422350 | Television Antenna Module Replacement | R5109 | GMNA |
| 3422400 | Mobile Telephone Antenna Replacement | R5111 | GMNA |
| 3422420 | Mobile Telephone Antenna Base Replacement | R5112 | GMNA |
| 3422440 | Mobile Telephone Microphone Replacement | R5114 | GMNA |
| 3422440 | Mobile Telephone Microphone Replacement | N000536 | Holden Australia |
| 3422440 | Mobile Telephone Microphone Replacement | N446050 | Holden Australia |
| 3422440 | Mobile Telephone Microphone Replacement | N780060 | Holden Australia |
| 3422440 | Mobile Telephone Microphone Replacement | R5114 | Holden Australia |
| 3422440 | Mobile Telephone Microphone Replacement | N446050 | Holden New Zealand |
| 3422440 | Mobile Telephone Microphone Replacement | N780060 | Holden New Zealand |
| 3422440 | Mobile Telephone Microphone Replacement | 9294200 | GMK Overseas |
| 3422460 | Mobile Telephone Control Module Replacement | R5115 | GMNA |
| 3422460 | Mobile Telephone Control Module Replacement | 9284800 | GMK Overseas |
| 3422510 | Communication Module Antenna Replacement | | |
| 3422530 | Mobile Telephone and Vehicle Location Antenna Replacement | R5119 | GMNA |
| 3422580 | Mobile Telephone Digital Antenna Replacement | R5121 | GMNA |
| 3422580 | Mobile Telephone Digital Antenna Replacement | N446300 | Holden Australia |
| 3422580 | Mobile Telephone Digital Antenna Replacement | N446300 | Holden New Zealand |
| 3422600 | Mobile Telephone and Vehicle Location Antenna Base Replacement | R5122 | GMNA |
| 3422620 | Digital Radio, Mobile Telephone, and Vehicle Location Antenna Replacement | R5123 | GMNA |
| 3422620 | Digital Radio, Mobile Telephone, and Vehicle Location Antenna Replacement | R5123 | Holden Australia |
| 3422640 | Digital Radio, Mobile Telephone, and Vehicle Location Base Replacement | R5124 | GMNA |
| 3422660 | Mobile Telephone Antenna Coaxial Cable Replacement | R5130 | GMNA |
| 3422660 | Mobile Telephone Antenna Coaxial Cable Replacement | R5132 | GMNA |
| 3422660 | Mobile Telephone Antenna Coaxial Cable Replacement | 8110500 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3422660 | Mobile Telephone Antenna Coaxial Cable Replacement | 9294500 | GMK Overseas |
| 3422680 | Mobile Telephone and Navigation Antenna Coaxial Cable Replacement | R5133 | GMNA |
| 3422700 | Digital Radio, Mobile Telephone, and Vehicle Location Antenna Cable Replacement | R5135 | GMNA |
| 3422700 | Digital Radio, Mobile Telephone, and Vehicle Location Antenna Cable Replacement | 6134000 | GMK Domestic |
| 3422720 | Electronic Navigation Antenna Replacement | R5139 | GMNA |
| 3422770 | Communication Interface Module Battery Replacement | N4197 | GMNA |
| 3422770 | Communication Interface Module Battery Replacement | N5872 | GMNA |
| 3422770 | Communication Interface Module Battery Replacement | R5142 | GMNA |
| 3422770 | Communication Interface Module Battery Replacement | RTA01 | GMNA |
| 3422770 | Communication Interface Module Battery Replacement | N000402 | Holden Australia |
| 3422770 | Communication Interface Module Battery Replacement | N446100 | Holden Australia |
| 3422790 | Communication Interface Module Replacement | R4143 | GMNA |
| 3422790 | Communication Interface Module Replacement | R5143 | GMNA |
| 3422790 | Communication Interface Module Replacement | R9717 | GMNA |
| 3422790 | Communication Interface Module Replacement | R9787 | GMNA |
| 3422790 | Communication Interface Module Replacement | N000408 | Holden Australia |
| 3422790 | Communication Interface Module Replacement | N446000 | Holden Australia |
| 3422790 | Communication Interface Module Replacement | N446000 | Holden New Zealand |
| 3422840 | Mobile Telephone Local Interface Module Replacement | R5146 | GMNA |
| 3422860 | Wireless Communication Interface Antenna Replacement | R5147 | GMNA |
| 3422860 | Wireless Communication Interface Antenna Replacement | R9810 | GMNA |
| 3422860 | Wireless Communication Interface Antenna Replacement | N780055 | Holden Australia |
| 3422860 | Wireless Communication Interface Antenna Replacement | N780055 | Holden New Zealand |
| 3422860 | Wireless Communication Interface Antenna Replacement | R000278 | Holden New Zealand |
| 3422930 | Navigation Signal Splitter Replacement | R5154 | GMNA |
| 3422950 | Navigation Information Display Bezel Replacement | R5155 | GMNA |
| 3422970 | Radio, Video, Audio Disc Player, and Navigation Information Display Actuator Replacement | R5156 | GMNA |
| 3422990 | Navigation Information Display Opening Cover Replacement | | |
| 3423010 | Mobile Telephone Base Replacement | R5158 | GMNA |
| 3423030 | Navigation Map Interface Module Receptacle Opening Cover Replacement | R5150 | GMNA |
| 3423030 | Navigation Map Interface Module Receptacle Opening Cover Replacement | R5159 | GMNA |
| 3423030 | Navigation Map Interface Module Receptacle Opening Cover Replacement | R604300 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3423030 | Navigation Map Interface Module Receptacle Opening Cover Replacement | R604310 | Holden Australia |
| 3423030 | Navigation Map Interface Module Receptacle Opening Cover Replacement | R604100 | Holden New Zealand |
| 3423030 | Navigation Map Interface Module Receptacle Opening Cover Replacement | R604300 | Holden New Zealand |
| 3423030 | Navigation Map Interface Module Receptacle Opening Cover Replacement | R604310 | Holden New Zealand |
| 3423050 | Communication Center Call Switch Replacement | R5498 | GMNA |
| 3423050 | Communication Center Call Switch Replacement | N780050 | Holden Australia |
| 3423050 | Communication Center Call Switch Replacement | N780050 | Holden New Zealand |
| 3423060 | Communication Center Call Transceiver Replacement | R5499 | GMNA |
| 3423070 | Digital Radio Antenna and Navigation Antenna Coaxial Cable Replacement | R5503 | GMNA |
| 3423090 | Navigation Information Display Replacement | | |
| 3423110 | Television Antenna Amplifier Replacement | R5518 | GMNA |
| 3423110 | Television Antenna Amplifier Replacement | 6122500 | GMK Domestic |
| 3423110 | Television Antenna Amplifier Replacement | 6130100 | GMK Domestic |
| 3423150 | Video Disc Player Replacement | C2560 | GMNA |
| 3423150 | Video Disc Player Replacement | R0770 | GMNA |
| 3423150 | Video Disc Player Replacement | R0772 | GMNA |
| 3423150 | Video Disc Player Replacement | R0773 | GMNA |
| 3423150 | Video Disc Player Replacement | R5520 | GMNA |
| 3423150 | Video Disc Player Replacement | R9736 | GMNA |
| 3423150 | Video Disc Player Replacement | R9796 | GMNA |
| 3423150 | Video Disc Player Replacement | R9802 | GMNA |
| 3423150 | Video Disc Player Replacement | 5823100 | GMK Domestic |
| 3423150 | Video Disc Player Replacement | 6110100 | GMK Domestic |
| 3423150 | Video Disc Player Replacement | N780100 | Holden Australia |
| 3423150 | Video Disc Player Replacement | N780150 | Holden Australia |
| 3423150 | Video Disc Player Replacement | R000124 | Holden Australia |
| 3423150 | Video Disc Player Replacement | R000128 | Holden Australia |
| 3423150 | Video Disc Player Replacement | R075100 | Holden Australia |
| 3423150 | Video Disc Player Replacement | R076100 | Holden Australia |
| 3423150 | Video Disc Player Replacement | R205500 | Holden Australia |
| 3423150 | Video Disc Player Replacement | R205505 | Holden Australia |
| 3423150 | Video Disc Player Replacement | R205510 | Holden Australia |
| 3423150 | Video Disc Player Replacement | R205540 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3423150 | Video Disc Player Replacement | R205650 | Holden Australia |
| 3423150 | Video Disc Player Replacement | N780100 | Holden New Zealand |
| 3423150 | Video Disc Player Replacement | N780100A1 | Holden New Zealand |
| 3423150 | Video Disc Player Replacement | N780150 | Holden New Zealand |
| 3423150 | Video Disc Player Replacement | R000124 | Holden New Zealand |
| 3423150 | Video Disc Player Replacement | R000128 | Holden New Zealand |
| 3423150 | Video Disc Player Replacement | R0751 | Holden New Zealand |
| 3423150 | Video Disc Player Replacement | R205500 | Holden New Zealand |
| 3423150 | Video Disc Player Replacement | R205540 | Holden New Zealand |
| 3423150 | Video Disc Player Replacement | R205650 | Holden New Zealand |
| 3423150 | Video Disc Player Replacement | 9283300 | GMK Overseas |
| 3423170 | Audio/Video Disc Player Adapter Replacement | R5521 | GMNA |
| 3423190 | Audio Disc Player and USB Receptacle Replacement | R5522 | GMNA |
| 3423190 | Audio Disc Player and USB Receptacle Replacement | 9285400 | GMK Overseas |
| 3423210 | Audio and Video Module Cable Replacement | R5523 | GMNA |
| 3423210 | Audio and Video Module Cable Replacement | 6130300 | GMK Domestic |
| 3423210 | Audio and Video Module Cable Replacement | 9286500 | GMK Overseas |
| 3423230 | Digital Video Antenna Cable Replacement | R5524 | GMNA |
| 3423250 | Video Disc Player Bezel Replacement | | |
| 3423330 | Multimedia Player Interface Module Replacement | R5537 | GMNA |
| 3423330 | Multimedia Player Interface Module Replacement | N340260 | Holden Australia |
| 3423330 | Multimedia Player Interface Module Replacement | N340260 | Holden New Zealand |
| 3423350 | USB Receptacle Replacement | R5538 | GMNA |
| 3423350 | USB Receptacle Replacement | R9788 | GMNA |
| 3423350 | USB Receptacle Replacement | R553800 | Holden Australia |
| 3423350 | USB Receptacle Replacement | R553800 | Holden New Zealand |
| 3423370 | Audio Disc Player, USB, Auxiliary In, and Memory Card Receptacle Replacement | R5539 | GMNA |
| 3423420 | Video Display Replacement | R5554 | GMNA |
| 3423420 | Video Display Replacement | R9768 | GMNA |
| 3423420 | Video Display Replacement | 6000930 | GMK Domestic |
| 3423420 | Video Display Replacement | 6110120 | GMK Domestic |
| 3423420 | Video Display Replacement | 6110900 | GMK Domestic |
| 3423420 | Video Display Replacement | N326500 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3423420 | Video Display Replacement | N326510 | Holden Australia |
| 3423420 | Video Display Replacement | R000233 | Holden Australia |
| 3423420 | Video Display Replacement | N220000 | Holden New Zealand |
| 3423420 | Video Display Replacement | N326500 | Holden New Zealand |
| 3423420 | Video Display Replacement | N326510 | Holden New Zealand |
| 3423420 | Video Display Replacement | 9292700 | GMK Overseas |
| 3423490 | Auxiliary Audio/Video Input Control Replacement | R5561 | GMNA |
| 3423510 | Audio/Video Interface Module Replacement | R5562 | GMNA |
| 3423510 | Audio/Video Interface Module Replacement | N780120 | Holden Australia |
| 3423510 | Audio/Video Interface Module Replacement | N780400 | Holden Australia |
| 3423510 | Audio/Video Interface Module Replacement | N780120 | Holden New Zealand |
| 3423510 | Audio/Video Interface Module Replacement | N780400 | Holden New Zealand |
| 3423530 | Headphone Connector Receptacle Replacement | | |
| 3423550 | Headphone Replacement | R5570 | GMNA |
| 3423550 | Headphone Replacement | R213399 | Holden Australia |
| 3423550 | Headphone Replacement | R213399 | Holden New Zealand |
| 3423660 | Digital Radio Receiver Replacement | N9608 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R0736 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R0737 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R0738 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R0750 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R0753 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R0754 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R0755 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R0756 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R0757 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R0758 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R0762 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R0763 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R0766 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R0767 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R0768 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R0774 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3423660 | Digital Radio Receiver Replacement | R0775 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R0776 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R5600 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R5650 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R5651 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | R5652 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | T5747 | GMNA |
| 3423660 | Digital Radio Receiver Replacement | 5512000 | GMK Domestic |
| 3423660 | Digital Radio Receiver Replacement | R075000 | Holden Australia |
| 3423660 | Digital Radio Receiver Replacement | R5600 | Holden Australia |
| 3423660 | Digital Radio Receiver Replacement | R0750 | Holden New Zealand |
| 3423680 | Digital Radio Antenna Cable Replacement | R5602 | GMNA |
| 3423680 | Digital Radio Antenna Cable Replacement | R9785 | GMNA |
| 3423680 | Digital Radio Antenna Cable Replacement | R200600 | Holden New Zealand |
| 3423700 | Digital Radio Transceiver Module Antenna Replacement | R5603 | GMNA |
| 3423720 | Digital Radio Antenna Replacement | R5604 | GMNA |
| 3429919 | Customer Concern Not Duplicated (CCND) - OnStar®/Bluetooth | N9991 | GMNA |
| 3429919 | Customer Concern Not Duplicated (CCND) - OnStar®/Bluetooth | R000278 | Holden Australia |
| 3429969 | Customer Concern Not Duplicated (CCND) - Entertainment/Radio/Navigation/USB | N9996 | GMNA |
| 3429969 | Customer Concern Not Duplicated (CCND) - Entertainment/Radio/Navigation/USB | 5814000 | GMK Domestic |
| 3430010 | Instrument Cluster Bulb Replacement | N0405 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | N0460 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | N0510 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | N0525 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | N0550 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | N0600 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | N0605 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | N0627 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | N0629 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | N0647 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | N0710 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | N0770 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | N0815 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3430010 | Instrument Cluster Bulb Replacement | N0830 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | N0840 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | N2812 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | N2926 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | N4105 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | N8500 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | T1786 | GMNA |
| 3430010 | Instrument Cluster Bulb Replacement | 5520500 | GMK Domestic |
| 3430010 | Instrument Cluster Bulb Replacement | 5710200 | GMK Domestic |
| 3430010 | Instrument Cluster Bulb Replacement | N062700 | Holden Australia |
| 3430010 | Instrument Cluster Bulb Replacement | N221970 | Holden Australia |
| 3430010 | Instrument Cluster Bulb Replacement | N221980 | Holden Australia |
| 3430010 | Instrument Cluster Bulb Replacement | N501550 | Holden Australia |
| 3430010 | Instrument Cluster Bulb Replacement | N712606 | Holden Australia |
| 3430010 | Instrument Cluster Bulb Replacement | N0627 | Holden New Zealand |
| 3430010 | Instrument Cluster Bulb Replacement | N062700 | Holden New Zealand |
| 3430010 | Instrument Cluster Bulb Replacement | N0647 | Holden New Zealand |
| 3430010 | Instrument Cluster Bulb Replacement | N115530 | Holden New Zealand |
| 3430010 | Instrument Cluster Bulb Replacement | N220010 | Holden New Zealand |
| 3430010 | Instrument Cluster Bulb Replacement | N221970 | Holden New Zealand |
| 3430010 | Instrument Cluster Bulb Replacement | N221980 | Holden New Zealand |
| 3430010 | Instrument Cluster Bulb Replacement | 9251700 | GMK Overseas |
| 3430090 | Multifunction Chime Alarm Replacement | N1890 | GMNA |
| 3430090 | Multifunction Chime Alarm Replacement | N4846 | GMNA |
| 3430090 | Multifunction Chime Alarm Replacement | N4847 | GMNA |
| 3430090 | Multifunction Chime Alarm Replacement | N6368 | GMNA |
| 3430140 | Accessory Switch Replacement | N1896 | GMNA |
| 3430140 | Accessory Switch Replacement | N2029 | GMNA |
| 3430280 | Driver Information Display Switch Replacement | N2068 | GMNA |
| 3430280 | Driver Information Display Switch Replacement | N2160 | GMNA |
| 3430280 | Driver Information Display Switch Replacement | N4174 | GMNA |
| 3430280 | Driver Information Display Switch Replacement | N4177 | GMNA |
| 3430280 | Driver Information Display Switch Replacement | N4178 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3430280 | Driver Information Display Switch Replacement | R4048 | GMNA |
| 3430280 | Driver Information Display Switch Replacement | 5721000 | GMK Domestic |
| 3430420 | Instrument Panel Multifunction Switch Replacement | 9324800 | GMK Overseas |
| 3430440 | Front Floor Console Multifunction Switch Replacement | N2356 | GMNA |
| 3430820 | Instrument Cluster Lens Replacement | N4115 | GMNA |
| 3430820 | Instrument Cluster Lens Replacement | N4130 | GMNA |
| 3430820 | Instrument Cluster Lens Replacement | N300600 | Holden Australia |
| 3430820 | Instrument Cluster Lens Replacement | N300600 | Holden New Zealand |
| 3430820 | Instrument Cluster Lens Replacement | 9250100 | GMK Overseas |
| 3430840 | Instrument Cluster Molding Replacement | N4116 | GMNA |
| 3430890 | Battery Charge Indicator Replacement | N4168 | GMNA |
| 3430910 | Driver Information Display and Multifunction Switch Replacement | N4169 | GMNA |
| 3430990 | Driver Information Display Replacement | N4173 | GMNA |
| 3431010 | Fuel Economy Indicator Switch Replacement | N4175 | GMNA |
| 3431010 | Fuel Economy Indicator Switch Replacement | R4175 | GMNA |
| 3431010 | Fuel Economy Indicator Switch Replacement | K500120 | Holden Australia |
| 3431010 | Fuel Economy Indicator Switch Replacement | K500120 | Holden New Zealand |
| 3431030 | Instrument Cluster Replacement | N4180 | GMNA |
| 3431030 | Instrument Cluster Replacement | N4186 | GMNA |
| 3431030 | Instrument Cluster Replacement | N4187 | GMNA |
| 3431030 | Instrument Cluster Replacement | N4188 | GMNA |
| 3431030 | Instrument Cluster Replacement | N4189 | GMNA |
| 3431030 | Instrument Cluster Replacement | N4195 | GMNA |
| 3431030 | Instrument Cluster Replacement | N4260 | GMNA |
| 3431030 | Instrument Cluster Replacement | 6140500 | GMK Domestic |
| 3431030 | Instrument Cluster Replacement | 6140600 | GMK Domestic |
| 3431030 | Instrument Cluster Replacement | C234000 | Holden Australia |
| 3431030 | Instrument Cluster Replacement | C247000 | Holden Australia |
| 3431030 | Instrument Cluster Replacement | N307500 | Holden Australia |
| 3431030 | Instrument Cluster Replacement | N312600 | Holden Australia |
| 3431030 | Instrument Cluster Replacement | N312710 | Holden Australia |
| 3431030 | Instrument Cluster Replacement | N4180 | Holden Australia |
| 3431030 | Instrument Cluster Replacement | N439900 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3431030 | Instrument Cluster Replacement | N452000 | Holden Australia |
| 3431030 | Instrument Cluster Replacement | C247000 | Holden New Zealand |
| 3431030 | Instrument Cluster Replacement | N312600 | Holden New Zealand |
| 3431030 | Instrument Cluster Replacement | N312710 | Holden New Zealand |
| 3431030 | Instrument Cluster Replacement | N439900 | Holden New Zealand |
| 3431030 | Instrument Cluster Replacement | 9250300 | GMK Overseas |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N4181 | GMNA |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | 6220100 | GMK Domestic |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N900287 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N900460 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N900525 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N900567 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N900568 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N900571 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N900719 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N900724 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N900976 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N900980 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N901000 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N901001 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N901002 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N901020 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N901304 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N901424 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N901485 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N901500 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N901565 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N901600 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N901605 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N901640 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N901722 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902101 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902102 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902103 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902105 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902106 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902108 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902116 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902139 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902201 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902525 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902535 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902555 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902585 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902657 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902662 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902698 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902740 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902961 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902966 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N903057 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N903058 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N903107 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N903109 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N903114 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N903115 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N903135 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N903140 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N903150 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N903225 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N903440 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N903445 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N903485 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N903596 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909000 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909001 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909002 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909003 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909004 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909005 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909006 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909007 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909008 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909009 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909010 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909011 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909012 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909013 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909014 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909015 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909016 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909017 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909018 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909019 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909020 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909021 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909022 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909024 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909025 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909026 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909029 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909031 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909046 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909051 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909052 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909055 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909070 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909071 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909072 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909073 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909082 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909087 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909094 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909095 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909100 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909101 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909107 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909117 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909121 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909126 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909128 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909139 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909149 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909155 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909159 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909164 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909165 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909166 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909167 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909168 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909169 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909171 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909173 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909174 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909177 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909179 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909184 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909192 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909193 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909197 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909283 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909299 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909420 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909423 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909460 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909550 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909562 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909567 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909575 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909621 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909670 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909806 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909810 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909996 | Holden Australia |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N900404 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N900567 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N900568 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N901000 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N901001 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N901020 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N901565 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902105 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902116 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902139 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902201 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902535 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N902966 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N903114 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N903445 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909000 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909001 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909008 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909011 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909016 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909018 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909024 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909052 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909100 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909101 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909126 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909139 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909155 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909159 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909184 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909299 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909422 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909621 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N909806 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N990061 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N990063 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N999001 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N999002 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N999007 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N999008 | Holden New Zealand |
| 3431050 | Instrument Cluster Indicator Lamp Replacement | N999053 | Holden New Zealand |
| 3431130 | Clock Replacement | N4200 | GMNA |
| 3431130 | Clock Replacement | N4210 | GMNA |
| 3431130 | Clock Replacement | 6424600 | GMK Domestic |
| 3431130 | Clock Replacement | 6424700 | GMK Domestic |
| 3431130 | Clock Replacement | N308500 | Holden Australia |
| 3431130 | Clock Replacement | N420000 | Holden Australia |
| 3431130 | Clock Replacement | N421000 | Holden Australia |
| 3431130 | Clock Replacement | N478000 | Holden Australia |
| 3431130 | Clock Replacement | N308500 | Holden New Zealand |
| 3431130 | Clock Replacement | N420000 | Holden New Zealand |
| 3431130 | Clock Replacement | N421000 | Holden New Zealand |
| 3431130 | Clock Replacement | 9320600 | GMK Overseas |
| 3431130 | Clock Replacement | 932060A | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3431240 | Speedometer Replacement | N4183 | GMNA |
| 3431240 | Speedometer Replacement | N4310 | GMNA |
| 3431240 | Speedometer Replacement | N6475 | GMNA |
| 3431240 | Speedometer Replacement | N300500 | Holden Australia |
| 3431240 | Speedometer Replacement | HSVECM1 | Holden New Zealand |
| 3431240 | Speedometer Replacement | N4410 | Holden New Zealand |
| 3431240 | Speedometer Replacement | 9250500 | GMK Overseas |
| 3431240 | Speedometer Replacement | 925050A | GMK Overseas |
| 3431350 | Tachometer Replacement | N4510 | GMNA |
| 3431350 | Tachometer Replacement | N4530 | GMNA |
| 3431350 | Tachometer Replacement | N4540 | GMNA |
| 3431350 | Tachometer Replacement | N4560 | GMNA |
| 3431350 | Tachometer Replacement | N310500 | Holden Australia |
| 3431350 | Tachometer Replacement | N326500A1 | Holden New Zealand |
| 3431350 | Tachometer Replacement | 9250700 | GMK Overseas |
| 3431390 | Turbocharger Pressure Power Indicator Replacement | N4514 | GMNA |
| 3431500 | Inside Air Temperature Sensor Replacement | J0758 | GMNA |
| 3431500 | Inside Air Temperature Sensor Replacement | N4629 | GMNA |
| 3431520 | Multifunction Auxiliary Gauge Replacement | N4639 | GMNA |
| 3431570 | Fuel Gauge Replacement | N4660 | GMNA |
| 3431570 | Fuel Gauge Replacement | N4680 | GMNA |
| 3431570 | Fuel Gauge Replacement | 6220500 | GMK Domestic |
| 3431570 | Fuel Gauge Replacement | 6220600 | GMK Domestic |
| 3431570 | Fuel Gauge Replacement | N301500 | Holden Australia |
| 3431570 | Fuel Gauge Replacement | 9251100 | GMK Overseas |
| 3431680 | Electronic Compass Module Replacement | N4819 | GMNA |
| 3431810 | Head-Up Display Replacement | N6295 | GMNA |
| 3431810 | Head-Up Display Replacement | R3100 | GMNA |
| 3431810 | Head-Up Display Replacement | R3102 | GMNA |
| 3431830 | Head-Up Display Dimmer Switch Replacement | R3105 | GMNA |
| 3432010 | Ambient Air Temperature Sensor Replacement | 8220702 | GMK Domestic |
| 3432030 | Ambient Air Temperature Gauge Sensor Replacement | | |
| 3432050 | Information Center Telltale Assembly Replacement | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 3439929 | Customer Concern Not Duplicated (CCND) - Cluster/Head Up Display | N9992 | GMNA |
| 3439929 | Customer Concern Not Duplicated (CCND) - Cluster/Head Up Display | N9992 | Holden Australia |
| 3439929 | Customer Concern Not Duplicated (CCND) - Cluster/Head Up Display | N9993 | Holden Australia |
| 3439929 | Customer Concern Not Duplicated (CCND) - Cluster/Head Up Display | N9997 | Holden Australia |
| 3440030 | Radio and Trip Odometer Control Switch Replacement | N4135 | GMNA |
| 3440030 | Radio and Trip Odometer Control Switch Replacement | N4320 | GMNA |
| 3440050 | Radio Control Switch Replacement - Steering Wheel | R0741 | GMNA |
| 3440050 | Radio Control Switch Replacement - Steering Wheel | R0742 | GMNA |
| 3440050 | Radio Control Switch Replacement - Steering Wheel | R0743 | GMNA |
| 3440050 | Radio Control Switch Replacement - Steering Wheel | R0744 | GMNA |
| 3440050 | Radio Control Switch Replacement - Steering Wheel | R0745 | GMNA |
| 3440050 | Radio Control Switch Replacement - Steering Wheel | 5821100 | GMK Domestic |
| 3440050 | Radio Control Switch Replacement - Steering Wheel | 5821200 | GMK Domestic |
| 3440050 | Radio Control Switch Replacement - Steering Wheel | R201600 | Holden New Zealand |
| 3440050 | Radio Control Switch Replacement - Steering Wheel | 9283800 | GMK Overseas |
| 3440550 | Cruise Control Switch Replacement | | |
| 4010150 | Cruise Control Module Replacement | R1220 | GMNA |
| 4010150 | Cruise Control Module Replacement | R122000 | Holden Australia |
| 4010150 | Cruise Control Module Replacement | R400100 | Holden Australia |
| 4010150 | Cruise Control Module Replacement | R401200 | Holden Australia |
| 4010150 | Cruise Control Module Replacement | R403100 | Holden Australia |
| 4010150 | Cruise Control Module Replacement | R122000 | Holden New Zealand |
| 4010150 | Cruise Control Module Replacement | R400100 | Holden New Zealand |
| 4010150 | Cruise Control Module Replacement | R401200 | Holden New Zealand |
| 4010260 | Cruise Control Vehicle Distance Module Sensor Replacement | R1224 | GMNA |
| 4010280 | Cruise Control Release Switch Replacement | R1240 | GMNA |
| 4010280 | Cruise Control Release Switch Replacement | R1240 | Holden Australia |
| 4010320 | Clutch Pedal Cruise Control Release Switch Replacement | R1245 | GMNA |
| 4010320 | Clutch Pedal Cruise Control Release Switch Replacement | N207550 | Holden Australia |
| 4010320 | Clutch Pedal Cruise Control Release Switch Replacement | N712306 | Holden Australia |
| 4010320 | Clutch Pedal Cruise Control Release Switch Replacement | N207550 | Holden New Zealand |
| 4010322 | Clutch Pedal Cruise Control Release Switch Adjustment | R1244 | GMNA |
| 4010322 | Clutch Pedal Cruise Control Release Switch Adjustment | R124000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4010322 | Clutch Pedal Cruise Control Release Switch Adjustment | R124000 | Holden New Zealand |
| 4010370 | Cruise Control Switch Replacement | R1247 | GMNA |
| 4010370 | Cruise Control Switch Replacement | R1262 | GMNA |
| 4010370 | Cruise Control Switch Replacement | R1265 | GMNA |
| 4010370 | Cruise Control Switch Replacement | R1280 | GMNA |
| 4010370 | Cruise Control Switch Replacement | R9516 | GMNA |
| 4010370 | Cruise Control Switch Replacement | 2213100 | GMK Domestic |
| 4010370 | Cruise Control Switch Replacement | N001940 | Holden Australia |
| 4010370 | Cruise Control Switch Replacement | N224100 | Holden Australia |
| 4010370 | Cruise Control Switch Replacement | N224600 | Holden Australia |
| 4010370 | Cruise Control Switch Replacement | N712317 | Holden Australia |
| 4010370 | Cruise Control Switch Replacement | N712519 | Holden Australia |
| 4010370 | Cruise Control Switch Replacement | N732119 | Holden Australia |
| 4010370 | Cruise Control Switch Replacement | R000221 | Holden Australia |
| 4010370 | Cruise Control Switch Replacement | R401100 | Holden Australia |
| 4010370 | Cruise Control Switch Replacement | N224100 | Holden New Zealand |
| 4010370 | Cruise Control Switch Replacement | N224600 | Holden New Zealand |
| 4010370 | Cruise Control Switch Replacement | R401100 | Holden New Zealand |
| 4010370 | Cruise Control Switch Replacement | 1821700 | GMK Overseas |
| 4010370 | Cruise Control Switch Replacement | 6410800 | GMK Overseas |
| 4020020 | Distributor Replacement | 1710110 | GMK Domestic |
| 4020020 | Distributor Replacement | 1721000 | GMK Domestic |
| 4020020 | Distributor Replacement | 1512100 | GMK Overseas |
| 4020020 | Distributor Replacement | 1512300 | GMK Overseas |
| 4020020 | Distributor Replacement | 1513100 | GMK Overseas |
| 4020020 | Distributor Replacement | 1514300 | GMK Overseas |
| 4020020 | Distributor Replacement | 1514700 | GMK Overseas |
| 4020040 | Crankshaft Position Sensor Replacement | J4354 | GMNA |
| 4020040 | Crankshaft Position Sensor Replacement | J4355 | GMNA |
| 4020040 | Crankshaft Position Sensor Replacement | J7938 | GMNA |
| 4020040 | Crankshaft Position Sensor Replacement | J4355 | Holden Australia |
| 4020040 | Crankshaft Position Sensor Replacement | J740250 | Holden Australia |
| 4020040 | Crankshaft Position Sensor Replacement | J740250 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4020040 | Crankshaft Position Sensor Replacement | J794400 | Holden New Zealand |
| 4020040 | Crankshaft Position Sensor Replacement | 1333700 | GMK Overseas |
| 4020040 | Crankshaft Position Sensor Replacement | 133370A | GMK Overseas |
| 4020050 | Spark Plug Wire Replacement | J4206 | GMNA |
| 4020050 | Spark Plug Wire Replacement | J4207 | GMNA |
| 4020050 | Spark Plug Wire Replacement | J4210 | GMNA |
| 4020050 | Spark Plug Wire Replacement | J4211 | GMNA |
| 4020050 | Spark Plug Wire Replacement | J4230 | GMNA |
| 4020050 | Spark Plug Wire Replacement | J4232 | GMNA |
| 4020050 | Spark Plug Wire Replacement | J4420 | GMNA |
| 4020050 | Spark Plug Wire Replacement | R9748 | GMNA |
| 4020050 | Spark Plug Wire Replacement | T5801 | GMNA |
| 4020050 | Spark Plug Wire Replacement | 1721200 | GMK Domestic |
| 4020050 | Spark Plug Wire Replacement | 1721300 | GMK Domestic |
| 4020050 | Spark Plug Wire Replacement | J4206 | Holden Australia |
| 4020050 | Spark Plug Wire Replacement | J420600 | Holden Australia |
| 4020050 | Spark Plug Wire Replacement | J420700 | Holden Australia |
| 4020050 | Spark Plug Wire Replacement | J442000 | Holden Australia |
| 4020050 | Spark Plug Wire Replacement | J730100 | Holden Australia |
| 4020050 | Spark Plug Wire Replacement | J420600 | Holden New Zealand |
| 4020050 | Spark Plug Wire Replacement | J420700 | Holden New Zealand |
| 4020050 | Spark Plug Wire Replacement | J730100 | Holden New Zealand |
| 4020050 | Spark Plug Wire Replacement | 1510100 | GMK Overseas |
| 4020050 | Spark Plug Wire Replacement | 1510200 | GMK Overseas |
| 4020050 | Spark Plug Wire Replacement | 151020X | GMK Overseas |
| 4020050 | Spark Plug Wire Replacement | 1510400 | GMK Overseas |
| 4020050 | Spark Plug Wire Replacement | 1510500 | GMK Overseas |
| 4020060 | Spark Plug Replacement | J4217 | GMNA |
| 4020060 | Spark Plug Replacement | J4226 | GMNA |
| 4020060 | Spark Plug Replacement | J4227 | GMNA |
| 4020060 | Spark Plug Replacement | J4403 | GMNA |
| 4020060 | Spark Plug Replacement | J7943 | GMNA |
| 4020060 | Spark Plug Replacement | 1721500 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4020060 | Spark Plug Replacement | 1721800 | GMK Domestic |
| 4020060 | Spark Plug Replacement | J4226 | Holden Australia |
| 4020060 | Spark Plug Replacement | J735100 | Holden Australia |
| 4020060 | Spark Plug Replacement | J735100 | Holden New Zealand |
| 4020060 | Spark Plug Replacement | 1510800 | GMK Overseas |
| 4020060 | Spark Plug Replacement | 1510900 | GMK Overseas |
| 4020060 | Spark Plug Replacement | 1511100 | GMK Overseas |
| 4020060 | Spark Plug Replacement | 1511200 | GMK Overseas |
| 4020070 | Ignition Coil Replacement | J4340 | GMNA |
| 4020070 | Ignition Coil Replacement | J4345 | GMNA |
| 4020070 | Ignition Coil Replacement | J4400 | GMNA |
| 4020070 | Ignition Coil Replacement | J4402 | GMNA |
| 4020070 | Ignition Coil Replacement | J4405 | GMNA |
| 4020070 | Ignition Coil Replacement | J715100 | GMNA |
| 4020070 | Ignition Coil Replacement | J7717 | GMNA |
| 4020070 | Ignition Coil Replacement | J7929 | GMNA |
| 4020070 | Ignition Coil Replacement | R9221 | GMNA |
| 4020070 | Ignition Coil Replacement | J4340 | Holden Australia |
| 4020070 | Ignition Coil Replacement | J434000 | Holden Australia |
| 4020070 | Ignition Coil Replacement | J4345 | Holden Australia |
| 4020070 | Ignition Coil Replacement | J515000 | Holden Australia |
| 4020070 | Ignition Coil Replacement | J712400 | Holden Australia |
| 4020070 | Ignition Coil Replacement | J715100 | Holden Australia |
| 4020070 | Ignition Coil Replacement | J724510 | Holden Australia |
| 4020070 | Ignition Coil Replacement | J434000 | Holden New Zealand |
| 4020070 | Ignition Coil Replacement | J712400 | Holden New Zealand |
| 4020070 | Ignition Coil Replacement | J715100 | Holden New Zealand |
| 4020070 | Ignition Coil Replacement | J724500 | Holden New Zealand |
| 4020070 | Ignition Coil Replacement | J724510 | Holden New Zealand |
| 4020070 | Ignition Coil Replacement | 8330300 | GMK Overseas |
| 4020090 | Ignition Coil Replacement - Bank 1 | J4341 | GMNA |
| 4020110 | Ignition Coil Replacement - Bank 2 | J4342 | GMNA |
| 4020130 | Ignition Control Module Replacement | J4343 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4020130 | Ignition Control Module Replacement | J4440 | GMNA |
| 4020130 | Ignition Control Module Replacement | 1721900 | GMK Domestic |
| 4020130 | Ignition Control Module Replacement | 1722100 | GMK Domestic |
| 4020130 | Ignition Control Module Replacement | 1722200 | GMK Domestic |
| 4020130 | Ignition Control Module Replacement | 1723500 | GMK Domestic |
| 4020130 | Ignition Control Module Replacement | 1723600 | GMK Domestic |
| 4020130 | Ignition Control Module Replacement | 1723700 | GMK Domestic |
| 4020130 | Ignition Control Module Replacement | J435000 | Holden Australia |
| 4020130 | Ignition Control Module Replacement | J638500 | Holden Australia |
| 4020130 | Ignition Control Module Replacement | J724520 | Holden Australia |
| 4020130 | Ignition Control Module Replacement | J724550 | Holden Australia |
| 4020130 | Ignition Control Module Replacement | J724520 | Holden New Zealand |
| 4020130 | Ignition Control Module Replacement | J724550 | Holden New Zealand |
| 4020130 | Ignition Control Module Replacement | 1511300 | GMK Overseas |
| 4020130 | Ignition Control Module Replacement | 1511400 | GMK Overseas |
| 4020130 | Ignition Control Module Replacement | 151140A | GMK Overseas |
| 4020130 | Ignition Control Module Replacement | 1511600 | GMK Overseas |
| 4020130 | Ignition Control Module Replacement | 1511700 | GMK Overseas |
| 4020130 | Ignition Control Module Replacement | 1511900 | GMK Overseas |
| 4020140 | Camshaft Position Actuator Solenoid Valve Replacement | J7942 | GMNA |
| 4020140 | Camshaft Position Actuator Solenoid Valve Replacement | 2201300 | GMK Domestic |
| 4020140 | Camshaft Position Actuator Solenoid Valve Replacement | 2203120 | GMK Domestic |
| 4020140 | Camshaft Position Actuator Solenoid Valve Replacement | J000929 | Holden Australia |
| 4020140 | Camshaft Position Actuator Solenoid Valve Replacement | J000929 | Holden New Zealand |
| 4020140 | Camshaft Position Actuator Solenoid Valve Replacement | 1333810 | GMK Overseas |
| 4020140 | Camshaft Position Actuator Solenoid Valve Replacement | 1333820 | GMK Overseas |
| 4020150 | Camshaft Position Sensor Replacement - Exhaust | J4351 | GMNA |
| 4020170 | Camshaft Position Sensor Replacement - Intake | J4352 | GMNA |
| 4020180 | Camshaft Position Sensor Wire Replacement | | |
| 4020190 | Camshaft Position Sensor Replacement - Bank 2 (Left Side) Exhaust | J4361 | GMNA |
| 4020210 | Camshaft Position Sensor Replacement - Bank 2 (Left Side) Intake | J4362 | GMNA |
| 4020230 | Camshaft Position Sensor Replacement - Bank 1 (Right Side) Exhaust | J4363 | GMNA |
| 4020250 | Camshaft Position Sensor Replacement - Bank 1 (Right Side) Intake | J4364 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4020260 | Camshaft Position Sensor Replacement | J4349 | GMNA |
| 4020260 | Camshaft Position Sensor Replacement | J4350 | GMNA |
| 4020260 | Camshaft Position Sensor Replacement | J6376 | GMNA |
| 4020260 | Camshaft Position Sensor Replacement | J4350 | Holden Australia |
| 4020260 | Camshaft Position Sensor Replacement | J795200 | Holden Australia |
| 4020260 | Camshaft Position Sensor Replacement | J6376 | Holden New Zealand |
| 4020260 | Camshaft Position Sensor Replacement | J795200 | Holden New Zealand |
| 4020260 | Camshaft Position Sensor Replacement | 1333800 | GMK Overseas |
| 4020270 | Knock Sensor 2 Replacement | J4432 | GMNA |
| 4020280 | Knock Sensor 1 Replacement | J4433 | GMNA |
| 4020290 | Knock Sensor Replacement - Bank 1 | J4435 | GMNA |
| 4020290 | Knock Sensor Replacement - Bank 1 | 1861700 | GMK Overseas |
| 4020290 | Knock Sensor Replacement - Bank 1 | 186170A | GMK Overseas |
| 4020300 | Knock Sensor Replacement - Left Side | | |
| 4020310 | Knock Sensor Replacement - Bank 2 | J4436 | GMNA |
| 4020310 | Knock Sensor Replacement - Bank 2 | 1861800 | GMK Overseas |
| 4020320 | Knock Sensor Replacement - Right Side | | |
| 4020330 | Knock Sensor Replacement | J4434 | GMNA |
| 4020330 | Knock Sensor Replacement | J4437 | GMNA |
| 4020330 | Knock Sensor Replacement | J4438 | GMNA |
| 4020330 | Knock Sensor Replacement | J5900 | GMNA |
| 4020330 | Knock Sensor Replacement | 2172200 | GMK Domestic |
| 4020330 | Knock Sensor Replacement | 2172300 | GMK Domestic |
| 4020330 | Knock Sensor Replacement | 2201100 | GMK Domestic |
| 4020330 | Knock Sensor Replacement | J4437 | Holden Australia |
| 4020330 | Knock Sensor Replacement | J597120 | Holden Australia |
| 4020330 | Knock Sensor Replacement | J637900 | Holden Australia |
| 4020330 | Knock Sensor Replacement | J724000 | Holden Australia |
| 4020330 | Knock Sensor Replacement | J724050 | Holden Australia |
| 4020330 | Knock Sensor Replacement | J724100 | Holden Australia |
| 4020330 | Knock Sensor Replacement | J724150 | Holden Australia |
| 4020330 | Knock Sensor Replacement | J597120 | Holden New Zealand |
| 4020330 | Knock Sensor Replacement | J724000 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4020330 | Knock Sensor Replacement | J724050 | Holden New Zealand |
| 4020330 | Knock Sensor Replacement | J724100 | Holden New Zealand |
| 4020330 | Knock Sensor Replacement | J724150 | Holden New Zealand |
| 4020330 | Knock Sensor Replacement | J795100 | Holden New Zealand |
| 4020330 | Knock Sensor Replacement | 1861300 | GMK Overseas |
| 4020340 | Glow Plug Wire Replacement | 1511500 | GMK Overseas |
| 4020350 | Glow Plug Replacement | J4760 | GMNA |
| 4020350 | Glow Plug Replacement | J4761 | GMNA |
| 4020350 | Glow Plug Replacement | J4767 | GMNA |
| 4020350 | Glow Plug Replacement | J4768 | GMNA |
| 4020350 | Glow Plug Replacement | T5695 | GMNA |
| 4020350 | Glow Plug Replacement | 1722400 | GMK Domestic |
| 4020350 | Glow Plug Replacement | J479000 | Holden Australia |
| 4020350 | Glow Plug Replacement | J479400 | Holden Australia |
| 4020350 | Glow Plug Replacement | J479700 | Holden Australia |
| 4020350 | Glow Plug Replacement | J486000 | Holden Australia |
| 4020350 | Glow Plug Replacement | J4790 | Holden New Zealand |
| 4020350 | Glow Plug Replacement | J479000 | Holden New Zealand |
| 4020350 | Glow Plug Replacement | J479000B | Holden New Zealand |
| 4020350 | Glow Plug Replacement | J479400 | Holden New Zealand |
| 4020350 | Glow Plug Replacement | J479700 | Holden New Zealand |
| 4020350 | Glow Plug Replacement | J486000 | Holden New Zealand |
| 4020350 | Glow Plug Replacement | 1510600 | GMK Overseas |
| 4020350 | Glow Plug Replacement | 1510700 | GMK Overseas |
| 4020370 | Glow Plug Controller Replacement | J4791 | GMNA |
| 4020370 | Glow Plug Controller Replacement | J4820 | GMNA |
| 4020370 | Glow Plug Controller Replacement | 2210100 | GMK Domestic |
| 4020370 | Glow Plug Controller Replacement | J486700 | Holden Australia |
| 4020370 | Glow Plug Controller Replacement | 1863100 | GMK Overseas |
| 4020390 | Air Cleaner Assembly Replacement | J5000 | GMNA |
| 4020390 | Air Cleaner Assembly Replacement | J7910 | GMNA |
| 4020390 | Air Cleaner Assembly Replacement | J7912 | GMNA |
| 4020390 | Air Cleaner Assembly Replacement | 1233300 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4020390 | Air Cleaner Assembly Replacement | 1233500 | GMK Domestic |
| 4020390 | Air Cleaner Assembly Replacement | 1240100 | GMK Domestic |
| 4020390 | Air Cleaner Assembly Replacement | J5000 | Holden Australia |
| 4020390 | Air Cleaner Assembly Replacement | J500000 | Holden Australia |
| 4020390 | Air Cleaner Assembly Replacement | J500300 | Holden Australia |
| 4020390 | Air Cleaner Assembly Replacement | J500700 | Holden Australia |
| 4020390 | Air Cleaner Assembly Replacement | J817500 | Holden Australia |
| 4020390 | Air Cleaner Assembly Replacement | J5000 | Holden New Zealand |
| 4020390 | Air Cleaner Assembly Replacement | J500000 | Holden New Zealand |
| 4020390 | Air Cleaner Assembly Replacement | J817500 | Holden New Zealand |
| 4020390 | Air Cleaner Assembly Replacement | 1910300 | GMK Overseas |
| 4020410 | Air Cleaner Snorkel Replacement | J7525 | GMNA |
| 4020410 | Air Cleaner Snorkel Replacement | 1242100 | GMK Domestic |
| 4020410 | Air Cleaner Snorkel Replacement | R905900 | Holden Australia |
| 4020410 | Air Cleaner Snorkel Replacement | R905900 | Holden New Zealand |
| 4020410 | Air Cleaner Snorkel Replacement | 1913300 | GMK Overseas |
| 4020430 | Intermediate Intake Air Duct Replacement | | |
| 4020470 | Air Cleaner Element Replacement | J5010 | GMNA |
| 4020470 | Air Cleaner Element Replacement | 1240400 | GMK Domestic |
| 4020470 | Air Cleaner Element Replacement | 1240500 | GMK Domestic |
| 4020470 | Air Cleaner Element Replacement | J501000 | Holden Australia |
| 4020470 | Air Cleaner Element Replacement | J5010 | Holden New Zealand |
| 4020470 | Air Cleaner Element Replacement | J501000 | Holden New Zealand |
| 4020470 | Air Cleaner Element Replacement | 1910500 | GMK Overseas |
| 4020530 | Intake Air Duct Replacement | J5015 | GMNA |
| 4020550 | Front Intake Air Duct Replacement | J5016 | GMNA |
| 4020550 | Front Intake Air Duct Replacement | 1244500 | GMK Domestic |
| 4020550 | Front Intake Air Duct Replacement | 1251600 | GMK Domestic |
| 4020550 | Front Intake Air Duct Replacement | 1911100 | GMK Overseas |
| 4020550 | Front Intake Air Duct Replacement | 1911200 | GMK Overseas |
| 4020570 | Air Cleaner Resonator Replacement | J5017 | GMNA |
| 4020570 | Air Cleaner Resonator Replacement | 1251300 | GMK Domestic |
| 4020570 | Air Cleaner Resonator Replacement | J301300 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4020570 | Air Cleaner Resonator Replacement | J301300 | Holden New Zealand |
| 4020570 | Air Cleaner Resonator Replacement | 1911300 | GMK Overseas |
| 4020570 | Air Cleaner Resonator Replacement | 1911500 | GMK Overseas |
| 4020570 | Air Cleaner Resonator Replacement | 1911800 | GMK Overseas |
| 4020570 | Air Cleaner Resonator Replacement | 1911900 | GMK Overseas |
| 4020570 | Air Cleaner Resonator Replacement | 1913200 | GMK Overseas |
| 4020590 | Air Cleaner Air Restriction Indicator Replacement | J5018 | GMNA |
| 4020630 | Air Cleaner Inlet Duct Replacement | J5020 | GMNA |
| 4020630 | Air Cleaner Inlet Duct Replacement | J501500 | Holden Australia |
| 4020630 | Air Cleaner Inlet Duct Replacement | J5020 | Holden Australia |
| 4020630 | Air Cleaner Inlet Duct Replacement | J5020 | Holden New Zealand |
| 4020630 | Air Cleaner Inlet Duct Replacement | J818520 | Holden New Zealand |
| 4020630 | Air Cleaner Inlet Duct Replacement | 1910700 | GMK Overseas |
| 4020650 | Rear Intake Air Duct Resonator Insulator Replacement | J5021 | GMNA |
| 4020650 | Rear Intake Air Duct Resonator Insulator Replacement | J5022 | GMNA |
| 4020670 | Rear Intake Air Duct Replacement | J5023 | GMNA |
| 4020670 | Rear Intake Air Duct Replacement | J818530 | Holden Australia |
| 4020670 | Rear Intake Air Duct Replacement | J818530 | Holden New Zealand |
| 4020670 | Rear Intake Air Duct Replacement | JG0901 | Holden New Zealand |
| 4020690 | Air Cleaner Outlet Duct Replacement | J5024 | GMNA |
| 4020690 | Air Cleaner Outlet Duct Replacement | 1212200 | GMK Domestic |
| 4020690 | Air Cleaner Outlet Duct Replacement | 1250100 | GMK Domestic |
| 4020690 | Air Cleaner Outlet Duct Replacement | J502500 | Holden Australia |
| 4020700 | Air Cleaner Upper Housing Replacement | J7568 | GMNA |
| 4020720 | Air Cleaner Lower Housing Replacement | J817600 | Holden Australia |
| 4020720 | Air Cleaner Lower Housing Replacement | J817600 | Holden New Zealand |
| 4020790 | Intake Air Heater Replacement | J5138 | GMNA |
| 4020790 | Intake Air Heater Replacement | J809300 | Holden Australia |
| 4020790 | Intake Air Heater Replacement | J809300 | Holden New Zealand |
| 4020790 | Intake Air Heater Replacement | J809310 | Holden New Zealand |
| 4020800 | Carburetor Replacement | | |
| 4020830 | Accelerator Control Cable Replacement | H4060 | GMNA |
| 4020830 | Accelerator Control Cable Replacement | J5328 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4020830 | Accelerator Control Cable Replacement | J5334 | GMNA |
| 4020830 | Accelerator Control Cable Replacement | 1122000 | GMK Domestic |
| 4020830 | Accelerator Control Cable Replacement | 1123000 | GMK Domestic |
| 4020830 | Accelerator Control Cable Replacement | J533300 | Holden Australia |
| 4020830 | Accelerator Control Cable Replacement | J533950 | Holden Australia |
| 4020830 | Accelerator Control Cable Replacement | J534000 | Holden Australia |
| 4020830 | Accelerator Control Cable Replacement | J534050 | Holden Australia |
| 4020830 | Accelerator Control Cable Replacement | J534500 | Holden Australia |
| 4020830 | Accelerator Control Cable Replacement | J534600 | Holden Australia |
| 4020830 | Accelerator Control Cable Replacement | J533300 | Holden New Zealand |
| 4020830 | Accelerator Control Cable Replacement | J816900 | Holden New Zealand |
| 4020830 | Accelerator Control Cable Replacement | 1820300 | GMK Overseas |
| 4020910 | Accelerator Pedal with Position Sensor Assembly Replacement | J5349 | GMNA |
| 4020910 | Accelerator Pedal with Position Sensor Assembly Replacement | 1010200 | GMK Domestic |
| 4020910 | Accelerator Pedal with Position Sensor Assembly Replacement | 1121600 | GMK Domestic |
| 4020910 | Accelerator Pedal with Position Sensor Assembly Replacement | J496030 | Holden Australia |
| 4020910 | Accelerator Pedal with Position Sensor Assembly Replacement | N000562 | Holden Australia |
| 4020910 | Accelerator Pedal with Position Sensor Assembly Replacement | J496030 | Holden New Zealand |
| 4020910 | Accelerator Pedal with Position Sensor Assembly Replacement | J814500 | Holden New Zealand |
| 4020910 | Accelerator Pedal with Position Sensor Assembly Replacement | 1821800 | GMK Overseas |
| 4020930 | Accelerator Pedal Replacement | J5350 | GMNA |
| 4020930 | Accelerator Pedal Replacement | J7718 | GMNA |
| 4020930 | Accelerator Pedal Replacement | 1010100 | GMK Domestic |
| 4020930 | Accelerator Pedal Replacement | 1121100 | GMK Domestic |
| 4020930 | Accelerator Pedal Replacement | 1121300 | GMK Domestic |
| 4020930 | Accelerator Pedal Replacement | J535000 | Holden Australia |
| 4020930 | Accelerator Pedal Replacement | J5350 | Holden New Zealand |
| 4020930 | Accelerator Pedal Replacement | J815600 | Holden New Zealand |
| 4020930 | Accelerator Pedal Replacement | 1820500 | GMK Overseas |
| 4020930 | Accelerator Pedal Replacement | 1820700 | GMK Overseas |
| 4020930 | Accelerator Pedal Replacement | 1822100 | GMK Overseas |
| 4020950 | Accelerator Pedal Lever Replacement | J815500 | Holden Australia |
| 4020950 | Accelerator Pedal Lever Replacement | J815500 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4021170 | Fuel Pump Module Replacement | J5435 | GMNA |
| 4021170 | Fuel Pump Module Replacement | J5467 | GMNA |
| 4021170 | Fuel Pump Module Replacement | J7810 | GMNA |
| 4021170 | Fuel Pump Module Replacement | L0763 | GMNA |
| 4021170 | Fuel Pump Module Replacement | R9223 | GMNA |
| 4021170 | Fuel Pump Module Replacement | 1462100 | GMK Domestic |
| 4021170 | Fuel Pump Module Replacement | 1462200 | GMK Domestic |
| 4021170 | Fuel Pump Module Replacement | 1470100 | GMK Domestic |
| 4021170 | Fuel Pump Module Replacement | E303300 | Holden Australia |
| 4021170 | Fuel Pump Module Replacement | L006310 | Holden Australia |
| 4021170 | Fuel Pump Module Replacement | L006340 | Holden Australia |
| 4021170 | Fuel Pump Module Replacement | L006350 | Holden Australia |
| 4021170 | Fuel Pump Module Replacement | L006360 | Holden Australia |
| 4021170 | Fuel Pump Module Replacement | L852500 | Holden Australia |
| 4021170 | Fuel Pump Module Replacement | L852550 | Holden Australia |
| 4021170 | Fuel Pump Module Replacement | F1250 | Holden New Zealand |
| 4021170 | Fuel Pump Module Replacement | F1251 | Holden New Zealand |
| 4021170 | Fuel Pump Module Replacement | F650200 | Holden New Zealand |
| 4021170 | Fuel Pump Module Replacement | L006310 | Holden New Zealand |
| 4021170 | Fuel Pump Module Replacement | L006340 | Holden New Zealand |
| 4021170 | Fuel Pump Module Replacement | L006350 | Holden New Zealand |
| 4021170 | Fuel Pump Module Replacement | L006360 | Holden New Zealand |
| 4021170 | Fuel Pump Module Replacement | L852500 | Holden New Zealand |
| 4021170 | Fuel Pump Module Replacement | L852550 | Holden New Zealand |
| 4021170 | Fuel Pump Module Replacement | 1710100 | GMK Overseas |
| 4021170 | Fuel Pump Module Replacement | 1710400 | GMK Overseas |
| 4021190 | Cold Start Fuel Feed Hose Replacement | J5441 | GMNA |
| 4021190 | Cold Start Fuel Feed Hose Replacement | F128100 | Holden Australia |
| 4021210 | Cold Start Fuel Pump Replacement | J5442 | GMNA |
| 4021230 | Cold Start Fuel Reservoir Replacement | | |
| 4021250 | Cold Start Fuel Solenoid Valve Hose Replacement | | |
| 4021270 | Cold Start Fuel Solenoid Valve Replacement | J5445 | GMNA |
| 4021330 | Fuel Line Replacement - Engine | J5472 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4021330 | Fuel Line Replacement - Engine | L0102 | GMNA |
| 4021330 | Fuel Line Replacement - Engine | L9729 | GMNA |
| 4021330 | Fuel Line Replacement - Engine | L0390 | Holden New Zealand |
| 4021330 | Fuel Line Replacement - Engine | L0410 | Holden New Zealand |
| 4021350 | Fuel Return Hose Replacement | J5473 | GMNA |
| 4021350 | Fuel Return Hose Replacement | L0550 | GMNA |
| 4021350 | Fuel Return Hose Replacement | 1531020 | GMK Domestic |
| 4021350 | Fuel Return Hose Replacement | L000260 | Holden Australia |
| 4021350 | Fuel Return Hose Replacement | 1720920 | GMK Overseas |
| 4021350 | Fuel Return Hose Replacement | 1720940 | GMK Overseas |
| 4021350 | Fuel Return Hose Replacement | 1721300 | GMK Overseas |
| 4021350 | Fuel Return Hose Replacement | 1721400 | GMK Overseas |
| 4021350 | Fuel Return Hose Replacement | 1721500 | GMK Overseas |
| 4021350 | Fuel Return Hose Replacement | 1721700 | GMK Overseas |
| 4021350 | Fuel Return Hose Replacement | 1723200 | GMK Overseas |
| 4021350 | Fuel Return Hose Replacement | 1811630 | GMK Overseas |
| 4021370 | Fuel Pipe Shield Replacement | J5474 | GMNA |
| 4021390 | Fuel Return Hose Replacement - Fuel Return Pipe to Fuel Injection Pump | J5475 | GMNA |
| 4021390 | Fuel Return Hose Replacement - Fuel Return Pipe to Fuel Injection Pump | L0284 | GMNA |
| 4021390 | Fuel Return Hose Replacement - Fuel Return Pipe to Fuel Injection Pump | L0286 | GMNA |
| 4021390 | Fuel Return Hose Replacement - Fuel Return Pipe to Fuel Injection Pump | L0288 | GMNA |
| 4021390 | Fuel Return Hose Replacement - Fuel Return Pipe to Fuel Injection Pump | L3502 | GMNA |
| 4021390 | Fuel Return Hose Replacement - Fuel Return Pipe to Fuel Injection Pump | T1324 | GMNA |
| 4021390 | Fuel Return Hose Replacement - Fuel Return Pipe to Fuel Injection Pump | J000421 | Holden Australia |
| 4021390 | Fuel Return Hose Replacement - Fuel Return Pipe to Fuel Injection Pump | J410200 | Holden Australia |
| 4021390 | Fuel Return Hose Replacement - Fuel Return Pipe to Fuel Injection Pump | L000239 | Holden Australia |
| 4021390 | Fuel Return Hose Replacement - Fuel Return Pipe to Fuel Injection Pump | 1721100 | GMK Overseas |
| 4021390 | Fuel Return Hose Replacement - Fuel Return Pipe to Fuel Injection Pump | 1812500 | GMK Overseas |
| 4021410 | Fuel Hose Replacement - Fuel Injection Pump to Fuel Feed Block | J5476 | GMNA |
| 4021410 | Fuel Hose Replacement - Fuel Injection Pump to Fuel Feed Block | L007100 | Holden New Zealand |
| 4021410 | Fuel Hose Replacement - Fuel Injection Pump to Fuel Feed Block | 1812300 | GMK Overseas |
| 4021430 | Fuel Hose Replacement - Fuel Filter/Heater Element Housing to Fuel Feed Block | J5477 | GMNA |
| 4021430 | Fuel Hose Replacement - Fuel Filter/Heater Element Housing to Fuel Feed Block | L1005 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4021430 | Fuel Hose Replacement - Fuel Filter/Heater Element Housing to Fuel Feed Block | J852500 | Holden New Zealand |
| 4021430 | Fuel Hose Replacement - Fuel Filter/Heater Element Housing to Fuel Feed Block | L009800 | Holden New Zealand |
| 4021430 | Fuel Hose Replacement - Fuel Filter/Heater Element Housing to Fuel Feed Block | 1720900 | GMK Overseas |
| 4021430 | Fuel Hose Replacement - Fuel Filter/Heater Element Housing to Fuel Feed Block | 1720910 | GMK Overseas |
| 4021450 | Fuel Feed and Return Pipe Replacement | F3031 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | F3037 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | I9324 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | J1140 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | J5478 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | K4260 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | L0200 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | L0280 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | L0282 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | L0325 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | L0330 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | L0335 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | L0340 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | L0345 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | L0350 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | L0380 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | L0390 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | L0410 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | L0621 | GMNA |
| 4021450 | Fuel Feed and Return Pipe Replacement | 1421200 | GMK Domestic |
| 4021450 | Fuel Feed and Return Pipe Replacement | L007100 | Holden Australia |
| 4021450 | Fuel Feed and Return Pipe Replacement | L008100 | Holden Australia |
| 4021450 | Fuel Feed and Return Pipe Replacement | L701800 | Holden Australia |
| 4021450 | Fuel Feed and Return Pipe Replacement | L701900 | Holden Australia |
| 4021450 | Fuel Feed and Return Pipe Replacement | J5565 | Holden New Zealand |
| 4021450 | Fuel Feed and Return Pipe Replacement | K422000 | Holden New Zealand |
| 4021450 | Fuel Feed and Return Pipe Replacement | K425000 | Holden New Zealand |
| 4021450 | Fuel Feed and Return Pipe Replacement | L000211 | Holden New Zealand |
| 4021450 | Fuel Feed and Return Pipe Replacement | L000226 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4021450 | Fuel Feed and Return Pipe Replacement | L008100 | Holden New Zealand |
| 4021490 | Throttle Body Adapter Replacement | | |
| 4021510 | Throttle Body Assembly Replacement | J5040 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5050 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5070 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5080 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5090 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5100 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5120 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5122 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5140 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5290 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5295 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5305 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5410 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5480 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5483 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5485 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5490 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5493 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J5984 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J6339 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J6340 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J7817 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J7917 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J7948 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | J7949 | GMNA |
| 4021510 | Throttle Body Assembly Replacement | 1251900 | GMK Domestic |
| 4021510 | Throttle Body Assembly Replacement | J000728 | Holden Australia |
| 4021510 | Throttle Body Assembly Replacement | J000731 | Holden Australia |
| 4021510 | Throttle Body Assembly Replacement | J504000 | Holden Australia |
| 4021510 | Throttle Body Assembly Replacement | J505000 | Holden Australia |
| 4021510 | Throttle Body Assembly Replacement | J508000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4021510 | Throttle Body Assembly Replacement | J510000 | Holden Australia |
| 4021510 | Throttle Body Assembly Replacement | J512000 | Holden Australia |
| 4021510 | Throttle Body Assembly Replacement | J512600 | Holden Australia |
| 4021510 | Throttle Body Assembly Replacement | J514000 | Holden Australia |
| 4021510 | Throttle Body Assembly Replacement | J529000 | Holden Australia |
| 4021510 | Throttle Body Assembly Replacement | J530500 | Holden Australia |
| 4021510 | Throttle Body Assembly Replacement | J5490 | Holden Australia |
| 4021510 | Throttle Body Assembly Replacement | J805170 | Holden Australia |
| 4021510 | Throttle Body Assembly Replacement | J805210 | Holden Australia |
| 4021510 | Throttle Body Assembly Replacement | J807600 | Holden Australia |
| 4021510 | Throttle Body Assembly Replacement | J512000 | Holden New Zealand |
| 4021510 | Throttle Body Assembly Replacement | J805170 | Holden New Zealand |
| 4021510 | Throttle Body Assembly Replacement | J805210 | Holden New Zealand |
| 4021510 | Throttle Body Assembly Replacement | J852510 | Holden New Zealand |
| 4021510 | Throttle Body Assembly Replacement | 1810100 | GMK Overseas |
| 4021510 | Throttle Body Assembly Replacement | 1810300 | GMK Overseas |
| 4021510 | Throttle Body Assembly Replacement | R318015 | GMK Overseas |
| 4021530 | Throttle Body Gasket Replacement | J5030 | GMNA |
| 4021530 | Throttle Body Gasket Replacement | J5115 | GMNA |
| 4021530 | Throttle Body Gasket Replacement | J5125 | GMNA |
| 4021530 | Throttle Body Gasket Replacement | J5491 | GMNA |
| 4021530 | Throttle Body Gasket Replacement | J5492 | GMNA |
| 4021530 | Throttle Body Gasket Replacement | 1252300 | GMK Domestic |
| 4021530 | Throttle Body Gasket Replacement | J503000 | Holden Australia |
| 4021530 | Throttle Body Gasket Replacement | J511500 | Holden Australia |
| 4021530 | Throttle Body Gasket Replacement | J512500 | Holden Australia |
| 4021530 | Throttle Body Gasket Replacement | J805200 | Holden Australia |
| 4021530 | Throttle Body Gasket Replacement | J805220 | Holden Australia |
| 4021530 | Throttle Body Gasket Replacement | J805200 | Holden New Zealand |
| 4021530 | Throttle Body Gasket Replacement | J805220 | Holden New Zealand |
| 4021530 | Throttle Body Gasket Replacement | 1810500 | GMK Overseas |
| 4021530 | Throttle Body Gasket Replacement | 1810600 | GMK Overseas |
| 4021570 | Throttle Inlet Absolute Pressure Sensor Replacement | J5494 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4021610 | Fuel Injector Fuel Meter Body Replacement | J5495 | GMNA |
| 4021610 | Fuel Injector Fuel Meter Body Replacement | J5496 | GMNA |
| 4021630 | Camshaft Position Actuator Intake Solenoid Valve Replacement | J5524 | GMNA |
| 4021630 | Camshaft Position Actuator Intake Solenoid Valve Replacement | 1336600 | GMK Overseas |
| 4021650 | Camshaft Position Actuator Exhaust Solenoid Valve Replacement | J5526 | GMNA |
| 4021670 | Camshaft Position Actuator Solenoid Valve Solenoid Replacement - Bank 1 (Right Side) Intake | J5528 | GMNA |
| 4021690 | Camshaft Position Actuator Solenoid Valve Solenoid Replacement - Bank 2 (Left Side) Intake | J5529 | GMNA |
| 4021710 | Camshaft Position Actuator Solenoid Valve Solenoid Replacement - Bank 1 (Right Side) Exhaust | J5530 | GMNA |
| 4021730 | Camshaft Position Actuator Solenoid Valve Solenoid Replacement - Bank 2 (Left Side) Exhaust | J5531 | GMNA |
| 4021730 | Camshaft Position Actuator Solenoid Valve Solenoid Replacement - Bank 2 (Left Side) Exhaust | J794100 | Holden Australia |
| 4021730 | Camshaft Position Actuator Solenoid Valve Solenoid Replacement - Bank 2 (Left Side) Exhaust | J794200 | Holden Australia |
| 4021730 | Camshaft Position Actuator Solenoid Valve Solenoid Replacement - Bank 2 (Left Side) Exhaust | J794200 | Holden New Zealand |
| 4021770 | Idle Air Control Valve Replacement | J5541 | GMNA |
| 4021770 | Idle Air Control Valve Replacement | J5542 | GMNA |
| 4021770 | Idle Air Control Valve Replacement | J5543 | GMNA |
| 4021770 | Idle Air Control Valve Replacement | N6333 | GMNA |
| 4021770 | Idle Air Control Valve Replacement | 1255200 | GMK Domestic |
| 4021770 | Idle Air Control Valve Replacement | 1255300 | GMK Domestic |
| 4021770 | Idle Air Control Valve Replacement | 1622500 | GMK Domestic |
| 4021770 | Idle Air Control Valve Replacement | J971800 | Holden Australia |
| 4021770 | Idle Air Control Valve Replacement | J971800 | Holden New Zealand |
| 4021770 | Idle Air Control Valve Replacement | 1811800 | GMK Overseas |
| 4021770 | Idle Air Control Valve Replacement | 1811820 | GMK Overseas |
| 4021770 | Idle Air Control Valve Replacement | 1811900 | GMK Overseas |
| 4021770 | Idle Air Control Valve Replacement | 181190X | GMK Overseas |
| 4021810 | Fuel Pressure Regulator Replacement | F0030 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4021810 | Fuel Pressure Regulator Replacement | J5560 | GMNA |
| 4021810 | Fuel Pressure Regulator Replacement | J5902 | GMNA |
| 4021810 | Fuel Pressure Regulator Replacement | 1511400 | GMK Domestic |
| 4021810 | Fuel Pressure Regulator Replacement | J000902 | Holden Australia |
| 4021810 | Fuel Pressure Regulator Replacement | J556000 | Holden Australia |
| 4021810 | Fuel Pressure Regulator Replacement | J903000 | Holden Australia |
| 4021810 | Fuel Pressure Regulator Replacement | J000902 | Holden New Zealand |
| 4021810 | Fuel Pressure Regulator Replacement | J556000 | Holden New Zealand |
| 4021810 | Fuel Pressure Regulator Replacement | J857500 | Holden New Zealand |
| 4021810 | Fuel Pressure Regulator Replacement | L000187 | Holden New Zealand |
| 4021810 | Fuel Pressure Regulator Replacement | L014100 | Holden New Zealand |
| 4021810 | Fuel Pressure Regulator Replacement | 1810800 | GMK Overseas |
| 4021810 | Fuel Pressure Regulator Replacement | 1810900 | GMK Overseas |
| 4021810 | Fuel Pressure Regulator Replacement | 1811650 | GMK Overseas |
| 4021830 | Fuel Pulse Dampener Replacement | J5561 | GMNA |
| 4021830 | Fuel Pulse Dampener Replacement | J5928 | GMNA |
| 4021840 | Fuel Pressure Limiting Valve Replacement | | |
| 4021870 | Accelerator Pedal Position Sensor Replacement | J5584 | GMNA |
| 4021870 | Accelerator Pedal Position Sensor Replacement | 1821900 | GMK Overseas |
| 4021880 | Secondary Air Injection Check Valve Replacement | J6085 | GMNA |
| 4021880 | Secondary Air Injection Check Valve Replacement | J6086 | GMNA |
| 4021880 | Secondary Air Injection Check Valve Replacement | J6090 | GMNA |
| 4021880 | Secondary Air Injection Check Valve Replacement | J6091 | GMNA |
| 4021880 | Secondary Air Injection Check Valve Replacement | J6130 | GMNA |
| 4021880 | Secondary Air Injection Check Valve Replacement | J6133 | GMNA |
| 4021880 | Secondary Air Injection Check Valve Replacement | J6085 | Holden Australia |
| 4021880 | Secondary Air Injection Check Valve Replacement | J980910 | Holden Australia |
| 4021880 | Secondary Air Injection Check Valve Replacement | J980910 | Holden New Zealand |
| 4021890 | Fuel Pump Replacement | J5434 | GMNA |
| 4021890 | Fuel Pump Replacement | J5590 | GMNA |
| 4021890 | Fuel Pump Replacement | J5915 | GMNA |
| 4021890 | Fuel Pump Replacement | J7826 | GMNA |
| 4021890 | Fuel Pump Replacement | J7828 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4021900 | Fuel Pump Cover Replacement | J5589 | GMNA |
| 4021900 | Fuel Pump Cover Replacement | J7814 | GMNA |
| 4021900 | Fuel Pump Cover Replacement | F504000 | Holden New Zealand |
| 4021920 | Fuel Pump Insulator Replacement | | |
| 4021930 | Secondary Injection Shutoff Valve Pressure Sensor Replacement | J5602 | GMNA |
| 4021950 | Fuel Pressure Sensor Replacement | J5603 | GMNA |
| 4021950 | Fuel Pressure Sensor Replacement | K4140 | GMNA |
| 4021950 | Fuel Pressure Sensor Replacement | K422000 | Holden Australia |
| 4021950 | Fuel Pressure Sensor Replacement | K425000 | Holden Australia |
| 4021950 | Fuel Pressure Sensor Replacement | L006370 | Holden Australia |
| 4021950 | Fuel Pressure Sensor Replacement | L062100 | Holden Australia |
| 4021950 | Fuel Pressure Sensor Replacement | 1711800 | GMK Overseas |
| 4021980 | Fuel Pump Flow Control Module Replacement | J5465 | GMNA |
| 4021980 | Fuel Pump Flow Control Module Replacement | J5604 | GMNA |
| 4021980 | Fuel Pump Flow Control Module Replacement | 1461810 | GMK Domestic |
| 4021980 | Fuel Pump Flow Control Module Replacement | 2210900 | GMK Domestic |
| 4021980 | Fuel Pump Flow Control Module Replacement | J858100 | Holden Australia |
| 4021990 | Fuel Pump Cycle Control Module Replacement | | |
| 4022010 | Engine Fuel Vacuum Switch Replacement | J5607 | GMNA |
| 4022030 | Fuel Heater Replacement | J5611 | GMNA |
| 4022030 | Fuel Heater Replacement | F202200 | Holden New Zealand |
| 4022030 | Fuel Heater Replacement | L122800 | Holden New Zealand |
| 4022040 | Fuel Injection Pump Metering Valve Replacement | | |
| 4022050 | Fuel Injection Fuel Feed Pipe Replacement | 1510400 | GMK Domestic |
| 4022050 | Fuel Injection Fuel Feed Pipe Replacement | 1531200 | GMK Domestic |
| 4022050 | Fuel Injection Fuel Feed Pipe Replacement | 1812000 | GMK Overseas |
| 4022060 | Humidity Sensor Replacement | | |
| 4022070 | Fuel Injection Fuel Return Pipe Replacement | | |
| 4022130 | Fuel High Pressure Pipe Replacement - Rail to Rail | J5639 | GMNA |
| 4022130 | Fuel High Pressure Pipe Replacement - Rail to Rail | J5930 | GMNA |
| 4022130 | Fuel High Pressure Pipe Replacement - Rail to Rail | J5931 | GMNA |
| 4022130 | Fuel High Pressure Pipe Replacement - Rail to Rail | J5935 | GMNA |
| 4022130 | Fuel High Pressure Pipe Replacement - Rail to Rail | J5937 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4022130 | Fuel High Pressure Pipe Replacement - Rail to Rail | J593500 | Holden Australia |
| 4022130 | Fuel High Pressure Pipe Replacement - Rail to Rail | J5935 | Holden New Zealand |
| 4022130 | Fuel High Pressure Pipe Replacement - Rail to Rail | J593500 | Holden New Zealand |
| 4022130 | Fuel High Pressure Pipe Replacement - Rail to Rail | J5936 | Holden New Zealand |
| 4022130 | Fuel High Pressure Pipe Replacement - Rail to Rail | 1811620 | GMK Overseas |
| 4022150 | Fuel High Pressure Pipe Replacement - Pump to Rail | J5640 | GMNA |
| 4022150 | Fuel High Pressure Pipe Replacement - Pump to Rail | 1811610 | GMK Overseas |
| 4022170 | Fuel Injection Fuel Feed Pipe Replacement - Left Side | J5641 | GMNA |
| 4022170 | Fuel Injection Fuel Feed Pipe Replacement - Left Side | J5922 | GMNA |
| 4022170 | Fuel Injection Fuel Feed Pipe Replacement - Left Side | J5925 | GMNA |
| 4022170 | Fuel Injection Fuel Feed Pipe Replacement - Left Side | J491060 | Holden Australia |
| 4022170 | Fuel Injection Fuel Feed Pipe Replacement - Left Side | L494240 | Holden Australia |
| 4022170 | Fuel Injection Fuel Feed Pipe Replacement - Left Side | L494240 | Holden New Zealand |
| 4022190 | Fuel Injection Fuel Feed Pipe Replacement - Right Side | J5642 | GMNA |
| 4022230 | Indirect Fuel Injector Replacement | J5644 | GMNA |
| 4022250 | Fuel Pressure Service Valve Replacement | J5646 | GMNA |
| 4022270 | Fuel Injection Fuel Return Pipe Replacement - Left Side | J5647 | GMNA |
| 4022290 | Fuel Injection Fuel Return Pipe Replacement - Right Side | J5648 | GMNA |
| 4022320 | Fuel Injection Fuel Feed Front Hose Replacement | | |
| 4022330 | Fuel Injector Replacement | J5556 | GMNA |
| 4022330 | Fuel Injector Replacement | J5557 | GMNA |
| 4022330 | Fuel Injector Replacement | J5612 | GMNA |
| 4022330 | Fuel Injector Replacement | J5620 | GMNA |
| 4022330 | Fuel Injector Replacement | J5645 | GMNA |
| 4022330 | Fuel Injector Replacement | J5650 | GMNA |
| 4022330 | Fuel Injector Replacement | J5651 | GMNA |
| 4022330 | Fuel Injector Replacement | J5652 | GMNA |
| 4022330 | Fuel Injector Replacement | J5923 | GMNA |
| 4022330 | Fuel Injector Replacement | J5926 | GMNA |
| 4022330 | Fuel Injector Replacement | J5947 | GMNA |
| 4022330 | Fuel Injector Replacement | J7801 | GMNA |
| 4022330 | Fuel Injector Replacement | J7805 | GMNA |
| 4022330 | Fuel Injector Replacement | J7807 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4022330 | Fuel Injector Replacement | T5603 | GMNA |
| 4022330 | Fuel Injector Replacement | 1600100 | GMK Domestic |
| 4022330 | Fuel Injector Replacement | J5650 | Holden Australia |
| 4022330 | Fuel Injector Replacement | J565000 | Holden Australia |
| 4022330 | Fuel Injector Replacement | J565100 | Holden Australia |
| 4022330 | Fuel Injector Replacement | J565200 | Holden Australia |
| 4022330 | Fuel Injector Replacement | J565250 | Holden Australia |
| 4022330 | Fuel Injector Replacement | J565300 | Holden Australia |
| 4022330 | Fuel Injector Replacement | J565400 | Holden Australia |
| 4022330 | Fuel Injector Replacement | J592600 | Holden Australia |
| 4022330 | Fuel Injector Replacement | J900000 | Holden Australia |
| 4022330 | Fuel Injector Replacement | J901010 | Holden Australia |
| 4022330 | Fuel Injector Replacement | T681001 | Holden Australia |
| 4022330 | Fuel Injector Replacement | T681002 | Holden Australia |
| 4022330 | Fuel Injector Replacement | J565000 | Holden New Zealand |
| 4022330 | Fuel Injector Replacement | J5920 | Holden New Zealand |
| 4022330 | Fuel Injector Replacement | J5922 | Holden New Zealand |
| 4022330 | Fuel Injector Replacement | J5923 | Holden New Zealand |
| 4022330 | Fuel Injector Replacement | J5925 | Holden New Zealand |
| 4022330 | Fuel Injector Replacement | J5926 | Holden New Zealand |
| 4022330 | Fuel Injector Replacement | J592600 | Holden New Zealand |
| 4022330 | Fuel Injector Replacement | J5928 | Holden New Zealand |
| 4022330 | Fuel Injector Replacement | J900000 | Holden New Zealand |
| 4022330 | Fuel Injector Replacement | T681002 | Holden New Zealand |
| 4022330 | Fuel Injector Replacement | 1811100 | GMK Overseas |
| 4022330 | Fuel Injector Replacement | 181110A | GMK Overseas |
| 4022330 | Fuel Injector Replacement | 181110B | GMK Overseas |
| 4022330 | Fuel Injector Replacement | 1811200 | GMK Overseas |
| 4022370 | Fuel Injection Fuel Rail Assembly Replacement - Bank 1 | J5655 | GMNA |
| 4022390 | Fuel Injection Fuel Rail Assembly Replacement - Bank 2 | J5656 | GMNA |
| 4022450 | Fuel Injection Fuel Rail Assembly Replacement | J5660 | GMNA |
| 4022450 | Fuel Injection Fuel Rail Assembly Replacement | J5665 | GMNA |
| 4022450 | Fuel Injection Fuel Rail Assembly Replacement | 1425800 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4022450 | Fuel Injection Fuel Rail Assembly Replacement | J5660 | Holden Australia |
| 4022450 | Fuel Injection Fuel Rail Assembly Replacement | J566000 | Holden Australia |
| 4022450 | Fuel Injection Fuel Rail Assembly Replacement | J566100 | Holden Australia |
| 4022450 | Fuel Injection Fuel Rail Assembly Replacement | J901000 | Holden Australia |
| 4022450 | Fuel Injection Fuel Rail Assembly Replacement | J5665 | Holden New Zealand |
| 4022450 | Fuel Injection Fuel Rail Assembly Replacement | J901000 | Holden New Zealand |
| 4022450 | Fuel Injection Fuel Rail Assembly Replacement | 1811300 | GMK Overseas |
| 4022450 | Fuel Injection Fuel Rail Assembly Replacement | 1811400 | GMK Overseas |
| 4022470 | Fuel Injection Fuel Rail Crossover Tube Replacement | J5661 | GMNA |
| 4022490 | Fuel Injection Fuel Rail Fuel Pressure Sensor Replacement | J5662 | GMNA |
| 4022490 | Fuel Injection Fuel Rail Fuel Pressure Sensor Replacement | 1811640 | GMK Overseas |
| 4022510 | Fuel Pressure Sensor Replacement - Fuel Feed Pipe | J5663 | GMNA |
| 4022510 | Fuel Pressure Sensor Replacement - Fuel Feed Pipe | J857400 | Holden New Zealand |
| 4022530 | Fuel Pressure Sensor Replacement - Fuel Injection Fuel Rail | J5664 | GMNA |
| 4022550 | Fuel Injection Fuel Feed Manifold Replacement | J5667 | GMNA |
| 4022570 | Fuel Injector Fuel Feed Pipe Replacement | 1720950 | GMK Overseas |
| 4022590 | Intake Air Valve Replacement | J5669 | GMNA |
| 4022590 | Intake Air Valve Replacement | J6390 | GMNA |
| 4022590 | Intake Air Valve Replacement | J5275 | Holden New Zealand |
| 4022600 | Engine Oil Pressure Sensor Replacement | | |
| 4022610 | Mass Airflow Sensor Replacement | J5670 | GMNA |
| 4022610 | Mass Airflow Sensor Replacement | J6532 | GMNA |
| 4022610 | Mass Airflow Sensor Replacement | 1221200 | GMK Domestic |
| 4022610 | Mass Airflow Sensor Replacement | J527600 | Holden Australia |
| 4022610 | Mass Airflow Sensor Replacement | J5670 | Holden Australia |
| 4022610 | Mass Airflow Sensor Replacement | j818510 | Holden Australia |
| 4022610 | Mass Airflow Sensor Replacement | J527600 | Holden New Zealand |
| 4022610 | Mass Airflow Sensor Replacement | J741000 | Holden New Zealand |
| 4022610 | Mass Airflow Sensor Replacement | J818510 | Holden New Zealand |
| 4022610 | Mass Airflow Sensor Replacement | 1913100 | GMK Overseas |
| 4022630 | Mass Airflow Sensor with Intake Air Temperature Sensor Replacement | J5672 | GMNA |
| 4022810 | Turbocharger Air Inlet Adapter Replacement | J5695 | GMNA |
| 4022810 | Turbocharger Air Inlet Adapter Replacement | J470900 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4022810 | Turbocharger Air Inlet Adapter Replacement | J470900 | Holden New Zealand |
| 4022870 | Charge Air Cooler Coolant Hose Replacement | J000857 | Holden Australia |
| 4022870 | Charge Air Cooler Coolant Hose Replacement | J000860 | Holden Australia |
| 4022870 | Charge Air Cooler Coolant Hose Replacement | 1913000 | GMK Overseas |
| 4022870 | Charge Air Cooler Coolant Hose Replacement | 1913400 | GMK Overseas |
| 4022880 | Charge Air Cooler Outlet Air Tube Replacement | | |
| 4022900 | Charge Air Cooler Inlet Air Tube Replacement | | |
| 4022910 | Charge Air Cooler Outlet Duct Elbow Replacement | | |
| 4022920 | Charge Air Cooler Outlet Duct Replacement | J5688 | GMNA |
| 4022920 | Charge Air Cooler Outlet Duct Replacement | J5689 | GMNA |
| 4022920 | Charge Air Cooler Outlet Duct Replacement | J5795 | GMNA |
| 4022920 | Charge Air Cooler Outlet Duct Replacement | J9747 | GMNA |
| 4022930 | Charge Air Bypass Valve Vacuum Tank Replacement | J5775 | GMNA |
| 4022940 | Charge Air Cooler Replacement | 1410100 | GMK Domestic |
| 4022940 | Charge Air Cooler Replacement | 1411800 | GMK Overseas |
| 4023000 | Turbocharger Wastegate Actuator Hose Replacement | | |
| 4023010 | Exhaust Gas Recirculation Valve Pipe Replacement | J6269 | GMNA |
| 4023010 | Exhaust Gas Recirculation Valve Pipe Replacement | J6275 | GMNA |
| 4023010 | Exhaust Gas Recirculation Valve Pipe Replacement | J984600 | Holden Australia |
| 4023010 | Exhaust Gas Recirculation Valve Pipe Replacement | J6269 | Holden New Zealand |
| 4023010 | Exhaust Gas Recirculation Valve Pipe Replacement | J6277 | Holden New Zealand |
| 4023010 | Exhaust Gas Recirculation Valve Pipe Replacement | 1932700 | GMK Overseas |
| 4023010 | Exhaust Gas Recirculation Valve Pipe Replacement | 1933100 | GMK Overseas |
| 4023010 | Exhaust Gas Recirculation Valve Pipe Replacement | 1933200 | GMK Overseas |
| 4023030 | Turbocharger Wastegate Actuator Replacement | J5800 | GMNA |
| 4023030 | Turbocharger Wastegate Actuator Replacement | J5805 | GMNA |
| 4023030 | Turbocharger Wastegate Actuator Replacement | J588000 | Holden Australia |
| 4023030 | Turbocharger Wastegate Actuator Replacement | J588000 | Holden New Zealand |
| 4023032 | Turbocharger Wastegate Actuator Adjustment | J5799 | GMNA |
| 4023050 | Charge Air Bypass Valve Replacement | J5801 | GMNA |
| 4023070 | Charge Air Bypass Valve Solenoid Replacement | J5802 | GMNA |
| 4023110 | Turbocharger Pressure Sensor Replacement | J5804 | GMNA |
| 4023130 | Turbocharger Vane Position Sensor Replacement | J5806 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4023130 | Turbocharger Vane Position Sensor Replacement | J7545 | GMNA |
| 4023150 | Turbocharger Control Solenoid Valve Replacement | J5807 | GMNA |
| 4023170 | Supercharger Bypass Valve Actuator Replacement | J5808 | GMNA |
| 4023190 | Charge Air Bypass Regulator Solenoid Valve Replacement | J5809 | GMNA |
| 4023200 | Turbocharger Wastegate Actuator Vacuum Control Solenoid Valve Replacement | | |
| 4023250 | Turbocharger Wastegate Regulator Solenoid Valve Replacement | J5814 | GMNA |
| 4023260 | Turbocharger Bypass Valve Solenoid Replacement | | |
| 4023270 | Charge Air Temperature Sensor Replacement | J5815 | GMNA |
| 4023290 | Exhaust Gas Recirculation Cooler Bypass Valve Replacement | J5816 | GMNA |
| 4023530 | Water in Fuel Indicator Sensor Replacement | J5914 | GMNA |
| 4023530 | Water in Fuel Indicator Sensor Replacement | L0739 | GMNA |
| 4023590 | Fuel Temperature Sensor Replacement | J5918 | GMNA |
| 4023590 | Fuel Temperature Sensor Replacement | J636800 | Holden Australia |
| 4023590 | Fuel Temperature Sensor Replacement | J6368 | Holden New Zealand |
| 4023590 | Fuel Temperature Sensor Replacement | J636800 | Holden New Zealand |
| 4023590 | Fuel Temperature Sensor Replacement | 1723600 | GMK Overseas |
| 4023850 | Vacuum Pump Assembly Replacement | J0240 | GMNA |
| 4023850 | Vacuum Pump Assembly Replacement | J0245 | GMNA |
| 4023850 | Vacuum Pump Assembly Replacement | J5948 | GMNA |
| 4023850 | Vacuum Pump Assembly Replacement | J6080 | GMNA |
| 4023850 | Vacuum Pump Assembly Replacement | J6190 | GMNA |
| 4023850 | Vacuum Pump Assembly Replacement | 1184120 | GMK Domestic |
| 4023850 | Vacuum Pump Assembly Replacement | 1232600 | GMK Domestic |
| 4023850 | Vacuum Pump Assembly Replacement | 1300900 | GMK Domestic |
| 4023850 | Vacuum Pump Assembly Replacement | J024000 | Holden Australia |
| 4023850 | Vacuum Pump Assembly Replacement | J024500 | Holden Australia |
| 4023850 | Vacuum Pump Assembly Replacement | J473300 | Holden Australia |
| 4023850 | Vacuum Pump Assembly Replacement | J484500 | Holden Australia |
| 4023850 | Vacuum Pump Assembly Replacement | J491030 | Holden Australia |
| 4023850 | Vacuum Pump Assembly Replacement | J590675 | Holden Australia |
| 4023850 | Vacuum Pump Assembly Replacement | J618000 | Holden Australia |
| 4023850 | Vacuum Pump Assembly Replacement | J0240 | Holden New Zealand |
| 4023850 | Vacuum Pump Assembly Replacement | J484500 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4023850 | Vacuum Pump Assembly Replacement | J491030 | Holden New Zealand |
| 4023850 | Vacuum Pump Assembly Replacement | 1951400 | GMK Overseas |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J5927 | GMNA |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J5951 | GMNA |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J5952 | GMNA |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J5953 | GMNA |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J5954 | GMNA |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J5958 | GMNA |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J5959 | GMNA |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J5960 | GMNA |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J5963 | GMNA |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J5990 | GMNA |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J595550 | Holden Australia |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J595800 | Holden Australia |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J5927 | Holden New Zealand |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J5951 | Holden New Zealand |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J5952 | Holden New Zealand |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J5953 | Holden New Zealand |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J5954 | Holden New Zealand |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J595550 | Holden New Zealand |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J5958 | Holden New Zealand |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J595800 | Holden New Zealand |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | J5959 | Holden New Zealand |
| 4023890 | Fuel Injection Pump Drive Pulley Replacement | 1812400 | GMK Overseas |
| 4023910 | Fuel Injection Pump Replacement | J5950 | GMNA |
| 4023910 | Fuel Injection Pump Replacement | J5955 | GMNA |
| 4023910 | Fuel Injection Pump Replacement | J5957 | GMNA |
| 4023910 | Fuel Injection Pump Replacement | J5995 | GMNA |
| 4023910 | Fuel Injection Pump Replacement | J7811 | GMNA |
| 4023910 | Fuel Injection Pump Replacement | T5607 | GMNA |
| 4023910 | Fuel Injection Pump Replacement | 1700120 | GMK Domestic |
| 4023910 | Fuel Injection Pump Replacement | 1710100 | GMK Domestic |
| 4023910 | Fuel Injection Pump Replacement | J491700 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4023910 | Fuel Injection Pump Replacement | J491750 | Holden Australia |
| 4023910 | Fuel Injection Pump Replacement | J595300 | Holden Australia |
| 4023910 | Fuel Injection Pump Replacement | J858000 | Holden Australia |
| 4023910 | Fuel Injection Pump Replacement | J491700 | Holden New Zealand |
| 4023910 | Fuel Injection Pump Replacement | J491750 | Holden New Zealand |
| 4023910 | Fuel Injection Pump Replacement | J5950 | Holden New Zealand |
| 4023910 | Fuel Injection Pump Replacement | J595000 | Holden New Zealand |
| 4023910 | Fuel Injection Pump Replacement | J595300 | Holden New Zealand |
| 4023910 | Fuel Injection Pump Replacement | J5955 | Holden New Zealand |
| 4023910 | Fuel Injection Pump Replacement | J5956 | Holden New Zealand |
| 4023910 | Fuel Injection Pump Replacement | J5957 | Holden New Zealand |
| 4023910 | Fuel Injection Pump Replacement | J5995 | Holden New Zealand |
| 4023910 | Fuel Injection Pump Replacement | 1811500 | GMK Overseas |
| 4023920 | Oil Pump Flow Control Valve Replacement | | |
| 4024050 | Intake Air Tuning Valve Vacuum Reservoir Replacement | J6036 | GMNA |
| 4024130 | Secondary Air Injection Pump Replacement | J6045 | GMNA |
| 4024130 | Secondary Air Injection Pump Replacement | J6046 | GMNA |
| 4024130 | Secondary Air Injection Pump Replacement | J6050 | GMNA |
| 4024130 | Secondary Air Injection Pump Replacement | J6051 | GMNA |
| 4024130 | Secondary Air Injection Pump Replacement | J6052 | GMNA |
| 4024130 | Secondary Air Injection Pump Replacement | J6071 | GMNA |
| 4024130 | Secondary Air Injection Pump Replacement | J6140 | GMNA |
| 4024130 | Secondary Air Injection Pump Replacement | J6050 | Holden Australia |
| 4024130 | Secondary Air Injection Pump Replacement | J605000 | Holden Australia |
| 4024130 | Secondary Air Injection Pump Replacement | J614000 | Holden Australia |
| 4024130 | Secondary Air Injection Pump Replacement | J980800 | Holden Australia |
| 4024130 | Secondary Air Injection Pump Replacement | J980800 | Holden New Zealand |
| 4024220 | Secondary Air Injection Check Valve Pipe Adapter Replacement - Left Side | | |
| 4024230 | Secondary Air Injection Shutoff and Check Valve Replacement | J6084 | GMNA |
| 4024230 | Secondary Air Injection Shutoff and Check Valve Replacement | R143027 | GMNA |
| 4024230 | Secondary Air Injection Shutoff and Check Valve Replacement | R143XXX | Holden New Zealand |
| 4024270 | Secondary Air Injection Bypass Valve Replacement - Bank 1 | J6088 | GMNA |
| 4024290 | Secondary Air Injection Bypass Valve Replacement - Bank 2 | J6089 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4024520 | Secondary Air Injection Pump Air Cleaner Hose Replacement | J6137 | GMNA |
| 4024520 | Secondary Air Injection Pump Air Cleaner Hose Replacement | J980700 | Holden Australia |
| 4024520 | Secondary Air Injection Pump Air Cleaner Hose Replacement | J980710 | Holden Australia |
| 4024520 | Secondary Air Injection Pump Air Cleaner Hose Replacement | J980710 | Holden New Zealand |
| 4024530 | Secondary Air Injection Pump Hose Replacement | J6125 | GMNA |
| 4024550 | Secondary Air Injection Pump Inlet Hose Replacement | J6126 | GMNA |
| 4024570 | Secondary Air Injection Pump Outlet Hose Replacement | J6127 | GMNA |
| 4024590 | Secondary Air Injection Pipe Replacement | J6123 | GMNA |
| 4024590 | Secondary Air Injection Pipe Replacement | J6129 | GMNA |
| 4024590 | Secondary Air Injection Pipe Replacement | 1251001 | GMK Domestic |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0799 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0800 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0810 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0812 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0813 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0830 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0831 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0847 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0857 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0858 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0861 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0862 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0870 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0881 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0886 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0887 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0890 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0892 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0893 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0894 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0895 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0896 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0897 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H0950 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H1700 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H1701 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H1707 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H1708 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H1709 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H1722 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H1723 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H1740 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | J6131 | GMNA |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H080000 | Holden Australia |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H402300 | Holden Australia |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H402400 | Holden Australia |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H402500 | Holden Australia |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H402600 | Holden Australia |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H404100 | Holden Australia |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H404200 | Holden Australia |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H404300 | Holden Australia |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H405320 | Holden Australia |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H405330 | Holden Australia |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H406100 | Holden Australia |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H406120 | Holden Australia |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H406200 | Holden Australia |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H406220 | Holden Australia |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H080000 | Holden New Zealand |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H1700 | Holden New Zealand |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H1710 | Holden New Zealand |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H1720 | Holden New Zealand |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H174000 | Holden New Zealand |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H402300 | Holden New Zealand |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H402400 | Holden New Zealand |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H402500 | Holden New Zealand |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H402600 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H404000 | Holden New Zealand |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H404300 | Holden New Zealand |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H405320 | Holden New Zealand |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H405330 | Holden New Zealand |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H406100 | Holden New Zealand |
| 4024610 | Secondary Air Injection Pump Pipe Replacement | H406200 | Holden New Zealand |
| 4024710 | Vacuum Modulator Replacement | J6262 | GMNA |
| 4024710 | Vacuum Modulator Replacement | K5250 | GMNA |
| 4024710 | Vacuum Modulator Replacement | K5251 | GMNA |
| 4024720 | Exhaust Gas Recirculation Cooler Replacement | J3122 | GMNA |
| 4024720 | Exhaust Gas Recirculation Cooler Replacement | 1322700 | GMK Domestic |
| 4024720 | Exhaust Gas Recirculation Cooler Replacement | J6275 | Holden New Zealand |
| 4024720 | Exhaust Gas Recirculation Cooler Replacement | 1933300 | GMK Overseas |
| 4024730 | Exhaust Gas Recirculation Valve Cooler Bypass Control Solenoid Valve Replacement | | |
| 4024740 | Exhaust Gas Recirculation Manifold Cooling Feed Hose Replacement | | |
| 4024760 | Exhaust Gas Recirculation Manifold Cooling Return Hose Replacement | | |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | J5982 | GMNA |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | J6270 | GMNA |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | J7903 | GMNA |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | J7906 | GMNA |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | J7907 | GMNA |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | 1321200 | GMK Domestic |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | 1321500 | GMK Domestic |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | 1322800 | GMK Domestic |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | 1324000 | GMK Domestic |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | J627000 | Holden Australia |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | J634000 | Holden Australia |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | J980500 | Holden Australia |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | J6270 | Holden New Zealand |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | J627000 | Holden New Zealand |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | J634000 | Holden New Zealand |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | J980500 | Holden New Zealand |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | 1314300 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4024770 | Exhaust Gas Recirculation Valve Replacement | 1930700 | GMK Overseas |
| 4024770 | Exhaust Gas Recirculation Valve Replacement | 193070X | GMK Overseas |
| 4024790 | Exhaust Gas Recirculation Vacuum Regulator Valve Solenoid Replacement | 1324200 | GMK Domestic |
| 4024790 | Exhaust Gas Recirculation Vacuum Regulator Valve Solenoid Replacement | 1950900 | GMK Overseas |
| 4024810 | Exhaust Gas Recirculation Valve Solenoid Replacement | | |
| 4024830 | Exhaust Gas Recirculation Valve Vacuum Tank Replacement | 1951300 | GMK Overseas |
| 4024850 | Exhaust Gas Recirculation Valve Adapter Replacement | J6280 | GMNA |
| 4024850 | Exhaust Gas Recirculation Valve Adapter Replacement | 1231800 | GMK Domestic |
| 4024890 | Exhaust Gas Recirculation Valve Temperature Sensor Replacement - Position 1 | J6288 | GMNA |
| 4024910 | Exhaust Gas Recirculation Valve Temperature Sensor Replacement - Position 2 | J6289 | GMNA |
| 4024920 | Exhaust Gas Recirculation Vacuum Regulator Solenoid Valve Replacement - EGR | | |
| 4025070 | Emission Reduction Fluid Injector Replacement | J6316 | GMNA |
| 4025070 | Emission Reduction Fluid Injector Replacement | 5470400 | GMK Overseas |
| 4025090 | Emission Reduction Fluid Exhaust Front Pipe Injector Supply Pipe Replacement | J6317 | GMNA |
| 4025110 | Emission Reduction Fluid Tank Opening Filler Replacement | J6318 | GMNA |
| 4025130 | Emission Reduction Fluid Tank Replacement | J6319 | GMNA |
| 4025130 | Emission Reduction Fluid Tank Replacement | K414500 | Holden Australia |
| 4025170 | Fuel Pressure Relief Valve Replacement | J6323 | GMNA |
| 4025190 | Intake Manifold Tuning Valve Replacement | J6329 | GMNA |
| 4025190 | Intake Manifold Tuning Valve Replacement | 1300800 | GMK Domestic |
| 4025190 | Intake Manifold Tuning Valve Replacement | 1951100 | GMK Overseas |
| 4025210 | Intake Manifold Tuning Valve Actuator Solenoid Replacement | J6330 | GMNA |
| 4025230 | Intake Manifold Tuning Valve Actuator Replacement | J6331 | GMNA |
| 4025230 | Intake Manifold Tuning Valve Actuator Replacement | 1931500 | GMK Overseas |
| 4025230 | Intake Manifold Tuning Valve Actuator Replacement | 1932400 | GMK Overseas |
| 4025250 | Intake Manifold Tuning Vacuum Control Solenoid Valve Replacement | J000911 | Holden Australia |
| 4025270 | Intake Manifold Runner Control Valve Actuator Solenoid Valve Replacement | J6333 | GMNA |
| 4025290 | Intake Air Tuning Valve Vacuum Control Solenoid Valve Replacement | | |
| 4025300 | Engine Coolant Temperature Sensor Replacement | J3536 | GMNA |
| 4025300 | Engine Coolant Temperature Sensor Replacement | J6368 | GMNA |
| 4025300 | Engine Coolant Temperature Sensor Replacement | N2230 | GMNA |
| 4025300 | Engine Coolant Temperature Sensor Replacement | N6268 | GMNA |
| 4025300 | Engine Coolant Temperature Sensor Replacement | 2210120 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4025300 | Engine Coolant Temperature Sensor Replacement | 2210500 | GMK Domestic |
| 4025300 | Engine Coolant Temperature Sensor Replacement | 2211000 | GMK Domestic |
| 4025300 | Engine Coolant Temperature Sensor Replacement | 6314100 | GMK Domestic |
| 4025300 | Engine Coolant Temperature Sensor Replacement | 6314200 | GMK Domestic |
| 4025300 | Engine Coolant Temperature Sensor Replacement | J6368 | Holden Australia |
| 4025300 | Engine Coolant Temperature Sensor Replacement | N317500 | Holden Australia |
| 4025300 | Engine Coolant Temperature Sensor Replacement | N317510 | Holden Australia |
| 4025300 | Engine Coolant Temperature Sensor Replacement | N317500 | Holden New Zealand |
| 4025300 | Engine Coolant Temperature Sensor Replacement | N317510 | Holden New Zealand |
| 4025300 | Engine Coolant Temperature Sensor Replacement | 1314100 | GMK Overseas |
| 4025300 | Engine Coolant Temperature Sensor Replacement | 1314400 | GMK Overseas |
| 4025300 | Engine Coolant Temperature Sensor Replacement | 1723700 | GMK Overseas |
| 4025300 | Engine Coolant Temperature Sensor Replacement | 1931100 | GMK Overseas |
| 4025300 | Engine Coolant Temperature Sensor Replacement | 193110X | GMK Overseas |
| 4025310 | Engine Coolant Temperature Sensor Replacement - Radiator Side | J6343 | GMNA |
| 4025310 | Engine Coolant Temperature Sensor Replacement - Radiator Side | J6344 | GMNA |
| 4025310 | Engine Coolant Temperature Sensor Replacement - Radiator Side | 2133000 | GMK Domestic |
| 4025310 | Engine Coolant Temperature Sensor Replacement - Radiator Side | 1930900 | GMK Overseas |
| 4025330 | Engine Coolant Temperature Sensor Replacement - Thermostat Side | J6345 | GMNA |
| 4025370 | Powertrain Control Module Replacement | J6347 | GMNA |
| 4025370 | Powertrain Control Module Replacement | J6349 | GMNA |
| 4025370 | Powertrain Control Module Replacement | J6359 | GMNA |
| 4025370 | Powertrain Control Module Replacement | J6360 | GMNA |
| 4025370 | Powertrain Control Module Replacement | J6360 | Holden Australia |
| 4025370 | Powertrain Control Module Replacement | J987610 | Holden Australia |
| 4025370 | Powertrain Control Module Replacement | J987610 | Holden New Zealand |
| 4025390 | Engine Control Module Replacement | J5671 | GMNA |
| 4025390 | Engine Control Module Replacement | J6361 | GMNA |
| 4025390 | Engine Control Module Replacement | R9232 | GMNA |
| 4025390 | Engine Control Module Replacement | 2152200 | GMK Domestic |
| 4025390 | Engine Control Module Replacement | 2210700 | GMK Domestic |
| 4025390 | Engine Control Module Replacement | 2212400 | GMK Domestic |
| 4025390 | Engine Control Module Replacement | J000613 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4025390 | Engine Control Module Replacement | J000622 | Holden Australia |
| 4025390 | Engine Control Module Replacement | J000666 | Holden Australia |
| 4025390 | Engine Control Module Replacement | J000683 | Holden Australia |
| 4025390 | Engine Control Module Replacement | J000689 | Holden Australia |
| 4025390 | Engine Control Module Replacement | J000713 | Holden Australia |
| 4025390 | Engine Control Module Replacement | J000767 | Holden Australia |
| 4025390 | Engine Control Module Replacement | J636000 | Holden Australia |
| 4025390 | Engine Control Module Replacement | J636200 | Holden Australia |
| 4025390 | Engine Control Module Replacement | J987510 | Holden Australia |
| 4025390 | Engine Control Module Replacement | J000683 | Holden New Zealand |
| 4025390 | Engine Control Module Replacement | J000689 | Holden New Zealand |
| 4025390 | Engine Control Module Replacement | J000713 | Holden New Zealand |
| 4025390 | Engine Control Module Replacement | J6360 | Holden New Zealand |
| 4025390 | Engine Control Module Replacement | J636000 | Holden New Zealand |
| 4025390 | Engine Control Module Replacement | J6361 | Holden New Zealand |
| 4025390 | Engine Control Module Replacement | J987510 | Holden New Zealand |
| 4025390 | Engine Control Module Replacement | 1860100 | GMK Overseas |
| 4025390 | Engine Control Module Replacement | 1860400 | GMK Overseas |
| 4025430 | Barometric Pressure Sensor Replacement | J6366 | GMNA |
| 4025430 | Barometric Pressure Sensor Replacement | J793900 | Holden Australia |
| 4025430 | Barometric Pressure Sensor Replacement | J793900 | Holden New Zealand |
| 4025470 | Manifold Absolute Pressure Sensor Replacement | J6370 | GMNA |
| 4025470 | Manifold Absolute Pressure Sensor Replacement | J740800 | GMNA |
| 4025470 | Manifold Absolute Pressure Sensor Replacement | 1254500 | GMK Domestic |
| 4025470 | Manifold Absolute Pressure Sensor Replacement | 1300100 | GMK Domestic |
| 4025470 | Manifold Absolute Pressure Sensor Replacement | 1300200 | GMK Domestic |
| 4025470 | Manifold Absolute Pressure Sensor Replacement | J460900 | Holden Australia |
| 4025470 | Manifold Absolute Pressure Sensor Replacement | J6370 | Holden Australia |
| 4025470 | Manifold Absolute Pressure Sensor Replacement | J637000 | Holden Australia |
| 4025470 | Manifold Absolute Pressure Sensor Replacement | J637800 | Holden Australia |
| 4025470 | Manifold Absolute Pressure Sensor Replacement | J740100 | Holden Australia |
| 4025470 | Manifold Absolute Pressure Sensor Replacement | N308800 | Holden Australia |
| 4025470 | Manifold Absolute Pressure Sensor Replacement | J460900 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4025470 | Manifold Absolute Pressure Sensor Replacement | J637800 | Holden New Zealand |
| 4025470 | Manifold Absolute Pressure Sensor Replacement | J740100 | Holden New Zealand |
| 4025470 | Manifold Absolute Pressure Sensor Replacement | N308800 | Holden New Zealand |
| 4025470 | Manifold Absolute Pressure Sensor Replacement | 1860800 | GMK Overseas |
| 4025470 | Manifold Absolute Pressure Sensor Replacement | 1860900 | GMK Overseas |
| 4025470 | Manifold Absolute Pressure Sensor Replacement | 186090X | GMK Overseas |
| 4025490 | Intake Air Temperature Sensor Replacement | J6371 | GMNA |
| 4025490 | Intake Air Temperature Sensor Replacement | J637100 | Holden Australia |
| 4025490 | Intake Air Temperature Sensor Replacement | J740200 | Holden Australia |
| 4025490 | Intake Air Temperature Sensor Replacement | J6371 | Holden New Zealand |
| 4025490 | Intake Air Temperature Sensor Replacement | J740200 | Holden New Zealand |
| 4025490 | Intake Air Temperature Sensor Replacement | 1910900 | GMK Overseas |
| 4025510 | Heated Oxygen Sensor Replacement - Sensor 1 | J6372 | GMNA |
| 4025510 | Heated Oxygen Sensor Replacement - Sensor 1 | J6372 | Holden Australia |
| 4025510 | Heated Oxygen Sensor Replacement - Sensor 1 | J637200 | Holden Australia |
| 4025510 | Heated Oxygen Sensor Replacement - Sensor 1 | J637200 | Holden New Zealand |
| 4025510 | Heated Oxygen Sensor Replacement - Sensor 1 | 1942100 | GMK Overseas |
| 4025530 | Throttle Position Sensor Replacement | J6374 | GMNA |
| 4025530 | Throttle Position Sensor Replacement | J6510 | GMNA |
| 4025530 | Throttle Position Sensor Replacement | J6513 | GMNA |
| 4025530 | Throttle Position Sensor Replacement | N6535 | GMNA |
| 4025530 | Throttle Position Sensor Replacement | J637400 | Holden Australia |
| 4025530 | Throttle Position Sensor Replacement | J637500 | Holden Australia |
| 4025530 | Throttle Position Sensor Replacement | J794150 | Holden Australia |
| 4025530 | Throttle Position Sensor Replacement | J6374 | Holden New Zealand |
| 4025530 | Throttle Position Sensor Replacement | J637400 | Holden New Zealand |
| 4025530 | Throttle Position Sensor Replacement | J6513 | Holden New Zealand |
| 4025530 | Throttle Position Sensor Replacement | J794100 | Holden New Zealand |
| 4025530 | Throttle Position Sensor Replacement | 1811600 | GMK Overseas |
| 4025530 | Throttle Position Sensor Replacement | 1811700 | GMK Overseas |
| 4025530 | Throttle Position Sensor Replacement | 181170X | GMK Overseas |
| 4025550 | Intake Air Pressure and Temperature Sensor Replacement | J6377 | GMNA |
| 4025570 | Supercharger Air Inlet Pressure Sensor Replacement | J6378 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4025570 | Supercharger Air Inlet Pressure Sensor Replacement | J6378 | Holden New Zealand |
| 4025590 | Heated Oxygen Sensor Replacement - Sensor 2 | J6380 | GMNA |
| 4025590 | Heated Oxygen Sensor Replacement - Sensor 2 | 1721002 | GMK Domestic |
| 4025590 | Heated Oxygen Sensor Replacement - Sensor 2 | J6380 | Holden Australia |
| 4025590 | Heated Oxygen Sensor Replacement - Sensor 2 | 1942200 | GMK Overseas |
| 4025610 | Supercharger Air Outlet Pressure Sensor Replacement | J6382 | GMNA |
| 4025650 | Intake Air Temperature (IAT) Sensor 2 Replacement | J6387 | GMNA |
| 4025690 | Evaporative Emission Canister Purge Solenoid Valve Replacement | J6400 | GMNA |
| 4025690 | Evaporative Emission Canister Purge Solenoid Valve Replacement | 1300400 | GMK Domestic |
| 4025690 | Evaporative Emission Canister Purge Solenoid Valve Replacement | 1461100 | GMK Domestic |
| 4025690 | Evaporative Emission Canister Purge Solenoid Valve Replacement | J6400 | Holden Australia |
| 4025690 | Evaporative Emission Canister Purge Solenoid Valve Replacement | F3263 | Holden New Zealand |
| 4025690 | Evaporative Emission Canister Purge Solenoid Valve Replacement | 1730300 | GMK Overseas |
| 4025710 | Evaporative Emission Canister Purge Tube Replacement | J6401 | GMNA |
| 4025710 | Evaporative Emission Canister Purge Tube Replacement | J820500 | Holden Australia |
| 4025730 | Evaporative Emission Canister Purge Pipe Replacement | J6402 | GMNA |
| 4025730 | Evaporative Emission Canister Purge Pipe Replacement | 1731900 | GMK Overseas |
| 4025750 | Evaporative Emission Canister Purge Solenoid Valve Hose Replacement | F7185 | GMNA |
| 4025750 | Evaporative Emission Canister Purge Solenoid Valve Hose Replacement | J6403 | GMNA |
| 4025750 | Evaporative Emission Canister Purge Solenoid Valve Hose Replacement | 1460500 | GMK Domestic |
| 4025750 | Evaporative Emission Canister Purge Solenoid Valve Hose Replacement | 1520400 | GMK Domestic |
| 4025750 | Evaporative Emission Canister Purge Solenoid Valve Hose Replacement | L013100 | Holden Australia |
| 4025750 | Evaporative Emission Canister Purge Solenoid Valve Hose Replacement | L015200 | Holden Australia |
| 4025750 | Evaporative Emission Canister Purge Solenoid Valve Hose Replacement | L122800 | Holden Australia |
| 4025750 | Evaporative Emission Canister Purge Solenoid Valve Hose Replacement | L013100 | Holden New Zealand |
| 4025750 | Evaporative Emission Canister Purge Solenoid Valve Hose Replacement | 1720930 | GMK Overseas |
| 4025750 | Evaporative Emission Canister Purge Solenoid Valve Hose Replacement | 1730700 | GMK Overseas |
| 4025810 | Exhaust Pressure Differential Sensor Pipe Replacement | J6443 | GMNA |
| 4025830 | Exhaust Pressure Differential Sensor Replacement | J6442 | GMNA |
| 4025830 | Exhaust Pressure Differential Sensor Replacement | J6444 | GMNA |
| 4025830 | Exhaust Pressure Differential Sensor Replacement | J6445 | GMNA |
| 4025830 | Exhaust Pressure Differential Sensor Replacement | J6460 | GMNA |
| 4025830 | Exhaust Pressure Differential Sensor Replacement | 1420201 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4025830 | Exhaust Pressure Differential Sensor Replacement | L2685 | Holden New Zealand |
| 4025830 | Exhaust Pressure Differential Sensor Replacement | 1963100 | GMK Overseas |
| 4025840 | Exhaust Temperature Sensor Replacement - Position 1 | 1420400 | GMK Domestic |
| 4025840 | Exhaust Temperature Sensor Replacement - Position 1 | 1963500 | GMK Overseas |
| 4025840 | Exhaust Temperature Sensor Replacement - Position 1 | 1963700 | GMK Overseas |
| 4025850 | Exhaust Pressure Sensor Replacement | 1963200 | GMK Overseas |
| 4025860 | Exhaust Temperature Sensor Replacement - Position 2 | J6447 | GMNA |
| 4025860 | Exhaust Temperature Sensor Replacement - Position 2 | 1420600 | GMK Domestic |
| 4025870 | Exhaust Temperature Sensor Replacement - Position 3 | J6451 | GMNA |
| 4025890 | Exhaust Temperature Sensor Replacement - Position 4 | J6452 | GMNA |
| 4025942 | Exhaust Particulate Filter Cleaning | J6450 | GMNA |
| 4025942 | Exhaust Particulate Filter Cleaning | 1412900 | GMK Domestic |
| 4025942 | Exhaust Particulate Filter Cleaning | 1413000 | GMK Domestic |
| 4025942 | Exhaust Particulate Filter Cleaning | 1963900 | GMK Overseas |
| 4025942 | Exhaust Particulate Filter Cleaning | 1970700 | GMK Overseas |
| 4025950 | Heated Oxygen Sensor Replacement | J6471 | GMNA |
| 4025950 | Heated Oxygen Sensor Replacement | J7900 | GMNA |
| 4025950 | Heated Oxygen Sensor Replacement | J7939 | GMNA |
| 4025950 | Heated Oxygen Sensor Replacement | J980420 | Holden Australia |
| 4025950 | Heated Oxygen Sensor Replacement | J980520 | Holden Australia |
| 4025950 | Heated Oxygen Sensor Replacement | J987600 | Holden Australia |
| 4025950 | Heated Oxygen Sensor Replacement | J987650 | Holden Australia |
| 4025950 | Heated Oxygen Sensor Replacement | J980400 | Holden New Zealand |
| 4025950 | Heated Oxygen Sensor Replacement | J980420 | Holden New Zealand |
| 4025950 | Heated Oxygen Sensor Replacement | J980520 | Holden New Zealand |
| 4025950 | Heated Oxygen Sensor Replacement | J987600 | Holden New Zealand |
| 4025950 | Heated Oxygen Sensor Replacement | J987600A4 | Holden New Zealand |
| 4025950 | Heated Oxygen Sensor Replacement | J987650 | Holden New Zealand |
| 4025950 | Heated Oxygen Sensor Replacement | 1940400 | GMK Overseas |
| 4025950 | Heated Oxygen Sensor Replacement | 1940410 | GMK Overseas |
| 4025950 | Heated Oxygen Sensor Replacement | 1940500 | GMK Overseas |
| 4025950 | Heated Oxygen Sensor Replacement | 194050X | GMK Overseas |
| 4025950 | Heated Oxygen Sensor Replacement | 1940600 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4025950 | Heated Oxygen Sensor Replacement | 1941200 | GMK Overseas |
| 4025950 | Heated Oxygen Sensor Replacement | 1941300 | GMK Overseas |
| 4025950 | Heated Oxygen Sensor Replacement | 1941400 | GMK Overseas |
| 4025950 | Heated Oxygen Sensor Replacement | 1941500 | GMK Overseas |
| 4025950 | Heated Oxygen Sensor Replacement | 1962400 | GMK Overseas |
| 4025950 | Heated Oxygen Sensor Replacement | 196240X | GMK Overseas |
| 4025950 | Heated Oxygen Sensor Replacement | 1962410 | GMK Overseas |
| 4025970 | Heated Oxygen Sensor Replacement - Bank 1 Sensor 1 | J6472 | GMNA |
| 4025990 | Heated Oxygen Sensor Replacement - Bank 1 Sensor 2 | J6473 | GMNA |
| 4026010 | Heated Oxygen Sensor Replacement - Bank 2 Sensor 1 | J6474 | GMNA |
| 4026030 | Heated Oxygen Sensor Replacement - Bank 2 Sensor 2 | J6475 | GMNA |
| 4026050 | Nitrogen Oxide Sensor Replacement - Position 1 | J6478 | GMNA |
| 4026070 | Nitrogen Oxide Sensor Replacement - Position 2 | J6479 | GMNA |
| 4026150 | Evaporative Emission Line Replacement - Engine | J6982 | GMNA |
| 4026150 | Evaporative Emission Line Replacement - Engine | J7815 | GMNA |
| 4026170 | Compressed Natural Gas Control Module Replacement | E4397 | GMNA |
| 4026170 | Compressed Natural Gas Control Module Replacement | J8300 | GMNA |
| 4026170 | Compressed Natural Gas Control Module Replacement | J8325 | GMNA |
| 4026170 | Compressed Natural Gas Control Module Replacement | J8339 | GMNA |
| 4026170 | Compressed Natural Gas Control Module Replacement | J8341 | GMNA |
| 4026170 | Compressed Natural Gas Control Module Replacement | L0800 | GMNA |
| 4026170 | Compressed Natural Gas Control Module Replacement | E303400 | Holden Australia |
| 4026170 | Compressed Natural Gas Control Module Replacement | E303500 | Holden Australia |
| 4026170 | Compressed Natural Gas Control Module Replacement | E303600 | Holden Australia |
| 4026170 | Compressed Natural Gas Control Module Replacement | F153000 | Holden Australia |
| 4026170 | Compressed Natural Gas Control Module Replacement | L1195 | Holden Australia |
| 4026170 | Compressed Natural Gas Control Module Replacement | L855000 | Holden Australia |
| 4026170 | Compressed Natural Gas Control Module Replacement | F1601 | Holden New Zealand |
| 4026170 | Compressed Natural Gas Control Module Replacement | F1607 | Holden New Zealand |
| 4026170 | Compressed Natural Gas Control Module Replacement | F1617 | Holden New Zealand |
| 4026170 | Compressed Natural Gas Control Module Replacement | L855000 | Holden New Zealand |
| 4026180 | LPG Tank Pressure Relief and Shutoff Valve Replacement | | |
| 4026240 | LPG Tank Filler Hose Replacement | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4026260 | LPG Fuel Feed Hose Replacement | J8328 | GMNA |
| 4026270 | LPG Fuel Tank Gauge Replacement | 5620900 | GMK Domestic |
| 4026270 | LPG Fuel Tank Gauge Replacement | 6313300 | GMK Domestic |
| 4026270 | LPG Fuel Tank Gauge Replacement | L701600 | Holden New Zealand |
| 4026280 | LPG Fuel Return Hose Replacement | | |
| 4026290 | LPG Service Hose Replacement | | |
| 4026300 | LPG Fuel Pressure and Temperature Sensor Replacement | J8386 | GMNA |
| 4026310 | LPG Convertor Replacement | 1620600 | GMK Domestic |
| 4026310 | LPG Convertor Replacement | 1620700 | GMK Domestic |
| 4026320 | LPG Fuel Filter Replacement | L701070 | Holden Australia |
| 4026330 | LPG Shutoff Valve Filter Replacement | | |
| 4026340 | LPG Fuel Tank Drain Valve Replacement | | |
| 4026360 | LPG Tank Filler Valve Receptacle Replacement | | |
| 4026390 | Compressed Natural Gas High Pressure Regulator Replacement | 1531000 | GMK Domestic |
| 4026390 | Compressed Natural Gas High Pressure Regulator Replacement | F3269 | Holden Australia |
| 4026400 | Liquefied Petroleum Gas Distributor Replacement | | |
| 4026410 | Compressed Natural Gas High Pressure Regulator Filter Replacement | J8343 | GMNA |
| 4026460 | LPG Fuel Tank Filler Valve Replacement | 1460600 | GMK Domestic |
| 4026460 | LPG Fuel Tank Filler Valve Replacement | L702000 | Holden Australia |
| 4026460 | LPG Fuel Tank Filler Valve Replacement | L702000 | Holden New Zealand |
| 4026480 | LPG Fuel Tank Fuel Pump and Fuel Tank Pressure Sensor Module Solenoid Replacement | | |
| 4026500 | LPG Fuel Tank Fuel Pump Module Replacement | L1160 | Holden New Zealand |
| 4026520 | LPG Tank Fill Bleeder Valve Replacement | | |
| 4026540 | LPG Tank Replacement | L790300 | Holden Australia |
| 4026550 | LPG Vapor Hose Replacement | J8384 | GMNA |
| 4026560 | LPG Fuel Tank Shield Replacement | | |
| 4026570 | Liquefied Petroleum Gas Liquid Hose Replacement | J8390 | GMNA |
| 4026580 | LPG Control Module Replacement | L701250 | Holden Australia |
| 4026580 | LPG Control Module Replacement | L701250 | Holden New Zealand |
| 4026650 | Liquefied Petroleum Gas Fuel Sender Control Module Replacement | | |
| 4026710 | Compressed Natural Gas Fuel Filter Replacement | | |
| 4026730 | Gasoline/Compressed Natural Gas Fuel Selector Switch Replacement | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4026760 | Gasoline/Compressed Natural Gas Fuel Selector Relay Replacement | | |
| 4026770 | Fuel Filter Replacement | L0110 | GMNA |
| 4026770 | Fuel Filter Replacement | L1198 | GMNA |
| 4026770 | Fuel Filter Replacement | F212300 | Holden Australia |
| 4026770 | Fuel Filter Replacement | J494240 | Holden Australia |
| 4026770 | Fuel Filter Replacement | L010500 | Holden Australia |
| 4026770 | Fuel Filter Replacement | F2122 | Holden New Zealand |
| 4026770 | Fuel Filter Replacement | F2122D | Holden New Zealand |
| 4026770 | Fuel Filter Replacement | F2123 | Holden New Zealand |
| 4026770 | Fuel Filter Replacement | F212300 | Holden New Zealand |
| 4026770 | Fuel Filter Replacement | F2125 | Holden New Zealand |
| 4026770 | Fuel Filter Replacement | F2126 | Holden New Zealand |
| 4026770 | Fuel Filter Replacement | F2127 | Holden New Zealand |
| 4026770 | Fuel Filter Replacement | J494240 | Holden New Zealand |
| 4026770 | Fuel Filter Replacement | L010500 | Holden New Zealand |
| 4026790 | Fuel Filter Assembly Replacement | J5420 | GMNA |
| 4026790 | Fuel Filter Assembly Replacement | J5450 | GMNA |
| 4026790 | Fuel Filter Assembly Replacement | J7809 | GMNA |
| 4026790 | Fuel Filter Assembly Replacement | L0111 | GMNA |
| 4026790 | Fuel Filter Assembly Replacement | L0720 | GMNA |
| 4026790 | Fuel Filter Assembly Replacement | L0731 | GMNA |
| 4026790 | Fuel Filter Assembly Replacement | L0749 | GMNA |
| 4026790 | Fuel Filter Assembly Replacement | L1240 | GMNA |
| 4026790 | Fuel Filter Assembly Replacement | L9705 | GMNA |
| 4026790 | Fuel Filter Assembly Replacement | 1420500 | GMK Domestic |
| 4026790 | Fuel Filter Assembly Replacement | F1500 | Holden Australia |
| 4026790 | Fuel Filter Assembly Replacement | F1501 | Holden Australia |
| 4026790 | Fuel Filter Assembly Replacement | F1507 | Holden Australia |
| 4026790 | Fuel Filter Assembly Replacement | F1511 | Holden Australia |
| 4026790 | Fuel Filter Assembly Replacement | J542000 | Holden Australia |
| 4026790 | Fuel Filter Assembly Replacement | L000281 | Holden Australia |
| 4026790 | Fuel Filter Assembly Replacement | L000284 | Holden Australia |
| 4026790 | Fuel Filter Assembly Replacement | L070000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4026790 | Fuel Filter Assembly Replacement | L074000 | Holden Australia |
| 4026790 | Fuel Filter Assembly Replacement | L074800 | Holden Australia |
| 4026790 | Fuel Filter Assembly Replacement | J5420 | Holden New Zealand |
| 4026790 | Fuel Filter Assembly Replacement | J542000 | Holden New Zealand |
| 4026790 | Fuel Filter Assembly Replacement | J5425 | Holden New Zealand |
| 4026790 | Fuel Filter Assembly Replacement | L0740 | Holden New Zealand |
| 4026790 | Fuel Filter Assembly Replacement | L074000 | Holden New Zealand |
| 4026790 | Fuel Filter Assembly Replacement | L074800 | Holden New Zealand |
| 4026790 | Fuel Filter Assembly Replacement | L2600 | Holden New Zealand |
| 4026790 | Fuel Filter Assembly Replacement | L2680 | Holden New Zealand |
| 4026790 | Fuel Filter Assembly Replacement | L702200 | Holden New Zealand |
| 4026790 | Fuel Filter Assembly Replacement | 1720300 | GMK Overseas |
| 4026810 | Primary Fuel Filter Replacement | L0112 | GMNA |
| 4026810 | Primary Fuel Filter Replacement | F2124 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | E4390 | GMNA |
| 4026830 | Fuel Feed Pipe Replacement | E4391 | GMNA |
| 4026830 | Fuel Feed Pipe Replacement | F1573 | GMNA |
| 4026830 | Fuel Feed Pipe Replacement | F3022 | GMNA |
| 4026830 | Fuel Feed Pipe Replacement | J5470 | GMNA |
| 4026830 | Fuel Feed Pipe Replacement | J7802 | GMNA |
| 4026830 | Fuel Feed Pipe Replacement | J8392 | GMNA |
| 4026830 | Fuel Feed Pipe Replacement | L0100 | GMNA |
| 4026830 | Fuel Feed Pipe Replacement | L0120 | GMNA |
| 4026830 | Fuel Feed Pipe Replacement | L0140 | GMNA |
| 4026830 | Fuel Feed Pipe Replacement | L0160 | GMNA |
| 4026830 | Fuel Feed Pipe Replacement | L0171 | GMNA |
| 4026830 | Fuel Feed Pipe Replacement | L0240 | GMNA |
| 4026830 | Fuel Feed Pipe Replacement | L3030 | GMNA |
| 4026830 | Fuel Feed Pipe Replacement | 1510300 | GMK Domestic |
| 4026830 | Fuel Feed Pipe Replacement | 1520600 | GMK Domestic |
| 4026830 | Fuel Feed Pipe Replacement | 1630500 | GMK Domestic |
| 4026830 | Fuel Feed Pipe Replacement | E000385 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | F130000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4026830 | Fuel Feed Pipe Replacement | F302300 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | F306000 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | H000269 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | J6982 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | J854600 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | J901100 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | J901200 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | J904100 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | L000190 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | L010100 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | L024000 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | L0260 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | L026000 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | L030000 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | L494250 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | L854330 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | L854340 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | L854400 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | L854500 | Holden Australia |
| 4026830 | Fuel Feed Pipe Replacement | E200300 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | F3023 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | F302300 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | F306300 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | F306500 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | F306600 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | F306700 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | F654500 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | H000269 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | J854600 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | J901200 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | J904100 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | L010000 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | L010100 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4026830 | Fuel Feed Pipe Replacement | L022000 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | L0240 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | L024000 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | L494250 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | L700900 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | L854330 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | L854340 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | L854400 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | R917094 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | R917095 | Holden New Zealand |
| 4026830 | Fuel Feed Pipe Replacement | 1720500 | GMK Overseas |
| 4026850 | Fuel Return Pipe Replacement | L0121 | GMNA |
| 4026850 | Fuel Return Pipe Replacement | L0125 | GMNA |
| 4026850 | Fuel Return Pipe Replacement | J494250 | Holden Australia |
| 4026850 | Fuel Return Pipe Replacement | L000242 | Holden New Zealand |
| 4026930 | Fuel Feed Front Pipe Replacement | L0158 | GMNA |
| 4026930 | Fuel Feed Front Pipe Replacement | J854300 | Holden New Zealand |
| 4026950 | Fuel Feed Rear Pipe Replacement | L0159 | GMNA |
| 4026950 | Fuel Feed Rear Pipe Replacement | L000242 | Holden Australia |
| 4026990 | Fuel Feed Intermediate Pipe Replacement | F1455 | GMNA |
| 4026990 | Fuel Feed Intermediate Pipe Replacement | L0170 | GMNA |
| 4026990 | Fuel Feed Intermediate Pipe Replacement | F165000 | Holden New Zealand |
| 4026990 | Fuel Feed Intermediate Pipe Replacement | F506200 | Holden New Zealand |
| 4027000 | Diesel Fuel Separator Replacement | | |
| 4027050 | Evaporative Emission Line Replacement - Engine to Chassis | L0220 | GMNA |
| 4027050 | Evaporative Emission Line Replacement - Engine to Chassis | L0260 | GMNA |
| 4027050 | Evaporative Emission Line Replacement - Engine to Chassis | L0262 | GMNA |
| 4027050 | Evaporative Emission Line Replacement - Engine to Chassis | L0263 | GMNA |
| 4027050 | Evaporative Emission Line Replacement - Engine to Chassis | K4126 | Holden Australia |
| 4027050 | Evaporative Emission Line Replacement - Engine to Chassis | L022000 | Holden Australia |
| 4027050 | Evaporative Emission Line Replacement - Engine to Chassis | L0100 | Holden New Zealand |
| 4027050 | Evaporative Emission Line Replacement - Engine to Chassis | L0120 | Holden New Zealand |
| 4027110 | Evaporative Emission Canister Vent Front Pipe Replacement | L0223 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4027130 | Evaporative Emission Canister Vent Rear Pipe Replacement | L0224 | GMNA |
| 4027170 | Fuel Feed Hose Replacement | F1050 | GMNA |
| 4027170 | Fuel Feed Hose Replacement | L0241 | GMNA |
| 4027170 | Fuel Feed Hose Replacement | 1520100 | GMK Domestic |
| 4027170 | Fuel Feed Hose Replacement | 1520101 | GMK Domestic |
| 4027170 | Fuel Feed Hose Replacement | 1620800 | GMK Domestic |
| 4027170 | Fuel Feed Hose Replacement | T681101 | Holden Australia |
| 4027170 | Fuel Feed Hose Replacement | T681101 | Holden New Zealand |
| 4027170 | Fuel Feed Hose Replacement | 1720800 | GMK Overseas |
| 4027170 | Fuel Feed Hose Replacement | 1723100 | GMK Overseas |
| 4027210 | Evaporative Emission Canister Hose Replacement | L0261 | GMNA |
| 4027240 | Fuel Line Replacement - Filter to Tank | | |
| 4027260 | Fuel Line Replacement - Chassis | L0244 | GMNA |
| 4027270 | Evaporative Emission Canister Air Inlet Hose Replacement | L0222 | GMNA |
| 4027270 | Evaporative Emission Canister Air Inlet Hose Replacement | L0264 | GMNA |
| 4027270 | Evaporative Emission Canister Air Inlet Hose Replacement | L0290 | GMNA |
| 4027270 | Evaporative Emission Canister Air Inlet Hose Replacement | 1461200 | GMK Domestic |
| 4027270 | Evaporative Emission Canister Air Inlet Hose Replacement | 1732100 | GMK Overseas |
| 4027290 | Evaporative Emission Canister Control Valve Vacuum Hose Replacement | L0265 | GMNA |
| 4027310 | Evaporative Emission Line Replacement - Chassis | L0269 | GMNA |
| 4027330 | Evaporative Emission Line Replacement - Canister to Tank | F9708 | GMNA |
| 4027330 | Evaporative Emission Line Replacement - Canister to Tank | L0270 | GMNA |
| 4027330 | Evaporative Emission Line Replacement - Canister to Tank | L0274 | GMNA |
| 4027330 | Evaporative Emission Line Replacement - Canister to Tank | K4140 | Holden New Zealand |
| 4027350 | Evaporative Emission System Hose/Pipe Replacement | L0271 | GMNA |
| 4027350 | Evaporative Emission System Hose/Pipe Replacement | L0272 | GMNA |
| 4027350 | Evaporative Emission System Hose/Pipe Replacement | L011100 | Holden Australia |
| 4027390 | Evaporative Emission Line Replacement - Tank | L0273 | GMNA |
| 4027390 | Evaporative Emission Line Replacement - Tank | F000188 | Holden Australia |
| 4027390 | Evaporative Emission Line Replacement - Tank | L0160 | Holden Australia |
| 4027390 | Evaporative Emission Line Replacement - Tank | 1720700 | GMK Overseas |
| 4027390 | Evaporative Emission Line Replacement - Tank | 1730900 | GMK Overseas |
| 4027390 | Evaporative Emission Line Replacement - Tank | 1731100 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4027430 | Evaporative Emission Line Replacement - Chassis to Canister | L0275 | GMNA |
| 4027430 | Evaporative Emission Line Replacement - Chassis to Canister | L0600 | GMNA |
| 4027430 | Evaporative Emission Line Replacement - Chassis to Canister | L015100 | Holden Australia |
| 4027430 | Evaporative Emission Line Replacement - Chassis to Canister | F000188 | Holden New Zealand |
| 4027430 | Evaporative Emission Line Replacement - Chassis to Canister | L015100 | Holden New Zealand |
| 4027450 | Evaporative Emission Rear Hose Replacement | L0277 | GMNA |
| 4027490 | Fuel Feed and Evaporative Emission Hose Replacement | L0281 | GMNA |
| 4027530 | Fuel Pump Fuel Feed Hose Replacement | L0283 | GMNA |
| 4027530 | Fuel Pump Fuel Feed Hose Replacement | L007200 | Holden New Zealand |
| 4027810 | Evaporative Emission System Vacuum Leak Detection Pump Replacement | L0612 | GMNA |
| 4027830 | Auxiliary Evaporative Emission Canister Replacement | L0613 | GMNA |
| 4027850 | Evaporative Emission Canister Vent Solenoid Valve Hose Replacement | J6980 | GMNA |
| 4027850 | Evaporative Emission Canister Vent Solenoid Valve Hose Replacement | J8380 | GMNA |
| 4027850 | Evaporative Emission Canister Vent Solenoid Valve Hose Replacement | L0614 | GMNA |
| 4027850 | Evaporative Emission Canister Vent Solenoid Valve Hose Replacement | H1740 | Holden New Zealand |
| 4027890 | Evaporative Emission Canister Vent Solenoid Valve Replacement | J6441 | GMNA |
| 4027890 | Evaporative Emission Canister Vent Solenoid Valve Replacement | J7908 | GMNA |
| 4027890 | Evaporative Emission Canister Vent Solenoid Valve Replacement | J7928 | GMNA |
| 4027890 | Evaporative Emission Canister Vent Solenoid Valve Replacement | L0616 | GMNA |
| 4027890 | Evaporative Emission Canister Vent Solenoid Valve Replacement | L0619 | GMNA |
| 4027890 | Evaporative Emission Canister Vent Solenoid Valve Replacement | L0625 | GMNA |
| 4027890 | Evaporative Emission Canister Vent Solenoid Valve Replacement | 1461600 | GMK Domestic |
| 4027890 | Evaporative Emission Canister Vent Solenoid Valve Replacement | F2022 | Holden New Zealand |
| 4027890 | Evaporative Emission Canister Vent Solenoid Valve Replacement | L002400 | Holden New Zealand |
| 4027890 | Evaporative Emission Canister Vent Solenoid Valve Replacement | 1732400 | GMK Overseas |
| 4027910 | Evaporative Emission Canister Solenoid Replacement | L0617 | GMNA |
| 4027930 | Fuel Tank Pressure Sensor Replacement | J6327 | GMNA |
| 4027930 | Fuel Tank Pressure Sensor Replacement | J7821 | GMNA |
| 4027930 | Fuel Tank Pressure Sensor Replacement | J7823 | GMNA |
| 4027930 | Fuel Tank Pressure Sensor Replacement | J7937 | GMNA |
| 4027930 | Fuel Tank Pressure Sensor Replacement | J8397 | GMNA |
| 4027930 | Fuel Tank Pressure Sensor Replacement | L0618 | GMNA |
| 4027930 | Fuel Tank Pressure Sensor Replacement | L0622 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4027930 | Fuel Tank Pressure Sensor Replacement | L701200 | Holden Australia |
| 4027930 | Fuel Tank Pressure Sensor Replacement | L015200 | Holden New Zealand |
| 4027930 | Fuel Tank Pressure Sensor Replacement | L070000 | Holden New Zealand |
| 4027930 | Fuel Tank Pressure Sensor Replacement | L701200 | Holden New Zealand |
| 4027950 | Evaporative Emission Canister Replacement | J8379 | GMNA |
| 4027950 | Evaporative Emission Canister Replacement | L0620 | GMNA |
| 4027950 | Evaporative Emission Canister Replacement | 1460700 | GMK Domestic |
| 4027950 | Evaporative Emission Canister Replacement | L014100 | Holden Australia |
| 4027950 | Evaporative Emission Canister Replacement | F2024 | Holden New Zealand |
| 4027950 | Evaporative Emission Canister Replacement | 1731500 | GMK Overseas |
| 4027950 | Evaporative Emission Canister Replacement | 173150A | GMK Overseas |
| 4027970 | Fuel Tank Vent Valve Replacement | J6325 | GMNA |
| 4027970 | Fuel Tank Vent Valve Replacement | J8377 | GMNA |
| 4027970 | Fuel Tank Vent Valve Replacement | L0626 | GMNA |
| 4027970 | Fuel Tank Vent Valve Replacement | L0760 | GMNA |
| 4027970 | Fuel Tank Vent Valve Replacement | L050000 | Holden Australia |
| 4027970 | Fuel Tank Vent Valve Replacement | L701400 | Holden Australia |
| 4027970 | Fuel Tank Vent Valve Replacement | L701450 | Holden Australia |
| 4027970 | Fuel Tank Vent Valve Replacement | L050000 | Holden New Zealand |
| 4027990 | Flexible Fuel Sensor Replacement | L0627 | GMNA |
| 4028130 | Fuel Cooler Replacement | L0750 | GMNA |
| 4028150 | Fuel Cooler Inlet Hose Replacement | L0751 | GMNA |
| 4028150 | Fuel Cooler Inlet Hose Replacement | F2135 | Holden New Zealand |
| 4028150 | Fuel Cooler Inlet Hose Replacement | F2136 | Holden New Zealand |
| 4028170 | Fuel Strainer Bowl Replacement | J5595 | GMNA |
| 4028170 | Fuel Strainer Bowl Replacement | L0752 | GMNA |
| 4028170 | Fuel Strainer Bowl Replacement | L006320 | Holden Australia |
| 4028170 | Fuel Strainer Bowl Replacement | F212200 | Holden New Zealand |
| 4028170 | Fuel Strainer Bowl Replacement | F2137 | Holden New Zealand |
| 4028170 | Fuel Strainer Bowl Replacement | F213700 | Holden New Zealand |
| 4028170 | Fuel Strainer Bowl Replacement | L006320 | Holden New Zealand |
| 4028250 | Fuel Tank Filler Cap Replacement | I9183 | GMNA |
| 4028250 | Fuel Tank Filler Cap Replacement | L1020 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4028250 | Fuel Tank Filler Cap Replacement | L9714 | GMNA |
| 4028250 | Fuel Tank Filler Cap Replacement | R9183 | GMNA |
| 4028250 | Fuel Tank Filler Cap Replacement | R9733 | GMNA |
| 4028250 | Fuel Tank Filler Cap Replacement | T5790 | GMNA |
| 4028250 | Fuel Tank Filler Cap Replacement | T5791 | GMNA |
| 4028250 | Fuel Tank Filler Cap Replacement | 1450120 | GMK Domestic |
| 4028250 | Fuel Tank Filler Cap Replacement | 1450200 | GMK Domestic |
| 4028250 | Fuel Tank Filler Cap Replacement | 1450300 | GMK Domestic |
| 4028250 | Fuel Tank Filler Cap Replacement | L006400 | Holden Australia |
| 4028250 | Fuel Tank Filler Cap Replacement | L1020 | Holden Australia |
| 4028250 | Fuel Tank Filler Cap Replacement | L102000 | Holden Australia |
| 4028250 | Fuel Tank Filler Cap Replacement | L700400 | Holden Australia |
| 4028250 | Fuel Tank Filler Cap Replacement | L702500 | Holden Australia |
| 4028250 | Fuel Tank Filler Cap Replacement | R606000 | Holden Australia |
| 4028250 | Fuel Tank Filler Cap Replacement | L006400 | Holden New Zealand |
| 4028250 | Fuel Tank Filler Cap Replacement | L1020 | Holden New Zealand |
| 4028250 | Fuel Tank Filler Cap Replacement | L102000 | Holden New Zealand |
| 4028250 | Fuel Tank Filler Cap Replacement | R606000 | Holden New Zealand |
| 4028250 | Fuel Tank Filler Cap Replacement | 1653013 | GMK Overseas |
| 4028250 | Fuel Tank Filler Cap Replacement | 1710600 | GMK Overseas |
| 4028250 | Fuel Tank Filler Cap Replacement | 9660300 | GMK Overseas |
| 4028250 | Fuel Tank Filler Cap Replacement | R796051 | GMK Overseas |
| 4028270 | Fuel Tank Filler Pipe Replacement | F3010 | GMNA |
| 4028270 | Fuel Tank Filler Pipe Replacement | F3011 | GMNA |
| 4028270 | Fuel Tank Filler Pipe Replacement | F3013 | GMNA |
| 4028270 | Fuel Tank Filler Pipe Replacement | L1040 | GMNA |
| 4028270 | Fuel Tank Filler Pipe Replacement | L1065 | GMNA |
| 4028270 | Fuel Tank Filler Pipe Replacement | L1068 | GMNA |
| 4028270 | Fuel Tank Filler Pipe Replacement | L9716 | GMNA |
| 4028270 | Fuel Tank Filler Pipe Replacement | F212200 | Holden Australia |
| 4028270 | Fuel Tank Filler Pipe Replacement | L002100 | Holden Australia |
| 4028270 | Fuel Tank Filler Pipe Replacement | L006330 | Holden Australia |
| 4028270 | Fuel Tank Filler Pipe Replacement | L1068 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4028270 | Fuel Tank Filler Pipe Replacement | L106800 | Holden Australia |
| 4028270 | Fuel Tank Filler Pipe Replacement | F162100 | Holden New Zealand |
| 4028270 | Fuel Tank Filler Pipe Replacement | F213900 | Holden New Zealand |
| 4028270 | Fuel Tank Filler Pipe Replacement | F505500 | Holden New Zealand |
| 4028270 | Fuel Tank Filler Pipe Replacement | L002100 | Holden New Zealand |
| 4028270 | Fuel Tank Filler Pipe Replacement | L006330 | Holden New Zealand |
| 4028270 | Fuel Tank Filler Pipe Replacement | L106800 | Holden New Zealand |
| 4028270 | Fuel Tank Filler Pipe Replacement | L700400 | Holden New Zealand |
| 4028270 | Fuel Tank Filler Pipe Replacement | L701400 | Holden New Zealand |
| 4028270 | Fuel Tank Filler Pipe Replacement | 1710700 | GMK Overseas |
| 4028270 | Fuel Tank Filler Pipe Replacement | 1712000 | GMK Overseas |
| 4028290 | Fuel Tank Vent Pipe Replacement | L1050 | GMNA |
| 4028290 | Fuel Tank Vent Pipe Replacement | E303020 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | F2182 | GMNA |
| 4028390 | Fuel Tank Filler Hose Replacement | H0841 | GMNA |
| 4028390 | Fuel Tank Filler Hose Replacement | K4138 | GMNA |
| 4028390 | Fuel Tank Filler Hose Replacement | K4167 | GMNA |
| 4028390 | Fuel Tank Filler Hose Replacement | K4170 | GMNA |
| 4028390 | Fuel Tank Filler Hose Replacement | L1072 | GMNA |
| 4028390 | Fuel Tank Filler Hose Replacement | L1080 | GMNA |
| 4028390 | Fuel Tank Filler Hose Replacement | L1100 | GMNA |
| 4028390 | Fuel Tank Filler Hose Replacement | 1450600 | GMK Domestic |
| 4028390 | Fuel Tank Filler Hose Replacement | F144000 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | F144100 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | F144500 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | F144700 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | F161000 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | F161100 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | F161700 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | F162000 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | F162100 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | F162700 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | F202200 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4028390 | Fuel Tank Filler Hose Replacement | F202300 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | H0799 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | H403110 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | H406110 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | H406210 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | J564000 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | K400250 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | K416300 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | K416400 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | L002300 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | L702100 | Holden Australia |
| 4028390 | Fuel Tank Filler Hose Replacement | E303500 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | F161000 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | F162000 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | F2023 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | F2028 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | F2680 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | F268100 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | F505000 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | F505200 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | H0800 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | H404100 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | H404200 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | H406120 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | H406220 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | J901100 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | K400250 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | K416400 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | L002300 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | L854410 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | L854500 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | L854510 | Holden New Zealand |
| 4028390 | Fuel Tank Filler Hose Replacement | 171030A | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4028390 | Fuel Tank Filler Hose Replacement | 1710500 | GMK Overseas |
| 4028430 | Fuel Tank Protector Replacement | L1140 | GMNA |
| 4028430 | Fuel Tank Protector Replacement | 1623300 | GMK Domestic |
| 4028430 | Fuel Tank Protector Replacement | L114000 | Holden Australia |
| 4028490 | Fuel Tank Strap Replacement | L1164 | GMNA |
| 4028490 | Fuel Tank Strap Replacement | L1166 | GMNA |
| 4028490 | Fuel Tank Strap Replacement | L1168 | GMNA |
| 4028490 | Fuel Tank Strap Replacement | 1450400 | GMK Domestic |
| 4028490 | Fuel Tank Strap Replacement | 1450700 | GMK Domestic |
| 4028490 | Fuel Tank Strap Replacement | L004100 | Holden Australia |
| 4028490 | Fuel Tank Strap Replacement | 1711500 | GMK Overseas |
| 4028490 | Fuel Tank Strap Replacement | 171150A | GMK Overseas |
| 4028500 | Fuel Tank Vent Valve Hose Replacement | | |
| 4028550 | Fuel Tank Crossover Tube Replacement | L1189 | GMNA |
| 4028570 | Fuel Tank Vent Hose Replacement | F4003 | GMNA |
| 4028570 | Fuel Tank Vent Hose Replacement | H0705 | GMNA |
| 4028570 | Fuel Tank Vent Hose Replacement | H0723 | GMNA |
| 4028570 | Fuel Tank Vent Hose Replacement | H0724 | GMNA |
| 4028570 | Fuel Tank Vent Hose Replacement | H0851 | GMNA |
| 4028570 | Fuel Tank Vent Hose Replacement | H0852 | GMNA |
| 4028570 | Fuel Tank Vent Hose Replacement | H0884 | GMNA |
| 4028570 | Fuel Tank Vent Hose Replacement | J6335 | GMNA |
| 4028570 | Fuel Tank Vent Hose Replacement | L1190 | GMNA |
| 4028570 | Fuel Tank Vent Hose Replacement | L1290 | GMNA |
| 4028570 | Fuel Tank Vent Hose Replacement | L700300 | Holden Australia |
| 4028570 | Fuel Tank Vent Hose Replacement | L700800 | Holden Australia |
| 4028570 | Fuel Tank Vent Hose Replacement | L700900 | Holden Australia |
| 4028570 | Fuel Tank Vent Hose Replacement | L701010 | Holden Australia |
| 4028570 | Fuel Tank Vent Hose Replacement | L701020 | Holden Australia |
| 4028570 | Fuel Tank Vent Hose Replacement | L701040 | Holden Australia |
| 4028570 | Fuel Tank Vent Hose Replacement | L701100 | Holden Australia |
| 4028570 | Fuel Tank Vent Hose Replacement | L701300 | Holden Australia |
| 4028570 | Fuel Tank Vent Hose Replacement | L702200 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4028570 | Fuel Tank Vent Hose Replacement | L702400 | Holden Australia |
| 4028570 | Fuel Tank Vent Hose Replacement | L790000 | Holden Australia |
| 4028570 | Fuel Tank Vent Hose Replacement | L854410 | Holden Australia |
| 4028570 | Fuel Tank Vent Hose Replacement | L854510 | Holden Australia |
| 4028570 | Fuel Tank Vent Hose Replacement | F212300D | Holden New Zealand |
| 4028570 | Fuel Tank Vent Hose Replacement | L011100 | Holden New Zealand |
| 4028590 | Primary Fuel Level Sensor Replacement | F2222 | GMNA |
| 4028590 | Primary Fuel Level Sensor Replacement | F9970 | GMNA |
| 4028590 | Primary Fuel Level Sensor Replacement | L1191 | GMNA |
| 4028590 | Primary Fuel Level Sensor Replacement | F600100 | Holden Australia |
| 4028590 | Primary Fuel Level Sensor Replacement | K206300 | Holden Australia |
| 4028590 | Primary Fuel Level Sensor Replacement | K206400 | Holden Australia |
| 4028590 | Primary Fuel Level Sensor Replacement | L000272 | Holden Australia |
| 4028590 | Primary Fuel Level Sensor Replacement | L000275 | Holden Australia |
| 4028590 | Primary Fuel Level Sensor Replacement | F212900 | Holden New Zealand |
| 4028590 | Primary Fuel Level Sensor Replacement | F600100 | Holden New Zealand |
| 4028590 | Primary Fuel Level Sensor Replacement | J903000 | Holden New Zealand |
| 4028590 | Primary Fuel Level Sensor Replacement | K206300 | Holden New Zealand |
| 4028590 | Primary Fuel Level Sensor Replacement | K206400 | Holden New Zealand |
| 4028590 | Primary Fuel Level Sensor Replacement | L000272 | Holden New Zealand |
| 4028590 | Primary Fuel Level Sensor Replacement | L1220 | Holden New Zealand |
| 4028610 | Secondary Fuel Level Sensor Replacement | L1192 | GMNA |
| 4028630 | Fuel Level Sensor Replacement - Left Side | L1193 | GMNA |
| 4028650 | Fuel Level Sensor Replacement - Right Side | F9711 | GMNA |
| 4028650 | Fuel Level Sensor Replacement - Right Side | J7804 | GMNA |
| 4028650 | Fuel Level Sensor Replacement - Right Side | K9805 | GMNA |
| 4028650 | Fuel Level Sensor Replacement - Right Side | L1194 | GMNA |
| 4028690 | Fuel Level Sensor Replacement | J5610 | GMNA |
| 4028690 | Fuel Level Sensor Replacement | J8378 | GMNA |
| 4028690 | Fuel Level Sensor Replacement | L1197 | GMNA |
| 4028690 | Fuel Level Sensor Replacement | L1197 | Holden Australia |
| 4028690 | Fuel Level Sensor Replacement | L701600 | Holden Australia |
| 4028730 | Fuel Tank Fuel Pump Module Replacement | J5433 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4028730 | Fuel Tank Fuel Pump Module Replacement | L1200 | GMNA |
| 4028730 | Fuel Tank Fuel Pump Module Replacement | J546500 | Holden Australia |
| 4028730 | Fuel Tank Fuel Pump Module Replacement | L1200 | Holden Australia |
| 4028730 | Fuel Tank Fuel Pump Module Replacement | J546500 | Holden New Zealand |
| 4028730 | Fuel Tank Fuel Pump Module Replacement | L1228 | Holden New Zealand |
| 4028730 | Fuel Tank Fuel Pump Module Replacement | L700500 | Holden New Zealand |
| 4028730 | Fuel Tank Fuel Pump Module Replacement | 1710300 | GMK Overseas |
| 4028730 | Fuel Tank Fuel Pump Module Replacement | 1711100 | GMK Overseas |
| 4028730 | Fuel Tank Fuel Pump Module Replacement | 171110A | GMK Overseas |
| 4028750 | Fuel Sender Assembly Replacement | J8382 | GMNA |
| 4028750 | Fuel Sender Assembly Replacement | L1195 | GMNA |
| 4028750 | Fuel Sender Assembly Replacement | L1204 | GMNA |
| 4028750 | Fuel Sender Assembly Replacement | 1511200 | GMK Domestic |
| 4028750 | Fuel Sender Assembly Replacement | 1511300 | GMK Domestic |
| 4028750 | Fuel Sender Assembly Replacement | F2003 | Holden Australia |
| 4028750 | Fuel Sender Assembly Replacement | F653100 | Holden Australia |
| 4028750 | Fuel Sender Assembly Replacement | J491050 | Holden Australia |
| 4028750 | Fuel Sender Assembly Replacement | L000248 | Holden Australia |
| 4028750 | Fuel Sender Assembly Replacement | L006300 | Holden Australia |
| 4028750 | Fuel Sender Assembly Replacement | L700600 | Holden Australia |
| 4028750 | Fuel Sender Assembly Replacement | F653100 | Holden New Zealand |
| 4028750 | Fuel Sender Assembly Replacement | J491050 | Holden New Zealand |
| 4028750 | Fuel Sender Assembly Replacement | L000239 | Holden New Zealand |
| 4028750 | Fuel Sender Assembly Replacement | L000275 | Holden New Zealand |
| 4028750 | Fuel Sender Assembly Replacement | L006300 | Holden New Zealand |
| 4028750 | Fuel Sender Assembly Replacement | L700600 | Holden New Zealand |
| 4028750 | Fuel Sender Assembly Replacement | L701100 | Holden New Zealand |
| 4028750 | Fuel Sender Assembly Replacement | 1711700 | GMK Overseas |
| 4028750 | Fuel Sender Assembly Replacement | 171170A | GMK Overseas |
| 4028770 | Fuel Pump Fuel Reservoir Pump Fuel Strainer Orifice Replacement | L1205 | GMNA |
| 4028790 | Fuel Tank Fuel Pump Module Replacement - Right Side | L1224 | GMNA |
| 4028810 | Fuel Tank Fuel Pump Module Replacement - Left Side | L1225 | GMNA |
| 4028810 | Fuel Tank Fuel Pump Module Replacement - Left Side | L007200 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4028830 | Fuel Tank Fuel Pump Module Replacement - Secondary | J7537 | GMNA |
| 4028830 | Fuel Tank Fuel Pump Module Replacement - Secondary | L1226 | GMNA |
| 4028850 | Fuel Tank Fuel Pump Module Replacement - Rear | L1228 | GMNA |
| 4028850 | Fuel Tank Fuel Pump Module Replacement - Rear | L2610 | Holden New Zealand |
| 4028860 | Fuel Level Sensor Float Replacement | | |
| 4028990 | Compressed Natural Gas Tank Cover Replacement - Aft Tank | | |
| 4029010 | Compressed Natural Gas Tank Cover Replacement - Cargo Tank | L1242 | GMNA |
| 4029030 | Compressed Natural Gas Tank Cover Replacement - Midship Tank | L1243 | GMNA |
| 4029050 | Compressed Natural Gas Tank Replacement - Aft Tank | L1244 | GMNA |
| 4029070 | Compressed Natural Gas Tank Replacement - Cargo Tank | | |
| 4029090 | Compressed Natural Gas Tank Replacement - Midship Tank | | |
| 4029110 | Compressed Natural Gas Tank Filler Valve Receptacle Replacement | L1247 | GMNA |
| 4029130 | CNG Tank High Pressure Shutoff Valve Solenoid Replacement | L1248 | GMNA |
| 4029150 | Compressed Natural Gas Tank Filler Check Valve Replacement | L1249 | GMNA |
| 4029190 | CNG High Pressure Shutoff Valve Replacement | L1251 | GMNA |
| 4029200 | CNG Tank High Pressure Shutoff Valve Replacement | | |
| 4029210 | Compressed Natural Gas Fuel Feed Hose Replacement | L1252 | GMNA |
| 4029220 | Compressed Natural Gas Tank Pressure Relief Valve Replacement | | |
| 4029230 | Compressed Natural Gas Fuel Feed Pipe Tee Replacement | J7829 | GMNA |
| 4029240 | CNG Tank Replacement | | |
| 4029250 | Fuel Tank Replacement | J7816 | GMNA |
| 4029250 | Fuel Tank Replacement | J7819 | GMNA |
| 4029250 | Fuel Tank Replacement | J7822 | GMNA |
| 4029250 | Fuel Tank Replacement | L1260 | GMNA |
| 4029250 | Fuel Tank Replacement | L1282 | GMNA |
| 4029250 | Fuel Tank Replacement | L1288 | GMNA |
| 4029250 | Fuel Tank Replacement | T5792 | GMNA |
| 4029250 | Fuel Tank Replacement | 1450100 | GMK Domestic |
| 4029250 | Fuel Tank Replacement | 1450110 | GMK Domestic |
| 4029250 | Fuel Tank Replacement | DA1710900 | Holden Australia |
| 4029250 | Fuel Tank Replacement | L000287 | Holden Australia |
| 4029250 | Fuel Tank Replacement | L000290 | Holden Australia |
| 4029250 | Fuel Tank Replacement | L001100 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4029250 | Fuel Tank Replacement | L1260 | Holden Australia |
| 4029250 | Fuel Tank Replacement | L128000 | Holden Australia |
| 4029250 | Fuel Tank Replacement | L001100 | Holden New Zealand |
| 4029250 | Fuel Tank Replacement | L1280 | Holden New Zealand |
| 4029250 | Fuel Tank Replacement | L128000 | Holden New Zealand |
| 4029250 | Fuel Tank Replacement | 1710900 | GMK Overseas |
| 4029250 | Fuel Tank Replacement | 171090A | GMK Overseas |
| 4029260 | Compressed Natural Gas Tank Cover Replacement | | |
| 4029270 | Fuel Tank Replacement - Right Side | L1280 | GMNA |
| 4029290 | Fuel Tank Replacement - Left Side | L1000 | GMNA |
| 4029290 | Fuel Tank Replacement - Left Side | L1281 | GMNA |
| 4029290 | Fuel Tank Replacement - Left Side | T5786 | GMNA |
| 4029310 | Auxiliary Fuel Tank Replacement | L1283 | GMNA |
| 4029310 | Auxiliary Fuel Tank Replacement | R9521 | GMNA |
| 4029310 | Auxiliary Fuel Tank Replacement | R9523 | GMNA |
| 4029310 | Auxiliary Fuel Tank Replacement | R9525 | GMNA |
| 4029310 | Auxiliary Fuel Tank Replacement | T5785 | GMNA |
| 4029310 | Auxiliary Fuel Tank Replacement | T5787 | GMNA |
| 4029350 | Cold Start Fuel Reservoir Cap Replacement | L3010 | GMNA |
| 4029350 | Cold Start Fuel Reservoir Cap Replacement | F000200 | Holden Australia |
| 4029350 | Cold Start Fuel Reservoir Cap Replacement | F000200 | Holden New Zealand |
| 4029370 | Cold Start Fuel Injector Seal Replacement | L3050 | GMNA |
| 4029390 | Cold Start Fuel Pump Relay Replacement | L1238 | GMNA |
| 4029390 | Cold Start Fuel Pump Relay Replacement | L3000 | GMNA |
| 4029390 | Cold Start Fuel Pump Relay Replacement | L3100 | GMNA |
| 4029390 | Cold Start Fuel Pump Relay Replacement | L701500 | Holden Australia |
| 4029390 | Cold Start Fuel Pump Relay Replacement | F142700 | Holden New Zealand |
| 4029390 | Cold Start Fuel Pump Relay Replacement | J6547 | Holden New Zealand |
| 4029390 | Cold Start Fuel Pump Relay Replacement | L701010 | Holden New Zealand |
| 4029410 | Fuel Pump Flow Control Module Relay Replacement | N2809 | GMNA |
| 4029490 | Glow Plug Relay Replacement | J4790 | GMNA |
| 4029490 | Glow Plug Relay Replacement | N2913 | GMNA |
| 4029490 | Glow Plug Relay Replacement | J479600 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4029800 | Emission Reduction Fluid Tank Reservoir Replacement | | |
| 4029820 | Emission Reduction Fluid Supply Pump Module Replacement | | |
| 4029859 | Inspection/Maintenance (I/M) - I/M Excessive Emissions Diagnosis - Emissions Testing | J9980 | GMNA |
| 4029859 | Inspection/Maintenance (I/M) - I/M Excessive Emissions Diagnosis - Emissions Testing | J982100 | Holden Australia |
| 4029859 | Inspection/Maintenance (I/M) - I/M Excessive Emissions Diagnosis - Emissions Testing | J9980 | Holden Australia |
| 4029859 | Inspection/Maintenance (I/M) - I/M Excessive Emissions Diagnosis - Emissions Testing | J982100 | Holden New Zealand |
| 4029869 | Inspection/Maintenance (I/M) - Complete System Set Procedure | J9981 | GMNA |
| 4029869 | Inspection/Maintenance (I/M) - Complete System Set Procedure | J9981 | Holden Australia |
| 4029879 | Inspection/Maintenance (I/M) - Evap System Pressure Test - Emissions Testing | J9982 | GMNA |
| 4029929 | Customer Concern Not Duplicated (CCND) - Engine Malfunction Indicator Lamp (MIL) Active | J6997 | GMNA |
| 4029929 | Customer Concern Not Duplicated (CCND) - Engine Malfunction Indicator Lamp (MIL) Active | J9992 | GMNA |
| 4029929 | Customer Concern Not Duplicated (CCND) - Engine Malfunction Indicator Lamp (MIL) Active | J9992 | Holden Australia |
| 4029959 | Customer Concern Not Duplicated (CCND) - Emissions | J9995 | GMNA |
| 4029959 | Customer Concern Not Duplicated (CCND) - Emissions | 1235120 | GMK Domestic |
| 4030010 | Engine Coolant Filler Cap Replacement | | |
| 4030060 | Engine Coolant Level Indicator Module Replacement | | |
| 4030100 | Radiator Drain Cock Replacement | J3040 | GMNA |
| 4030100 | Radiator Drain Cock Replacement | J3537 | GMNA |
| 4030100 | Radiator Drain Cock Replacement | 2110300 | GMK Domestic |
| 4030100 | Radiator Drain Cock Replacement | J304000 | Holden Australia |
| 4030100 | Radiator Drain Cock Replacement | J304000 | Holden New Zealand |
| 4030100 | Radiator Drain Cock Replacement | 1410300 | GMK Overseas |
| 4030170 | Radiator Replacement | B9856 | GMNA |
| 4030170 | Radiator Replacement | J3060 | GMNA |
| 4030170 | Radiator Replacement | J3080 | GMNA |
| 4030170 | Radiator Replacement | J3100 | GMNA |
| 4030170 | Radiator Replacement | J3120 | GMNA |
| 4030170 | Radiator Replacement | J3123 | GMNA |
| 4030170 | Radiator Replacement | J3125 | GMNA |
| 4030170 | Radiator Replacement | J3141 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4030170 | Radiator Replacement | J3163 | GMNA |
| 4030170 | Radiator Replacement | J3210 | GMNA |
| 4030170 | Radiator Replacement | J3211 | GMNA |
| 4030170 | Radiator Replacement | J7611 | GMNA |
| 4030170 | Radiator Replacement | J9100 | GMNA |
| 4030170 | Radiator Replacement | J9110 | GMNA |
| 4030170 | Radiator Replacement | J9120 | GMNA |
| 4030170 | Radiator Replacement | K6352 | GMNA |
| 4030170 | Radiator Replacement | 1633100 | GMK Domestic |
| 4030170 | Radiator Replacement | 2110100 | GMK Domestic |
| 4030170 | Radiator Replacement | J000872 | Holden Australia |
| 4030170 | Radiator Replacement | J000878 | Holden Australia |
| 4030170 | Radiator Replacement | J000881 | Holden Australia |
| 4030170 | Radiator Replacement | J000884 | Holden Australia |
| 4030170 | Radiator Replacement | J000887 | Holden Australia |
| 4030170 | Radiator Replacement | J000990 | Holden Australia |
| 4030170 | Radiator Replacement | J000993 | Holden Australia |
| 4030170 | Radiator Replacement | J308000 | Holden Australia |
| 4030170 | Radiator Replacement | J309000 | Holden Australia |
| 4030170 | Radiator Replacement | J3100 | Holden Australia |
| 4030170 | Radiator Replacement | J312300 | Holden Australia |
| 4030170 | Radiator Replacement | J312700 | Holden Australia |
| 4030170 | Radiator Replacement | J312800 | Holden Australia |
| 4030170 | Radiator Replacement | J312850 | Holden Australia |
| 4030170 | Radiator Replacement | J350000 | Holden Australia |
| 4030170 | Radiator Replacement | J350500 | Holden Australia |
| 4030170 | Radiator Replacement | J352000 | Holden Australia |
| 4030170 | Radiator Replacement | J600500 | Holden Australia |
| 4030170 | Radiator Replacement | J600510 | Holden Australia |
| 4030170 | Radiator Replacement | J600530 | Holden Australia |
| 4030170 | Radiator Replacement | J605599 | Holden Australia |
| 4030170 | Radiator Replacement | J000878 | Holden New Zealand |
| 4030170 | Radiator Replacement | J000881 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4030170 | Radiator Replacement | J3060 | Holden New Zealand |
| 4030170 | Radiator Replacement | J3080 | Holden New Zealand |
| 4030170 | Radiator Replacement | J308000 | Holden New Zealand |
| 4030170 | Radiator Replacement | J309000 | Holden New Zealand |
| 4030170 | Radiator Replacement | J3100 | Holden New Zealand |
| 4030170 | Radiator Replacement | J3120 | Holden New Zealand |
| 4030170 | Radiator Replacement | J3123 | Holden New Zealand |
| 4030170 | Radiator Replacement | J3124 | Holden New Zealand |
| 4030170 | Radiator Replacement | J3125 | Holden New Zealand |
| 4030170 | Radiator Replacement | J350000 | Holden New Zealand |
| 4030170 | Radiator Replacement | J350500 | Holden New Zealand |
| 4030170 | Radiator Replacement | J352000 | Holden New Zealand |
| 4030170 | Radiator Replacement | J600500 | Holden New Zealand |
| 4030170 | Radiator Replacement | J600510 | Holden New Zealand |
| 4030170 | Radiator Replacement | J600530 | Holden New Zealand |
| 4030170 | Radiator Replacement | J605599 | Holden New Zealand |
| 4030170 | Radiator Replacement | 1410500 | GMK Overseas |
| 4030170 | Radiator Replacement | 141050A | GMK Overseas |
| 4030172 | Radiator Reconditioning | 1620120 | GMK Domestic |
| 4030220 | Auxiliary Engine Oil Cooler Replacement | | |
| 4030270 | Engine Oil Cooler Core Replacement | | |
| 4030280 | Engine Oil Cooler Inlet and Outlet Hose Replacement | | |
| 4030380 | Engine Oil Cooler Gasket Replacement | J3030 | GMNA |
| 4030380 | Engine Oil Cooler Gasket Replacement | J3164 | GMNA |
| 4030450 | Engine Oil Cooler Adapter Replacement | J3140 | GMNA |
| 4030460 | Engine Oil Cooler Pipe Replacement | J3170 | GMNA |
| 4030460 | Engine Oil Cooler Pipe Replacement | J3173 | GMNA |
| 4030460 | Engine Oil Cooler Pipe Replacement | J3174 | GMNA |
| 4030460 | Engine Oil Cooler Pipe Replacement | 1322300 | GMK Domestic |
| 4030460 | Engine Oil Cooler Pipe Replacement | 1425700 | GMK Domestic |
| 4030460 | Engine Oil Cooler Pipe Replacement | J116500 | Holden Australia |
| 4030460 | Engine Oil Cooler Pipe Replacement | J601950 | Holden Australia |
| 4030460 | Engine Oil Cooler Pipe Replacement | J116400 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4030460 | Engine Oil Cooler Pipe Replacement | J116500 | Holden New Zealand |
| 4030460 | Engine Oil Cooler Pipe Replacement | 1234200 | GMK Overseas |
| 4030480 | Engine Oil Cooler Coolant Inlet Hose Replacement | | |
| 4030500 | Engine Oil Cooler Inlet Pipe Replacement | 1234000 | GMK Overseas |
| 4030520 | Engine Oil Cooler Outlet Pipe Replacement | 1234100 | GMK Overseas |
| 4030560 | Turbocharger Coolant Feed Pipe Replacement | | |
| 4030570 | Turbocharger Coolant Return Pipe Replacement | J5886 | GMNA |
| 4030630 | Engine Oil Cooler Inlet Hose Replacement | | |
| 4030650 | Engine Oil Cooler Outlet Hose Replacement | J3179 | GMNA |
| 4030690 | Radiator Surge Tank Overflow Hose Replacement | | |
| 4030860 | Radiator Upper Mount Replacement | J3208 | GMNA |
| 4030860 | Radiator Upper Mount Replacement | 2110400 | GMK Domestic |
| 4030860 | Radiator Upper Mount Replacement | 2110500 | GMK Domestic |
| 4030880 | Radiator Lower Mount Replacement | | |
| 4030900 | Radiator Air Upper Seal Replacement | | |
| 4030920 | Radiator Air Seal Replacement | | |
| 4030940 | Radiator Air Lower Seal Replacement | | |
| 4030960 | Radiator Air Inlet Duct Replacement | J6356 | GMNA |
| 4030980 | Radiator Air Side Baffle Replacement - Right Side | | |
| 4031000 | Radiator Air Side Baffle Replacement - Left Side | | |
| 4031080 | Radiator Air Upper Baffle and Deflector Replacement | J3232 | GMNA |
| 4031080 | Radiator Air Upper Baffle and Deflector Replacement | J7531 | GMNA |
| 4031080 | Radiator Air Upper Baffle and Deflector Replacement | N5810 | GMNA |
| 4031080 | Radiator Air Upper Baffle and Deflector Replacement | R9301 | GMNA |
| 4031100 | Radiator Air Lower Baffle and Deflector Replacement | B0770 | GMNA |
| 4031100 | Radiator Air Lower Baffle and Deflector Replacement | J3220 | GMNA |
| 4031100 | Radiator Air Lower Baffle and Deflector Replacement | J3229 | GMNA |
| 4031100 | Radiator Air Lower Baffle and Deflector Replacement | J3233 | GMNA |
| 4031100 | Radiator Air Lower Baffle and Deflector Replacement | J7625 | GMNA |
| 4031120 | Radiator Air Side Baffle and Deflector Replacement | J3230 | GMNA |
| 4031120 | Radiator Air Side Baffle and Deflector Replacement | J3231 | GMNA |
| 4031140 | Radiator Air Baffle Replacement | | |
| 4031160 | Engine Coolant Fan Upper Shroud Replacement | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4031180 | Engine Coolant Fan Lower Shroud Replacement | | |
| 4031200 | Engine Coolant Fan Shroud Replacement | J3242 | GMNA |
| 4031200 | Engine Coolant Fan Shroud Replacement | J3243 | GMNA |
| 4031200 | Engine Coolant Fan Shroud Replacement | J3244 | GMNA |
| 4031200 | Engine Coolant Fan Shroud Replacement | J3245 | GMNA |
| 4031200 | Engine Coolant Fan Shroud Replacement | J3246 | GMNA |
| 4031200 | Engine Coolant Fan Shroud Replacement | J3247 | GMNA |
| 4031200 | Engine Coolant Fan Shroud Replacement | J6220 | GMNA |
| 4031200 | Engine Coolant Fan Shroud Replacement | J9130 | GMNA |
| 4031200 | Engine Coolant Fan Shroud Replacement | J000890 | Holden Australia |
| 4031200 | Engine Coolant Fan Shroud Replacement | J324200 | Holden Australia |
| 4031200 | Engine Coolant Fan Shroud Replacement | J324300 | Holden Australia |
| 4031200 | Engine Coolant Fan Shroud Replacement | J324700 | Holden Australia |
| 4031200 | Engine Coolant Fan Shroud Replacement | J325000 | Holden Australia |
| 4031200 | Engine Coolant Fan Shroud Replacement | J603500 | Holden Australia |
| 4031200 | Engine Coolant Fan Shroud Replacement | J603510 | Holden Australia |
| 4031200 | Engine Coolant Fan Shroud Replacement | J603550 | Holden Australia |
| 4031200 | Engine Coolant Fan Shroud Replacement | J000890 | Holden New Zealand |
| 4031200 | Engine Coolant Fan Shroud Replacement | J3240 | Holden New Zealand |
| 4031200 | Engine Coolant Fan Shroud Replacement | J324700 | Holden New Zealand |
| 4031200 | Engine Coolant Fan Shroud Replacement | J603500 | Holden New Zealand |
| 4031200 | Engine Coolant Fan Shroud Replacement | J603550 | Holden New Zealand |
| 4031200 | Engine Coolant Fan Shroud Replacement | 1430700 | GMK Overseas |
| 4031200 | Engine Coolant Fan Shroud Replacement | 143070A | GMK Overseas |
| 4031280 | Radiator Surge Tank Replacement | D9749 | GMNA |
| 4031280 | Radiator Surge Tank Replacement | D9750 | GMNA |
| 4031280 | Radiator Surge Tank Replacement | J3032 | GMNA |
| 4031280 | Radiator Surge Tank Replacement | J3033 | GMNA |
| 4031280 | Radiator Surge Tank Replacement | J3039 | GMNA |
| 4031280 | Radiator Surge Tank Replacement | J3250 | GMNA |
| 4031280 | Radiator Surge Tank Replacement | J3260 | GMNA |
| 4031280 | Radiator Surge Tank Replacement | J3285 | GMNA |
| 4031280 | Radiator Surge Tank Replacement | J7617 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4031280 | Radiator Surge Tank Replacement | J7629 | GMNA |
| 4031280 | Radiator Surge Tank Replacement | J7935 | GMNA |
| 4031280 | Radiator Surge Tank Replacement | N5020 | GMNA |
| 4031280 | Radiator Surge Tank Replacement | N5040 | GMNA |
| 4031280 | Radiator Surge Tank Replacement | J326000 | Holden Australia |
| 4031280 | Radiator Surge Tank Replacement | J602100 | Holden Australia |
| 4031280 | Radiator Surge Tank Replacement | N359200 | Holden Australia |
| 4031280 | Radiator Surge Tank Replacement | J3260 | Holden New Zealand |
| 4031280 | Radiator Surge Tank Replacement | J326000 | Holden New Zealand |
| 4031280 | Radiator Surge Tank Replacement | J601800 | Holden New Zealand |
| 4031280 | Radiator Surge Tank Replacement | J602100 | Holden New Zealand |
| 4031280 | Radiator Surge Tank Replacement | N359200 | Holden New Zealand |
| 4031280 | Radiator Surge Tank Replacement | 1450400 | GMK Overseas |
| 4031300 | Radiator Surge Tank Engine Hose Replacement | | |
| 4031320 | Coolant Recovery Reservoir Hose Replacement | | |
| 4031340 | Radiator Surge Tank Outlet Hose Replacement | J3251 | GMNA |
| 4031340 | Radiator Surge Tank Outlet Hose Replacement | J3253 | GMNA |
| 4031340 | Radiator Surge Tank Outlet Hose Replacement | J3419 | GMNA |
| 4031340 | Radiator Surge Tank Outlet Hose Replacement | 2121400 | GMK Domestic |
| 4031340 | Radiator Surge Tank Outlet Hose Replacement | J601500 | Holden Australia |
| 4031340 | Radiator Surge Tank Outlet Hose Replacement | J601500 | Holden New Zealand |
| 4031340 | Radiator Surge Tank Outlet Hose Replacement | 1450300 | GMK Overseas |
| 4031340 | Radiator Surge Tank Outlet Hose Replacement | 1451900 | GMK Overseas |
| 4031360 | Radiator Surge Tank Inlet Hose Replacement | J3181 | GMNA |
| 4031360 | Radiator Surge Tank Inlet Hose Replacement | J3254 | GMNA |
| 4031360 | Radiator Surge Tank Inlet Hose Replacement | 2123300 | GMK Domestic |
| 4031360 | Radiator Surge Tank Inlet Hose Replacement | J601600 | Holden Australia |
| 4031360 | Radiator Surge Tank Inlet Hose Replacement | J601600 | Holden New Zealand |
| 4031360 | Radiator Surge Tank Inlet Hose Replacement | 1451200 | GMK Overseas |
| 4031360 | Radiator Surge Tank Inlet Hose Replacement | 1452200 | GMK Overseas |
| 4031380 | Radiator Surge Tank Cap Replacement | B1420 | GMNA |
| 4031380 | Radiator Surge Tank Cap Replacement | J3020 | GMNA |
| 4031380 | Radiator Surge Tank Cap Replacement | J3255 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4031380 | Radiator Surge Tank Cap Replacement | 2110200 | GMK Domestic |
| 4031380 | Radiator Surge Tank Cap Replacement | 2121000 | GMK Domestic |
| 4031380 | Radiator Surge Tank Cap Replacement | J3020 | Holden Australia |
| 4031380 | Radiator Surge Tank Cap Replacement | J302000 | Holden Australia |
| 4031380 | Radiator Surge Tank Cap Replacement | J600100 | Holden Australia |
| 4031380 | Radiator Surge Tank Cap Replacement | J600150 | Holden Australia |
| 4031380 | Radiator Surge Tank Cap Replacement | J3020 | Holden New Zealand |
| 4031380 | Radiator Surge Tank Cap Replacement | J600100 | Holden New Zealand |
| 4031380 | Radiator Surge Tank Cap Replacement | J600150 | Holden New Zealand |
| 4031380 | Radiator Surge Tank Cap Replacement | 1410700 | GMK Overseas |
| 4031380 | Radiator Surge Tank Cap Replacement | 1454100 | GMK Overseas |
| 4031400 | Coolant Recovery Reservoir Replacement | 1514800 | GMK Overseas |
| 4031420 | Coolant Recovery Expansion Tank Inlet Hose Replacement | | |
| 4031440 | Coolant Recovery Reservoir Vent Hose Replacement | J3264 | GMNA |
| 4031460 | Engine Coolant Air Bleed Hose Replacement | J3265 | GMNA |
| 4031460 | Engine Coolant Air Bleed Hose Replacement | J3514 | GMNA |
| 4031460 | Engine Coolant Air Bleed Hose Replacement | J326500 | Holden Australia |
| 4031460 | Engine Coolant Air Bleed Hose Replacement | J327000 | Holden Australia |
| 4031460 | Engine Coolant Air Bleed Hose Replacement | J601610 | Holden Australia |
| 4031460 | Engine Coolant Air Bleed Hose Replacement | J326500 | Holden New Zealand |
| 4031460 | Engine Coolant Air Bleed Hose Replacement | J327000 | Holden New Zealand |
| 4031460 | Engine Coolant Air Bleed Hose Replacement | J601610 | Holden New Zealand |
| 4031510 | Water Pump Inlet Hose Replacement | J3301 | GMNA |
| 4031510 | Water Pump Inlet Hose Replacement | 2120500 | GMK Domestic |
| 4031510 | Water Pump Inlet Hose Replacement | 1452100 | GMK Overseas |
| 4031560 | Coolant Recovery Reservoir Outlet Hose Replacement | J3306 | GMNA |
| 4031560 | Coolant Recovery Reservoir Outlet Hose Replacement | J3323 | GMNA |
| 4031560 | Coolant Recovery Reservoir Outlet Hose Replacement | J601650 | Holden Australia |
| 4031560 | Coolant Recovery Reservoir Outlet Hose Replacement | J601710 | Holden Australia |
| 4031560 | Coolant Recovery Reservoir Outlet Hose Replacement | J601650 | Holden New Zealand |
| 4031560 | Coolant Recovery Reservoir Outlet Hose Replacement | 1451600 | GMK Overseas |
| 4031580 | Coolant Recovery Reservoir Inlet Hose Replacement | J3180 | GMNA |
| 4031580 | Coolant Recovery Reservoir Inlet Hose Replacement | J3252 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4031580 | Coolant Recovery Reservoir Inlet Hose Replacement | J3305 | GMNA |
| 4031580 | Coolant Recovery Reservoir Inlet Hose Replacement | J3307 | GMNA |
| 4031580 | Coolant Recovery Reservoir Inlet Hose Replacement | J3322 | GMNA |
| 4031580 | Coolant Recovery Reservoir Inlet Hose Replacement | J3325 | GMNA |
| 4031580 | Coolant Recovery Reservoir Inlet Hose Replacement | J318000 | Holden Australia |
| 4031580 | Coolant Recovery Reservoir Inlet Hose Replacement | J326100 | Holden Australia |
| 4031580 | Coolant Recovery Reservoir Inlet Hose Replacement | J601450 | Holden Australia |
| 4031580 | Coolant Recovery Reservoir Inlet Hose Replacement | J601560 | Holden Australia |
| 4031580 | Coolant Recovery Reservoir Inlet Hose Replacement | J602500 | Holden Australia |
| 4031580 | Coolant Recovery Reservoir Inlet Hose Replacement | J318000 | Holden New Zealand |
| 4031580 | Coolant Recovery Reservoir Inlet Hose Replacement | J601450 | Holden New Zealand |
| 4031580 | Coolant Recovery Reservoir Inlet Hose Replacement | J602500 | Holden New Zealand |
| 4031600 | Radiator Inlet Hose Replacement | J3302 | GMNA |
| 4031600 | Radiator Inlet Hose Replacement | J3303 | GMNA |
| 4031600 | Radiator Inlet Hose Replacement | J3308 | GMNA |
| 4031600 | Radiator Inlet Hose Replacement | J3352 | GMNA |
| 4031600 | Radiator Inlet Hose Replacement | J3357 | GMNA |
| 4031600 | Radiator Inlet Hose Replacement | J8391 | GMNA |
| 4031600 | Radiator Inlet Hose Replacement | J9422 | GMNA |
| 4031600 | Radiator Inlet Hose Replacement | 2120100 | GMK Domestic |
| 4031600 | Radiator Inlet Hose Replacement | J3362 | Holden Australia |
| 4031600 | Radiator Inlet Hose Replacement | J336200 | Holden Australia |
| 4031600 | Radiator Inlet Hose Replacement | J3367 | Holden Australia |
| 4031600 | Radiator Inlet Hose Replacement | J336700 | Holden Australia |
| 4031600 | Radiator Inlet Hose Replacement | J601000 | Holden Australia |
| 4031600 | Radiator Inlet Hose Replacement | J601100 | Holden Australia |
| 4031600 | Radiator Inlet Hose Replacement | J601980 | Holden Australia |
| 4031600 | Radiator Inlet Hose Replacement | J602200 | Holden Australia |
| 4031600 | Radiator Inlet Hose Replacement | J602300 | Holden Australia |
| 4031600 | Radiator Inlet Hose Replacement | J3362 | Holden New Zealand |
| 4031600 | Radiator Inlet Hose Replacement | J336200 | Holden New Zealand |
| 4031600 | Radiator Inlet Hose Replacement | J3367 | Holden New Zealand |
| 4031600 | Radiator Inlet Hose Replacement | J336700 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4031600 | Radiator Inlet Hose Replacement | J601000 | Holden New Zealand |
| 4031600 | Radiator Inlet Hose Replacement | J601100 | Holden New Zealand |
| 4031600 | Radiator Inlet Hose Replacement | J601680 | Holden New Zealand |
| 4031600 | Radiator Inlet Hose Replacement | J602200 | Holden New Zealand |
| 4031600 | Radiator Inlet Hose Replacement | J602200A2 | Holden New Zealand |
| 4031600 | Radiator Inlet Hose Replacement | 1450700 | GMK Overseas |
| 4031620 | Radiator Outlet Hose Replacement | J3309 | GMNA |
| 4031620 | Radiator Outlet Hose Replacement | J3310 | GMNA |
| 4031620 | Radiator Outlet Hose Replacement | J3353 | GMNA |
| 4031620 | Radiator Outlet Hose Replacement | J3370 | GMNA |
| 4031620 | Radiator Outlet Hose Replacement | J9423 | GMNA |
| 4031620 | Radiator Outlet Hose Replacement | J3363 | Holden Australia |
| 4031620 | Radiator Outlet Hose Replacement | J336300 | Holden Australia |
| 4031620 | Radiator Outlet Hose Replacement | J601200 | Holden Australia |
| 4031620 | Radiator Outlet Hose Replacement | J601210 | Holden Australia |
| 4031620 | Radiator Outlet Hose Replacement | J601510 | Holden Australia |
| 4031620 | Radiator Outlet Hose Replacement | J601520 | Holden Australia |
| 4031620 | Radiator Outlet Hose Replacement | J3363 | Holden New Zealand |
| 4031620 | Radiator Outlet Hose Replacement | J336300 | Holden New Zealand |
| 4031620 | Radiator Outlet Hose Replacement | J601200 | Holden New Zealand |
| 4031620 | Radiator Outlet Hose Replacement | J601210 | Holden New Zealand |
| 4031620 | Radiator Outlet Hose Replacement | J601510 | Holden New Zealand |
| 4031620 | Radiator Outlet Hose Replacement | 1450800 | GMK Overseas |
| 4031620 | Radiator Outlet Hose Replacement | 1457100 | GMK Overseas |
| 4031640 | Radiator Outlet Front Hose Replacement | | |
| 4031660 | Radiator Vent Inlet Hose Replacement | J3311 | GMNA |
| 4031680 | Radiator Vent Outlet Hose Replacement | | |
| 4031700 | Radiator Bypass Hose Replacement | | |
| 4031720 | Radiator Vent Valve Replacement | J3314 | GMNA |
| 4031740 | Radiator Inlet Front Hose Replacement | | |
| 4031760 | Radiator Inlet Rear Hose Replacement | | |
| 4031800 | Coolant Recovery Reservoir Pipe Replacement | | |
| 4031850 | Radiator Outlet Hose Connector Replacement - Radiator Side | J3341 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4031850 | Radiator Outlet Hose Connector Replacement - Radiator Side | 1450500 | GMK Overseas |
| 4031850 | Radiator Outlet Hose Connector Replacement - Radiator Side | 145050A | GMK Overseas |
| 4031870 | Radiator Outlet Hose Connector Replacement- Engine Side | J3342 | GMNA |
| 4031890 | Radiator Outlet Pipe Replacement | | |
| 4032000 | Throttle Body Heater Inlet Hose Replacement | J3368 | GMNA |
| 4032000 | Throttle Body Heater Inlet Hose Replacement | K4128 | GMNA |
| 4032000 | Throttle Body Heater Inlet Hose Replacement | 1451800 | GMK Overseas |
| 4032000 | Throttle Body Heater Inlet Hose Replacement | 1454600 | GMK Overseas |
| 4032000 | Throttle Body Heater Inlet Hose Replacement | 1454800 | GMK Overseas |
| 4032020 | Throttle Body Heater Outlet Hose Replacement | J3369 | GMNA |
| 4032020 | Throttle Body Heater Outlet Hose Replacement | 2120600 | GMK Domestic |
| 4032020 | Throttle Body Heater Outlet Hose Replacement | 1451700 | GMK Overseas |
| 4032020 | Throttle Body Heater Outlet Hose Replacement | 1454700 | GMK Overseas |
| 4032040 | Throttle Body Heater Inlet Pipe Replacement | | |
| 4032060 | Throttle Body Heater Outlet Pipe Replacement | J3371 | GMNA |
| 4032110 | Engine Coolant Inlet Pipe Replacement | J608200 | Holden Australia |
| 4032110 | Engine Coolant Inlet Pipe Replacement | J608200 | Holden New Zealand |
| 4032130 | Engine Coolant Inlet Hose Replacement | J3379 | GMNA |
| 4032150 | Fan Blade Replacement | | |
| 4032170 | Fan Clutch Replacement | J3390 | GMNA |
| 4032170 | Fan Clutch Replacement | J9220 | GMNA |
| 4032170 | Fan Clutch Replacement | J3390 | Holden Australia |
| 4032170 | Fan Clutch Replacement | J339000 | Holden Australia |
| 4032170 | Fan Clutch Replacement | J606550 | Holden Australia |
| 4032170 | Fan Clutch Replacement | J3390 | Holden New Zealand |
| 4032170 | Fan Clutch Replacement | J339000 | Holden New Zealand |
| 4032170 | Fan Clutch Replacement | J606550 | Holden New Zealand |
| 4032190 | Fan Pulley Replacement | J3393 | GMNA |
| 4032190 | Fan Pulley Replacement | J0701 | Holden New Zealand |
| 4032210 | Fan Control Module Replacement | J3395 | GMNA |
| 4032260 | Engine Coolant Fan Replacement | J3375 | GMNA |
| 4032260 | Engine Coolant Fan Replacement | J3380 | GMNA |
| 4032260 | Engine Coolant Fan Replacement | J9200 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4032260 | Engine Coolant Fan Replacement | J9210 | GMNA |
| 4032260 | Engine Coolant Fan Replacement | 1630100 | GMK Domestic |
| 4032260 | Engine Coolant Fan Replacement | 1633000 | GMK Domestic |
| 4032260 | Engine Coolant Fan Replacement | 2130400 | GMK Domestic |
| 4032260 | Engine Coolant Fan Replacement | 2130600 | GMK Domestic |
| 4032260 | Engine Coolant Fan Replacement | J3380 | Holden Australia |
| 4032260 | Engine Coolant Fan Replacement | J606100 | Holden Australia |
| 4032260 | Engine Coolant Fan Replacement | J606150 | Holden Australia |
| 4032260 | Engine Coolant Fan Replacement | J3380 | Holden New Zealand |
| 4032260 | Engine Coolant Fan Replacement | J606100 | Holden New Zealand |
| 4032260 | Engine Coolant Fan Replacement | J606150 | Holden New Zealand |
| 4032260 | Engine Coolant Fan Replacement | J606500 | Holden New Zealand |
| 4032260 | Engine Coolant Fan Replacement | 1430900 | GMK Overseas |
| 4032260 | Engine Coolant Fan Replacement | 1431100 | GMK Overseas |
| 4032280 | Engine Coolant Fan Motor Replacement | J3403 | GMNA |
| 4032280 | Engine Coolant Fan Motor Replacement | J337300 | Holden Australia |
| 4032280 | Engine Coolant Fan Motor Replacement | J341000 | Holden Australia |
| 4032280 | Engine Coolant Fan Motor Replacement | J606810 | Holden Australia |
| 4032280 | Engine Coolant Fan Motor Replacement | 1431200 | GMK Overseas |
| 4032280 | Engine Coolant Fan Motor Replacement | 1431300 | GMK Overseas |
| 4032280 | Engine Coolant Fan Motor Replacement | 1431500 | GMK Overseas |
| 4032300 | Engine Coolant Fan Resistor Replacement - Right Side | J3404 | GMNA |
| 4032320 | Engine Coolant Fan Resistor Replacement - Left Side | | |
| 4032370 | Auxiliary Engine Coolant Fan and Fan Motor Replacement | 2130100 | GMK Domestic |
| 4032370 | Auxiliary Engine Coolant Fan and Fan Motor Replacement | 1431400 | GMK Overseas |
| 4032390 | Engine Coolant Fan Resistor Replacement | J3410 | GMNA |
| 4032390 | Engine Coolant Fan Resistor Replacement | J3411 | GMNA |
| 4032390 | Engine Coolant Fan Resistor Replacement | 8211600 | GMK Domestic |
| 4032390 | Engine Coolant Fan Resistor Replacement | J606200 | Holden Australia |
| 4032390 | Engine Coolant Fan Resistor Replacement | 9280100 | GMK Overseas |
| 4032440 | Drive Belt Tensioner Replacement - Water Pump | J3421 | GMNA |
| 4032460 | Drive Belt Tensioner Shield Replacement | | |
| 4032510 | Thermostat Bypass Hose Replacement | J3458 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4032530 | Thermostat Bypass Pipe Replacement | J3459 | GMNA |
| 4032580 | Heater Water Bypass Inlet Hose Replacement | J3463 | GMNA |
| 4032580 | Heater Water Bypass Inlet Hose Replacement | D111300 | Holden Australia |
| 4032580 | Heater Water Bypass Inlet Hose Replacement | D111300 | Holden New Zealand |
| 4032580 | Heater Water Bypass Inlet Hose Replacement | J336900 | Holden New Zealand |
| 4032590 | Heater Outlet Pipe Replacement | | |
| 4032660 | Water Outlet Tube Replacement | | |
| 4032680 | Water Outlet Replacement | J608100 | Holden Australia |
| 4032690 | Water Pump Inlet Pipe Replacement | | |
| 4032720 | Water Pump Belt Replacement | J0669 | GMNA |
| 4032720 | Water Pump Belt Replacement | 2132000 | GMK Domestic |
| 4032730 | Water Pump Sprocket Replacement | J3476 | GMNA |
| 4032750 | Water Pump Replacement | J3417 | GMNA |
| 4032750 | Water Pump Replacement | J3430 | GMNA |
| 4032750 | Water Pump Replacement | J3462 | GMNA |
| 4032750 | Water Pump Replacement | J3475 | GMNA |
| 4032750 | Water Pump Replacement | J3478 | GMNA |
| 4032750 | Water Pump Replacement | J3480 | GMNA |
| 4032750 | Water Pump Replacement | J3485 | GMNA |
| 4032750 | Water Pump Replacement | J3495 | GMNA |
| 4032750 | Water Pump Replacement | 1820100 | GMK Domestic |
| 4032750 | Water Pump Replacement | 2100120 | GMK Domestic |
| 4032750 | Water Pump Replacement | J3480 | Holden Australia |
| 4032750 | Water Pump Replacement | J609100 | Holden Australia |
| 4032750 | Water Pump Replacement | J3462 | Holden New Zealand |
| 4032750 | Water Pump Replacement | J3480 | Holden New Zealand |
| 4032750 | Water Pump Replacement | J3485 | Holden New Zealand |
| 4032750 | Water Pump Replacement | J609100 | Holden New Zealand |
| 4032750 | Water Pump Replacement | J609100A | Holden New Zealand |
| 4032750 | Water Pump Replacement | 1333500 | GMK Overseas |
| 4032750 | Water Pump Replacement | 133350A | GMK Overseas |
| 4032750 | Water Pump Replacement | 133350B | GMK Overseas |
| 4032750 | Water Pump Replacement | 1336700 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4032770 | Water Pump Outlet Pipe Replacement | J3470 | GMNA |
| 4032770 | Water Pump Outlet Pipe Replacement | J3484 | GMNA |
| 4032770 | Water Pump Outlet Pipe Replacement | J3513 | GMNA |
| 4032770 | Water Pump Outlet Pipe Replacement | J461710 | Holden Australia |
| 4032770 | Water Pump Outlet Pipe Replacement | J461730 | Holden Australia |
| 4032770 | Water Pump Outlet Pipe Replacement | J608110 | Holden Australia |
| 4032770 | Water Pump Outlet Pipe Replacement | J609150 | Holden Australia |
| 4032770 | Water Pump Outlet Pipe Replacement | J3483 | Holden New Zealand |
| 4032770 | Water Pump Outlet Pipe Replacement | J461710 | Holden New Zealand |
| 4032770 | Water Pump Outlet Pipe Replacement | J461730 | Holden New Zealand |
| 4032770 | Water Pump Outlet Pipe Replacement | J608110 | Holden New Zealand |
| 4032770 | Water Pump Outlet Pipe Replacement | J609150 | Holden New Zealand |
| 4032790 | Engine Water Outlet Adapter Replacement | J3486 | GMNA |
| 4032790 | Engine Water Outlet Adapter Replacement | 1612200 | GMK Domestic |
| 4032790 | Engine Water Outlet Adapter Replacement | 1481500 | GMK Overseas |
| 4032790 | Engine Water Outlet Adapter Replacement | 1481600 | GMK Overseas |
| 4032800 | Water Pump Pulley Replacement | J3420 | GMNA |
| 4032800 | Water Pump Pulley Replacement | J3422 | GMNA |
| 4032800 | Water Pump Pulley Replacement | J3420 | Holden Australia |
| 4032800 | Water Pump Pulley Replacement | J606600 | Holden Australia |
| 4032800 | Water Pump Pulley Replacement | J606600 | Holden New Zealand |
| 4032800 | Water Pump Pulley Replacement | 1333600 | GMK Overseas |
| 4032810 | Engine Coolant Thermostat Replacement | J3500 | GMNA |
| 4032810 | Engine Coolant Thermostat Replacement | J3503 | GMNA |
| 4032810 | Engine Coolant Thermostat Replacement | J3504 | GMNA |
| 4032810 | Engine Coolant Thermostat Replacement | J000541 | Holden Australia |
| 4032810 | Engine Coolant Thermostat Replacement | J608130 | Holden Australia |
| 4032810 | Engine Coolant Thermostat Replacement | J3500 | Holden New Zealand |
| 4032810 | Engine Coolant Thermostat Replacement | J3502 | Holden New Zealand |
| 4032810 | Engine Coolant Thermostat Replacement | J3503 | Holden New Zealand |
| 4032810 | Engine Coolant Thermostat Replacement | J608130 | Holden New Zealand |
| 4032810 | Engine Coolant Thermostat Replacement | 1480300 | GMK Overseas |
| 4032810 | Engine Coolant Thermostat Replacement | 1480500 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4032810 | Engine Coolant Thermostat Replacement | 148050A | GMK Overseas |
| 4032810 | Engine Coolant Thermostat Replacement | 148050X | GMK Overseas |
| 4032810 | Engine Coolant Thermostat Replacement | R014069 | GMK Overseas |
| 4032830 | Engine Coolant Thermostat Housing Replacement | J3501 | GMNA |
| 4032830 | Engine Coolant Thermostat Housing Replacement | J3510 | GMNA |
| 4032830 | Engine Coolant Thermostat Housing Replacement | J6260 | GMNA |
| 4032830 | Engine Coolant Thermostat Housing Replacement | N3500 | GMNA |
| 4032830 | Engine Coolant Thermostat Housing Replacement | J608500 | Holden Australia |
| 4032830 | Engine Coolant Thermostat Housing Replacement | J3501 | Holden New Zealand |
| 4032830 | Engine Coolant Thermostat Housing Replacement | J608500 | Holden New Zealand |
| 4032830 | Engine Coolant Thermostat Housing Replacement | 1480700 | GMK Overseas |
| 4032830 | Engine Coolant Thermostat Housing Replacement | 1480900 | GMK Overseas |
| 4032870 | Engine Coolant Outlet Pipe Replacement | J3362 | GMNA |
| 4032870 | Engine Coolant Outlet Pipe Replacement | J3506 | GMNA |
| 4032890 | Engine Oil Cooler Connector Replacement | | |
| 4032900 | Engine Oil Cooler Replacement | 1231600 | GMK Overseas |
| 4032910 | Exhaust Gas Recirculation Cooling Pipe Replacement - Upper | J3508 | GMNA |
| 4032910 | Exhaust Gas Recirculation Cooling Pipe Replacement - Upper | 1933500 | GMK Overseas |
| 4032930 | Exhaust Gas Recirculation Cooling Pipe Replacement - Lower | J3509 | GMNA |
| 4032930 | Exhaust Gas Recirculation Cooling Pipe Replacement - Lower | 1933400 | GMK Overseas |
| 4032950 | Exhaust Gas Recirculation Cooler Water Bypass Outlet Hose Replacement | J3511 | GMNA |
| 4032990 | Exhaust Gas Recirculation Manifold Cooling Return Hose Replacement | | |
| 4033000 | Engine Coolant Air Bleed Pipe Replacement | | |
| 4033140 | Engine Coolant Thermostat Lower Housing Replacement | J3519 | GMNA |
| 4033180 | Engine Coolant Heater Replacement | | |
| 4033190 | Engine Coolant Heater Replacement - Left Side | J3521 | GMNA |
| 4033190 | Engine Coolant Heater Replacement - Left Side | J3521 | Holden New Zealand |
| 4033240 | Engine Coolant Heater Cord Replacement | J3523 | GMNA |
| 4033240 | Engine Coolant Heater Cord Replacement | 1481800 | GMK Overseas |
| 4033260 | Engine Coolant Heater Replacement - Right Side | | |
| 4033340 | Engine Coolant Crossover Pipe Replacement | J3465 | GMNA |
| 4033340 | Engine Coolant Crossover Pipe Replacement | J3529 | GMNA |
| 4033340 | Engine Coolant Crossover Pipe Replacement | 1591500 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4033350 | Engine Coolant Temperature Sensor Replacement - Radiator | | |
| 4033392 | Coolant System Flushing | J3000 | GMNA |
| 4033392 | Coolant System Flushing | J3010 | GMNA |
| 4033392 | Coolant System Flushing | J3540 | GMNA |
| 4033392 | Coolant System Flushing | J7552 | GMNA |
| 4033392 | Coolant System Flushing | J7601 | GMNA |
| 4033392 | Coolant System Flushing | J7603 | GMNA |
| 4033392 | Coolant System Flushing | 1600030 | GMK Domestic |
| 4033392 | Coolant System Flushing | 1750300 | GMK Domestic |
| 4033392 | Coolant System Flushing | 1750400 | GMK Domestic |
| 4033392 | Coolant System Flushing | J3540 | Holden Australia |
| 4033392 | Coolant System Flushing | J600520 | Holden Australia |
| 4033392 | Coolant System Flushing | J3540 | Holden New Zealand |
| 4033392 | Coolant System Flushing | PRESTEST | Holden New Zealand |
| 4033392 | Coolant System Flushing | 1411700 | GMK Overseas |
| 4033410 | Auxiliary Water Pump Replacement | J3580 | GMNA |
| 4033410 | Auxiliary Water Pump Replacement | J609200 | Holden Australia |
| 4033410 | Auxiliary Water Pump Replacement | J609200 | Holden New Zealand |
| 4033430 | Auxiliary Water Pump Outlet Upper Hose Replacement | | |
| 4033450 | Auxiliary Water Pump Inlet Hose Replacement | D2785 | GMNA |
| 4033450 | Auxiliary Water Pump Inlet Hose Replacement | J3585 | GMNA |
| 4033450 | Auxiliary Water Pump Inlet Hose Replacement | J601620 | Holden Australia |
| 4033470 | Auxiliary Water Pump Outlet Hose Replacement | J3584 | GMNA |
| 4033470 | Auxiliary Water Pump Outlet Hose Replacement | J3586 | GMNA |
| 4033490 | Distributor Replacement | J4260 | GMNA |
| 4033490 | Distributor Replacement | J4300 | GMNA |
| 4033490 | Distributor Replacement | J4320 | GMNA |
| 4033490 | Distributor Replacement | J4325 | GMNA |
| 4033490 | Distributor Replacement | J4326 | GMNA |
| 4033490 | Distributor Replacement | J4360 | GMNA |
| 4033490 | Distributor Replacement | J4380 | GMNA |
| 4033490 | Distributor Replacement | J4430 | GMNA |
| 4033490 | Distributor Replacement | J4450 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4033490 | Distributor Replacement | J4460 | GMNA |
| 4033490 | Distributor Replacement | J4480 | GMNA |
| 4033490 | Distributor Replacement | J4485 | GMNA |
| 4033490 | Distributor Replacement | J4490 | GMNA |
| 4033490 | Distributor Replacement | J4520 | GMNA |
| 4033490 | Distributor Replacement | J4530 | GMNA |
| 4033490 | Distributor Replacement | J4535 | GMNA |
| 4033490 | Distributor Replacement | J7706 | GMNA |
| 4033490 | Distributor Replacement | J7707 | GMNA |
| 4033490 | Distributor Replacement | J7708 | GMNA |
| 4033490 | Distributor Replacement | J436000 | Holden Australia |
| 4033490 | Distributor Replacement | J448000 | Holden Australia |
| 4033490 | Distributor Replacement | J452000 | Holden Australia |
| 4033490 | Distributor Replacement | J453000 | Holden Australia |
| 4033490 | Distributor Replacement | J716100 | Holden Australia |
| 4033490 | Distributor Replacement | J723100 | Holden Australia |
| 4033490 | Distributor Replacement | J723100 | Holden New Zealand |
| 4033500 | Charge Air Cooler Replacement | | |
| 4033510 | Charge Air Cooler Coolant Reservoir Replacement | J5680 | GMNA |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J5698 | GMNA |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J5700 | GMNA |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J5711 | GMNA |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J5713 | GMNA |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J5714 | GMNA |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J5719 | GMNA |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J5720 | GMNA |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J5721 | GMNA |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J5723 | GMNA |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J5812 | GMNA |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J5813 | GMNA |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J473350 | Holden Australia |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J473380 | Holden Australia |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J473390 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J000857 | Holden New Zealand |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J000860 | Holden New Zealand |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J473350 | Holden New Zealand |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J473380 | Holden New Zealand |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | J473390 | Holden New Zealand |
| 4033520 | Charge Air Cooler Coolant Hose Replacement | R914055 | Holden New Zealand |
| 4033530 | Charge Air Cooler Coolant Hose Replacement - Radiator to Reservoir | | |
| 4033550 | Charge Air Cooler Coolant Hose Replacement - Radiator to Pump | | |
| 4033570 | Charge Air Cooler Coolant Hose Replacement - Cooler to Radiator | | |
| 4033590 | Charge Air Cooler Coolant Hose Replacement - Pump to Cooler | J5715 | GMNA |
| 4033590 | Charge Air Cooler Coolant Hose Replacement - Pump to Cooler | J5796 | GMNA |
| 4033590 | Charge Air Cooler Coolant Hose Replacement - Pump to Cooler | J5797 | GMNA |
| 4033590 | Charge Air Cooler Coolant Hose Replacement - Pump to Cooler | J000947 | Holden Australia |
| 4033590 | Charge Air Cooler Coolant Hose Replacement - Pump to Cooler | J5890 | Holden New Zealand |
| 4033590 | Charge Air Cooler Coolant Hose Replacement - Pump to Cooler | R914055 | GMK Overseas |
| 4033610 | Charge Air Cooler Coolant Pipe Replacement | J5697 | GMNA |
| 4033610 | Charge Air Cooler Coolant Pipe Replacement | J5712 | GMNA |
| 4033610 | Charge Air Cooler Coolant Pipe Replacement | J5716 | GMNA |
| 4033610 | Charge Air Cooler Coolant Pipe Replacement | J5724 | GMNA |
| 4033610 | Charge Air Cooler Coolant Pipe Replacement | J5793 | GMNA |
| 4033610 | Charge Air Cooler Coolant Pipe Replacement | J5794 | GMNA |
| 4033610 | Charge Air Cooler Coolant Pipe Replacement | J601540 | Holden Australia |
| 4033610 | Charge Air Cooler Coolant Pipe Replacement | J601550 | Holden Australia |
| 4033610 | Charge Air Cooler Coolant Pipe Replacement | J601530 | Holden New Zealand |
| 4033610 | Charge Air Cooler Coolant Pipe Replacement | 1913700 | GMK Overseas |
| 4033620 | Charge Air Cooler Inlet Duct Replacement | | |
| 4033640 | Charge Air Cooler Inlet Hose Replacement | 1913500 | GMK Overseas |
| 4033670 | Charge Air Cooler Coolant Hose Replacement - Reservoir to Pipe | | |
| 4033690 | Charge Air Cooler Coolant Hose Replacement - Pipe to Pump | | |
| 4033710 | Charge Air Cooler Coolant Hose Replacement - Engine to Pipe | | |
| 4033730 | Charge Air Cooler Coolant Hose Replacement - Engine to Reservoir | | |
| 4033750 | Charge Air Cooler Coolant Hose Replacement - Radiator to Pipe | | |
| 4033770 | Charge Air Cooler Coolant Outlet Pipe Replacement | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4033780 | Charge Air Cooler Radiator Drain Plug Replacement | | |
| 4033790 | Charge Air Cooler Coolant Pump Replacement | J5776 | GMNA |
| 4033850 | Charge Air Cooler Outlet Hose Replacement | 1913600 | GMK Overseas |
| 4033860 | Turbocharger Coolant Return Hose Replacement | J5889 | GMNA |
| 4033860 | Turbocharger Coolant Return Hose Replacement | J589000 | Holden Australia |
| 4033940 | Exhaust Gas Recirculation Valve Cooler Replacement | J6281 | GMNA |
| 4033940 | Exhaust Gas Recirculation Valve Cooler Replacement | J982510 | Holden Australia |
| 4033940 | Exhaust Gas Recirculation Valve Cooler Replacement | J982510 | Holden New Zealand |
| 4033960 | Exhaust Gas Recirculation Valve Cooling Feed Hose Replacement | J6282 | GMNA |
| 4039949 | Customer Concern Not Duplicated (CCND) - Engine Cooling | J9994 | GMNA |
| 4039949 | Customer Concern Not Duplicated (CCND) - Engine Cooling | 1781000 | GMK Domestic |
| 4039949 | Customer Concern Not Duplicated (CCND) - Engine Cooling | J9994 | Holden Australia |
| 4040060 | Battery Tray Replacement | B1782 | GMNA |
| 4040060 | Battery Tray Replacement | N0160 | GMNA |
| 4040060 | Battery Tray Replacement | N003500 | Holden Australia |
| 4040060 | Battery Tray Replacement | N016000 | Holden Australia |
| 4040060 | Battery Tray Replacement | N003500 | Holden New Zealand |
| 4040060 | Battery Tray Replacement | N0160 | Holden New Zealand |
| 4040060 | Battery Tray Replacement | 1571100 | GMK Overseas |
| 4040060 | Battery Tray Replacement | 1571200 | GMK Overseas |
| 4040060 | Battery Tray Replacement | 9751100 | GMK Overseas |
| 4040060 | Battery Tray Replacement | 975110A | GMK Overseas |
| 4040070 | Battery Sensor Replacement | | |
| 4040080 | Generator Pulley Replacement | J4020 | GMNA |
| 4040080 | Generator Pulley Replacement | J7548 | GMNA |
| 4040080 | Generator Pulley Replacement | 5110400 | GMK Domestic |
| 4040080 | Generator Pulley Replacement | 5332400 | GMK Domestic |
| 4040080 | Generator Pulley Replacement | J000698 | Holden Australia |
| 4040080 | Generator Pulley Replacement | J402000 | Holden Australia |
| 4040080 | Generator Pulley Replacement | J000698 | Holden New Zealand |
| 4040080 | Generator Pulley Replacement | 1540100 | GMK Overseas |
| 4040080 | Generator Pulley Replacement | 1540200 | GMK Overseas |
| 4040100 | Generator Drive Motor Rotor Replacement | 1545100 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4040120 | Generator Drive Motor Stator Replacement | 1542100 | GMK Overseas |
| 4040140 | Generator Rotor Drive End Bearing Replacement | J4042 | GMNA |
| 4040140 | Generator Rotor Drive End Bearing Replacement | J4047 | GMNA |
| 4040140 | Generator Rotor Drive End Bearing Replacement | 1540500 | GMK Overseas |
| 4040140 | Generator Rotor Drive End Bearing Replacement | 1540600 | GMK Overseas |
| 4040140 | Generator Rotor Drive End Bearing Replacement | 1545500 | GMK Overseas |
| 4040190 | Voltage Regulator Replacement | J4060 | GMNA |
| 4040190 | Voltage Regulator Replacement | J7712 | GMNA |
| 4040190 | Voltage Regulator Replacement | N6287 | GMNA |
| 4040190 | Voltage Regulator Replacement | 5111200 | GMK Domestic |
| 4040190 | Voltage Regulator Replacement | J406000 | Holden Australia |
| 4040190 | Voltage Regulator Replacement | J592800 | Holden Australia |
| 4040190 | Voltage Regulator Replacement | J408100 | Holden New Zealand |
| 4040190 | Voltage Regulator Replacement | J592800 | Holden New Zealand |
| 4040190 | Voltage Regulator Replacement | J705100 | Holden New Zealand |
| 4040190 | Voltage Regulator Replacement | NZE5502 | Holden New Zealand |
| 4040190 | Voltage Regulator Replacement | 1541300 | GMK Overseas |
| 4040190 | Voltage Regulator Replacement | 1541400 | GMK Overseas |
| 4040190 | Voltage Regulator Replacement | 1542600 | GMK Overseas |
| 4040190 | Voltage Regulator Replacement | 1542700 | GMK Overseas |
| 4040210 | Generator Battery Control Module Replacement | | |
| 4040230 | Battery Current Sensor Replacement | J4066 | GMNA |
| 4040250 | Generator Cover Replacement | | |
| 4040320 | Generator Replacement | J4100 | GMNA |
| 4040320 | Generator Replacement | 5331400 | GMK Domestic |
| 4040320 | Generator Replacement | J4100 | Holden Australia |
| 4040320 | Generator Replacement | J410000 | Holden Australia |
| 4040320 | Generator Replacement | J410100 | Holden Australia |
| 4040320 | Generator Replacement | J591200 | Holden Australia |
| 4040320 | Generator Replacement | J4100 | Holden New Zealand |
| 4040320 | Generator Replacement | J410000 | Holden New Zealand |
| 4040320 | Generator Replacement | J410100 | Holden New Zealand |
| 4040320 | Generator Replacement | J591200 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4040320 | Generator Replacement | 1541700 | GMK Overseas |
| 4040320 | Generator Replacement | 1541800 | GMK Overseas |
| 4040322 | Generator Overhaul | J4099 | GMNA |
| 4040340 | Auxiliary Generator Replacement | J4101 | GMNA |
| 4041080 | Engine Ground Cable Replacement | J4560 | GMNA |
| 4041080 | Engine Ground Cable Replacement | 1571500 | GMK Overseas |
| 4041100 | Starter Shield Replacement | J4575 | GMNA |
| 4041150 | Starter Solenoid Switch Replacement | J4580 | GMNA |
| 4041150 | Starter Solenoid Switch Replacement | J4581 | GMNA |
| 4041150 | Starter Solenoid Switch Replacement | J458000 | Holden Australia |
| 4041150 | Starter Solenoid Switch Replacement | J458000 | Holden New Zealand |
| 4041150 | Starter Solenoid Switch Replacement | 1560100 | GMK Overseas |
| 4041150 | Starter Solenoid Switch Replacement | 1560200 | GMK Overseas |
| 4041150 | Starter Solenoid Switch Replacement | 1560300 | GMK Overseas |
| 4041250 | Starter Replacement | J4640 | GMNA |
| 4041250 | Starter Replacement | J9550 | GMNA |
| 4041250 | Starter Replacement | 2150900 | GMK Domestic |
| 4041250 | Starter Replacement | 2151000 | GMK Domestic |
| 4041250 | Starter Replacement | J000556 | Holden Australia |
| 4041250 | Starter Replacement | J4640 | Holden Australia |
| 4041250 | Starter Replacement | J464000 | Holden Australia |
| 4041250 | Starter Replacement | J594000 | Holden Australia |
| 4041250 | Starter Replacement | J000556 | Holden New Zealand |
| 4041250 | Starter Replacement | J4640 | Holden New Zealand |
| 4041250 | Starter Replacement | J464000 | Holden New Zealand |
| 4041250 | Starter Replacement | J594000 | Holden New Zealand |
| 4041250 | Starter Replacement | 1560800 | GMK Overseas |
| 4041250 | Starter Replacement | 1560900 | GMK Overseas |
| 4041250 | Starter Replacement | 156090A | GMK Overseas |
| 4041250 | Starter Replacement | 1561100 | GMK Overseas |
| 4041250 | Starter Replacement | 1562100 | GMK Overseas |
| 4041252 | Starter Overhaul | J4620 | GMNA |
| 4041252 | Starter Overhaul | J9540 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4041252 | Starter Overhaul | 2151100 | GMK Domestic |
| 4041252 | Starter Overhaul | 2151120 | GMK Domestic |
| 4041252 | Starter Overhaul | 2151200 | GMK Domestic |
| 4041252 | Starter Overhaul | J594500 | Holden Australia |
| 4041252 | Starter Overhaul | J4620 | Holden New Zealand |
| 4041252 | Starter Overhaul | J594500 | Holden New Zealand |
| 4041252 | Starter Overhaul | 1560400 | GMK Overseas |
| 4041252 | Starter Overhaul | 1560500 | GMK Overseas |
| 4041252 | Starter Overhaul | 1560600 | GMK Overseas |
| 4041252 | Starter Overhaul | 1561200 | GMK Overseas |
| 4041252 | Starter Overhaul | 1561500 | GMK Overseas |
| 4041252 | Starter Overhaul | 1561900 | GMK Overseas |
| 4041252 | Starter Overhaul | 1562500 | GMK Overseas |
| 4041460 | Battery Positive Cable Terminal Cover Replacement | N0107 | GMNA |
| 4041510 | Battery Replacement | N0110 | GMNA |
| 4041510 | Battery Replacement | N4196 | GMNA |
| 4041510 | Battery Replacement | N9549 | GMNA |
| 4041510 | Battery Replacement | RT001 | GMNA |
| 4041510 | Battery Replacement | N000333 | Holden Australia |
| 4041510 | Battery Replacement | N000500 | Holden Australia |
| 4041510 | Battery Replacement | N000502 | Holden Australia |
| 4041510 | Battery Replacement | N000525 | Holden Australia |
| 4041510 | Battery Replacement | N000600 | Holden Australia |
| 4041510 | Battery Replacement | N0110 | Holden Australia |
| 4041510 | Battery Replacement | N011000 | Holden Australia |
| 4041510 | Battery Replacement | W200700 | Holden Australia |
| 4041510 | Battery Replacement | N000333 | Holden New Zealand |
| 4041510 | Battery Replacement | N000500 | Holden New Zealand |
| 4041510 | Battery Replacement | N000502 | Holden New Zealand |
| 4041510 | Battery Replacement | N000600 | Holden New Zealand |
| 4041510 | Battery Replacement | N0110 | Holden New Zealand |
| 4041510 | Battery Replacement | N011000 | Holden New Zealand |
| 4041510 | Battery Replacement | 1570300 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4041512 | Battery Charging and Testing | J7733 | GMNA |
| 4041512 | Battery Charging and Testing | N0100 | GMNA |
| 4041512 | Battery Charging and Testing | P0122 | GMNA |
| 4041512 | Battery Charging and Testing | R9755 | GMNA |
| 4041512 | Battery Charging and Testing | 5120120 | GMK Domestic |
| 4041512 | Battery Charging and Testing | N000550 | Holden Australia |
| 4041512 | Battery Charging and Testing | N0100 | Holden Australia |
| 4041512 | Battery Charging and Testing | N900500 | Holden Australia |
| 4041512 | Battery Charging and Testing | N000550 | Holden New Zealand |
| 4041512 | Battery Charging and Testing | N0006001 | Holden New Zealand |
| 4041512 | Battery Charging and Testing | R051007 | Holden New Zealand |
| 4041512 | Battery Charging and Testing | R051008 | Holden New Zealand |
| 4041512 | Battery Charging and Testing | 1570200 | GMK Overseas |
| 4041530 | Battery Case Upper Cover Replacement | N0111 | GMNA |
| 4041550 | Battery Cover Replacement | N0112 | GMNA |
| 4041550 | Battery Cover Replacement | N003000 | Holden Australia |
| 4041550 | Battery Cover Replacement | N003000 | Holden New Zealand |
| 4041550 | Battery Cover Replacement | 1570900 | GMK Overseas |
| 4041550 | Battery Cover Replacement | 1571400 | GMK Overseas |
| 4041570 | Battery Box Replacement | N0113 | GMNA |
| 4041590 | Auxiliary Battery Positive Cable Replacement - Battery to Battery Relay | N0114 | GMNA |
| 4041610 | Generator and Starter Cable Replacement | N0115 | GMNA |
| 4041630 | Starter Solenoid Cable Replacement | N0116 | GMNA |
| 4041710 | Battery Positive Cable Replacement | J7702 | GMNA |
| 4041710 | Battery Positive Cable Replacement | N0119 | GMNA |
| 4041710 | Battery Positive Cable Replacement | N0120 | GMNA |
| 4041710 | Battery Positive Cable Replacement | N0125 | GMNA |
| 4041710 | Battery Positive Cable Replacement | N0135 | GMNA |
| 4041710 | Battery Positive Cable Replacement | N0180 | GMNA |
| 4041710 | Battery Positive Cable Replacement | N0181 | GMNA |
| 4041710 | Battery Positive Cable Replacement | N9551 | GMNA |
| 4041710 | Battery Positive Cable Replacement | N9625 | GMNA |
| 4041710 | Battery Positive Cable Replacement | 5341800 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4041710 | Battery Positive Cable Replacement | N000300 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N000363 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N001500 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N012000 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N0131 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710185 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710186 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710187 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710188 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710190 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710191 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710196 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710285 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710286 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710287 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710288 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710289 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710290 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710291 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710292 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710293 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710295 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710296 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N710297 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N730190 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N730292 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910185 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910186 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910187 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910188 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910189 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910192 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910194 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4041710 | Battery Positive Cable Replacement | N910195 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910196 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910197 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910285 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910287 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910288 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910289 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910290 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910291 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910293 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910296 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910297 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910298 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910388 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910389 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910390 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910391 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910392 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910393 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910394 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910395 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N910397 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N911586 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N911587 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N911588 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N911589 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N911592 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N911594 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N911595 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N911596 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N915987 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N915989 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N915990 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4041710 | Battery Positive Cable Replacement | N915991 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N915993 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N915995 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N915996 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N915997 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N916085 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N916086 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N916087 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N916088 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N916089 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N916090 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N916091 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N916092 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N916093 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N916094 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N916096 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N916097 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N916098 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N916184 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N916196 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N930106 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N930186 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N930188 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N930191 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N930288 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N930388 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N930389 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N930394 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N930395 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N940190 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N940294 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N940387 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950108 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4041710 | Battery Positive Cable Replacement | N950110 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950186 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950187 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950188 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950189 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950190 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950195 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950284 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950285 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950286 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950287 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950288 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950289 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950290 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950291 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950292 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950296 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950386 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950389 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950390 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950393 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950394 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950396 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N950397 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N954506 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N954589 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N954593 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N954691 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N954696 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N955686 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N955687 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N955690 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N955692 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4041710 | Battery Positive Cable Replacement | N955695 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N955696 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N955697 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N955787 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N955788 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N955794 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N955795 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N955796 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N955797 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N955891 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N955896 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N955990 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N955997 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960111 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960186 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960187 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960188 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960189 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960190 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960196 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960285 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960287 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960288 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960289 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960290 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960291 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960292 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960293 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960295 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960296 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960297 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960385 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960386 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4041710 | Battery Positive Cable Replacement | N960388 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960389 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960390 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960391 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960393 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960394 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960395 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960396 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N960397 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N965906 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N965987 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N965988 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N965989 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N965990 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N965994 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N965996 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N966087 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N966089 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N966090 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N966091 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N966093 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N966096 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N966097 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N967491 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N967587 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N967689 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N967691 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N967796 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N967987 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N967991 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N967998 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N970111 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N970188 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4041710 | Battery Positive Cable Replacement | N970190 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N970386 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N970389 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N970395 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N973906 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N973988 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N973989 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N973994 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N974085 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N974186 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N974189 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N974193 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N974194 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N974197 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N980188 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N980189 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N980385 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N980388 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N980394 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N980395 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N984296 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N984297 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N984385 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N984395 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N984588 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N984595 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N984691 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N984692 | Holden Australia |
| 4041710 | Battery Positive Cable Replacement | N000363 | Holden New Zealand |
| 4041710 | Battery Positive Cable Replacement | N001500 | Holden New Zealand |
| 4041710 | Battery Positive Cable Replacement | N0120 | Holden New Zealand |
| 4041710 | Battery Positive Cable Replacement | N012000 | Holden New Zealand |
| 4041710 | Battery Positive Cable Replacement | N0128 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4041710 | Battery Positive Cable Replacement | 1570800 | GMK Overseas |
| 4041710 | Battery Positive Cable Replacement | 9110300R | GMK Overseas |
| 4041760 | Battery Positive Junction Block Cable Replacement | N0122 | GMNA |
| 4041780 | Generator Cable Replacement | N0123 | GMNA |
| 4041800 | Battery Positive Fuse Block Cable Replacement | N0124 | GMNA |
| 4041820 | Battery Negative Cable Replacement | J7710 | GMNA |
| 4041820 | Battery Negative Cable Replacement | N0126 | GMNA |
| 4041820 | Battery Negative Cable Replacement | N0127 | GMNA |
| 4041820 | Battery Negative Cable Replacement | N001600 | Holden Australia |
| 4041820 | Battery Negative Cable Replacement | N012600 | Holden Australia |
| 4041820 | Battery Negative Cable Replacement | N710106 | Holden Australia |
| 4041820 | Battery Negative Cable Replacement | N710109 | Holden Australia |
| 4041820 | Battery Negative Cable Replacement | N730106 | Holden Australia |
| 4041820 | Battery Negative Cable Replacement | N910101 | Holden Australia |
| 4041820 | Battery Negative Cable Replacement | N930104 | Holden Australia |
| 4041820 | Battery Negative Cable Replacement | N950102 | Holden Australia |
| 4041820 | Battery Negative Cable Replacement | N960102 | Holden Australia |
| 4041820 | Battery Negative Cable Replacement | N965901 | Holden Australia |
| 4041820 | Battery Negative Cable Replacement | N970102 | Holden Australia |
| 4041820 | Battery Negative Cable Replacement | N973901 | Holden Australia |
| 4041820 | Battery Negative Cable Replacement | N973907 | Holden Australia |
| 4041820 | Battery Negative Cable Replacement | N980101 | Holden Australia |
| 4041820 | Battery Negative Cable Replacement | N001600 | Holden New Zealand |
| 4041820 | Battery Negative Cable Replacement | N012600 | Holden New Zealand |
| 4041820 | Battery Negative Cable Replacement | 1570600 | GMK Overseas |
| 4041900 | Battery Positive and Negative Cable Replacement | N0131 | GMNA |
| 4041900 | Battery Positive and Negative Cable Replacement | 1570700 | GMK Overseas |
| 4041900 | Battery Positive and Negative Cable Replacement | 9110300 | GMK Overseas |
| 4041920 | Battery Negative Cable Extension Cable Replacement | N0132 | GMNA |
| 4041940 | Auxiliary Battery Negative Cable Replacement | N0133 | GMNA |
| 4041960 | Auxiliary Battery Positive Cable Replacement | N0134 | GMNA |
| 4041980 | Generator Battery Jumper Cable Replacement | N0136 | GMNA |
| 4042030 | Battery Positive Cable Extension Cable Junction Block Replacement | N0138 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4042050 | Battery Positive Cable Junction Block Terminal Replacement | | |
| 4042080 | Battery Heat Shield Replacement | N0170 | GMNA |
| 4042080 | Battery Heat Shield Replacement | 1571300 | GMK Overseas |
| 4042250 | Starter Relay Replacement | N2810 | GMNA |
| 4042250 | Starter Relay Replacement | N281000 | Holden Australia |
| 4042250 | Starter Relay Replacement | N2810 | Holden New Zealand |
| 4042270 | Auxiliary Battery Relay Replacement | N2811 | GMNA |
| 4042290 | Engine Wiring Harness Assembly Replacement | D1706 | GMNA |
| 4042290 | Engine Wiring Harness Assembly Replacement | J4558 | GMNA |
| 4042290 | Engine Wiring Harness Assembly Replacement | N6270 | GMNA |
| 4042290 | Engine Wiring Harness Assembly Replacement | N6970 | GMNA |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910485 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910486 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910487 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910488 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910489 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910490 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910491 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910492 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910495 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910496 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910585 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910586 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910587 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910588 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910589 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910590 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910591 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910592 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910593 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910595 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910596 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910597 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4042290 | Engine Wiring Harness Assembly Replacement | N910685 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910686 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910687 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910688 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910689 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910690 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910691 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910692 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910693 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910694 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910695 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910696 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910697 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910786 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910787 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910788 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910790 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910791 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910797 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910885 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910886 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910887 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910888 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910889 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910890 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910891 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910892 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910895 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910896 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910985 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910986 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910987 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910988 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4042290 | Engine Wiring Harness Assembly Replacement | N910989 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910990 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910991 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910992 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910993 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910994 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910996 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N910997 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911086 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911087 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911088 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911089 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911090 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911092 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911093 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911096 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911097 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911185 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911186 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911187 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911188 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911189 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911191 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911194 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911195 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911196 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911284 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911285 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911286 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911287 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911288 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911290 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911291 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4042290 | Engine Wiring Harness Assembly Replacement | N911292 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911293 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911296 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N911297 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N920694 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N920889 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N921190 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N921204 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N930487 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N930488 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N930492 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N930586 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N930593 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N930687 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N930689 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N930693 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N930786 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N930885 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N930891 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N930896 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N930990 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N930993 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N931186 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N940486 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N940590 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N940596 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N940692 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N940697 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N940785 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N940787 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N940887 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N940888 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N940889 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4042290 | Engine Wiring Harness Assembly Replacement | N941095 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N941187 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N941188 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N941193 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N945688 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N945691 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N945693 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950485 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950486 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950487 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950488 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950489 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950492 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950493 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950586 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950587 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950590 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950591 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950592 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950595 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950596 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950597 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950686 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950687 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950688 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950689 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950690 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950692 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950785 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950788 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950792 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950794 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950886 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4042290 | Engine Wiring Harness Assembly Replacement | N950888 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950889 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950890 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950891 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950895 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950896 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950986 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950990 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950991 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950992 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950993 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950995 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N950996 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951085 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951087 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951090 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951091 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951092 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951093 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951096 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951098 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951186 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951188 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951189 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951190 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951193 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951196 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951285 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951289 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951291 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951292 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951293 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N951295 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4042290 | Engine Wiring Harness Assembly Replacement | N951296 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960485 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960486 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960487 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960488 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960489 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960490 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960491 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960492 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960495 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960496 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960497 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960585 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960586 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960587 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960588 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960589 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960590 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960591 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960592 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960593 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960595 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960596 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960597 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960685 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960687 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960688 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960691 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960693 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960694 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960695 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960696 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960697 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4042290 | Engine Wiring Harness Assembly Replacement | N960785 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960786 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960787 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960788 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960789 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960792 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960794 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960795 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960796 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960797 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960886 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960888 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960889 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960890 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960891 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960892 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960895 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960896 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960985 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960986 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960990 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960991 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960992 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960993 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960994 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960995 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960996 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N960997 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961086 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961087 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961088 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961089 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961096 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4042290 | Engine Wiring Harness Assembly Replacement | N961097 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961184 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961185 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961186 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961187 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961188 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961189 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961190 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961191 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961193 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961196 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961197 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961198 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961287 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961290 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961291 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961292 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961296 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N961297 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970486 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970487 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970488 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970489 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970492 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970496 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970589 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970591 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970596 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970688 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970693 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970695 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970696 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970697 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4042290 | Engine Wiring Harness Assembly Replacement | N970785 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970786 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970789 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970794 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970795 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970888 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970889 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970890 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970891 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970892 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970895 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970896 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970986 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970990 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970991 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970992 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970993 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970994 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N970996 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N971085 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N971087 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N971088 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N971094 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N971095 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N971185 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N971186 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N971188 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N971189 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N971190 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N971196 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N971197 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N971288 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N971290 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4042290 | Engine Wiring Harness Assembly Replacement | N971291 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N971296 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N971297 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N980886 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N980890 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N980891 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N980895 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N980896 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N980990 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N980991 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N980992 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N980993 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N980994 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N981087 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N981096 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N981097 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N981186 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N981188 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N981189 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N981195 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N981198 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N981290 | Holden Australia |
| 4042290 | Engine Wiring Harness Assembly Replacement | N405599R | Holden New Zealand |
| 4042290 | Engine Wiring Harness Assembly Replacement | N627000 | Holden New Zealand |
| 4042510 | Battery Isolator Replacement | N0109 | GMNA |
| 4049939 | Customer Concern Not Duplicated (CCND) - Engine Electrical | J9993 | GMNA |
| 4049939 | Customer Concern Not Duplicated (CCND) - Engine Electrical | J9993 | Holden Australia |
| 4049939 | Customer Concern Not Duplicated (CCND) - Engine Electrical | 9112900R | GMK Overseas |
| 4049979 | Customer Concern Not Duplicated (CCND) - 12V Battery/Charging System | N9997 | GMNA |
| 4050010 | Exhaust Manifold Heat Shield Replacement | J0097 | GMNA |
| 4050010 | Exhaust Manifold Heat Shield Replacement | L2380 | GMNA |
| 4050010 | Exhaust Manifold Heat Shield Replacement | 1310400 | GMK Domestic |
| 4050010 | Exhaust Manifold Heat Shield Replacement | 1321000 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4050010 | Exhaust Manifold Heat Shield Replacement | J509400 | Holden Australia |
| 4050010 | Exhaust Manifold Heat Shield Replacement | L2380 | Holden Australia |
| 4050010 | Exhaust Manifold Heat Shield Replacement | J509400 | Holden New Zealand |
| 4050010 | Exhaust Manifold Heat Shield Replacement | 1940800 | GMK Overseas |
| 4050010 | Exhaust Manifold Heat Shield Replacement | 1940910 | GMK Overseas |
| 4050010 | Exhaust Manifold Heat Shield Replacement | 1940920 | GMK Overseas |
| 4050020 | Exhaust Manifold Replacement - Right Side | J0100 | GMNA |
| 4050020 | Exhaust Manifold Replacement - Right Side | J303200 | Holden Australia |
| 4050020 | Exhaust Manifold Replacement - Right Side | J0100 | Holden New Zealand |
| 4050020 | Exhaust Manifold Replacement - Right Side | J303100 | Holden New Zealand |
| 4050020 | Exhaust Manifold Replacement - Right Side | 1940310 | GMK Overseas |
| 4050030 | Exhaust Manifold Heat Shield Replacement - Right Side | J0098 | GMNA |
| 4050030 | Exhaust Manifold Heat Shield Replacement - Right Side | L2378 | GMNA |
| 4050040 | Exhaust Manifold Replacement - Left Side | J0101 | GMNA |
| 4050040 | Exhaust Manifold Replacement - Left Side | J303100 | Holden Australia |
| 4050040 | Exhaust Manifold Replacement - Left Side | J303200 | Holden New Zealand |
| 4050040 | Exhaust Manifold Replacement - Left Side | 1940320 | GMK Overseas |
| 4050050 | Exhaust Manifold Heat Shield Replacement - Left Side | J0099 | GMNA |
| 4050050 | Exhaust Manifold Heat Shield Replacement - Left Side | L2379 | GMNA |
| 4050070 | Exhaust Manifold with Catalytic Converter Replacement | J0102 | GMNA |
| 4050070 | Exhaust Manifold with Catalytic Converter Replacement | J0103 | GMNA |
| 4050070 | Exhaust Manifold with Catalytic Converter Replacement | J0104 | GMNA |
| 4050070 | Exhaust Manifold with Catalytic Converter Replacement | J0104 | Holden Australia |
| 4050070 | Exhaust Manifold with Catalytic Converter Replacement | J0103 | Holden New Zealand |
| 4050070 | Exhaust Manifold with Catalytic Converter Replacement | J0103C | Holden New Zealand |
| 4050090 | Exhaust Turbocharger Inlet Pipe Replacement - Bank 1 | J5784 | GMNA |
| 4050110 | Turbocharger Exhaust Pipe Replacement | J5785 | GMNA |
| 4050110 | Turbocharger Exhaust Pipe Replacement | J5790 | GMNA |
| 4050130 | Exhaust Turbocharger Inlet Pipe Replacement - Bank 2 | J5786 | GMNA |
| 4050150 | Exhaust Turbocharger Inlet Pipe Adapter Replacement | J5787 | GMNA |
| 4050170 | Exhaust Manifold Outlet Pipe Replacement - Right Side | J5788 | GMNA |
| 4050190 | Exhaust Manifold Outlet Pipe Replacement - Left Side | J5789 | GMNA |
| 4050272 | Exhaust System Alignment | L2004 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4050272 | Exhaust System Alignment | L9713 | GMNA |
| 4050272 | Exhaust System Alignment | L9727 | GMNA |
| 4050272 | Exhaust System Alignment | L000269 | Holden Australia |
| 4050272 | Exhaust System Alignment | L2004 | Holden Australia |
| 4050272 | Exhaust System Alignment | L000269 | Holden New Zealand |
| 4050272 | Exhaust System Alignment | 1960100 | GMK Overseas |
| 4050380 | Exhaust Crossover Pipe Replacement | L2070 | GMNA |
| 4050380 | Exhaust Crossover Pipe Replacement | L2080 | GMNA |
| 4050380 | Exhaust Crossover Pipe Replacement | L208000 | Holden Australia |
| 4050380 | Exhaust Crossover Pipe Replacement | L208000 | Holden New Zealand |
| 4050400 | Exhaust Manifold Pipe Seal Replacement | L2085 | GMNA |
| 4050420 | Exhaust Front Pipe Replacement | L2120 | GMNA |
| 4050420 | Exhaust Front Pipe Replacement | L2125 | GMNA |
| 4050420 | Exhaust Front Pipe Replacement | L2140 | GMNA |
| 4050420 | Exhaust Front Pipe Replacement | L2150 | GMNA |
| 4050420 | Exhaust Front Pipe Replacement | L2160 | GMNA |
| 4050420 | Exhaust Front Pipe Replacement | L216000 | Holden Australia |
| 4050420 | Exhaust Front Pipe Replacement | L504150 | Holden Australia |
| 4050420 | Exhaust Front Pipe Replacement | L2160 | Holden New Zealand |
| 4050420 | Exhaust Front Pipe Replacement | L216000 | Holden New Zealand |
| 4050480 | Exhaust Pipe Replacement - Right Side | L2100 | GMNA |
| 4050480 | Exhaust Pipe Replacement - Right Side | L504200 | Holden Australia |
| 4050500 | Exhaust Pipe Replacement - Left Side | L2101 | GMNA |
| 4050500 | Exhaust Pipe Replacement - Left Side | 1411000 | GMK Domestic |
| 4050500 | Exhaust Pipe Replacement - Left Side | 1411100 | GMK Domestic |
| 4050500 | Exhaust Pipe Replacement - Left Side | 1411300 | GMK Domestic |
| 4050500 | Exhaust Pipe Replacement - Left Side | 1960900 | GMK Overseas |
| 4050500 | Exhaust Pipe Replacement - Left Side | 196090A | GMK Overseas |
| 4050520 | Exhaust Flexible Pipe Replacement | L2106 | GMNA |
| 4050520 | Exhaust Flexible Pipe Replacement | L3505 | GMNA |
| 4050570 | Exhaust Pressure Sensor Pipe Replacement | L2108 | GMNA |
| 4050590 | Exhaust Pressure Sensor Pipe Replacement - Front | | |
| 4050650 | Exhaust Manifold Rear Pipe Replacement | L2162 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4050670 | Exhaust Manifold Pipe Replacement | L2163 | GMNA |
| 4050780 | Catalytic Converter Heat Shield Replacement | L2280 | GMNA |
| 4050780 | Catalytic Converter Heat Shield Replacement | 1414400 | GMK Domestic |
| 4050780 | Catalytic Converter Heat Shield Replacement | 1414500 | GMK Domestic |
| 4050780 | Catalytic Converter Heat Shield Replacement | L2280 | Holden Australia |
| 4050780 | Catalytic Converter Heat Shield Replacement | L228000 | Holden Australia |
| 4050780 | Catalytic Converter Heat Shield Replacement | L228000 | Holden New Zealand |
| 4050780 | Catalytic Converter Heat Shield Replacement | 1961300 | GMK Overseas |
| 4050820 | Exhaust Particulate Filter Heat Shield Replacement - Front | L2285 | GMNA |
| 4050840 | Exhaust Particulate Filter Heat Shield Replacement - Rear | J8337 | GMNA |
| 4050860 | Exhaust Particulate Filter Replacement | L2295 | GMNA |
| 4050860 | Exhaust Particulate Filter Replacement | 1412800 | GMK Domestic |
| 4050860 | Exhaust Particulate Filter Replacement | L502650 | Holden Australia |
| 4050860 | Exhaust Particulate Filter Replacement | F502650 | Holden New Zealand |
| 4050860 | Exhaust Particulate Filter Replacement | L502650 | Holden New Zealand |
| 4050860 | Exhaust Particulate Filter Replacement | 1961400 | GMK Overseas |
| 4050880 | Catalytic Converter Replacement - Left Side | L2298 | GMNA |
| 4050880 | Catalytic Converter Replacement - Left Side | L504100 | Holden Australia |
| 4050880 | Catalytic Converter Replacement - Left Side | L504100 | Holden New Zealand |
| 4050900 | Catalytic Converter Replacement - Right Side | L2299 | GMNA |
| 4050920 | Catalytic Converter Replacement | L2300 | GMNA |
| 4050920 | Catalytic Converter Replacement | L2305 | GMNA |
| 4050920 | Catalytic Converter Replacement | T5616 | GMNA |
| 4050920 | Catalytic Converter Replacement | T5629 | GMNA |
| 4050920 | Catalytic Converter Replacement | T5630 | GMNA |
| 4050920 | Catalytic Converter Replacement | T5656 | GMNA |
| 4050920 | Catalytic Converter Replacement | T5725 | GMNA |
| 4050920 | Catalytic Converter Replacement | T5726 | GMNA |
| 4050920 | Catalytic Converter Replacement | 1413900 | GMK Domestic |
| 4050920 | Catalytic Converter Replacement | 1414100 | GMK Domestic |
| 4050920 | Catalytic Converter Replacement | 1414200 | GMK Domestic |
| 4050920 | Catalytic Converter Replacement | 1420200 | GMK Domestic |
| 4050920 | Catalytic Converter Replacement | J502930 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4050920 | Catalytic Converter Replacement | L2300 | Holden Australia |
| 4050920 | Catalytic Converter Replacement | L2305 | Holden Australia |
| 4050920 | Catalytic Converter Replacement | L514150 | Holden Australia |
| 4050920 | Catalytic Converter Replacement | J502930 | Holden New Zealand |
| 4050920 | Catalytic Converter Replacement | L2620 | Holden New Zealand |
| 4050920 | Catalytic Converter Replacement | L502500 | Holden New Zealand |
| 4050920 | Catalytic Converter Replacement | L514150 | Holden New Zealand |
| 4050920 | Catalytic Converter Replacement | 1961500 | GMK Overseas |
| 4050920 | Catalytic Converter Replacement | 1961600 | GMK Overseas |
| 4050920 | Catalytic Converter Replacement | 1961610 | GMK Overseas |
| 4050920 | Catalytic Converter Replacement | 1961620 | GMK Overseas |
| 4050940 | Three-Way Catalytic Converter Replacement | L2301 | GMNA |
| 4050940 | Three-Way Catalytic Converter Replacement | L230000 | Holden Australia |
| 4050940 | Three-Way Catalytic Converter Replacement | L230100 | Holden Australia |
| 4050940 | Three-Way Catalytic Converter Replacement | L230200 | Holden Australia |
| 4050940 | Three-Way Catalytic Converter Replacement | L230300 | Holden Australia |
| 4050940 | Three-Way Catalytic Converter Replacement | L230000 | Holden New Zealand |
| 4050940 | Three-Way Catalytic Converter Replacement | L230100 | Holden New Zealand |
| 4050960 | Warm Up Three-Way Catalytic Converter Replacement | L2302 | GMNA |
| 4051040 | Oxygen Sensor Wiring Harness Heat Shield Replacement | L2375 | GMNA |
| 4051090 | Exhaust Pipe Heat Shield Replacement | L2390 | GMNA |
| 4051090 | Exhaust Pipe Heat Shield Replacement | L2400 | GMNA |
| 4051090 | Exhaust Pipe Heat Shield Replacement | L502300 | Holden Australia |
| 4051090 | Exhaust Pipe Heat Shield Replacement | L502300 | Holden New Zealand |
| 4051110 | Exhaust Front Heat Shield Replacement | L2402 | GMNA |
| 4051130 | Exhaust Rear Muffler Heat Shield Replacement | L2403 | GMNA |
| 4051130 | Exhaust Rear Muffler Heat Shield Replacement | L2599 | GMNA |
| 4051130 | Exhaust Rear Muffler Heat Shield Replacement | L9712 | GMNA |
| 4051130 | Exhaust Rear Muffler Heat Shield Replacement | 1420100 | GMK Domestic |
| 4051130 | Exhaust Rear Muffler Heat Shield Replacement | L509500 | Holden Australia |
| 4051130 | Exhaust Rear Muffler Heat Shield Replacement | L509700 | Holden Australia |
| 4051130 | Exhaust Rear Muffler Heat Shield Replacement | L509710 | Holden Australia |
| 4051130 | Exhaust Rear Muffler Heat Shield Replacement | L509500 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4051130 | Exhaust Rear Muffler Heat Shield Replacement | L509600 | Holden New Zealand |
| 4051130 | Exhaust Rear Muffler Heat Shield Replacement | L509700 | Holden New Zealand |
| 4051130 | Exhaust Rear Muffler Heat Shield Replacement | 1961700 | GMK Overseas |
| 4051150 | Exhaust Heat Shield Replacement | L2410 | GMNA |
| 4051160 | Turbocharger Heat Shield Replacement | 1240700 | GMK Domestic |
| 4051160 | Turbocharger Heat Shield Replacement | 1326100 | GMK Domestic |
| 4051160 | Turbocharger Heat Shield Replacement | 1942300 | GMK Overseas |
| 4051170 | Transmission Heat Shield Replacement | | |
| 4051190 | Turbocharger Wastegate Actuator Vacuum Control Solenoid Valve Splash Shield Replacement | L2414 | GMNA |
| 4051210 | Front Axle Propeller Shaft Heat Shield Replacement | L2415 | GMNA |
| 4051290 | Exhaust Muffler Insulator, Hanger, and Bracket Replacement | L2520 | GMNA |
| 4051290 | Exhaust Muffler Insulator, Hanger, and Bracket Replacement | L2022 | Holden New Zealand |
| 4051300 | Exhaust Muffler Front Heat Shield Replacement | | |
| 4051400 | Fuel Tank Heat Shield Replacement | L2539 | GMNA |
| 4051400 | Fuel Tank Heat Shield Replacement | F905200 | Holden Australia |
| 4051420 | Exhaust Muffler Intermediate Heat Shield Replacement | L2540 | GMNA |
| 4051420 | Exhaust Muffler Intermediate Heat Shield Replacement | 1412700 | GMK Domestic |
| 4051420 | Exhaust Muffler Intermediate Heat Shield Replacement | L509600 | Holden Australia |
| 4051420 | Exhaust Muffler Intermediate Heat Shield Replacement | 1961900 | GMK Overseas |
| 4051440 | Exhaust Muffler Heat Shield Replacement | L2541 | GMNA |
| 4051460 | Exhaust Muffler Center Heat Shield Replacement | L2542 | GMNA |
| 4051480 | Exhaust Heat Shield Replacement - Rear Fascia | L2543 | GMNA |
| 4051490 | Exhaust Muffler Rear Heat Shield Replacement | | |
| 4051530 | Exhaust Muffler Replacement | L2584 | GMNA |
| 4051530 | Exhaust Muffler Replacement | 1251400 | GMK Domestic |
| 4051530 | Exhaust Muffler Replacement | 1412100 | GMK Domestic |
| 4051530 | Exhaust Muffler Replacement | 1412400 | GMK Domestic |
| 4051530 | Exhaust Muffler Replacement | L2584 | Holden Australia |
| 4051530 | Exhaust Muffler Replacement | L503100 | Holden Australia |
| 4051530 | Exhaust Muffler Replacement | L2584 | Holden New Zealand |
| 4051530 | Exhaust Muffler Replacement | L502400 | Holden New Zealand |
| 4051530 | Exhaust Muffler Replacement | 1962200 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4051550 | Exhaust Muffler Replacement - Right Side | L2590 | GMNA |
| 4051550 | Exhaust Muffler Replacement - Right Side | 1962210 | GMK Overseas |
| 4051570 | Exhaust Muffler Replacement - Left Side | L2591 | GMNA |
| 4051570 | Exhaust Muffler Replacement - Left Side | L258400 | Holden Australia |
| 4051570 | Exhaust Muffler Replacement - Left Side | L258400 | Holden New Zealand |
| 4051570 | Exhaust Muffler Replacement - Left Side | 1962220 | GMK Overseas |
| 4051590 | Exhaust Rear Muffler Replacement | L2592 | GMNA |
| 4051590 | Exhaust Rear Muffler Replacement | L503200 | Holden Australia |
| 4051590 | Exhaust Rear Muffler Replacement | L503200 | Holden New Zealand |
| 4051610 | Exhaust Rear Auxiliary Muffler Replacement | J8371 | GMNA |
| 4051690 | Exhaust Resonator Replacement | L2700 | GMNA |
| 4051690 | Exhaust Resonator Replacement | L2720 | GMNA |
| 4051690 | Exhaust Resonator Replacement | 1962100 | GMK Overseas |
| 4051710 | Tail Pipe Replacement | L2800 | GMNA |
| 4051710 | Tail Pipe Replacement | L9728 | GMNA |
| 4051710 | Tail Pipe Replacement | R607500 | Holden Australia |
| 4051710 | Tail Pipe Replacement | L2800 | Holden New Zealand |
| 4051710 | Tail Pipe Replacement | R607500 | Holden New Zealand |
| 4051730 | Exhaust Muffler Rear Pipe Replacement | L2801 | GMNA |
| 4051730 | Exhaust Muffler Rear Pipe Replacement | R819007 | Holden New Zealand |
| 4051810 | Exhaust Tail Pipe Flow Valve Control Module Replacement | L2830 | GMNA |
| 4051830 | Exhaust Tail Pipe Flow Control Valve Solenoid Replacement | L2831 | GMNA |
| 4051850 | Exhaust Tail Pipe Flow Valve Vacuum Pipe Reservoir Tank Replacement | L2832 | GMNA |
| 4051900 | Exhaust Pipe Replacement | L2840 | GMNA |
| 4051900 | Exhaust Pipe Replacement | L2630 | Holden New Zealand |
| 4051980 | Exhaust Muffler with Resonator, Exhaust, and Tail Pipe Replacement | L2904 | GMNA |
| 4051980 | Exhaust Muffler with Resonator, Exhaust, and Tail Pipe Replacement | 1410300 | GMK Domestic |
| 4051980 | Exhaust Muffler with Resonator, Exhaust, and Tail Pipe Replacement | 1410800 | GMK Domestic |
| 4051980 | Exhaust Muffler with Resonator, Exhaust, and Tail Pipe Replacement | L503500 | Holden Australia |
| 4051980 | Exhaust Muffler with Resonator, Exhaust, and Tail Pipe Replacement | L503510 | Holden Australia |
| 4051980 | Exhaust Muffler with Resonator, Exhaust, and Tail Pipe Replacement | L500000 | Holden New Zealand |
| 4051980 | Exhaust Muffler with Resonator, Exhaust, and Tail Pipe Replacement | L503500 | Holden New Zealand |
| 4051980 | Exhaust Muffler with Resonator, Exhaust, and Tail Pipe Replacement | L503510 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4051980 | Exhaust Muffler with Resonator, Exhaust, and Tail Pipe Replacement | 1962500 | GMK Overseas |
| 4052410 | Exhaust Manifold Replacement | J0108 | GMNA |
| 4052410 | Exhaust Manifold Replacement | J5791 | GMNA |
| 4052410 | Exhaust Manifold Replacement | J7518 | GMNA |
| 4052410 | Exhaust Manifold Replacement | J7520 | GMNA |
| 4052410 | Exhaust Manifold Replacement | 1310500 | GMK Domestic |
| 4052410 | Exhaust Manifold Replacement | J202500 | Holden Australia |
| 4052410 | Exhaust Manifold Replacement | J202500 | Holden New Zealand |
| 4052410 | Exhaust Manifold Replacement | 1940200 | GMK Overseas |
| 4052410 | Exhaust Manifold Replacement | 1940300 | GMK Overseas |
| 4059959 | Customer Concern Not Duplicated (CCND) - Engine Exhaust | L9995 | GMNA |
| 4059959 | Customer Concern Not Duplicated (CCND) - Engine Exhaust | 1250320 | GMK Domestic |
| 4059959 | Customer Concern Not Duplicated (CCND) - Engine Exhaust | 1410900 | GMK Domestic |
| 4060150 | Intake Manifold Tube Replacement | J0153 | GMNA |
| 4060160 | Intake Manifold Insulator Replacement | L512210 | Holden Australia |
| 4060160 | Intake Manifold Insulator Replacement | L512230 | Holden Australia |
| 4060160 | Intake Manifold Insulator Replacement | L512240 | Holden Australia |
| 4060160 | Intake Manifold Insulator Replacement | L512210 | Holden New Zealand |
| 4060160 | Intake Manifold Insulator Replacement | L512230 | Holden New Zealand |
| 4060160 | Intake Manifold Insulator Replacement | L512240 | Holden New Zealand |
| 4060170 | Fuel Injector Sight Shield Replacement | J0159 | GMNA |
| 4060230 | Intake Manifold Cover Replacement - Front | J0192 | GMNA |
| 4060250 | Intake Manifold Cover Replacement - Rear | J0193 | GMNA |
| 4060330 | Engine Block Valley Cover Replacement | J0207 | GMNA |
| 4060330 | Engine Block Valley Cover Replacement | J300620 | Holden Australia |
| 4060330 | Engine Block Valley Cover Replacement | J313100 | Holden Australia |
| 4060330 | Engine Block Valley Cover Replacement | J313200 | Holden Australia |
| 4060330 | Engine Block Valley Cover Replacement | J313250 | Holden Australia |
| 4060330 | Engine Block Valley Cover Replacement | J313300 | Holden Australia |
| 4060330 | Engine Block Valley Cover Replacement | J313500 | Holden Australia |
| 4060330 | Engine Block Valley Cover Replacement | J300620 | Holden New Zealand |
| 4060330 | Engine Block Valley Cover Replacement | J313100 | Holden New Zealand |
| 4060330 | Engine Block Valley Cover Replacement | J313200 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4060330 | Engine Block Valley Cover Replacement | J313250 | Holden New Zealand |
| 4060330 | Engine Block Valley Cover Replacement | J313300 | Holden New Zealand |
| 4060330 | Engine Block Valley Cover Replacement | J313500 | Holden New Zealand |
| 4060350 | Intake Manifold Cover Replacement | J0110 | GMNA |
| 4060350 | Intake Manifold Cover Replacement | J0150 | GMNA |
| 4060350 | Intake Manifold Cover Replacement | J0194 | GMNA |
| 4060350 | Intake Manifold Cover Replacement | J0231 | GMNA |
| 4060350 | Intake Manifold Cover Replacement | J300650 | Holden Australia |
| 4060350 | Intake Manifold Cover Replacement | J300650 | Holden New Zealand |
| 4060370 | Engine Cover Replacement | J0232 | GMNA |
| 4060370 | Engine Cover Replacement | J1953 | GMNA |
| 4060370 | Engine Cover Replacement | 1220100 | GMK Domestic |
| 4060370 | Engine Cover Replacement | J000651 | Holden Australia |
| 4060370 | Engine Cover Replacement | J000710 | Holden Australia |
| 4060370 | Engine Cover Replacement | J000854 | Holden Australia |
| 4060370 | Engine Cover Replacement | J000651 | Holden New Zealand |
| 4060370 | Engine Cover Replacement | J000710 | Holden New Zealand |
| 4060390 | Engine Sight Shield Replacement | J8374 | GMNA |
| 4060450 | Intake Manifold Replacement | J0199 | GMNA |
| 4060450 | Intake Manifold Replacement | J0201 | GMNA |
| 4060450 | Intake Manifold Replacement | J0205 | GMNA |
| 4060450 | Intake Manifold Replacement | J0210 | GMNA |
| 4060450 | Intake Manifold Replacement | J0250 | GMNA |
| 4060450 | Intake Manifold Replacement | J0290 | GMNA |
| 4060450 | Intake Manifold Replacement | R9222 | GMNA |
| 4060450 | Intake Manifold Replacement | J020300 | Holden Australia |
| 4060450 | Intake Manifold Replacement | J020600 | Holden Australia |
| 4060450 | Intake Manifold Replacement | J020700 | Holden Australia |
| 4060450 | Intake Manifold Replacement | J020800 | Holden Australia |
| 4060450 | Intake Manifold Replacement | J020900 | Holden Australia |
| 4060450 | Intake Manifold Replacement | J021000 | Holden Australia |
| 4060450 | Intake Manifold Replacement | J021100 | Holden Australia |
| 4060450 | Intake Manifold Replacement | J021200 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4060450 | Intake Manifold Replacement | J021300 | Holden Australia |
| 4060450 | Intake Manifold Replacement | J0250 | Holden Australia |
| 4060450 | Intake Manifold Replacement | J300500 | Holden Australia |
| 4060450 | Intake Manifold Replacement | J300600 | Holden Australia |
| 4060450 | Intake Manifold Replacement | J300700 | Holden Australia |
| 4060450 | Intake Manifold Replacement | J300800 | Holden Australia |
| 4060450 | Intake Manifold Replacement | J306010 | Holden Australia |
| 4060450 | Intake Manifold Replacement | J306020 | Holden Australia |
| 4060450 | Intake Manifold Replacement | J020300 | Holden New Zealand |
| 4060450 | Intake Manifold Replacement | J020600 | Holden New Zealand |
| 4060450 | Intake Manifold Replacement | J020700 | Holden New Zealand |
| 4060450 | Intake Manifold Replacement | J300500 | Holden New Zealand |
| 4060450 | Intake Manifold Replacement | J300600 | Holden New Zealand |
| 4060450 | Intake Manifold Replacement | J300700 | Holden New Zealand |
| 4060450 | Intake Manifold Replacement | J300800 | Holden New Zealand |
| 4060450 | Intake Manifold Replacement | J306010 | Holden New Zealand |
| 4060450 | Intake Manifold Replacement | J306020 | Holden New Zealand |
| 4060450 | Intake Manifold Replacement | 1930100 | GMK Overseas |
| 4060450 | Intake Manifold Replacement | 1930200 | GMK Overseas |
| 4060470 | Intake Manifold Gasket Replacement | J0010 | GMNA |
| 4060470 | Intake Manifold Gasket Replacement | J0030 | GMNA |
| 4060470 | Intake Manifold Gasket Replacement | J0130 | GMNA |
| 4060470 | Intake Manifold Gasket Replacement | J0200 | GMNA |
| 4060470 | Intake Manifold Gasket Replacement | J0226 | GMNA |
| 4060470 | Intake Manifold Gasket Replacement | J0227 | GMNA |
| 4060470 | Intake Manifold Gasket Replacement | J0228 | GMNA |
| 4060470 | Intake Manifold Gasket Replacement | J0251 | GMNA |
| 4060470 | Intake Manifold Gasket Replacement | 1251700 | GMK Domestic |
| 4060470 | Intake Manifold Gasket Replacement | J0251 | Holden Australia |
| 4060470 | Intake Manifold Gasket Replacement | J300610 | Holden Australia |
| 4060470 | Intake Manifold Gasket Replacement | J301510 | Holden Australia |
| 4060470 | Intake Manifold Gasket Replacement | J301520 | Holden Australia |
| 4060470 | Intake Manifold Gasket Replacement | J301800 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4060470 | Intake Manifold Gasket Replacement | J302300 | Holden Australia |
| 4060470 | Intake Manifold Gasket Replacement | J0104 | Holden New Zealand |
| 4060470 | Intake Manifold Gasket Replacement | J0200 | Holden New Zealand |
| 4060470 | Intake Manifold Gasket Replacement | J0203 | Holden New Zealand |
| 4060470 | Intake Manifold Gasket Replacement | J0205 | Holden New Zealand |
| 4060470 | Intake Manifold Gasket Replacement | J0206 | Holden New Zealand |
| 4060470 | Intake Manifold Gasket Replacement | J0206A | Holden New Zealand |
| 4060470 | Intake Manifold Gasket Replacement | J300610 | Holden New Zealand |
| 4060470 | Intake Manifold Gasket Replacement | J301510 | Holden New Zealand |
| 4060470 | Intake Manifold Gasket Replacement | J301800 | Holden New Zealand |
| 4060470 | Intake Manifold Gasket Replacement | J302300 | Holden New Zealand |
| 4060470 | Intake Manifold Gasket Replacement | 1931600 | GMK Overseas |
| 4060470 | Intake Manifold Gasket Replacement | 1931700 | GMK Overseas |
| 4060470 | Intake Manifold Gasket Replacement | 1932100 | GMK Overseas |
| 4060490 | Upper Intake Manifold Cover Replacement | J0195 | GMNA |
| 4060490 | Upper Intake Manifold Cover Replacement | J0253 | GMNA |
| 4060510 | Upper Intake Manifold Replacement | J0220 | GMNA |
| 4060510 | Upper Intake Manifold Replacement | J0221 | GMNA |
| 4060510 | Upper Intake Manifold Replacement | J0254 | GMNA |
| 4060510 | Upper Intake Manifold Replacement | 1931300 | GMK Overseas |
| 4060530 | Upper Intake Manifold Gasket Replacement | J0255 | GMNA |
| 4060530 | Upper Intake Manifold Gasket Replacement | 1254800 | GMK Domestic |
| 4060530 | Upper Intake Manifold Gasket Replacement | J0204 | Holden New Zealand |
| 4060550 | Lower Intake Manifold Replacement | J0224 | GMNA |
| 4060550 | Lower Intake Manifold Replacement | J0225 | GMNA |
| 4060550 | Lower Intake Manifold Replacement | J0258 | GMNA |
| 4060550 | Lower Intake Manifold Replacement | 1252700 | GMK Domestic |
| 4060550 | Lower Intake Manifold Replacement | 1931800 | GMK Overseas |
| 4060570 | Lower Intake Manifold Gasket Replacement | J0259 | GMNA |
| 4060590 | Intake Manifold Replacement - Right Side | J0260 | GMNA |
| 4060610 | Intake Manifold Gasket Replacement - Right Side | J0261 | GMNA |
| 4060610 | Intake Manifold Gasket Replacement - Right Side | J020200 | Holden New Zealand |
| 4060610 | Intake Manifold Gasket Replacement - Right Side | J020500 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4060610 | Intake Manifold Gasket Replacement - Right Side | J301500 | Holden New Zealand |
| 4060630 | Intake Manifold Replacement - Left Side | J0264 | GMNA |
| 4060650 | Intake Manifold Gasket Replacement - Left Side | J0265 | GMNA |
| 4060670 | Center Intake Manifold Replacement | J0268 | GMNA |
| 4060690 | Center Intake Manifold Gasket Replacement | J0269 | GMNA |
| 4060710 | Valve Rocker Arm Upper Cover Replacement - Right Side | J0280 | GMNA |
| 4060730 | Valve Rocker Arm Upper Cover Replacement - Left Side | J0281 | GMNA |
| 4060810 | Valve Rocker Arm Lower Cover Replacement - Left Side | J0285 | GMNA |
| 4060830 | Valve Rocker Arm Lower Cover Replacement - Right Side | J0286 | GMNA |
| 4060850 | Valve Rocker Arm Cover Replacement - Right Side | J0300 | GMNA |
| 4060870 | Valve Rocker Arm Cover Replacement - Left Side | J0301 | GMNA |
| 4060910 | Valve Rocker Arm Cover Replacement | J0302 | GMNA |
| 4060910 | Valve Rocker Arm Cover Replacement | J0308 | GMNA |
| 4060910 | Valve Rocker Arm Cover Replacement | 1212600 | GMK Domestic |
| 4060910 | Valve Rocker Arm Cover Replacement | 1213800 | GMK Domestic |
| 4060910 | Valve Rocker Arm Cover Replacement | 1214100 | GMK Domestic |
| 4060910 | Valve Rocker Arm Cover Replacement | 1214700 | GMK Domestic |
| 4060910 | Valve Rocker Arm Cover Replacement | J030300 | Holden Australia |
| 4060910 | Valve Rocker Arm Cover Replacement | J030600 | Holden Australia |
| 4060910 | Valve Rocker Arm Cover Replacement | J030700 | Holden Australia |
| 4060910 | Valve Rocker Arm Cover Replacement | J0308 | Holden Australia |
| 4060910 | Valve Rocker Arm Cover Replacement | J030800 | Holden Australia |
| 4060910 | Valve Rocker Arm Cover Replacement | J030900 | Holden Australia |
| 4060910 | Valve Rocker Arm Cover Replacement | J030950 | Holden Australia |
| 4060910 | Valve Rocker Arm Cover Replacement | J031000 | Holden Australia |
| 4060910 | Valve Rocker Arm Cover Replacement | J031100 | Holden Australia |
| 4060910 | Valve Rocker Arm Cover Replacement | J031200 | Holden Australia |
| 4060910 | Valve Rocker Arm Cover Replacement | J109100 | Holden Australia |
| 4060910 | Valve Rocker Arm Cover Replacement | J207000 | Holden Australia |
| 4060910 | Valve Rocker Arm Cover Replacement | J207050 | Holden Australia |
| 4060910 | Valve Rocker Arm Cover Replacement | J307000 | Holden Australia |
| 4060910 | Valve Rocker Arm Cover Replacement | J307100 | Holden Australia |
| 4060910 | Valve Rocker Arm Cover Replacement | J307150 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4060910 | Valve Rocker Arm Cover Replacement | J307200 | Holden Australia |
| 4060910 | Valve Rocker Arm Cover Replacement | J307250 | Holden Australia |
| 4060910 | Valve Rocker Arm Cover Replacement | J0303 | Holden New Zealand |
| 4060910 | Valve Rocker Arm Cover Replacement | J030300 | Holden New Zealand |
| 4060910 | Valve Rocker Arm Cover Replacement | J0304 | Holden New Zealand |
| 4060910 | Valve Rocker Arm Cover Replacement | J0305 | Holden New Zealand |
| 4060910 | Valve Rocker Arm Cover Replacement | J0308 | Holden New Zealand |
| 4060910 | Valve Rocker Arm Cover Replacement | J030800 | Holden New Zealand |
| 4060910 | Valve Rocker Arm Cover Replacement | J0309 | Holden New Zealand |
| 4060910 | Valve Rocker Arm Cover Replacement | J030900 | Holden New Zealand |
| 4060910 | Valve Rocker Arm Cover Replacement | J109100 | Holden New Zealand |
| 4060910 | Valve Rocker Arm Cover Replacement | J207000 | Holden New Zealand |
| 4060910 | Valve Rocker Arm Cover Replacement | J207050 | Holden New Zealand |
| 4060910 | Valve Rocker Arm Cover Replacement | J307000 | Holden New Zealand |
| 4060910 | Valve Rocker Arm Cover Replacement | J307100 | Holden New Zealand |
| 4060910 | Valve Rocker Arm Cover Replacement | J307150 | Holden New Zealand |
| 4060910 | Valve Rocker Arm Cover Replacement | J307200 | Holden New Zealand |
| 4060910 | Valve Rocker Arm Cover Replacement | J307250 | Holden New Zealand |
| 4060910 | Valve Rocker Arm Cover Replacement | 1322100 | GMK Overseas |
| 4060930 | Camshaft Cover Replacement | J0309 | GMNA |
| 4060930 | Camshaft Cover Replacement | J0315 | GMNA |
| 4060930 | Camshaft Cover Replacement | J0316 | GMNA |
| 4060930 | Camshaft Cover Replacement | J0317 | GMNA |
| 4060930 | Camshaft Cover Replacement | J0318 | GMNA |
| 4060930 | Camshaft Cover Replacement | J0319 | GMNA |
| 4060930 | Camshaft Cover Replacement | J0848 | GMNA |
| 4060930 | Camshaft Cover Replacement | 1156100 | GMK Domestic |
| 4060930 | Camshaft Cover Replacement | 1220200 | GMK Domestic |
| 4060930 | Camshaft Cover Replacement | 1220300 | GMK Domestic |
| 4060930 | Camshaft Cover Replacement | 1220400 | GMK Domestic |
| 4060930 | Camshaft Cover Replacement | 1220600 | GMK Domestic |
| 4060930 | Camshaft Cover Replacement | J304700 | Holden Australia |
| 4060930 | Camshaft Cover Replacement | J304700 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4060930 | Camshaft Cover Replacement | R013075 | Holden New Zealand |
| 4060930 | Camshaft Cover Replacement | 1322800 | GMK Overseas |
| 4060930 | Camshaft Cover Replacement | 1323200 | GMK Overseas |
| 4060930 | Camshaft Cover Replacement | 1323400 | GMK Overseas |
| 4060950 | Camshaft Cover Replacement - Right Side | J0310 | GMNA |
| 4060950 | Camshaft Cover Replacement - Right Side | J0868 | GMNA |
| 4060970 | Camshaft Cover Replacement - Left Side | J0311 | GMNA |
| 4060970 | Camshaft Cover Replacement - Left Side | J0869 | GMNA |
| 4060970 | Camshaft Cover Replacement - Left Side | R013077 | Holden New Zealand |
| 4060980 | Camshaft Rear Cover Replacement | | |
| 4060990 | Camshaft Housing Cover Replacement | | |
| 4061030 | Camshaft Housing Replacement | J0870 | GMNA |
| 4061030 | Camshaft Housing Replacement | J0871 | GMNA |
| 4061030 | Camshaft Housing Replacement | J0873 | GMNA |
| 4061030 | Camshaft Housing Replacement | J0882 | GMNA |
| 4061030 | Camshaft Housing Replacement | 1213600 | GMK Domestic |
| 4061030 | Camshaft Housing Replacement | 1213700 | GMK Domestic |
| 4061030 | Camshaft Housing Replacement | J314200 | Holden Australia |
| 4061030 | Camshaft Housing Replacement | J314200 | Holden New Zealand |
| 4061030 | Camshaft Housing Replacement | 1322500 | GMK Overseas |
| 4061170 | Valve Rocker Arm Replacement - Right Side | J0350 | GMNA |
| 4061190 | Valve Rocker Arm Replacement - Left Side | J0351 | GMNA |
| 4061190 | Valve Rocker Arm Replacement - Left Side | J307010 | Holden Australia |
| 4061190 | Valve Rocker Arm Replacement - Left Side | J307040 | Holden Australia |
| 4061190 | Valve Rocker Arm Replacement - Left Side | J307110 | Holden Australia |
| 4061190 | Valve Rocker Arm Replacement - Left Side | J307140 | Holden Australia |
| 4061190 | Valve Rocker Arm Replacement - Left Side | J307210 | Holden Australia |
| 4061190 | Valve Rocker Arm Replacement - Left Side | J307240 | Holden Australia |
| 4061190 | Valve Rocker Arm Replacement - Left Side | J307010 | Holden New Zealand |
| 4061190 | Valve Rocker Arm Replacement - Left Side | J307040 | Holden New Zealand |
| 4061190 | Valve Rocker Arm Replacement - Left Side | J307110 | Holden New Zealand |
| 4061190 | Valve Rocker Arm Replacement - Left Side | J307140 | Holden New Zealand |
| 4061190 | Valve Rocker Arm Replacement - Left Side | J307210 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4061210 | Hydraulic Valve Lash Adjuster Replacement - Right Side | | |
| 4061230 | Hydraulic Valve Lash Adjuster Replacement - Left Side | | |
| 4061250 | Hydraulic Valve Lash Adjuster Arm Replacement | J0355 | GMNA |
| 4061250 | Hydraulic Valve Lash Adjuster Arm Replacement | J0420 | GMNA |
| 4061250 | Hydraulic Valve Lash Adjuster Arm Replacement | J0423 | GMNA |
| 4061250 | Hydraulic Valve Lash Adjuster Arm Replacement | J0560 | GMNA |
| 4061250 | Hydraulic Valve Lash Adjuster Arm Replacement | 1313100 | GMK Overseas |
| 4061250 | Hydraulic Valve Lash Adjuster Arm Replacement | 131310B | GMK Overseas |
| 4061270 | Hydraulic Valve Lash Adjuster Replacement | | |
| 4061310 | Valve Rocker Arm Replacement | J0336 | GMNA |
| 4061310 | Valve Rocker Arm Replacement | J0337 | GMNA |
| 4061310 | Valve Rocker Arm Replacement | J0338 | GMNA |
| 4061310 | Valve Rocker Arm Replacement | J0340 | GMNA |
| 4061310 | Valve Rocker Arm Replacement | J0341 | GMNA |
| 4061310 | Valve Rocker Arm Replacement | J0342 | GMNA |
| 4061310 | Valve Rocker Arm Replacement | J0343 | GMNA |
| 4061310 | Valve Rocker Arm Replacement | J0357 | GMNA |
| 4061310 | Valve Rocker Arm Replacement | J0358 | GMNA |
| 4061310 | Valve Rocker Arm Replacement | J0359 | GMNA |
| 4061310 | Valve Rocker Arm Replacement | J0360 | GMNA |
| 4061310 | Valve Rocker Arm Replacement | J0361 | GMNA |
| 4061310 | Valve Rocker Arm Replacement | J0367 | GMNA |
| 4061310 | Valve Rocker Arm Replacement | J0368 | GMNA |
| 4061310 | Valve Rocker Arm Replacement | J0370 | GMNA |
| 4061310 | Valve Rocker Arm Replacement | J0371 | GMNA |
| 4061310 | Valve Rocker Arm Replacement | J0377 | GMNA |
| 4061310 | Valve Rocker Arm Replacement | 1163000 | GMK Domestic |
| 4061310 | Valve Rocker Arm Replacement | 1211100 | GMK Domestic |
| 4061310 | Valve Rocker Arm Replacement | 1211600 | GMK Domestic |
| 4061310 | Valve Rocker Arm Replacement | 1212000 | GMK Domestic |
| 4061310 | Valve Rocker Arm Replacement | 1212100 | GMK Domestic |
| 4061310 | Valve Rocker Arm Replacement | J035700 | Holden Australia |
| 4061310 | Valve Rocker Arm Replacement | J035800 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4061310 | Valve Rocker Arm Replacement | J035900 | Holden Australia |
| 4061310 | Valve Rocker Arm Replacement | J035950 | Holden Australia |
| 4061310 | Valve Rocker Arm Replacement | J036100 | Holden Australia |
| 4061310 | Valve Rocker Arm Replacement | J0358 | Holden New Zealand |
| 4061310 | Valve Rocker Arm Replacement | J035800 | Holden New Zealand |
| 4061310 | Valve Rocker Arm Replacement | J0359 | Holden New Zealand |
| 4061310 | Valve Rocker Arm Replacement | J0360 | Holden New Zealand |
| 4061310 | Valve Rocker Arm Replacement | 1312100 | GMK Overseas |
| 4061310 | Valve Rocker Arm Replacement | 131210B | GMK Overseas |
| 4061310 | Valve Rocker Arm Replacement | 1323500 | GMK Overseas |
| 4061310 | Valve Rocker Arm Replacement | 132350B | GMK Overseas |
| 4061310 | Valve Rocker Arm Replacement | 1323900 | GMK Overseas |
| 4061310 | Valve Rocker Arm Replacement | 132390B | GMK Overseas |
| 4061310 | Valve Rocker Arm Replacement | 132390C | GMK Overseas |
| 4061532 | Valve Clearance Adjustment | J0519 | GMNA |
| 4061532 | Valve Clearance Adjustment | 1141120 | GMK Domestic |
| 4061532 | Valve Clearance Adjustment | J042300 | Holden Australia |
| 4061532 | Valve Clearance Adjustment | J042600 | Holden Australia |
| 4061532 | Valve Clearance Adjustment | J042700 | Holden Australia |
| 4061532 | Valve Clearance Adjustment | J042800 | Holden Australia |
| 4061532 | Valve Clearance Adjustment | J307300 | Holden Australia |
| 4061532 | Valve Clearance Adjustment | J042300 | Holden New Zealand |
| 4061532 | Valve Clearance Adjustment | J0425 | Holden New Zealand |
| 4061532 | Valve Clearance Adjustment | 1313000 | GMK Overseas |
| 4061532 | Valve Clearance Adjustment | 1314900 | GMK Overseas |
| 4061550 | Cylinder Head Opening Plate Replacement | J0493 | GMNA |
| 4061550 | Cylinder Head Opening Plate Replacement | J0866 | GMNA |
| 4061550 | Cylinder Head Opening Plate Replacement | 1111700 | GMK Domestic |
| 4061550 | Cylinder Head Opening Plate Replacement | 1140100 | GMK Domestic |
| 4061550 | Cylinder Head Opening Plate Replacement | 1211700 | GMK Overseas |
| 4061550 | Cylinder Head Opening Plate Replacement | 1212100 | GMK Overseas |
| 4061670 | Cylinder Head Gasket Replacement - Right Side | J0500 | GMNA |
| 4061670 | Cylinder Head Gasket Replacement - Right Side | J050000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4061670 | Cylinder Head Gasket Replacement - Right Side | J310100 | Holden Australia |
| 4061670 | Cylinder Head Gasket Replacement - Right Side | J310100 | Holden New Zealand |
| 4061690 | Cylinder Head Gasket Replacement - Left Side | J0501 | GMNA |
| 4061690 | Cylinder Head Gasket Replacement - Left Side | 1140201 | GMK Domestic |
| 4061690 | Cylinder Head Gasket Replacement - Left Side | 1156700 | GMK Domestic |
| 4061690 | Cylinder Head Gasket Replacement - Left Side | 1156800 | GMK Domestic |
| 4061690 | Cylinder Head Gasket Replacement - Left Side | J310010 | Holden Australia |
| 4061690 | Cylinder Head Gasket Replacement - Left Side | J310200 | Holden Australia |
| 4061690 | Cylinder Head Gasket Replacement - Left Side | J310200 | Holden New Zealand |
| 4061730 | Cylinder Head Gasket Replacement | J0505 | GMNA |
| 4061730 | Cylinder Head Gasket Replacement | J0508 | GMNA |
| 4061730 | Cylinder Head Gasket Replacement | J1057 | GMNA |
| 4061730 | Cylinder Head Gasket Replacement | 1160100 | GMK Domestic |
| 4061730 | Cylinder Head Gasket Replacement | J050300 | Holden Australia |
| 4061730 | Cylinder Head Gasket Replacement | J050600 | Holden Australia |
| 4061730 | Cylinder Head Gasket Replacement | J050700 | Holden Australia |
| 4061730 | Cylinder Head Gasket Replacement | J0508 | Holden Australia |
| 4061730 | Cylinder Head Gasket Replacement | J050800 | Holden Australia |
| 4061730 | Cylinder Head Gasket Replacement | J050950 | Holden Australia |
| 4061730 | Cylinder Head Gasket Replacement | J051000 | Holden Australia |
| 4061730 | Cylinder Head Gasket Replacement | J051100 | Holden Australia |
| 4061730 | Cylinder Head Gasket Replacement | J210000 | Holden Australia |
| 4061730 | Cylinder Head Gasket Replacement | J0503 | Holden New Zealand |
| 4061730 | Cylinder Head Gasket Replacement | J0505 | Holden New Zealand |
| 4061730 | Cylinder Head Gasket Replacement | J0506 | Holden New Zealand |
| 4061730 | Cylinder Head Gasket Replacement | J050700 | Holden New Zealand |
| 4061730 | Cylinder Head Gasket Replacement | J0508 | Holden New Zealand |
| 4061730 | Cylinder Head Gasket Replacement | J210000 | Holden New Zealand |
| 4061730 | Cylinder Head Gasket Replacement | 1312300 | GMK Overseas |
| 4061730 | Cylinder Head Gasket Replacement | 131230A | GMK Overseas |
| 4061750 | Oil Flow Check Valve Replacement | J0509 | GMNA |
| 4061750 | Oil Flow Check Valve Replacement | J603000 | Holden Australia |
| 4061750 | Oil Flow Check Valve Replacement | 1232600 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4061770 | Cylinder Head Replacement - Right Side | J0510 | GMNA |
| 4061770 | Cylinder Head Replacement - Right Side | J051050 | Holden Australia |
| 4061770 | Cylinder Head Replacement - Right Side | J310400 | Holden New Zealand |
| 4061770 | Cylinder Head Replacement - Right Side | 1312610 | GMK Overseas |
| 4061770 | Cylinder Head Replacement - Right Side | 1312620 | GMK Overseas |
| 4061790 | Cylinder Head Replacement - Left Side | J0511 | GMNA |
| 4061790 | Cylinder Head Replacement - Left Side | J310500 | Holden New Zealand |
| 4061790 | Cylinder Head Replacement - Left Side | 1312640 | GMK Overseas |
| 4061790 | Cylinder Head Replacement - Left Side | 1312650 | GMK Overseas |
| 4061830 | Cylinder Head Replacement | J0517 | GMNA |
| 4061830 | Cylinder Head Replacement | J0518 | GMNA |
| 4061830 | Cylinder Head Replacement | J3530 | GMNA |
| 4061830 | Cylinder Head Replacement | 1156000 | GMK Domestic |
| 4061830 | Cylinder Head Replacement | 1156400 | GMK Domestic |
| 4061830 | Cylinder Head Replacement | 1160200 | GMK Domestic |
| 4061830 | Cylinder Head Replacement | 1160300 | GMK Domestic |
| 4061830 | Cylinder Head Replacement | J051300 | Holden Australia |
| 4061830 | Cylinder Head Replacement | J051600 | Holden Australia |
| 4061830 | Cylinder Head Replacement | J051700 | Holden Australia |
| 4061830 | Cylinder Head Replacement | J0518 | Holden Australia |
| 4061830 | Cylinder Head Replacement | J051800 | Holden Australia |
| 4061830 | Cylinder Head Replacement | J051900 | Holden Australia |
| 4061830 | Cylinder Head Replacement | J052000 | Holden Australia |
| 4061830 | Cylinder Head Replacement | J210050 | Holden Australia |
| 4061830 | Cylinder Head Replacement | J310150 | Holden Australia |
| 4061830 | Cylinder Head Replacement | J310250 | Holden Australia |
| 4061830 | Cylinder Head Replacement | J310300 | Holden Australia |
| 4061830 | Cylinder Head Replacement | J310350 | Holden Australia |
| 4061830 | Cylinder Head Replacement | J310400 | Holden Australia |
| 4061830 | Cylinder Head Replacement | J310450 | Holden Australia |
| 4061830 | Cylinder Head Replacement | J310500 | Holden Australia |
| 4061830 | Cylinder Head Replacement | J310550 | Holden Australia |
| 4061830 | Cylinder Head Replacement | J310600 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4061830 | Cylinder Head Replacement | J310650 | Holden Australia |
| 4061830 | Cylinder Head Replacement | J051300 | Holden New Zealand |
| 4061830 | Cylinder Head Replacement | J0514 | Holden New Zealand |
| 4061830 | Cylinder Head Replacement | J0515 | Holden New Zealand |
| 4061830 | Cylinder Head Replacement | J0516 | Holden New Zealand |
| 4061830 | Cylinder Head Replacement | J051800 | Holden New Zealand |
| 4061830 | Cylinder Head Replacement | J0519 | Holden New Zealand |
| 4061830 | Cylinder Head Replacement | J051900 | Holden New Zealand |
| 4061830 | Cylinder Head Replacement | J210050 | Holden New Zealand |
| 4061830 | Cylinder Head Replacement | J310250 | Holden New Zealand |
| 4061830 | Cylinder Head Replacement | J310350 | Holden New Zealand |
| 4061830 | Cylinder Head Replacement | J310450 | Holden New Zealand |
| 4061830 | Cylinder Head Replacement | J310550 | Holden New Zealand |
| 4061830 | Cylinder Head Replacement | J310650 | Holden New Zealand |
| 4061830 | Cylinder Head Replacement | 1312400 | GMK Overseas |
| 4061830 | Cylinder Head Replacement | 1312500 | GMK Overseas |
| 4061830 | Cylinder Head Replacement | 131250A | GMK Overseas |
| 4061830 | Cylinder Head Replacement | 131250B | GMK Overseas |
| 4061830 | Cylinder Head Replacement | 1312600 | GMK Overseas |
| 4061830 | Cylinder Head Replacement | 131260A | GMK Overseas |
| 4061850 | Intake or Exhaust Valve Replacement - Right Side | J0520 | GMNA |
| 4061850 | Intake or Exhaust Valve Replacement - Right Side | 1312710 | GMK Overseas |
| 4061870 | Intake or Exhaust Valve Replacement - Left Side | J0521 | GMNA |
| 4061870 | Intake or Exhaust Valve Replacement - Left Side | 1161500 | GMK Domestic |
| 4061870 | Intake or Exhaust Valve Replacement - Left Side | 1312720 | GMK Overseas |
| 4061910 | Intake or Exhaust Valve Replacement | J0527 | GMNA |
| 4061910 | Intake or Exhaust Valve Replacement | J0528 | GMNA |
| 4061910 | Intake or Exhaust Valve Replacement | T5671 | GMNA |
| 4061910 | Intake or Exhaust Valve Replacement | J0528 | Holden Australia |
| 4061910 | Intake or Exhaust Valve Replacement | J210010 | Holden Australia |
| 4061910 | Intake or Exhaust Valve Replacement | 1312700 | GMK Overseas |
| 4061910 | Intake or Exhaust Valve Replacement | 131270A | GMK Overseas |
| 4061910 | Intake or Exhaust Valve Replacement | 131270C | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4061910 | Intake or Exhaust Valve Replacement | 131270D | GMK Overseas |
| 4061970 | Valve Stem Oil Seal and Valve Spring Replacement - Right Side | J0540 | GMNA |
| 4061990 | Valve Stem Oil Seal and Valve Spring Replacement - Left Side | J0541 | GMNA |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J0544 | GMNA |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J0545 | GMNA |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J0546 | GMNA |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J0547 | GMNA |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J0548 | GMNA |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J0550 | GMNA |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J0551 | GMNA |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J0556 | GMNA |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J7511 | GMNA |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | 1160800 | GMK Domestic |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | 1160900 | GMK Domestic |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | 1161520 | GMK Domestic |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | 1161800 | GMK Domestic |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | 1162000 | GMK Domestic |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | 1162100 | GMK Domestic |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J054300 | Holden Australia |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J054600 | Holden Australia |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J054700 | Holden Australia |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J054800 | Holden Australia |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J054900 | Holden Australia |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J207030 | Holden Australia |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J307030 | Holden Australia |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J307130 | Holden Australia |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J307230 | Holden Australia |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J207030 | Holden New Zealand |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J307030 | Holden New Zealand |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J307130 | Holden New Zealand |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J307130A3 | Holden New Zealand |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | J307230 | Holden New Zealand |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | 1312800 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | 131280C | GMK Overseas |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | 131280D | GMK Overseas |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | 1312900 | GMK Overseas |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | 131290C | GMK Overseas |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | 131290D | GMK Overseas |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | 1313300 | GMK Overseas |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | 1313400 | GMK Overseas |
| 4062090 | Valve Stem Oil Seal and Valve Spring Replacement | 1314600 | GMK Overseas |
| 4062190 | Hydraulic Valve Lash Adjuster Replacement - Intake | J0565 | GMNA |
| 4062210 | Hydraulic Valve Lash Adjuster Replacement - Exhaust | J0566 | GMNA |
| 4062230 | Valve Push Rod Replacement - Right Side | J0580 | GMNA |
| 4062250 | Valve Push Rod Replacement - Left Side | J0581 | GMNA |
| 4062250 | Valve Push Rod Replacement - Left Side | J0588 | GMNA |
| 4062250 | Valve Push Rod Replacement - Left Side | J058300 | Holden Australia |
| 4062250 | Valve Push Rod Replacement - Left Side | J058300 | Holden New Zealand |
| 4062350 | Valve Lifter Oil Manifold Replacement | J0610 | GMNA |
| 4062390 | Valve Lifter Replacement - Right Side | J0620 | GMNA |
| 4062391 | Valve Lifter Replacement - Both Sides | J0627 | GMNA |
| 4062410 | Valve Lifter Replacement - Left Side | J0621 | GMNA |
| 4062450 | Valve Lifter Replacement | J0623 | GMNA |
| 4062450 | Valve Lifter Replacement | J0628 | GMNA |
| 4062450 | Valve Lifter Replacement | J0629 | GMNA |
| 4062450 | Valve Lifter Replacement | J7532 | GMNA |
| 4062450 | Valve Lifter Replacement | J7533 | GMNA |
| 4062450 | Valve Lifter Replacement | 1209990 | GMK Domestic |
| 4062450 | Valve Lifter Replacement | J062100 | Holden Australia |
| 4062450 | Valve Lifter Replacement | J062150 | Holden Australia |
| 4062450 | Valve Lifter Replacement | J062300 | Holden Australia |
| 4062450 | Valve Lifter Replacement | J062600 | Holden Australia |
| 4062450 | Valve Lifter Replacement | J062700 | Holden Australia |
| 4062450 | Valve Lifter Replacement | J062900 | Holden Australia |
| 4062450 | Valve Lifter Replacement | J062950 | Holden Australia |
| 4062450 | Valve Lifter Replacement | J311100 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4062450 | Valve Lifter Replacement | J311100 | Holden New Zealand |
| 4062450 | Valve Lifter Replacement | 1313500 | GMK Overseas |
| 4062450 | Valve Lifter Replacement | 131350C | GMK Overseas |
| 4062450 | Valve Lifter Replacement | 131350D | GMK Overseas |
| 4062450 | Valve Lifter Replacement | 1313800 | GMK Overseas |
| 4062450 | Valve Lifter Replacement | 131380C | GMK Overseas |
| 4062450 | Valve Lifter Replacement | 131380D | GMK Overseas |
| 4062710 | Drive Belt Replacement | J0658 | GMNA |
| 4062710 | Drive Belt Replacement | 1111000 | GMK Domestic |
| 4062710 | Drive Belt Replacement | 1132000 | GMK Domestic |
| 4062710 | Drive Belt Replacement | J607100 | Holden Australia |
| 4062710 | Drive Belt Replacement | W200200 | Holden Australia |
| 4062710 | Drive Belt Replacement | J607100 | Holden New Zealand |
| 4062710 | Drive Belt Replacement | 1132200 | GMK Overseas |
| 4062750 | Air Conditioning Compressor Belt Replacement | J0662 | GMNA |
| 4062750 | Air Conditioning Compressor Belt Replacement | 6111020 | GMK Domestic |
| 4062750 | Air Conditioning Compressor Belt Replacement | D000402 | Holden Australia |
| 4062750 | Air Conditioning Compressor Belt Replacement | 1131600 | GMK Overseas |
| 4062770 | Generator Belt Replacement | J0663 | GMNA |
| 4062770 | Generator Belt Replacement | J0663 | Holden New Zealand |
| 4062830 | Drive Belt Replacement - Accessory | J0667 | GMNA |
| 4062830 | Drive Belt Replacement - Accessory | R9226 | GMNA |
| 4062850 | Supercharger Belt Replacement | J0668 | GMNA |
| 4062910 | Supercharger Belt Idler Pulley Replacement | J3313 | GMNA |
| 4062970 | Supercharger Belt Tensioner Replacement | J0677 | GMNA |
| 4062990 | Drive Belt Tensioner Replacement - Air Conditioning | J0679 | GMNA |
| 4063010 | Drive Belt Tensioner Replacement | J0675 | GMNA |
| 4063010 | Drive Belt Tensioner Replacement | J0676 | GMNA |
| 4063010 | Drive Belt Tensioner Replacement | J0680 | GMNA |
| 4063010 | Drive Belt Tensioner Replacement | J0680 | Holden Australia |
| 4063010 | Drive Belt Tensioner Replacement | J068000 | Holden Australia |
| 4063010 | Drive Belt Tensioner Replacement | J607250 | Holden Australia |
| 4063010 | Drive Belt Tensioner Replacement | J607250 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4063010 | Drive Belt Tensioner Replacement | 1132400 | GMK Overseas |
| 4063050 | Water Pump and Generator Belt Tensioner Replacement | J0682 | GMNA |
| 4063070 | Air Conditioning Compressor and Power Steering Pump Belt Tensioner Replacement | D4005 | GMNA |
| 4063070 | Air Conditioning Compressor and Power Steering Pump Belt Tensioner Replacement | D4006 | GMNA |
| 4063070 | Air Conditioning Compressor and Power Steering Pump Belt Tensioner Replacement | H9742 | GMNA |
| 4063070 | Air Conditioning Compressor and Power Steering Pump Belt Tensioner Replacement | J0683 | GMNA |
| 4063070 | Air Conditioning Compressor and Power Steering Pump Belt Tensioner Replacement | J7540 | GMNA |
| 4063070 | Air Conditioning Compressor and Power Steering Pump Belt Tensioner Replacement | 6111100 | GMK Domestic |
| 4063070 | Air Conditioning Compressor and Power Steering Pump Belt Tensioner Replacement | 8117220 | GMK Domestic |
| 4063070 | Air Conditioning Compressor and Power Steering Pump Belt Tensioner Replacement | D312000 | Holden Australia |
| 4063070 | Air Conditioning Compressor and Power Steering Pump Belt Tensioner Replacement | D312100 | Holden Australia |
| 4063070 | Air Conditioning Compressor and Power Steering Pump Belt Tensioner Replacement | D312000 | Holden New Zealand |
| 4063070 | Air Conditioning Compressor and Power Steering Pump Belt Tensioner Replacement | D312100 | Holden New Zealand |
| 4063070 | Air Conditioning Compressor and Power Steering Pump Belt Tensioner Replacement | 7330400 | GMK Overseas |
| 4063110 | Drive Belt Tensioner Replacement - Accessory | J0685 | GMNA |
| 4063170 | Drive Belt and Pulley Cover Replacement | | |
| 4063190 | Belt Idler Pulley Replacement - Upper | | |
| 4063210 | Belt Idler Pulley Replacement | J0671 | GMNA |
| 4063210 | Belt Idler Pulley Replacement | J0687 | GMNA |
| 4063210 | Belt Idler Pulley Replacement | J0690 | GMNA |
| 4063210 | Belt Idler Pulley Replacement | 1111200 | GMK Domestic |
| 4063210 | Belt Idler Pulley Replacement | 1132300 | GMK Domestic |
| 4063210 | Belt Idler Pulley Replacement | D301170 | Holden Australia |
| 4063210 | Belt Idler Pulley Replacement | D312050 | Holden Australia |
| 4063210 | Belt Idler Pulley Replacement | D402000 | Holden Australia |
| 4063210 | Belt Idler Pulley Replacement | J0690 | Holden Australia |
| 4063210 | Belt Idler Pulley Replacement | D312050 | Holden New Zealand |
| 4063210 | Belt Idler Pulley Replacement | D402000 | Holden New Zealand |
| 4063210 | Belt Idler Pulley Replacement | 1132300 | GMK Overseas |
| 4063230 | Drive Belt Idler Pulley Replacement | J0692 | GMNA |
| 4063230 | Drive Belt Idler Pulley Replacement | J081000 | Holden Australia |
| 4063230 | Drive Belt Idler Pulley Replacement | J081300 | Holden Australia |
| 4063230 | Drive Belt Idler Pulley Replacement | J081600 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4063230 | Drive Belt Idler Pulley Replacement | J081700 | Holden Australia |
| 4063230 | Drive Belt Idler Pulley Replacement | J081800 | Holden Australia |
| 4063230 | Drive Belt Idler Pulley Replacement | J082700 | Holden Australia |
| 4063230 | Drive Belt Idler Pulley Replacement | J604500 | Holden Australia |
| 4063230 | Drive Belt Idler Pulley Replacement | J606800 | Holden Australia |
| 4063230 | Drive Belt Idler Pulley Replacement | J606900 | Holden Australia |
| 4063230 | Drive Belt Idler Pulley Replacement | J607200 | Holden Australia |
| 4063230 | Drive Belt Idler Pulley Replacement | J607350 | Holden Australia |
| 4063230 | Drive Belt Idler Pulley Replacement | J607550 | Holden Australia |
| 4063230 | Drive Belt Idler Pulley Replacement | J606800 | Holden New Zealand |
| 4063230 | Drive Belt Idler Pulley Replacement | J606900 | Holden New Zealand |
| 4063230 | Drive Belt Idler Pulley Replacement | J607200 | Holden New Zealand |
| 4063230 | Drive Belt Idler Pulley Replacement | J607350 | Holden New Zealand |
| 4063230 | Drive Belt Idler Pulley Replacement | J607550 | Holden New Zealand |
| 4063250 | Crankshaft Pulley Replacement | J0695 | GMNA |
| 4063250 | Crankshaft Pulley Replacement | J0700 | GMNA |
| 4063250 | Crankshaft Pulley Replacement | 1150400 | GMK Domestic |
| 4063250 | Crankshaft Pulley Replacement | 1150500 | GMK Domestic |
| 4063250 | Crankshaft Pulley Replacement | J000493 | Holden Australia |
| 4063250 | Crankshaft Pulley Replacement | J000800 | Holden Australia |
| 4063250 | Crankshaft Pulley Replacement | J070000 | Holden Australia |
| 4063250 | Crankshaft Pulley Replacement | J070300 | Holden Australia |
| 4063250 | Crankshaft Pulley Replacement | J070600 | Holden Australia |
| 4063250 | Crankshaft Pulley Replacement | J070700 | Holden Australia |
| 4063250 | Crankshaft Pulley Replacement | J070800 | Holden Australia |
| 4063250 | Crankshaft Pulley Replacement | J070900 | Holden Australia |
| 4063250 | Crankshaft Pulley Replacement | J070950 | Holden Australia |
| 4063250 | Crankshaft Pulley Replacement | J071000 | Holden Australia |
| 4063250 | Crankshaft Pulley Replacement | J312400 | Holden Australia |
| 4063250 | Crankshaft Pulley Replacement | J0700 | Holden New Zealand |
| 4063250 | Crankshaft Pulley Replacement | J0703 | Holden New Zealand |
| 4063250 | Crankshaft Pulley Replacement | J070300 | Holden New Zealand |
| 4063250 | Crankshaft Pulley Replacement | J312400 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4063250 | Crankshaft Pulley Replacement | 1332100 | GMK Overseas |
| 4063290 | Crankshaft Balancer Replacement | J0715 | GMNA |
| 4063290 | Crankshaft Balancer Replacement | J0720 | GMNA |
| 4063290 | Crankshaft Balancer Replacement | J312500 | Holden Australia |
| 4063290 | Crankshaft Balancer Replacement | J312500 | Holden New Zealand |
| 4063310 | Timing Belt Front Cover Replacement | J0735 | GMNA |
| 4063310 | Timing Belt Front Cover Replacement | 1162800 | GMK Domestic |
| 4063310 | Timing Belt Front Cover Replacement | 1231100 | GMK Domestic |
| 4063310 | Timing Belt Front Cover Replacement | J313400 | Holden Australia |
| 4063310 | Timing Belt Front Cover Replacement | J313400 | Holden New Zealand |
| 4063310 | Timing Belt Front Cover Replacement | 1334800 | GMK Overseas |
| 4063330 | Timing Belt Rear Cover Replacement | J0736 | GMNA |
| 4063330 | Timing Belt Rear Cover Replacement | 1332300 | GMK Overseas |
| 4063350 | Timing Belt Upper Front Cover Replacement | J0737 | GMNA |
| 4063350 | Timing Belt Upper Front Cover Replacement | 1334100 | GMK Overseas |
| 4063350 | Timing Belt Upper Front Cover Replacement | 1334200 | GMK Overseas |
| 4063370 | Timing Belt Center Front Cover Replacement | J0738 | GMNA |
| 4063390 | Timing Belt Lower Front Cover Replacement | J0739 | GMNA |
| 4063390 | Timing Belt Lower Front Cover Replacement | J313750 | Holden Australia |
| 4063390 | Timing Belt Lower Front Cover Replacement | J313750 | Holden New Zealand |
| 4063390 | Timing Belt Lower Front Cover Replacement | 1334300 | GMK Overseas |
| 4063430 | Crankshaft Front Oil Seal Replacement | J0741 | GMNA |
| 4063430 | Crankshaft Front Oil Seal Replacement | J0747 | GMNA |
| 4063430 | Crankshaft Front Oil Seal Replacement | J0748 | GMNA |
| 4063430 | Crankshaft Front Oil Seal Replacement | J0750 | GMNA |
| 4063430 | Crankshaft Front Oil Seal Replacement | J0753 | GMNA |
| 4063430 | Crankshaft Front Oil Seal Replacement | J0770 | GMNA |
| 4063430 | Crankshaft Front Oil Seal Replacement | J1010 | GMNA |
| 4063430 | Crankshaft Front Oil Seal Replacement | 1141700 | GMK Domestic |
| 4063430 | Crankshaft Front Oil Seal Replacement | J074300 | Holden Australia |
| 4063430 | Crankshaft Front Oil Seal Replacement | J074600 | Holden Australia |
| 4063430 | Crankshaft Front Oil Seal Replacement | J074700 | Holden Australia |
| 4063430 | Crankshaft Front Oil Seal Replacement | J074800 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4063430 | Crankshaft Front Oil Seal Replacement | J074900 | Holden Australia |
| 4063430 | Crankshaft Front Oil Seal Replacement | J0750 | Holden Australia |
| 4063430 | Crankshaft Front Oil Seal Replacement | J075300 | Holden Australia |
| 4063430 | Crankshaft Front Oil Seal Replacement | J075600 | Holden Australia |
| 4063430 | Crankshaft Front Oil Seal Replacement | J075650 | Holden Australia |
| 4063430 | Crankshaft Front Oil Seal Replacement | J312600 | Holden Australia |
| 4063430 | Crankshaft Front Oil Seal Replacement | J0750 | Holden New Zealand |
| 4063430 | Crankshaft Front Oil Seal Replacement | J0751 | Holden New Zealand |
| 4063430 | Crankshaft Front Oil Seal Replacement | J0752 | Holden New Zealand |
| 4063430 | Crankshaft Front Oil Seal Replacement | J075300 | Holden New Zealand |
| 4063430 | Crankshaft Front Oil Seal Replacement | J075400 | Holden New Zealand |
| 4063430 | Crankshaft Front Oil Seal Replacement | J075500 | Holden New Zealand |
| 4063430 | Crankshaft Front Oil Seal Replacement | 1232300 | GMK Overseas |
| 4063470 | Timing Chain Upper Guide Replacement | L2161 | GMNA |
| 4063470 | Timing Chain Upper Guide Replacement | J462605 | Holden Australia |
| 4063490 | Timing Chain Lower Guide Replacement | | |
| 4063510 | Timing Chain Oil Nozzle Replacement | | |
| 4063530 | Adjustable Timing Chain Guide Replacement | J0767 | GMNA |
| 4063550 | Primary Timing Chain Replacement | J0768 | GMNA |
| 4063550 | Primary Timing Chain Replacement | J0817 | GMNA |
| 4063550 | Primary Timing Chain Replacement | 1223400 | GMK Domestic |
| 4063550 | Primary Timing Chain Replacement | J079050 | Holden Australia |
| 4063550 | Primary Timing Chain Replacement | J213510 | Holden Australia |
| 4063550 | Primary Timing Chain Replacement | J213550 | Holden Australia |
| 4063550 | Primary Timing Chain Replacement | J213800 | Holden Australia |
| 4063550 | Primary Timing Chain Replacement | J213510 | Holden New Zealand |
| 4063550 | Primary Timing Chain Replacement | J213550 | Holden New Zealand |
| 4063550 | Primary Timing Chain Replacement | J213800 | Holden New Zealand |
| 4063550 | Primary Timing Chain Replacement | 1334600 | GMK Overseas |
| 4063550 | Primary Timing Chain Replacement | 1335300 | GMK Overseas |
| 4063570 | Primary Camshaft Intermediate Drive Chain Replacement | J0769 | GMNA |
| 4063610 | Engine Front Cover Replacement | J0771 | GMNA |
| 4063610 | Engine Front Cover Replacement | J313550 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4063610 | Engine Front Cover Replacement | J463040 | Holden Australia |
| 4063630 | Engine Front Cover with Oil Pump Replacement | J0772 | GMNA |
| 4063630 | Engine Front Cover with Oil Pump Replacement | 1332200 | GMK Overseas |
| 4063650 | Secondary Timing Chain Guide Replacement - Left Side | J0773 | GMNA |
| 4063690 | Secondary Timing Chain Guide Replacement - Right Side | J0775 | GMNA |
| 4063710 | Secondary Camshaft Intermediate Drive Chain Replacement - Right Side | J0776 | GMNA |
| 4063730 | Secondary Camshaft Intermediate Drive Chain Replacement - Left Side | J0777 | GMNA |
| 4063750 | Secondary Camshaft Intermediate Drive Chain Tensioner Replacement - Right Side | J0778 | GMNA |
| 4063770 | Secondary Camshaft Intermediate Drive Chain Tensioner Replacement - Left Side | J0779 | GMNA |
| 4063810 | Primary Timing Chain Guide Replacement - Lower | J0774 | GMNA |
| 4063810 | Primary Timing Chain Guide Replacement - Lower | J0781 | GMNA |
| 4063830 | Secondary Timing Chain Tensioner Shoe Replacement - Right Side | J0782 | GMNA |
| 4063830 | Secondary Timing Chain Tensioner Shoe Replacement - Right Side | 1230000 | GMK Domestic |
| 4063850 | Secondary Timing Chain Tensioner Shoe Replacement - Left Side | J0783 | GMNA |
| 4063850 | Secondary Timing Chain Tensioner Shoe Replacement - Left Side | 1230100 | GMK Domestic |
| 4063870 | Timing Chain Guide Replacement | J0784 | GMNA |
| 4063870 | Timing Chain Guide Replacement | J0785 | GMNA |
| 4063870 | Timing Chain Guide Replacement | 1225200 | GMK Domestic |
| 4063870 | Timing Chain Guide Replacement | J0785 | Holden Australia |
| 4063910 | Primary Timing Chain Guide Replacement - Upper | J0786 | GMNA |
| 4063990 | Timing Chain Tensioner Replacement | J0791 | GMNA |
| 4063990 | Timing Chain Tensioner Replacement | J0811 | GMNA |
| 4063990 | Timing Chain Tensioner Replacement | J0813 | GMNA |
| 4063990 | Timing Chain Tensioner Replacement | J1944 | GMNA |
| 4063990 | Timing Chain Tensioner Replacement | J112700 | Holden Australia |
| 4063990 | Timing Chain Tensioner Replacement | J314000 | Holden Australia |
| 4063990 | Timing Chain Tensioner Replacement | J314010 | Holden Australia |
| 4063990 | Timing Chain Tensioner Replacement | J314100 | Holden Australia |
| 4063990 | Timing Chain Tensioner Replacement | J112700 | Holden New Zealand |
| 4063990 | Timing Chain Tensioner Replacement | J314000 | Holden New Zealand |
| 4063990 | Timing Chain Tensioner Replacement | J314010 | Holden New Zealand |
| 4063990 | Timing Chain Tensioner Replacement | J314100 | Holden New Zealand |
| 4063990 | Timing Chain Tensioner Replacement | 1335400 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4063990 | Timing Chain Tensioner Replacement | 1335500 | GMK Overseas |
| 4063990 | Timing Chain Tensioner Replacement | 133700 | GMK Overseas |
| 4064010 | Timing Chain Tensioner Shoe Replacement | J0792 | GMNA |
| 4064010 | Timing Chain Tensioner Shoe Replacement | J0812 | GMNA |
| 4064070 | Timing Belt Replacement | J0800 | GMNA |
| 4064070 | Timing Belt Replacement | J7517 | GMNA |
| 4064070 | Timing Belt Replacement | 1160605 | GMK Domestic |
| 4064070 | Timing Belt Replacement | 1222100 | GMK Domestic |
| 4064070 | Timing Belt Replacement | 1223000 | GMK Domestic |
| 4064070 | Timing Belt Replacement | J000827 | Holden Australia |
| 4064070 | Timing Belt Replacement | J313510 | Holden Australia |
| 4064070 | Timing Belt Replacement | 1332500 | GMK Overseas |
| 4064070 | Timing Belt Replacement | 133250A | GMK Overseas |
| 4064070 | Timing Belt Replacement | 133250C | GMK Overseas |
| 4064070 | Timing Belt Replacement | 133250E | GMK Overseas |
| 4064072 | Timing Belt Adjustment | J0802 | GMNA |
| 4064072 | Timing Belt Adjustment | 1120400 | GMK Domestic |
| 4064072 | Timing Belt Adjustment | 1231400 | GMK Domestic |
| 4064072 | Timing Belt Adjustment | 1231500 | GMK Domestic |
| 4064072 | Timing Belt Adjustment | 1332700 | GMK Overseas |
| 4064110 | Timing Belt Cover Replacement | J0790 | GMNA |
| 4064110 | Timing Belt Cover Replacement | J0793 | GMNA |
| 4064110 | Timing Belt Cover Replacement | J0795 | GMNA |
| 4064110 | Timing Belt Cover Replacement | J0799 | GMNA |
| 4064110 | Timing Belt Cover Replacement | J0808 | GMNA |
| 4064110 | Timing Belt Cover Replacement | J313450 | Holden Australia |
| 4064120 | Camshaft Timing Pulley Replacement | 1333900 | GMK Overseas |
| 4064150 | Timing Belt Tensioner Replacement | J0815 | GMNA |
| 4064150 | Timing Belt Tensioner Replacement | J000660 | Holden Australia |
| 4064150 | Timing Belt Tensioner Replacement | J081900 | Holden Australia |
| 4064150 | Timing Belt Tensioner Replacement | J082000 | Holden Australia |
| 4064150 | Timing Belt Tensioner Replacement | J082100 | Holden Australia |
| 4064150 | Timing Belt Tensioner Replacement | J082800 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4064150 | Timing Belt Tensioner Replacement | J313900 | Holden Australia |
| 4064150 | Timing Belt Tensioner Replacement | 1332900 | GMK Overseas |
| 4064150 | Timing Belt Tensioner Replacement | 133290A | GMK Overseas |
| 4064150 | Timing Belt Tensioner Replacement | 133290B | GMK Overseas |
| 4064150 | Timing Belt Tensioner Replacement | 1334500 | GMK Overseas |
| 4064170 | Timing Belt Idler Pulley Replacement | J0816 | GMNA |
| 4064190 | Camshaft Position Actuator Adjuster Replacement | J0818 | GMNA |
| 4064230 | Camshaft Timing Chain Replacement | J0659 | GMNA |
| 4064230 | Camshaft Timing Chain Replacement | J0820 | GMNA |
| 4064230 | Camshaft Timing Chain Replacement | J080000 | Holden Australia |
| 4064230 | Camshaft Timing Chain Replacement | J080500 | Holden Australia |
| 4064230 | Camshaft Timing Chain Replacement | J080700 | Holden Australia |
| 4064230 | Camshaft Timing Chain Replacement | J080800 | Holden Australia |
| 4064230 | Camshaft Timing Chain Replacement | J080850 | Holden Australia |
| 4064230 | Camshaft Timing Chain Replacement | J080900 | Holden Australia |
| 4064230 | Camshaft Timing Chain Replacement | J080950 | Holden Australia |
| 4064230 | Camshaft Timing Chain Replacement | J313900 | Holden New Zealand |
| 4064250 | Camshaft Position Actuator Solenoid Valve Replacement | J0821 | GMNA |
| 4064250 | Camshaft Position Actuator Solenoid Valve Replacement | J0822 | GMNA |
| 4064290 | Camshaft Position Actuator Replacement | J0824 | GMNA |
| 4064290 | Camshaft Position Actuator Replacement | 1213200 | GMK Domestic |
| 4064290 | Camshaft Position Actuator Replacement | 1336400 | GMK Overseas |
| 4064290 | Camshaft Position Actuator Replacement | 1336500 | GMK Overseas |
| 4064310 | Secondary Timing Chain Replacement - Right Side | J0825 | GMNA |
| 4064310 | Secondary Timing Chain Replacement - Right Side | J213600 | Holden Australia |
| 4064310 | Secondary Timing Chain Replacement - Right Side | J213600 | Holden New Zealand |
| 4064310 | Secondary Timing Chain Replacement - Right Side | 1335100 | GMK Overseas |
| 4064330 | Secondary Timing Chain Replacement - Left Side | J0826 | GMNA |
| 4064330 | Secondary Timing Chain Replacement - Left Side | 1160902 | GMK Domestic |
| 4064330 | Secondary Timing Chain Replacement - Left Side | 1225100 | GMK Domestic |
| 4064330 | Secondary Timing Chain Replacement - Left Side | J213700 | Holden Australia |
| 4064330 | Secondary Timing Chain Replacement - Left Side | J314060 | Holden Australia |
| 4064330 | Secondary Timing Chain Replacement - Left Side | J213700 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4064330 | Secondary Timing Chain Replacement - Left Side | J314060 | Holden New Zealand |
| 4064330 | Secondary Timing Chain Replacement - Left Side | 1335200 | GMK Overseas |
| 4064350 | Primary Camshaft Intermediate Drive Chain Tensioner Replacement | J0828 | GMNA |
| 4064370 | Timing Chain Dampener Replacement | | |
| 4064390 | Crankshaft Sprocket Replacement | J0830 | GMNA |
| 4064390 | Crankshaft Sprocket Replacement | 1221500 | GMK Domestic |
| 4064390 | Crankshaft Sprocket Replacement | 1221600 | GMK Domestic |
| 4064390 | Crankshaft Sprocket Replacement | J083300 | Holden Australia |
| 4064390 | Crankshaft Sprocket Replacement | J083700 | Holden Australia |
| 4064390 | Crankshaft Sprocket Replacement | J083800 | Holden Australia |
| 4064390 | Crankshaft Sprocket Replacement | J114100 | Holden Australia |
| 4064390 | Crankshaft Sprocket Replacement | J314110 | Holden Australia |
| 4064390 | Crankshaft Sprocket Replacement | J0836 | Holden New Zealand |
| 4064390 | Crankshaft Sprocket Replacement | J114100 | Holden New Zealand |
| 4064390 | Crankshaft Sprocket Replacement | J1450 | Holden New Zealand |
| 4064390 | Crankshaft Sprocket Replacement | J314110 | Holden New Zealand |
| 4064390 | Crankshaft Sprocket Replacement | 1333100 | GMK Overseas |
| 4064410 | Camshaft Replacement - Left Side | J0831 | GMNA |
| 4064430 | Camshaft Replacement - Right Side | J0832 | GMNA |
| 4064430 | Camshaft Replacement - Right Side | J085800 | Holden Australia |
| 4064450 | Camshaft Intake Sprocket Replacement | J0835 | GMNA |
| 4064470 | Camshaft Exhaust Sprocket Replacement | J0836 | GMNA |
| 4064470 | Camshaft Exhaust Sprocket Replacement | J0837 | GMNA |
| 4064470 | Camshaft Exhaust Sprocket Replacement | J0838 | GMNA |
| 4064530 | Camshaft Timing Chain and Sprocket Replacement | J0839 | GMNA |
| 4064530 | Camshaft Timing Chain and Sprocket Replacement | 1160700 | GMK Domestic |
| 4064530 | Camshaft Timing Chain and Sprocket Replacement | J0839 | Holden Australia |
| 4064550 | Camshaft Drive Sprocket Replacement | J0840 | GMNA |
| 4064550 | Camshaft Drive Sprocket Replacement | 1223300 | GMK Domestic |
| 4064550 | Camshaft Drive Sprocket Replacement | J0840 | Holden Australia |
| 4064550 | Camshaft Drive Sprocket Replacement | J314300 | Holden Australia |
| 4064550 | Camshaft Drive Sprocket Replacement | J314350 | Holden Australia |
| 4064550 | Camshaft Drive Sprocket Replacement | J314400 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4064550 | Camshaft Drive Sprocket Replacement | J314450 | Holden Australia |
| 4064550 | Camshaft Drive Sprocket Replacement | J314560 | Holden Australia |
| 4064550 | Camshaft Drive Sprocket Replacement | J314350 | Holden New Zealand |
| 4064550 | Camshaft Drive Sprocket Replacement | J314400 | Holden New Zealand |
| 4064550 | Camshaft Drive Sprocket Replacement | J314450 | Holden New Zealand |
| 4064550 | Camshaft Drive Sprocket Replacement | J314560 | Holden New Zealand |
| 4064550 | Camshaft Drive Sprocket Replacement | 1335900 | GMK Overseas |
| 4064550 | Camshaft Drive Sprocket Replacement | 1336100 | GMK Overseas |
| 4064570 | Camshaft Gear Replacement | J0841 | GMNA |
| 4064570 | Camshaft Gear Replacement | J5962 | GMNA |
| 4064570 | Camshaft Gear Replacement | 1221900 | GMK Domestic |
| 4064570 | Camshaft Gear Replacement | 1222000 | GMK Domestic |
| 4064570 | Camshaft Gear Replacement | 1222020 | GMK Domestic |
| 4064570 | Camshaft Gear Replacement | J082300 | Holden Australia |
| 4064570 | Camshaft Gear Replacement | J084000 | Holden Australia |
| 4064570 | Camshaft Gear Replacement | J084300 | Holden Australia |
| 4064570 | Camshaft Gear Replacement | J084800 | Holden Australia |
| 4064570 | Camshaft Gear Replacement | J214150 | Holden Australia |
| 4064570 | Camshaft Gear Replacement | J214160 | Holden Australia |
| 4064570 | Camshaft Gear Replacement | J596200 | Holden Australia |
| 4064570 | Camshaft Gear Replacement | J0842 | Holden New Zealand |
| 4064570 | Camshaft Gear Replacement | J084300 | Holden New Zealand |
| 4064570 | Camshaft Gear Replacement | J5962 | Holden New Zealand |
| 4064570 | Camshaft Gear Replacement | J596200 | Holden New Zealand |
| 4064570 | Camshaft Gear Replacement | 1333300 | GMK Overseas |
| 4064570 | Camshaft Gear Replacement | 133330A | GMK Overseas |
| 4064570 | Camshaft Gear Replacement | 1336200 | GMK Overseas |
| 4064570 | Camshaft Gear Replacement | 1336300 | GMK Overseas |
| 4064610 | Timing Chain Idler Sprocket Replacement - Left Side | J0844 | GMNA |
| 4064630 | Timing Chain Idler Sprocket Replacement - Right Side | J0845 | GMNA |
| 4064650 | Camshaft Bearing Replacement | J0846 | GMNA |
| 4064650 | Camshaft Bearing Replacement | 1150200 | GMK Domestic |
| 4064690 | Camshaft Replacement | J0850 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4064690 | Camshaft Replacement | J0860 | GMNA |
| 4064690 | Camshaft Replacement | J7528 | GMNA |
| 4064690 | Camshaft Replacement | J7529 | GMNA |
| 4064690 | Camshaft Replacement | J7530 | GMNA |
| 4064690 | Camshaft Replacement | J7534 | GMNA |
| 4064690 | Camshaft Replacement | J7535 | GMNA |
| 4064690 | Camshaft Replacement | J7536 | GMNA |
| 4064690 | Camshaft Replacement | 1162300 | GMK Domestic |
| 4064690 | Camshaft Replacement | 1162400 | GMK Domestic |
| 4064690 | Camshaft Replacement | 1162600 | GMK Domestic |
| 4064690 | Camshaft Replacement | 1162700 | GMK Domestic |
| 4064690 | Camshaft Replacement | J085000 | Holden Australia |
| 4064690 | Camshaft Replacement | J085100 | Holden Australia |
| 4064690 | Camshaft Replacement | J085300 | Holden Australia |
| 4064690 | Camshaft Replacement | J085700 | Holden Australia |
| 4064690 | Camshaft Replacement | J085900 | Holden Australia |
| 4064690 | Camshaft Replacement | J086000 | Holden Australia |
| 4064690 | Camshaft Replacement | J086100 | Holden Australia |
| 4064690 | Camshaft Replacement | J086150 | Holden Australia |
| 4064690 | Camshaft Replacement | J088000 | Holden Australia |
| 4064690 | Camshaft Replacement | J088100 | Holden Australia |
| 4064690 | Camshaft Replacement | J314500 | Holden Australia |
| 4064690 | Camshaft Replacement | J351000 | Holden Australia |
| 4064690 | Camshaft Replacement | J462000 | Holden Australia |
| 4064690 | Camshaft Replacement | J0850 | Holden New Zealand |
| 4064690 | Camshaft Replacement | J0852 | Holden New Zealand |
| 4064690 | Camshaft Replacement | J0853 | Holden New Zealand |
| 4064690 | Camshaft Replacement | J0853B | Holden New Zealand |
| 4064690 | Camshaft Replacement | J314500 | Holden New Zealand |
| 4064690 | Camshaft Replacement | J314580 | Holden New Zealand |
| 4064690 | Camshaft Replacement | J351000 | Holden New Zealand |
| 4064690 | Camshaft Replacement | J462000 | Holden New Zealand |
| 4064690 | Camshaft Replacement | 1322300 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4064690 | Camshaft Replacement | 132230A | GMK Overseas |
| 4064690 | Camshaft Replacement | 132230F | GMK Overseas |
| 4064710 | Camshaft Front Oil Seal Replacement | J0851 | GMNA |
| 4064710 | Camshaft Front Oil Seal Replacement | 1323000 | GMK Overseas |
| 4064730 | Camshaft Seal Replacement | J0852 | GMNA |
| 4064730 | Camshaft Seal Replacement | J0853 | GMNA |
| 4064730 | Camshaft Seal Replacement | J0854 | GMNA |
| 4064730 | Camshaft Seal Replacement | J0883 | GMNA |
| 4064730 | Camshaft Seal Replacement | J0884 | GMNA |
| 4064730 | Camshaft Seal Replacement | J7549 | GMNA |
| 4064730 | Camshaft Seal Replacement | J086200 | Holden Australia |
| 4064730 | Camshaft Seal Replacement | J304500 | Holden Australia |
| 4064730 | Camshaft Seal Replacement | J314600 | Holden Australia |
| 4064730 | Camshaft Seal Replacement | J314620 | Holden Australia |
| 4064730 | Camshaft Seal Replacement | J314630 | Holden Australia |
| 4064730 | Camshaft Seal Replacement | J315000 | Holden Australia |
| 4064730 | Camshaft Seal Replacement | J0854 | Holden New Zealand |
| 4064730 | Camshaft Seal Replacement | J304500 | Holden New Zealand |
| 4064730 | Camshaft Seal Replacement | J314600 | Holden New Zealand |
| 4064730 | Camshaft Seal Replacement | J314620 | Holden New Zealand |
| 4064730 | Camshaft Seal Replacement | J314630 | Holden New Zealand |
| 4064730 | Camshaft Seal Replacement | J315000 | Holden New Zealand |
| 4064730 | Camshaft Seal Replacement | 1322900 | GMK Overseas |
| 4064730 | Camshaft Seal Replacement | 132290A | GMK Overseas |
| 4064770 | Intake Camshaft Replacement | J0855 | GMNA |
| 4064770 | Intake Camshaft Replacement | J0855 | Holden Australia |
| 4064770 | Intake Camshaft Replacement | J314590 | Holden Australia |
| 4064770 | Intake Camshaft Replacement | J314610 | Holden Australia |
| 4064770 | Intake Camshaft Replacement | J314590 | Holden New Zealand |
| 4064770 | Intake Camshaft Replacement | 1322400 | GMK Overseas |
| 4064770 | Intake Camshaft Replacement | 132240C | GMK Overseas |
| 4064790 | Exhaust Camshaft Replacement | J0856 | GMNA |
| 4064790 | Exhaust Camshaft Replacement | J314570 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4064790 | Exhaust Camshaft Replacement | J314580 | Holden Australia |
| 4064790 | Exhaust Camshaft Replacement | 1322600 | GMK Overseas |
| 4064870 | Camshaft Position Actuator Magnet Replacement | J0861 | GMNA |
| 4064870 | Camshaft Position Actuator Magnet Replacement | J7902 | GMNA |
| 4064890 | Intake Camshaft Replacement - Right Side | J0862 | GMNA |
| 4064910 | Exhaust Camshaft Replacement - Right Side | J0863 | GMNA |
| 4064930 | Intake Camshaft Replacement - Left Side | J0864 | GMNA |
| 4064950 | Exhaust Camshaft Replacement - Left Side | J0865 | GMNA |
| 4065070 | Camshaft Position Intake Actuator Replacement | J0891 | GMNA |
| 4065070 | Camshaft Position Intake Actuator Replacement | 1336800 | GMK Overseas |
| 4065090 | Camshaft Position Exhaust Actuator Replacement | J0892 | GMNA |
| 4065090 | Camshaft Position Exhaust Actuator Replacement | 1336900 | GMK Overseas |
| 4065110 | Camshaft Position Actuator Replacement - Bank 2 (Left Side) Exhaust | J0893 | GMNA |
| 4065130 | Camshaft Position Actuator Replacement - Bank 1 (Right Side) Exhaust | J0894 | GMNA |
| 4065150 | Camshaft Position Actuator Replacement - Bank 2 (Left Side) Intake | J0895 | GMNA |
| 4065170 | Camshaft Position Actuator Replacement - Bank 1 (Right Side) Intake | J0896 | GMNA |
| 4065190 | Camshaft Position Actuator Replacement - Bank 2 | J0897 | GMNA |
| 4065210 | Camshaft Position Actuator Replacement - Bank 1 | J0898 | GMNA |
| 4065230 | Oil Filler Cap Replacement | J0900 | GMNA |
| 4065230 | Oil Filler Cap Replacement | J090000 | Holden Australia |
| 4065230 | Oil Filler Cap Replacement | J318500 | Holden Australia |
| 4065230 | Oil Filler Cap Replacement | J0900 | Holden New Zealand |
| 4065230 | Oil Filler Cap Replacement | J090000 | Holden New Zealand |
| 4065230 | Oil Filler Cap Replacement | J318500 | Holden New Zealand |
| 4065230 | Oil Filler Cap Replacement | 1233800 | GMK Overseas |
| 4065230 | Oil Filler Cap Replacement | 1322700 | GMK Overseas |
| 4065250 | Camshaft Intake Sprocket with Actuator Replacement | J0903 | GMNA |
| 4065270 | Camshaft Exhaust Sprocket with Actuator Replacement | J0904 | GMNA |
| 4065290 | Camshaft Position Sensor Exciter Ring Replacement | J0905 | GMNA |
| 4065290 | Camshaft Position Sensor Exciter Ring Replacement | J4347 | GMNA |
| 4065370 | Oil Level Indicator Replacement | J0920 | GMNA |
| 4065370 | Oil Level Indicator Replacement | 1421700 | GMK Domestic |
| 4065370 | Oil Level Indicator Replacement | J000550 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4065370 | Oil Level Indicator Replacement | J317500 | Holden Australia |
| 4065370 | Oil Level Indicator Replacement | J317500 | Holden New Zealand |
| 4065370 | Oil Level Indicator Replacement | 1210200 | GMK Overseas |
| 4065390 | Oil Level Indicator Tube Replacement | J0930 | GMNA |
| 4065390 | Oil Level Indicator Tube Replacement | J7505 | GMNA |
| 4065390 | Oil Level Indicator Tube Replacement | J000779 | Holden Australia |
| 4065390 | Oil Level Indicator Tube Replacement | J093000 | Holden Australia |
| 4065390 | Oil Level Indicator Tube Replacement | J217700 | Holden Australia |
| 4065390 | Oil Level Indicator Tube Replacement | J000779 | Holden New Zealand |
| 4065390 | Oil Level Indicator Tube Replacement | J0930 | Holden New Zealand |
| 4065390 | Oil Level Indicator Tube Replacement | J093000 | Holden New Zealand |
| 4065390 | Oil Level Indicator Tube Replacement | J0930A | Holden New Zealand |
| 4065390 | Oil Level Indicator Tube Replacement | J217700 | Holden New Zealand |
| 4065390 | Oil Level Indicator Tube Replacement | 1210300 | GMK Overseas |
| 4065410 | Oil Filler Tube Replacement | J0931 | GMNA |
| 4065410 | Oil Filler Tube Replacement | J0932 | GMNA |
| 4065450 | Engine Oil Cooler Replacement | J0933 | GMNA |
| 4065450 | Engine Oil Cooler Replacement | J3126 | GMNA |
| 4065450 | Engine Oil Cooler Replacement | J116300 | Holden Australia |
| 4065450 | Engine Oil Cooler Replacement | J116300 | Holden New Zealand |
| 4065470 | Engine Oil Cooler Hose Replacement | J0935 | GMNA |
| 4065470 | Engine Oil Cooler Hose Replacement | 2120400 | GMK Domestic |
| 4065490 | Engine Oil Heater Replacement | J0936 | GMNA |
| 4065530 | Oil Filter Replacement | J0945 | GMNA |
| 4065530 | Oil Filter Replacement | J0950 | GMNA |
| 4065530 | Oil Filter Replacement | 1421000 | GMK Domestic |
| 4065530 | Oil Filter Replacement | 1421500 | GMK Domestic |
| 4065530 | Oil Filter Replacement | J0950 | Holden Australia |
| 4065530 | Oil Filter Replacement | J095000 | Holden Australia |
| 4065530 | Oil Filter Replacement | J095100 | Holden Australia |
| 4065530 | Oil Filter Replacement | J095200 | Holden Australia |
| 4065530 | Oil Filter Replacement | J095300 | Holden Australia |
| 4065530 | Oil Filter Replacement | J095700 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4065530 | Oil Filter Replacement | J095800 | Holden Australia |
| 4065530 | Oil Filter Replacement | J095900 | Holden Australia |
| 4065530 | Oil Filter Replacement | J095950 | Holden Australia |
| 4065530 | Oil Filter Replacement | J096100 | Holden Australia |
| 4065530 | Oil Filter Replacement | J103000 | Holden Australia |
| 4065530 | Oil Filter Replacement | J103100 | Holden Australia |
| 4065530 | Oil Filter Replacement | J103300 | Holden Australia |
| 4065530 | Oil Filter Replacement | J103400 | Holden Australia |
| 4065530 | Oil Filter Replacement | J103600 | Holden Australia |
| 4065530 | Oil Filter Replacement | J316200 | Holden Australia |
| 4065530 | Oil Filter Replacement | J0945 | Holden New Zealand |
| 4065530 | Oil Filter Replacement | J0950 | Holden New Zealand |
| 4065530 | Oil Filter Replacement | J095000 | Holden New Zealand |
| 4065530 | Oil Filter Replacement | J095300 | Holden New Zealand |
| 4065530 | Oil Filter Replacement | J0955 | Holden New Zealand |
| 4065530 | Oil Filter Replacement | J095900 | Holden New Zealand |
| 4065530 | Oil Filter Replacement | J316200 | Holden New Zealand |
| 4065530 | Oil Filter Replacement | 1231100 | GMK Overseas |
| 4065540 | Oil Filter Housing Replacement | | |
| 4065550 | Oil Filter Assembly Replacement | J0958 | GMNA |
| 4065570 | Oil Filter Adapter Replacement | J0960 | GMNA |
| 4065570 | Oil Filter Adapter Replacement | J0965 | GMNA |
| 4065570 | Oil Filter Adapter Replacement | J0966 | GMNA |
| 4065570 | Oil Filter Adapter Replacement | 1421600 | GMK Domestic |
| 4065570 | Oil Filter Adapter Replacement | J096000 | Holden Australia |
| 4065570 | Oil Filter Adapter Replacement | J316100 | Holden Australia |
| 4065570 | Oil Filter Adapter Replacement | J316300 | Holden Australia |
| 4065570 | Oil Filter Adapter Replacement | J0960 | Holden New Zealand |
| 4065570 | Oil Filter Adapter Replacement | J096000 | Holden New Zealand |
| 4065570 | Oil Filter Adapter Replacement | J316100 | Holden New Zealand |
| 4065570 | Oil Filter Adapter Replacement | J316300 | Holden New Zealand |
| 4065570 | Oil Filter Adapter Replacement | 1231200 | GMK Overseas |
| 4065590 | Oil Filter Upper End Plate Replacement | J0961 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4065590 | Oil Filter Upper End Plate Replacement | 1421100 | GMK Domestic |
| 4065610 | Oil Filter Adapter and Oil Cooler Assembly Replacement | J0964 | GMNA |
| 4065610 | Oil Filter Adapter and Oil Cooler Assembly Replacement | J0967 | GMNA |
| 4065630 | Oil Filter Bypass Valve Replacement | J0970 | GMNA |
| 4065630 | Oil Filter Bypass Valve Replacement | 1301500 | GMK Domestic |
| 4065630 | Oil Filter Bypass Valve Replacement | J000633 | Holden Australia |
| 4065630 | Oil Filter Bypass Valve Replacement | J106000 | Holden Australia |
| 4065630 | Oil Filter Bypass Valve Replacement | J460430 | Holden Australia |
| 4065630 | Oil Filter Bypass Valve Replacement | J460430 | Holden New Zealand |
| 4065630 | Oil Filter Bypass Valve Replacement | 1210500 | GMK Overseas |
| 4065650 | Oil Pressure Relief Valve Replacement | J0971 | GMNA |
| 4065650 | Oil Pressure Relief Valve Replacement | J0982 | GMNA |
| 4065650 | Oil Pressure Relief Valve Replacement | 1232700 | GMK Overseas |
| 4065650 | Oil Pressure Relief Valve Replacement | 1233900 | GMK Overseas |
| 4065750 | Valve Lifter Oil Filter Replacement | J0981 | GMNA |
| 4065770 | Oil Tank Replacement | J0986 | GMNA |
| 4065790 | Oil Tank Outlet Hose Replacement | F600110 | Holden Australia |
| 4065790 | Oil Tank Outlet Hose Replacement | F600130 | Holden Australia |
| 4065790 | Oil Tank Outlet Hose Replacement | F600130 | Holden New Zealand |
| 4065810 | Oil Tank Inlet Hose Replacement | J0955 | GMNA |
| 4065810 | Oil Tank Inlet Hose Replacement | J0988 | GMNA |
| 4065810 | Oil Tank Inlet Hose Replacement | J317000 | Holden Australia |
| 4065810 | Oil Tank Inlet Hose Replacement | J586600 | Holden Australia |
| 4065810 | Oil Tank Inlet Hose Replacement | J317000 | Holden New Zealand |
| 4065810 | Oil Tank Inlet Hose Replacement | J586600 | Holden New Zealand |
| 4065830 | Oil Pan Drain Plug Replacement | F9703 | GMNA |
| 4065830 | Oil Pan Drain Plug Replacement | J0990 | GMNA |
| 4065830 | Oil Pan Drain Plug Replacement | 1432000 | GMK Domestic |
| 4065830 | Oil Pan Drain Plug Replacement | 1231300 | GMK Overseas |
| 4065850 | Oil Pan Cover Replacement | J0999 | GMNA |
| 4065850 | Oil Pan Cover Replacement | J3128 | GMNA |
| 4065850 | Oil Pan Cover Replacement | J315400 | Holden Australia |
| 4065850 | Oil Pan Cover Replacement | J315400 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4065870 | Oil Pan Replacement | J0998 | GMNA |
| 4065870 | Oil Pan Replacement | J1000 | GMNA |
| 4065870 | Oil Pan Replacement | J1003 | GMNA |
| 4065870 | Oil Pan Replacement | J1007 | GMNA |
| 4065870 | Oil Pan Replacement | 1325300 | GMK Domestic |
| 4065870 | Oil Pan Replacement | 1430120 | GMK Domestic |
| 4065870 | Oil Pan Replacement | 1431200 | GMK Domestic |
| 4065870 | Oil Pan Replacement | J099200 | Holden Australia |
| 4065870 | Oil Pan Replacement | J099400 | Holden Australia |
| 4065870 | Oil Pan Replacement | J099500 | Holden Australia |
| 4065870 | Oil Pan Replacement | J099600 | Holden Australia |
| 4065870 | Oil Pan Replacement | J099800 | Holden Australia |
| 4065870 | Oil Pan Replacement | J1000 | Holden Australia |
| 4065870 | Oil Pan Replacement | J100100 | Holden Australia |
| 4065870 | Oil Pan Replacement | J100300 | Holden Australia |
| 4065870 | Oil Pan Replacement | J100700 | Holden Australia |
| 4065870 | Oil Pan Replacement | J100800 | Holden Australia |
| 4065870 | Oil Pan Replacement | J100900 | Holden Australia |
| 4065870 | Oil Pan Replacement | J100950 | Holden Australia |
| 4065870 | Oil Pan Replacement | J101000 | Holden Australia |
| 4065870 | Oil Pan Replacement | J101050 | Holden Australia |
| 4065870 | Oil Pan Replacement | J115600 | Holden Australia |
| 4065870 | Oil Pan Replacement | J315500 | Holden Australia |
| 4065870 | Oil Pan Replacement | J315520 | Holden Australia |
| 4065870 | Oil Pan Replacement | J315530 | Holden Australia |
| 4065870 | Oil Pan Replacement | J315600 | Holden Australia |
| 4065870 | Oil Pan Replacement | J099200 | Holden New Zealand |
| 4065870 | Oil Pan Replacement | J100100 | Holden New Zealand |
| 4065870 | Oil Pan Replacement | J1003 | Holden New Zealand |
| 4065870 | Oil Pan Replacement | J100300 | Holden New Zealand |
| 4065870 | Oil Pan Replacement | J1004 | Holden New Zealand |
| 4065870 | Oil Pan Replacement | J315500 | Holden New Zealand |
| 4065870 | Oil Pan Replacement | J315520 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4065870 | Oil Pan Replacement | J315530 | Holden New Zealand |
| 4065870 | Oil Pan Replacement | J315600 | Holden New Zealand |
| 4065870 | Oil Pan Replacement | 1231500 | GMK Overseas |
| 4065890 | Upper Oil Pan Replacement | J1001 | GMNA |
| 4065890 | Upper Oil Pan Replacement | 1426500 | GMK Domestic |
| 4065890 | Upper Oil Pan Replacement | 1610300 | GMK Domestic |
| 4065890 | Upper Oil Pan Replacement | 1231510 | GMK Overseas |
| 4065910 | Lower Oil Pan Replacement | J1002 | GMNA |
| 4065910 | Lower Oil Pan Replacement | J100200 | Holden Australia |
| 4065910 | Lower Oil Pan Replacement | J1002 | Holden New Zealand |
| 4066050 | Oil Pump Drive Gear Replacement | J1018 | GMNA |
| 4066050 | Oil Pump Drive Gear Replacement | J1035 | GMNA |
| 4066050 | Oil Pump Drive Gear Replacement | J1040 | GMNA |
| 4066050 | Oil Pump Drive Gear Replacement | 1310600 | GMK Domestic |
| 4066050 | Oil Pump Drive Gear Replacement | 1423200 | GMK Domestic |
| 4066050 | Oil Pump Drive Gear Replacement | 1423300 | GMK Domestic |
| 4066050 | Oil Pump Drive Gear Replacement | J101300 | Holden Australia |
| 4066050 | Oil Pump Drive Gear Replacement | J101700 | Holden Australia |
| 4066050 | Oil Pump Drive Gear Replacement | J316600 | Holden Australia |
| 4066050 | Oil Pump Drive Gear Replacement | J602000 | Holden Australia |
| 4066050 | Oil Pump Drive Gear Replacement | J316600 | Holden New Zealand |
| 4066070 | Oil Pump Replacement | J1015 | GMNA |
| 4066070 | Oil Pump Replacement | J1016 | GMNA |
| 4066070 | Oil Pump Replacement | J1020 | GMNA |
| 4066070 | Oil Pump Replacement | J1021 | GMNA |
| 4066070 | Oil Pump Replacement | 1422200 | GMK Domestic |
| 4066070 | Oil Pump Replacement | 1422400 | GMK Domestic |
| 4066070 | Oil Pump Replacement | 1422500 | GMK Domestic |
| 4066070 | Oil Pump Replacement | J101600 | Holden Australia |
| 4066070 | Oil Pump Replacement | J1020 | Holden Australia |
| 4066070 | Oil Pump Replacement | J102000 | Holden Australia |
| 4066070 | Oil Pump Replacement | J102100 | Holden Australia |
| 4066070 | Oil Pump Replacement | J102200 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4066070 | Oil Pump Replacement | J102300 | Holden Australia |
| 4066070 | Oil Pump Replacement | J102700 | Holden Australia |
| 4066070 | Oil Pump Replacement | J102900 | Holden Australia |
| 4066070 | Oil Pump Replacement | J316500 | Holden Australia |
| 4066070 | Oil Pump Replacement | J600900 | Holden Australia |
| 4066070 | Oil Pump Replacement | J604000 | Holden Australia |
| 4066070 | Oil Pump Replacement | J1023 | Holden New Zealand |
| 4066070 | Oil Pump Replacement | J1025 | Holden New Zealand |
| 4066070 | Oil Pump Replacement | J316500 | Holden New Zealand |
| 4066070 | Oil Pump Replacement | 1231700 | GMK Overseas |
| 4066070 | Oil Pump Replacement | 123170B | GMK Overseas |
| 4066070 | Oil Pump Replacement | 1231800 | GMK Overseas |
| 4066090 | Oil Pump Housing Replacement | | |
| 4066110 | Oil Pump Cover Replacement | J1025 | GMNA |
| 4066110 | Oil Pump Cover Replacement | 1423500 | GMK Domestic |
| 4066150 | Oil Pump Drive Replacement | J1050 | GMNA |
| 4066150 | Oil Pump Drive Replacement | J1055 | GMNA |
| 4066150 | Oil Pump Drive Replacement | J1065 | GMNA |
| 4066150 | Oil Pump Drive Replacement | J213520 | Holden Australia |
| 4066170 | Oil Pump Seal Replacement | 1311200 | GMK Domestic |
| 4066170 | Oil Pump Seal Replacement | 1423900 | GMK Domestic |
| 4066170 | Oil Pump Seal Replacement | 1232900 | GMK Overseas |
| 4066210 | Oil Pump Suction Pipe and Screen Assembly Replacement | J1060 | GMNA |
| 4066210 | Oil Pump Suction Pipe and Screen Assembly Replacement | J1070 | GMNA |
| 4066210 | Oil Pump Suction Pipe and Screen Assembly Replacement | J117300 | Holden Australia |
| 4066210 | Oil Pump Suction Pipe and Screen Assembly Replacement | J117350 | Holden Australia |
| 4066210 | Oil Pump Suction Pipe and Screen Assembly Replacement | J117300 | Holden New Zealand |
| 4066210 | Oil Pump Suction Pipe and Screen Assembly Replacement | J117350 | Holden New Zealand |
| 4066210 | Oil Pump Suction Pipe and Screen Assembly Replacement | J117350A1 | Holden New Zealand |
| 4066210 | Oil Pump Suction Pipe and Screen Assembly Replacement | 1232100 | GMK Overseas |
| 4066230 | Piston Oil Nozzle Replacement | J1061 | GMNA |
| 4066230 | Piston Oil Nozzle Replacement | J7516 | GMNA |
| 4066230 | Piston Oil Nozzle Replacement | 1322200 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4066250 | Crankshaft Rear Oil Seal and Housing Replacement | J1080 | GMNA |
| 4066250 | Crankshaft Rear Oil Seal and Housing Replacement | J1080 | Holden Australia |
| 4066250 | Crankshaft Rear Oil Seal and Housing Replacement | J112900 | Holden Australia |
| 4066250 | Crankshaft Rear Oil Seal and Housing Replacement | J112950 | Holden Australia |
| 4066250 | Crankshaft Rear Oil Seal and Housing Replacement | J320720 | Holden Australia |
| 4066250 | Crankshaft Rear Oil Seal and Housing Replacement | J320720 | Holden New Zealand |
| 4066270 | Crankshaft Rear Oil Seal Housing Replacement | J1081 | GMNA |
| 4066270 | Crankshaft Rear Oil Seal Housing Replacement | 1222300 | GMK Overseas |
| 4066270 | Crankshaft Rear Oil Seal Housing Replacement | 1222500 | GMK Overseas |
| 4066290 | Balance Shaft Replacement - Right Side | J1082 | GMNA |
| 4066310 | Balance Shaft Replacement - Left Side | J1083 | GMNA |
| 4066330 | Balancer Shaft Replacement | J1085 | GMNA |
| 4066330 | Balancer Shaft Replacement | J1092 | GMNA |
| 4066330 | Balancer Shaft Replacement | J105000 | Holden Australia |
| 4066350 | Balancer Shaft Front Bearing and Rear Bearing Replacement | J1086 | GMNA |
| 4066350 | Balancer Shaft Front Bearing and Rear Bearing Replacement | NZE5523 | Holden New Zealand |
| 4066370 | Balance Chain Replacement | J1087 | GMNA |
| 4066370 | Balance Chain Replacement | J1091 | GMNA |
| 4066370 | Balance Chain Replacement | 1124600 | GMK Domestic |
| 4066370 | Balance Chain Replacement | 1153000 | GMK Domestic |
| 4066370 | Balance Chain Replacement | 1333510 | GMK Overseas |
| 4066390 | Balance Chain Tensioner Replacement | J1088 | GMNA |
| 4066400 | Balancer Shaft Driven Sprocket Replacement | | |
| 4066450 | Balancer Chain Guide Replacement | J1093 | GMNA |
| 4066470 | Balance Shaft Sprocket Replacement - Exhaust Side | | |
| 4066490 | Balance Shaft Sprocket Replacement - Intake Side | | |
| 4066510 | Water Pump and Balance Shaft Chain Replacement | J1096 | GMNA |
| 4066530 | Water Pump and Balance Shaft Chain Tensioner Replacement | | |
| 4066550 | Water Pump and Balance Shaft Chain Crankshaft Sprocket Replacement | J1098 | GMNA |
| 4066570 | Balancer Chain Guide Replacement - Lower | | |
| 4066590 | Balancer Chain Guide Replacement - Upper | | |
| 4066600 | Balancer Shaft Driven Gear Replacement | | |
| 4066610 | Balancer Chain Adjust Guide Replacement | J1099 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4066610 | Balancer Chain Adjust Guide Replacement | J1101 | GMNA |
| 4066620 | Balancer Shaft Drive Gear Replacement | | |
| 4066630 | Water Pump Cover Replacement | | |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J1105 | GMNA |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J1120 | GMNA |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J1123 | GMNA |
| 4066650 | Crankshaft Rear Oil Seal Replacement | 1150800 | GMK Domestic |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J1120 | Holden Australia |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J112000 | Holden Australia |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J112100 | Holden Australia |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J112200 | Holden Australia |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J112300 | Holden Australia |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J112800 | Holden Australia |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J320100 | Holden Australia |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J320250 | Holden Australia |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J320725 | Holden Australia |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J1120 | Holden New Zealand |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J112000 | Holden New Zealand |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J112000C | Holden New Zealand |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J112300 | Holden New Zealand |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J1125B | Holden New Zealand |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J320100 | Holden New Zealand |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J320250 | Holden New Zealand |
| 4066650 | Crankshaft Rear Oil Seal Replacement | J320725 | Holden New Zealand |
| 4066650 | Crankshaft Rear Oil Seal Replacement | 1220200 | GMK Overseas |
| 4066650 | Crankshaft Rear Oil Seal Replacement | 122020C | GMK Overseas |
| 4066650 | Crankshaft Rear Oil Seal Replacement | 1220400 | GMK Overseas |
| 4066690 | Connecting Rod Bearing Replacement | J1180 | GMNA |
| 4066690 | Connecting Rod Bearing Replacement | 1155700 | GMK Domestic |
| 4066690 | Connecting Rod Bearing Replacement | 1155800 | GMK Domestic |
| 4066690 | Connecting Rod Bearing Replacement | J118100 | Holden Australia |
| 4066690 | Connecting Rod Bearing Replacement | J118300 | Holden Australia |
| 4066690 | Connecting Rod Bearing Replacement | J118700 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4066690 | Connecting Rod Bearing Replacement | J320510 | Holden Australia |
| 4066690 | Connecting Rod Bearing Replacement | J118700 | Holden New Zealand |
| 4066690 | Connecting Rod Bearing Replacement | J320510 | Holden New Zealand |
| 4066710 | Lower Crankcase Seal/Sealant Replacement | J1011 | GMNA |
| 4066710 | Lower Crankcase Seal/Sealant Replacement | J1190 | GMNA |
| 4066710 | Lower Crankcase Seal/Sealant Replacement | 1222900 | GMK Overseas |
| 4066750 | Crankshaft Replacement | J1200 | GMNA |
| 4066750 | Crankshaft Replacement | 1120000 | GMK Domestic |
| 4066750 | Crankshaft Replacement | J120100 | Holden Australia |
| 4066750 | Crankshaft Replacement | J120200 | Holden Australia |
| 4066750 | Crankshaft Replacement | J120300 | Holden Australia |
| 4066750 | Crankshaft Replacement | J120700 | Holden Australia |
| 4066750 | Crankshaft Replacement | J120900 | Holden Australia |
| 4066750 | Crankshaft Replacement | J320000 | Holden Australia |
| 4066750 | Crankshaft Replacement | J1203 | Holden New Zealand |
| 4066750 | Crankshaft Replacement | J1204 | Holden New Zealand |
| 4066750 | Crankshaft Replacement | J1205 | Holden New Zealand |
| 4066750 | Crankshaft Replacement | J320000 | Holden New Zealand |
| 4066750 | Crankshaft Replacement | 1220600 | GMK Overseas |
| 4066750 | Crankshaft Replacement | 122060C | GMK Overseas |
| 4066750 | Crankshaft Replacement | 1221100 | GMK Overseas |
| 4066750 | Crankshaft Replacement | 122110A | GMK Overseas |
| 4066750 | Crankshaft Replacement | 122110C | GMK Overseas |
| 4066750 | Crankshaft Replacement | 122110E | GMK Overseas |
| 4066750 | Crankshaft Replacement | 122110J | GMK Overseas |
| 4066750 | Crankshaft Replacement | 122110L | GMK Overseas |
| 4066750 | Crankshaft Replacement | 1221200 | GMK Overseas |
| 4066750 | Crankshaft Replacement | 122120E | GMK Overseas |
| 4066770 | Piston Ring Replacement | J1297 | GMNA |
| 4066770 | Piston Ring Replacement | 1155000 | GMK Domestic |
| 4066770 | Piston Ring Replacement | J000580 | Holden Australia |
| 4066770 | Piston Ring Replacement | J000695 | Holden Australia |
| 4066770 | Piston Ring Replacement | J000695 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4066790 | Piston Ring Replacement - Right Side | J1298 | GMNA |
| 4066810 | Piston Ring Replacement - Left Side | J1299 | GMNA |
| 4066830 | Piston, Connecting Rod, and Bearing Replacement - Right Side | J1300 | GMNA |
| 4066830 | Piston, Connecting Rod, and Bearing Replacement - Right Side | 1155600 | GMK Domestic |
| 4066830 | Piston, Connecting Rod, and Bearing Replacement - Right Side | J1300 | Holden New Zealand |
| 4066830 | Piston, Connecting Rod, and Bearing Replacement - Right Side | J1301 | Holden New Zealand |
| 4066830 | Piston, Connecting Rod, and Bearing Replacement - Right Side | J13033 | Holden New Zealand |
| 4066830 | Piston, Connecting Rod, and Bearing Replacement - Right Side | J13034 | Holden New Zealand |
| 4066830 | Piston, Connecting Rod, and Bearing Replacement - Right Side | J13035 | Holden New Zealand |
| 4066830 | Piston, Connecting Rod, and Bearing Replacement - Right Side | J13037 | Holden New Zealand |
| 4066830 | Piston, Connecting Rod, and Bearing Replacement - Right Side | J1303A | Holden New Zealand |
| 4066830 | Piston, Connecting Rod, and Bearing Replacement - Right Side | J1308 | Holden New Zealand |
| 4066830 | Piston, Connecting Rod, and Bearing Replacement - Right Side | 1221600 | GMK Overseas |
| 4066850 | Piston, Connecting Rod, and Bearing Replacement - Left Side | J1301 | GMNA |
| 4066850 | Piston, Connecting Rod, and Bearing Replacement - Left Side | 1221610 | GMK Overseas |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J1302 | GMNA |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J1303 | GMNA |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J1307 | GMNA |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J1308 | GMNA |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J1309 | GMNA |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | 1155500 | GMK Domestic |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J130300 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J130700 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J1308 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J130800 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J130900 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J130950 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J131050 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J230000 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J230020 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J230050 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J307020 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J307120 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J307220 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J330000 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J330020 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J330050 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J330100 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J330120 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J330150 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J330200 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J330220 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J330250 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J338150 | Holden Australia |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J1302 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J1303 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J1305 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J130800 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J130900 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J1310 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J230000 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J230020 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J230050 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J307020 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J307120 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J330000 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J330020 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J330050 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J330100 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J330120 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J330200 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J330220 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | J338150 | Holden New Zealand |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | 1220800 | GMK Overseas |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | 122080B | GMK Overseas |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | 1221500 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | 122150A | GMK Overseas |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | 122150C | GMK Overseas |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | 122150D | GMK Overseas |
| 4066890 | Piston, Connecting Rod, and Bearing Replacement | 1221800 | GMK Overseas |
| 4066910 | Cylinder Sleeve Replacement | J1335 | GMNA |
| 4066950 | Automatic Transmission Flex Plate Replacement | J1400 | GMNA |
| 4066950 | Automatic Transmission Flex Plate Replacement | 1152200 | GMK Domestic |
| 4066950 | Automatic Transmission Flex Plate Replacement | J140100 | Holden Australia |
| 4066950 | Automatic Transmission Flex Plate Replacement | J1401 | Holden New Zealand |
| 4066950 | Automatic Transmission Flex Plate Replacement | 1221900 | GMK Overseas |
| 4066950 | Automatic Transmission Flex Plate Replacement | 1222700 | GMK Overseas |
| 4066970 | Engine Flywheel Replacement | J1420 | GMNA |
| 4066970 | Engine Flywheel Replacement | T5594 | GMNA |
| 4066970 | Engine Flywheel Replacement | 1152100 | GMK Domestic |
| 4066970 | Engine Flywheel Replacement | J000773 | Holden Australia |
| 4066970 | Engine Flywheel Replacement | J1420 | Holden Australia |
| 4066970 | Engine Flywheel Replacement | J142100 | Holden Australia |
| 4066970 | Engine Flywheel Replacement | J142200 | Holden Australia |
| 4066970 | Engine Flywheel Replacement | J142300 | Holden Australia |
| 4066970 | Engine Flywheel Replacement | J142700 | Holden Australia |
| 4066970 | Engine Flywheel Replacement | J142800 | Holden Australia |
| 4066970 | Engine Flywheel Replacement | J335500 | Holden Australia |
| 4066970 | Engine Flywheel Replacement | J000773 | Holden New Zealand |
| 4066970 | Engine Flywheel Replacement | J1420 | Holden New Zealand |
| 4066970 | Engine Flywheel Replacement | J1425 | Holden New Zealand |
| 4066970 | Engine Flywheel Replacement | J142700 | Holden New Zealand |
| 4066970 | Engine Flywheel Replacement | J1430 | Holden New Zealand |
| 4066970 | Engine Flywheel Replacement | J335500 | Holden New Zealand |
| 4066970 | Engine Flywheel Replacement | 1221700 | GMK Overseas |
| 4066970 | Engine Flywheel Replacement | 122170C | GMK Overseas |
| 4067010 | Flywheel Housing Replacement | J1460 | GMNA |
| 4067010 | Flywheel Housing Replacement | J7510 | GMNA |
| 4067010 | Flywheel Housing Replacement | J1464 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4067050 | Engine Front Mount Replacement - Left Side | J1501 | GMNA |
| 4067070 | Engine Front Mount Replacement | J1502 | GMNA |
| 4067070 | Engine Front Mount Replacement | 1112100 | GMK Domestic |
| 4067070 | Engine Front Mount Replacement | 1112300 | GMK Domestic |
| 4067070 | Engine Front Mount Replacement | 1140300 | GMK Domestic |
| 4067070 | Engine Front Mount Replacement | 1380800 | GMK Overseas |
| 4067080 | Engine Mount Replacement - Left Side | J1496 | GMNA |
| 4067080 | Engine Mount Replacement - Left Side | J1509 | GMNA |
| 4067080 | Engine Mount Replacement - Left Side | J337200 | Holden Australia |
| 4067080 | Engine Mount Replacement - Left Side | J337200 | Holden New Zealand |
| 4067080 | Engine Mount Replacement - Left Side | 1380500 | GMK Overseas |
| 4067090 | Engine Mount Replacement | J1505 | GMNA |
| 4067090 | Engine Mount Replacement | J000704 | Holden Australia |
| 4067090 | Engine Mount Replacement | J237000 | Holden Australia |
| 4067090 | Engine Mount Replacement | J000704 | Holden New Zealand |
| 4067090 | Engine Mount Replacement | J1501 | Holden New Zealand |
| 4067090 | Engine Mount Replacement | J1510 | Holden New Zealand |
| 4067090 | Engine Mount Replacement | J338100 | Holden New Zealand |
| 4067090 | Engine Mount Replacement | 1380300 | GMK Overseas |
| 4067150 | Engine Mount Replacement - Right Side | J1508 | GMNA |
| 4067150 | Engine Mount Replacement - Right Side | 1112200 | GMK Domestic |
| 4067150 | Engine Mount Replacement - Right Side | 1140400 | GMK Domestic |
| 4067150 | Engine Mount Replacement - Right Side | J337100 | Holden Australia |
| 4067150 | Engine Mount Replacement - Right Side | J337100 | Holden New Zealand |
| 4067150 | Engine Mount Replacement - Right Side | 1380100 | GMK Overseas |
| 4067150 | Engine Mount Replacement - Right Side | 1383700 | GMK Overseas |
| 4067150 | Engine Mount Replacement - Right Side | 1383900 | GMK Overseas |
| 4067150 | Engine Mount Replacement - Right Side | 1384100 | GMK Overseas |
| 4067150 | Engine Mount Replacement - Right Side | 1384200 | GMK Overseas |
| 4067150 | Engine Mount Replacement - Right Side | 1384300 | GMK Overseas |
| 4067210 | Engine Rear Mount Replacement | J1515 | GMNA |
| 4067210 | Engine Rear Mount Replacement | J1516 | GMNA |
| 4067210 | Engine Rear Mount Replacement | 1112800 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4067210 | Engine Rear Mount Replacement | 1140700 | GMK Domestic |
| 4067210 | Engine Rear Mount Replacement | 1141000 | GMK Domestic |
| 4067210 | Engine Rear Mount Replacement | 1141020 | GMK Domestic |
| 4067210 | Engine Rear Mount Replacement | 1380700 | GMK Overseas |
| 4067210 | Engine Rear Mount Replacement | 1381300 | GMK Overseas |
| 4067210 | Engine Rear Mount Replacement | 1381500 | GMK Overseas |
| 4067250 | Engine Mount Snubber Replacement | J1519 | GMNA |
| 4067270 | Engine Mount Strut Replacement | J1520 | GMNA |
| 4067270 | Engine Mount Strut Replacement | J1521 | GMNA |
| 4067270 | Engine Mount Strut Replacement | 1141500 | GMK Domestic |
| 4067270 | Engine Mount Strut Replacement | 1381100 | GMK Overseas |
| 4067270 | Engine Mount Strut Replacement | 1383500 | GMK Overseas |
| 4067290 | Engine Mount Strut Replacement - Right Side | J1522 | GMNA |
| 4067300 | Engine Mount Vacuum Tank Replacement | | |
| 4067320 | Engine Mount Vacuum Filter Replacement | | |
| 4067340 | Engine Mount Vacuum Valve Replacement | | |
| 4067350 | Engine Block Plug Replacement | J1600 | GMNA |
| 4067350 | Engine Block Plug Replacement | J7512 | GMNA |
| 4067350 | Engine Block Plug Replacement | 1111800 | GMK Domestic |
| 4067350 | Engine Block Plug Replacement | 1140110 | GMK Domestic |
| 4067350 | Engine Block Plug Replacement | 1210700 | GMK Overseas |
| 4067350 | Engine Block Plug Replacement | 1210900 | GMK Overseas |
| 4067390 | Camshaft Bearing Front Cap Replacement | | |
| 4067410 | Camshaft Rear Bearing Hole Plug Replacement | J0867 | GMNA |
| 4067410 | Camshaft Rear Bearing Hole Plug Replacement | J0876 | GMNA |
| 4067410 | Camshaft Rear Bearing Hole Plug Replacement | J0877 | GMNA |
| 4067410 | Camshaft Rear Bearing Hole Plug Replacement | J0879 | GMNA |
| 4067410 | Camshaft Rear Bearing Hole Plug Replacement | J1650 | GMNA |
| 4067410 | Camshaft Rear Bearing Hole Plug Replacement | J1651 | GMNA |
| 4067410 | Camshaft Rear Bearing Hole Plug Replacement | J1660 | GMNA |
| 4067470 | Partial Engine Replacement | J1820 | GMNA |
| 4067470 | Partial Engine Replacement | 1130300 | GMK Domestic |
| 4067470 | Partial Engine Replacement | J182000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4067470 | Partial Engine Replacement | J182100 | Holden Australia |
| 4067470 | Partial Engine Replacement | J182200 | Holden Australia |
| 4067470 | Partial Engine Replacement | J182300 | Holden Australia |
| 4067470 | Partial Engine Replacement | J182700 | Holden Australia |
| 4067470 | Partial Engine Replacement | J182800 | Holden Australia |
| 4067470 | Partial Engine Replacement | J182900 | Holden Australia |
| 4067470 | Partial Engine Replacement | J182950 | Holden Australia |
| 4067470 | Partial Engine Replacement | J182300 | Holden New Zealand |
| 4067470 | Partial Engine Replacement | J1825 | Holden New Zealand |
| 4067470 | Partial Engine Replacement | J182700 | Holden New Zealand |
| 4067470 | Partial Engine Replacement | 1211100 | GMK Overseas |
| 4067470 | Partial Engine Replacement | 1211200 | GMK Overseas |
| 4067490 | Engine Replacement | 1110100 | GMK Overseas |
| 4067490 | Engine Replacement | 111010A | GMK Overseas |
| 4067490 | Engine Replacement | 111010B | GMK Overseas |
| 4067490 | Engine Replacement | 111010C | GMK Overseas |
| 4067490 | Engine Replacement | 1110300 | GMK Overseas |
| 4067490 | Engine Replacement | 111030C | GMK Overseas |
| 4067490 | Engine Replacement | 1110600 | GMK Overseas |
| 4067490 | Engine Replacement | 111060A | GMK Overseas |
| 4067490 | Engine Replacement | 1110700 | GMK Overseas |
| 4067510 | Engine Assembly Replacement | J1880 | GMNA |
| 4067510 | Engine Assembly Replacement | J1952 | GMNA |
| 4067510 | Engine Assembly Replacement | J1880 | Holden Australia |
| 4067510 | Engine Assembly Replacement | J1885 | Holden New Zealand |
| 4067510 | Engine Assembly Replacement | 1110200 | GMK Overseas |
| 4067510 | Engine Assembly Replacement | 1110800 | GMK Overseas |
| 4067510 | Engine Assembly Replacement | 111080A | GMK Overseas |
| 4067510 | Engine Assembly Replacement | 111080B | GMK Overseas |
| 4067510 | Engine Assembly Replacement | 111080C | GMK Overseas |
| 4067510 | Engine Assembly Replacement | 1110900 | GMK Overseas |
| 4067510 | Engine Assembly Replacement | 111090A | GMK Overseas |
| 4067510 | Engine Assembly Replacement | 111090B | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4067510 | Engine Assembly Replacement | 111090C | GMK Overseas |
| 4067550 | Engine Oil Cooler Housing Replacement | 1424600 | GMK Domestic |
| 4067550 | Engine Oil Cooler Housing Replacement | 1231400 | GMK Overseas |
| 4067570 | Engine Oil Cooler Shield Replacement | J3143 | GMNA |
| 4067630 | Oil Pump Screen Replacement | J1059 | GMNA |
| 4067630 | Oil Pump Screen Replacement | J3512 | GMNA |
| 4067650 | Crankshaft Position Sensor Reluctor Ring Replacement | J4356 | GMNA |
| 4067650 | Crankshaft Position Sensor Reluctor Ring Replacement | 1151000 | GMK Domestic |
| 4067650 | Crankshaft Position Sensor Reluctor Ring Replacement | 1221300 | GMK Overseas |
| 4067650 | Crankshaft Position Sensor Reluctor Ring Replacement | 122130A | GMK Overseas |
| 4067870 | Charge Air Cooler Cover Replacement | | |
| 4068290 | Turbocharger Replacement | J5855 | GMNA |
| 4068290 | Turbocharger Replacement | J5860 | GMNA |
| 4068290 | Turbocharger Replacement | R9224 | GMNA |
| 4068290 | Turbocharger Replacement | J000619 | Holden Australia |
| 4068290 | Turbocharger Replacement | J470400 | Holden Australia |
| 4068290 | Turbocharger Replacement | J586300 | Holden Australia |
| 4068290 | Turbocharger Replacement | J586450 | Holden Australia |
| 4068290 | Turbocharger Replacement | J818200 | Holden Australia |
| 4068290 | Turbocharger Replacement | J470400 | Holden New Zealand |
| 4068290 | Turbocharger Replacement | J5860 | Holden New Zealand |
| 4068290 | Turbocharger Replacement | J5861 | Holden New Zealand |
| 4068290 | Turbocharger Replacement | J5862 | Holden New Zealand |
| 4068290 | Turbocharger Replacement | J586300 | Holden New Zealand |
| 4068290 | Turbocharger Replacement | J5864 | Holden New Zealand |
| 4068290 | Turbocharger Replacement | J586450 | Holden New Zealand |
| 4068290 | Turbocharger Replacement | 1941600 | GMK Overseas |
| 4068310 | Turbocharger Oil Return Hose Replacement | | |
| 4068330 | Turbocharger Oil Return Pipe Replacement | J5870 | GMNA |
| 4068330 | Turbocharger Oil Return Pipe Replacement | 1400320 | GMK Domestic |
| 4068330 | Turbocharger Oil Return Pipe Replacement | J484550 | Holden Australia |
| 4068330 | Turbocharger Oil Return Pipe Replacement | J586700 | Holden Australia |
| 4068330 | Turbocharger Oil Return Pipe Replacement | J586500 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4068330 | Turbocharger Oil Return Pipe Replacement | J5866 | Holden New Zealand |
| 4068330 | Turbocharger Oil Return Pipe Replacement | J5867 | Holden New Zealand |
| 4068330 | Turbocharger Oil Return Pipe Replacement | J586700 | Holden New Zealand |
| 4068330 | Turbocharger Oil Return Pipe Replacement | J5870 | Holden New Zealand |
| 4068330 | Turbocharger Oil Return Pipe Replacement | J587000 | Holden New Zealand |
| 4068330 | Turbocharger Oil Return Pipe Replacement | 1941800 | GMK Overseas |
| 4068330 | Turbocharger Oil Return Pipe Replacement | 1941900 | GMK Overseas |
| 4068350 | Turbocharger Oil Feed Pipe Replacement | J5865 | GMNA |
| 4068350 | Turbocharger Oil Feed Pipe Replacement | J5880 | GMNA |
| 4068350 | Turbocharger Oil Feed Pipe Replacement | 1326200 | GMK Domestic |
| 4068350 | Turbocharger Oil Feed Pipe Replacement | J473340 | Holden Australia |
| 4068350 | Turbocharger Oil Feed Pipe Replacement | J484540 | Holden Australia |
| 4068350 | Turbocharger Oil Feed Pipe Replacement | J473340 | Holden New Zealand |
| 4068350 | Turbocharger Oil Feed Pipe Replacement | J5865 | Holden New Zealand |
| 4068350 | Turbocharger Oil Feed Pipe Replacement | J5880 | Holden New Zealand |
| 4068350 | Turbocharger Oil Feed Pipe Replacement | 1941700 | GMK Overseas |
| 4068360 | Turbocharger Heat Shield Replacement | | |
| 4068410 | Supercharger Replacement | J5908 | GMNA |
| 4068430 | Positive Crankcase Ventilation Valve Replacement | J6000 | GMNA |
| 4068430 | Positive Crankcase Ventilation Valve Replacement | J7604 | GMNA |
| 4068430 | Positive Crankcase Ventilation Valve Replacement | J7921 | GMNA |
| 4068430 | Positive Crankcase Ventilation Valve Replacement | 1220700 | GMK Domestic |
| 4068430 | Positive Crankcase Ventilation Valve Replacement | 1220800 | GMK Domestic |
| 4068430 | Positive Crankcase Ventilation Valve Replacement | J000631 | Holden Australia |
| 4068430 | Positive Crankcase Ventilation Valve Replacement | J600000 | Holden Australia |
| 4068430 | Positive Crankcase Ventilation Valve Replacement | J950100 | Holden Australia |
| 4068430 | Positive Crankcase Ventilation Valve Replacement | J000631 | Holden New Zealand |
| 4068430 | Positive Crankcase Ventilation Valve Replacement | J6000 | Holden New Zealand |
| 4068430 | Positive Crankcase Ventilation Valve Replacement | J600000 | Holden New Zealand |
| 4068430 | Positive Crankcase Ventilation Valve Replacement | J950100 | Holden New Zealand |
| 4068430 | Positive Crankcase Ventilation Valve Replacement | 1233200 | GMK Overseas |
| 4068430 | Positive Crankcase Ventilation Valve Replacement | 1233700 | GMK Overseas |
| 4068430 | Positive Crankcase Ventilation Valve Replacement | 1234567 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4068450 | Positive Crankcase Ventilation Oil Separator Replacement | J6001 | GMNA |
| 4068450 | Headlamp Switch Trim Plate Replacement | J6001 | GMNA |
| 4068470 | Positive Crankcase Ventilation Tube Replacement | J6002 | GMNA |
| 4068490 | Positive Crankcase Ventilation Hose/Pipe/Tube Replacement | J6003 | GMNA |
| 4068490 | Positive Crankcase Ventilation Hose/Pipe/Tube Replacement | J6030 | GMNA |
| 4068490 | Positive Crankcase Ventilation Hose/Pipe/Tube Replacement | J6730 | GMNA |
| 4068490 | Positive Crankcase Ventilation Hose/Pipe/Tube Replacement | J6731 | GMNA |
| 4068490 | Positive Crankcase Ventilation Hose/Pipe/Tube Replacement | J950110 | Holden Australia |
| 4068490 | Positive Crankcase Ventilation Hose/Pipe/Tube Replacement | J951300 | Holden Australia |
| 4068490 | Positive Crankcase Ventilation Hose/Pipe/Tube Replacement | J951300 | Holden New Zealand |
| 4068490 | Positive Crankcase Ventilation Hose/Pipe/Tube Replacement | 1233100 | GMK Overseas |
| 4068490 | Positive Crankcase Ventilation Hose/Pipe/Tube Replacement | 1233500 | GMK Overseas |
| 4068490 | Positive Crankcase Ventilation Hose/Pipe/Tube Replacement | 1932600 | GMK Overseas |
| 4068510 | Crankcase Depression Regulator Valve Replacement | J6004 | GMNA |
| 4068510 | Crankcase Depression Regulator Valve Replacement | J6690 | GMNA |
| 4068510 | Crankcase Depression Regulator Valve Replacement | J471010 | Holden Australia |
| 4068510 | Crankcase Depression Regulator Valve Replacement | J471010 | Holden New Zealand |
| 4069420 | Positive Crankcase Ventilation Oil Separator Drain Hose Replacement | | |
| 4069440 | Positive Crankcase Ventilation Oil Separator Hose Replacement | | |
| 4069670 | Engine Oil Level Indicator Switch Replacement | N2215 | GMNA |
| 4069670 | Engine Oil Level Indicator Switch Replacement | N4845 | GMNA |
| 4069690 | Engine Oil Pressure Switch Replacement | N2220 | GMNA |
| 4069690 | Engine Oil Pressure Switch Replacement | N2221 | GMNA |
| 4069690 | Engine Oil Pressure Switch Replacement | T5619 | GMNA |
| 4069690 | Engine Oil Pressure Switch Replacement | 1423700 | GMK Domestic |
| 4069690 | Engine Oil Pressure Switch Replacement | N2220 | Holden Australia |
| 4069690 | Engine Oil Pressure Switch Replacement | N222000 | Holden Australia |
| 4069690 | Engine Oil Pressure Switch Replacement | N2220 | Holden New Zealand |
| 4069690 | Engine Oil Pressure Switch Replacement | N222000 | Holden New Zealand |
| 4069690 | Engine Oil Pressure Switch Replacement | N2221 | Holden New Zealand |
| 4069730 | Engine Oil Pressure Indicator Switch Replacement | N2222 | GMNA |
| 4069730 | Engine Oil Pressure Indicator Switch Replacement | 1211500 | GMK Overseas |
| 4069770 | Engine Oil Level Sensor Replacement | N4580 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069770 | Engine Oil Level Sensor Replacement | 2211900 | GMK Domestic |
| 4069770 | Engine Oil Level Sensor Replacement | 2212000 | GMK Domestic |
| 4069770 | Engine Oil Level Sensor Replacement | 2212100 | GMK Domestic |
| 4069770 | Engine Oil Level Sensor Replacement | J221950 | Holden Australia |
| 4069770 | Engine Oil Level Sensor Replacement | 1231910 | GMK Overseas |
| 4069770 | Engine Oil Level Sensor Replacement | 1232200 | GMK Overseas |
| 4069770 | Engine Oil Level Sensor Replacement | 5010700 | GMK Overseas |
| 4069790 | Engine Oil Pressure Sensor Replacement | J7542 | GMNA |
| 4069790 | Engine Oil Pressure Sensor Replacement | N4585 | GMNA |
| 4069790 | Engine Oil Pressure Sensor Replacement | N318500 | Holden Australia |
| 4069790 | Engine Oil Pressure Sensor Replacement | N318500 | Holden New Zealand |
| 4069790 | Engine Oil Pressure Sensor Replacement | 1231900 | GMK Overseas |
| 4069810 | Engine Oil Temperature Sensor Replacement | N4590 | GMNA |
| 4069810 | Engine Oil Temperature Sensor Replacement | 2211500 | GMK Domestic |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J0322 | GMNA |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J0323 | GMNA |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J0327 | GMNA |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J7513 | GMNA |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J7514 | GMNA |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J7714 | GMNA |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J7930 | GMNA |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J7936 | GMNA |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J9991 | GMNA |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | 1020120 | GMK Domestic |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | 1100120 | GMK Domestic |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | 5121320 | GMK Domestic |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J000514 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J000636 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J000654 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J000657 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J000692 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J000725 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J000794 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J000833 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J000836 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J022000 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J032300 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J320150 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J335550 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J338010 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J479100 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J517200 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J525000 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J597200 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J606000 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J635100 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J635300 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J654100 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J654200 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J794900 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900001 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900002 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900003 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900004 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900008 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900009 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900010 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900011 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900012 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900013 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900014 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900015 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900016 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900017 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900018 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900019 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900020 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900021 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900022 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900023 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900024 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900025 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900026 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900027 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900028 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900029 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900030 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900031 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900032 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900033 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900034 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900035 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900036 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900037 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900038 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900040 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900041 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900042 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900043 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900044 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900045 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900046 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900047 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900048 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900049 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900050 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900051 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900052 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900053 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900054 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900055 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900056 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900057 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900058 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900059 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900060 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900061 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900062 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900063 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900064 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900065 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900066 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900067 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900068 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900069 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900070 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900071 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900072 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900073 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900075 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900076 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900078 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900080 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900081 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900082 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900083 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900084 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900085 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900087 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900088 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900089 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900090 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900091 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900092 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900093 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900094 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900095 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900096 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900097 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900098 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900100 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900101 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900102 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900103 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900105 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900106 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900107 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900108 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900110 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900111 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900112 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900113 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900115 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900116 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900117 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900118 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900120 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900121 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900122 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900123 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900125 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900128 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900130 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900131 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900132 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900133 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900134 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900135 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900136 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900137 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900138 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900139 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900140 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900141 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900150 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900151 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900152 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900153 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900154 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900155 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900156 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900157 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900158 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900159 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900160 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900161 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900167 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900168 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900170 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900171 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900172 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900173 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900174 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900175 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900180 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900190 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900191 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900193 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900196 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900197 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900198 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900200 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900201 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900202 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900203 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900204 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900205 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900206 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900207 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900208 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900215 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900216 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900217 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900218 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900219 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900220 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900221 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900222 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900223 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900229 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900230 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900234 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900235 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900243 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900251 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900253 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900261 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900262 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900263 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900264 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900265 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900267 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900268 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900269 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900270 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900271 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900273 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900274 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900276 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900277 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900299 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900300 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900301 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900302 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900303 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900304 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900305 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900306 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900313 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900315 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900318 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900320 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900324 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900325 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900326 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900327 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900328 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900330 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900332 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900333 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900335 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900336 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900337 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900338 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900340 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900341 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900342 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900343 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900346 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900347 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900348 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900351 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900352 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900353 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900354 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900355 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900356 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900357 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900358 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900365 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900366 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900367 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900368 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900374 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900380 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900381 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900391 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900392 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900393 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900400 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900401 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900402 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900403 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900404 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900405 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900406 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900415 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900420 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900423 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900425 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900430 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900432 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900440 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900442 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900443 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900444 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900446 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900453 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900458 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900459 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900460 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900461 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900462 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900463 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900480 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900481 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900489 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900500 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900501 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900502 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900503 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900504 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900505 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900506 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900507 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900513 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900520 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900521 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900522 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900523 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900530 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900532 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900533 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900544 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900545 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900546 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900550 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900556 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900560 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900561 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900562 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900563 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900564 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900565 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900566 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900567 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900568 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900571 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900572 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900573 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900575 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900576 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900601 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900602 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900603 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900604 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900605 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900606 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900607 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900608 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900610 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900615 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900616 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900617 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900621 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900622 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900623 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900625 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900626 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900627 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900628 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900629 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J90062B | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900630 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900633 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900638 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900641 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900643 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900645 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900646 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900647 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900650 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900651 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900652 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900654 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900656 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900660 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900670 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900671 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900672 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900673 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900674 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900683 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900685 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900686 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900687 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900689 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J90068A | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900690 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900691 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900692 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900693 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900697 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900698 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900700 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900703 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900704 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900705 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900706 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900711 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900712 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900716 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900717 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900719 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900722 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900724 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900725 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900730 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900740 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900741 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900742 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900748 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900751 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900753 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900756 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900757 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900758 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900768 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900785 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900800 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900801 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900833 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900835 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900843 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900850 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900851 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900852 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900856 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900864 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900961 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901011 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901012 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901013 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901014 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901019 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901064 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901093 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901094 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901101 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901105 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901106 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901107 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901109 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901110 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901111 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901112 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901114 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901115 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901116 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901118 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901120 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901121 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901122 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901125 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901130 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901133 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901134 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901138 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901153 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901167 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901170 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901171 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901173 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901175 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901180 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901191 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901209 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901210 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901220 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901221 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901223 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901224 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901227 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901228 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901230 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901232 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901234 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901235 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901238 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901243 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901255 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901257 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901258 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901271 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901273 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901275 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901280 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901290 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901295 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901300 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901310 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901311 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901320 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901326 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901327 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901328 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901329 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901335 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901336 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901340 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901345 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901351 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901361 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901372 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901380 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901381 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901382 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901403 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901404 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901405 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901406 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901407 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901441 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901446 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901447 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901450 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901481 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901482 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901483 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901485 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901486 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901500 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901501 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901502 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901503 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901508 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901509 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901510 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901512 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901514 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901515 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901516 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901517 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901520 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901523 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901525 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901526 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901530 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901535 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901539 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901540 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901546 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901550 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901551 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901555 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901565 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901571 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901574 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901575 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901585 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901589 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901600 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901601 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901602 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901605 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901606 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901610 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901611 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901612 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901613 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901614 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901615 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901616 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901618 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J90161C | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901620 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901621 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901623 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901625 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901626 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901627 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901628 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901629 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901630 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901631 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901632 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901633 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901635 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901637 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901639 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901640 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901642 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901643 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901648 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901649 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901650 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901651 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901661 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901663 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901668 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901677 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901678 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901679 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901680 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901681 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901682 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901683 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901689 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901690 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901691 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901700 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901703 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901706 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901740 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901793 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901810 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901811 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901813 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901835 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901845 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901860 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901870 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901875 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901895 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901896 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901900 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901901 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902002 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902006 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902007 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902008 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902009 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902031 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902032 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902066 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902067 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902068 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902075 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902080 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902084 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902088 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902089 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902090 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902091 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902092 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902093 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902094 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902095 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902096 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902097 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902098 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902099 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902100 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902101 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902103 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902104 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902105 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902106 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902107 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902108 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902110 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902119 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902120 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902122 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902123 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902125 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902127 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902128 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902135 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902138 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902139 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902140 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902141 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902146 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902147 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902149 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902150 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902176 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902177 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902178 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902179 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902180 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902187 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902188 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902189 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902190 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902195 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902196 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902197 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902198 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902226 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902227 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902228 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902229 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902231 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902232 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902234 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902235 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902237 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902238 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902239 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902242 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902243 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902247 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902251 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902254 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902264 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902269 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902270 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902271 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902272 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902273 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902279 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902293 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902297 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902298 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902299 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902300 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902301 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902303 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902304 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902306 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902310 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902312 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902313 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902315 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902316 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902344 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902422 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J90244A | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902452 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902453 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902454 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902455 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902458 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902463 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902500 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902501 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902510 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902533 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902534 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902544 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902610 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902626 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902629 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902636 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902687 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902745 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902963 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J903027 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J903902 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J903924 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J9991 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J999999 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | N225000 | Holden Australia |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J000636 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J000657 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J000692 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J000725 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J000791 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J022000 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J032300 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J335550 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J338010 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J597200 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J606000 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J635100 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J792300 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J792310 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J792600 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J794900 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900001 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900008 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900009 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900010 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900011 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900012 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900013 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900014 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900015 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900016 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900017 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900018 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900019 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900021 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900024 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900025 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900026 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900030 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900032 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900033 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900035 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900036 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900040 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900041 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900042 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900044 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900045 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900047 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900050 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900051 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900055 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900056 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900058 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900059 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900060 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900061 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900063 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900068 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900070 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900071 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900076 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900082 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900087 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900088 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900089 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900093 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900095 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900096 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900100 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900101 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900102 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900103 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900106 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900107 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900108 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900110 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900111 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900112 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900113 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900115 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900116 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900117 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900118 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900119 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900120 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900121 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900122 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900123 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900128 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900130 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900131 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900132 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900133 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900134 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900135 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900136 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900137 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900138 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900140 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900141 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900150 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900151 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900152 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900153 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900154 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900155 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900157 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900158 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900160 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900161 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900170 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900171 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900172 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900174 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900175 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900180 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900191 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900193 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900197 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900198 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900200 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900201 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900203 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900204 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900215 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900216 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900220 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900221 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900222 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900223 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900230 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900234 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900243 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900251 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900253 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900261 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900263 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900264 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900276 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900299 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900300 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900301 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900302 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900303 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900304 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900305 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900306 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900315 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900320 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900325 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900326 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900327 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900328 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900332 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900335 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900336 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900338 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900340 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900341 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900342 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900346 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900348 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900351 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900353 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900354 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900356 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900380 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900400 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900401 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900403 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900404 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900405 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900420 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900422 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900425 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900430 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900440 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900443 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900451 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900458 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900460 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900461 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900463 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900480 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900481 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900489 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900500 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900502 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900504 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900505 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900506 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900513 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900544 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900560 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900561 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900562 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900567 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900568 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900571 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900601 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900602 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900603 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900604 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900606 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900607 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900615 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900621 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900622 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900625 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900626 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900627 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900633 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900641 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900650 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900685 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900686 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900689 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J90068A | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900690 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900700 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900703 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900704 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900705 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900717 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900719 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900740 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900742 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900748 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900751 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900800 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900833 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900850 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900851 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900852 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900856 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J900864 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901001 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901010 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901011 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901012 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901013 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901056 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901064 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901094 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901096 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901106 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901112 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901120 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901122 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901130 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901133 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901191 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901223 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901234 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901238 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901258 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901271 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901320 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901327 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901335 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901361 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901372 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901380 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901404 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901405 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901446 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901447 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901481 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901502 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901503 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901510 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901514 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901516 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901520 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901523 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901526 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901530 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901540 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901551 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901571 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901574 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901585 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901606 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901610 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901612 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901613 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901614 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901616 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J90161C | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901625 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901626 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901627 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901629 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901630 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901631 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901632 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901650 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901651 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901655 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901663 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901668 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901678 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901690 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901691 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901700 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901740 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901810 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901813 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901870 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J901901 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902006 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902008 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902031 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902067 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902068 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902080 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902084 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902088 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902090 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902092 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902095 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902096 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902097 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902098 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902099 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902100 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902101 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902105 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902106 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902107 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902108 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902119 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902120 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902122 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902123 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902127 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902135 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902138 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902139 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902140 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902146 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902176 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902177 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902187 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902189 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902190 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902195 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902229 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902231 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902232 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902234 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902237 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902251 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902254 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902264 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902270 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902271 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902272 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902273 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902293 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902297 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902298 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902299 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J90244A | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902453 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902463 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902533 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902544 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902610 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902626 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902629 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J902636 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | J903924 | Holden New Zealand |
| 4069919 | Customer Concern Not Duplicated (CCND) - Engine Concern | P901328 | Holden New Zealand |
| 4410030 | Floor Air Outlet Duct Trim Cover Replacement | C2840 | GMNA |
| 4410040 | Heater and Air Conditioning Control Temperature Knob Replacement | | |
| 4410050 | Mode Valve Lever Replacement | 7136100 | GMK Overseas |
| 4410070 | Auxiliary Air Conditioning Blower Switch Replacement | R171061 | Holden New Zealand |
| 4410100 | Auxiliary Heater and Air Conditioning Control Bezel Replacement | | |
| 4410110 | Heater and Air Conditioning Remote Control Replacement | | |
| 4410140 | Heater and Air Conditioning Control Temperature Lever Replacement - Left Side | | |
| 4410160 | Heater and Air Conditioning Control Temperature Lever Replacement - Right Side | D0396 | GMNA |
| 4410180 | Heater and Air Conditioning Control Temperature Lever Replacement - Lower Left Side | | |
| 4410200 | Front Floor Console Rear Air Valve Lever Replacement | D0398 | GMNA |
| 4410210 | Mode Control Cable Replacement | D0401 | GMNA |
| 4410210 | Mode Control Cable Replacement | D0420 | GMNA |
| 4410210 | Mode Control Cable Replacement | D0426 | GMNA |
| 4410210 | Mode Control Cable Replacement | D0438 | GMNA |
| 4410210 | Mode Control Cable Replacement | D0439 | GMNA |
| 4410210 | Mode Control Cable Replacement | D0440 | GMNA |
| 4410210 | Mode Control Cable Replacement | D0448 | GMNA |
| 4410210 | Mode Control Cable Replacement | D0450 | GMNA |
| 4410210 | Mode Control Cable Replacement | D1838 | GMNA |
| 4410210 | Mode Control Cable Replacement | 8142200 | GMK Domestic |
| 4410210 | Mode Control Cable Replacement | D113100 | Holden Australia |
| 4410210 | Mode Control Cable Replacement | D113100 | Holden New Zealand |
| 4410210 | Mode Control Cable Replacement | 7350900 | GMK Overseas |
| 4410220 | Blower Motor Resistor Replacement | D1000 | GMNA |
| 4410220 | Blower Motor Resistor Replacement | D1002 | GMNA |
| 4410220 | Blower Motor Resistor Replacement | J7619 | GMNA |
| 4410220 | Blower Motor Resistor Replacement | N2080 | GMNA |
| 4410220 | Blower Motor Resistor Replacement | N9682 | GMNA |
| 4410220 | Blower Motor Resistor Replacement | D000399 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4410220 | Blower Motor Resistor Replacement | D1002 | Holden Australia |
| 4410220 | Blower Motor Resistor Replacement | D100200 | Holden Australia |
| 4410220 | Blower Motor Resistor Replacement | D108100 | Holden Australia |
| 4410220 | Blower Motor Resistor Replacement | D329100 | Holden Australia |
| 4410220 | Blower Motor Resistor Replacement | D330100 | Holden Australia |
| 4410220 | Blower Motor Resistor Replacement | D333110 | Holden Australia |
| 4410220 | Blower Motor Resistor Replacement | D000390 | Holden New Zealand |
| 4410220 | Blower Motor Resistor Replacement | D000399 | Holden New Zealand |
| 4410220 | Blower Motor Resistor Replacement | D108100 | Holden New Zealand |
| 4410220 | Blower Motor Resistor Replacement | D329100 | Holden New Zealand |
| 4410220 | Blower Motor Resistor Replacement | D330100 | Holden New Zealand |
| 4410220 | Blower Motor Resistor Replacement | D333110 | Holden New Zealand |
| 4410220 | Blower Motor Resistor Replacement | D333120 | Holden New Zealand |
| 4410220 | Blower Motor Resistor Replacement | 7133400 | GMK Overseas |
| 4410220 | Blower Motor Resistor Replacement | 7133410 | GMK Overseas |
| 4410220 | Blower Motor Resistor Replacement | 7140100 | GMK Overseas |
| 4410240 | Auxiliary Blower Motor Resistor Replacement | D1001 | GMNA |
| 4410240 | Auxiliary Blower Motor Resistor Replacement | D1005 | GMNA |
| 4410250 | Auxiliary Blower Control Module Replacement | D0891 | GMNA |
| 4410260 | Evaporator Air Temperature Sensor Replacement | 7134300 | GMK Overseas |
| 4410330 | Air Conditioning Refrigerant Pressure Sensor Valve Replacement | 7342000 | GMK Overseas |
| 4410350 | Air Conditioning Refrigerant Pressure Sensor Replacement - High Pressure | | |
| 4410370 | Air Conditioning Refrigerant Pressure Sensor Replacement - Low Pressure | | |
| 4410380 | Air Conditioning Refrigerant Temperature Sensor Replacement | 7133800 | GMK Overseas |
| 4410390 | Air Conditioning Cycling Switch Replacement | D1180 | GMNA |
| 4410410 | Air Conditioning (A/C) Refrigerant Pressure Sensor Replacement | D0347 | GMNA |
| 4410410 | Air Conditioning (A/C) Refrigerant Pressure Sensor Replacement | D1128 | GMNA |
| 4410410 | Air Conditioning (A/C) Refrigerant Pressure Sensor Replacement | D1135 | GMNA |
| 4410410 | Air Conditioning (A/C) Refrigerant Pressure Sensor Replacement | D1195 | GMNA |
| 4410410 | Air Conditioning (A/C) Refrigerant Pressure Sensor Replacement | N9525 | GMNA |
| 4410410 | Air Conditioning (A/C) Refrigerant Pressure Sensor Replacement | D308100 | Holden Australia |
| 4410410 | Air Conditioning (A/C) Refrigerant Pressure Sensor Replacement | D308100 | Holden New Zealand |
| 4410410 | Air Conditioning (A/C) Refrigerant Pressure Sensor Replacement | 7341900 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4410410 | Air Conditioning (A/C) Refrigerant Pressure Sensor Replacement | 734190A | GMK Overseas |
| 4410420 | Ambient Air Temperature Sensor Replacement | | |
| 4410430 | Air Conditioning (A/C) Refrigerant Low Temperature Sensor Replacement | | |
| 4410500 | Rear Floor Air Distributor Replacement | D1315 | GMNA |
| 4410500 | Rear Floor Air Distributor Replacement | D1517 | GMNA |
| 4410500 | Rear Floor Air Distributor Replacement | D013600 | Holden Australia |
| 4410500 | Rear Floor Air Distributor Replacement | D352100 | Holden Australia |
| 4410500 | Rear Floor Air Distributor Replacement | D013600 | Holden New Zealand |
| 4410500 | Rear Floor Air Distributor Replacement | D352100 | Holden New Zealand |
| 4410500 | Rear Floor Air Distributor Replacement | 7112700 | GMK Overseas |
| 4410500 | Rear Floor Air Distributor Replacement | 7112800 | GMK Overseas |
| 4410500 | Rear Floor Air Distributor Replacement | 7112900 | GMK Overseas |
| 4410500 | Rear Floor Air Distributor Replacement | 7113300 | GMK Overseas |
| 4410500 | Rear Floor Air Distributor Replacement | 7113400 | GMK Overseas |
| 4410500 | Rear Floor Air Distributor Replacement | 7113500 | GMK Overseas |
| 4410520 | Blower Motor Cover Replacement | | |
| 4410600 | Blower Motor Replacement | B6811 | GMNA |
| 4410600 | Blower Motor Replacement | D1320 | GMNA |
| 4410600 | Blower Motor Replacement | D1322 | GMNA |
| 4410600 | Blower Motor Replacement | D1324 | GMNA |
| 4410600 | Blower Motor Replacement | D1327 | GMNA |
| 4410600 | Blower Motor Replacement | D1328 | GMNA |
| 4410600 | Blower Motor Replacement | D1835 | GMNA |
| 4410600 | Blower Motor Replacement | D3122 | GMNA |
| 4410600 | Blower Motor Replacement | D3125 | GMNA |
| 4410600 | Blower Motor Replacement | D9753 | GMNA |
| 4410600 | Blower Motor Replacement | D9758 | GMNA |
| 4410600 | Blower Motor Replacement | D9777 | GMNA |
| 4410600 | Blower Motor Replacement | D106100 | Holden Australia |
| 4410600 | Blower Motor Replacement | D106150 | Holden Australia |
| 4410600 | Blower Motor Replacement | D132000 | Holden Australia |
| 4410600 | Blower Motor Replacement | D1322 | Holden Australia |
| 4410600 | Blower Motor Replacement | D132200 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4410600 | Blower Motor Replacement | D132300 | Holden Australia |
| 4410600 | Blower Motor Replacement | D327100 | Holden Australia |
| 4410600 | Blower Motor Replacement | D327150 | Holden Australia |
| 4410600 | Blower Motor Replacement | J000797 | Holden Australia |
| 4410600 | Blower Motor Replacement | D106100 | Holden New Zealand |
| 4410600 | Blower Motor Replacement | D106150 | Holden New Zealand |
| 4410600 | Blower Motor Replacement | D1320 | Holden New Zealand |
| 4410600 | Blower Motor Replacement | D132000 | Holden New Zealand |
| 4410600 | Blower Motor Replacement | D1322 | Holden New Zealand |
| 4410600 | Blower Motor Replacement | D132200 | Holden New Zealand |
| 4410600 | Blower Motor Replacement | D1323 | Holden New Zealand |
| 4410600 | Blower Motor Replacement | D132300 | Holden New Zealand |
| 4410600 | Blower Motor Replacement | D1340 | Holden New Zealand |
| 4410600 | Blower Motor Replacement | D134000 | Holden New Zealand |
| 4410600 | Blower Motor Replacement | D327100 | Holden New Zealand |
| 4410600 | Blower Motor Replacement | D327150 | Holden New Zealand |
| 4410600 | Blower Motor Replacement | 7140700 | GMK Overseas |
| 4410650 | Auxiliary Blower Motor Replacement | D1020 | GMNA |
| 4410650 | Auxiliary Blower Motor Replacement | D1321 | GMNA |
| 4410650 | Auxiliary Blower Motor Replacement | D1325 | GMNA |
| 4410650 | Auxiliary Blower Motor Replacement | D1326 | GMNA |
| 4410650 | Auxiliary Blower Motor Replacement | D2873 | GMNA |
| 4410650 | Auxiliary Blower Motor Replacement | D132100 | Holden Australia |
| 4410650 | Auxiliary Blower Motor Replacement | D504000 | Holden Australia |
| 4410650 | Auxiliary Blower Motor Replacement | D507000 | Holden Australia |
| 4410650 | Auxiliary Blower Motor Replacement | D331400 | Holden New Zealand |
| 4410750 | Inside Air Valve Water Deflector Replacement | 6310300 | GMK Domestic |
| 4410770 | Side Window Defogger Outlet Grille Replacement | D1435 | GMNA |
| 4410770 | Side Window Defogger Outlet Grille Replacement | D1444 | GMNA |
| 4410770 | Side Window Defogger Outlet Grille Replacement | D1445 | GMNA |
| 4410770 | Side Window Defogger Outlet Grille Replacement | D1447 | GMNA |
| 4410770 | Side Window Defogger Outlet Grille Replacement | D1448 | GMNA |
| 4410770 | Side Window Defogger Outlet Grille Replacement | D1449 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4410770 | Side Window Defogger Outlet Grille Replacement | 6420600 | GMK Domestic |
| 4410770 | Side Window Defogger Outlet Grille Replacement | 8212500 | GMK Domestic |
| 4410790 | Instrument Panel Outer Air Outlet Deflector Replacement - Right Side | | |
| 4410810 | Instrument Panel Outer Air Outlet Deflector Replacement - Left Side | | |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | C2203 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | C2204 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | C2368 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D1400 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D1401 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D1436 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D1437 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D1440 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D1441 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D1454 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D1455 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D1466 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D1468 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D1469 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D1480 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D1525 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D9746 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D9760 | GMNA |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D1440 | Holden Australia |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D1441 | Holden Australia |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D358100 | Holden Australia |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D358200 | Holden Australia |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D012100 | Holden New Zealand |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D012200 | Holden New Zealand |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D012300 | Holden New Zealand |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D1440 | Holden New Zealand |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D358100 | Holden New Zealand |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | D358200 | Holden New Zealand |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | 9311910 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | 9313300 | GMK Overseas |
| 4410850 | Instrument Panel Outer Air Outlet Replacement - Right Side | 9314300 | GMK Overseas |
| 4410870 | Instrument Panel Outer Air Outlet Replacement - Left Side | 9311900 | GMK Overseas |
| 4410870 | Instrument Panel Outer Air Outlet Replacement - Left Side | 9314400 | GMK Overseas |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D0359 | GMNA |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D1406 | GMNA |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D1409 | GMNA |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D1439 | GMNA |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D1442 | GMNA |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D1443 | GMNA |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D1446 | GMNA |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D1465 | GMNA |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D1467 | GMNA |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D9728 | GMNA |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D9742 | GMNA |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D016000 | Holden Australia |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D016100 | Holden Australia |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D016200 | Holden Australia |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D1442 | Holden Australia |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D1443 | Holden Australia |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D144600 | Holden Australia |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D358300 | Holden Australia |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D358500 | Holden Australia |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D358600 | Holden Australia |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D016000 | Holden New Zealand |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D016100 | Holden New Zealand |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D016200 | Holden New Zealand |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D358300 | Holden New Zealand |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D358500 | Holden New Zealand |
| 4410990 | Instrument Panel Center Air Outlet Replacement | D358600 | Holden New Zealand |
| 4410990 | Instrument Panel Center Air Outlet Replacement | 7110100 | GMK Overseas |
| 4410990 | Instrument Panel Center Air Outlet Replacement | 7111100 | GMK Overseas |
| 4410990 | Instrument Panel Center Air Outlet Replacement | 9311800 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4410990 | Instrument Panel Center Air Outlet Replacement | 9311810 | GMK Overseas |
| 4410990 | Instrument Panel Center Air Outlet Replacement | 9311920 | GMK Overseas |
| 4411010 | Side Window Defogger Outlet Deflector Replacement | | |
| 4411030 | Side Window Defogger Outlet Grille Replacement - Right Side | | |
| 4411050 | Side Window Defogger Outlet Grille Replacement - Left Side | | |
| 4411070 | Front Floor Console Rear Air Outlet Replacement | C3131 | GMNA |
| 4411070 | Front Floor Console Rear Air Outlet Replacement | D1450 | GMNA |
| 4411070 | Front Floor Console Rear Air Outlet Replacement | D1453 | GMNA |
| 4411070 | Front Floor Console Rear Air Outlet Replacement | D1457 | GMNA |
| 4411070 | Front Floor Console Rear Air Outlet Replacement | D1590 | GMNA |
| 4411070 | Front Floor Console Rear Air Outlet Replacement | D145700 | Holden Australia |
| 4411070 | Front Floor Console Rear Air Outlet Replacement | D358400 | Holden Australia |
| 4411070 | Front Floor Console Rear Air Outlet Replacement | D505000 | Holden Australia |
| 4411070 | Front Floor Console Rear Air Outlet Replacement | D352200 | Holden New Zealand |
| 4411070 | Front Floor Console Rear Air Outlet Replacement | D358400 | Holden New Zealand |
| 4411120 | Auxiliary Floor Air Outlet Replacement | D1452 | GMNA |
| 4411120 | Auxiliary Floor Air Outlet Replacement | D9770 | GMNA |
| 4411120 | Auxiliary Floor Air Outlet Replacement | 7112400 | GMK Overseas |
| 4411140 | Front Floor Console Rear Air Outlet Deflector Housing Replacement | | |
| 4411160 | Floor Air Valve Lever Replacement | | |
| 4411180 | Temperature Valve Actuator Lever Replacement | | |
| 4411190 | Instrument Panel Outer Air Outlet Bezel Replacement | | |
| 4411220 | Auxiliary Air Conditioning Air Outlet Deflector Replacement | | |
| 4411240 | Instrument Panel Center Air Outlet Grille Replacement | C2372 | GMNA |
| 4411240 | Instrument Panel Center Air Outlet Grille Replacement | D907300 | Holden Australia |
| 4411240 | Instrument Panel Center Air Outlet Grille Replacement | D907310 | Holden Australia |
| 4411240 | Instrument Panel Center Air Outlet Grille Replacement | D907320 | Holden Australia |
| 4411240 | Instrument Panel Center Air Outlet Grille Replacement | D907300 | Holden New Zealand |
| 4411240 | Instrument Panel Center Air Outlet Grille Replacement | D907310 | Holden New Zealand |
| 4411240 | Instrument Panel Center Air Outlet Grille Replacement | D907320 | Holden New Zealand |
| 4411280 | Instrument Panel Center Air Outlet Deflector Housing Replacement | | |
| 4411300 | Instrument Panel Outer Air Outlet Grille Replacement | D1473 | GMNA |
| 4411340 | Heater and Air Conditioning Control Cam Replacement | 8142400 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4411340 | Heater and Air Conditioning Control Cam Replacement | 7135800 | GMK Overseas |
| 4411340 | Heater and Air Conditioning Control Cam Replacement | 7350200 | GMK Overseas |
| 4411410 | Front Floor Console Rear Air Duct Replacement | D1451 | GMNA |
| 4411410 | Front Floor Console Rear Air Duct Replacement | D1518 | GMNA |
| 4411410 | Front Floor Console Rear Air Duct Replacement | D1522 | GMNA |
| 4411410 | Front Floor Console Rear Air Duct Replacement | D1523 | GMNA |
| 4411410 | Front Floor Console Rear Air Duct Replacement | J5985 | GMNA |
| 4411410 | Front Floor Console Rear Air Duct Replacement | D013000 | Holden Australia |
| 4411410 | Front Floor Console Rear Air Duct Replacement | D013500 | Holden Australia |
| 4411410 | Front Floor Console Rear Air Duct Replacement | D352200 | Holden Australia |
| 4411410 | Front Floor Console Rear Air Duct Replacement | D352300 | Holden Australia |
| 4411410 | Front Floor Console Rear Air Duct Replacement | D501000 | Holden Australia |
| 4411410 | Front Floor Console Rear Air Duct Replacement | D013000 | Holden New Zealand |
| 4411410 | Front Floor Console Rear Air Duct Replacement | D013500 | Holden New Zealand |
| 4411410 | Front Floor Console Rear Air Duct Replacement | D352300 | Holden New Zealand |
| 4411420 | Air Inlet Valve Actuator Replacement | 7132800 | GMK Overseas |
| 4411430 | Air Inlet Valve Actuator Gear Replacement | | |
| 4411450 | Mode Control Cam Actuator Replacement | | |
| 4411460 | Air Inlet Valve and Inside Air Valve Control Cam Replacement | D101300 | Holden Australia |
| 4411460 | Air Inlet Valve and Inside Air Valve Control Cam Replacement | 7135400 | GMK Overseas |
| 4411510 | Mode Valve Replacement | | |
| 4411520 | Temperature Valve Replacement | | |
| 4411550 | Air Inlet Valve Lever Replacement | | |
| 4411570 | Mixer Valve Replacement | | |
| 4411590 | Vent Valve Replacement | | |
| 4411610 | Defroster Valve Replacement | | |
| 4411630 | Air Inlet Valve Replacement | | |
| 4411740 | Air Inlet Housing Front Panel Replacement | | |
| 4411760 | Air Inlet Replacement | | |
| 4411780 | Air Inlet Assembly Replacement | D1920 | GMNA |
| 4411780 | Air Inlet Assembly Replacement | D1921 | GMNA |
| 4411780 | Air Inlet Assembly Replacement | D1999 | GMNA |
| 4411780 | Air Inlet Assembly Replacement | D2005 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4411780 | Air Inlet Assembly Replacement | D2520 | GMNA |
| 4411780 | Air Inlet Assembly Replacement | J502000 | Holden Australia |
| 4411780 | Air Inlet Assembly Replacement | 7112200 | GMK Overseas |
| 4411780 | Air Inlet Assembly Replacement | 7131800 | GMK Overseas |
| 4411920 | Heater Lower Case Replacement | | |
| 4411940 | Blower Front Case Replacement | | |
| 4411960 | Blower Case Replacement | | |
| 4411970 | Heater Case Replacement | | |
| 4412010 | Passenger Compartment Air Filter Housing Replacement | | |
| 4412090 | Auxiliary Heater Case Replacement | D1342 | GMNA |
| 4412090 | Auxiliary Heater Case Replacement | D2242 | GMNA |
| 4412090 | Auxiliary Heater Case Replacement | D2243 | GMNA |
| 4412090 | Auxiliary Heater Case Replacement | D2248 | GMNA |
| 4412090 | Auxiliary Heater Case Replacement | D2249 | GMNA |
| 4412090 | Auxiliary Heater Case Replacement | D2250 | GMNA |
| 4412090 | Auxiliary Heater Case Replacement | D2251 | GMNA |
| 4412090 | Auxiliary Heater Case Replacement | D3114 | GMNA |
| 4412090 | Auxiliary Heater Case Replacement | D3205 | GMNA |
| 4412090 | Auxiliary Heater Case Replacement | D3224 | GMNA |
| 4412090 | Auxiliary Heater Case Replacement | D3226 | GMNA |
| 4412090 | Auxiliary Heater Case Replacement | D3227 | GMNA |
| 4412090 | Auxiliary Heater Case Replacement | D4210 | GMNA |
| 4412110 | Auxiliary Air Conditioning Evaporator and Blower Case Replacement - Inboard | | |
| 4412130 | Auxiliary Air Conditioning Evaporator and Blower Case Replacement - Outboard | | |
| 4412150 | Auxiliary Air Conditioning Evaporator and Blower Lower Case Replacement | | |
| 4412170 | Heater Core Cover Replacement | | |
| 4412220 | Air Distributor Case Replacement - Left Side | | |
| 4412240 | Air Distributor Case Replacement - Right Side | | |
| 4412260 | Air Distributor Case Replacement - Center | 7114100 | GMK Overseas |
| 4412280 | Air Distributor Case Replacement | | |
| 4412330 | Blower Upper Case Replacement | | |
| 4412350 | Blower Lower Case Replacement | | |
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | D2002 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | D2108 | GMNA |
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | D2125 | GMNA |
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | D2223 | GMNA |
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | D2224 | GMNA |
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | D2225 | GMNA |
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | D2462 | GMNA |
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | D2463 | GMNA |
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | D2502 | GMNA |
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | N6031 | GMNA |
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | N6032 | GMNA |
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | R9225 | GMNA |
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | D000363 | Holden Australia |
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | D318100 | Holden Australia |
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | D318150 | Holden Australia |
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | D318100 | Holden New Zealand |
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | D318150 | Holden New Zealand |
| 4412370 | Heater and Air Conditioning Evaporator Module Replacement | 7132100 | GMK Overseas |
| 4412390 | Heater Assembly Replacement | | |
| 4412410 | Air Conditioning Evaporator Upper Case Replacement | D1319 | GMNA |
| 4412410 | Air Conditioning Evaporator Upper Case Replacement | D2260 | GMNA |
| 4412410 | Air Conditioning Evaporator Upper Case Replacement | D2263 | GMNA |
| 4412410 | Air Conditioning Evaporator Upper Case Replacement | D2460 | GMNA |
| 4412410 | Air Conditioning Evaporator Upper Case Replacement | D2506 | GMNA |
| 4412410 | Air Conditioning Evaporator Upper Case Replacement | D9722 | GMNA |
| 4412410 | Air Conditioning Evaporator Upper Case Replacement | D141000 | Holden New Zealand |
| 4412410 | Air Conditioning Evaporator Upper Case Replacement | 7130100 | GMK Overseas |
| 4412410 | Air Conditioning Evaporator Upper Case Replacement | 713010A | GMK Overseas |
| 4412410 | Air Conditioning Evaporator Upper Case Replacement | 7130200 | GMK Overseas |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | B9799 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D0223 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D1330 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D1340 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2009 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2109 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2214 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2215 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2216 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2217 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2218 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2220 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2232 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2317 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2318 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2319 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2320 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2420 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2461 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2480 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2507 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2508 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2509 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2510 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2511 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D3002 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D9714 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D9735 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D9757 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D9767 | GMNA |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D000345 | Holden Australia |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D104100 | Holden Australia |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2109 | Holden Australia |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D222000 | Holden Australia |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D222200 | Holden Australia |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D251000 | Holden Australia |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D000345 | Holden New Zealand |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D104100 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2220 | Holden New Zealand |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D222000 | Holden New Zealand |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D2510 | Holden New Zealand |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D251000 | Holden New Zealand |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | D350199 | Holden New Zealand |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | 7140900 | GMK Overseas |
| 4412430 | Air Conditioning Evaporator Lower Case Replacement | 714090A | GMK Overseas |
| 4412450 | Air Conditioning (A/C) Evaporator Case Assembly Replacement | | |
| 4412460 | Heater and Air Conditioning Evaporator Case Replacement | 7134100 | GMK Overseas |
| 4412460 | Heater and Air Conditioning Evaporator Case Replacement | 713410A | GMK Overseas |
| 4412500 | Heater Water Shutoff Valve Actuator Inlet Hose Replacement | D2695 | GMNA |
| 4412500 | Heater Water Shutoff Valve Actuator Inlet Hose Replacement | 7210100 | GMK Overseas |
| 4412520 | Heater Water Shutoff Valve Inlet Hose Replacement | D2696 | GMNA |
| 4412540 | Heater Water Auxiliary Pump Inlet Hose Replacement | D2160 | GMNA |
| 4412540 | Heater Water Auxiliary Pump Inlet Hose Replacement | D2162 | GMNA |
| 4412540 | Heater Water Auxiliary Pump Inlet Hose Replacement | D2164 | GMNA |
| 4412540 | Heater Water Auxiliary Pump Inlet Hose Replacement | D2697 | GMNA |
| 4412540 | Heater Water Auxiliary Pump Inlet Hose Replacement | D2757 | GMNA |
| 4412540 | Heater Water Auxiliary Pump Inlet Hose Replacement | D2860 | GMNA |
| 4412540 | Heater Water Auxiliary Pump Inlet Hose Replacement | D2861 | GMNA |
| 4412540 | Heater Water Auxiliary Pump Inlet Hose Replacement | J3440 | GMNA |
| 4412560 | Heater Water Shutoff Valve Replacement | D2698 | GMNA |
| 4412580 | Heater Water Auxiliary Pump Replacement | D2699 | GMNA |
| 4412580 | Heater Water Auxiliary Pump Replacement | 7210500 | GMK Overseas |
| 4412600 | Heater Water Valve Replacement | D2700 | GMNA |
| 4412600 | Heater Water Valve Replacement | D2705 | GMNA |
| 4412600 | Heater Water Valve Replacement | D9754 | GMNA |
| 4412600 | Heater Water Valve Replacement | J3026 | GMNA |
| 4412600 | Heater Water Valve Replacement | J7615 | GMNA |
| 4412600 | Heater Water Valve Replacement | 8141400 | GMK Domestic |
| 4412600 | Heater Water Valve Replacement | D111700 | Holden Australia |
| 4412600 | Heater Water Valve Replacement | D111700 | Holden New Zealand |
| 4412642 | Cooling System Spring Band Clamp Repositioning | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4412720 | Heater Vent Hose Replacement | | |
| 4412740 | Heater Outlet Hose Vapor Vent Hose Replacement | | |
| 4412760 | Heater Core Inlet Tube Replacement | 7135500 | GMK Overseas |
| 4412780 | Heater Core Outlet Tube Replacement | 7135600 | GMK Overseas |
| 4412800 | Heater Inlet Pipe Adapter Replacement | | |
| 4412820 | Heater Inlet Pipe Replacement | D2735 | Holden Australia |
| 4412820 | Heater Inlet Pipe Replacement | D2736 | Holden Australia |
| 4412860 | Heater Inlet And Outlet Pipe Replacement | D2737 | GMNA |
| 4412940 | Auxiliary Heater Inlet and Outlet Hose Connector Retainer and Seal Replacement | | |
| 4413050 | Heater Inlet Rear and Outlet Hose Replacement | D2741 | GMNA |
| 4413050 | Heater Inlet Rear and Outlet Hose Replacement | D2751 | GMNA |
| 4413050 | Heater Inlet Rear and Outlet Hose Replacement | D2789 | GMNA |
| 4413050 | Heater Inlet Rear and Outlet Hose Replacement | D2790 | GMNA |
| 4413050 | Heater Inlet Rear and Outlet Hose Replacement | D2791 | GMNA |
| 4413050 | Heater Inlet Rear and Outlet Hose Replacement | N2743 | GMNA |
| 4413050 | Heater Inlet Rear and Outlet Hose Replacement | M000241 | Holden Australia |
| 4413100 | Heater Inlet Hose Replacement | D2730 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | D2732 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | D2735 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | D2740 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | D2744 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | D2747 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | D2748 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | D2750 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | D2774 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | D2784 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | D2787 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | D2794 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | D2797 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | D3290 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | J3270 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | J3363 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | J3367 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4413100 | Heater Inlet Hose Replacement | J3378 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | J7606 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | J7607 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | J7620 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | J9427 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | J9442 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | J9443 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | J9447 | GMNA |
| 4413100 | Heater Inlet Hose Replacement | D111110 | Holden Australia |
| 4413100 | Heater Inlet Hose Replacement | D111400 | Holden Australia |
| 4413100 | Heater Inlet Hose Replacement | D274600 | Holden Australia |
| 4413100 | Heater Inlet Hose Replacement | D274700 | Holden Australia |
| 4413100 | Heater Inlet Hose Replacement | D2774 | Holden Australia |
| 4413100 | Heater Inlet Hose Replacement | D2775 | Holden Australia |
| 4413100 | Heater Inlet Hose Replacement | D2787 | Holden Australia |
| 4413100 | Heater Inlet Hose Replacement | D278700 | Holden Australia |
| 4413100 | Heater Inlet Hose Replacement | D278900 | Holden Australia |
| 4413100 | Heater Inlet Hose Replacement | D279100 | Holden Australia |
| 4413100 | Heater Inlet Hose Replacement | J000782 | Holden Australia |
| 4413100 | Heater Inlet Hose Replacement | J601350 | Holden Australia |
| 4413100 | Heater Inlet Hose Replacement | J601590 | Holden Australia |
| 4413100 | Heater Inlet Hose Replacement | M000244 | Holden Australia |
| 4413100 | Heater Inlet Hose Replacement | D111110 | Holden New Zealand |
| 4413100 | Heater Inlet Hose Replacement | D111400 | Holden New Zealand |
| 4413100 | Heater Inlet Hose Replacement | D2746 | Holden New Zealand |
| 4413100 | Heater Inlet Hose Replacement | D274600 | Holden New Zealand |
| 4413100 | Heater Inlet Hose Replacement | D2747 | Holden New Zealand |
| 4413100 | Heater Inlet Hose Replacement | D274700 | Holden New Zealand |
| 4413100 | Heater Inlet Hose Replacement | D278700 | Holden New Zealand |
| 4413100 | Heater Inlet Hose Replacement | J000782 | Holden New Zealand |
| 4413100 | Heater Inlet Hose Replacement | J601350 | Holden New Zealand |
| 4413100 | Heater Inlet Hose Replacement | JG0908 | Holden New Zealand |
| 4413100 | Heater Inlet Hose Replacement | 1453100 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4413100 | Heater Inlet Hose Replacement | 1453300 | GMK Overseas |
| 4413120 | Heater Outlet Hose Replacement | D2731 | GMNA |
| 4413120 | Heater Outlet Hose Replacement | D2733 | GMNA |
| 4413120 | Heater Outlet Hose Replacement | D2736 | GMNA |
| 4413120 | Heater Outlet Hose Replacement | D2745 | GMNA |
| 4413120 | Heater Outlet Hose Replacement | D2746 | GMNA |
| 4413120 | Heater Outlet Hose Replacement | D2749 | GMNA |
| 4413120 | Heater Outlet Hose Replacement | D2752 | GMNA |
| 4413120 | Heater Outlet Hose Replacement | D2775 | GMNA |
| 4413120 | Heater Outlet Hose Replacement | D2779 | GMNA |
| 4413120 | Heater Outlet Hose Replacement | D2799 | GMNA |
| 4413120 | Heater Outlet Hose Replacement | J3292 | GMNA |
| 4413120 | Heater Outlet Hose Replacement | J3473 | GMNA |
| 4413120 | Heater Outlet Hose Replacement | J3474 | GMNA |
| 4413120 | Heater Outlet Hose Replacement | 8141000 | GMK Domestic |
| 4413120 | Heater Outlet Hose Replacement | 8141200 | GMK Domestic |
| 4413120 | Heater Outlet Hose Replacement | D111150 | Holden Australia |
| 4413120 | Heater Outlet Hose Replacement | D111500 | Holden Australia |
| 4413120 | Heater Outlet Hose Replacement | J601300 | Holden Australia |
| 4413120 | Heater Outlet Hose Replacement | D000405 | Holden New Zealand |
| 4413120 | Heater Outlet Hose Replacement | D111150 | Holden New Zealand |
| 4413120 | Heater Outlet Hose Replacement | D111500 | Holden New Zealand |
| 4413120 | Heater Outlet Hose Replacement | D274900 | Holden New Zealand |
| 4413120 | Heater Outlet Hose Replacement | J601300 | Holden New Zealand |
| 4413120 | Heater Outlet Hose Replacement | 1453200 | GMK Overseas |
| 4413120 | Heater Outlet Hose Replacement | R014058 | GMK Overseas |
| 4413140 | Heater Inlet Front Hose Replacement | | |
| 4413160 | Heater Inlet Rear Hose Replacement | | |
| 4413440 | Heater Outlet Front Hose Replacement | | |
| 4413490 | Auxiliary Heater Inlet Hose Replacement | | |
| 4413510 | Auxiliary Heater Outlet Hose Replacement | | |
| 4413590 | Auxiliary Heater Core Tube Replacement | | |
| 4413640 | Auxiliary Heater Core Replacement | D2801 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4413640 | Auxiliary Heater Core Replacement | D2819 | GMNA |
| 4413640 | Auxiliary Heater Core Replacement | D2821 | GMNA |
| 4413640 | Auxiliary Heater Core Replacement | D280100 | Holden Australia |
| 4413640 | Auxiliary Heater Core Replacement | 7133900 | GMK Overseas |
| 4413660 | Heater Core Replacement | C2181 | GMNA |
| 4413660 | Heater Core Replacement | D2800 | GMNA |
| 4413660 | Heater Core Replacement | D2802 | GMNA |
| 4413660 | Heater Core Replacement | D2808 | GMNA |
| 4413660 | Heater Core Replacement | D2820 | GMNA |
| 4413660 | Heater Core Replacement | D2822 | GMNA |
| 4413660 | Heater Core Replacement | D2823 | GMNA |
| 4413660 | Heater Core Replacement | D2828 | GMNA |
| 4413660 | Heater Core Replacement | D9766 | GMNA |
| 4413660 | Heater Core Replacement | N1960 | GMNA |
| 4413660 | Heater Core Replacement | 8124000 | GMK Domestic |
| 4413660 | Heater Core Replacement | D102100 | Holden Australia |
| 4413660 | Heater Core Replacement | D280000 | Holden Australia |
| 4413660 | Heater Core Replacement | D280200 | Holden Australia |
| 4413660 | Heater Core Replacement | D282000 | Holden Australia |
| 4413660 | Heater Core Replacement | D2822 | Holden Australia |
| 4413660 | Heater Core Replacement | D282200 | Holden Australia |
| 4413660 | Heater Core Replacement | D337100 | Holden Australia |
| 4413660 | Heater Core Replacement | D102100 | Holden New Zealand |
| 4413660 | Heater Core Replacement | D280000 | Holden New Zealand |
| 4413660 | Heater Core Replacement | D280200 | Holden New Zealand |
| 4413660 | Heater Core Replacement | D282000 | Holden New Zealand |
| 4413660 | Heater Core Replacement | D282200 | Holden New Zealand |
| 4413660 | Heater Core Replacement | D337100 | Holden New Zealand |
| 4413660 | Heater Core Replacement | 7130300 | GMK Overseas |
| 4413660 | Heater Core Replacement | 713030A | GMK Overseas |
| 4413660 | Heater Core Replacement | 713030B | GMK Overseas |
| 4413660 | Heater Core Replacement | 7130500 | GMK Overseas |
| 4413660 | Heater Core Replacement | 713050A | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4413710 | Fuel Pressure Regulator Replacement | D2836 | GMNA |
| 4413730 | Engine Coolant Heater Cover Replacement | D2837 | GMNA |
| 4413750 | Engine Coolant Heater Combustion Chamber Temperature Sensor Replacement | | |
| 4413770 | Engine Coolant Heater Combustion Fan Replacement | D2839 | GMNA |
| 4413790 | Engine Coolant Heater Switch Replacement | D2840 | GMNA |
| 4413810 | Engine Coolant Heater Air Supply Hose Replacement | D2841 | GMNA |
| 4413830 | Engine Coolant Heater Control Module Replacement | D2842 | GMNA |
| 4413850 | Engine Coolant Heater Control Replacement | | |
| 4413870 | Engine Coolant Heater Combustion Chamber Replacement | | |
| 4413890 | Engine Coolant Heater Fuel Pump Replacement | | |
| 4413910 | Engine Coolant Heater Exhaust Muffler Replacement | | |
| 4413930 | Engine Coolant Heater Exhaust Pipe Replacement | | |
| 4413950 | Engine Coolant Heater Combustion Fan Cover Replacement | | |
| 4413970 | Glow Plug Shell Replacement | | |
| 4413990 | Auxiliary Electric Heater Replacement | | |
| 4414010 | Heater Coolant Pump Replacement | D2850 | GMNA |
| 4414010 | Heater Coolant Pump Replacement | D2855 | GMNA |
| 4414010 | Heater Coolant Pump Replacement | J4660 | GMNA |
| 4414010 | Heater Coolant Pump Replacement | 1920600 | GMK Domestic |
| 4414030 | Heater Coolant Heater Fuel Pump Replacement | D2864 | GMNA |
| 4414050 | Heater Coolant Heater Air Supply Hose Replacement | | |
| 4414070 | Heater Coolant Heater Exhaust Muffler Replacement | D2866 | GMNA |
| 4414070 | Heater Coolant Heater Exhaust Muffler Replacement | L1294 | GMNA |
| 4414070 | Heater Coolant Heater Exhaust Muffler Replacement | D000227 | Holden Australia |
| 4414090 | Heater Coolant Heater Replacement | D2867 | GMNA |
| 4414110 | Heater Coolant Heater Combustion Sensor Replacement | D2838 | GMNA |
| 4414110 | Heater Coolant Heater Combustion Sensor Replacement | D2868 | GMNA |
| 4414130 | Heater Coolant Heater Air Temperature Sensor Replacement | | |
| 4414180 | Heater Coolant Heater Control Replacement | D2843 | GMNA |
| 4414180 | Heater Coolant Heater Control Replacement | D2871 | GMNA |
| 4414230 | Heater Coolant Heater Blower Replacement | | |
| 4414250 | Heater Coolant Heater Glow Plug Replacement | D2874 | GMNA |
| 4414260 | Heater and Air Conditioning Control Vacuum Pump Replacement | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4414270 | Heater Coolant Heater Heat Shield Replacement | 7130600 | GMK Overseas |
| 4414280 | Auxiliary Heater Replacement | | |
| 4414290 | Air Conditioning Evaporator and Blower Module Drain Hose Replacement | D3010 | GMNA |
| 4414290 | Air Conditioning Evaporator and Blower Module Drain Hose Replacement | D3300 | GMNA |
| 4414290 | Air Conditioning Evaporator and Blower Module Drain Hose Replacement | D9755 | GMNA |
| 4414290 | Air Conditioning Evaporator and Blower Module Drain Hose Replacement | D9765 | GMNA |
| 4414290 | Air Conditioning Evaporator and Blower Module Drain Hose Replacement | D000360 | Holden Australia |
| 4414290 | Air Conditioning Evaporator and Blower Module Drain Hose Replacement | D000381 | Holden Australia |
| 4414290 | Air Conditioning Evaporator and Blower Module Drain Hose Replacement | D323100 | Holden Australia |
| 4414290 | Air Conditioning Evaporator and Blower Module Drain Hose Replacement | D000360 | Holden New Zealand |
| 4414290 | Air Conditioning Evaporator and Blower Module Drain Hose Replacement | D000414 | Holden New Zealand |
| 4414290 | Air Conditioning Evaporator and Blower Module Drain Hose Replacement | D323100 | Holden New Zealand |
| 4414290 | Air Conditioning Evaporator and Blower Module Drain Hose Replacement | 7133500 | GMK Overseas |
| 4414290 | Air Conditioning Evaporator and Blower Module Drain Hose Replacement | 7340100 | GMK Overseas |
| 4414310 | Air Conditioning Refrigerant High Pressure Service Valve Replacement | | |
| 4414330 | Air Conditioning Refrigerant Service Valve Core Replacement | D3019 | GMNA |
| 4414330 | Air Conditioning Refrigerant Service Valve Core Replacement | D3020 | GMNA |
| 4414330 | Air Conditioning Refrigerant Service Valve Core Replacement | D3160 | GMNA |
| 4414330 | Air Conditioning Refrigerant Service Valve Core Replacement | M5084 | GMNA |
| 4414330 | Air Conditioning Refrigerant Service Valve Core Replacement | M5085 | GMNA |
| 4414330 | Air Conditioning Refrigerant Service Valve Core Replacement | J312300 | Holden New Zealand |
| 4414330 | Air Conditioning Refrigerant Service Valve Core Replacement | 7340200 | GMK Overseas |
| 4414330 | Air Conditioning Refrigerant Service Valve Core Replacement | 7343100 | GMK Overseas |
| 4414350 | Air Conditioning O-Ring Seal Replacement | D3055 | GMNA |
| 4414350 | Air Conditioning O-Ring Seal Replacement | D301120 | Holden Australia |
| 4414370 | Air Conditioning Compressor Hose Seal Replacement | D000384 | Holden Australia |
| 4414370 | Air Conditioning Compressor Hose Seal Replacement | D000384 | Holden New Zealand |
| 4414570 | Air Conditioning Refrigerant Pressure Sensor O-Ring Seal Replacement | D3047 | GMNA |
| 4414570 | Air Conditioning Refrigerant Pressure Sensor O-Ring Seal Replacement | D200650 | Holden Australia |
| 4414570 | Air Conditioning Refrigerant Pressure Sensor O-Ring Seal Replacement | D200750 | Holden Australia |
| 4414570 | Air Conditioning Refrigerant Pressure Sensor O-Ring Seal Replacement | D200650 | Holden New Zealand |
| 4414570 | Air Conditioning Refrigerant Pressure Sensor O-Ring Seal Replacement | D200750 | Holden New Zealand |
| 4414950 | Air Conditioning Evaporator Hose Assembly Replacement | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4414970 | Air Conditioning Compressor and Evaporator Hose Replacement | | |
| 4414990 | Air Conditioning Evaporator Thermal Expansion Valve Hose Replacement | | |
| 4415010 | Air Conditioning Compressor Hose Replacement | | |
| 4415030 | Air Conditioning Compressor Front Hose Replacement | D3068 | GMNA |
| 4415080 | Air Conditioning Condenser and Air Conditioning Evaporator Tube Replacement | 7341000 | GMK Overseas |
| 4415160 | Heater Core Inlet and Outlet Pipe Filter Replacement | | |
| 4415220 | Air Conditioning Compressor Tube Replacement | | |
| 4415480 | Air Conditioning Evaporator Thermal Expansion Valve Tube Replacement | | |
| 4415800 | Air Conditioning Condenser Hose Replacement | | |
| 4415820 | Air Conditioning Condenser and Evaporator Hose Replacement | D307000 | Holden Australia |
| 4415840 | Auxiliary Air Conditioning Evaporator Hose Replacement | | |
| 4415860 | Auxiliary Air Conditioning Evaporator and Auxiliary Heater Hose Replacement - Intermediate | | |
| 4415880 | Air Conditioning Compressor and Condenser Hose Replacement | | |
| 4415900 | Auxiliary Air Conditioning Evaporator Tube with Auxiliary Heater Inlet and Outlet Pipe Replacement | | |
| 4415920 | Air Conditioning Evaporator Tube Replacement - Outlet | | |
| 4415940 | Air Conditioning Evaporator Tube Replacement | 7134400 | GMK Overseas |
| 4415960 | Air Conditioning Evaporator Front Tube Replacement | | |
| 4415980 | Air Conditioning Evaporator Rear Tube Replacement | | |
| 4416000 | Condenser Outlet Tube Replacement | D3131 | GMNA |
| 4416020 | Condenser Tube Replacement | | |
| 4416040 | Air Conditioning Condenser Replacement | D3077 | GMNA |
| 4416040 | Air Conditioning Condenser Replacement | D3132 | GMNA |
| 4416040 | Air Conditioning Condenser Replacement | D3140 | GMNA |
| 4416040 | Air Conditioning Condenser Replacement | D3140 | Holden Australia |
| 4416040 | Air Conditioning Condenser Replacement | D314000 | Holden Australia |
| 4416040 | Air Conditioning Condenser Replacement | D314100 | Holden Australia |
| 4416040 | Air Conditioning Condenser Replacement | D3140 | Holden New Zealand |
| 4416040 | Air Conditioning Condenser Replacement | D314000 | Holden New Zealand |
| 4416040 | Air Conditioning Condenser Replacement | D314100 | Holden New Zealand |
| 4416040 | Air Conditioning Condenser Replacement | 7341400 | GMK Overseas |
| 4416040 | Air Conditioning Condenser Replacement | 734140A | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4416090 | Air Conditioning Refrigerant Desiccant Replacement | D3175 | GMNA |
| 4416110 | Receiver and Dehydrator Replacement | D3180 | GMNA |
| 4416110 | Receiver and Dehydrator Replacement | D3182 | GMNA |
| 4416110 | Receiver and Dehydrator Replacement | D316100 | Holden Australia |
| 4416110 | Receiver and Dehydrator Replacement | D3180 | Holden Australia |
| 4416110 | Receiver and Dehydrator Replacement | D316100 | Holden New Zealand |
| 4416110 | Receiver and Dehydrator Replacement | 7341700 | GMK Overseas |
| 4416110 | Receiver and Dehydrator Replacement | 734170A | GMK Overseas |
| 4416130 | Air Conditioning Evaporator Tube Orifice Replacement | D3200 | GMNA |
| 4416180 | Air Conditioning Evaporator Thermal Expansion Valve Replacement | D3065 | GMNA |
| 4416180 | Air Conditioning Evaporator Thermal Expansion Valve Replacement | D3091 | GMNA |
| 4416180 | Air Conditioning Evaporator Thermal Expansion Valve Replacement | D3220 | GMNA |
| 4416180 | Air Conditioning Evaporator Thermal Expansion Valve Replacement | D000396 | Holden Australia |
| 4416180 | Air Conditioning Evaporator Thermal Expansion Valve Replacement | D319000 | Holden Australia |
| 4416180 | Air Conditioning Evaporator Thermal Expansion Valve Replacement | D319100 | Holden Australia |
| 4416180 | Air Conditioning Evaporator Thermal Expansion Valve Replacement | D3220 | Holden Australia |
| 4416180 | Air Conditioning Evaporator Thermal Expansion Valve Replacement | D322000 | Holden Australia |
| 4416180 | Air Conditioning Evaporator Thermal Expansion Valve Replacement | D000396 | Holden New Zealand |
| 4416180 | Air Conditioning Evaporator Thermal Expansion Valve Replacement | D319000 | Holden New Zealand |
| 4416180 | Air Conditioning Evaporator Thermal Expansion Valve Replacement | D322000 | Holden New Zealand |
| 4416180 | Air Conditioning Evaporator Thermal Expansion Valve Replacement | 7131600 | GMK Overseas |
| 4416180 | Air Conditioning Evaporator Thermal Expansion Valve Replacement | 713160A | GMK Overseas |
| 4416180 | Air Conditioning Evaporator Thermal Expansion Valve Replacement | 7131700 | GMK Overseas |
| 4416230 | Auxiliary Air Conditioning Evaporator Thermal Expansion Valve Replacement | D3210 | GMNA |
| 4416230 | Auxiliary Air Conditioning Evaporator Thermal Expansion Valve Replacement | D3223 | GMNA |
| 4416230 | Auxiliary Air Conditioning Evaporator Thermal Expansion Valve Replacement | D503000 | Holden Australia |
| 4416330 | Auxiliary Air Conditioning Evaporator Outlet Rear Hose Replacement | | |
| 4416440 | Air Conditioning (AC) Refrigerant Filter Replacement | D3250 | GMNA |
| 4416440 | Air Conditioning (AC) Refrigerant Filter Replacement | D3255 | GMNA |
| 4416440 | Air Conditioning (AC) Refrigerant Filter Replacement | D3258 | GMNA |
| 4416440 | Air Conditioning (AC) Refrigerant Filter Replacement | D325000 | Holden Australia |
| 4416440 | Air Conditioning (AC) Refrigerant Filter Replacement | D325000 | Holden New Zealand |
| 4416440 | Air Conditioning (AC) Refrigerant Filter Replacement | 7341800 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4416460 | Air Conditioning Accumulator Replacement | D3186 | GMNA |
| 4416460 | Air Conditioning Accumulator Replacement | D3238 | GMNA |
| 4416460 | Air Conditioning Accumulator Replacement | D3280 | GMNA |
| 4416460 | Air Conditioning Accumulator Replacement | D328000 | Holden Australia |
| 4416510 | Air Conditioning Evaporator Core Replacement | D3126 | GMNA |
| 4416510 | Air Conditioning Evaporator Core Replacement | D3127 | GMNA |
| 4416510 | Air Conditioning Evaporator Core Replacement | D3320 | GMNA |
| 4416510 | Air Conditioning Evaporator Core Replacement | D3344 | GMNA |
| 4416510 | Air Conditioning Evaporator Core Replacement | 6120300 | GMK Domestic |
| 4416510 | Air Conditioning Evaporator Core Replacement | D330200 | Holden Australia |
| 4416510 | Air Conditioning Evaporator Core Replacement | D3320 | Holden Australia |
| 4416510 | Air Conditioning Evaporator Core Replacement | D330200 | Holden New Zealand |
| 4416510 | Air Conditioning Evaporator Core Replacement | 7130700 | GMK Overseas |
| 4416510 | Air Conditioning Evaporator Core Replacement | 713070A | GMK Overseas |
| 4416510 | Air Conditioning Evaporator Core Replacement | 7130900 | GMK Overseas |
| 4416510 | Air Conditioning Evaporator Core Replacement | 713090A | GMK Overseas |
| 4416510 | Air Conditioning Evaporator Core Replacement | 713090B | GMK Overseas |
| 4416510 | Air Conditioning Evaporator Core Replacement | 7131900 | GMK Overseas |
| 4416510 | Air Conditioning Evaporator Core Replacement | 713190A | GMK Overseas |
| 4416560 | Auxiliary Air Conditioning Evaporator Replacement | D3228 | GMNA |
| 4416560 | Auxiliary Air Conditioning Evaporator Replacement | D3229 | GMNA |
| 4416560 | Auxiliary Air Conditioning Evaporator Replacement | D3230 | GMNA |
| 4416560 | Auxiliary Air Conditioning Evaporator Replacement | D3231 | GMNA |
| 4416560 | Auxiliary Air Conditioning Evaporator Replacement | D3345 | GMNA |
| 4416560 | Auxiliary Air Conditioning Evaporator Replacement | D502000 | Holden Australia |
| 4416700 | Compressor Pressure Relief Valve Replacement | D4200 | GMNA |
| 4416700 | Compressor Pressure Relief Valve Replacement | D4201 | GMNA |
| 4416700 | Compressor Pressure Relief Valve Replacement | D4202 | GMNA |
| 4416700 | Compressor Pressure Relief Valve Replacement | D4205 | GMNA |
| 4416700 | Compressor Pressure Relief Valve Replacement | D4400 | GMNA |
| 4416700 | Compressor Pressure Relief Valve Replacement | D4480 | GMNA |
| 4416700 | Compressor Pressure Relief Valve Replacement | 6112000 | GMK Domestic |
| 4416700 | Compressor Pressure Relief Valve Replacement | 8116500 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4416700 | Compressor Pressure Relief Valve Replacement | D310400 | Holden Australia |
| 4416700 | Compressor Pressure Relief Valve Replacement | D4200 | Holden Australia |
| 4416700 | Compressor Pressure Relief Valve Replacement | D310400 | Holden New Zealand |
| 4416700 | Compressor Pressure Relief Valve Replacement | D332100 | Holden New Zealand |
| 4416700 | Compressor Pressure Relief Valve Replacement | 7320100 | GMK Overseas |
| 4416700 | Compressor Pressure Relief Valve Replacement | 732010A | GMK Overseas |
| 4416720 | Compressor Variable Displacement Control Valve Replacement | D4204 | GMNA |
| 4416720 | Compressor Variable Displacement Control Valve Replacement | 8116600 | GMK Domestic |
| 4416720 | Compressor Variable Displacement Control Valve Replacement | D333700 | Holden Australia |
| 4416720 | Compressor Variable Displacement Control Valve Replacement | D333700 | Holden New Zealand |
| 4416720 | Compressor Variable Displacement Control Valve Replacement | D333700002 | Holden New Zealand |
| 4416720 | Compressor Variable Displacement Control Valve Replacement | 7320200 | GMK Overseas |
| 4416720 | Compressor Variable Displacement Control Valve Replacement | 732020A | GMK Overseas |
| 4416820 | Air Conditioning Clutch Replacement | D4240 | GMNA |
| 4416820 | Air Conditioning Clutch Replacement | D4241 | GMNA |
| 4416820 | Air Conditioning Clutch Replacement | D4244 | GMNA |
| 4416820 | Air Conditioning Clutch Replacement | D000212 | Holden Australia |
| 4416820 | Air Conditioning Clutch Replacement | D301110 | Holden Australia |
| 4416820 | Air Conditioning Clutch Replacement | D301130 | Holden Australia |
| 4416820 | Air Conditioning Clutch Replacement | D424000 | Holden Australia |
| 4416820 | Air Conditioning Clutch Replacement | D301110 | Holden New Zealand |
| 4416820 | Air Conditioning Clutch Replacement | D301130 | Holden New Zealand |
| 4416820 | Air Conditioning Clutch Replacement | D424000 | Holden New Zealand |
| 4416820 | Air Conditioning Clutch Replacement | 7320400 | GMK Overseas |
| 4416820 | Air Conditioning Clutch Replacement | 732040A | GMK Overseas |
| 4416820 | Air Conditioning Clutch Replacement | 7320410 | GMK Overseas |
| 4416820 | Air Conditioning Clutch Replacement | 7320800 | GMK Overseas |
| 4416820 | Air Conditioning Clutch Replacement | 732080A | GMK Overseas |
| 4416870 | Air Conditioning Clutch Rotor and Bearing Replacement | 7320600 | GMK Overseas |
| 4416870 | Air Conditioning Clutch Rotor and Bearing Replacement | 732060A | GMK Overseas |
| 4416870 | Air Conditioning Clutch Rotor and Bearing Replacement | 7320610 | GMK Overseas |
| 4416890 | Air Conditioning Compressor Pulley Replacement | D4270 | GMNA |
| 4416890 | Air Conditioning Compressor Pulley Replacement | 7330500 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4416910 | Air Conditioning Clutch Coil Replacement | 7320810 | GMK Overseas |
| 4416930 | Air Conditioning Compressor Shaft Seal Replacement | | |
| 4417010 | Air Conditioning Compressor Oil Drain Plug Replacement | D4331 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D4020 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D4224 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D4260 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D4280 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D4290 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D4320 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D4330 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D4340 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D4360 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D4380 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D4420 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D4430 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D4440 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D4449 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D4701 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D9721 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D9727 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D9761 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D9762 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D9771 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | J7509 | GMNA |
| 4417120 | Air Conditioning Compressor Replacement | D000209 | Holden Australia |
| 4417120 | Air Conditioning Compressor Replacement | D301100 | Holden Australia |
| 4417120 | Air Conditioning Compressor Replacement | D4440 | Holden Australia |
| 4417120 | Air Conditioning Compressor Replacement | D444000 | Holden Australia |
| 4417120 | Air Conditioning Compressor Replacement | D301100 | Holden New Zealand |
| 4417120 | Air Conditioning Compressor Replacement | D4440 | Holden New Zealand |
| 4417120 | Air Conditioning Compressor Replacement | D444000 | Holden New Zealand |
| 4417120 | Air Conditioning Compressor Replacement | 7321100 | GMK Overseas |
| 4417120 | Air Conditioning Compressor Replacement | 732110A | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4417120 | Air Conditioning Compressor Replacement | 7322100 | GMK Overseas |
| 4417120 | Air Conditioning Compressor Replacement | 732210A | GMK Overseas |
| 4417120 | Air Conditioning Compressor Replacement | 732210B | GMK Overseas |
| 4417120 | Air Conditioning Compressor Replacement | 7322500 | GMK Overseas |
| 4417120 | Air Conditioning Compressor Replacement | 7330100 | GMK Overseas |
| 4417120 | Air Conditioning Compressor Replacement | 73411100 | GMK Overseas |
| 4417120 | Air Conditioning Compressor Replacement | 96897427 | GMK Overseas |
| 4417120 | Air Conditioning Compressor Replacement | A773030 | GMK Overseas |
| 4417169 | A/C System Analysis | D0005 | GMNA |
| 4417169 | A/C System Analysis | D1138 | GMNA |
| 4417169 | A/C System Analysis | D3000 | GMNA |
| 4417169 | A/C System Analysis | D4450 | GMNA |
| 4417169 | A/C System Analysis | D4700 | GMNA |
| 4417169 | A/C System Analysis | D4702 | GMNA |
| 4417169 | A/C System Analysis | D4704 | GMNA |
| 4417169 | A/C System Analysis | D9701 | GMNA |
| 4417169 | A/C System Analysis | D9702 | GMNA |
| 4417169 | A/C System Analysis | D9703 | GMNA |
| 4417169 | A/C System Analysis | D9706 | GMNA |
| 4417169 | A/C System Analysis | D9707 | GMNA |
| 4417169 | A/C System Analysis | D9708 | GMNA |
| 4417169 | A/C System Analysis | D9709 | GMNA |
| 4417169 | A/C System Analysis | D9715 | GMNA |
| 4417169 | A/C System Analysis | D9718 | GMNA |
| 4417169 | A/C System Analysis | D9723 | GMNA |
| 4417169 | A/C System Analysis | D9729 | GMNA |
| 4417169 | A/C System Analysis | D9730 | GMNA |
| 4417169 | A/C System Analysis | J7608 | GMNA |
| 4417169 | A/C System Analysis | J7609 | GMNA |
| 4417169 | A/C System Analysis | J7621 | GMNA |
| 4417169 | A/C System Analysis | J7701 | GMNA |
| 4417169 | A/C System Analysis | N8502 | GMNA |
| 4417169 | A/C System Analysis | R0110 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4417169 | A/C System Analysis | D000206 | Holden Australia |
| 4417169 | A/C System Analysis | D000339 | Holden Australia |
| 4417169 | A/C System Analysis | D300000 | Holden Australia |
| 4417169 | A/C System Analysis | D900002 | Holden Australia |
| 4417169 | A/C System Analysis | D900003 | Holden Australia |
| 4417169 | A/C System Analysis | D900004 | Holden Australia |
| 4417169 | A/C System Analysis | D900005 | Holden Australia |
| 4417169 | A/C System Analysis | D900011 | Holden Australia |
| 4417169 | A/C System Analysis | D900012 | Holden Australia |
| 4417169 | A/C System Analysis | D900013 | Holden Australia |
| 4417169 | A/C System Analysis | D900014 | Holden Australia |
| 4417169 | A/C System Analysis | D900015 | Holden Australia |
| 4417169 | A/C System Analysis | D900016 | Holden Australia |
| 4417169 | A/C System Analysis | D900017 | Holden Australia |
| 4417169 | A/C System Analysis | D900018 | Holden Australia |
| 4417169 | A/C System Analysis | D900019 | Holden Australia |
| 4417169 | A/C System Analysis | D900021 | Holden Australia |
| 4417169 | A/C System Analysis | D900022 | Holden Australia |
| 4417169 | A/C System Analysis | D900023 | Holden Australia |
| 4417169 | A/C System Analysis | D900024 | Holden Australia |
| 4417169 | A/C System Analysis | D900035 | Holden Australia |
| 4417169 | A/C System Analysis | D900036 | Holden Australia |
| 4417169 | A/C System Analysis | D900037 | Holden Australia |
| 4417169 | A/C System Analysis | D900038 | Holden Australia |
| 4417169 | A/C System Analysis | D900039 | Holden Australia |
| 4417169 | A/C System Analysis | D900040 | Holden Australia |
| 4417169 | A/C System Analysis | D900041 | Holden Australia |
| 4417169 | A/C System Analysis | D900043 | Holden Australia |
| 4417169 | A/C System Analysis | D900044 | Holden Australia |
| 4417169 | A/C System Analysis | D900046 | Holden Australia |
| 4417169 | A/C System Analysis | D900047 | Holden Australia |
| 4417169 | A/C System Analysis | D900048 | Holden Australia |
| 4417169 | A/C System Analysis | D900050 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4417169 | A/C System Analysis | D900051 | Holden Australia |
| 4417169 | A/C System Analysis | D900052 | Holden Australia |
| 4417169 | A/C System Analysis | D900057 | Holden Australia |
| 4417169 | A/C System Analysis | D900163 | Holden Australia |
| 4417169 | A/C System Analysis | D900185 | Holden Australia |
| 4417169 | A/C System Analysis | D900188 | Holden Australia |
| 4417169 | A/C System Analysis | D900193 | Holden Australia |
| 4417169 | A/C System Analysis | D900194 | Holden Australia |
| 4417169 | A/C System Analysis | D900195 | Holden Australia |
| 4417169 | A/C System Analysis | D900197 | Holden Australia |
| 4417169 | A/C System Analysis | D900233 | Holden Australia |
| 4417169 | A/C System Analysis | D900249 | Holden Australia |
| 4417169 | A/C System Analysis | D900283 | Holden Australia |
| 4417169 | A/C System Analysis | D900368 | Holden Australia |
| 4417169 | A/C System Analysis | D900408 | Holden Australia |
| 4417169 | A/C System Analysis | D900412 | Holden Australia |
| 4417169 | A/C System Analysis | D900530 | Holden Australia |
| 4417169 | A/C System Analysis | D900532 | Holden Australia |
| 4417169 | A/C System Analysis | D901530 | Holden Australia |
| 4417169 | A/C System Analysis | D901532 | Holden Australia |
| 4417169 | A/C System Analysis | D902930 | Holden Australia |
| 4417169 | A/C System Analysis | D903779 | Holden Australia |
| 4417169 | A/C System Analysis | D903843 | Holden Australia |
| 4417169 | A/C System Analysis | D904100 | Holden Australia |
| 4417169 | A/C System Analysis | D3000 | Holden New Zealand |
| 4417169 | A/C System Analysis | D300000 | Holden New Zealand |
| 4417169 | A/C System Analysis | D900015 | Holden New Zealand |
| 4417169 | A/C System Analysis | D900016 | Holden New Zealand |
| 4417169 | A/C System Analysis | D900017 | Holden New Zealand |
| 4417169 | A/C System Analysis | D900021 | Holden New Zealand |
| 4417169 | A/C System Analysis | D900039 | Holden New Zealand |
| 4417169 | A/C System Analysis | D900408 | Holden New Zealand |
| 4417169 | A/C System Analysis | D904100 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4417169 | A/C System Analysis | D904110 | Holden New Zealand |
| 4417169 | A/C System Analysis | D908600 | Holden New Zealand |
| 4417169 | A/C System Analysis | E904100 | Holden New Zealand |
| 4417169 | A/C System Analysis | 7130800 | GMK Overseas |
| 4417169 | A/C System Analysis | 7138000 | GMK Overseas |
| 4417169 | A/C System Analysis | 7352600 | GMK Overseas |
| 4417180 | Accessory DC Power Control Module Cooling Air Inlet Duct Replacement | 7510200 | GMK Overseas |
| 4417200 | Accessory DC Power Control Module Cooling Air Duct Replacement | | |
| 4417220 | Accessory DC Power Control Module Cooling Blower Replacement | D4455 | GMNA |
| 4417260 | Blower Motor Relay Replacement | N2822 | GMNA |
| 4417260 | Blower Motor Relay Replacement | 7133700 | GMK Overseas |
| 4417270 | Air Conditioning Compressor Relay Replacement | | |
| 4420030 | Mode Valve Lever Replacement | | |
| 4420050 | Heater and Air Conditioning Control Replacement | | |
| 4420060 | Auxiliary Heater and Air Conditioning Control Module Replacement | | |
| 4420080 | Auxiliary Heater and Air Conditioning Control Replacement | | |
| 4420110 | Heater and Air Conditioning Remote Control Replacement | D0371 | GMNA |
| 4420110 | Heater and Air Conditioning Remote Control Replacement | D0770 | GMNA |
| 4420110 | Heater and Air Conditioning Remote Control Replacement | D0780 | GMNA |
| 4420110 | Heater and Air Conditioning Remote Control Replacement | D0790 | GMNA |
| 4420110 | Heater and Air Conditioning Remote Control Replacement | D1837 | GMNA |
| 4420110 | Heater and Air Conditioning Remote Control Replacement | D1839 | GMNA |
| 4420110 | Heater and Air Conditioning Remote Control Replacement | D2226 | GMNA |
| 4420120 | Vent Valve Lever Replacement | 7136200 | GMK Overseas |
| 4420160 | Inside Air Temperature Sensor Aspirator Replacement | D0519 | GMNA |
| 4420160 | Inside Air Temperature Sensor Aspirator Replacement | 8220700 | GMK Domestic |
| 4420170 | Air Conditioning Refrigerant Temperature Sensor Replacement - Right Side | 7135100 | GMK Overseas |
| 4420170 | Air Conditioning Refrigerant Temperature Sensor Replacement - Right Side | 713510A | GMK Overseas |
| 4420170 | Air Conditioning Refrigerant Temperature Sensor Replacement - Right Side | 7135200 | GMK Overseas |
| 4420210 | Air Conditioning Refrigerant Temperature Sensor Replacement - Left Side | | |
| 4420220 | Duct Air Temperature Sensor Replacement | | |
| 4420260 | Duct Air Temperature Sensor Replacement - Upper Right Side | | |
| 4420280 | Duct Air Temperature Sensor Replacement - Lower Right Side | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4420300 | Duct Air Temperature Sensor Replacement - Upper Left Side | | |
| 4420320 | Duct Air Temperature Sensor Replacement - Lower Left Side | | |
| 4420340 | Duct Air Temperature Sensor Replacement - Upper | | |
| 4420360 | Duct Air Temperature Sensor Replacement - Lower | | |
| 4420400 | Heater and Blower and Air Conditioning Control Module Replacement | | |
| 4420410 | Blower Motor Control Module Replacement | D0890 | GMNA |
| 4420410 | Blower Motor Control Module Replacement | D0890 | Holden Australia |
| 4420420 | Air Conditioning Refrigerant Temperature Sensor Replacement | | |
| 4420430 | Evaporator Air Temperature Sensor Replacement | | |
| 4420460 | Automatic A/C Engine Coolant Temperature Sensor Replacement | | |
| 4420470 | Ambient Air Temperature Sensor Replacement | | |
| 4420490 | Sun Load Temperature Sensor Replacement | 7352100 | GMK Overseas |
| 4420500 | Ambient Air Quality Sensor Replacement | D1208 | GMNA |
| 4420500 | Ambient Air Quality Sensor Replacement | D1209 | GMNA |
| 4420500 | Ambient Air Quality Sensor Replacement | 8220900 | GMK Domestic |
| 4420520 | Outside Air Quality Sensor Replacement | 7352500 | GMK Overseas |
| 4420530 | Inside Air Temperature Sensor Replacement - Left Side Upper | 7134600 | GMK Overseas |
| 4420540 | Inside Air Temperature Sensor Replacement - Left Side Lower | | |
| 4420560 | Inside Air Temperature Sensor Replacement - Right Side Upper | | |
| 4420570 | Inside Air Temperature Sensor Replacement - Right Side Lower | | |
| 4420590 | Inside Air Temperature Sensor Replacement | 7352300 | GMK Overseas |
| 4420600 | Mode Valve Link Replacement | D0500 | GMNA |
| 4420600 | Mode Valve Link Replacement | D0520 | GMNA |
| 4420600 | Mode Valve Link Replacement | D0540 | GMNA |
| 4420600 | Mode Valve Link Replacement | D0550 | GMNA |
| 4420600 | Mode Valve Link Replacement | D0551 | GMNA |
| 4420600 | Mode Valve Link Replacement | D0552 | GMNA |
| 4420600 | Mode Valve Link Replacement | D1212 | GMNA |
| 4420600 | Mode Valve Link Replacement | N6033 | GMNA |
| 4420600 | Mode Valve Link Replacement | N317650 | Holden Australia |
| 4420600 | Mode Valve Link Replacement | N317650 | Holden New Zealand |
| 4420610 | Defroster Valve Actuator Replacement | | |
| 4420670 | Air Inlet Valve Actuator Replacement - Right Side | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4420690 | Air Inlet Valve Actuator Replacement - Left Side | | |
| 4420700 | Air Inlet Valve Actuator Replacement - Front | | |
| 4420740 | Air Inlet Valve Actuator Replacement - Rear | | |
| 4420780 | Temperature Valve Actuator Replacement | 7133200 | GMK Overseas |
| 4420790 | Air Inlet Valve Actuator Replacement | | |
| 4420810 | Temperature Valve Actuator Replacement - Right Side | | |
| 4420820 | Temperature Valve Actuator Replacement - Left Side | | |
| 4420840 | Inside Air Valve Actuator Replacement | | |
| 4420890 | Mode Valve Actuator Replacement - Left Side | | |
| 4420960 | Mode Valve Actuator Replacement - Console | | |
| 4420980 | Air Inlet Valve Lever Replacement - Front | | |
| 4420990 | Air Inlet Valve Lever Replacement - Middle | | |
| 4421000 | Air Inlet Valve Lever Replacement - Rear | | |
| 4421020 | Air Inlet Valve Actuator Gear Replacement | | |
| 4421030 | Auxiliary Temperature Valve Actuator Replacement | | |
| 4421050 | Auxiliary Mode Valve Actuator Replacement | | |
| 4421060 | Mode Control Cam Actuator Replacement | | |
| 4421080 | Mode Control Cam Replacement | 7135700 | GMK Overseas |
| 4421090 | Air Inlet Valve and Inside Air Valve Control Cam Replacement | | |
| 4421110 | Mode Valve Gear Replacement | 7135900 | GMK Overseas |
| 4421140 | Temperature Valve Replacement | | |
| 4421150 | Mode Valve Actuator Replacement | 7132900 | GMK Overseas |
| 4421170 | Mode Valve Actuator Gear Replacement | | |
| 4421190 | Air Conditioning Condenser Fan Relay Replacement | | |
| 4421230 | Inside Air Moisture and Windshield Temperature Sensor Replacement | N3574 | GMNA |
| 4421230 | Inside Air Moisture and Windshield Temperature Sensor Replacement | 6423700 | GMK Domestic |
| 4421230 | Inside Air Moisture and Windshield Temperature Sensor Replacement | 8220400 | GMK Domestic |
| 4421230 | Inside Air Moisture and Windshield Temperature Sensor Replacement | 8220800 | GMK Domestic |
| 4421230 | Inside Air Moisture and Windshield Temperature Sensor Replacement | 7133300 | GMK Overseas |
| 4421250 | Ambient Air Temperature Gauge Sensor Replacement | | |
| 4429959 | Customer Concern Not Duplicated (CCND) - HVAC | | |
| 4430010 | Heater and Air Conditioning Control Temperature Knob Replacement | D0100 | GMNA |
| 4430010 | Heater and Air Conditioning Control Temperature Knob Replacement | D010000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4430010 | Heater and Air Conditioning Control Temperature Knob Replacement | D333250 | Holden Australia |
| 4430010 | Heater and Air Conditioning Control Temperature Knob Replacement | D0100 | Holden New Zealand |
| 4430010 | Heater and Air Conditioning Control Temperature Knob Replacement | D010000 | Holden New Zealand |
| 4430010 | Heater and Air Conditioning Control Temperature Knob Replacement | D333250 | Holden New Zealand |
| 4430030 | Mode Valve Lever Replacement | | |
| 4430110 | Auxiliary Blower Switch Replacement | D0221 | GMNA |
| 4430110 | Auxiliary Blower Switch Replacement | D022000 | Holden New Zealand |
| 4430130 | Blower Motor Switch Replacement | D0222 | GMNA |
| 4430130 | Blower Motor Switch Replacement | 7323100 | GMK Overseas |
| 4430130 | Blower Motor Switch Replacement | 9322100 | GMK Overseas |
| 4430270 | Heater Control Replacement | D0360 | GMNA |
| 4430270 | Heater Control Replacement | D036000 | Holden Australia |
| 4430270 | Heater Control Replacement | D0360 | Holden New Zealand |
| 4430270 | Heater Control Replacement | D036000 | Holden New Zealand |
| 4430290 | Heater and Air Conditioning Control Bezel Replacement | D0361 | GMNA |
| 4430290 | Heater and Air Conditioning Control Bezel Replacement | 8214600 | GMK Domestic |
| 4430310 | Heater and Air Conditioning Control Replacement | D0190 | GMNA |
| 4430310 | Heater and Air Conditioning Control Replacement | D0340 | GMNA |
| 4430310 | Heater and Air Conditioning Control Replacement | D0362 | GMNA |
| 4430310 | Heater and Air Conditioning Control Replacement | D0365 | GMNA |
| 4430310 | Heater and Air Conditioning Control Replacement | D0370 | GMNA |
| 4430310 | Heater and Air Conditioning Control Replacement | D0850 | GMNA |
| 4430310 | Heater and Air Conditioning Control Replacement | D0362 | Holden Australia |
| 4430310 | Heater and Air Conditioning Control Replacement | D036200 | Holden Australia |
| 4430310 | Heater and Air Conditioning Control Replacement | D110100 | Holden Australia |
| 4430310 | Heater and Air Conditioning Control Replacement | D333100 | Holden Australia |
| 4430310 | Heater and Air Conditioning Control Replacement | D036200 | Holden New Zealand |
| 4430310 | Heater and Air Conditioning Control Replacement | D110100 | Holden New Zealand |
| 4430310 | Heater and Air Conditioning Control Replacement | D333000 | Holden New Zealand |
| 4430310 | Heater and Air Conditioning Control Replacement | D333100 | Holden New Zealand |
| 4430310 | Heater and Air Conditioning Control Replacement | D333100A1 | Holden New Zealand |
| 4430330 | Auxiliary Heater and Air Conditioning Control Module Replacement | D0363 | GMNA |
| 4430330 | Auxiliary Heater and Air Conditioning Control Module Replacement | D0901 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4430350 | Auxiliary Heater and Air Conditioning Control Replacement - Front | D0366 | GMNA |
| 4430370 | Auxiliary Heater and Air Conditioning Control Replacement - Rear | D0367 | GMNA |
| 4430390 | Auxiliary Heater and Air Conditioning Control Replacement | D0368 | GMNA |
| 4430400 | Heater and Air Conditioning Remote Control Replacement | | |
| 4430410 | Vent Valve Lever Replacement | | |
| 4430470 | Temperature Control Cable Replacement | D0400 | GMNA |
| 4430470 | Temperature Control Cable Replacement | D0402 | GMNA |
| 4430470 | Temperature Control Cable Replacement | D0437 | GMNA |
| 4430470 | Temperature Control Cable Replacement | D0447 | GMNA |
| 4430470 | Temperature Control Cable Replacement | D112100 | Holden Australia |
| 4430470 | Temperature Control Cable Replacement | P101100 | Holden Australia |
| 4430470 | Temperature Control Cable Replacement | D112100 | Holden New Zealand |
| 4430470 | Temperature Control Cable Replacement | 7350500 | GMK Overseas |
| 4430490 | Inside Air Recirculating Control Cable Replacement | D0430 | GMNA |
| 4430490 | Inside Air Recirculating Control Cable Replacement | D0436 | GMNA |
| 4430490 | Inside Air Recirculating Control Cable Replacement | 6310900 | GMK Domestic |
| 4430490 | Inside Air Recirculating Control Cable Replacement | D000342 | Holden Australia |
| 4430490 | Inside Air Recirculating Control Cable Replacement | D115500 | Holden Australia |
| 4430490 | Inside Air Recirculating Control Cable Replacement | D115500 | Holden New Zealand |
| 4430490 | Inside Air Recirculating Control Cable Replacement | 7350800 | GMK Overseas |
| 4430660 | Air Conditioning Refrigerant Temperature Sensor Replacement - Right Side | | |
| 4430700 | Inside Air Temperature Sensor Replacement - Left Side Lower | D0566 | GMNA |
| 4430790 | Heater and Blower and Air Conditioning Control Module Replacement | D0889 | GMNA |
| 4430910 | Air Conditioning Refrigerant Temperature Sensor Replacement | D1125 | GMNA |
| 4430910 | Air Conditioning Refrigerant Temperature Sensor Replacement | D1126 | GMNA |
| 4430910 | Air Conditioning Refrigerant Temperature Sensor Replacement | D1205 | GMNA |
| 4430910 | Air Conditioning Refrigerant Temperature Sensor Replacement | D1206 | GMNA |
| 4430930 | Evaporator Air Temperature Sensor Replacement | D1127 | GMNA |
| 4430930 | Evaporator Air Temperature Sensor Replacement | D000393 | Holden Australia |
| 4430930 | Evaporator Air Temperature Sensor Replacement | D114000 | Holden Australia |
| 4430930 | Evaporator Air Temperature Sensor Replacement | D332700 | Holden Australia |
| 4430930 | Evaporator Air Temperature Sensor Replacement | D332800 | Holden Australia |
| 4430930 | Evaporator Air Temperature Sensor Replacement | D000393 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4430930 | Evaporator Air Temperature Sensor Replacement | D114000 | Holden New Zealand |
| 4430930 | Evaporator Air Temperature Sensor Replacement | D332700 | Holden New Zealand |
| 4430950 | Ambient Air Temperature Sensor Replacement | D1200 | GMNA |
| 4430950 | Ambient Air Temperature Sensor Replacement | D1210 | GMNA |
| 4430950 | Ambient Air Temperature Sensor Replacement | D1211 | GMNA |
| 4430950 | Ambient Air Temperature Sensor Replacement | D9741 | GMNA |
| 4430950 | Ambient Air Temperature Sensor Replacement | N4630 | GMNA |
| 4430950 | Ambient Air Temperature Sensor Replacement | N5215 | GMNA |
| 4430950 | Ambient Air Temperature Sensor Replacement | N9509 | GMNA |
| 4430950 | Ambient Air Temperature Sensor Replacement | N317600 | Holden Australia |
| 4430950 | Ambient Air Temperature Sensor Replacement | N317600 | Holden New Zealand |
| 4430950 | Ambient Air Temperature Sensor Replacement | 7351700 | GMK Overseas |
| 4430970 | Sun Load Temperature Sensor Replacement | D1202 | GMNA |
| 4430970 | Sun Load Temperature Sensor Replacement | D1203 | GMNA |
| 4430970 | Sun Load Temperature Sensor Replacement | N0354 | GMNA |
| 4430970 | Sun Load Temperature Sensor Replacement | N0355 | GMNA |
| 4430970 | Sun Load Temperature Sensor Replacement | N0362 | GMNA |
| 4430970 | Sun Load Temperature Sensor Replacement | N0365 | GMNA |
| 4430970 | Sun Load Temperature Sensor Replacement | N0366 | GMNA |
| 4430970 | Sun Load Temperature Sensor Replacement | R4230 | GMNA |
| 4430970 | Sun Load Temperature Sensor Replacement | N0355 | Holden Australia |
| 4430970 | Sun Load Temperature Sensor Replacement | N317700 | Holden Australia |
| 4430970 | Sun Load Temperature Sensor Replacement | N317700 | Holden New Zealand |
| 4431020 | Heater and Air Conditioning Control Cam Replacement | D1496 | GMNA |
| 4431020 | Heater and Air Conditioning Control Cam Replacement | D1825 | GMNA |
| 4431020 | Heater and Air Conditioning Control Cam Replacement | D1826 | GMNA |
| 4431020 | Heater and Air Conditioning Control Cam Replacement | D1831 | GMNA |
| 4431020 | Heater and Air Conditioning Control Cam Replacement | D1832 | GMNA |
| 4431020 | Heater and Air Conditioning Control Cam Replacement | D1833 | GMNA |
| 4431020 | Heater and Air Conditioning Control Cam Replacement | D1850 | GMNA |
| 4431020 | Heater and Air Conditioning Control Cam Replacement | D107100 | Holden Australia |
| 4431020 | Heater and Air Conditioning Control Cam Replacement | 7135300 | GMK Overseas |
| 4431040 | Heater and Air Conditioning Control Vacuum Tank Replacement | D1740 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4431040 | Heater and Air Conditioning Control Vacuum Tank Replacement | 7342700 | GMK Overseas |
| 4431040 | Heater and Air Conditioning Control Vacuum Tank Replacement | 7342800 | GMK Overseas |
| 4431040 | Heater and Air Conditioning Control Vacuum Tank Replacement | 7342900 | GMK Overseas |
| 4431060 | Vacuum Pump Assembly Replacement | D1741 | GMNA |
| 4431060 | Vacuum Pump Assembly Replacement | D2875 | GMNA |
| 4431060 | Vacuum Pump Assembly Replacement | J5527 | GMNA |
| 4431080 | Temperature Valve Link Replacement | 7136300 | GMK Overseas |
| 4431100 | Air Inlet Valve Link Replacement | | |
| 4431120 | Mode Valve Link Replacement | | |
| 4431140 | Defroster Valve Actuator Replacement | | |
| 4431150 | Air Inlet Valve Actuator Replacement - Left Side | | |
| 4431250 | Air Inlet Valve Actuator Replacement - Front | D1791 | GMNA |
| 4431400 | Temperature Valve Actuator Replacement | D1809 | GMNA |
| 4431400 | Temperature Valve Actuator Replacement | D1811 | GMNA |
| 4431400 | Temperature Valve Actuator Replacement | D1812 | GMNA |
| 4431400 | Temperature Valve Actuator Replacement | D1815 | GMNA |
| 4431400 | Temperature Valve Actuator Replacement | D1836 | GMNA |
| 4431400 | Temperature Valve Actuator Replacement | D9752 | GMNA |
| 4431400 | Temperature Valve Actuator Replacement | D9756 | GMNA |
| 4431400 | Temperature Valve Actuator Replacement | D021500 | Holden Australia |
| 4431400 | Temperature Valve Actuator Replacement | D1811 | Holden Australia |
| 4431400 | Temperature Valve Actuator Replacement | D908300 | Holden Australia |
| 4431400 | Temperature Valve Actuator Replacement | D908510 | Holden Australia |
| 4431400 | Temperature Valve Actuator Replacement | D021500 | Holden New Zealand |
| 4431400 | Temperature Valve Actuator Replacement | D107100 | Holden New Zealand |
| 4431400 | Temperature Valve Actuator Replacement | D181100 | Holden New Zealand |
| 4431400 | Temperature Valve Actuator Replacement | D908300 | Holden New Zealand |
| 4431420 | Air Inlet Valve Actuator Replacement | D1788 | GMNA |
| 4431420 | Air Inlet Valve Actuator Replacement | D1789 | GMNA |
| 4431420 | Air Inlet Valve Actuator Replacement | D1810 | GMNA |
| 4431420 | Air Inlet Valve Actuator Replacement | D1814 | GMNA |
| 4431420 | Air Inlet Valve Actuator Replacement | D1834 | GMNA |
| 4431420 | Air Inlet Valve Actuator Replacement | D1885 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4431420 | Air Inlet Valve Actuator Replacement | D000215 | Holden Australia |
| 4431420 | Air Inlet Valve Actuator Replacement | D021120 | Holden Australia |
| 4431420 | Air Inlet Valve Actuator Replacement | D1810 | Holden Australia |
| 4431420 | Air Inlet Valve Actuator Replacement | D908420 | Holden Australia |
| 4431420 | Air Inlet Valve Actuator Replacement | D021120 | Holden New Zealand |
| 4431420 | Air Inlet Valve Actuator Replacement | D908420 | Holden New Zealand |
| 4431440 | Temperature Valve Actuator Replacement - Right Side | | |
| 4431460 | Temperature Valve Actuator Replacement - Left Side | | |
| 4431510 | Inside Air Valve Actuator Replacement | | |
| 4431590 | Mode Valve Actuator Replacement - Left Side | | |
| 4431610 | Mode Valve Actuator Replacement | D1780 | GMNA |
| 4431610 | Mode Valve Actuator Replacement | D1784 | GMNA |
| 4431610 | Mode Valve Actuator Replacement | D1787 | GMNA |
| 4431610 | Mode Valve Actuator Replacement | D1800 | GMNA |
| 4431610 | Mode Valve Actuator Replacement | D1807 | GMNA |
| 4431610 | Mode Valve Actuator Replacement | D1808 | GMNA |
| 4431610 | Mode Valve Actuator Replacement | D1817 | GMNA |
| 4431610 | Mode Valve Actuator Replacement | D1820 | GMNA |
| 4431610 | Mode Valve Actuator Replacement | D1823 | GMNA |
| 4431610 | Mode Valve Actuator Replacement | D1824 | GMNA |
| 4431610 | Mode Valve Actuator Replacement | D1829 | GMNA |
| 4431610 | Mode Valve Actuator Replacement | D1830 | GMNA |
| 4431610 | Mode Valve Actuator Replacement | D1842 | GMNA |
| 4431610 | Mode Valve Actuator Replacement | D1843 | GMNA |
| 4431610 | Mode Valve Actuator Replacement | D4705 | GMNA |
| 4431610 | Mode Valve Actuator Replacement | D9773 | GMNA |
| 4431610 | Mode Valve Actuator Replacement | D021420 | Holden Australia |
| 4431610 | Mode Valve Actuator Replacement | D021430 | Holden Australia |
| 4431610 | Mode Valve Actuator Replacement | D021440 | Holden Australia |
| 4431610 | Mode Valve Actuator Replacement | D021450 | Holden Australia |
| 4431610 | Mode Valve Actuator Replacement | D021460 | Holden Australia |
| 4431610 | Mode Valve Actuator Replacement | D908520 | Holden Australia |
| 4431610 | Mode Valve Actuator Replacement | D021430 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 4431610 | Mode Valve Actuator Replacement | D021440 | Holden New Zealand |
| 4431610 | Mode Valve Actuator Replacement | D021450 | Holden New Zealand |
| 4431610 | Mode Valve Actuator Replacement | D021460 | Holden New Zealand |
| 4431610 | Mode Valve Actuator Replacement | D900233 | Holden New Zealand |
| 4431610 | Mode Valve Actuator Replacement | D908510 | Holden New Zealand |
| 4431610 | Mode Valve Actuator Replacement | D908520 | Holden New Zealand |
| 4431630 | Mode Valve Actuator Gear Replacement | | |
| 4431650 | Air Inlet Valve Actuator Gear Replacement | | |
| 4431670 | Auxiliary Temperature Valve Actuator Replacement | D1813 | GMNA |
| 4431670 | Auxiliary Temperature Valve Actuator Replacement | D1818 | GMNA |
| 4431670 | Auxiliary Temperature Valve Actuator Replacement | D1821 | GMNA |
| 4431670 | Auxiliary Temperature Valve Actuator Replacement | D1827 | GMNA |
| 4431670 | Auxiliary Temperature Valve Actuator Replacement | D1876 | GMNA |
| 4431690 | Auxiliary Mode Valve Actuator Replacement | D1822 | GMNA |
| 4431690 | Auxiliary Mode Valve Actuator Replacement | D1828 | GMNA |
| 4431710 | Mode Control Cam Actuator Replacement | | |
| 4431730 | Mode Control Cam Replacement | | |
| 4431770 | Mode Valve Gear Replacement | | |
| 4431850 | Mode Valve Actuator Replacement - Upper | | |
| 4431870 | Mode Valve Actuator Replacement - Lower | | |
| 4431890 | Air Inlet Valve Lever Replacement - Middle | | |
| 4431910 | Air Inlet Valve Lever Replacement - Rear | | |
| 4431920 | Air Inlet Valve Lever Replacement | | |
| 4432030 | Air Inlet Valve Replacement | | |
| 4432240 | Air Conditioning Condenser Fan Relay Replacement | N2912 | GMNA |
| 4439959 | Customer Concern Not Duplicated (CCND) - HVAC | D9995 | GMNA |
| 4439959 | Customer Concern Not Duplicated (CCND) - HVAC | 1779920 | GMK Domestic |
| 4439959 | Customer Concern Not Duplicated (CCND) - HVAC | 6002120 | GMK Domestic |
| 5010010 | Drive Motor Generator Power Inverter Module Cover Replacement | N5768 | GMNA |
| 5010140 | Drive Motor Generator Control Module Sight Shield Replacement | N5869 | GMNA |
| 5010160 | Drive Motor Generator Control Module Assembly Replacement | N5870 | GMNA |
| 5010180 | Starter Generator Replacement | N5873 | GMNA |
| 5010200 | Generator Control Module 3-Phase Cable Assembly Replacement | N5874 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5010220 | Accessory DC Power Control Module Replacement | N5876 | GMNA |
| 5010240 | Drive Motor Generator Power Inverter Module Replacement | N5877 | GMNA |
| 5010260 | High Voltage Circuit Impact Detection Sensor Replacement | N5778 | GMNA |
| 5010260 | High Voltage Circuit Impact Detection Sensor Replacement | N5878 | GMNA |
| 5019989 | Customer Concern Not Duplicated (CCND) - Hybrid Electronics and Charging | N9998 | GMNA |
| 5020060 | Generator Battery Vent Fan Relay Replacement | N5827 | GMNA |
| 5020080 | Generator Battery Vent Fan Replacement | N5828 | GMNA |
| 5020100 | Auxiliary Radiator Inlet Hose Replacement | N5847 | GMNA |
| 5020100 | Auxiliary Radiator Inlet Hose Replacement | 1920100 | GMK Domestic |
| 5020120 | Auxiliary Radiator Outlet Hose Replacement | 1921300 | GMK Domestic |
| 5020120 | Auxiliary Radiator Outlet Hose Replacement | 2221000 | GMK Domestic |
| 5020140 | Auxiliary Radiator Replacement | 1920200 | GMK Domestic |
| 5020190 | Generator Control Module Coolant Radiator Replacement | J4661 | GMNA |
| 5020190 | Generator Control Module Coolant Radiator Replacement | J4662 | GMNA |
| 5020190 | Generator Control Module Coolant Radiator Replacement | J4663 | GMNA |
| 5020190 | Generator Control Module Coolant Radiator Replacement | J4665 | GMNA |
| 5020190 | Generator Control Module Coolant Radiator Replacement | N5853 | GMNA |
| 5020210 | Generator Control Module Coolant Pump Replacement | N5854 | GMNA |
| 5020230 | Generator Control Module Coolant Pump Hose Replacement | N5855 | GMNA |
| 5020250 | Generator Control Module Coolant Hose Replacement | J3304 | GMNA |
| 5020250 | Generator Control Module Coolant Hose Replacement | N5856 | GMNA |
| 5020250 | Generator Control Module Coolant Hose Replacement | N5918 | GMNA |
| 5020270 | Generator Control Module Coolant Outlet Hose Replacement | | |
| 5020310 | Coolant Temperature Sensor Replacement | N5861 | GMNA |
| 5020310 | Coolant Temperature Sensor Replacement | N5860 | Holden New Zealand |
| 5020330 | Heater Coolant Pump Hose Replacement | | |
| 5020340 | Underbody Air Deflector Replacement | | |
| 5020370 | Drive Motor Generator Control Module Coolant Pump Hose Replacement | N5857 | GMNA |
| 5020370 | Drive Motor Generator Control Module Coolant Pump Hose Replacement | N5911 | GMNA |
| 5020390 | Drive Motor Battery Coolant Pump Inlet Hose Replacement | N5912 | GMNA |
| 5020410 | Drive Motor Battery Coolant Inlet Hose Replacement | N5914 | GMNA |
| 5020410 | Drive Motor Battery Coolant Inlet Hose Replacement | 1630900 | GMK Overseas |
| 5020450 | Drive Motor Battery Coolant Cooler Replacement | N5916 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5020490 | Generator Control Module Coolant Inlet Hose Replacement | | |
| 5020510 | Generator Control Module Coolant Radiator Hose Replacement | | |
| 5020530 | Drive Motor Generator Control Module Cooling Outlet Hose Replacement | 1920500 | GMK Domestic |
| 5020530 | Drive Motor Generator Control Module Cooling Outlet Hose Replacement | 2216200 | GMK Domestic |
| 5020550 | Generator Control Module Coolant Tank Hose Replacement | N5921 | GMNA |
| 5020570 | Drive Motor Power Inverter Module Cooling Inlet Hose Replacement | N5922 | GMNA |
| 5020590 | Drive Motor Battery Radiator Surge Tank Replacement | N5923 | GMNA |
| 5020610 | Drive Motor Battery Coolant Cooler Outlet Hose Replacement | N5924 | GMNA |
| 5020630 | Drive Motor Battery Coolant Flow Control Valve Replacement | N5925 | GMNA |
| 5020650 | Drive Motor Battery Radiator Inlet Hose Replacement | N5926 | GMNA |
| 5020670 | Drive Motor Battery Radiator Outlet Hose Replacement | | |
| 5020690 | Drive Motor Battery Coolant Cooler Inlet Hose Assembly Replacement | N5928 | GMNA |
| 5020710 | Drive Motor Battery Coolant Cooler Inlet Hose Replacement | N5929 | GMNA |
| 5020730 | Drive Motor Battery Coolant Radiator Replacement | N5930 | GMNA |
| 5020750 | Drive Motor Generator Control Module Radiator Outlet Hose Replacement | N5931 | GMNA |
| 5020770 | Drive Motor Battery Coolant Outlet Hose Replacement | N5932 | GMNA |
| 5020770 | Drive Motor Battery Coolant Outlet Hose Replacement | 1634700 | GMK Overseas |
| 5020790 | Drive Motor Battery Coolant Filter Replacement | N5933 | GMNA |
| 5020810 | Drive Motor Battery Coolant/Air Separator Replacement | 1920700 | GMK Domestic |
| 5020810 | Drive Motor Battery Coolant/Air Separator Replacement | 2216500 | GMK Domestic |
| 5020830 | Radiator Grille Screen Replacement | N5935 | GMNA |
| 5020830 | Radiator Grille Screen Replacement | 1634300 | GMK Overseas |
| 5020850 | Drive Motor Battery Coolant Pump Replacement | N5936 | GMNA |
| 5020850 | Drive Motor Battery Coolant Pump Replacement | 1920300 | GMK Domestic |
| 5020870 | Drive Motor Battery Cooling Blower Replacement | N5937 | GMNA |
| 5020870 | Drive Motor Battery Cooling Blower Replacement | 1920800 | GMK Domestic |
| 5020870 | Drive Motor Battery Cooling Blower Replacement | 2220100 | GMK Domestic |
| 5020890 | Drive Motor Battery Cooling Blower Outlet Duct Replacement | N5938 | GMNA |
| 5020890 | Drive Motor Battery Cooling Blower Outlet Duct Replacement | N5946 | GMNA |
| 5020890 | Drive Motor Battery Cooling Blower Outlet Duct Replacement | 1920900 | GMK Domestic |
| 5020910 | Drive Motor Battery Cooling Air Outlet Duct Replacement | 1921100 | GMK Domestic |
| 5020930 | Drive Motor Battery Cooling Air Inlet Upper Duct Replacement | 1921200 | GMK Domestic |
| 5020950 | Generator Control Module Cooling Air Outlet Duct Replacement | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5021100 | Cell Battery Cooling Manifold Inlet Hose Replacement | | |
| 5021200 | Cell Battery Cooling Manifold Outlet Hose Replacement | | |
| 5021300 | Cell Battery Cooling Plate Hose Replacement | | |
| 5021400 | Drive Motor Battery Coolant Level Sensor Replacement | | |
| 5021500 | Battery Heater Replacement | | |
| 5030010 | Battery Positive Cable Extension Cable Replacement | N5755 | GMNA |
| 5030030 | Drive Motor Battery Cover Replacement | N5769 | GMNA |
| 5030050 | Drive Motor Battery Negative Relay Cable Replacement | | |
| 5030070 | Drive Motor Battery Positive Relay Cable Replacement | N5771 | GMNA |
| 5030090 | Drive Motor Battery Positive and Negative Cable Replacement | N5772 | GMNA |
| 5030170 | Battery Vent Hose Replacement | | |
| 5030190 | 36-Volt Battery Internal Cable Replacement | N5780 | GMNA |
| 5030210 | Drive Motor Battery Wire Junction Block Relay Replacement | N5781 | GMNA |
| 5030230 | 300-Volt Battery Positive and Negative Cable Replacement | N5782 | GMNA |
| 5030250 | Auxiliary Battery Wiring Harness Replacement | N5783 | GMNA |
| 5030270 | Battery Cable Replacement | R083052 | Holden New Zealand |
| 5030270 | Battery Cable Replacement | 9110100 | GMK Overseas |
| 5030290 | Cell Battery Replacement | | |
| 5030310 | Drive Motor Battery High Voltage Manual Disconnect Lever Replacement | N5786 | GMNA |
| 5030330 | Drive Motor Battery Interface Control Module Replacement | N5787 | GMNA |
| 5030350 | Battery Energy Control Module Cover Replacement | N5788 | GMNA |
| 5030370 | Battery Terminal Cover Replacement | N5789 | GMNA |
| 5030390 | Drive Motor Battery Cable Terminal Extension Cover Replacement | N5790 | GMNA |
| 5030530 | Drive Motor Battery 300-Volt Positive and Negative Cable Replacement | N5795 | GMNA |
| 5030550 | 36-Volt Battery Positive Cable Replacement | N5796 | GMNA |
| 5030570 | 36-Volt Battery Negative Cable Replacement | N5797 | GMNA |
| 5030590 | Drive Motor Battery Cable Terminal Extension Replacement | N5798 | GMNA |
| 5030610 | Battery Tray Replacement | N5799 | GMNA |
| 5030640 | 175 Amp Mega Fuse Replacement | | |
| 5030650 | Battery Auxiliary Tray Replacement | N5802 | GMNA |
| 5030670 | Generator Battery Fuse Replacement | N5803 | GMNA |
| 5030690 | Generator Battery Cover Access Door Replacement | | |
| 5030710 | Drive Motor Battery Current Sensor Replacement | N5805 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5030710 | Drive Motor Battery Current Sensor Replacement | 1652500 | GMK Overseas |
| 5030760 | Drive Motor Battery Inverter Current Limit Resistor Replacement | N5807 | GMNA |
| 5030780 | Generator Battery Cover Replacement | N5809 | GMNA |
| 5030800 | Drive Motor Battery Control Module Harness Replacement | | |
| 5030840 | Generator Battery Carrier Replacement | N5813 | GMNA |
| 5030860 | Drive Motor Power Inverter Current Limit Relay Replacement | N5814 | GMNA |
| 5030880 | Drive Motor Battery Positive and Negative High Voltage Contactor Relay Replacement | N5815 | GMNA |
| 5031010 | Battery Energy Control Module Replacement | N5821 | GMNA |
| 5031010 | Battery Energy Control Module Replacement | 1901100 | GMK Domestic |
| 5031010 | Battery Energy Control Module Replacement | 2213300 | GMK Domestic |
| 5031030 | Drive Motor Battery Replacement and Shipping Preparation | N5823 | GMNA |
| 5031030 | Drive Motor Battery Replacement and Shipping Preparation | 1652100 | GMK Overseas |
| 5031050 | Generator Battery Replacement | N5824 | GMNA |
| 5031050 | Generator Battery Replacement | 1901200 | GMK Domestic |
| 5031070 | Generator Battery Temperature Sensor Replacement | N5826 | GMNA |
| 5031090 | Drive Motor Battery High Voltage Manual Disconnect Knob Housing Replacement | N5829 | GMNA |
| 5031110 | Drive Motor Battery Sensor Module Wiring Harness Replacement | N5830 | GMNA |
| 5031160 | Generator Battery Temperature Sensor Wiring Harness Replacement | N5832 | GMNA |
| 5031180 | Battery Cover Seal Replacement | N5833 | GMNA |
| 5031200 | Drive Motor Generator Battery Cable Replacement | N5834 | GMNA |
| 5031200 | Drive Motor Generator Battery Cable Replacement | 1901300 | GMK Domestic |
| 5031200 | Drive Motor Generator Battery Cable Replacement | 2213900 | GMK Domestic |
| 5031220 | Generator Control Module Cable Cover Replacement | N5835 | GMNA |
| 5031240 | Drive Motor Generator Battery High Voltage Manual Disconnect Connector Replacement | N5836 | GMNA |
| 5031260 | Battery Energy Control Module Wiring Junction Block Replacement | N5838 | GMNA |
| 5031280 | Generator Battery Control Wiring Harness Replacement | N5839 | GMNA |
| 5031280 | Generator Battery Control Wiring Harness Replacement | 1901400 | GMK Domestic |
| 5031280 | Generator Battery Control Wiring Harness Replacement | 2214000 | GMK Domestic |
| 5031300 | Battery Energy Control Module Wiring Harness Replacement | N5840 | GMNA |
| 5031320 | Battery Charger and 14 V Power Module Maxi 20 A Fuse Replacement | N5843 | GMNA |
| 5031320 | Battery Charger and 14 V Power Module Maxi 20 A Fuse Replacement | 1652300 | GMK Overseas |
| 5031400 | Generator Control and Battery Module Replacement and Shipping Preparation | N5866 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5031440 | Generator Control Module Replacement | N5875 | GMNA |
| 5031460 | Generator Control Module Cover Replacement | N5879 | GMNA |
| 5031490 | Underbody Air Deflector Replacement | | |
| 5040010 | Charge Port Door Ajar Indicator Switch Replacement | N5300 | GMNA |
| 5040030 | Charge Port Door Actuator Cable Replacement | N5301 | GMNA |
| 5040050 | Drive Motor Battery Charger Receptacle Replacement | N5302 | GMNA |
| 5040070 | Charge Port Housing Bezel Replacement | N5303 | GMNA |
| 5040090 | Charge Port Door Replacement | N5304 | GMNA |
| 5040110 | Charge Port Housing Replacement | N5305 | GMNA |
| 5040130 | Charge Port Door Actuator Replacement | N5306 | GMNA |
| 5040150 | Charge Port Door Hinge Bezel Replacement | N5307 | GMNA |
| 5040170 | Charge Port Door Hinge Seal Replacement | N5308 | GMNA |
| 5040190 | Charge Port Door Actuator Seal Replacement | N5309 | GMNA |
| 5040210 | Drive Motor Battery Charger Replacement | N5310 | GMNA |
| 5040230 | Drive Motor Battery Charger Cable Replacement | N5311 | GMNA |
| 5040230 | Drive Motor Battery Charger Cable Replacement | N9675 | GMNA |
| 5410010 | Data Link Resistor Replacement | N000559 | Holden Australia |
| 5410010 | Data Link Resistor Replacement | N000559 | Holden New Zealand |
| 5410030 | Body Control Module Replacement | N4800 | GMNA |
| 5410030 | Body Control Module Replacement | N4850 | GMNA |
| 5410030 | Body Control Module Replacement | N4865 | GMNA |
| 5410030 | Body Control Module Replacement | N4866 | GMNA |
| 5410030 | Body Control Module Replacement | N9564 | GMNA |
| 5410030 | Body Control Module Replacement | 5710900 | GMK Domestic |
| 5410030 | Body Control Module Replacement | 5712500 | GMK Domestic |
| 5410030 | Body Control Module Replacement | N000336 | Holden Australia |
| 5410030 | Body Control Module Replacement | N000441 | Holden Australia |
| 5410030 | Body Control Module Replacement | N4800 | Holden Australia |
| 5410030 | Body Control Module Replacement | N506600 | Holden Australia |
| 5410030 | Body Control Module Replacement | N000336 | Holden New Zealand |
| 5410030 | Body Control Module Replacement | N000441 | Holden New Zealand |
| 5410030 | Body Control Module Replacement | N000719 | Holden New Zealand |
| 5410030 | Body Control Module Replacement | N506600 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5410030 | Body Control Module Replacement | 9292500 | GMK Overseas |
| 5410030 | Body Control Module Replacement | 9292600 | GMK Overseas |
| 5410030 | Body Control Module Replacement | 9292800 | GMK Overseas |
| 5410030 | Body Control Module Replacement | 9293600 | GMK Overseas |
| 5410080 | Auxiliary Body Control Module Replacement | N4804 | GMNA |
| 5410120 | Serial Data Gateway Module Replacement | N4806 | GMNA |
| 5410120 | Serial Data Gateway Module Replacement | 5822800 | GMK Domestic |
| 5410140 | Hybrid Powertrain Control Module 2 Replacement | N4812 | GMNA |
| 5410160 | Door Lock, Theft Deterrent, and Power Window Control Module Replacement | | |
| 5410210 | Door Lock and Power Window Control Module Replacement | N4851 | GMNA |
| 5410320 | Rear Integration Body Control Module Replacement | N4859 | GMNA |
| 5420080 | 12-Volt Accessory Power Receptacle Replacement | N0145 | GMNA |
| 5420080 | 12-Volt Accessory Power Receptacle Replacement | N0145 | Holden Australia |
| 5420080 | 12-Volt Accessory Power Receptacle Replacement | 9341700 | GMK Overseas |
| 5420100 | 120-Volt Accessory Power Receptacle Replacement | N0146 | GMNA |
| 5420100 | 120-Volt Accessory Power Receptacle Replacement | R500500 | Holden Australia |
| 5420120 | Accessory Power Receptacle Replacement | J4670 | GMNA |
| 5420120 | Accessory Power Receptacle Replacement | J4671 | GMNA |
| 5420120 | Accessory Power Receptacle Replacement | N0149 | GMNA |
| 5420120 | Accessory Power Receptacle Replacement | 5423300 | GMK Domestic |
| 5420120 | Accessory Power Receptacle Replacement | 5813100 | GMK Domestic |
| 5420120 | Accessory Power Receptacle Replacement | N311800 | Holden Australia |
| 5420120 | Accessory Power Receptacle Replacement | N311800 | Holden New Zealand |
| 5420120 | Accessory Power Receptacle Replacement | 9341900 | GMK Overseas |
| 5420140 | Accessory Power Receptacle Retainer Replacement | N0151 | GMNA |
| 5420160 | Front Floor Console Accessory Power Rear Receptacle Replacement | N0152 | GMNA |
| 5420160 | Front Floor Console Accessory Power Rear Receptacle Replacement | N5120 | GMNA |
| 5420180 | Cigarette Lighter Replacement | N4000 | GMNA |
| 5420180 | Cigarette Lighter Replacement | 6423900 | GMK Domestic |
| 5420180 | Cigarette Lighter Replacement | N311600 | Holden Australia |
| 5420180 | Cigarette Lighter Replacement | N311600 | Holden New Zealand |
| 5420180 | Cigarette Lighter Replacement | 9340600 | GMK Overseas |
| 5420200 | Cigarette Lighter Receptacle Replacement | N0924 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5420200 | Cigarette Lighter Receptacle Replacement | N0925 | GMNA |
| 5420200 | Cigarette Lighter Receptacle Replacement | N4010 | GMNA |
| 5420200 | Cigarette Lighter Receptacle Replacement | N311700 | Holden Australia |
| 5420200 | Cigarette Lighter Receptacle Replacement | N311500 | Holden New Zealand |
| 5420200 | Cigarette Lighter Receptacle Replacement | N311700 | Holden New Zealand |
| 5420200 | Cigarette Lighter Receptacle Replacement | N4010 | Holden New Zealand |
| 5420200 | Cigarette Lighter Receptacle Replacement | N401000 | Holden New Zealand |
| 5420200 | Cigarette Lighter Receptacle Replacement | 9340700 | GMK Overseas |
| 5420200 | Cigarette Lighter Receptacle Replacement | 9340900 | GMK Overseas |
| 5420220 | Accessory AC and DC Power Control Module Replacement | N4794 | GMNA |
| 5430010 | Body Ground Stud or Nut Repair or Replacement | B9699 | GMNA |
| 5430010 | Body Ground Stud or Nut Repair or Replacement | B9704 | GMNA |
| 5430010 | Body Ground Stud or Nut Repair or Replacement | N9556 | GMNA |
| 5430020 | Steering Column Key Release Lever Knob Replacement | E7189 | GMNA |
| 5430030 | Ignition Lock Cylinder Control Solenoid Replacement | E7190 | GMNA |
| 5430030 | Ignition Lock Cylinder Control Solenoid Replacement | E9454 | GMNA |
| 5430030 | Ignition Lock Cylinder Control Solenoid Replacement | E9459 | GMNA |
| 5430030 | Ignition Lock Cylinder Control Solenoid Replacement | E9528 | GMNA |
| 5430030 | Ignition Lock Cylinder Control Solenoid Replacement | M000250 | Holden Australia |
| 5430040 | Ignition Lock Cylinder Replacement | E7200 | GMNA |
| 5430040 | Ignition Lock Cylinder Replacement | E7215 | GMNA |
| 5430040 | Ignition Lock Cylinder Replacement | N9654 | GMNA |
| 5430040 | Ignition Lock Cylinder Replacement | E7200 | Holden Australia |
| 5430040 | Ignition Lock Cylinder Replacement | E720000 | Holden Australia |
| 5430040 | Ignition Lock Cylinder Replacement | M200510 | Holden Australia |
| 5430040 | Ignition Lock Cylinder Replacement | N312500 | Holden Australia |
| 5430040 | Ignition Lock Cylinder Replacement | E720000 | Holden New Zealand |
| 5430040 | Ignition Lock Cylinder Replacement | N312500 | Holden New Zealand |
| 5430040 | Ignition Lock Cylinder Replacement | 9680600 | GMK Overseas |
| 5430050 | Ignition Lock Cylinder Case Replacement | E7202 | GMNA |
| 5430050 | Ignition Lock Cylinder Case Replacement | E7340 | GMNA |
| 5430050 | Ignition Lock Cylinder Case Replacement | E7202 | Holden Australia |
| 5430070 | Ignition and Start Switch Housing Replacement | E7205 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430070 | Ignition and Start Switch Housing Replacement | J7724 | GMNA |
| 5430070 | Ignition and Start Switch Housing Replacement | M005100 | Holden Australia |
| 5430070 | Ignition and Start Switch Housing Replacement | M012510 | Holden Australia |
| 5430070 | Ignition and Start Switch Housing Replacement | M005100 | Holden New Zealand |
| 5430070 | Ignition and Start Switch Housing Replacement | 6432900 | GMK Overseas |
| 5430090 | Ignition Lock Cylinder Opening Trim Cover Replacement | C2940 | GMNA |
| 5430090 | Ignition Lock Cylinder Opening Trim Cover Replacement | E7221 | GMNA |
| 5430110 | Front Compartment Fuse Block Cover Replacement | N1710 | GMNA |
| 5430130 | Fuse Replacement | J7725 | GMNA |
| 5430130 | Fuse Replacement | J7732 | GMNA |
| 5430130 | Fuse Replacement | N1690 | GMNA |
| 5430130 | Fuse Replacement | N1720 | GMNA |
| 5430130 | Fuse Replacement | N9515 | GMNA |
| 5430130 | Fuse Replacement | N9659 | GMNA |
| 5430130 | Fuse Replacement | 5341700 | GMK Domestic |
| 5430130 | Fuse Replacement | N1720 | Holden Australia |
| 5430130 | Fuse Replacement | N172000 | Holden Australia |
| 5430130 | Fuse Replacement | N414505 | Holden Australia |
| 5430130 | Fuse Replacement | N414510 | Holden Australia |
| 5430130 | Fuse Replacement | N414515 | Holden Australia |
| 5430130 | Fuse Replacement | N414520 | Holden Australia |
| 5430130 | Fuse Replacement | N414525 | Holden Australia |
| 5430130 | Fuse Replacement | N414530 | Holden Australia |
| 5430130 | Fuse Replacement | N414540 | Holden Australia |
| 5430130 | Fuse Replacement | N414550 | Holden Australia |
| 5430130 | Fuse Replacement | N414560 | Holden Australia |
| 5430130 | Fuse Replacement | N414575 | Holden Australia |
| 5430130 | Fuse Replacement | N414580 | Holden Australia |
| 5430130 | Fuse Replacement | N712602 | Holden Australia |
| 5430130 | Fuse Replacement | N955202 | Holden Australia |
| 5430130 | Fuse Replacement | N955707 | Holden Australia |
| 5430130 | Fuse Replacement | N965017 | Holden Australia |
| 5430130 | Fuse Replacement | N1720 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430130 | Fuse Replacement | N172000 | Holden New Zealand |
| 5430130 | Fuse Replacement | N413500 | Holden New Zealand |
| 5430130 | Fuse Replacement | N414505 | Holden New Zealand |
| 5430130 | Fuse Replacement | N414510 | Holden New Zealand |
| 5430130 | Fuse Replacement | N414515 | Holden New Zealand |
| 5430130 | Fuse Replacement | N414520 | Holden New Zealand |
| 5430130 | Fuse Replacement | N414525 | Holden New Zealand |
| 5430130 | Fuse Replacement | N414530 | Holden New Zealand |
| 5430130 | Fuse Replacement | N414540 | Holden New Zealand |
| 5430130 | Fuse Replacement | N414560 | Holden New Zealand |
| 5430130 | Fuse Replacement | N414575 | Holden New Zealand |
| 5430130 | Fuse Replacement | 1583500 | GMK Overseas |
| 5430130 | Fuse Replacement | 1583700 | GMK Overseas |
| 5430140 | Front Compartment Fuse Block Fuse Replacement | | |
| 5430150 | 200 Amp Mega Fuse and Auxiliary Electrical Center 12VDC Junction Block Replacement | N1729 | GMNA |
| 5430170 | Engine Wiring Harness Junction Block Replacement | N1730 | GMNA |
| 5430170 | Engine Wiring Harness Junction Block Replacement | N1730 | Holden Australia |
| 5430190 | Instrument Panel Wiring Harness Junction Block Replacement | N1731 | GMNA |
| 5430190 | Instrument Panel Wiring Harness Junction Block Replacement | N1732 | GMNA |
| 5430210 | Accessory Wiring Junction Block Replacement | N1733 | GMNA |
| 5430230 | Body Wiring Harness Junction Block Replacement | N1734 | GMNA |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912585 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912586 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912587 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912588 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912589 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912590 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912591 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912592 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912595 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912596 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912597 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912684 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430230 | Body Wiring Harness Junction Block Replacement | N912685 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912686 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912687 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912688 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912689 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912690 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912691 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912693 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912696 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912789 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912790 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912792 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912793 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912794 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912796 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912885 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912886 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912887 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912888 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912889 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912890 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912891 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912895 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912896 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912897 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912985 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912986 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912987 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912988 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912989 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912990 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912991 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912992 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430230 | Body Wiring Harness Junction Block Replacement | N912993 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912994 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912995 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N912997 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913084 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913085 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913086 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913087 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913088 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913089 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913090 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913091 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913092 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913093 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913095 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913096 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913097 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913286 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913287 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913288 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913289 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913295 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913386 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913387 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913388 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913389 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913391 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913392 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913394 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913395 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913396 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913397 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913886 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430230 | Body Wiring Harness Junction Block Replacement | N913887 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913893 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913894 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N913895 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N914085 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N914086 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N914087 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N914091 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N914092 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N914096 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N914097 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N916684 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N916685 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N916690 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N916691 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N916890 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N916893 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N916894 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N922890 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N922896 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932286 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932290 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932292 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932294 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932295 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932296 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932297 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932384 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932385 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932386 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932387 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932389 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932390 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430230 | Body Wiring Harness Junction Block Replacement | N932391 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932392 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932396 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932485 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932486 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932489 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932490 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932491 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932494 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932495 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932496 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N932497 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N933086 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N933087 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N933090 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N933096 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942585 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942586 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942587 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942588 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942591 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942594 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942596 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942685 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942686 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942688 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942690 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942691 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942692 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942693 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942694 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942695 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942696 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430230 | Body Wiring Harness Junction Block Replacement | N942786 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942788 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942792 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942795 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N942796 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N943085 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N943086 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N943090 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N943094 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N943291 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N943292 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N943296 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N943297 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N943788 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N943790 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N943797 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952285 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952286 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952287 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952289 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952290 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952291 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952292 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952293 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952294 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952295 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952296 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952384 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952385 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952387 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952388 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952389 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952390 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430230 | Body Wiring Harness Junction Block Replacement | N952391 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952392 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952393 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952394 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952395 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952396 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952397 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952484 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952485 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952486 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952487 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952488 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952490 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952491 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952492 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952493 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952494 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952495 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952496 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952497 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952991 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952992 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952995 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952996 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N952997 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N953388 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N953389 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N953390 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N953392 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N953393 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N953394 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N953487 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N953491 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430230 | Body Wiring Harness Junction Block Replacement | N953495 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N953496 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N953497 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N954986 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N954996 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N955485 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N955486 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N955487 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N955489 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N955490 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N955491 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N955492 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N955494 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N955495 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N955496 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N955589 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N955591 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N955593 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N955594 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962485 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962486 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962487 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962488 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962489 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962490 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962491 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962494 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962495 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962496 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962497 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962584 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962585 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962586 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430230 | Body Wiring Harness Junction Block Replacement | N962587 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962588 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962589 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962590 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962591 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962593 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962594 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962595 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962596 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962597 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962598 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962684 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962685 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962686 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962687 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962688 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962689 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962690 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962691 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962692 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962693 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962694 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962695 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962696 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962697 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962698 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962784 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962785 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962786 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962787 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962788 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962789 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962790 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430230 | Body Wiring Harness Junction Block Replacement | N962791 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962792 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962793 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962794 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962795 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962796 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N962797 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N963586 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N963587 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N963590 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N963591 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N966485 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N966486 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N966490 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N966491 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N966492 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N966497 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967185 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967186 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967187 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967188 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967189 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967190 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967194 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967195 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967196 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967284 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967286 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967288 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967289 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967290 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967293 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967294 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430230 | Body Wiring Harness Junction Block Replacement | N967295 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967296 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N967297 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972285 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972287 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972288 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972289 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972290 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972291 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972294 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972295 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972297 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972388 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972391 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972392 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972393 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972394 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972396 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972397 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972787 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972789 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972790 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972795 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972796 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972885 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972886 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972887 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972893 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972894 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972895 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972896 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972897 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972898 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430230 | Body Wiring Harness Junction Block Replacement | N972987 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972988 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972989 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972991 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972994 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972995 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N972996 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N974287 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N974294 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982585 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982586 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982587 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982588 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982589 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982590 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982591 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982593 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982594 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982684 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982685 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982686 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982688 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982690 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982691 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982694 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982786 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982789 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982790 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982791 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982792 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982794 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982795 | Holden Australia |
| 5430230 | Body Wiring Harness Junction Block Replacement | N982796 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430230 | Body Wiring Harness Junction Block Replacement | N982797 | Holden Australia |
| 5430340 | Front Compartment Fuse Block Housing Replacement | N1738 | GMNA |
| 5430360 | Front Compartment Fuse Block Replacement | N1739 | GMNA |
| 5430360 | Front Compartment Fuse Block Replacement | N1739 | Holden Australia |
| 5430360 | Front Compartment Fuse Block Replacement | 1582700 | GMK Overseas |
| 5430400 | Circuit Breaker Replacement | N1780 | GMNA |
| 5430420 | Rear Body Fuse Block Replacement | N1919 | GMNA |
| 5430440 | Fuse Block Replacement | N1920 | GMNA |
| 5430440 | Fuse Block Replacement | N6410 | GMNA |
| 5430440 | Fuse Block Replacement | N9508 | GMNA |
| 5430440 | Fuse Block Replacement | N717502 | Holden Australia |
| 5430440 | Fuse Block Replacement | N966906 | Holden Australia |
| 5430440 | Fuse Block Replacement | 1584900 | GMK Overseas |
| 5430460 | Ignition and Start Switch Replacement | N2320 | GMNA |
| 5430460 | Ignition and Start Switch Replacement | N2889 | GMNA |
| 5430460 | Ignition and Start Switch Replacement | N6335 | GMNA |
| 5430460 | Ignition and Start Switch Replacement | 2171100 | GMK Domestic |
| 5430460 | Ignition and Start Switch Replacement | N2320 | Holden Australia |
| 5430460 | Ignition and Start Switch Replacement | N232000 | Holden Australia |
| 5430460 | Ignition and Start Switch Replacement | N313500 | Holden Australia |
| 5430460 | Ignition and Start Switch Replacement | N712325 | Holden Australia |
| 5430460 | Ignition and Start Switch Replacement | N712518 | Holden Australia |
| 5430460 | Ignition and Start Switch Replacement | N712530 | Holden Australia |
| 5430460 | Ignition and Start Switch Replacement | N732118 | Holden Australia |
| 5430460 | Ignition and Start Switch Replacement | N2320 | Holden New Zealand |
| 5430460 | Ignition and Start Switch Replacement | N232000 | Holden New Zealand |
| 5430460 | Ignition and Start Switch Replacement | N313000 | Holden New Zealand |
| 5430460 | Ignition and Start Switch Replacement | N313500 | Holden New Zealand |
| 5430460 | Ignition and Start Switch Replacement | 6432700 | GMK Overseas |
| 5430460 | Ignition and Start Switch Replacement | 643270A | GMK Overseas |
| 5430510 | Relay Replacement | D1029 | GMNA |
| 5430510 | Relay Replacement | D1033 | GMNA |
| 5430510 | Relay Replacement | D1035 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430510 | Relay Replacement | D1040 | GMNA |
| 5430510 | Relay Replacement | F2930 | GMNA |
| 5430510 | Relay Replacement | J4792 | GMNA |
| 5430510 | Relay Replacement | N0195 | GMNA |
| 5430510 | Relay Replacement | N0370 | GMNA |
| 5430510 | Relay Replacement | N0371 | GMNA |
| 5430510 | Relay Replacement | N2795 | GMNA |
| 5430510 | Relay Replacement | N2808 | GMNA |
| 5430510 | Relay Replacement | N2820 | GMNA |
| 5430510 | Relay Replacement | N2824 | GMNA |
| 5430510 | Relay Replacement | N2825 | GMNA |
| 5430510 | Relay Replacement | N2830 | GMNA |
| 5430510 | Relay Replacement | N2835 | GMNA |
| 5430510 | Relay Replacement | N2838 | GMNA |
| 5430510 | Relay Replacement | N2839 | GMNA |
| 5430510 | Relay Replacement | N2840 | GMNA |
| 5430510 | Relay Replacement | N2842 | GMNA |
| 5430510 | Relay Replacement | N2846 | GMNA |
| 5430510 | Relay Replacement | N2847 | GMNA |
| 5430510 | Relay Replacement | N2848 | GMNA |
| 5430510 | Relay Replacement | N2853 | GMNA |
| 5430510 | Relay Replacement | N2854 | GMNA |
| 5430510 | Relay Replacement | N2855 | GMNA |
| 5430510 | Relay Replacement | N2856 | GMNA |
| 5430510 | Relay Replacement | N2863 | GMNA |
| 5430510 | Relay Replacement | N2870 | GMNA |
| 5430510 | Relay Replacement | N2873 | GMNA |
| 5430510 | Relay Replacement | N2880 | GMNA |
| 5430510 | Relay Replacement | N2883 | GMNA |
| 5430510 | Relay Replacement | N2885 | GMNA |
| 5430510 | Relay Replacement | N2887 | GMNA |
| 5430510 | Relay Replacement | N2895 | GMNA |
| 5430510 | Relay Replacement | N2900 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430510 | Relay Replacement | N2901 | GMNA |
| 5430510 | Relay Replacement | N2902 | GMNA |
| 5430510 | Relay Replacement | N2904 | GMNA |
| 5430510 | Relay Replacement | N2914 | GMNA |
| 5430510 | Relay Replacement | N2920 | GMNA |
| 5430510 | Relay Replacement | N2923 | GMNA |
| 5430510 | Relay Replacement | N2924 | GMNA |
| 5430510 | Relay Replacement | N2940 | GMNA |
| 5430510 | Relay Replacement | N2952 | GMNA |
| 5430510 | Relay Replacement | N2980 | GMNA |
| 5430510 | Relay Replacement | N2988 | GMNA |
| 5430510 | Relay Replacement | N2989 | GMNA |
| 5430510 | Relay Replacement | N2990 | GMNA |
| 5430510 | Relay Replacement | N2992 | GMNA |
| 5430510 | Relay Replacement | N2993 | GMNA |
| 5430510 | Relay Replacement | N3100 | GMNA |
| 5430510 | Relay Replacement | N9620 | GMNA |
| 5430510 | Relay Replacement | N9667 | GMNA |
| 5430510 | Relay Replacement | R0620 | GMNA |
| 5430510 | Relay Replacement | R2120 | GMNA |
| 5430510 | Relay Replacement | R2160 | GMNA |
| 5430510 | Relay Replacement | R2980 | GMNA |
| 5430510 | Relay Replacement | R2981 | GMNA |
| 5430510 | Relay Replacement | R4400 | GMNA |
| 5430510 | Relay Replacement | R5530 | GMNA |
| 5430510 | Relay Replacement | 1621100 | GMK Domestic |
| 5430510 | Relay Replacement | 5712700 | GMK Domestic |
| 5430510 | Relay Replacement | 5713000 | GMK Domestic |
| 5430510 | Relay Replacement | 5713600 | GMK Domestic |
| 5430510 | Relay Replacement | 5713700 | GMK Domestic |
| 5430510 | Relay Replacement | 5713800 | GMK Domestic |
| 5430510 | Relay Replacement | 5714200 | GMK Domestic |
| 5430510 | Relay Replacement | 6410700 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430510 | Relay Replacement | 8212300 | GMK Domestic |
| 5430510 | Relay Replacement | 8423100 | GMK Domestic |
| 5430510 | Relay Replacement | 8611600 | GMK Domestic |
| 5430510 | Relay Replacement | 8830700 | GMK Domestic |
| 5430510 | Relay Replacement | D102700 | Holden Australia |
| 5430510 | Relay Replacement | D102900 | Holden Australia |
| 5430510 | Relay Replacement | F400700 | Holden Australia |
| 5430510 | Relay Replacement | J479200 | Holden Australia |
| 5430510 | Relay Replacement | J512900 | Holden Australia |
| 5430510 | Relay Replacement | J523000 | Holden Australia |
| 5430510 | Relay Replacement | N000435 | Holden Australia |
| 5430510 | Relay Replacement | N000444 | Holden Australia |
| 5430510 | Relay Replacement | N000472 | Holden Australia |
| 5430510 | Relay Replacement | N001800 | Holden Australia |
| 5430510 | Relay Replacement | N001810 | Holden Australia |
| 5430510 | Relay Replacement | N001820 | Holden Australia |
| 5430510 | Relay Replacement | N001830 | Holden Australia |
| 5430510 | Relay Replacement | N001835 | Holden Australia |
| 5430510 | Relay Replacement | N001840 | Holden Australia |
| 5430510 | Relay Replacement | N001860 | Holden Australia |
| 5430510 | Relay Replacement | N001865 | Holden Australia |
| 5430510 | Relay Replacement | N001880 | Holden Australia |
| 5430510 | Relay Replacement | N001890 | Holden Australia |
| 5430510 | Relay Replacement | N001900 | Holden Australia |
| 5430510 | Relay Replacement | N001910 | Holden Australia |
| 5430510 | Relay Replacement | N001930 | Holden Australia |
| 5430510 | Relay Replacement | N001970 | Holden Australia |
| 5430510 | Relay Replacement | N001980 | Holden Australia |
| 5430510 | Relay Replacement | N001990 | Holden Australia |
| 5430510 | Relay Replacement | N002000 | Holden Australia |
| 5430510 | Relay Replacement | N002100 | Holden Australia |
| 5430510 | Relay Replacement | N002110 | Holden Australia |
| 5430510 | Relay Replacement | N002120 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430510 | Relay Replacement | N002150 | Holden Australia |
| 5430510 | Relay Replacement | N002200 | Holden Australia |
| 5430510 | Relay Replacement | N002250 | Holden Australia |
| 5430510 | Relay Replacement | N002350 | Holden Australia |
| 5430510 | Relay Replacement | N002400 | Holden Australia |
| 5430510 | Relay Replacement | N002450 | Holden Australia |
| 5430510 | Relay Replacement | N002455 | Holden Australia |
| 5430510 | Relay Replacement | N104600 | Holden Australia |
| 5430510 | Relay Replacement | N105800 | Holden Australia |
| 5430510 | Relay Replacement | N117500 | Holden Australia |
| 5430510 | Relay Replacement | N219100 | Holden Australia |
| 5430510 | Relay Replacement | N2808 | Holden Australia |
| 5430510 | Relay Replacement | N2815 | Holden Australia |
| 5430510 | Relay Replacement | N2819 | Holden Australia |
| 5430510 | Relay Replacement | N282000 | Holden Australia |
| 5430510 | Relay Replacement | N283000 | Holden Australia |
| 5430510 | Relay Replacement | N284000 | Holden Australia |
| 5430510 | Relay Replacement | N285000 | Holden Australia |
| 5430510 | Relay Replacement | N285600 | Holden Australia |
| 5430510 | Relay Replacement | N287000 | Holden Australia |
| 5430510 | Relay Replacement | N288000 | Holden Australia |
| 5430510 | Relay Replacement | N290000 | Holden Australia |
| 5430510 | Relay Replacement | N291000 | Holden Australia |
| 5430510 | Relay Replacement | N291200 | Holden Australia |
| 5430510 | Relay Replacement | N292000 | Holden Australia |
| 5430510 | Relay Replacement | N292200 | Holden Australia |
| 5430510 | Relay Replacement | N293000 | Holden Australia |
| 5430510 | Relay Replacement | N296000 | Holden Australia |
| 5430510 | Relay Replacement | N297000 | Holden Australia |
| 5430510 | Relay Replacement | N298000 | Holden Australia |
| 5430510 | Relay Replacement | N299000 | Holden Australia |
| 5430510 | Relay Replacement | N312400 | Holden Australia |
| 5430510 | Relay Replacement | N359700 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430510 | Relay Replacement | N411005 | Holden Australia |
| 5430510 | Relay Replacement | N414535 | Holden Australia |
| 5430510 | Relay Replacement | N414600 | Holden Australia |
| 5430510 | Relay Replacement | N479600 | Holden Australia |
| 5430510 | Relay Replacement | N506750 | Holden Australia |
| 5430510 | Relay Replacement | N712601 | Holden Australia |
| 5430510 | Relay Replacement | N712604 | Holden Australia |
| 5430510 | Relay Replacement | N712605 | Holden Australia |
| 5430510 | Relay Replacement | N712607 | Holden Australia |
| 5430510 | Relay Replacement | N712608 | Holden Australia |
| 5430510 | Relay Replacement | N712609 | Holden Australia |
| 5430510 | Relay Replacement | N712610 | Holden Australia |
| 5430510 | Relay Replacement | N712611 | Holden Australia |
| 5430510 | Relay Replacement | N732203 | Holden Australia |
| 5430510 | Relay Replacement | N911401 | Holden Australia |
| 5430510 | Relay Replacement | N911402 | Holden Australia |
| 5430510 | Relay Replacement | N911403 | Holden Australia |
| 5430510 | Relay Replacement | N911404 | Holden Australia |
| 5430510 | Relay Replacement | N911405 | Holden Australia |
| 5430510 | Relay Replacement | N911407 | Holden Australia |
| 5430510 | Relay Replacement | N911408 | Holden Australia |
| 5430510 | Relay Replacement | N911410 | Holden Australia |
| 5430510 | Relay Replacement | N911411 | Holden Australia |
| 5430510 | Relay Replacement | N911412 | Holden Australia |
| 5430510 | Relay Replacement | N912005 | Holden Australia |
| 5430510 | Relay Replacement | N912007 | Holden Australia |
| 5430510 | Relay Replacement | N912008 | Holden Australia |
| 5430510 | Relay Replacement | N912009 | Holden Australia |
| 5430510 | Relay Replacement | N912010 | Holden Australia |
| 5430510 | Relay Replacement | N912011 | Holden Australia |
| 5430510 | Relay Replacement | N912012 | Holden Australia |
| 5430510 | Relay Replacement | N931401 | Holden Australia |
| 5430510 | Relay Replacement | N931403 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430510 | Relay Replacement | N931404 | Holden Australia |
| 5430510 | Relay Replacement | N931405 | Holden Australia |
| 5430510 | Relay Replacement | N931409 | Holden Australia |
| 5430510 | Relay Replacement | N931807 | Holden Australia |
| 5430510 | Relay Replacement | N931810 | Holden Australia |
| 5430510 | Relay Replacement | N941308 | Holden Australia |
| 5430510 | Relay Replacement | N941309 | Holden Australia |
| 5430510 | Relay Replacement | N941311 | Holden Australia |
| 5430510 | Relay Replacement | N941804 | Holden Australia |
| 5430510 | Relay Replacement | N951308 | Holden Australia |
| 5430510 | Relay Replacement | N951401 | Holden Australia |
| 5430510 | Relay Replacement | N951402 | Holden Australia |
| 5430510 | Relay Replacement | N951404 | Holden Australia |
| 5430510 | Relay Replacement | N951406 | Holden Australia |
| 5430510 | Relay Replacement | N951407 | Holden Australia |
| 5430510 | Relay Replacement | N951408 | Holden Australia |
| 5430510 | Relay Replacement | N951409 | Holden Australia |
| 5430510 | Relay Replacement | N951411 | Holden Australia |
| 5430510 | Relay Replacement | N951412 | Holden Australia |
| 5430510 | Relay Replacement | N951706 | Holden Australia |
| 5430510 | Relay Replacement | N951708 | Holden Australia |
| 5430510 | Relay Replacement | N951711 | Holden Australia |
| 5430510 | Relay Replacement | N951712 | Holden Australia |
| 5430510 | Relay Replacement | N954803 | Holden Australia |
| 5430510 | Relay Replacement | N954804 | Holden Australia |
| 5430510 | Relay Replacement | N954806 | Holden Australia |
| 5430510 | Relay Replacement | N954813 | Holden Australia |
| 5430510 | Relay Replacement | N961401 | Holden Australia |
| 5430510 | Relay Replacement | N961402 | Holden Australia |
| 5430510 | Relay Replacement | N961404 | Holden Australia |
| 5430510 | Relay Replacement | N961406 | Holden Australia |
| 5430510 | Relay Replacement | N961407 | Holden Australia |
| 5430510 | Relay Replacement | N961408 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430510 | Relay Replacement | N961409 | Holden Australia |
| 5430510 | Relay Replacement | N961410 | Holden Australia |
| 5430510 | Relay Replacement | N961411 | Holden Australia |
| 5430510 | Relay Replacement | N961412 | Holden Australia |
| 5430510 | Relay Replacement | N961904 | Holden Australia |
| 5430510 | Relay Replacement | N961906 | Holden Australia |
| 5430510 | Relay Replacement | N961907 | Holden Australia |
| 5430510 | Relay Replacement | N961908 | Holden Australia |
| 5430510 | Relay Replacement | N961909 | Holden Australia |
| 5430510 | Relay Replacement | N961911 | Holden Australia |
| 5430510 | Relay Replacement | N961912 | Holden Australia |
| 5430510 | Relay Replacement | N966301 | Holden Australia |
| 5430510 | Relay Replacement | N966302 | Holden Australia |
| 5430510 | Relay Replacement | N966303 | Holden Australia |
| 5430510 | Relay Replacement | N966304 | Holden Australia |
| 5430510 | Relay Replacement | N966306 | Holden Australia |
| 5430510 | Relay Replacement | N966309 | Holden Australia |
| 5430510 | Relay Replacement | N966310 | Holden Australia |
| 5430510 | Relay Replacement | N966311 | Holden Australia |
| 5430510 | Relay Replacement | N966312 | Holden Australia |
| 5430510 | Relay Replacement | N966903 | Holden Australia |
| 5430510 | Relay Replacement | N966905 | Holden Australia |
| 5430510 | Relay Replacement | N966907 | Holden Australia |
| 5430510 | Relay Replacement | N966908 | Holden Australia |
| 5430510 | Relay Replacement | N966909 | Holden Australia |
| 5430510 | Relay Replacement | N966910 | Holden Australia |
| 5430510 | Relay Replacement | N966911 | Holden Australia |
| 5430510 | Relay Replacement | N966912 | Holden Australia |
| 5430510 | Relay Replacement | N966913 | Holden Australia |
| 5430510 | Relay Replacement | N971504 | Holden Australia |
| 5430510 | Relay Replacement | N971505 | Holden Australia |
| 5430510 | Relay Replacement | N971509 | Holden Australia |
| 5430510 | Relay Replacement | N971710 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430510 | Relay Replacement | N974402 | Holden Australia |
| 5430510 | Relay Replacement | N974404 | Holden Australia |
| 5430510 | Relay Replacement | N974408 | Holden Australia |
| 5430510 | Relay Replacement | N974409 | Holden Australia |
| 5430510 | Relay Replacement | N974410 | Holden Australia |
| 5430510 | Relay Replacement | N974411 | Holden Australia |
| 5430510 | Relay Replacement | N974412 | Holden Australia |
| 5430510 | Relay Replacement | N974608 | Holden Australia |
| 5430510 | Relay Replacement | N974613 | Holden Australia |
| 5430510 | Relay Replacement | N981403 | Holden Australia |
| 5430510 | Relay Replacement | N981409 | Holden Australia |
| 5430510 | Relay Replacement | N981412 | Holden Australia |
| 5430510 | Relay Replacement | N982004 | Holden Australia |
| 5430510 | Relay Replacement | N982006 | Holden Australia |
| 5430510 | Relay Replacement | D102700 | Holden New Zealand |
| 5430510 | Relay Replacement | D102900 | Holden New Zealand |
| 5430510 | Relay Replacement | D1040 | Holden New Zealand |
| 5430510 | Relay Replacement | D205100 | Holden New Zealand |
| 5430510 | Relay Replacement | F400700 | Holden New Zealand |
| 5430510 | Relay Replacement | N000435 | Holden New Zealand |
| 5430510 | Relay Replacement | N000444 | Holden New Zealand |
| 5430510 | Relay Replacement | N000472 | Holden New Zealand |
| 5430510 | Relay Replacement | N001800 | Holden New Zealand |
| 5430510 | Relay Replacement | N001810 | Holden New Zealand |
| 5430510 | Relay Replacement | N001820 | Holden New Zealand |
| 5430510 | Relay Replacement | N001830 | Holden New Zealand |
| 5430510 | Relay Replacement | N001840 | Holden New Zealand |
| 5430510 | Relay Replacement | N001850 | Holden New Zealand |
| 5430510 | Relay Replacement | N001860 | Holden New Zealand |
| 5430510 | Relay Replacement | N001865 | Holden New Zealand |
| 5430510 | Relay Replacement | N001880 | Holden New Zealand |
| 5430510 | Relay Replacement | N001890 | Holden New Zealand |
| 5430510 | Relay Replacement | N001900 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430510 | Relay Replacement | N001910 | Holden New Zealand |
| 5430510 | Relay Replacement | N001930 | Holden New Zealand |
| 5430510 | Relay Replacement | N001960 | Holden New Zealand |
| 5430510 | Relay Replacement | N001970 | Holden New Zealand |
| 5430510 | Relay Replacement | N001980 | Holden New Zealand |
| 5430510 | Relay Replacement | N001990 | Holden New Zealand |
| 5430510 | Relay Replacement | N002000 | Holden New Zealand |
| 5430510 | Relay Replacement | N002100 | Holden New Zealand |
| 5430510 | Relay Replacement | N002110 | Holden New Zealand |
| 5430510 | Relay Replacement | N002150 | Holden New Zealand |
| 5430510 | Relay Replacement | N002200 | Holden New Zealand |
| 5430510 | Relay Replacement | N002250 | Holden New Zealand |
| 5430510 | Relay Replacement | N002350 | Holden New Zealand |
| 5430510 | Relay Replacement | N002400 | Holden New Zealand |
| 5430510 | Relay Replacement | N104600 | Holden New Zealand |
| 5430510 | Relay Replacement | N117500 | Holden New Zealand |
| 5430510 | Relay Replacement | N219100 | Holden New Zealand |
| 5430510 | Relay Replacement | N251500 | Holden New Zealand |
| 5430510 | Relay Replacement | N2800 | Holden New Zealand |
| 5430510 | Relay Replacement | N2830 | Holden New Zealand |
| 5430510 | Relay Replacement | N284000 | Holden New Zealand |
| 5430510 | Relay Replacement | N285000 | Holden New Zealand |
| 5430510 | Relay Replacement | N2900 | Holden New Zealand |
| 5430510 | Relay Replacement | N293000 | Holden New Zealand |
| 5430510 | Relay Replacement | N297000 | Holden New Zealand |
| 5430510 | Relay Replacement | N299000 | Holden New Zealand |
| 5430510 | Relay Replacement | N312400 | Holden New Zealand |
| 5430510 | Relay Replacement | N359700 | Holden New Zealand |
| 5430510 | Relay Replacement | N413600 | Holden New Zealand |
| 5430510 | Relay Replacement | N414535 | Holden New Zealand |
| 5430510 | Relay Replacement | N414600 | Holden New Zealand |
| 5430510 | Relay Replacement | N479600 | Holden New Zealand |
| 5430510 | Relay Replacement | R104600 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430510 | Relay Replacement | 1580100 | GMK Overseas |
| 5430510 | Relay Replacement | 1580200 | GMK Overseas |
| 5430510 | Relay Replacement | 1580300 | GMK Overseas |
| 5430510 | Relay Replacement | 1580400 | GMK Overseas |
| 5430510 | Relay Replacement | 1580500 | GMK Overseas |
| 5430510 | Relay Replacement | 1580600 | GMK Overseas |
| 5430510 | Relay Replacement | 1580700 | GMK Overseas |
| 5430510 | Relay Replacement | 1580800 | GMK Overseas |
| 5430510 | Relay Replacement | 1580900 | GMK Overseas |
| 5430510 | Relay Replacement | 1581100 | GMK Overseas |
| 5430510 | Relay Replacement | 1581300 | GMK Overseas |
| 5430510 | Relay Replacement | 1581500 | GMK Overseas |
| 5430510 | Relay Replacement | 1581600 | GMK Overseas |
| 5430510 | Relay Replacement | 1582100 | GMK Overseas |
| 5430710 | Engine Stop/Start Mode Control Switch Replacement | N4780 | GMNA |
| 5430710 | Engine Stop/Start Mode Control Switch Replacement | N5299 | GMNA |
| 5430710 | Engine Stop/Start Mode Control Switch Replacement | J533900 | Holden Australia |
| 5430710 | Engine Stop/Start Mode Control Switch Replacement | J5339 | Holden New Zealand |
| 5430730 | 175 Amp Mega Fuse Replacement | | |
| 5430840 | Terminal Replacement | J7723 | GMNA |
| 5430840 | Terminal Replacement | N6650 | GMNA |
| 5430840 | Terminal Replacement | N9545 | GMNA |
| 5430840 | Terminal Replacement | N9644 | GMNA |
| 5430840 | Terminal Replacement | N001570 | Holden Australia |
| 5430840 | Terminal Replacement | N0107 | Holden Australia |
| 5430840 | Terminal Replacement | N001570 | Holden New Zealand |
| 5430860 | Connector Kit Replacement | N6651 | GMNA |
| 5430860 | Connector Kit Replacement | N9662 | GMNA |
| 5430860 | Connector Kit Replacement | J000845 | Holden Australia |
| 5430860 | Connector Kit Replacement | N401550 | Holden Australia |
| 5430860 | Connector Kit Replacement | N403550 | Holden Australia |
| 5430860 | Connector Kit Replacement | N466550 | Holden Australia |
| 5430860 | Connector Kit Replacement | N6651 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430860 | Connector Kit Replacement | N401550 | Holden New Zealand |
| 5430860 | Connector Kit Replacement | N466550 | Holden New Zealand |
| 5430880 | Connector with Leads Assembly Replacement | N6652 | GMNA |
| 5430902 | Wire-to-Wire Repair | D1704 | GMNA |
| 5430902 | Wire-to-Wire Repair | N6556 | GMNA |
| 5430902 | Wire-to-Wire Repair | N9607 | GMNA |
| 5430902 | Wire-to-Wire Repair | N9677 | GMNA |
| 5430902 | Wire-to-Wire Repair | R9142 | GMNA |
| 5430902 | Wire-to-Wire Repair | R9795 | GMNA |
| 5430902 | Wire-to-Wire Repair | 2211200 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 2211400 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5344000 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5344200 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5410500 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5410600 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5412000 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5412020 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5412400 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5412500 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5421000 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5421600 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5421700 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5422300 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5422400 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5423100 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5423400 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5423800 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5509990 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | 5510100 | GMK Domestic |
| 5430902 | Wire-to-Wire Repair | N311650 | Holden Australia |
| 5430902 | Wire-to-Wire Repair | N453550 | Holden Australia |
| 5430902 | Wire-to-Wire Repair | N453650 | Holden Australia |
| 5430902 | Wire-to-Wire Repair | N6653 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430902 | Wire-to-Wire Repair | N6655 | Holden Australia |
| 5430902 | Wire-to-Wire Repair | R9231 | Holden Australia |
| 5430902 | Wire-to-Wire Repair | AFM0000 | Holden New Zealand |
| 5430902 | Wire-to-Wire Repair | J000893 | Holden New Zealand |
| 5430902 | Wire-to-Wire Repair | N311650 | Holden New Zealand |
| 5430902 | Wire-to-Wire Repair | N401820 | Holden New Zealand |
| 5430902 | Wire-to-Wire Repair | N6655 | Holden New Zealand |
| 5430902 | Wire-to-Wire Repair | NZ5533 | Holden New Zealand |
| 5430902 | Wire-to-Wire Repair | R200250 | Holden New Zealand |
| 5430902 | Wire-to-Wire Repair | RG1203 | Holden New Zealand |
| 5430902 | Wire-to-Wire Repair | 9110600 | GMK Overseas |
| 5430902 | Wire-to-Wire Repair | 9111100 | GMK Overseas |
| 5430902 | Wire-to-Wire Repair | T391024 | GMK Overseas |
| 5430902 | Wire-to-Wire Repair | T591005 | GMK Overseas |
| 5430902 | Wire-to-Wire Repair | T591011 | GMK Overseas |
| 5430902 | Wire-to-Wire Repair | T683006 | GMK Overseas |
| 5430902 | Wire-to-Wire Repair | T791010 | GMK Overseas |
| 5430922 | Connector Reconnection | D9778 | GMNA |
| 5430922 | Connector Reconnection | N6654 | GMNA |
| 5430922 | Connector Reconnection | N6730 | GMNA |
| 5430922 | Connector Reconnection | N9513 | GMNA |
| 5430922 | Connector Reconnection | N9530 | GMNA |
| 5430922 | Connector Reconnection | N9577 | GMNA |
| 5430922 | Connector Reconnection | N9590 | GMNA |
| 5430922 | Connector Reconnection | N9595 | GMNA |
| 5430922 | Connector Reconnection | N9606 | GMNA |
| 5430922 | Connector Reconnection | N9639 | GMNA |
| 5430922 | Connector Reconnection | N9670 | GMNA |
| 5430922 | Connector Reconnection | R9734 | GMNA |
| 5430922 | Connector Reconnection | R9765 | GMNA |
| 5430922 | Connector Reconnection | N000520 | Holden Australia |
| 5430922 | Connector Reconnection | N6654 | Holden Australia |
| 5430922 | Connector Reconnection | N710401 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N710402 | Holden Australia |
| 5430922 | Connector Reconnection | N710403 | Holden Australia |
| 5430922 | Connector Reconnection | N710404 | Holden Australia |
| 5430922 | Connector Reconnection | N710405 | Holden Australia |
| 5430922 | Connector Reconnection | N710406 | Holden Australia |
| 5430922 | Connector Reconnection | N710407 | Holden Australia |
| 5430922 | Connector Reconnection | N710408 | Holden Australia |
| 5430922 | Connector Reconnection | N710409 | Holden Australia |
| 5430922 | Connector Reconnection | N710410 | Holden Australia |
| 5430922 | Connector Reconnection | N710411 | Holden Australia |
| 5430922 | Connector Reconnection | N710412 | Holden Australia |
| 5430922 | Connector Reconnection | N710501 | Holden Australia |
| 5430922 | Connector Reconnection | N710502 | Holden Australia |
| 5430922 | Connector Reconnection | N710503 | Holden Australia |
| 5430922 | Connector Reconnection | N710601 | Holden Australia |
| 5430922 | Connector Reconnection | N710602 | Holden Australia |
| 5430922 | Connector Reconnection | N710603 | Holden Australia |
| 5430922 | Connector Reconnection | N710606 | Holden Australia |
| 5430922 | Connector Reconnection | N710701 | Holden Australia |
| 5430922 | Connector Reconnection | N710702 | Holden Australia |
| 5430922 | Connector Reconnection | N710703 | Holden Australia |
| 5430922 | Connector Reconnection | N710704 | Holden Australia |
| 5430922 | Connector Reconnection | N710705 | Holden Australia |
| 5430922 | Connector Reconnection | N710706 | Holden Australia |
| 5430922 | Connector Reconnection | N710707 | Holden Australia |
| 5430922 | Connector Reconnection | N710801 | Holden Australia |
| 5430922 | Connector Reconnection | N710802 | Holden Australia |
| 5430922 | Connector Reconnection | N710803 | Holden Australia |
| 5430922 | Connector Reconnection | N710804 | Holden Australia |
| 5430922 | Connector Reconnection | N710805 | Holden Australia |
| 5430922 | Connector Reconnection | N710806 | Holden Australia |
| 5430922 | Connector Reconnection | N710807 | Holden Australia |
| 5430922 | Connector Reconnection | N710808 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N710809 | Holden Australia |
| 5430922 | Connector Reconnection | N710901 | Holden Australia |
| 5430922 | Connector Reconnection | N710902 | Holden Australia |
| 5430922 | Connector Reconnection | N710904 | Holden Australia |
| 5430922 | Connector Reconnection | N710905 | Holden Australia |
| 5430922 | Connector Reconnection | N711001 | Holden Australia |
| 5430922 | Connector Reconnection | N711002 | Holden Australia |
| 5430922 | Connector Reconnection | N711003 | Holden Australia |
| 5430922 | Connector Reconnection | N711004 | Holden Australia |
| 5430922 | Connector Reconnection | N711005 | Holden Australia |
| 5430922 | Connector Reconnection | N711101 | Holden Australia |
| 5430922 | Connector Reconnection | N711102 | Holden Australia |
| 5430922 | Connector Reconnection | N711201 | Holden Australia |
| 5430922 | Connector Reconnection | N711203 | Holden Australia |
| 5430922 | Connector Reconnection | N711204 | Holden Australia |
| 5430922 | Connector Reconnection | N711205 | Holden Australia |
| 5430922 | Connector Reconnection | N711206 | Holden Australia |
| 5430922 | Connector Reconnection | N711207 | Holden Australia |
| 5430922 | Connector Reconnection | N711208 | Holden Australia |
| 5430922 | Connector Reconnection | N711210 | Holden Australia |
| 5430922 | Connector Reconnection | N711301 | Holden Australia |
| 5430922 | Connector Reconnection | N711303 | Holden Australia |
| 5430922 | Connector Reconnection | N711305 | Holden Australia |
| 5430922 | Connector Reconnection | N711306 | Holden Australia |
| 5430922 | Connector Reconnection | N711307 | Holden Australia |
| 5430922 | Connector Reconnection | N711308 | Holden Australia |
| 5430922 | Connector Reconnection | N711309 | Holden Australia |
| 5430922 | Connector Reconnection | N711310 | Holden Australia |
| 5430922 | Connector Reconnection | N711312 | Holden Australia |
| 5430922 | Connector Reconnection | N711313 | Holden Australia |
| 5430922 | Connector Reconnection | N711315 | Holden Australia |
| 5430922 | Connector Reconnection | N711316 | Holden Australia |
| 5430922 | Connector Reconnection | N711319 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N711401 | Holden Australia |
| 5430922 | Connector Reconnection | N711402 | Holden Australia |
| 5430922 | Connector Reconnection | N711403 | Holden Australia |
| 5430922 | Connector Reconnection | N711404 | Holden Australia |
| 5430922 | Connector Reconnection | N711405 | Holden Australia |
| 5430922 | Connector Reconnection | N711406 | Holden Australia |
| 5430922 | Connector Reconnection | N711407 | Holden Australia |
| 5430922 | Connector Reconnection | N711410 | Holden Australia |
| 5430922 | Connector Reconnection | N711411 | Holden Australia |
| 5430922 | Connector Reconnection | N711501 | Holden Australia |
| 5430922 | Connector Reconnection | N711502 | Holden Australia |
| 5430922 | Connector Reconnection | N711505 | Holden Australia |
| 5430922 | Connector Reconnection | N711601 | Holden Australia |
| 5430922 | Connector Reconnection | N711602 | Holden Australia |
| 5430922 | Connector Reconnection | N711603 | Holden Australia |
| 5430922 | Connector Reconnection | N711604 | Holden Australia |
| 5430922 | Connector Reconnection | N711701 | Holden Australia |
| 5430922 | Connector Reconnection | N711702 | Holden Australia |
| 5430922 | Connector Reconnection | N711704 | Holden Australia |
| 5430922 | Connector Reconnection | N711705 | Holden Australia |
| 5430922 | Connector Reconnection | N711706 | Holden Australia |
| 5430922 | Connector Reconnection | N711707 | Holden Australia |
| 5430922 | Connector Reconnection | N711801 | Holden Australia |
| 5430922 | Connector Reconnection | N711802 | Holden Australia |
| 5430922 | Connector Reconnection | N711803 | Holden Australia |
| 5430922 | Connector Reconnection | N711805 | Holden Australia |
| 5430922 | Connector Reconnection | N711901 | Holden Australia |
| 5430922 | Connector Reconnection | N711902 | Holden Australia |
| 5430922 | Connector Reconnection | N711903 | Holden Australia |
| 5430922 | Connector Reconnection | N711904 | Holden Australia |
| 5430922 | Connector Reconnection | N711905 | Holden Australia |
| 5430922 | Connector Reconnection | N711906 | Holden Australia |
| 5430922 | Connector Reconnection | N711907 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N711908 | Holden Australia |
| 5430922 | Connector Reconnection | N711909 | Holden Australia |
| 5430922 | Connector Reconnection | N711911 | Holden Australia |
| 5430922 | Connector Reconnection | N711912 | Holden Australia |
| 5430922 | Connector Reconnection | N711913 | Holden Australia |
| 5430922 | Connector Reconnection | N711914 | Holden Australia |
| 5430922 | Connector Reconnection | N711915 | Holden Australia |
| 5430922 | Connector Reconnection | N711916 | Holden Australia |
| 5430922 | Connector Reconnection | N711917 | Holden Australia |
| 5430922 | Connector Reconnection | N711918 | Holden Australia |
| 5430922 | Connector Reconnection | N711919 | Holden Australia |
| 5430922 | Connector Reconnection | N711920 | Holden Australia |
| 5430922 | Connector Reconnection | N711921 | Holden Australia |
| 5430922 | Connector Reconnection | N711922 | Holden Australia |
| 5430922 | Connector Reconnection | N711923 | Holden Australia |
| 5430922 | Connector Reconnection | N711924 | Holden Australia |
| 5430922 | Connector Reconnection | N711925 | Holden Australia |
| 5430922 | Connector Reconnection | N711926 | Holden Australia |
| 5430922 | Connector Reconnection | N712001 | Holden Australia |
| 5430922 | Connector Reconnection | N712002 | Holden Australia |
| 5430922 | Connector Reconnection | N712003 | Holden Australia |
| 5430922 | Connector Reconnection | N712004 | Holden Australia |
| 5430922 | Connector Reconnection | N712005 | Holden Australia |
| 5430922 | Connector Reconnection | N712007 | Holden Australia |
| 5430922 | Connector Reconnection | N712008 | Holden Australia |
| 5430922 | Connector Reconnection | N712010 | Holden Australia |
| 5430922 | Connector Reconnection | N712011 | Holden Australia |
| 5430922 | Connector Reconnection | N712012 | Holden Australia |
| 5430922 | Connector Reconnection | N712103 | Holden Australia |
| 5430922 | Connector Reconnection | N712104 | Holden Australia |
| 5430922 | Connector Reconnection | N712105 | Holden Australia |
| 5430922 | Connector Reconnection | N712106 | Holden Australia |
| 5430922 | Connector Reconnection | N712107 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N712108 | Holden Australia |
| 5430922 | Connector Reconnection | N712201 | Holden Australia |
| 5430922 | Connector Reconnection | N712202 | Holden Australia |
| 5430922 | Connector Reconnection | N712204 | Holden Australia |
| 5430922 | Connector Reconnection | N712206 | Holden Australia |
| 5430922 | Connector Reconnection | N712207 | Holden Australia |
| 5430922 | Connector Reconnection | N712208 | Holden Australia |
| 5430922 | Connector Reconnection | N712209 | Holden Australia |
| 5430922 | Connector Reconnection | N712210 | Holden Australia |
| 5430922 | Connector Reconnection | N712211 | Holden Australia |
| 5430922 | Connector Reconnection | N712212 | Holden Australia |
| 5430922 | Connector Reconnection | N712213 | Holden Australia |
| 5430922 | Connector Reconnection | N712215 | Holden Australia |
| 5430922 | Connector Reconnection | N712216 | Holden Australia |
| 5430922 | Connector Reconnection | N712217 | Holden Australia |
| 5430922 | Connector Reconnection | N712218 | Holden Australia |
| 5430922 | Connector Reconnection | N712301 | Holden Australia |
| 5430922 | Connector Reconnection | N712307 | Holden Australia |
| 5430922 | Connector Reconnection | N712308 | Holden Australia |
| 5430922 | Connector Reconnection | N712310 | Holden Australia |
| 5430922 | Connector Reconnection | N712312 | Holden Australia |
| 5430922 | Connector Reconnection | N712313 | Holden Australia |
| 5430922 | Connector Reconnection | N712314 | Holden Australia |
| 5430922 | Connector Reconnection | N712315 | Holden Australia |
| 5430922 | Connector Reconnection | N712316 | Holden Australia |
| 5430922 | Connector Reconnection | N712318 | Holden Australia |
| 5430922 | Connector Reconnection | N712320 | Holden Australia |
| 5430922 | Connector Reconnection | N712321 | Holden Australia |
| 5430922 | Connector Reconnection | N712322 | Holden Australia |
| 5430922 | Connector Reconnection | N712402 | Holden Australia |
| 5430922 | Connector Reconnection | N712405 | Holden Australia |
| 5430922 | Connector Reconnection | N712409 | Holden Australia |
| 5430922 | Connector Reconnection | N712411 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N712412 | Holden Australia |
| 5430922 | Connector Reconnection | N712415 | Holden Australia |
| 5430922 | Connector Reconnection | N712416 | Holden Australia |
| 5430922 | Connector Reconnection | N712418 | Holden Australia |
| 5430922 | Connector Reconnection | N712419 | Holden Australia |
| 5430922 | Connector Reconnection | N712501 | Holden Australia |
| 5430922 | Connector Reconnection | N712506 | Holden Australia |
| 5430922 | Connector Reconnection | N712512 | Holden Australia |
| 5430922 | Connector Reconnection | N712513 | Holden Australia |
| 5430922 | Connector Reconnection | N712516 | Holden Australia |
| 5430922 | Connector Reconnection | N712520 | Holden Australia |
| 5430922 | Connector Reconnection | N712521 | Holden Australia |
| 5430922 | Connector Reconnection | N712701 | Holden Australia |
| 5430922 | Connector Reconnection | N712702 | Holden Australia |
| 5430922 | Connector Reconnection | N712703 | Holden Australia |
| 5430922 | Connector Reconnection | N712704 | Holden Australia |
| 5430922 | Connector Reconnection | N712705 | Holden Australia |
| 5430922 | Connector Reconnection | N712706 | Holden Australia |
| 5430922 | Connector Reconnection | N712801 | Holden Australia |
| 5430922 | Connector Reconnection | N712802 | Holden Australia |
| 5430922 | Connector Reconnection | N712803 | Holden Australia |
| 5430922 | Connector Reconnection | N712804 | Holden Australia |
| 5430922 | Connector Reconnection | N712805 | Holden Australia |
| 5430922 | Connector Reconnection | N712806 | Holden Australia |
| 5430922 | Connector Reconnection | N712807 | Holden Australia |
| 5430922 | Connector Reconnection | N712901 | Holden Australia |
| 5430922 | Connector Reconnection | N712902 | Holden Australia |
| 5430922 | Connector Reconnection | N712903 | Holden Australia |
| 5430922 | Connector Reconnection | N712904 | Holden Australia |
| 5430922 | Connector Reconnection | N713101 | Holden Australia |
| 5430922 | Connector Reconnection | N713102 | Holden Australia |
| 5430922 | Connector Reconnection | N713103 | Holden Australia |
| 5430922 | Connector Reconnection | N713104 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N713105 | Holden Australia |
| 5430922 | Connector Reconnection | N713106 | Holden Australia |
| 5430922 | Connector Reconnection | N713107 | Holden Australia |
| 5430922 | Connector Reconnection | N713108 | Holden Australia |
| 5430922 | Connector Reconnection | N713109 | Holden Australia |
| 5430922 | Connector Reconnection | N713110 | Holden Australia |
| 5430922 | Connector Reconnection | N713111 | Holden Australia |
| 5430922 | Connector Reconnection | N713112 | Holden Australia |
| 5430922 | Connector Reconnection | N713113 | Holden Australia |
| 5430922 | Connector Reconnection | N713114 | Holden Australia |
| 5430922 | Connector Reconnection | N713117 | Holden Australia |
| 5430922 | Connector Reconnection | N713118 | Holden Australia |
| 5430922 | Connector Reconnection | N713119 | Holden Australia |
| 5430922 | Connector Reconnection | N713120 | Holden Australia |
| 5430922 | Connector Reconnection | N713122 | Holden Australia |
| 5430922 | Connector Reconnection | N713123 | Holden Australia |
| 5430922 | Connector Reconnection | N713124 | Holden Australia |
| 5430922 | Connector Reconnection | N713125 | Holden Australia |
| 5430922 | Connector Reconnection | N713202 | Holden Australia |
| 5430922 | Connector Reconnection | N713203 | Holden Australia |
| 5430922 | Connector Reconnection | N713204 | Holden Australia |
| 5430922 | Connector Reconnection | N713207 | Holden Australia |
| 5430922 | Connector Reconnection | N713208 | Holden Australia |
| 5430922 | Connector Reconnection | N713211 | Holden Australia |
| 5430922 | Connector Reconnection | N713303 | Holden Australia |
| 5430922 | Connector Reconnection | N713305 | Holden Australia |
| 5430922 | Connector Reconnection | N713306 | Holden Australia |
| 5430922 | Connector Reconnection | N713307 | Holden Australia |
| 5430922 | Connector Reconnection | N713401 | Holden Australia |
| 5430922 | Connector Reconnection | N713402 | Holden Australia |
| 5430922 | Connector Reconnection | N713501 | Holden Australia |
| 5430922 | Connector Reconnection | N713502 | Holden Australia |
| 5430922 | Connector Reconnection | N713503 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N713504 | Holden Australia |
| 5430922 | Connector Reconnection | N713505 | Holden Australia |
| 5430922 | Connector Reconnection | N713506 | Holden Australia |
| 5430922 | Connector Reconnection | N713507 | Holden Australia |
| 5430922 | Connector Reconnection | N713508 | Holden Australia |
| 5430922 | Connector Reconnection | N713509 | Holden Australia |
| 5430922 | Connector Reconnection | N713510 | Holden Australia |
| 5430922 | Connector Reconnection | N713513 | Holden Australia |
| 5430922 | Connector Reconnection | N713514 | Holden Australia |
| 5430922 | Connector Reconnection | N713516 | Holden Australia |
| 5430922 | Connector Reconnection | N713601 | Holden Australia |
| 5430922 | Connector Reconnection | N713602 | Holden Australia |
| 5430922 | Connector Reconnection | N713603 | Holden Australia |
| 5430922 | Connector Reconnection | N713604 | Holden Australia |
| 5430922 | Connector Reconnection | N713605 | Holden Australia |
| 5430922 | Connector Reconnection | N713606 | Holden Australia |
| 5430922 | Connector Reconnection | N713607 | Holden Australia |
| 5430922 | Connector Reconnection | N713608 | Holden Australia |
| 5430922 | Connector Reconnection | N713609 | Holden Australia |
| 5430922 | Connector Reconnection | N713610 | Holden Australia |
| 5430922 | Connector Reconnection | N713612 | Holden Australia |
| 5430922 | Connector Reconnection | N713613 | Holden Australia |
| 5430922 | Connector Reconnection | N713614 | Holden Australia |
| 5430922 | Connector Reconnection | N713615 | Holden Australia |
| 5430922 | Connector Reconnection | N713616 | Holden Australia |
| 5430922 | Connector Reconnection | N713701 | Holden Australia |
| 5430922 | Connector Reconnection | N713702 | Holden Australia |
| 5430922 | Connector Reconnection | N713703 | Holden Australia |
| 5430922 | Connector Reconnection | N713706 | Holden Australia |
| 5430922 | Connector Reconnection | N713708 | Holden Australia |
| 5430922 | Connector Reconnection | N713710 | Holden Australia |
| 5430922 | Connector Reconnection | N713711 | Holden Australia |
| 5430922 | Connector Reconnection | N713801 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N713803 | Holden Australia |
| 5430922 | Connector Reconnection | N713901 | Holden Australia |
| 5430922 | Connector Reconnection | N713902 | Holden Australia |
| 5430922 | Connector Reconnection | N713903 | Holden Australia |
| 5430922 | Connector Reconnection | N713904 | Holden Australia |
| 5430922 | Connector Reconnection | N713905 | Holden Australia |
| 5430922 | Connector Reconnection | N713906 | Holden Australia |
| 5430922 | Connector Reconnection | N713908 | Holden Australia |
| 5430922 | Connector Reconnection | N713909 | Holden Australia |
| 5430922 | Connector Reconnection | N713910 | Holden Australia |
| 5430922 | Connector Reconnection | N713911 | Holden Australia |
| 5430922 | Connector Reconnection | N714002 | Holden Australia |
| 5430922 | Connector Reconnection | N714003 | Holden Australia |
| 5430922 | Connector Reconnection | N714004 | Holden Australia |
| 5430922 | Connector Reconnection | N714005 | Holden Australia |
| 5430922 | Connector Reconnection | N714006 | Holden Australia |
| 5430922 | Connector Reconnection | N714101 | Holden Australia |
| 5430922 | Connector Reconnection | N714102 | Holden Australia |
| 5430922 | Connector Reconnection | N714104 | Holden Australia |
| 5430922 | Connector Reconnection | N714105 | Holden Australia |
| 5430922 | Connector Reconnection | N714106 | Holden Australia |
| 5430922 | Connector Reconnection | N714107 | Holden Australia |
| 5430922 | Connector Reconnection | N714108 | Holden Australia |
| 5430922 | Connector Reconnection | N714110 | Holden Australia |
| 5430922 | Connector Reconnection | N714111 | Holden Australia |
| 5430922 | Connector Reconnection | N714112 | Holden Australia |
| 5430922 | Connector Reconnection | N714201 | Holden Australia |
| 5430922 | Connector Reconnection | N714202 | Holden Australia |
| 5430922 | Connector Reconnection | N714203 | Holden Australia |
| 5430922 | Connector Reconnection | N714301 | Holden Australia |
| 5430922 | Connector Reconnection | N714302 | Holden Australia |
| 5430922 | Connector Reconnection | N714303 | Holden Australia |
| 5430922 | Connector Reconnection | N714304 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N714305 | Holden Australia |
| 5430922 | Connector Reconnection | N714306 | Holden Australia |
| 5430922 | Connector Reconnection | N714307 | Holden Australia |
| 5430922 | Connector Reconnection | N714308 | Holden Australia |
| 5430922 | Connector Reconnection | N714309 | Holden Australia |
| 5430922 | Connector Reconnection | N714401 | Holden Australia |
| 5430922 | Connector Reconnection | N714402 | Holden Australia |
| 5430922 | Connector Reconnection | N714501 | Holden Australia |
| 5430922 | Connector Reconnection | N714502 | Holden Australia |
| 5430922 | Connector Reconnection | N714503 | Holden Australia |
| 5430922 | Connector Reconnection | N714504 | Holden Australia |
| 5430922 | Connector Reconnection | N714505 | Holden Australia |
| 5430922 | Connector Reconnection | N714506 | Holden Australia |
| 5430922 | Connector Reconnection | N714601 | Holden Australia |
| 5430922 | Connector Reconnection | N714602 | Holden Australia |
| 5430922 | Connector Reconnection | N714603 | Holden Australia |
| 5430922 | Connector Reconnection | N714604 | Holden Australia |
| 5430922 | Connector Reconnection | N714605 | Holden Australia |
| 5430922 | Connector Reconnection | N714606 | Holden Australia |
| 5430922 | Connector Reconnection | N714607 | Holden Australia |
| 5430922 | Connector Reconnection | N714608 | Holden Australia |
| 5430922 | Connector Reconnection | N714701 | Holden Australia |
| 5430922 | Connector Reconnection | N714702 | Holden Australia |
| 5430922 | Connector Reconnection | N714703 | Holden Australia |
| 5430922 | Connector Reconnection | N714704 | Holden Australia |
| 5430922 | Connector Reconnection | N714705 | Holden Australia |
| 5430922 | Connector Reconnection | N714706 | Holden Australia |
| 5430922 | Connector Reconnection | N714707 | Holden Australia |
| 5430922 | Connector Reconnection | N714708 | Holden Australia |
| 5430922 | Connector Reconnection | N714709 | Holden Australia |
| 5430922 | Connector Reconnection | N714710 | Holden Australia |
| 5430922 | Connector Reconnection | N714711 | Holden Australia |
| 5430922 | Connector Reconnection | N714712 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N714713 | Holden Australia |
| 5430922 | Connector Reconnection | N714714 | Holden Australia |
| 5430922 | Connector Reconnection | N714715 | Holden Australia |
| 5430922 | Connector Reconnection | N714716 | Holden Australia |
| 5430922 | Connector Reconnection | N714717 | Holden Australia |
| 5430922 | Connector Reconnection | N714719 | Holden Australia |
| 5430922 | Connector Reconnection | N714720 | Holden Australia |
| 5430922 | Connector Reconnection | N714721 | Holden Australia |
| 5430922 | Connector Reconnection | N714722 | Holden Australia |
| 5430922 | Connector Reconnection | N714723 | Holden Australia |
| 5430922 | Connector Reconnection | N714724 | Holden Australia |
| 5430922 | Connector Reconnection | N714725 | Holden Australia |
| 5430922 | Connector Reconnection | N714726 | Holden Australia |
| 5430922 | Connector Reconnection | N714727 | Holden Australia |
| 5430922 | Connector Reconnection | N714728 | Holden Australia |
| 5430922 | Connector Reconnection | N714729 | Holden Australia |
| 5430922 | Connector Reconnection | N714730 | Holden Australia |
| 5430922 | Connector Reconnection | N714731 | Holden Australia |
| 5430922 | Connector Reconnection | N714732 | Holden Australia |
| 5430922 | Connector Reconnection | N714901 | Holden Australia |
| 5430922 | Connector Reconnection | N714902 | Holden Australia |
| 5430922 | Connector Reconnection | N714903 | Holden Australia |
| 5430922 | Connector Reconnection | N715001 | Holden Australia |
| 5430922 | Connector Reconnection | N715002 | Holden Australia |
| 5430922 | Connector Reconnection | N715003 | Holden Australia |
| 5430922 | Connector Reconnection | N715004 | Holden Australia |
| 5430922 | Connector Reconnection | N715005 | Holden Australia |
| 5430922 | Connector Reconnection | N715105 | Holden Australia |
| 5430922 | Connector Reconnection | N715106 | Holden Australia |
| 5430922 | Connector Reconnection | N715109 | Holden Australia |
| 5430922 | Connector Reconnection | N715110 | Holden Australia |
| 5430922 | Connector Reconnection | N715201 | Holden Australia |
| 5430922 | Connector Reconnection | N715202 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N715203 | Holden Australia |
| 5430922 | Connector Reconnection | N715302 | Holden Australia |
| 5430922 | Connector Reconnection | N715303 | Holden Australia |
| 5430922 | Connector Reconnection | N715304 | Holden Australia |
| 5430922 | Connector Reconnection | N715305 | Holden Australia |
| 5430922 | Connector Reconnection | N715306 | Holden Australia |
| 5430922 | Connector Reconnection | N715307 | Holden Australia |
| 5430922 | Connector Reconnection | N715308 | Holden Australia |
| 5430922 | Connector Reconnection | N715309 | Holden Australia |
| 5430922 | Connector Reconnection | N715310 | Holden Australia |
| 5430922 | Connector Reconnection | N715402 | Holden Australia |
| 5430922 | Connector Reconnection | N715406 | Holden Australia |
| 5430922 | Connector Reconnection | N715407 | Holden Australia |
| 5430922 | Connector Reconnection | N715408 | Holden Australia |
| 5430922 | Connector Reconnection | N715409 | Holden Australia |
| 5430922 | Connector Reconnection | N715410 | Holden Australia |
| 5430922 | Connector Reconnection | N715501 | Holden Australia |
| 5430922 | Connector Reconnection | N715502 | Holden Australia |
| 5430922 | Connector Reconnection | N715503 | Holden Australia |
| 5430922 | Connector Reconnection | N715504 | Holden Australia |
| 5430922 | Connector Reconnection | N715505 | Holden Australia |
| 5430922 | Connector Reconnection | N715506 | Holden Australia |
| 5430922 | Connector Reconnection | N715508 | Holden Australia |
| 5430922 | Connector Reconnection | N715510 | Holden Australia |
| 5430922 | Connector Reconnection | N715511 | Holden Australia |
| 5430922 | Connector Reconnection | N715512 | Holden Australia |
| 5430922 | Connector Reconnection | N715601 | Holden Australia |
| 5430922 | Connector Reconnection | N715602 | Holden Australia |
| 5430922 | Connector Reconnection | N715603 | Holden Australia |
| 5430922 | Connector Reconnection | N715604 | Holden Australia |
| 5430922 | Connector Reconnection | N715606 | Holden Australia |
| 5430922 | Connector Reconnection | N715607 | Holden Australia |
| 5430922 | Connector Reconnection | N715701 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N715702 | Holden Australia |
| 5430922 | Connector Reconnection | N715705 | Holden Australia |
| 5430922 | Connector Reconnection | N715706 | Holden Australia |
| 5430922 | Connector Reconnection | N715707 | Holden Australia |
| 5430922 | Connector Reconnection | N715708 | Holden Australia |
| 5430922 | Connector Reconnection | N715709 | Holden Australia |
| 5430922 | Connector Reconnection | N715710 | Holden Australia |
| 5430922 | Connector Reconnection | N715803 | Holden Australia |
| 5430922 | Connector Reconnection | N715805 | Holden Australia |
| 5430922 | Connector Reconnection | N715903 | Holden Australia |
| 5430922 | Connector Reconnection | N716002 | Holden Australia |
| 5430922 | Connector Reconnection | N716006 | Holden Australia |
| 5430922 | Connector Reconnection | N716103 | Holden Australia |
| 5430922 | Connector Reconnection | N716202 | Holden Australia |
| 5430922 | Connector Reconnection | N716301 | Holden Australia |
| 5430922 | Connector Reconnection | N716501 | Holden Australia |
| 5430922 | Connector Reconnection | N716502 | Holden Australia |
| 5430922 | Connector Reconnection | N716503 | Holden Australia |
| 5430922 | Connector Reconnection | N716504 | Holden Australia |
| 5430922 | Connector Reconnection | N716505 | Holden Australia |
| 5430922 | Connector Reconnection | N716506 | Holden Australia |
| 5430922 | Connector Reconnection | N716507 | Holden Australia |
| 5430922 | Connector Reconnection | N716508 | Holden Australia |
| 5430922 | Connector Reconnection | N716509 | Holden Australia |
| 5430922 | Connector Reconnection | N716510 | Holden Australia |
| 5430922 | Connector Reconnection | N716511 | Holden Australia |
| 5430922 | Connector Reconnection | N716512 | Holden Australia |
| 5430922 | Connector Reconnection | N716513 | Holden Australia |
| 5430922 | Connector Reconnection | N716514 | Holden Australia |
| 5430922 | Connector Reconnection | N716515 | Holden Australia |
| 5430922 | Connector Reconnection | N716605 | Holden Australia |
| 5430922 | Connector Reconnection | N716607 | Holden Australia |
| 5430922 | Connector Reconnection | N716801 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N716802 | Holden Australia |
| 5430922 | Connector Reconnection | N716803 | Holden Australia |
| 5430922 | Connector Reconnection | N716805 | Holden Australia |
| 5430922 | Connector Reconnection | N716808 | Holden Australia |
| 5430922 | Connector Reconnection | N717003 | Holden Australia |
| 5430922 | Connector Reconnection | N717004 | Holden Australia |
| 5430922 | Connector Reconnection | N717006 | Holden Australia |
| 5430922 | Connector Reconnection | N717009 | Holden Australia |
| 5430922 | Connector Reconnection | N717014 | Holden Australia |
| 5430922 | Connector Reconnection | N717101 | Holden Australia |
| 5430922 | Connector Reconnection | N717201 | Holden Australia |
| 5430922 | Connector Reconnection | N717202 | Holden Australia |
| 5430922 | Connector Reconnection | N717203 | Holden Australia |
| 5430922 | Connector Reconnection | N717204 | Holden Australia |
| 5430922 | Connector Reconnection | N717205 | Holden Australia |
| 5430922 | Connector Reconnection | N717206 | Holden Australia |
| 5430922 | Connector Reconnection | N717208 | Holden Australia |
| 5430922 | Connector Reconnection | N717209 | Holden Australia |
| 5430922 | Connector Reconnection | N717210 | Holden Australia |
| 5430922 | Connector Reconnection | N717211 | Holden Australia |
| 5430922 | Connector Reconnection | N717212 | Holden Australia |
| 5430922 | Connector Reconnection | N717213 | Holden Australia |
| 5430922 | Connector Reconnection | N717301 | Holden Australia |
| 5430922 | Connector Reconnection | N717407 | Holden Australia |
| 5430922 | Connector Reconnection | N717703 | Holden Australia |
| 5430922 | Connector Reconnection | N717706 | Holden Australia |
| 5430922 | Connector Reconnection | N717707 | Holden Australia |
| 5430922 | Connector Reconnection | N717803 | Holden Australia |
| 5430922 | Connector Reconnection | N717804 | Holden Australia |
| 5430922 | Connector Reconnection | N717901 | Holden Australia |
| 5430922 | Connector Reconnection | N717903 | Holden Australia |
| 5430922 | Connector Reconnection | N718001 | Holden Australia |
| 5430922 | Connector Reconnection | N718006 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N718105 | Holden Australia |
| 5430922 | Connector Reconnection | N718107 | Holden Australia |
| 5430922 | Connector Reconnection | N718111 | Holden Australia |
| 5430922 | Connector Reconnection | N718112 | Holden Australia |
| 5430922 | Connector Reconnection | N718116 | Holden Australia |
| 5430922 | Connector Reconnection | N718201 | Holden Australia |
| 5430922 | Connector Reconnection | N718203 | Holden Australia |
| 5430922 | Connector Reconnection | N718205 | Holden Australia |
| 5430922 | Connector Reconnection | N718212 | Holden Australia |
| 5430922 | Connector Reconnection | N718216 | Holden Australia |
| 5430922 | Connector Reconnection | N718219 | Holden Australia |
| 5430922 | Connector Reconnection | N718222 | Holden Australia |
| 5430922 | Connector Reconnection | N718225 | Holden Australia |
| 5430922 | Connector Reconnection | N718226 | Holden Australia |
| 5430922 | Connector Reconnection | N718228 | Holden Australia |
| 5430922 | Connector Reconnection | N718230 | Holden Australia |
| 5430922 | Connector Reconnection | N718234 | Holden Australia |
| 5430922 | Connector Reconnection | N718304 | Holden Australia |
| 5430922 | Connector Reconnection | N718307 | Holden Australia |
| 5430922 | Connector Reconnection | N718409 | Holden Australia |
| 5430922 | Connector Reconnection | N718410 | Holden Australia |
| 5430922 | Connector Reconnection | N718425 | Holden Australia |
| 5430922 | Connector Reconnection | N718703 | Holden Australia |
| 5430922 | Connector Reconnection | N718707 | Holden Australia |
| 5430922 | Connector Reconnection | N718709 | Holden Australia |
| 5430922 | Connector Reconnection | N718713 | Holden Australia |
| 5430922 | Connector Reconnection | N718714 | Holden Australia |
| 5430922 | Connector Reconnection | N718715 | Holden Australia |
| 5430922 | Connector Reconnection | N718716 | Holden Australia |
| 5430922 | Connector Reconnection | N718717 | Holden Australia |
| 5430922 | Connector Reconnection | N718718 | Holden Australia |
| 5430922 | Connector Reconnection | N718719 | Holden Australia |
| 5430922 | Connector Reconnection | N718804 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N719003 | Holden Australia |
| 5430922 | Connector Reconnection | N719006 | Holden Australia |
| 5430922 | Connector Reconnection | N719101 | Holden Australia |
| 5430922 | Connector Reconnection | N719102 | Holden Australia |
| 5430922 | Connector Reconnection | N719105 | Holden Australia |
| 5430922 | Connector Reconnection | N719110 | Holden Australia |
| 5430922 | Connector Reconnection | N719201 | Holden Australia |
| 5430922 | Connector Reconnection | N719202 | Holden Australia |
| 5430922 | Connector Reconnection | N719204 | Holden Australia |
| 5430922 | Connector Reconnection | N719207 | Holden Australia |
| 5430922 | Connector Reconnection | N719208 | Holden Australia |
| 5430922 | Connector Reconnection | N719210 | Holden Australia |
| 5430922 | Connector Reconnection | N719303 | Holden Australia |
| 5430922 | Connector Reconnection | N719304 | Holden Australia |
| 5430922 | Connector Reconnection | N719310 | Holden Australia |
| 5430922 | Connector Reconnection | N719311 | Holden Australia |
| 5430922 | Connector Reconnection | N719403 | Holden Australia |
| 5430922 | Connector Reconnection | N719404 | Holden Australia |
| 5430922 | Connector Reconnection | N719405 | Holden Australia |
| 5430922 | Connector Reconnection | N719406 | Holden Australia |
| 5430922 | Connector Reconnection | N730101 | Holden Australia |
| 5430922 | Connector Reconnection | N730102 | Holden Australia |
| 5430922 | Connector Reconnection | N730201 | Holden Australia |
| 5430922 | Connector Reconnection | N730204 | Holden Australia |
| 5430922 | Connector Reconnection | N730205 | Holden Australia |
| 5430922 | Connector Reconnection | N730301 | Holden Australia |
| 5430922 | Connector Reconnection | N730501 | Holden Australia |
| 5430922 | Connector Reconnection | N730603 | Holden Australia |
| 5430922 | Connector Reconnection | N730606 | Holden Australia |
| 5430922 | Connector Reconnection | N730702 | Holden Australia |
| 5430922 | Connector Reconnection | N730703 | Holden Australia |
| 5430922 | Connector Reconnection | N730704 | Holden Australia |
| 5430922 | Connector Reconnection | N730707 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N730806 | Holden Australia |
| 5430922 | Connector Reconnection | N730807 | Holden Australia |
| 5430922 | Connector Reconnection | N730808 | Holden Australia |
| 5430922 | Connector Reconnection | N730901 | Holden Australia |
| 5430922 | Connector Reconnection | N731103 | Holden Australia |
| 5430922 | Connector Reconnection | N731108 | Holden Australia |
| 5430922 | Connector Reconnection | N731111 | Holden Australia |
| 5430922 | Connector Reconnection | N731203 | Holden Australia |
| 5430922 | Connector Reconnection | N731206 | Holden Australia |
| 5430922 | Connector Reconnection | N731209 | Holden Australia |
| 5430922 | Connector Reconnection | N731212 | Holden Australia |
| 5430922 | Connector Reconnection | N731213 | Holden Australia |
| 5430922 | Connector Reconnection | N731301 | Holden Australia |
| 5430922 | Connector Reconnection | N731303 | Holden Australia |
| 5430922 | Connector Reconnection | N731304 | Holden Australia |
| 5430922 | Connector Reconnection | N731306 | Holden Australia |
| 5430922 | Connector Reconnection | N731601 | Holden Australia |
| 5430922 | Connector Reconnection | N731602 | Holden Australia |
| 5430922 | Connector Reconnection | N731606 | Holden Australia |
| 5430922 | Connector Reconnection | N731701 | Holden Australia |
| 5430922 | Connector Reconnection | N731702 | Holden Australia |
| 5430922 | Connector Reconnection | N731705 | Holden Australia |
| 5430922 | Connector Reconnection | N731706 | Holden Australia |
| 5430922 | Connector Reconnection | N731708 | Holden Australia |
| 5430922 | Connector Reconnection | N731709 | Holden Australia |
| 5430922 | Connector Reconnection | N731712 | Holden Australia |
| 5430922 | Connector Reconnection | N731713 | Holden Australia |
| 5430922 | Connector Reconnection | N731714 | Holden Australia |
| 5430922 | Connector Reconnection | N731715 | Holden Australia |
| 5430922 | Connector Reconnection | N731717 | Holden Australia |
| 5430922 | Connector Reconnection | N731719 | Holden Australia |
| 5430922 | Connector Reconnection | N731720 | Holden Australia |
| 5430922 | Connector Reconnection | N731722 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N731724 | Holden Australia |
| 5430922 | Connector Reconnection | N731726 | Holden Australia |
| 5430922 | Connector Reconnection | N731809 | Holden Australia |
| 5430922 | Connector Reconnection | N731810 | Holden Australia |
| 5430922 | Connector Reconnection | N731907 | Holden Australia |
| 5430922 | Connector Reconnection | N732002 | Holden Australia |
| 5430922 | Connector Reconnection | N732007 | Holden Australia |
| 5430922 | Connector Reconnection | N732008 | Holden Australia |
| 5430922 | Connector Reconnection | N732009 | Holden Australia |
| 5430922 | Connector Reconnection | N732011 | Holden Australia |
| 5430922 | Connector Reconnection | N732014 | Holden Australia |
| 5430922 | Connector Reconnection | N732015 | Holden Australia |
| 5430922 | Connector Reconnection | N732016 | Holden Australia |
| 5430922 | Connector Reconnection | N732017 | Holden Australia |
| 5430922 | Connector Reconnection | N732101 | Holden Australia |
| 5430922 | Connector Reconnection | N732108 | Holden Australia |
| 5430922 | Connector Reconnection | N732109 | Holden Australia |
| 5430922 | Connector Reconnection | N732112 | Holden Australia |
| 5430922 | Connector Reconnection | N732113 | Holden Australia |
| 5430922 | Connector Reconnection | N732114 | Holden Australia |
| 5430922 | Connector Reconnection | N732121 | Holden Australia |
| 5430922 | Connector Reconnection | N732303 | Holden Australia |
| 5430922 | Connector Reconnection | N732304 | Holden Australia |
| 5430922 | Connector Reconnection | N732306 | Holden Australia |
| 5430922 | Connector Reconnection | N732402 | Holden Australia |
| 5430922 | Connector Reconnection | N732403 | Holden Australia |
| 5430922 | Connector Reconnection | N732404 | Holden Australia |
| 5430922 | Connector Reconnection | N732405 | Holden Australia |
| 5430922 | Connector Reconnection | N732409 | Holden Australia |
| 5430922 | Connector Reconnection | N732502 | Holden Australia |
| 5430922 | Connector Reconnection | N732504 | Holden Australia |
| 5430922 | Connector Reconnection | N732505 | Holden Australia |
| 5430922 | Connector Reconnection | N732702 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N732704 | Holden Australia |
| 5430922 | Connector Reconnection | N732705 | Holden Australia |
| 5430922 | Connector Reconnection | N732708 | Holden Australia |
| 5430922 | Connector Reconnection | N732711 | Holden Australia |
| 5430922 | Connector Reconnection | N732716 | Holden Australia |
| 5430922 | Connector Reconnection | N732717 | Holden Australia |
| 5430922 | Connector Reconnection | N732902 | Holden Australia |
| 5430922 | Connector Reconnection | N732903 | Holden Australia |
| 5430922 | Connector Reconnection | N732905 | Holden Australia |
| 5430922 | Connector Reconnection | N732906 | Holden Australia |
| 5430922 | Connector Reconnection | N732907 | Holden Australia |
| 5430922 | Connector Reconnection | N732910 | Holden Australia |
| 5430922 | Connector Reconnection | N732912 | Holden Australia |
| 5430922 | Connector Reconnection | N732913 | Holden Australia |
| 5430922 | Connector Reconnection | N732915 | Holden Australia |
| 5430922 | Connector Reconnection | N733004 | Holden Australia |
| 5430922 | Connector Reconnection | N733104 | Holden Australia |
| 5430922 | Connector Reconnection | N733105 | Holden Australia |
| 5430922 | Connector Reconnection | N733201 | Holden Australia |
| 5430922 | Connector Reconnection | N733202 | Holden Australia |
| 5430922 | Connector Reconnection | N733302 | Holden Australia |
| 5430922 | Connector Reconnection | N733305 | Holden Australia |
| 5430922 | Connector Reconnection | N733306 | Holden Australia |
| 5430922 | Connector Reconnection | N733307 | Holden Australia |
| 5430922 | Connector Reconnection | N733310 | Holden Australia |
| 5430922 | Connector Reconnection | N733311 | Holden Australia |
| 5430922 | Connector Reconnection | N733312 | Holden Australia |
| 5430922 | Connector Reconnection | N733401 | Holden Australia |
| 5430922 | Connector Reconnection | N733402 | Holden Australia |
| 5430922 | Connector Reconnection | N733403 | Holden Australia |
| 5430922 | Connector Reconnection | N733502 | Holden Australia |
| 5430922 | Connector Reconnection | N733503 | Holden Australia |
| 5430922 | Connector Reconnection | N733510 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N733511 | Holden Australia |
| 5430922 | Connector Reconnection | N733513 | Holden Australia |
| 5430922 | Connector Reconnection | N733514 | Holden Australia |
| 5430922 | Connector Reconnection | N733515 | Holden Australia |
| 5430922 | Connector Reconnection | N733517 | Holden Australia |
| 5430922 | Connector Reconnection | N733525 | Holden Australia |
| 5430922 | Connector Reconnection | N733526 | Holden Australia |
| 5430922 | Connector Reconnection | N733528 | Holden Australia |
| 5430922 | Connector Reconnection | N733530 | Holden Australia |
| 5430922 | Connector Reconnection | N733531 | Holden Australia |
| 5430922 | Connector Reconnection | N733603 | Holden Australia |
| 5430922 | Connector Reconnection | N733701 | Holden Australia |
| 5430922 | Connector Reconnection | N733704 | Holden Australia |
| 5430922 | Connector Reconnection | N733801 | Holden Australia |
| 5430922 | Connector Reconnection | N733802 | Holden Australia |
| 5430922 | Connector Reconnection | N733803 | Holden Australia |
| 5430922 | Connector Reconnection | N733804 | Holden Australia |
| 5430922 | Connector Reconnection | N733805 | Holden Australia |
| 5430922 | Connector Reconnection | N733902 | Holden Australia |
| 5430922 | Connector Reconnection | N733906 | Holden Australia |
| 5430922 | Connector Reconnection | N734005 | Holden Australia |
| 5430922 | Connector Reconnection | N734102 | Holden Australia |
| 5430922 | Connector Reconnection | N734103 | Holden Australia |
| 5430922 | Connector Reconnection | N734104 | Holden Australia |
| 5430922 | Connector Reconnection | N734109 | Holden Australia |
| 5430922 | Connector Reconnection | N734205 | Holden Australia |
| 5430922 | Connector Reconnection | N734207 | Holden Australia |
| 5430922 | Connector Reconnection | N734209 | Holden Australia |
| 5430922 | Connector Reconnection | N734301 | Holden Australia |
| 5430922 | Connector Reconnection | N734304 | Holden Australia |
| 5430922 | Connector Reconnection | N734307 | Holden Australia |
| 5430922 | Connector Reconnection | N734401 | Holden Australia |
| 5430922 | Connector Reconnection | N734403 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N734404 | Holden Australia |
| 5430922 | Connector Reconnection | N734501 | Holden Australia |
| 5430922 | Connector Reconnection | N734502 | Holden Australia |
| 5430922 | Connector Reconnection | N734503 | Holden Australia |
| 5430922 | Connector Reconnection | N734601 | Holden Australia |
| 5430922 | Connector Reconnection | N734602 | Holden Australia |
| 5430922 | Connector Reconnection | N734603 | Holden Australia |
| 5430922 | Connector Reconnection | N734604 | Holden Australia |
| 5430922 | Connector Reconnection | N734605 | Holden Australia |
| 5430922 | Connector Reconnection | N734607 | Holden Australia |
| 5430922 | Connector Reconnection | N734608 | Holden Australia |
| 5430922 | Connector Reconnection | N734609 | Holden Australia |
| 5430922 | Connector Reconnection | N734610 | Holden Australia |
| 5430922 | Connector Reconnection | N734701 | Holden Australia |
| 5430922 | Connector Reconnection | N734702 | Holden Australia |
| 5430922 | Connector Reconnection | N734705 | Holden Australia |
| 5430922 | Connector Reconnection | N734706 | Holden Australia |
| 5430922 | Connector Reconnection | N734708 | Holden Australia |
| 5430922 | Connector Reconnection | N734709 | Holden Australia |
| 5430922 | Connector Reconnection | N734710 | Holden Australia |
| 5430922 | Connector Reconnection | N734801 | Holden Australia |
| 5430922 | Connector Reconnection | N734804 | Holden Australia |
| 5430922 | Connector Reconnection | N734806 | Holden Australia |
| 5430922 | Connector Reconnection | N734901 | Holden Australia |
| 5430922 | Connector Reconnection | N734904 | Holden Australia |
| 5430922 | Connector Reconnection | N734906 | Holden Australia |
| 5430922 | Connector Reconnection | N734907 | Holden Australia |
| 5430922 | Connector Reconnection | N735005 | Holden Australia |
| 5430922 | Connector Reconnection | N735008 | Holden Australia |
| 5430922 | Connector Reconnection | N735102 | Holden Australia |
| 5430922 | Connector Reconnection | N735103 | Holden Australia |
| 5430922 | Connector Reconnection | N735201 | Holden Australia |
| 5430922 | Connector Reconnection | N735203 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N735204 | Holden Australia |
| 5430922 | Connector Reconnection | N735205 | Holden Australia |
| 5430922 | Connector Reconnection | N735206 | Holden Australia |
| 5430922 | Connector Reconnection | N735207 | Holden Australia |
| 5430922 | Connector Reconnection | N735209 | Holden Australia |
| 5430922 | Connector Reconnection | N735302 | Holden Australia |
| 5430922 | Connector Reconnection | N735304 | Holden Australia |
| 5430922 | Connector Reconnection | N735305 | Holden Australia |
| 5430922 | Connector Reconnection | N735307 | Holden Australia |
| 5430922 | Connector Reconnection | N735308 | Holden Australia |
| 5430922 | Connector Reconnection | N735309 | Holden Australia |
| 5430922 | Connector Reconnection | N735310 | Holden Australia |
| 5430922 | Connector Reconnection | N735311 | Holden Australia |
| 5430922 | Connector Reconnection | N735312 | Holden Australia |
| 5430922 | Connector Reconnection | N735313 | Holden Australia |
| 5430922 | Connector Reconnection | N735314 | Holden Australia |
| 5430922 | Connector Reconnection | N735315 | Holden Australia |
| 5430922 | Connector Reconnection | N735401 | Holden Australia |
| 5430922 | Connector Reconnection | N735402 | Holden Australia |
| 5430922 | Connector Reconnection | N735403 | Holden Australia |
| 5430922 | Connector Reconnection | N735404 | Holden Australia |
| 5430922 | Connector Reconnection | N735405 | Holden Australia |
| 5430922 | Connector Reconnection | N735406 | Holden Australia |
| 5430922 | Connector Reconnection | N735501 | Holden Australia |
| 5430922 | Connector Reconnection | N735602 | Holden Australia |
| 5430922 | Connector Reconnection | N735607 | Holden Australia |
| 5430922 | Connector Reconnection | N735701 | Holden Australia |
| 5430922 | Connector Reconnection | N910105 | Holden Australia |
| 5430922 | Connector Reconnection | N910107 | Holden Australia |
| 5430922 | Connector Reconnection | N910108 | Holden Australia |
| 5430922 | Connector Reconnection | N910203 | Holden Australia |
| 5430922 | Connector Reconnection | N910205 | Holden Australia |
| 5430922 | Connector Reconnection | N910302 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N910305 | Holden Australia |
| 5430922 | Connector Reconnection | N910401 | Holden Australia |
| 5430922 | Connector Reconnection | N910402 | Holden Australia |
| 5430922 | Connector Reconnection | N910403 | Holden Australia |
| 5430922 | Connector Reconnection | N910404 | Holden Australia |
| 5430922 | Connector Reconnection | N910405 | Holden Australia |
| 5430922 | Connector Reconnection | N910406 | Holden Australia |
| 5430922 | Connector Reconnection | N910407 | Holden Australia |
| 5430922 | Connector Reconnection | N910408 | Holden Australia |
| 5430922 | Connector Reconnection | N910409 | Holden Australia |
| 5430922 | Connector Reconnection | N910410 | Holden Australia |
| 5430922 | Connector Reconnection | N910411 | Holden Australia |
| 5430922 | Connector Reconnection | N910412 | Holden Australia |
| 5430922 | Connector Reconnection | N910413 | Holden Australia |
| 5430922 | Connector Reconnection | N910501 | Holden Australia |
| 5430922 | Connector Reconnection | N910503 | Holden Australia |
| 5430922 | Connector Reconnection | N910504 | Holden Australia |
| 5430922 | Connector Reconnection | N910505 | Holden Australia |
| 5430922 | Connector Reconnection | N910506 | Holden Australia |
| 5430922 | Connector Reconnection | N910507 | Holden Australia |
| 5430922 | Connector Reconnection | N910508 | Holden Australia |
| 5430922 | Connector Reconnection | N910509 | Holden Australia |
| 5430922 | Connector Reconnection | N910601 | Holden Australia |
| 5430922 | Connector Reconnection | N910603 | Holden Australia |
| 5430922 | Connector Reconnection | N910604 | Holden Australia |
| 5430922 | Connector Reconnection | N910605 | Holden Australia |
| 5430922 | Connector Reconnection | N910607 | Holden Australia |
| 5430922 | Connector Reconnection | N910608 | Holden Australia |
| 5430922 | Connector Reconnection | N910609 | Holden Australia |
| 5430922 | Connector Reconnection | N910610 | Holden Australia |
| 5430922 | Connector Reconnection | N910611 | Holden Australia |
| 5430922 | Connector Reconnection | N910701 | Holden Australia |
| 5430922 | Connector Reconnection | N910703 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N910801 | Holden Australia |
| 5430922 | Connector Reconnection | N910803 | Holden Australia |
| 5430922 | Connector Reconnection | N910804 | Holden Australia |
| 5430922 | Connector Reconnection | N910805 | Holden Australia |
| 5430922 | Connector Reconnection | N910806 | Holden Australia |
| 5430922 | Connector Reconnection | N910807 | Holden Australia |
| 5430922 | Connector Reconnection | N910808 | Holden Australia |
| 5430922 | Connector Reconnection | N910810 | Holden Australia |
| 5430922 | Connector Reconnection | N910812 | Holden Australia |
| 5430922 | Connector Reconnection | N910901 | Holden Australia |
| 5430922 | Connector Reconnection | N910902 | Holden Australia |
| 5430922 | Connector Reconnection | N910903 | Holden Australia |
| 5430922 | Connector Reconnection | N910904 | Holden Australia |
| 5430922 | Connector Reconnection | N910905 | Holden Australia |
| 5430922 | Connector Reconnection | N910906 | Holden Australia |
| 5430922 | Connector Reconnection | N910907 | Holden Australia |
| 5430922 | Connector Reconnection | N910908 | Holden Australia |
| 5430922 | Connector Reconnection | N910909 | Holden Australia |
| 5430922 | Connector Reconnection | N910910 | Holden Australia |
| 5430922 | Connector Reconnection | N910911 | Holden Australia |
| 5430922 | Connector Reconnection | N910912 | Holden Australia |
| 5430922 | Connector Reconnection | N910913 | Holden Australia |
| 5430922 | Connector Reconnection | N910914 | Holden Australia |
| 5430922 | Connector Reconnection | N910915 | Holden Australia |
| 5430922 | Connector Reconnection | N910916 | Holden Australia |
| 5430922 | Connector Reconnection | N910918 | Holden Australia |
| 5430922 | Connector Reconnection | N910919 | Holden Australia |
| 5430922 | Connector Reconnection | N911002 | Holden Australia |
| 5430922 | Connector Reconnection | N911003 | Holden Australia |
| 5430922 | Connector Reconnection | N911004 | Holden Australia |
| 5430922 | Connector Reconnection | N911005 | Holden Australia |
| 5430922 | Connector Reconnection | N911007 | Holden Australia |
| 5430922 | Connector Reconnection | N911008 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N911009 | Holden Australia |
| 5430922 | Connector Reconnection | N911010 | Holden Australia |
| 5430922 | Connector Reconnection | N911011 | Holden Australia |
| 5430922 | Connector Reconnection | N911012 | Holden Australia |
| 5430922 | Connector Reconnection | N911013 | Holden Australia |
| 5430922 | Connector Reconnection | N911102 | Holden Australia |
| 5430922 | Connector Reconnection | N911103 | Holden Australia |
| 5430922 | Connector Reconnection | N911104 | Holden Australia |
| 5430922 | Connector Reconnection | N911106 | Holden Australia |
| 5430922 | Connector Reconnection | N911107 | Holden Australia |
| 5430922 | Connector Reconnection | N911108 | Holden Australia |
| 5430922 | Connector Reconnection | N911201 | Holden Australia |
| 5430922 | Connector Reconnection | N911202 | Holden Australia |
| 5430922 | Connector Reconnection | N911203 | Holden Australia |
| 5430922 | Connector Reconnection | N911204 | Holden Australia |
| 5430922 | Connector Reconnection | N911205 | Holden Australia |
| 5430922 | Connector Reconnection | N911206 | Holden Australia |
| 5430922 | Connector Reconnection | N911207 | Holden Australia |
| 5430922 | Connector Reconnection | N911208 | Holden Australia |
| 5430922 | Connector Reconnection | N911209 | Holden Australia |
| 5430922 | Connector Reconnection | N911210 | Holden Australia |
| 5430922 | Connector Reconnection | N911211 | Holden Australia |
| 5430922 | Connector Reconnection | N911212 | Holden Australia |
| 5430922 | Connector Reconnection | N911213 | Holden Australia |
| 5430922 | Connector Reconnection | N911214 | Holden Australia |
| 5430922 | Connector Reconnection | N911302 | Holden Australia |
| 5430922 | Connector Reconnection | N911303 | Holden Australia |
| 5430922 | Connector Reconnection | N911304 | Holden Australia |
| 5430922 | Connector Reconnection | N911305 | Holden Australia |
| 5430922 | Connector Reconnection | N911306 | Holden Australia |
| 5430922 | Connector Reconnection | N911307 | Holden Australia |
| 5430922 | Connector Reconnection | N911308 | Holden Australia |
| 5430922 | Connector Reconnection | N911309 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N911310 | Holden Australia |
| 5430922 | Connector Reconnection | N911311 | Holden Australia |
| 5430922 | Connector Reconnection | N911312 | Holden Australia |
| 5430922 | Connector Reconnection | N911313 | Holden Australia |
| 5430922 | Connector Reconnection | N911314 | Holden Australia |
| 5430922 | Connector Reconnection | N911315 | Holden Australia |
| 5430922 | Connector Reconnection | N911316 | Holden Australia |
| 5430922 | Connector Reconnection | N911317 | Holden Australia |
| 5430922 | Connector Reconnection | N911318 | Holden Australia |
| 5430922 | Connector Reconnection | N911319 | Holden Australia |
| 5430922 | Connector Reconnection | N911320 | Holden Australia |
| 5430922 | Connector Reconnection | N911321 | Holden Australia |
| 5430922 | Connector Reconnection | N911322 | Holden Australia |
| 5430922 | Connector Reconnection | N911323 | Holden Australia |
| 5430922 | Connector Reconnection | N911502 | Holden Australia |
| 5430922 | Connector Reconnection | N911503 | Holden Australia |
| 5430922 | Connector Reconnection | N911504 | Holden Australia |
| 5430922 | Connector Reconnection | N911505 | Holden Australia |
| 5430922 | Connector Reconnection | N911506 | Holden Australia |
| 5430922 | Connector Reconnection | N911507 | Holden Australia |
| 5430922 | Connector Reconnection | N911508 | Holden Australia |
| 5430922 | Connector Reconnection | N911601 | Holden Australia |
| 5430922 | Connector Reconnection | N911602 | Holden Australia |
| 5430922 | Connector Reconnection | N911603 | Holden Australia |
| 5430922 | Connector Reconnection | N911604 | Holden Australia |
| 5430922 | Connector Reconnection | N911605 | Holden Australia |
| 5430922 | Connector Reconnection | N911606 | Holden Australia |
| 5430922 | Connector Reconnection | N911607 | Holden Australia |
| 5430922 | Connector Reconnection | N911608 | Holden Australia |
| 5430922 | Connector Reconnection | N911609 | Holden Australia |
| 5430922 | Connector Reconnection | N911610 | Holden Australia |
| 5430922 | Connector Reconnection | N911612 | Holden Australia |
| 5430922 | Connector Reconnection | N911613 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N911614 | Holden Australia |
| 5430922 | Connector Reconnection | N911615 | Holden Australia |
| 5430922 | Connector Reconnection | N911616 | Holden Australia |
| 5430922 | Connector Reconnection | N911701 | Holden Australia |
| 5430922 | Connector Reconnection | N911702 | Holden Australia |
| 5430922 | Connector Reconnection | N911703 | Holden Australia |
| 5430922 | Connector Reconnection | N911704 | Holden Australia |
| 5430922 | Connector Reconnection | N911705 | Holden Australia |
| 5430922 | Connector Reconnection | N911706 | Holden Australia |
| 5430922 | Connector Reconnection | N911707 | Holden Australia |
| 5430922 | Connector Reconnection | N911708 | Holden Australia |
| 5430922 | Connector Reconnection | N911709 | Holden Australia |
| 5430922 | Connector Reconnection | N911710 | Holden Australia |
| 5430922 | Connector Reconnection | N911711 | Holden Australia |
| 5430922 | Connector Reconnection | N911712 | Holden Australia |
| 5430922 | Connector Reconnection | N911713 | Holden Australia |
| 5430922 | Connector Reconnection | N911714 | Holden Australia |
| 5430922 | Connector Reconnection | N911715 | Holden Australia |
| 5430922 | Connector Reconnection | N911716 | Holden Australia |
| 5430922 | Connector Reconnection | N911717 | Holden Australia |
| 5430922 | Connector Reconnection | N911718 | Holden Australia |
| 5430922 | Connector Reconnection | N911719 | Holden Australia |
| 5430922 | Connector Reconnection | N911721 | Holden Australia |
| 5430922 | Connector Reconnection | N911722 | Holden Australia |
| 5430922 | Connector Reconnection | N911802 | Holden Australia |
| 5430922 | Connector Reconnection | N911803 | Holden Australia |
| 5430922 | Connector Reconnection | N911804 | Holden Australia |
| 5430922 | Connector Reconnection | N911805 | Holden Australia |
| 5430922 | Connector Reconnection | N911806 | Holden Australia |
| 5430922 | Connector Reconnection | N911807 | Holden Australia |
| 5430922 | Connector Reconnection | N911808 | Holden Australia |
| 5430922 | Connector Reconnection | N911809 | Holden Australia |
| 5430922 | Connector Reconnection | N911811 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N911812 | Holden Australia |
| 5430922 | Connector Reconnection | N911813 | Holden Australia |
| 5430922 | Connector Reconnection | N911814 | Holden Australia |
| 5430922 | Connector Reconnection | N911815 | Holden Australia |
| 5430922 | Connector Reconnection | N911817 | Holden Australia |
| 5430922 | Connector Reconnection | N911818 | Holden Australia |
| 5430922 | Connector Reconnection | N911819 | Holden Australia |
| 5430922 | Connector Reconnection | N911901 | Holden Australia |
| 5430922 | Connector Reconnection | N911902 | Holden Australia |
| 5430922 | Connector Reconnection | N911903 | Holden Australia |
| 5430922 | Connector Reconnection | N911904 | Holden Australia |
| 5430922 | Connector Reconnection | N911905 | Holden Australia |
| 5430922 | Connector Reconnection | N911906 | Holden Australia |
| 5430922 | Connector Reconnection | N911907 | Holden Australia |
| 5430922 | Connector Reconnection | N911908 | Holden Australia |
| 5430922 | Connector Reconnection | N911909 | Holden Australia |
| 5430922 | Connector Reconnection | N911910 | Holden Australia |
| 5430922 | Connector Reconnection | N911911 | Holden Australia |
| 5430922 | Connector Reconnection | N911912 | Holden Australia |
| 5430922 | Connector Reconnection | N911913 | Holden Australia |
| 5430922 | Connector Reconnection | N911914 | Holden Australia |
| 5430922 | Connector Reconnection | N911915 | Holden Australia |
| 5430922 | Connector Reconnection | N911916 | Holden Australia |
| 5430922 | Connector Reconnection | N911917 | Holden Australia |
| 5430922 | Connector Reconnection | N911918 | Holden Australia |
| 5430922 | Connector Reconnection | N911919 | Holden Australia |
| 5430922 | Connector Reconnection | N911920 | Holden Australia |
| 5430922 | Connector Reconnection | N911921 | Holden Australia |
| 5430922 | Connector Reconnection | N911922 | Holden Australia |
| 5430922 | Connector Reconnection | N911924 | Holden Australia |
| 5430922 | Connector Reconnection | N911925 | Holden Australia |
| 5430922 | Connector Reconnection | N911926 | Holden Australia |
| 5430922 | Connector Reconnection | N912101 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N912102 | Holden Australia |
| 5430922 | Connector Reconnection | N912103 | Holden Australia |
| 5430922 | Connector Reconnection | N912104 | Holden Australia |
| 5430922 | Connector Reconnection | N912105 | Holden Australia |
| 5430922 | Connector Reconnection | N912201 | Holden Australia |
| 5430922 | Connector Reconnection | N912202 | Holden Australia |
| 5430922 | Connector Reconnection | N912203 | Holden Australia |
| 5430922 | Connector Reconnection | N912204 | Holden Australia |
| 5430922 | Connector Reconnection | N912205 | Holden Australia |
| 5430922 | Connector Reconnection | N912206 | Holden Australia |
| 5430922 | Connector Reconnection | N912207 | Holden Australia |
| 5430922 | Connector Reconnection | N912208 | Holden Australia |
| 5430922 | Connector Reconnection | N912209 | Holden Australia |
| 5430922 | Connector Reconnection | N912210 | Holden Australia |
| 5430922 | Connector Reconnection | N912211 | Holden Australia |
| 5430922 | Connector Reconnection | N912212 | Holden Australia |
| 5430922 | Connector Reconnection | N912301 | Holden Australia |
| 5430922 | Connector Reconnection | N912302 | Holden Australia |
| 5430922 | Connector Reconnection | N912303 | Holden Australia |
| 5430922 | Connector Reconnection | N912304 | Holden Australia |
| 5430922 | Connector Reconnection | N912305 | Holden Australia |
| 5430922 | Connector Reconnection | N912306 | Holden Australia |
| 5430922 | Connector Reconnection | N912501 | Holden Australia |
| 5430922 | Connector Reconnection | N912502 | Holden Australia |
| 5430922 | Connector Reconnection | N912503 | Holden Australia |
| 5430922 | Connector Reconnection | N912504 | Holden Australia |
| 5430922 | Connector Reconnection | N912505 | Holden Australia |
| 5430922 | Connector Reconnection | N912506 | Holden Australia |
| 5430922 | Connector Reconnection | N912507 | Holden Australia |
| 5430922 | Connector Reconnection | N912508 | Holden Australia |
| 5430922 | Connector Reconnection | N912509 | Holden Australia |
| 5430922 | Connector Reconnection | N912510 | Holden Australia |
| 5430922 | Connector Reconnection | N912511 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N912512 | Holden Australia |
| 5430922 | Connector Reconnection | N912514 | Holden Australia |
| 5430922 | Connector Reconnection | N912515 | Holden Australia |
| 5430922 | Connector Reconnection | N912516 | Holden Australia |
| 5430922 | Connector Reconnection | N912518 | Holden Australia |
| 5430922 | Connector Reconnection | N912519 | Holden Australia |
| 5430922 | Connector Reconnection | N912520 | Holden Australia |
| 5430922 | Connector Reconnection | N912521 | Holden Australia |
| 5430922 | Connector Reconnection | N912522 | Holden Australia |
| 5430922 | Connector Reconnection | N912523 | Holden Australia |
| 5430922 | Connector Reconnection | N912601 | Holden Australia |
| 5430922 | Connector Reconnection | N912602 | Holden Australia |
| 5430922 | Connector Reconnection | N912603 | Holden Australia |
| 5430922 | Connector Reconnection | N912604 | Holden Australia |
| 5430922 | Connector Reconnection | N912605 | Holden Australia |
| 5430922 | Connector Reconnection | N912606 | Holden Australia |
| 5430922 | Connector Reconnection | N912607 | Holden Australia |
| 5430922 | Connector Reconnection | N912609 | Holden Australia |
| 5430922 | Connector Reconnection | N912612 | Holden Australia |
| 5430922 | Connector Reconnection | N912613 | Holden Australia |
| 5430922 | Connector Reconnection | N912701 | Holden Australia |
| 5430922 | Connector Reconnection | N912702 | Holden Australia |
| 5430922 | Connector Reconnection | N912704 | Holden Australia |
| 5430922 | Connector Reconnection | N912708 | Holden Australia |
| 5430922 | Connector Reconnection | N912801 | Holden Australia |
| 5430922 | Connector Reconnection | N912802 | Holden Australia |
| 5430922 | Connector Reconnection | N912901 | Holden Australia |
| 5430922 | Connector Reconnection | N912902 | Holden Australia |
| 5430922 | Connector Reconnection | N912903 | Holden Australia |
| 5430922 | Connector Reconnection | N912904 | Holden Australia |
| 5430922 | Connector Reconnection | N912905 | Holden Australia |
| 5430922 | Connector Reconnection | N912906 | Holden Australia |
| 5430922 | Connector Reconnection | N912907 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N912908 | Holden Australia |
| 5430922 | Connector Reconnection | N912909 | Holden Australia |
| 5430922 | Connector Reconnection | N912910 | Holden Australia |
| 5430922 | Connector Reconnection | N912912 | Holden Australia |
| 5430922 | Connector Reconnection | N912914 | Holden Australia |
| 5430922 | Connector Reconnection | N912915 | Holden Australia |
| 5430922 | Connector Reconnection | N912916 | Holden Australia |
| 5430922 | Connector Reconnection | N913001 | Holden Australia |
| 5430922 | Connector Reconnection | N913002 | Holden Australia |
| 5430922 | Connector Reconnection | N913003 | Holden Australia |
| 5430922 | Connector Reconnection | N913005 | Holden Australia |
| 5430922 | Connector Reconnection | N913007 | Holden Australia |
| 5430922 | Connector Reconnection | N913008 | Holden Australia |
| 5430922 | Connector Reconnection | N913009 | Holden Australia |
| 5430922 | Connector Reconnection | N913010 | Holden Australia |
| 5430922 | Connector Reconnection | N913012 | Holden Australia |
| 5430922 | Connector Reconnection | N913013 | Holden Australia |
| 5430922 | Connector Reconnection | N913014 | Holden Australia |
| 5430922 | Connector Reconnection | N913015 | Holden Australia |
| 5430922 | Connector Reconnection | N913016 | Holden Australia |
| 5430922 | Connector Reconnection | N913101 | Holden Australia |
| 5430922 | Connector Reconnection | N913102 | Holden Australia |
| 5430922 | Connector Reconnection | N913103 | Holden Australia |
| 5430922 | Connector Reconnection | N913106 | Holden Australia |
| 5430922 | Connector Reconnection | N913107 | Holden Australia |
| 5430922 | Connector Reconnection | N913108 | Holden Australia |
| 5430922 | Connector Reconnection | N913110 | Holden Australia |
| 5430922 | Connector Reconnection | N913111 | Holden Australia |
| 5430922 | Connector Reconnection | N913201 | Holden Australia |
| 5430922 | Connector Reconnection | N913202 | Holden Australia |
| 5430922 | Connector Reconnection | N913203 | Holden Australia |
| 5430922 | Connector Reconnection | N913301 | Holden Australia |
| 5430922 | Connector Reconnection | N913302 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N913303 | Holden Australia |
| 5430922 | Connector Reconnection | N913304 | Holden Australia |
| 5430922 | Connector Reconnection | N913305 | Holden Australia |
| 5430922 | Connector Reconnection | N913306 | Holden Australia |
| 5430922 | Connector Reconnection | N913308 | Holden Australia |
| 5430922 | Connector Reconnection | N913309 | Holden Australia |
| 5430922 | Connector Reconnection | N913310 | Holden Australia |
| 5430922 | Connector Reconnection | N913311 | Holden Australia |
| 5430922 | Connector Reconnection | N913312 | Holden Australia |
| 5430922 | Connector Reconnection | N913502 | Holden Australia |
| 5430922 | Connector Reconnection | N913503 | Holden Australia |
| 5430922 | Connector Reconnection | N913504 | Holden Australia |
| 5430922 | Connector Reconnection | N913505 | Holden Australia |
| 5430922 | Connector Reconnection | N913506 | Holden Australia |
| 5430922 | Connector Reconnection | N913507 | Holden Australia |
| 5430922 | Connector Reconnection | N913508 | Holden Australia |
| 5430922 | Connector Reconnection | N913509 | Holden Australia |
| 5430922 | Connector Reconnection | N913510 | Holden Australia |
| 5430922 | Connector Reconnection | N913512 | Holden Australia |
| 5430922 | Connector Reconnection | N913601 | Holden Australia |
| 5430922 | Connector Reconnection | N913602 | Holden Australia |
| 5430922 | Connector Reconnection | N913603 | Holden Australia |
| 5430922 | Connector Reconnection | N913605 | Holden Australia |
| 5430922 | Connector Reconnection | N913701 | Holden Australia |
| 5430922 | Connector Reconnection | N913702 | Holden Australia |
| 5430922 | Connector Reconnection | N913703 | Holden Australia |
| 5430922 | Connector Reconnection | N913704 | Holden Australia |
| 5430922 | Connector Reconnection | N913705 | Holden Australia |
| 5430922 | Connector Reconnection | N913706 | Holden Australia |
| 5430922 | Connector Reconnection | N913707 | Holden Australia |
| 5430922 | Connector Reconnection | N913708 | Holden Australia |
| 5430922 | Connector Reconnection | N913801 | Holden Australia |
| 5430922 | Connector Reconnection | N913802 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N913901 | Holden Australia |
| 5430922 | Connector Reconnection | N913902 | Holden Australia |
| 5430922 | Connector Reconnection | N913903 | Holden Australia |
| 5430922 | Connector Reconnection | N913904 | Holden Australia |
| 5430922 | Connector Reconnection | N913906 | Holden Australia |
| 5430922 | Connector Reconnection | N914001 | Holden Australia |
| 5430922 | Connector Reconnection | N914002 | Holden Australia |
| 5430922 | Connector Reconnection | N914003 | Holden Australia |
| 5430922 | Connector Reconnection | N914004 | Holden Australia |
| 5430922 | Connector Reconnection | N914005 | Holden Australia |
| 5430922 | Connector Reconnection | N914006 | Holden Australia |
| 5430922 | Connector Reconnection | N914007 | Holden Australia |
| 5430922 | Connector Reconnection | N914008 | Holden Australia |
| 5430922 | Connector Reconnection | N914101 | Holden Australia |
| 5430922 | Connector Reconnection | N914102 | Holden Australia |
| 5430922 | Connector Reconnection | N914103 | Holden Australia |
| 5430922 | Connector Reconnection | N914104 | Holden Australia |
| 5430922 | Connector Reconnection | N914105 | Holden Australia |
| 5430922 | Connector Reconnection | N914107 | Holden Australia |
| 5430922 | Connector Reconnection | N914108 | Holden Australia |
| 5430922 | Connector Reconnection | N914109 | Holden Australia |
| 5430922 | Connector Reconnection | N914110 | Holden Australia |
| 5430922 | Connector Reconnection | N914111 | Holden Australia |
| 5430922 | Connector Reconnection | N914112 | Holden Australia |
| 5430922 | Connector Reconnection | N914113 | Holden Australia |
| 5430922 | Connector Reconnection | N914114 | Holden Australia |
| 5430922 | Connector Reconnection | N914115 | Holden Australia |
| 5430922 | Connector Reconnection | N914116 | Holden Australia |
| 5430922 | Connector Reconnection | N914117 | Holden Australia |
| 5430922 | Connector Reconnection | N914119 | Holden Australia |
| 5430922 | Connector Reconnection | N914120 | Holden Australia |
| 5430922 | Connector Reconnection | N914121 | Holden Australia |
| 5430922 | Connector Reconnection | N914122 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N914123 | Holden Australia |
| 5430922 | Connector Reconnection | N914124 | Holden Australia |
| 5430922 | Connector Reconnection | N914125 | Holden Australia |
| 5430922 | Connector Reconnection | N914126 | Holden Australia |
| 5430922 | Connector Reconnection | N914127 | Holden Australia |
| 5430922 | Connector Reconnection | N914128 | Holden Australia |
| 5430922 | Connector Reconnection | N914129 | Holden Australia |
| 5430922 | Connector Reconnection | N914130 | Holden Australia |
| 5430922 | Connector Reconnection | N914131 | Holden Australia |
| 5430922 | Connector Reconnection | N914132 | Holden Australia |
| 5430922 | Connector Reconnection | N914301 | Holden Australia |
| 5430922 | Connector Reconnection | N914302 | Holden Australia |
| 5430922 | Connector Reconnection | N914303 | Holden Australia |
| 5430922 | Connector Reconnection | N914401 | Holden Australia |
| 5430922 | Connector Reconnection | N914402 | Holden Australia |
| 5430922 | Connector Reconnection | N914501 | Holden Australia |
| 5430922 | Connector Reconnection | N914502 | Holden Australia |
| 5430922 | Connector Reconnection | N914503 | Holden Australia |
| 5430922 | Connector Reconnection | N914504 | Holden Australia |
| 5430922 | Connector Reconnection | N914505 | Holden Australia |
| 5430922 | Connector Reconnection | N914506 | Holden Australia |
| 5430922 | Connector Reconnection | N914507 | Holden Australia |
| 5430922 | Connector Reconnection | N914508 | Holden Australia |
| 5430922 | Connector Reconnection | N914509 | Holden Australia |
| 5430922 | Connector Reconnection | N914510 | Holden Australia |
| 5430922 | Connector Reconnection | N914601 | Holden Australia |
| 5430922 | Connector Reconnection | N914602 | Holden Australia |
| 5430922 | Connector Reconnection | N914603 | Holden Australia |
| 5430922 | Connector Reconnection | N914604 | Holden Australia |
| 5430922 | Connector Reconnection | N914702 | Holden Australia |
| 5430922 | Connector Reconnection | N914703 | Holden Australia |
| 5430922 | Connector Reconnection | N914704 | Holden Australia |
| 5430922 | Connector Reconnection | N914705 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N914706 | Holden Australia |
| 5430922 | Connector Reconnection | N914707 | Holden Australia |
| 5430922 | Connector Reconnection | N914709 | Holden Australia |
| 5430922 | Connector Reconnection | N914710 | Holden Australia |
| 5430922 | Connector Reconnection | N914711 | Holden Australia |
| 5430922 | Connector Reconnection | N914801 | Holden Australia |
| 5430922 | Connector Reconnection | N914805 | Holden Australia |
| 5430922 | Connector Reconnection | N914806 | Holden Australia |
| 5430922 | Connector Reconnection | N914807 | Holden Australia |
| 5430922 | Connector Reconnection | N914808 | Holden Australia |
| 5430922 | Connector Reconnection | N914809 | Holden Australia |
| 5430922 | Connector Reconnection | N914810 | Holden Australia |
| 5430922 | Connector Reconnection | N914813 | Holden Australia |
| 5430922 | Connector Reconnection | N914901 | Holden Australia |
| 5430922 | Connector Reconnection | N914902 | Holden Australia |
| 5430922 | Connector Reconnection | N914903 | Holden Australia |
| 5430922 | Connector Reconnection | N914904 | Holden Australia |
| 5430922 | Connector Reconnection | N914905 | Holden Australia |
| 5430922 | Connector Reconnection | N914906 | Holden Australia |
| 5430922 | Connector Reconnection | N914908 | Holden Australia |
| 5430922 | Connector Reconnection | N914909 | Holden Australia |
| 5430922 | Connector Reconnection | N914911 | Holden Australia |
| 5430922 | Connector Reconnection | N914912 | Holden Australia |
| 5430922 | Connector Reconnection | N914913 | Holden Australia |
| 5430922 | Connector Reconnection | N914914 | Holden Australia |
| 5430922 | Connector Reconnection | N914915 | Holden Australia |
| 5430922 | Connector Reconnection | N914916 | Holden Australia |
| 5430922 | Connector Reconnection | N914917 | Holden Australia |
| 5430922 | Connector Reconnection | N914918 | Holden Australia |
| 5430922 | Connector Reconnection | N914919 | Holden Australia |
| 5430922 | Connector Reconnection | N914920 | Holden Australia |
| 5430922 | Connector Reconnection | N915001 | Holden Australia |
| 5430922 | Connector Reconnection | N915002 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N915003 | Holden Australia |
| 5430922 | Connector Reconnection | N915005 | Holden Australia |
| 5430922 | Connector Reconnection | N915006 | Holden Australia |
| 5430922 | Connector Reconnection | N915008 | Holden Australia |
| 5430922 | Connector Reconnection | N915009 | Holden Australia |
| 5430922 | Connector Reconnection | N915010 | Holden Australia |
| 5430922 | Connector Reconnection | N915013 | Holden Australia |
| 5430922 | Connector Reconnection | N915014 | Holden Australia |
| 5430922 | Connector Reconnection | N915015 | Holden Australia |
| 5430922 | Connector Reconnection | N915016 | Holden Australia |
| 5430922 | Connector Reconnection | N915017 | Holden Australia |
| 5430922 | Connector Reconnection | N915022 | Holden Australia |
| 5430922 | Connector Reconnection | N915023 | Holden Australia |
| 5430922 | Connector Reconnection | N915024 | Holden Australia |
| 5430922 | Connector Reconnection | N915025 | Holden Australia |
| 5430922 | Connector Reconnection | N915026 | Holden Australia |
| 5430922 | Connector Reconnection | N915027 | Holden Australia |
| 5430922 | Connector Reconnection | N915028 | Holden Australia |
| 5430922 | Connector Reconnection | N915101 | Holden Australia |
| 5430922 | Connector Reconnection | N915102 | Holden Australia |
| 5430922 | Connector Reconnection | N915103 | Holden Australia |
| 5430922 | Connector Reconnection | N915104 | Holden Australia |
| 5430922 | Connector Reconnection | N915201 | Holden Australia |
| 5430922 | Connector Reconnection | N915202 | Holden Australia |
| 5430922 | Connector Reconnection | N915204 | Holden Australia |
| 5430922 | Connector Reconnection | N915501 | Holden Australia |
| 5430922 | Connector Reconnection | N915503 | Holden Australia |
| 5430922 | Connector Reconnection | N915601 | Holden Australia |
| 5430922 | Connector Reconnection | N915602 | Holden Australia |
| 5430922 | Connector Reconnection | N915604 | Holden Australia |
| 5430922 | Connector Reconnection | N915605 | Holden Australia |
| 5430922 | Connector Reconnection | N915701 | Holden Australia |
| 5430922 | Connector Reconnection | N915702 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N915703 | Holden Australia |
| 5430922 | Connector Reconnection | N915704 | Holden Australia |
| 5430922 | Connector Reconnection | N915901 | Holden Australia |
| 5430922 | Connector Reconnection | N915902 | Holden Australia |
| 5430922 | Connector Reconnection | N915903 | Holden Australia |
| 5430922 | Connector Reconnection | N915904 | Holden Australia |
| 5430922 | Connector Reconnection | N915905 | Holden Australia |
| 5430922 | Connector Reconnection | N915906 | Holden Australia |
| 5430922 | Connector Reconnection | N915907 | Holden Australia |
| 5430922 | Connector Reconnection | N915908 | Holden Australia |
| 5430922 | Connector Reconnection | N915909 | Holden Australia |
| 5430922 | Connector Reconnection | N916001 | Holden Australia |
| 5430922 | Connector Reconnection | N916003 | Holden Australia |
| 5430922 | Connector Reconnection | N916004 | Holden Australia |
| 5430922 | Connector Reconnection | N916005 | Holden Australia |
| 5430922 | Connector Reconnection | N916006 | Holden Australia |
| 5430922 | Connector Reconnection | N916007 | Holden Australia |
| 5430922 | Connector Reconnection | N916008 | Holden Australia |
| 5430922 | Connector Reconnection | N916009 | Holden Australia |
| 5430922 | Connector Reconnection | N916010 | Holden Australia |
| 5430922 | Connector Reconnection | N916011 | Holden Australia |
| 5430922 | Connector Reconnection | N916012 | Holden Australia |
| 5430922 | Connector Reconnection | N916013 | Holden Australia |
| 5430922 | Connector Reconnection | N916014 | Holden Australia |
| 5430922 | Connector Reconnection | N916104 | Holden Australia |
| 5430922 | Connector Reconnection | N916107 | Holden Australia |
| 5430922 | Connector Reconnection | N916201 | Holden Australia |
| 5430922 | Connector Reconnection | N916202 | Holden Australia |
| 5430922 | Connector Reconnection | N916301 | Holden Australia |
| 5430922 | Connector Reconnection | N916302 | Holden Australia |
| 5430922 | Connector Reconnection | N916401 | Holden Australia |
| 5430922 | Connector Reconnection | N916402 | Holden Australia |
| 5430922 | Connector Reconnection | N916403 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N916404 | Holden Australia |
| 5430922 | Connector Reconnection | N916405 | Holden Australia |
| 5430922 | Connector Reconnection | N916406 | Holden Australia |
| 5430922 | Connector Reconnection | N916407 | Holden Australia |
| 5430922 | Connector Reconnection | N916408 | Holden Australia |
| 5430922 | Connector Reconnection | N916506 | Holden Australia |
| 5430922 | Connector Reconnection | N916614 | Holden Australia |
| 5430922 | Connector Reconnection | N916701 | Holden Australia |
| 5430922 | Connector Reconnection | N916802 | Holden Australia |
| 5430922 | Connector Reconnection | N916803 | Holden Australia |
| 5430922 | Connector Reconnection | N916810 | Holden Australia |
| 5430922 | Connector Reconnection | N916812 | Holden Australia |
| 5430922 | Connector Reconnection | N917002 | Holden Australia |
| 5430922 | Connector Reconnection | N917112 | Holden Australia |
| 5430922 | Connector Reconnection | N917116 | Holden Australia |
| 5430922 | Connector Reconnection | N917118 | Holden Australia |
| 5430922 | Connector Reconnection | N917207 | Holden Australia |
| 5430922 | Connector Reconnection | N917404 | Holden Australia |
| 5430922 | Connector Reconnection | N917405 | Holden Australia |
| 5430922 | Connector Reconnection | N917406 | Holden Australia |
| 5430922 | Connector Reconnection | N917502 | Holden Australia |
| 5430922 | Connector Reconnection | N917504 | Holden Australia |
| 5430922 | Connector Reconnection | N917508 | Holden Australia |
| 5430922 | Connector Reconnection | N917510 | Holden Australia |
| 5430922 | Connector Reconnection | N917601 | Holden Australia |
| 5430922 | Connector Reconnection | N917602 | Holden Australia |
| 5430922 | Connector Reconnection | N917606 | Holden Australia |
| 5430922 | Connector Reconnection | N917802 | Holden Australia |
| 5430922 | Connector Reconnection | N917906 | Holden Australia |
| 5430922 | Connector Reconnection | N917908 | Holden Australia |
| 5430922 | Connector Reconnection | N917911 | Holden Australia |
| 5430922 | Connector Reconnection | N918001 | Holden Australia |
| 5430922 | Connector Reconnection | N918003 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N918004 | Holden Australia |
| 5430922 | Connector Reconnection | N918005 | Holden Australia |
| 5430922 | Connector Reconnection | N918008 | Holden Australia |
| 5430922 | Connector Reconnection | N918009 | Holden Australia |
| 5430922 | Connector Reconnection | N918010 | Holden Australia |
| 5430922 | Connector Reconnection | N918011 | Holden Australia |
| 5430922 | Connector Reconnection | N930108 | Holden Australia |
| 5430922 | Connector Reconnection | N930205 | Holden Australia |
| 5430922 | Connector Reconnection | N930403 | Holden Australia |
| 5430922 | Connector Reconnection | N930405 | Holden Australia |
| 5430922 | Connector Reconnection | N930406 | Holden Australia |
| 5430922 | Connector Reconnection | N930409 | Holden Australia |
| 5430922 | Connector Reconnection | N930412 | Holden Australia |
| 5430922 | Connector Reconnection | N930604 | Holden Australia |
| 5430922 | Connector Reconnection | N930702 | Holden Australia |
| 5430922 | Connector Reconnection | N930801 | Holden Australia |
| 5430922 | Connector Reconnection | N930806 | Holden Australia |
| 5430922 | Connector Reconnection | N930807 | Holden Australia |
| 5430922 | Connector Reconnection | N930808 | Holden Australia |
| 5430922 | Connector Reconnection | N930811 | Holden Australia |
| 5430922 | Connector Reconnection | N930901 | Holden Australia |
| 5430922 | Connector Reconnection | N930903 | Holden Australia |
| 5430922 | Connector Reconnection | N930904 | Holden Australia |
| 5430922 | Connector Reconnection | N930905 | Holden Australia |
| 5430922 | Connector Reconnection | N930906 | Holden Australia |
| 5430922 | Connector Reconnection | N930910 | Holden Australia |
| 5430922 | Connector Reconnection | N930913 | Holden Australia |
| 5430922 | Connector Reconnection | N931004 | Holden Australia |
| 5430922 | Connector Reconnection | N931103 | Holden Australia |
| 5430922 | Connector Reconnection | N931204 | Holden Australia |
| 5430922 | Connector Reconnection | N931206 | Holden Australia |
| 5430922 | Connector Reconnection | N931212 | Holden Australia |
| 5430922 | Connector Reconnection | N931304 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N931308 | Holden Australia |
| 5430922 | Connector Reconnection | N931310 | Holden Australia |
| 5430922 | Connector Reconnection | N931314 | Holden Australia |
| 5430922 | Connector Reconnection | N931315 | Holden Australia |
| 5430922 | Connector Reconnection | N931318 | Holden Australia |
| 5430922 | Connector Reconnection | N931320 | Holden Australia |
| 5430922 | Connector Reconnection | N931324 | Holden Australia |
| 5430922 | Connector Reconnection | N931325 | Holden Australia |
| 5430922 | Connector Reconnection | N931326 | Holden Australia |
| 5430922 | Connector Reconnection | N931606 | Holden Australia |
| 5430922 | Connector Reconnection | N931607 | Holden Australia |
| 5430922 | Connector Reconnection | N931608 | Holden Australia |
| 5430922 | Connector Reconnection | N931609 | Holden Australia |
| 5430922 | Connector Reconnection | N931610 | Holden Australia |
| 5430922 | Connector Reconnection | N931612 | Holden Australia |
| 5430922 | Connector Reconnection | N931615 | Holden Australia |
| 5430922 | Connector Reconnection | N931617 | Holden Australia |
| 5430922 | Connector Reconnection | N931618 | Holden Australia |
| 5430922 | Connector Reconnection | N931619 | Holden Australia |
| 5430922 | Connector Reconnection | N931620 | Holden Australia |
| 5430922 | Connector Reconnection | N931621 | Holden Australia |
| 5430922 | Connector Reconnection | N931701 | Holden Australia |
| 5430922 | Connector Reconnection | N931702 | Holden Australia |
| 5430922 | Connector Reconnection | N931703 | Holden Australia |
| 5430922 | Connector Reconnection | N931705 | Holden Australia |
| 5430922 | Connector Reconnection | N931706 | Holden Australia |
| 5430922 | Connector Reconnection | N931708 | Holden Australia |
| 5430922 | Connector Reconnection | N931709 | Holden Australia |
| 5430922 | Connector Reconnection | N931710 | Holden Australia |
| 5430922 | Connector Reconnection | N931711 | Holden Australia |
| 5430922 | Connector Reconnection | N931714 | Holden Australia |
| 5430922 | Connector Reconnection | N931716 | Holden Australia |
| 5430922 | Connector Reconnection | N931718 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N931719 | Holden Australia |
| 5430922 | Connector Reconnection | N931720 | Holden Australia |
| 5430922 | Connector Reconnection | N931722 | Holden Australia |
| 5430922 | Connector Reconnection | N931725 | Holden Australia |
| 5430922 | Connector Reconnection | N931727 | Holden Australia |
| 5430922 | Connector Reconnection | N931901 | Holden Australia |
| 5430922 | Connector Reconnection | N931904 | Holden Australia |
| 5430922 | Connector Reconnection | N931905 | Holden Australia |
| 5430922 | Connector Reconnection | N932001 | Holden Australia |
| 5430922 | Connector Reconnection | N932003 | Holden Australia |
| 5430922 | Connector Reconnection | N932004 | Holden Australia |
| 5430922 | Connector Reconnection | N932006 | Holden Australia |
| 5430922 | Connector Reconnection | N932102 | Holden Australia |
| 5430922 | Connector Reconnection | N932103 | Holden Australia |
| 5430922 | Connector Reconnection | N932104 | Holden Australia |
| 5430922 | Connector Reconnection | N932105 | Holden Australia |
| 5430922 | Connector Reconnection | N932106 | Holden Australia |
| 5430922 | Connector Reconnection | N932301 | Holden Australia |
| 5430922 | Connector Reconnection | N932302 | Holden Australia |
| 5430922 | Connector Reconnection | N932303 | Holden Australia |
| 5430922 | Connector Reconnection | N932304 | Holden Australia |
| 5430922 | Connector Reconnection | N932305 | Holden Australia |
| 5430922 | Connector Reconnection | N932307 | Holden Australia |
| 5430922 | Connector Reconnection | N932312 | Holden Australia |
| 5430922 | Connector Reconnection | N932314 | Holden Australia |
| 5430922 | Connector Reconnection | N932317 | Holden Australia |
| 5430922 | Connector Reconnection | N932318 | Holden Australia |
| 5430922 | Connector Reconnection | N932319 | Holden Australia |
| 5430922 | Connector Reconnection | N932320 | Holden Australia |
| 5430922 | Connector Reconnection | N932402 | Holden Australia |
| 5430922 | Connector Reconnection | N932502 | Holden Australia |
| 5430922 | Connector Reconnection | N932503 | Holden Australia |
| 5430922 | Connector Reconnection | N932505 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N932508 | Holden Australia |
| 5430922 | Connector Reconnection | N932509 | Holden Australia |
| 5430922 | Connector Reconnection | N932510 | Holden Australia |
| 5430922 | Connector Reconnection | N932512 | Holden Australia |
| 5430922 | Connector Reconnection | N932513 | Holden Australia |
| 5430922 | Connector Reconnection | N932602 | Holden Australia |
| 5430922 | Connector Reconnection | N932603 | Holden Australia |
| 5430922 | Connector Reconnection | N932604 | Holden Australia |
| 5430922 | Connector Reconnection | N932703 | Holden Australia |
| 5430922 | Connector Reconnection | N932804 | Holden Australia |
| 5430922 | Connector Reconnection | N932806 | Holden Australia |
| 5430922 | Connector Reconnection | N932807 | Holden Australia |
| 5430922 | Connector Reconnection | N932901 | Holden Australia |
| 5430922 | Connector Reconnection | N932902 | Holden Australia |
| 5430922 | Connector Reconnection | N932903 | Holden Australia |
| 5430922 | Connector Reconnection | N932905 | Holden Australia |
| 5430922 | Connector Reconnection | N932906 | Holden Australia |
| 5430922 | Connector Reconnection | N932907 | Holden Australia |
| 5430922 | Connector Reconnection | N932908 | Holden Australia |
| 5430922 | Connector Reconnection | N932909 | Holden Australia |
| 5430922 | Connector Reconnection | N932910 | Holden Australia |
| 5430922 | Connector Reconnection | N932911 | Holden Australia |
| 5430922 | Connector Reconnection | N932912 | Holden Australia |
| 5430922 | Connector Reconnection | N932914 | Holden Australia |
| 5430922 | Connector Reconnection | N932915 | Holden Australia |
| 5430922 | Connector Reconnection | N933002 | Holden Australia |
| 5430922 | Connector Reconnection | N933003 | Holden Australia |
| 5430922 | Connector Reconnection | N933102 | Holden Australia |
| 5430922 | Connector Reconnection | N933103 | Holden Australia |
| 5430922 | Connector Reconnection | N933104 | Holden Australia |
| 5430922 | Connector Reconnection | N933201 | Holden Australia |
| 5430922 | Connector Reconnection | N933202 | Holden Australia |
| 5430922 | Connector Reconnection | N933203 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N933205 | Holden Australia |
| 5430922 | Connector Reconnection | N933206 | Holden Australia |
| 5430922 | Connector Reconnection | N933208 | Holden Australia |
| 5430922 | Connector Reconnection | N933210 | Holden Australia |
| 5430922 | Connector Reconnection | N933211 | Holden Australia |
| 5430922 | Connector Reconnection | N933212 | Holden Australia |
| 5430922 | Connector Reconnection | N933213 | Holden Australia |
| 5430922 | Connector Reconnection | N933214 | Holden Australia |
| 5430922 | Connector Reconnection | N933217 | Holden Australia |
| 5430922 | Connector Reconnection | N933224 | Holden Australia |
| 5430922 | Connector Reconnection | N933225 | Holden Australia |
| 5430922 | Connector Reconnection | N933226 | Holden Australia |
| 5430922 | Connector Reconnection | N933227 | Holden Australia |
| 5430922 | Connector Reconnection | N933228 | Holden Australia |
| 5430922 | Connector Reconnection | N933229 | Holden Australia |
| 5430922 | Connector Reconnection | N933231 | Holden Australia |
| 5430922 | Connector Reconnection | N933302 | Holden Australia |
| 5430922 | Connector Reconnection | N933401 | Holden Australia |
| 5430922 | Connector Reconnection | N933402 | Holden Australia |
| 5430922 | Connector Reconnection | N933501 | Holden Australia |
| 5430922 | Connector Reconnection | N933604 | Holden Australia |
| 5430922 | Connector Reconnection | N933605 | Holden Australia |
| 5430922 | Connector Reconnection | N933702 | Holden Australia |
| 5430922 | Connector Reconnection | N933704 | Holden Australia |
| 5430922 | Connector Reconnection | N933709 | Holden Australia |
| 5430922 | Connector Reconnection | N933710 | Holden Australia |
| 5430922 | Connector Reconnection | N933804 | Holden Australia |
| 5430922 | Connector Reconnection | N933806 | Holden Australia |
| 5430922 | Connector Reconnection | N933808 | Holden Australia |
| 5430922 | Connector Reconnection | N933814 | Holden Australia |
| 5430922 | Connector Reconnection | N933815 | Holden Australia |
| 5430922 | Connector Reconnection | N933820 | Holden Australia |
| 5430922 | Connector Reconnection | N933823 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N933901 | Holden Australia |
| 5430922 | Connector Reconnection | N933902 | Holden Australia |
| 5430922 | Connector Reconnection | N933903 | Holden Australia |
| 5430922 | Connector Reconnection | N933904 | Holden Australia |
| 5430922 | Connector Reconnection | N933905 | Holden Australia |
| 5430922 | Connector Reconnection | N933906 | Holden Australia |
| 5430922 | Connector Reconnection | N934001 | Holden Australia |
| 5430922 | Connector Reconnection | N934002 | Holden Australia |
| 5430922 | Connector Reconnection | N934003 | Holden Australia |
| 5430922 | Connector Reconnection | N934004 | Holden Australia |
| 5430922 | Connector Reconnection | N934101 | Holden Australia |
| 5430922 | Connector Reconnection | N934102 | Holden Australia |
| 5430922 | Connector Reconnection | N934103 | Holden Australia |
| 5430922 | Connector Reconnection | N934104 | Holden Australia |
| 5430922 | Connector Reconnection | N934105 | Holden Australia |
| 5430922 | Connector Reconnection | N934107 | Holden Australia |
| 5430922 | Connector Reconnection | N934108 | Holden Australia |
| 5430922 | Connector Reconnection | N934201 | Holden Australia |
| 5430922 | Connector Reconnection | N934202 | Holden Australia |
| 5430922 | Connector Reconnection | N934203 | Holden Australia |
| 5430922 | Connector Reconnection | N934205 | Holden Australia |
| 5430922 | Connector Reconnection | N934206 | Holden Australia |
| 5430922 | Connector Reconnection | N934207 | Holden Australia |
| 5430922 | Connector Reconnection | N934208 | Holden Australia |
| 5430922 | Connector Reconnection | N934210 | Holden Australia |
| 5430922 | Connector Reconnection | N934301 | Holden Australia |
| 5430922 | Connector Reconnection | N934302 | Holden Australia |
| 5430922 | Connector Reconnection | N934304 | Holden Australia |
| 5430922 | Connector Reconnection | N934306 | Holden Australia |
| 5430922 | Connector Reconnection | N934307 | Holden Australia |
| 5430922 | Connector Reconnection | N934308 | Holden Australia |
| 5430922 | Connector Reconnection | N934309 | Holden Australia |
| 5430922 | Connector Reconnection | N934310 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N934311 | Holden Australia |
| 5430922 | Connector Reconnection | N934315 | Holden Australia |
| 5430922 | Connector Reconnection | N934316 | Holden Australia |
| 5430922 | Connector Reconnection | N934406 | Holden Australia |
| 5430922 | Connector Reconnection | N934409 | Holden Australia |
| 5430922 | Connector Reconnection | N934414 | Holden Australia |
| 5430922 | Connector Reconnection | N934418 | Holden Australia |
| 5430922 | Connector Reconnection | N934703 | Holden Australia |
| 5430922 | Connector Reconnection | N934801 | Holden Australia |
| 5430922 | Connector Reconnection | N934802 | Holden Australia |
| 5430922 | Connector Reconnection | N934901 | Holden Australia |
| 5430922 | Connector Reconnection | N934904 | Holden Australia |
| 5430922 | Connector Reconnection | N934905 | Holden Australia |
| 5430922 | Connector Reconnection | N934906 | Holden Australia |
| 5430922 | Connector Reconnection | N934907 | Holden Australia |
| 5430922 | Connector Reconnection | N934908 | Holden Australia |
| 5430922 | Connector Reconnection | N934909 | Holden Australia |
| 5430922 | Connector Reconnection | N935002 | Holden Australia |
| 5430922 | Connector Reconnection | N935003 | Holden Australia |
| 5430922 | Connector Reconnection | N935004 | Holden Australia |
| 5430922 | Connector Reconnection | N935005 | Holden Australia |
| 5430922 | Connector Reconnection | N935006 | Holden Australia |
| 5430922 | Connector Reconnection | N935008 | Holden Australia |
| 5430922 | Connector Reconnection | N935010 | Holden Australia |
| 5430922 | Connector Reconnection | N935011 | Holden Australia |
| 5430922 | Connector Reconnection | N935012 | Holden Australia |
| 5430922 | Connector Reconnection | N935013 | Holden Australia |
| 5430922 | Connector Reconnection | N935014 | Holden Australia |
| 5430922 | Connector Reconnection | N935015 | Holden Australia |
| 5430922 | Connector Reconnection | N935103 | Holden Australia |
| 5430922 | Connector Reconnection | N935106 | Holden Australia |
| 5430922 | Connector Reconnection | N935107 | Holden Australia |
| 5430922 | Connector Reconnection | N935109 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N940105 | Holden Australia |
| 5430922 | Connector Reconnection | N940202 | Holden Australia |
| 5430922 | Connector Reconnection | N940401 | Holden Australia |
| 5430922 | Connector Reconnection | N940402 | Holden Australia |
| 5430922 | Connector Reconnection | N940612 | Holden Australia |
| 5430922 | Connector Reconnection | N940802 | Holden Australia |
| 5430922 | Connector Reconnection | N940807 | Holden Australia |
| 5430922 | Connector Reconnection | N940812 | Holden Australia |
| 5430922 | Connector Reconnection | N940813 | Holden Australia |
| 5430922 | Connector Reconnection | N940818 | Holden Australia |
| 5430922 | Connector Reconnection | N940904 | Holden Australia |
| 5430922 | Connector Reconnection | N940905 | Holden Australia |
| 5430922 | Connector Reconnection | N941003 | Holden Australia |
| 5430922 | Connector Reconnection | N941101 | Holden Australia |
| 5430922 | Connector Reconnection | N941102 | Holden Australia |
| 5430922 | Connector Reconnection | N941103 | Holden Australia |
| 5430922 | Connector Reconnection | N941202 | Holden Australia |
| 5430922 | Connector Reconnection | N941204 | Holden Australia |
| 5430922 | Connector Reconnection | N941206 | Holden Australia |
| 5430922 | Connector Reconnection | N941210 | Holden Australia |
| 5430922 | Connector Reconnection | N941219 | Holden Australia |
| 5430922 | Connector Reconnection | N941220 | Holden Australia |
| 5430922 | Connector Reconnection | N941225 | Holden Australia |
| 5430922 | Connector Reconnection | N941226 | Holden Australia |
| 5430922 | Connector Reconnection | N941228 | Holden Australia |
| 5430922 | Connector Reconnection | N941401 | Holden Australia |
| 5430922 | Connector Reconnection | N941403 | Holden Australia |
| 5430922 | Connector Reconnection | N941423 | Holden Australia |
| 5430922 | Connector Reconnection | N941429 | Holden Australia |
| 5430922 | Connector Reconnection | N941602 | Holden Australia |
| 5430922 | Connector Reconnection | N941603 | Holden Australia |
| 5430922 | Connector Reconnection | N941604 | Holden Australia |
| 5430922 | Connector Reconnection | N941609 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N941611 | Holden Australia |
| 5430922 | Connector Reconnection | N941613 | Holden Australia |
| 5430922 | Connector Reconnection | N941625 | Holden Australia |
| 5430922 | Connector Reconnection | N941632 | Holden Australia |
| 5430922 | Connector Reconnection | N941635 | Holden Australia |
| 5430922 | Connector Reconnection | N941637 | Holden Australia |
| 5430922 | Connector Reconnection | N941643 | Holden Australia |
| 5430922 | Connector Reconnection | N941644 | Holden Australia |
| 5430922 | Connector Reconnection | N942004 | Holden Australia |
| 5430922 | Connector Reconnection | N942007 | Holden Australia |
| 5430922 | Connector Reconnection | N942101 | Holden Australia |
| 5430922 | Connector Reconnection | N942501 | Holden Australia |
| 5430922 | Connector Reconnection | N942502 | Holden Australia |
| 5430922 | Connector Reconnection | N942503 | Holden Australia |
| 5430922 | Connector Reconnection | N942504 | Holden Australia |
| 5430922 | Connector Reconnection | N942505 | Holden Australia |
| 5430922 | Connector Reconnection | N942507 | Holden Australia |
| 5430922 | Connector Reconnection | N942508 | Holden Australia |
| 5430922 | Connector Reconnection | N942511 | Holden Australia |
| 5430922 | Connector Reconnection | N942514 | Holden Australia |
| 5430922 | Connector Reconnection | N942516 | Holden Australia |
| 5430922 | Connector Reconnection | N942519 | Holden Australia |
| 5430922 | Connector Reconnection | N942520 | Holden Australia |
| 5430922 | Connector Reconnection | N942521 | Holden Australia |
| 5430922 | Connector Reconnection | N942522 | Holden Australia |
| 5430922 | Connector Reconnection | N942602 | Holden Australia |
| 5430922 | Connector Reconnection | N942603 | Holden Australia |
| 5430922 | Connector Reconnection | N942604 | Holden Australia |
| 5430922 | Connector Reconnection | N942608 | Holden Australia |
| 5430922 | Connector Reconnection | N942609 | Holden Australia |
| 5430922 | Connector Reconnection | N942705 | Holden Australia |
| 5430922 | Connector Reconnection | N942706 | Holden Australia |
| 5430922 | Connector Reconnection | N942707 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N942806 | Holden Australia |
| 5430922 | Connector Reconnection | N942808 | Holden Australia |
| 5430922 | Connector Reconnection | N942887 | Holden Australia |
| 5430922 | Connector Reconnection | N942890 | Holden Australia |
| 5430922 | Connector Reconnection | N942897 | Holden Australia |
| 5430922 | Connector Reconnection | N942906 | Holden Australia |
| 5430922 | Connector Reconnection | N942909 | Holden Australia |
| 5430922 | Connector Reconnection | N942987 | Holden Australia |
| 5430922 | Connector Reconnection | N942988 | Holden Australia |
| 5430922 | Connector Reconnection | N942991 | Holden Australia |
| 5430922 | Connector Reconnection | N943203 | Holden Australia |
| 5430922 | Connector Reconnection | N943501 | Holden Australia |
| 5430922 | Connector Reconnection | N943606 | Holden Australia |
| 5430922 | Connector Reconnection | N943611 | Holden Australia |
| 5430922 | Connector Reconnection | N943613 | Holden Australia |
| 5430922 | Connector Reconnection | N943615 | Holden Australia |
| 5430922 | Connector Reconnection | N943618 | Holden Australia |
| 5430922 | Connector Reconnection | N943619 | Holden Australia |
| 5430922 | Connector Reconnection | N943624 | Holden Australia |
| 5430922 | Connector Reconnection | N943625 | Holden Australia |
| 5430922 | Connector Reconnection | N943628 | Holden Australia |
| 5430922 | Connector Reconnection | N943703 | Holden Australia |
| 5430922 | Connector Reconnection | N945001 | Holden Australia |
| 5430922 | Connector Reconnection | N950101 | Holden Australia |
| 5430922 | Connector Reconnection | N950202 | Holden Australia |
| 5430922 | Connector Reconnection | N950204 | Holden Australia |
| 5430922 | Connector Reconnection | N950302 | Holden Australia |
| 5430922 | Connector Reconnection | N950305 | Holden Australia |
| 5430922 | Connector Reconnection | N950402 | Holden Australia |
| 5430922 | Connector Reconnection | N950403 | Holden Australia |
| 5430922 | Connector Reconnection | N950404 | Holden Australia |
| 5430922 | Connector Reconnection | N950405 | Holden Australia |
| 5430922 | Connector Reconnection | N950406 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N950407 | Holden Australia |
| 5430922 | Connector Reconnection | N950408 | Holden Australia |
| 5430922 | Connector Reconnection | N950409 | Holden Australia |
| 5430922 | Connector Reconnection | N950410 | Holden Australia |
| 5430922 | Connector Reconnection | N950411 | Holden Australia |
| 5430922 | Connector Reconnection | N950503 | Holden Australia |
| 5430922 | Connector Reconnection | N950504 | Holden Australia |
| 5430922 | Connector Reconnection | N950505 | Holden Australia |
| 5430922 | Connector Reconnection | N950508 | Holden Australia |
| 5430922 | Connector Reconnection | N950509 | Holden Australia |
| 5430922 | Connector Reconnection | N950601 | Holden Australia |
| 5430922 | Connector Reconnection | N950603 | Holden Australia |
| 5430922 | Connector Reconnection | N950605 | Holden Australia |
| 5430922 | Connector Reconnection | N950701 | Holden Australia |
| 5430922 | Connector Reconnection | N950801 | Holden Australia |
| 5430922 | Connector Reconnection | N950803 | Holden Australia |
| 5430922 | Connector Reconnection | N950804 | Holden Australia |
| 5430922 | Connector Reconnection | N950805 | Holden Australia |
| 5430922 | Connector Reconnection | N950806 | Holden Australia |
| 5430922 | Connector Reconnection | N950807 | Holden Australia |
| 5430922 | Connector Reconnection | N950809 | Holden Australia |
| 5430922 | Connector Reconnection | N950901 | Holden Australia |
| 5430922 | Connector Reconnection | N950902 | Holden Australia |
| 5430922 | Connector Reconnection | N950904 | Holden Australia |
| 5430922 | Connector Reconnection | N950905 | Holden Australia |
| 5430922 | Connector Reconnection | N950906 | Holden Australia |
| 5430922 | Connector Reconnection | N950907 | Holden Australia |
| 5430922 | Connector Reconnection | N950908 | Holden Australia |
| 5430922 | Connector Reconnection | N950909 | Holden Australia |
| 5430922 | Connector Reconnection | N950911 | Holden Australia |
| 5430922 | Connector Reconnection | N950912 | Holden Australia |
| 5430922 | Connector Reconnection | N951003 | Holden Australia |
| 5430922 | Connector Reconnection | N951005 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N951006 | Holden Australia |
| 5430922 | Connector Reconnection | N951008 | Holden Australia |
| 5430922 | Connector Reconnection | N951009 | Holden Australia |
| 5430922 | Connector Reconnection | N951010 | Holden Australia |
| 5430922 | Connector Reconnection | N951101 | Holden Australia |
| 5430922 | Connector Reconnection | N951102 | Holden Australia |
| 5430922 | Connector Reconnection | N951103 | Holden Australia |
| 5430922 | Connector Reconnection | N951105 | Holden Australia |
| 5430922 | Connector Reconnection | N951201 | Holden Australia |
| 5430922 | Connector Reconnection | N951202 | Holden Australia |
| 5430922 | Connector Reconnection | N951203 | Holden Australia |
| 5430922 | Connector Reconnection | N951204 | Holden Australia |
| 5430922 | Connector Reconnection | N951205 | Holden Australia |
| 5430922 | Connector Reconnection | N951206 | Holden Australia |
| 5430922 | Connector Reconnection | N951207 | Holden Australia |
| 5430922 | Connector Reconnection | N951301 | Holden Australia |
| 5430922 | Connector Reconnection | N951302 | Holden Australia |
| 5430922 | Connector Reconnection | N951303 | Holden Australia |
| 5430922 | Connector Reconnection | N951304 | Holden Australia |
| 5430922 | Connector Reconnection | N951305 | Holden Australia |
| 5430922 | Connector Reconnection | N951306 | Holden Australia |
| 5430922 | Connector Reconnection | N951307 | Holden Australia |
| 5430922 | Connector Reconnection | N951309 | Holden Australia |
| 5430922 | Connector Reconnection | N951310 | Holden Australia |
| 5430922 | Connector Reconnection | N951313 | Holden Australia |
| 5430922 | Connector Reconnection | N951314 | Holden Australia |
| 5430922 | Connector Reconnection | N951315 | Holden Australia |
| 5430922 | Connector Reconnection | N951316 | Holden Australia |
| 5430922 | Connector Reconnection | N951317 | Holden Australia |
| 5430922 | Connector Reconnection | N951318 | Holden Australia |
| 5430922 | Connector Reconnection | N951319 | Holden Australia |
| 5430922 | Connector Reconnection | N951320 | Holden Australia |
| 5430922 | Connector Reconnection | N951321 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N951322 | Holden Australia |
| 5430922 | Connector Reconnection | N951323 | Holden Australia |
| 5430922 | Connector Reconnection | N951324 | Holden Australia |
| 5430922 | Connector Reconnection | N951325 | Holden Australia |
| 5430922 | Connector Reconnection | N951327 | Holden Australia |
| 5430922 | Connector Reconnection | N951328 | Holden Australia |
| 5430922 | Connector Reconnection | N951501 | Holden Australia |
| 5430922 | Connector Reconnection | N951503 | Holden Australia |
| 5430922 | Connector Reconnection | N951504 | Holden Australia |
| 5430922 | Connector Reconnection | N951505 | Holden Australia |
| 5430922 | Connector Reconnection | N951506 | Holden Australia |
| 5430922 | Connector Reconnection | N951507 | Holden Australia |
| 5430922 | Connector Reconnection | N951509 | Holden Australia |
| 5430922 | Connector Reconnection | N951510 | Holden Australia |
| 5430922 | Connector Reconnection | N951511 | Holden Australia |
| 5430922 | Connector Reconnection | N951514 | Holden Australia |
| 5430922 | Connector Reconnection | N951516 | Holden Australia |
| 5430922 | Connector Reconnection | N951518 | Holden Australia |
| 5430922 | Connector Reconnection | N951519 | Holden Australia |
| 5430922 | Connector Reconnection | N951520 | Holden Australia |
| 5430922 | Connector Reconnection | N951521 | Holden Australia |
| 5430922 | Connector Reconnection | N951522 | Holden Australia |
| 5430922 | Connector Reconnection | N951523 | Holden Australia |
| 5430922 | Connector Reconnection | N951524 | Holden Australia |
| 5430922 | Connector Reconnection | N951526 | Holden Australia |
| 5430922 | Connector Reconnection | N951527 | Holden Australia |
| 5430922 | Connector Reconnection | N951528 | Holden Australia |
| 5430922 | Connector Reconnection | N951529 | Holden Australia |
| 5430922 | Connector Reconnection | N951530 | Holden Australia |
| 5430922 | Connector Reconnection | N951531 | Holden Australia |
| 5430922 | Connector Reconnection | N951533 | Holden Australia |
| 5430922 | Connector Reconnection | N951534 | Holden Australia |
| 5430922 | Connector Reconnection | N951535 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N951536 | Holden Australia |
| 5430922 | Connector Reconnection | N951537 | Holden Australia |
| 5430922 | Connector Reconnection | N951538 | Holden Australia |
| 5430922 | Connector Reconnection | N951540 | Holden Australia |
| 5430922 | Connector Reconnection | N951541 | Holden Australia |
| 5430922 | Connector Reconnection | N951543 | Holden Australia |
| 5430922 | Connector Reconnection | N951544 | Holden Australia |
| 5430922 | Connector Reconnection | N951701 | Holden Australia |
| 5430922 | Connector Reconnection | N951901 | Holden Australia |
| 5430922 | Connector Reconnection | N951903 | Holden Australia |
| 5430922 | Connector Reconnection | N951904 | Holden Australia |
| 5430922 | Connector Reconnection | N951905 | Holden Australia |
| 5430922 | Connector Reconnection | N951906 | Holden Australia |
| 5430922 | Connector Reconnection | N951907 | Holden Australia |
| 5430922 | Connector Reconnection | N952001 | Holden Australia |
| 5430922 | Connector Reconnection | N952002 | Holden Australia |
| 5430922 | Connector Reconnection | N952003 | Holden Australia |
| 5430922 | Connector Reconnection | N952004 | Holden Australia |
| 5430922 | Connector Reconnection | N952201 | Holden Australia |
| 5430922 | Connector Reconnection | N952202 | Holden Australia |
| 5430922 | Connector Reconnection | N952203 | Holden Australia |
| 5430922 | Connector Reconnection | N952204 | Holden Australia |
| 5430922 | Connector Reconnection | N952205 | Holden Australia |
| 5430922 | Connector Reconnection | N952206 | Holden Australia |
| 5430922 | Connector Reconnection | N952207 | Holden Australia |
| 5430922 | Connector Reconnection | N952208 | Holden Australia |
| 5430922 | Connector Reconnection | N952209 | Holden Australia |
| 5430922 | Connector Reconnection | N952211 | Holden Australia |
| 5430922 | Connector Reconnection | N952212 | Holden Australia |
| 5430922 | Connector Reconnection | N952213 | Holden Australia |
| 5430922 | Connector Reconnection | N952214 | Holden Australia |
| 5430922 | Connector Reconnection | N952215 | Holden Australia |
| 5430922 | Connector Reconnection | N952216 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N952217 | Holden Australia |
| 5430922 | Connector Reconnection | N952218 | Holden Australia |
| 5430922 | Connector Reconnection | N952219 | Holden Australia |
| 5430922 | Connector Reconnection | N952220 | Holden Australia |
| 5430922 | Connector Reconnection | N952221 | Holden Australia |
| 5430922 | Connector Reconnection | N952222 | Holden Australia |
| 5430922 | Connector Reconnection | N952223 | Holden Australia |
| 5430922 | Connector Reconnection | N952224 | Holden Australia |
| 5430922 | Connector Reconnection | N952225 | Holden Australia |
| 5430922 | Connector Reconnection | N952301 | Holden Australia |
| 5430922 | Connector Reconnection | N952302 | Holden Australia |
| 5430922 | Connector Reconnection | N952303 | Holden Australia |
| 5430922 | Connector Reconnection | N952304 | Holden Australia |
| 5430922 | Connector Reconnection | N952401 | Holden Australia |
| 5430922 | Connector Reconnection | N952402 | Holden Australia |
| 5430922 | Connector Reconnection | N952403 | Holden Australia |
| 5430922 | Connector Reconnection | N952404 | Holden Australia |
| 5430922 | Connector Reconnection | N952405 | Holden Australia |
| 5430922 | Connector Reconnection | N952406 | Holden Australia |
| 5430922 | Connector Reconnection | N952407 | Holden Australia |
| 5430922 | Connector Reconnection | N952409 | Holden Australia |
| 5430922 | Connector Reconnection | N952412 | Holden Australia |
| 5430922 | Connector Reconnection | N952413 | Holden Australia |
| 5430922 | Connector Reconnection | N952414 | Holden Australia |
| 5430922 | Connector Reconnection | N952602 | Holden Australia |
| 5430922 | Connector Reconnection | N952603 | Holden Australia |
| 5430922 | Connector Reconnection | N952605 | Holden Australia |
| 5430922 | Connector Reconnection | N952606 | Holden Australia |
| 5430922 | Connector Reconnection | N952607 | Holden Australia |
| 5430922 | Connector Reconnection | N952608 | Holden Australia |
| 5430922 | Connector Reconnection | N952609 | Holden Australia |
| 5430922 | Connector Reconnection | N952610 | Holden Australia |
| 5430922 | Connector Reconnection | N952612 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N952702 | Holden Australia |
| 5430922 | Connector Reconnection | N952703 | Holden Australia |
| 5430922 | Connector Reconnection | N952704 | Holden Australia |
| 5430922 | Connector Reconnection | N952705 | Holden Australia |
| 5430922 | Connector Reconnection | N952706 | Holden Australia |
| 5430922 | Connector Reconnection | N952708 | Holden Australia |
| 5430922 | Connector Reconnection | N952709 | Holden Australia |
| 5430922 | Connector Reconnection | N952712 | Holden Australia |
| 5430922 | Connector Reconnection | N952713 | Holden Australia |
| 5430922 | Connector Reconnection | N952801 | Holden Australia |
| 5430922 | Connector Reconnection | N952802 | Holden Australia |
| 5430922 | Connector Reconnection | N952807 | Holden Australia |
| 5430922 | Connector Reconnection | N952808 | Holden Australia |
| 5430922 | Connector Reconnection | N952809 | Holden Australia |
| 5430922 | Connector Reconnection | N952810 | Holden Australia |
| 5430922 | Connector Reconnection | N952811 | Holden Australia |
| 5430922 | Connector Reconnection | N952814 | Holden Australia |
| 5430922 | Connector Reconnection | N952815 | Holden Australia |
| 5430922 | Connector Reconnection | N952816 | Holden Australia |
| 5430922 | Connector Reconnection | N952902 | Holden Australia |
| 5430922 | Connector Reconnection | N952904 | Holden Australia |
| 5430922 | Connector Reconnection | N953101 | Holden Australia |
| 5430922 | Connector Reconnection | N953102 | Holden Australia |
| 5430922 | Connector Reconnection | N953103 | Holden Australia |
| 5430922 | Connector Reconnection | N953104 | Holden Australia |
| 5430922 | Connector Reconnection | N953105 | Holden Australia |
| 5430922 | Connector Reconnection | N953201 | Holden Australia |
| 5430922 | Connector Reconnection | N953202 | Holden Australia |
| 5430922 | Connector Reconnection | N953203 | Holden Australia |
| 5430922 | Connector Reconnection | N953204 | Holden Australia |
| 5430922 | Connector Reconnection | N953205 | Holden Australia |
| 5430922 | Connector Reconnection | N953206 | Holden Australia |
| 5430922 | Connector Reconnection | N953207 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N953208 | Holden Australia |
| 5430922 | Connector Reconnection | N953209 | Holden Australia |
| 5430922 | Connector Reconnection | N953210 | Holden Australia |
| 5430922 | Connector Reconnection | N953211 | Holden Australia |
| 5430922 | Connector Reconnection | N953212 | Holden Australia |
| 5430922 | Connector Reconnection | N953215 | Holden Australia |
| 5430922 | Connector Reconnection | N953216 | Holden Australia |
| 5430922 | Connector Reconnection | N953217 | Holden Australia |
| 5430922 | Connector Reconnection | N953219 | Holden Australia |
| 5430922 | Connector Reconnection | N953220 | Holden Australia |
| 5430922 | Connector Reconnection | N953221 | Holden Australia |
| 5430922 | Connector Reconnection | N953222 | Holden Australia |
| 5430922 | Connector Reconnection | N953223 | Holden Australia |
| 5430922 | Connector Reconnection | N953224 | Holden Australia |
| 5430922 | Connector Reconnection | N953225 | Holden Australia |
| 5430922 | Connector Reconnection | N953226 | Holden Australia |
| 5430922 | Connector Reconnection | N953227 | Holden Australia |
| 5430922 | Connector Reconnection | N953228 | Holden Australia |
| 5430922 | Connector Reconnection | N953229 | Holden Australia |
| 5430922 | Connector Reconnection | N953230 | Holden Australia |
| 5430922 | Connector Reconnection | N953231 | Holden Australia |
| 5430922 | Connector Reconnection | N953232 | Holden Australia |
| 5430922 | Connector Reconnection | N953233 | Holden Australia |
| 5430922 | Connector Reconnection | N953401 | Holden Australia |
| 5430922 | Connector Reconnection | N953402 | Holden Australia |
| 5430922 | Connector Reconnection | N953403 | Holden Australia |
| 5430922 | Connector Reconnection | N953405 | Holden Australia |
| 5430922 | Connector Reconnection | N953406 | Holden Australia |
| 5430922 | Connector Reconnection | N953501 | Holden Australia |
| 5430922 | Connector Reconnection | N953502 | Holden Australia |
| 5430922 | Connector Reconnection | N953601 | Holden Australia |
| 5430922 | Connector Reconnection | N953604 | Holden Australia |
| 5430922 | Connector Reconnection | N953801 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N953802 | Holden Australia |
| 5430922 | Connector Reconnection | N953803 | Holden Australia |
| 5430922 | Connector Reconnection | N953804 | Holden Australia |
| 5430922 | Connector Reconnection | N953805 | Holden Australia |
| 5430922 | Connector Reconnection | N953806 | Holden Australia |
| 5430922 | Connector Reconnection | N953807 | Holden Australia |
| 5430922 | Connector Reconnection | N953808 | Holden Australia |
| 5430922 | Connector Reconnection | N953809 | Holden Australia |
| 5430922 | Connector Reconnection | N953810 | Holden Australia |
| 5430922 | Connector Reconnection | N953811 | Holden Australia |
| 5430922 | Connector Reconnection | N953812 | Holden Australia |
| 5430922 | Connector Reconnection | N953814 | Holden Australia |
| 5430922 | Connector Reconnection | N953815 | Holden Australia |
| 5430922 | Connector Reconnection | N953901 | Holden Australia |
| 5430922 | Connector Reconnection | N953904 | Holden Australia |
| 5430922 | Connector Reconnection | N953905 | Holden Australia |
| 5430922 | Connector Reconnection | N953907 | Holden Australia |
| 5430922 | Connector Reconnection | N953908 | Holden Australia |
| 5430922 | Connector Reconnection | N953910 | Holden Australia |
| 5430922 | Connector Reconnection | N953911 | Holden Australia |
| 5430922 | Connector Reconnection | N953914 | Holden Australia |
| 5430922 | Connector Reconnection | N953915 | Holden Australia |
| 5430922 | Connector Reconnection | N953916 | Holden Australia |
| 5430922 | Connector Reconnection | N954002 | Holden Australia |
| 5430922 | Connector Reconnection | N954003 | Holden Australia |
| 5430922 | Connector Reconnection | N954004 | Holden Australia |
| 5430922 | Connector Reconnection | N954005 | Holden Australia |
| 5430922 | Connector Reconnection | N954204 | Holden Australia |
| 5430922 | Connector Reconnection | N954206 | Holden Australia |
| 5430922 | Connector Reconnection | N954211 | Holden Australia |
| 5430922 | Connector Reconnection | N954213 | Holden Australia |
| 5430922 | Connector Reconnection | N954301 | Holden Australia |
| 5430922 | Connector Reconnection | N954310 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N954311 | Holden Australia |
| 5430922 | Connector Reconnection | N954503 | Holden Australia |
| 5430922 | Connector Reconnection | N954702 | Holden Australia |
| 5430922 | Connector Reconnection | N955001 | Holden Australia |
| 5430922 | Connector Reconnection | N955006 | Holden Australia |
| 5430922 | Connector Reconnection | N955009 | Holden Australia |
| 5430922 | Connector Reconnection | N955010 | Holden Australia |
| 5430922 | Connector Reconnection | N955014 | Holden Australia |
| 5430922 | Connector Reconnection | N955016 | Holden Australia |
| 5430922 | Connector Reconnection | N955017 | Holden Australia |
| 5430922 | Connector Reconnection | N955025 | Holden Australia |
| 5430922 | Connector Reconnection | N955026 | Holden Australia |
| 5430922 | Connector Reconnection | N955028 | Holden Australia |
| 5430922 | Connector Reconnection | N955029 | Holden Australia |
| 5430922 | Connector Reconnection | N955030 | Holden Australia |
| 5430922 | Connector Reconnection | N955032 | Holden Australia |
| 5430922 | Connector Reconnection | N955033 | Holden Australia |
| 5430922 | Connector Reconnection | N955034 | Holden Australia |
| 5430922 | Connector Reconnection | N955035 | Holden Australia |
| 5430922 | Connector Reconnection | N955038 | Holden Australia |
| 5430922 | Connector Reconnection | N955039 | Holden Australia |
| 5430922 | Connector Reconnection | N955040 | Holden Australia |
| 5430922 | Connector Reconnection | N955042 | Holden Australia |
| 5430922 | Connector Reconnection | N955043 | Holden Australia |
| 5430922 | Connector Reconnection | N955303 | Holden Australia |
| 5430922 | Connector Reconnection | N955305 | Holden Australia |
| 5430922 | Connector Reconnection | N955402 | Holden Australia |
| 5430922 | Connector Reconnection | N955404 | Holden Australia |
| 5430922 | Connector Reconnection | N955405 | Holden Australia |
| 5430922 | Connector Reconnection | N955406 | Holden Australia |
| 5430922 | Connector Reconnection | N955408 | Holden Australia |
| 5430922 | Connector Reconnection | N955409 | Holden Australia |
| 5430922 | Connector Reconnection | N955412 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N955413 | Holden Australia |
| 5430922 | Connector Reconnection | N955414 | Holden Australia |
| 5430922 | Connector Reconnection | N955415 | Holden Australia |
| 5430922 | Connector Reconnection | N955416 | Holden Australia |
| 5430922 | Connector Reconnection | N955418 | Holden Australia |
| 5430922 | Connector Reconnection | N955420 | Holden Australia |
| 5430922 | Connector Reconnection | N955501 | Holden Australia |
| 5430922 | Connector Reconnection | N955503 | Holden Australia |
| 5430922 | Connector Reconnection | N955602 | Holden Australia |
| 5430922 | Connector Reconnection | N955603 | Holden Australia |
| 5430922 | Connector Reconnection | N955604 | Holden Australia |
| 5430922 | Connector Reconnection | N955701 | Holden Australia |
| 5430922 | Connector Reconnection | N955702 | Holden Australia |
| 5430922 | Connector Reconnection | N955703 | Holden Australia |
| 5430922 | Connector Reconnection | N955704 | Holden Australia |
| 5430922 | Connector Reconnection | N955706 | Holden Australia |
| 5430922 | Connector Reconnection | N955708 | Holden Australia |
| 5430922 | Connector Reconnection | N955709 | Holden Australia |
| 5430922 | Connector Reconnection | N955909 | Holden Australia |
| 5430922 | Connector Reconnection | N955916 | Holden Australia |
| 5430922 | Connector Reconnection | N955917 | Holden Australia |
| 5430922 | Connector Reconnection | N960101 | Holden Australia |
| 5430922 | Connector Reconnection | N960109 | Holden Australia |
| 5430922 | Connector Reconnection | N960202 | Holden Australia |
| 5430922 | Connector Reconnection | N960205 | Holden Australia |
| 5430922 | Connector Reconnection | N960302 | Holden Australia |
| 5430922 | Connector Reconnection | N960305 | Holden Australia |
| 5430922 | Connector Reconnection | N960401 | Holden Australia |
| 5430922 | Connector Reconnection | N960402 | Holden Australia |
| 5430922 | Connector Reconnection | N960403 | Holden Australia |
| 5430922 | Connector Reconnection | N960404 | Holden Australia |
| 5430922 | Connector Reconnection | N960405 | Holden Australia |
| 5430922 | Connector Reconnection | N960406 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N960407 | Holden Australia |
| 5430922 | Connector Reconnection | N960408 | Holden Australia |
| 5430922 | Connector Reconnection | N960409 | Holden Australia |
| 5430922 | Connector Reconnection | N960410 | Holden Australia |
| 5430922 | Connector Reconnection | N960411 | Holden Australia |
| 5430922 | Connector Reconnection | N960412 | Holden Australia |
| 5430922 | Connector Reconnection | N960501 | Holden Australia |
| 5430922 | Connector Reconnection | N960503 | Holden Australia |
| 5430922 | Connector Reconnection | N960504 | Holden Australia |
| 5430922 | Connector Reconnection | N960505 | Holden Australia |
| 5430922 | Connector Reconnection | N960506 | Holden Australia |
| 5430922 | Connector Reconnection | N960507 | Holden Australia |
| 5430922 | Connector Reconnection | N960508 | Holden Australia |
| 5430922 | Connector Reconnection | N960509 | Holden Australia |
| 5430922 | Connector Reconnection | N960601 | Holden Australia |
| 5430922 | Connector Reconnection | N960603 | Holden Australia |
| 5430922 | Connector Reconnection | N960604 | Holden Australia |
| 5430922 | Connector Reconnection | N960605 | Holden Australia |
| 5430922 | Connector Reconnection | N960607 | Holden Australia |
| 5430922 | Connector Reconnection | N960608 | Holden Australia |
| 5430922 | Connector Reconnection | N960609 | Holden Australia |
| 5430922 | Connector Reconnection | N960611 | Holden Australia |
| 5430922 | Connector Reconnection | N960612 | Holden Australia |
| 5430922 | Connector Reconnection | N960701 | Holden Australia |
| 5430922 | Connector Reconnection | N960801 | Holden Australia |
| 5430922 | Connector Reconnection | N960804 | Holden Australia |
| 5430922 | Connector Reconnection | N960805 | Holden Australia |
| 5430922 | Connector Reconnection | N960806 | Holden Australia |
| 5430922 | Connector Reconnection | N960807 | Holden Australia |
| 5430922 | Connector Reconnection | N960808 | Holden Australia |
| 5430922 | Connector Reconnection | N960813 | Holden Australia |
| 5430922 | Connector Reconnection | N960901 | Holden Australia |
| 5430922 | Connector Reconnection | N960902 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N960903 | Holden Australia |
| 5430922 | Connector Reconnection | N960904 | Holden Australia |
| 5430922 | Connector Reconnection | N960905 | Holden Australia |
| 5430922 | Connector Reconnection | N960906 | Holden Australia |
| 5430922 | Connector Reconnection | N960907 | Holden Australia |
| 5430922 | Connector Reconnection | N960908 | Holden Australia |
| 5430922 | Connector Reconnection | N960909 | Holden Australia |
| 5430922 | Connector Reconnection | N960910 | Holden Australia |
| 5430922 | Connector Reconnection | N960911 | Holden Australia |
| 5430922 | Connector Reconnection | N960914 | Holden Australia |
| 5430922 | Connector Reconnection | N960915 | Holden Australia |
| 5430922 | Connector Reconnection | N960918 | Holden Australia |
| 5430922 | Connector Reconnection | N961001 | Holden Australia |
| 5430922 | Connector Reconnection | N961002 | Holden Australia |
| 5430922 | Connector Reconnection | N961003 | Holden Australia |
| 5430922 | Connector Reconnection | N961004 | Holden Australia |
| 5430922 | Connector Reconnection | N961005 | Holden Australia |
| 5430922 | Connector Reconnection | N961006 | Holden Australia |
| 5430922 | Connector Reconnection | N961007 | Holden Australia |
| 5430922 | Connector Reconnection | N961008 | Holden Australia |
| 5430922 | Connector Reconnection | N961009 | Holden Australia |
| 5430922 | Connector Reconnection | N961010 | Holden Australia |
| 5430922 | Connector Reconnection | N961011 | Holden Australia |
| 5430922 | Connector Reconnection | N961012 | Holden Australia |
| 5430922 | Connector Reconnection | N961101 | Holden Australia |
| 5430922 | Connector Reconnection | N961102 | Holden Australia |
| 5430922 | Connector Reconnection | N961103 | Holden Australia |
| 5430922 | Connector Reconnection | N961104 | Holden Australia |
| 5430922 | Connector Reconnection | N961105 | Holden Australia |
| 5430922 | Connector Reconnection | N961106 | Holden Australia |
| 5430922 | Connector Reconnection | N961108 | Holden Australia |
| 5430922 | Connector Reconnection | N961109 | Holden Australia |
| 5430922 | Connector Reconnection | N961110 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N961202 | Holden Australia |
| 5430922 | Connector Reconnection | N961203 | Holden Australia |
| 5430922 | Connector Reconnection | N961204 | Holden Australia |
| 5430922 | Connector Reconnection | N961205 | Holden Australia |
| 5430922 | Connector Reconnection | N961206 | Holden Australia |
| 5430922 | Connector Reconnection | N961207 | Holden Australia |
| 5430922 | Connector Reconnection | N961208 | Holden Australia |
| 5430922 | Connector Reconnection | N961209 | Holden Australia |
| 5430922 | Connector Reconnection | N961210 | Holden Australia |
| 5430922 | Connector Reconnection | N961212 | Holden Australia |
| 5430922 | Connector Reconnection | N961213 | Holden Australia |
| 5430922 | Connector Reconnection | N961301 | Holden Australia |
| 5430922 | Connector Reconnection | N961302 | Holden Australia |
| 5430922 | Connector Reconnection | N961303 | Holden Australia |
| 5430922 | Connector Reconnection | N961304 | Holden Australia |
| 5430922 | Connector Reconnection | N961305 | Holden Australia |
| 5430922 | Connector Reconnection | N961306 | Holden Australia |
| 5430922 | Connector Reconnection | N961307 | Holden Australia |
| 5430922 | Connector Reconnection | N961308 | Holden Australia |
| 5430922 | Connector Reconnection | N961309 | Holden Australia |
| 5430922 | Connector Reconnection | N961310 | Holden Australia |
| 5430922 | Connector Reconnection | N961313 | Holden Australia |
| 5430922 | Connector Reconnection | N961314 | Holden Australia |
| 5430922 | Connector Reconnection | N961315 | Holden Australia |
| 5430922 | Connector Reconnection | N961316 | Holden Australia |
| 5430922 | Connector Reconnection | N961317 | Holden Australia |
| 5430922 | Connector Reconnection | N961318 | Holden Australia |
| 5430922 | Connector Reconnection | N961319 | Holden Australia |
| 5430922 | Connector Reconnection | N961320 | Holden Australia |
| 5430922 | Connector Reconnection | N961321 | Holden Australia |
| 5430922 | Connector Reconnection | N961322 | Holden Australia |
| 5430922 | Connector Reconnection | N961323 | Holden Australia |
| 5430922 | Connector Reconnection | N961324 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N961326 | Holden Australia |
| 5430922 | Connector Reconnection | N961327 | Holden Australia |
| 5430922 | Connector Reconnection | N961501 | Holden Australia |
| 5430922 | Connector Reconnection | N961502 | Holden Australia |
| 5430922 | Connector Reconnection | N961503 | Holden Australia |
| 5430922 | Connector Reconnection | N961504 | Holden Australia |
| 5430922 | Connector Reconnection | N961505 | Holden Australia |
| 5430922 | Connector Reconnection | N961506 | Holden Australia |
| 5430922 | Connector Reconnection | N961507 | Holden Australia |
| 5430922 | Connector Reconnection | N961508 | Holden Australia |
| 5430922 | Connector Reconnection | N961509 | Holden Australia |
| 5430922 | Connector Reconnection | N961510 | Holden Australia |
| 5430922 | Connector Reconnection | N961511 | Holden Australia |
| 5430922 | Connector Reconnection | N961513 | Holden Australia |
| 5430922 | Connector Reconnection | N961514 | Holden Australia |
| 5430922 | Connector Reconnection | N961515 | Holden Australia |
| 5430922 | Connector Reconnection | N961516 | Holden Australia |
| 5430922 | Connector Reconnection | N961517 | Holden Australia |
| 5430922 | Connector Reconnection | N961518 | Holden Australia |
| 5430922 | Connector Reconnection | N961519 | Holden Australia |
| 5430922 | Connector Reconnection | N961520 | Holden Australia |
| 5430922 | Connector Reconnection | N961521 | Holden Australia |
| 5430922 | Connector Reconnection | N961522 | Holden Australia |
| 5430922 | Connector Reconnection | N961523 | Holden Australia |
| 5430922 | Connector Reconnection | N961524 | Holden Australia |
| 5430922 | Connector Reconnection | N961525 | Holden Australia |
| 5430922 | Connector Reconnection | N961526 | Holden Australia |
| 5430922 | Connector Reconnection | N961528 | Holden Australia |
| 5430922 | Connector Reconnection | N961529 | Holden Australia |
| 5430922 | Connector Reconnection | N961530 | Holden Australia |
| 5430922 | Connector Reconnection | N961531 | Holden Australia |
| 5430922 | Connector Reconnection | N961532 | Holden Australia |
| 5430922 | Connector Reconnection | N961533 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N961534 | Holden Australia |
| 5430922 | Connector Reconnection | N961535 | Holden Australia |
| 5430922 | Connector Reconnection | N961536 | Holden Australia |
| 5430922 | Connector Reconnection | N961537 | Holden Australia |
| 5430922 | Connector Reconnection | N961701 | Holden Australia |
| 5430922 | Connector Reconnection | N961703 | Holden Australia |
| 5430922 | Connector Reconnection | N961704 | Holden Australia |
| 5430922 | Connector Reconnection | N961705 | Holden Australia |
| 5430922 | Connector Reconnection | N961706 | Holden Australia |
| 5430922 | Connector Reconnection | N961707 | Holden Australia |
| 5430922 | Connector Reconnection | N961708 | Holden Australia |
| 5430922 | Connector Reconnection | N961709 | Holden Australia |
| 5430922 | Connector Reconnection | N961710 | Holden Australia |
| 5430922 | Connector Reconnection | N961711 | Holden Australia |
| 5430922 | Connector Reconnection | N961712 | Holden Australia |
| 5430922 | Connector Reconnection | N961713 | Holden Australia |
| 5430922 | Connector Reconnection | N961714 | Holden Australia |
| 5430922 | Connector Reconnection | N961716 | Holden Australia |
| 5430922 | Connector Reconnection | N961717 | Holden Australia |
| 5430922 | Connector Reconnection | N961718 | Holden Australia |
| 5430922 | Connector Reconnection | N961719 | Holden Australia |
| 5430922 | Connector Reconnection | N961720 | Holden Australia |
| 5430922 | Connector Reconnection | N961721 | Holden Australia |
| 5430922 | Connector Reconnection | N961722 | Holden Australia |
| 5430922 | Connector Reconnection | N961723 | Holden Australia |
| 5430922 | Connector Reconnection | N961724 | Holden Australia |
| 5430922 | Connector Reconnection | N961725 | Holden Australia |
| 5430922 | Connector Reconnection | N961726 | Holden Australia |
| 5430922 | Connector Reconnection | N961727 | Holden Australia |
| 5430922 | Connector Reconnection | N961728 | Holden Australia |
| 5430922 | Connector Reconnection | N961729 | Holden Australia |
| 5430922 | Connector Reconnection | N961730 | Holden Australia |
| 5430922 | Connector Reconnection | N961732 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N961733 | Holden Australia |
| 5430922 | Connector Reconnection | N961734 | Holden Australia |
| 5430922 | Connector Reconnection | N961735 | Holden Australia |
| 5430922 | Connector Reconnection | N961736 | Holden Australia |
| 5430922 | Connector Reconnection | N961737 | Holden Australia |
| 5430922 | Connector Reconnection | N961738 | Holden Australia |
| 5430922 | Connector Reconnection | N961739 | Holden Australia |
| 5430922 | Connector Reconnection | N961740 | Holden Australia |
| 5430922 | Connector Reconnection | N961741 | Holden Australia |
| 5430922 | Connector Reconnection | N961742 | Holden Australia |
| 5430922 | Connector Reconnection | N961743 | Holden Australia |
| 5430922 | Connector Reconnection | N962001 | Holden Australia |
| 5430922 | Connector Reconnection | N962002 | Holden Australia |
| 5430922 | Connector Reconnection | N962003 | Holden Australia |
| 5430922 | Connector Reconnection | N962005 | Holden Australia |
| 5430922 | Connector Reconnection | N962006 | Holden Australia |
| 5430922 | Connector Reconnection | N962007 | Holden Australia |
| 5430922 | Connector Reconnection | N962101 | Holden Australia |
| 5430922 | Connector Reconnection | N962102 | Holden Australia |
| 5430922 | Connector Reconnection | N962103 | Holden Australia |
| 5430922 | Connector Reconnection | N962104 | Holden Australia |
| 5430922 | Connector Reconnection | N962105 | Holden Australia |
| 5430922 | Connector Reconnection | N962106 | Holden Australia |
| 5430922 | Connector Reconnection | N962107 | Holden Australia |
| 5430922 | Connector Reconnection | N962201 | Holden Australia |
| 5430922 | Connector Reconnection | N962202 | Holden Australia |
| 5430922 | Connector Reconnection | N962203 | Holden Australia |
| 5430922 | Connector Reconnection | N962204 | Holden Australia |
| 5430922 | Connector Reconnection | N962301 | Holden Australia |
| 5430922 | Connector Reconnection | N962401 | Holden Australia |
| 5430922 | Connector Reconnection | N962402 | Holden Australia |
| 5430922 | Connector Reconnection | N962403 | Holden Australia |
| 5430922 | Connector Reconnection | N962404 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N962405 | Holden Australia |
| 5430922 | Connector Reconnection | N962406 | Holden Australia |
| 5430922 | Connector Reconnection | N962407 | Holden Australia |
| 5430922 | Connector Reconnection | N962408 | Holden Australia |
| 5430922 | Connector Reconnection | N962409 | Holden Australia |
| 5430922 | Connector Reconnection | N962410 | Holden Australia |
| 5430922 | Connector Reconnection | N962411 | Holden Australia |
| 5430922 | Connector Reconnection | N962412 | Holden Australia |
| 5430922 | Connector Reconnection | N962413 | Holden Australia |
| 5430922 | Connector Reconnection | N962414 | Holden Australia |
| 5430922 | Connector Reconnection | N962415 | Holden Australia |
| 5430922 | Connector Reconnection | N962416 | Holden Australia |
| 5430922 | Connector Reconnection | N962417 | Holden Australia |
| 5430922 | Connector Reconnection | N962418 | Holden Australia |
| 5430922 | Connector Reconnection | N962419 | Holden Australia |
| 5430922 | Connector Reconnection | N962421 | Holden Australia |
| 5430922 | Connector Reconnection | N962422 | Holden Australia |
| 5430922 | Connector Reconnection | N962423 | Holden Australia |
| 5430922 | Connector Reconnection | N962425 | Holden Australia |
| 5430922 | Connector Reconnection | N962426 | Holden Australia |
| 5430922 | Connector Reconnection | N962427 | Holden Australia |
| 5430922 | Connector Reconnection | N962428 | Holden Australia |
| 5430922 | Connector Reconnection | N962501 | Holden Australia |
| 5430922 | Connector Reconnection | N962503 | Holden Australia |
| 5430922 | Connector Reconnection | N962504 | Holden Australia |
| 5430922 | Connector Reconnection | N962505 | Holden Australia |
| 5430922 | Connector Reconnection | N962506 | Holden Australia |
| 5430922 | Connector Reconnection | N962601 | Holden Australia |
| 5430922 | Connector Reconnection | N962602 | Holden Australia |
| 5430922 | Connector Reconnection | N962603 | Holden Australia |
| 5430922 | Connector Reconnection | N962604 | Holden Australia |
| 5430922 | Connector Reconnection | N962605 | Holden Australia |
| 5430922 | Connector Reconnection | N962606 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N962607 | Holden Australia |
| 5430922 | Connector Reconnection | N962608 | Holden Australia |
| 5430922 | Connector Reconnection | N962609 | Holden Australia |
| 5430922 | Connector Reconnection | N962610 | Holden Australia |
| 5430922 | Connector Reconnection | N962611 | Holden Australia |
| 5430922 | Connector Reconnection | N962612 | Holden Australia |
| 5430922 | Connector Reconnection | N962701 | Holden Australia |
| 5430922 | Connector Reconnection | N962702 | Holden Australia |
| 5430922 | Connector Reconnection | N962703 | Holden Australia |
| 5430922 | Connector Reconnection | N962705 | Holden Australia |
| 5430922 | Connector Reconnection | N962706 | Holden Australia |
| 5430922 | Connector Reconnection | N962707 | Holden Australia |
| 5430922 | Connector Reconnection | N962708 | Holden Australia |
| 5430922 | Connector Reconnection | N962709 | Holden Australia |
| 5430922 | Connector Reconnection | N962710 | Holden Australia |
| 5430922 | Connector Reconnection | N962712 | Holden Australia |
| 5430922 | Connector Reconnection | N962713 | Holden Australia |
| 5430922 | Connector Reconnection | N962714 | Holden Australia |
| 5430922 | Connector Reconnection | N962715 | Holden Australia |
| 5430922 | Connector Reconnection | N962716 | Holden Australia |
| 5430922 | Connector Reconnection | N962801 | Holden Australia |
| 5430922 | Connector Reconnection | N962802 | Holden Australia |
| 5430922 | Connector Reconnection | N962803 | Holden Australia |
| 5430922 | Connector Reconnection | N962806 | Holden Australia |
| 5430922 | Connector Reconnection | N962807 | Holden Australia |
| 5430922 | Connector Reconnection | N962809 | Holden Australia |
| 5430922 | Connector Reconnection | N962811 | Holden Australia |
| 5430922 | Connector Reconnection | N962812 | Holden Australia |
| 5430922 | Connector Reconnection | N963002 | Holden Australia |
| 5430922 | Connector Reconnection | N963003 | Holden Australia |
| 5430922 | Connector Reconnection | N963004 | Holden Australia |
| 5430922 | Connector Reconnection | N963005 | Holden Australia |
| 5430922 | Connector Reconnection | N963006 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N963007 | Holden Australia |
| 5430922 | Connector Reconnection | N963008 | Holden Australia |
| 5430922 | Connector Reconnection | N963009 | Holden Australia |
| 5430922 | Connector Reconnection | N963010 | Holden Australia |
| 5430922 | Connector Reconnection | N963011 | Holden Australia |
| 5430922 | Connector Reconnection | N963012 | Holden Australia |
| 5430922 | Connector Reconnection | N963102 | Holden Australia |
| 5430922 | Connector Reconnection | N963103 | Holden Australia |
| 5430922 | Connector Reconnection | N963104 | Holden Australia |
| 5430922 | Connector Reconnection | N963105 | Holden Australia |
| 5430922 | Connector Reconnection | N963106 | Holden Australia |
| 5430922 | Connector Reconnection | N963107 | Holden Australia |
| 5430922 | Connector Reconnection | N963109 | Holden Australia |
| 5430922 | Connector Reconnection | N963110 | Holden Australia |
| 5430922 | Connector Reconnection | N963111 | Holden Australia |
| 5430922 | Connector Reconnection | N963113 | Holden Australia |
| 5430922 | Connector Reconnection | N963202 | Holden Australia |
| 5430922 | Connector Reconnection | N963204 | Holden Australia |
| 5430922 | Connector Reconnection | N963205 | Holden Australia |
| 5430922 | Connector Reconnection | N963207 | Holden Australia |
| 5430922 | Connector Reconnection | N963208 | Holden Australia |
| 5430922 | Connector Reconnection | N963209 | Holden Australia |
| 5430922 | Connector Reconnection | N963210 | Holden Australia |
| 5430922 | Connector Reconnection | N963302 | Holden Australia |
| 5430922 | Connector Reconnection | N963305 | Holden Australia |
| 5430922 | Connector Reconnection | N963501 | Holden Australia |
| 5430922 | Connector Reconnection | N963502 | Holden Australia |
| 5430922 | Connector Reconnection | N963503 | Holden Australia |
| 5430922 | Connector Reconnection | N963505 | Holden Australia |
| 5430922 | Connector Reconnection | N963506 | Holden Australia |
| 5430922 | Connector Reconnection | N963507 | Holden Australia |
| 5430922 | Connector Reconnection | N963601 | Holden Australia |
| 5430922 | Connector Reconnection | N963602 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N963603 | Holden Australia |
| 5430922 | Connector Reconnection | N963604 | Holden Australia |
| 5430922 | Connector Reconnection | N963701 | Holden Australia |
| 5430922 | Connector Reconnection | N963702 | Holden Australia |
| 5430922 | Connector Reconnection | N963703 | Holden Australia |
| 5430922 | Connector Reconnection | N963704 | Holden Australia |
| 5430922 | Connector Reconnection | N963705 | Holden Australia |
| 5430922 | Connector Reconnection | N963706 | Holden Australia |
| 5430922 | Connector Reconnection | N963707 | Holden Australia |
| 5430922 | Connector Reconnection | N963708 | Holden Australia |
| 5430922 | Connector Reconnection | N963709 | Holden Australia |
| 5430922 | Connector Reconnection | N963710 | Holden Australia |
| 5430922 | Connector Reconnection | N963711 | Holden Australia |
| 5430922 | Connector Reconnection | N963712 | Holden Australia |
| 5430922 | Connector Reconnection | N963713 | Holden Australia |
| 5430922 | Connector Reconnection | N963714 | Holden Australia |
| 5430922 | Connector Reconnection | N963715 | Holden Australia |
| 5430922 | Connector Reconnection | N963716 | Holden Australia |
| 5430922 | Connector Reconnection | N963718 | Holden Australia |
| 5430922 | Connector Reconnection | N963719 | Holden Australia |
| 5430922 | Connector Reconnection | N963720 | Holden Australia |
| 5430922 | Connector Reconnection | N963721 | Holden Australia |
| 5430922 | Connector Reconnection | N963722 | Holden Australia |
| 5430922 | Connector Reconnection | N963723 | Holden Australia |
| 5430922 | Connector Reconnection | N963724 | Holden Australia |
| 5430922 | Connector Reconnection | N963725 | Holden Australia |
| 5430922 | Connector Reconnection | N963726 | Holden Australia |
| 5430922 | Connector Reconnection | N963727 | Holden Australia |
| 5430922 | Connector Reconnection | N963728 | Holden Australia |
| 5430922 | Connector Reconnection | N963730 | Holden Australia |
| 5430922 | Connector Reconnection | N963731 | Holden Australia |
| 5430922 | Connector Reconnection | N963732 | Holden Australia |
| 5430922 | Connector Reconnection | N963801 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N963802 | Holden Australia |
| 5430922 | Connector Reconnection | N963803 | Holden Australia |
| 5430922 | Connector Reconnection | N963804 | Holden Australia |
| 5430922 | Connector Reconnection | N963902 | Holden Australia |
| 5430922 | Connector Reconnection | N963903 | Holden Australia |
| 5430922 | Connector Reconnection | N964001 | Holden Australia |
| 5430922 | Connector Reconnection | N964002 | Holden Australia |
| 5430922 | Connector Reconnection | N964101 | Holden Australia |
| 5430922 | Connector Reconnection | N964102 | Holden Australia |
| 5430922 | Connector Reconnection | N964103 | Holden Australia |
| 5430922 | Connector Reconnection | N964104 | Holden Australia |
| 5430922 | Connector Reconnection | N964201 | Holden Australia |
| 5430922 | Connector Reconnection | N964202 | Holden Australia |
| 5430922 | Connector Reconnection | N964203 | Holden Australia |
| 5430922 | Connector Reconnection | N964301 | Holden Australia |
| 5430922 | Connector Reconnection | N964302 | Holden Australia |
| 5430922 | Connector Reconnection | N964303 | Holden Australia |
| 5430922 | Connector Reconnection | N964304 | Holden Australia |
| 5430922 | Connector Reconnection | N964306 | Holden Australia |
| 5430922 | Connector Reconnection | N964307 | Holden Australia |
| 5430922 | Connector Reconnection | N964308 | Holden Australia |
| 5430922 | Connector Reconnection | N964309 | Holden Australia |
| 5430922 | Connector Reconnection | N964310 | Holden Australia |
| 5430922 | Connector Reconnection | N964311 | Holden Australia |
| 5430922 | Connector Reconnection | N964312 | Holden Australia |
| 5430922 | Connector Reconnection | N964313 | Holden Australia |
| 5430922 | Connector Reconnection | N964314 | Holden Australia |
| 5430922 | Connector Reconnection | N964315 | Holden Australia |
| 5430922 | Connector Reconnection | N964316 | Holden Australia |
| 5430922 | Connector Reconnection | N964317 | Holden Australia |
| 5430922 | Connector Reconnection | N964318 | Holden Australia |
| 5430922 | Connector Reconnection | N964320 | Holden Australia |
| 5430922 | Connector Reconnection | N964321 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N964325 | Holden Australia |
| 5430922 | Connector Reconnection | N964326 | Holden Australia |
| 5430922 | Connector Reconnection | N964327 | Holden Australia |
| 5430922 | Connector Reconnection | N964328 | Holden Australia |
| 5430922 | Connector Reconnection | N964401 | Holden Australia |
| 5430922 | Connector Reconnection | N964402 | Holden Australia |
| 5430922 | Connector Reconnection | N964404 | Holden Australia |
| 5430922 | Connector Reconnection | N964405 | Holden Australia |
| 5430922 | Connector Reconnection | N964408 | Holden Australia |
| 5430922 | Connector Reconnection | N964601 | Holden Australia |
| 5430922 | Connector Reconnection | N964701 | Holden Australia |
| 5430922 | Connector Reconnection | N964702 | Holden Australia |
| 5430922 | Connector Reconnection | N964703 | Holden Australia |
| 5430922 | Connector Reconnection | N964801 | Holden Australia |
| 5430922 | Connector Reconnection | N964802 | Holden Australia |
| 5430922 | Connector Reconnection | N964901 | Holden Australia |
| 5430922 | Connector Reconnection | N964902 | Holden Australia |
| 5430922 | Connector Reconnection | N965024 | Holden Australia |
| 5430922 | Connector Reconnection | N965028 | Holden Australia |
| 5430922 | Connector Reconnection | N965029 | Holden Australia |
| 5430922 | Connector Reconnection | N965126 | Holden Australia |
| 5430922 | Connector Reconnection | N965201 | Holden Australia |
| 5430922 | Connector Reconnection | N965306 | Holden Australia |
| 5430922 | Connector Reconnection | N965404 | Holden Australia |
| 5430922 | Connector Reconnection | N965411 | Holden Australia |
| 5430922 | Connector Reconnection | N965413 | Holden Australia |
| 5430922 | Connector Reconnection | N965809 | Holden Australia |
| 5430922 | Connector Reconnection | N965810 | Holden Australia |
| 5430922 | Connector Reconnection | N965907 | Holden Australia |
| 5430922 | Connector Reconnection | N966002 | Holden Australia |
| 5430922 | Connector Reconnection | N966005 | Holden Australia |
| 5430922 | Connector Reconnection | N966102 | Holden Australia |
| 5430922 | Connector Reconnection | N966105 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N966201 | Holden Australia |
| 5430922 | Connector Reconnection | N966202 | Holden Australia |
| 5430922 | Connector Reconnection | N966203 | Holden Australia |
| 5430922 | Connector Reconnection | N966204 | Holden Australia |
| 5430922 | Connector Reconnection | N966205 | Holden Australia |
| 5430922 | Connector Reconnection | N966206 | Holden Australia |
| 5430922 | Connector Reconnection | N966207 | Holden Australia |
| 5430922 | Connector Reconnection | N966208 | Holden Australia |
| 5430922 | Connector Reconnection | N966209 | Holden Australia |
| 5430922 | Connector Reconnection | N966210 | Holden Australia |
| 5430922 | Connector Reconnection | N966213 | Holden Australia |
| 5430922 | Connector Reconnection | N966214 | Holden Australia |
| 5430922 | Connector Reconnection | N966215 | Holden Australia |
| 5430922 | Connector Reconnection | N966216 | Holden Australia |
| 5430922 | Connector Reconnection | N966217 | Holden Australia |
| 5430922 | Connector Reconnection | N966218 | Holden Australia |
| 5430922 | Connector Reconnection | N966219 | Holden Australia |
| 5430922 | Connector Reconnection | N966220 | Holden Australia |
| 5430922 | Connector Reconnection | N966221 | Holden Australia |
| 5430922 | Connector Reconnection | N966222 | Holden Australia |
| 5430922 | Connector Reconnection | N966223 | Holden Australia |
| 5430922 | Connector Reconnection | N966224 | Holden Australia |
| 5430922 | Connector Reconnection | N966225 | Holden Australia |
| 5430922 | Connector Reconnection | N966228 | Holden Australia |
| 5430922 | Connector Reconnection | N966404 | Holden Australia |
| 5430922 | Connector Reconnection | N966405 | Holden Australia |
| 5430922 | Connector Reconnection | N966406 | Holden Australia |
| 5430922 | Connector Reconnection | N966409 | Holden Australia |
| 5430922 | Connector Reconnection | N966501 | Holden Australia |
| 5430922 | Connector Reconnection | N966502 | Holden Australia |
| 5430922 | Connector Reconnection | N966503 | Holden Australia |
| 5430922 | Connector Reconnection | N966505 | Holden Australia |
| 5430922 | Connector Reconnection | N966506 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N966507 | Holden Australia |
| 5430922 | Connector Reconnection | N966508 | Holden Australia |
| 5430922 | Connector Reconnection | N966509 | Holden Australia |
| 5430922 | Connector Reconnection | N966510 | Holden Australia |
| 5430922 | Connector Reconnection | N966511 | Holden Australia |
| 5430922 | Connector Reconnection | N966513 | Holden Australia |
| 5430922 | Connector Reconnection | N966514 | Holden Australia |
| 5430922 | Connector Reconnection | N966515 | Holden Australia |
| 5430922 | Connector Reconnection | N966516 | Holden Australia |
| 5430922 | Connector Reconnection | N966517 | Holden Australia |
| 5430922 | Connector Reconnection | N966518 | Holden Australia |
| 5430922 | Connector Reconnection | N966519 | Holden Australia |
| 5430922 | Connector Reconnection | N966520 | Holden Australia |
| 5430922 | Connector Reconnection | N966521 | Holden Australia |
| 5430922 | Connector Reconnection | N966522 | Holden Australia |
| 5430922 | Connector Reconnection | N966523 | Holden Australia |
| 5430922 | Connector Reconnection | N966524 | Holden Australia |
| 5430922 | Connector Reconnection | N966525 | Holden Australia |
| 5430922 | Connector Reconnection | N966527 | Holden Australia |
| 5430922 | Connector Reconnection | N966528 | Holden Australia |
| 5430922 | Connector Reconnection | N966529 | Holden Australia |
| 5430922 | Connector Reconnection | N966530 | Holden Australia |
| 5430922 | Connector Reconnection | N966531 | Holden Australia |
| 5430922 | Connector Reconnection | N966532 | Holden Australia |
| 5430922 | Connector Reconnection | N966533 | Holden Australia |
| 5430922 | Connector Reconnection | N966534 | Holden Australia |
| 5430922 | Connector Reconnection | N966535 | Holden Australia |
| 5430922 | Connector Reconnection | N966701 | Holden Australia |
| 5430922 | Connector Reconnection | N966704 | Holden Australia |
| 5430922 | Connector Reconnection | N966706 | Holden Australia |
| 5430922 | Connector Reconnection | N966707 | Holden Australia |
| 5430922 | Connector Reconnection | N966709 | Holden Australia |
| 5430922 | Connector Reconnection | N966710 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N966711 | Holden Australia |
| 5430922 | Connector Reconnection | N966712 | Holden Australia |
| 5430922 | Connector Reconnection | N966714 | Holden Australia |
| 5430922 | Connector Reconnection | N966716 | Holden Australia |
| 5430922 | Connector Reconnection | N966717 | Holden Australia |
| 5430922 | Connector Reconnection | N966718 | Holden Australia |
| 5430922 | Connector Reconnection | N966719 | Holden Australia |
| 5430922 | Connector Reconnection | N966720 | Holden Australia |
| 5430922 | Connector Reconnection | N966721 | Holden Australia |
| 5430922 | Connector Reconnection | N966723 | Holden Australia |
| 5430922 | Connector Reconnection | N966724 | Holden Australia |
| 5430922 | Connector Reconnection | N966725 | Holden Australia |
| 5430922 | Connector Reconnection | N966726 | Holden Australia |
| 5430922 | Connector Reconnection | N966727 | Holden Australia |
| 5430922 | Connector Reconnection | N966728 | Holden Australia |
| 5430922 | Connector Reconnection | N966729 | Holden Australia |
| 5430922 | Connector Reconnection | N966731 | Holden Australia |
| 5430922 | Connector Reconnection | N966732 | Holden Australia |
| 5430922 | Connector Reconnection | N966733 | Holden Australia |
| 5430922 | Connector Reconnection | N966734 | Holden Australia |
| 5430922 | Connector Reconnection | N966735 | Holden Australia |
| 5430922 | Connector Reconnection | N966736 | Holden Australia |
| 5430922 | Connector Reconnection | N966737 | Holden Australia |
| 5430922 | Connector Reconnection | N966738 | Holden Australia |
| 5430922 | Connector Reconnection | N966739 | Holden Australia |
| 5430922 | Connector Reconnection | N966741 | Holden Australia |
| 5430922 | Connector Reconnection | N967001 | Holden Australia |
| 5430922 | Connector Reconnection | N967002 | Holden Australia |
| 5430922 | Connector Reconnection | N967003 | Holden Australia |
| 5430922 | Connector Reconnection | N967004 | Holden Australia |
| 5430922 | Connector Reconnection | N967101 | Holden Australia |
| 5430922 | Connector Reconnection | N967102 | Holden Australia |
| 5430922 | Connector Reconnection | N967103 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N967104 | Holden Australia |
| 5430922 | Connector Reconnection | N967105 | Holden Australia |
| 5430922 | Connector Reconnection | N967106 | Holden Australia |
| 5430922 | Connector Reconnection | N967107 | Holden Australia |
| 5430922 | Connector Reconnection | N967108 | Holden Australia |
| 5430922 | Connector Reconnection | N967109 | Holden Australia |
| 5430922 | Connector Reconnection | N967111 | Holden Australia |
| 5430922 | Connector Reconnection | N967112 | Holden Australia |
| 5430922 | Connector Reconnection | N967113 | Holden Australia |
| 5430922 | Connector Reconnection | N967114 | Holden Australia |
| 5430922 | Connector Reconnection | N967115 | Holden Australia |
| 5430922 | Connector Reconnection | N967116 | Holden Australia |
| 5430922 | Connector Reconnection | N967118 | Holden Australia |
| 5430922 | Connector Reconnection | N967119 | Holden Australia |
| 5430922 | Connector Reconnection | N967120 | Holden Australia |
| 5430922 | Connector Reconnection | N967201 | Holden Australia |
| 5430922 | Connector Reconnection | N967203 | Holden Australia |
| 5430922 | Connector Reconnection | N967204 | Holden Australia |
| 5430922 | Connector Reconnection | N967205 | Holden Australia |
| 5430922 | Connector Reconnection | N967206 | Holden Australia |
| 5430922 | Connector Reconnection | N967502 | Holden Australia |
| 5430922 | Connector Reconnection | N967503 | Holden Australia |
| 5430922 | Connector Reconnection | N967601 | Holden Australia |
| 5430922 | Connector Reconnection | N967603 | Holden Australia |
| 5430922 | Connector Reconnection | N967709 | Holden Australia |
| 5430922 | Connector Reconnection | N967711 | Holden Australia |
| 5430922 | Connector Reconnection | N967714 | Holden Australia |
| 5430922 | Connector Reconnection | N967715 | Holden Australia |
| 5430922 | Connector Reconnection | N967911 | Holden Australia |
| 5430922 | Connector Reconnection | N967917 | Holden Australia |
| 5430922 | Connector Reconnection | N970202 | Holden Australia |
| 5430922 | Connector Reconnection | N970205 | Holden Australia |
| 5430922 | Connector Reconnection | N970305 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N970401 | Holden Australia |
| 5430922 | Connector Reconnection | N970402 | Holden Australia |
| 5430922 | Connector Reconnection | N970403 | Holden Australia |
| 5430922 | Connector Reconnection | N970405 | Holden Australia |
| 5430922 | Connector Reconnection | N970408 | Holden Australia |
| 5430922 | Connector Reconnection | N970410 | Holden Australia |
| 5430922 | Connector Reconnection | N970411 | Holden Australia |
| 5430922 | Connector Reconnection | N970503 | Holden Australia |
| 5430922 | Connector Reconnection | N970504 | Holden Australia |
| 5430922 | Connector Reconnection | N970507 | Holden Australia |
| 5430922 | Connector Reconnection | N970508 | Holden Australia |
| 5430922 | Connector Reconnection | N970509 | Holden Australia |
| 5430922 | Connector Reconnection | N970601 | Holden Australia |
| 5430922 | Connector Reconnection | N970603 | Holden Australia |
| 5430922 | Connector Reconnection | N970605 | Holden Australia |
| 5430922 | Connector Reconnection | N970608 | Holden Australia |
| 5430922 | Connector Reconnection | N970609 | Holden Australia |
| 5430922 | Connector Reconnection | N970610 | Holden Australia |
| 5430922 | Connector Reconnection | N970701 | Holden Australia |
| 5430922 | Connector Reconnection | N970801 | Holden Australia |
| 5430922 | Connector Reconnection | N970803 | Holden Australia |
| 5430922 | Connector Reconnection | N970804 | Holden Australia |
| 5430922 | Connector Reconnection | N970805 | Holden Australia |
| 5430922 | Connector Reconnection | N970808 | Holden Australia |
| 5430922 | Connector Reconnection | N970812 | Holden Australia |
| 5430922 | Connector Reconnection | N970901 | Holden Australia |
| 5430922 | Connector Reconnection | N970903 | Holden Australia |
| 5430922 | Connector Reconnection | N970904 | Holden Australia |
| 5430922 | Connector Reconnection | N970905 | Holden Australia |
| 5430922 | Connector Reconnection | N970906 | Holden Australia |
| 5430922 | Connector Reconnection | N970908 | Holden Australia |
| 5430922 | Connector Reconnection | N970909 | Holden Australia |
| 5430922 | Connector Reconnection | N970914 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N970918 | Holden Australia |
| 5430922 | Connector Reconnection | N971002 | Holden Australia |
| 5430922 | Connector Reconnection | N971003 | Holden Australia |
| 5430922 | Connector Reconnection | N971004 | Holden Australia |
| 5430922 | Connector Reconnection | N971005 | Holden Australia |
| 5430922 | Connector Reconnection | N971006 | Holden Australia |
| 5430922 | Connector Reconnection | N971007 | Holden Australia |
| 5430922 | Connector Reconnection | N971008 | Holden Australia |
| 5430922 | Connector Reconnection | N971009 | Holden Australia |
| 5430922 | Connector Reconnection | N971011 | Holden Australia |
| 5430922 | Connector Reconnection | N971012 | Holden Australia |
| 5430922 | Connector Reconnection | N971101 | Holden Australia |
| 5430922 | Connector Reconnection | N971102 | Holden Australia |
| 5430922 | Connector Reconnection | N971103 | Holden Australia |
| 5430922 | Connector Reconnection | N971107 | Holden Australia |
| 5430922 | Connector Reconnection | N971204 | Holden Australia |
| 5430922 | Connector Reconnection | N971205 | Holden Australia |
| 5430922 | Connector Reconnection | N971207 | Holden Australia |
| 5430922 | Connector Reconnection | N971208 | Holden Australia |
| 5430922 | Connector Reconnection | N971209 | Holden Australia |
| 5430922 | Connector Reconnection | N971302 | Holden Australia |
| 5430922 | Connector Reconnection | N971307 | Holden Australia |
| 5430922 | Connector Reconnection | N971308 | Holden Australia |
| 5430922 | Connector Reconnection | N971401 | Holden Australia |
| 5430922 | Connector Reconnection | N971402 | Holden Australia |
| 5430922 | Connector Reconnection | N971407 | Holden Australia |
| 5430922 | Connector Reconnection | N971408 | Holden Australia |
| 5430922 | Connector Reconnection | N971413 | Holden Australia |
| 5430922 | Connector Reconnection | N971414 | Holden Australia |
| 5430922 | Connector Reconnection | N971415 | Holden Australia |
| 5430922 | Connector Reconnection | N971417 | Holden Australia |
| 5430922 | Connector Reconnection | N971418 | Holden Australia |
| 5430922 | Connector Reconnection | N971419 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N971421 | Holden Australia |
| 5430922 | Connector Reconnection | N971601 | Holden Australia |
| 5430922 | Connector Reconnection | N971602 | Holden Australia |
| 5430922 | Connector Reconnection | N971603 | Holden Australia |
| 5430922 | Connector Reconnection | N971604 | Holden Australia |
| 5430922 | Connector Reconnection | N971605 | Holden Australia |
| 5430922 | Connector Reconnection | N971606 | Holden Australia |
| 5430922 | Connector Reconnection | N971608 | Holden Australia |
| 5430922 | Connector Reconnection | N971609 | Holden Australia |
| 5430922 | Connector Reconnection | N971610 | Holden Australia |
| 5430922 | Connector Reconnection | N971612 | Holden Australia |
| 5430922 | Connector Reconnection | N971615 | Holden Australia |
| 5430922 | Connector Reconnection | N971616 | Holden Australia |
| 5430922 | Connector Reconnection | N971619 | Holden Australia |
| 5430922 | Connector Reconnection | N971620 | Holden Australia |
| 5430922 | Connector Reconnection | N971621 | Holden Australia |
| 5430922 | Connector Reconnection | N971701 | Holden Australia |
| 5430922 | Connector Reconnection | N971703 | Holden Australia |
| 5430922 | Connector Reconnection | N971801 | Holden Australia |
| 5430922 | Connector Reconnection | N971803 | Holden Australia |
| 5430922 | Connector Reconnection | N971804 | Holden Australia |
| 5430922 | Connector Reconnection | N971805 | Holden Australia |
| 5430922 | Connector Reconnection | N971807 | Holden Australia |
| 5430922 | Connector Reconnection | N971808 | Holden Australia |
| 5430922 | Connector Reconnection | N971813 | Holden Australia |
| 5430922 | Connector Reconnection | N971814 | Holden Australia |
| 5430922 | Connector Reconnection | N971815 | Holden Australia |
| 5430922 | Connector Reconnection | N972002 | Holden Australia |
| 5430922 | Connector Reconnection | N972201 | Holden Australia |
| 5430922 | Connector Reconnection | N972202 | Holden Australia |
| 5430922 | Connector Reconnection | N972203 | Holden Australia |
| 5430922 | Connector Reconnection | N972204 | Holden Australia |
| 5430922 | Connector Reconnection | N972205 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N972206 | Holden Australia |
| 5430922 | Connector Reconnection | N972207 | Holden Australia |
| 5430922 | Connector Reconnection | N972208 | Holden Australia |
| 5430922 | Connector Reconnection | N972209 | Holden Australia |
| 5430922 | Connector Reconnection | N972211 | Holden Australia |
| 5430922 | Connector Reconnection | N972212 | Holden Australia |
| 5430922 | Connector Reconnection | N972502 | Holden Australia |
| 5430922 | Connector Reconnection | N972503 | Holden Australia |
| 5430922 | Connector Reconnection | N972504 | Holden Australia |
| 5430922 | Connector Reconnection | N972506 | Holden Australia |
| 5430922 | Connector Reconnection | N972507 | Holden Australia |
| 5430922 | Connector Reconnection | N972508 | Holden Australia |
| 5430922 | Connector Reconnection | N972601 | Holden Australia |
| 5430922 | Connector Reconnection | N972602 | Holden Australia |
| 5430922 | Connector Reconnection | N972604 | Holden Australia |
| 5430922 | Connector Reconnection | N972606 | Holden Australia |
| 5430922 | Connector Reconnection | N972607 | Holden Australia |
| 5430922 | Connector Reconnection | N972610 | Holden Australia |
| 5430922 | Connector Reconnection | N972701 | Holden Australia |
| 5430922 | Connector Reconnection | N972703 | Holden Australia |
| 5430922 | Connector Reconnection | N972801 | Holden Australia |
| 5430922 | Connector Reconnection | N972802 | Holden Australia |
| 5430922 | Connector Reconnection | N972803 | Holden Australia |
| 5430922 | Connector Reconnection | N972804 | Holden Australia |
| 5430922 | Connector Reconnection | N972806 | Holden Australia |
| 5430922 | Connector Reconnection | N972808 | Holden Australia |
| 5430922 | Connector Reconnection | N972809 | Holden Australia |
| 5430922 | Connector Reconnection | N972811 | Holden Australia |
| 5430922 | Connector Reconnection | N972812 | Holden Australia |
| 5430922 | Connector Reconnection | N972901 | Holden Australia |
| 5430922 | Connector Reconnection | N972902 | Holden Australia |
| 5430922 | Connector Reconnection | N972903 | Holden Australia |
| 5430922 | Connector Reconnection | N972904 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N972905 | Holden Australia |
| 5430922 | Connector Reconnection | N972906 | Holden Australia |
| 5430922 | Connector Reconnection | N973001 | Holden Australia |
| 5430922 | Connector Reconnection | N973002 | Holden Australia |
| 5430922 | Connector Reconnection | N973003 | Holden Australia |
| 5430922 | Connector Reconnection | N973004 | Holden Australia |
| 5430922 | Connector Reconnection | N973005 | Holden Australia |
| 5430922 | Connector Reconnection | N973006 | Holden Australia |
| 5430922 | Connector Reconnection | N973008 | Holden Australia |
| 5430922 | Connector Reconnection | N973009 | Holden Australia |
| 5430922 | Connector Reconnection | N973010 | Holden Australia |
| 5430922 | Connector Reconnection | N973011 | Holden Australia |
| 5430922 | Connector Reconnection | N973012 | Holden Australia |
| 5430922 | Connector Reconnection | N973013 | Holden Australia |
| 5430922 | Connector Reconnection | N973102 | Holden Australia |
| 5430922 | Connector Reconnection | N973103 | Holden Australia |
| 5430922 | Connector Reconnection | N973205 | Holden Australia |
| 5430922 | Connector Reconnection | N973206 | Holden Australia |
| 5430922 | Connector Reconnection | N973302 | Holden Australia |
| 5430922 | Connector Reconnection | N973404 | Holden Australia |
| 5430922 | Connector Reconnection | N973406 | Holden Australia |
| 5430922 | Connector Reconnection | N973407 | Holden Australia |
| 5430922 | Connector Reconnection | N973408 | Holden Australia |
| 5430922 | Connector Reconnection | N973410 | Holden Australia |
| 5430922 | Connector Reconnection | N973501 | Holden Australia |
| 5430922 | Connector Reconnection | N974005 | Holden Australia |
| 5430922 | Connector Reconnection | N974102 | Holden Australia |
| 5430922 | Connector Reconnection | N974201 | Holden Australia |
| 5430922 | Connector Reconnection | N974202 | Holden Australia |
| 5430922 | Connector Reconnection | N974205 | Holden Australia |
| 5430922 | Connector Reconnection | N974207 | Holden Australia |
| 5430922 | Connector Reconnection | N974208 | Holden Australia |
| 5430922 | Connector Reconnection | N974303 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N974306 | Holden Australia |
| 5430922 | Connector Reconnection | N974307 | Holden Australia |
| 5430922 | Connector Reconnection | N974308 | Holden Australia |
| 5430922 | Connector Reconnection | N974310 | Holden Australia |
| 5430922 | Connector Reconnection | N974313 | Holden Australia |
| 5430922 | Connector Reconnection | N974314 | Holden Australia |
| 5430922 | Connector Reconnection | N974315 | Holden Australia |
| 5430922 | Connector Reconnection | N974316 | Holden Australia |
| 5430922 | Connector Reconnection | N974317 | Holden Australia |
| 5430922 | Connector Reconnection | N974318 | Holden Australia |
| 5430922 | Connector Reconnection | N974319 | Holden Australia |
| 5430922 | Connector Reconnection | N974323 | Holden Australia |
| 5430922 | Connector Reconnection | N974502 | Holden Australia |
| 5430922 | Connector Reconnection | N974503 | Holden Australia |
| 5430922 | Connector Reconnection | N974504 | Holden Australia |
| 5430922 | Connector Reconnection | N974505 | Holden Australia |
| 5430922 | Connector Reconnection | N974508 | Holden Australia |
| 5430922 | Connector Reconnection | N974510 | Holden Australia |
| 5430922 | Connector Reconnection | N974511 | Holden Australia |
| 5430922 | Connector Reconnection | N974512 | Holden Australia |
| 5430922 | Connector Reconnection | N974515 | Holden Australia |
| 5430922 | Connector Reconnection | N974516 | Holden Australia |
| 5430922 | Connector Reconnection | N974519 | Holden Australia |
| 5430922 | Connector Reconnection | N974520 | Holden Australia |
| 5430922 | Connector Reconnection | N974601 | Holden Australia |
| 5430922 | Connector Reconnection | N974602 | Holden Australia |
| 5430922 | Connector Reconnection | N974603 | Holden Australia |
| 5430922 | Connector Reconnection | N974702 | Holden Australia |
| 5430922 | Connector Reconnection | N974901 | Holden Australia |
| 5430922 | Connector Reconnection | N974904 | Holden Australia |
| 5430922 | Connector Reconnection | N974905 | Holden Australia |
| 5430922 | Connector Reconnection | N974907 | Holden Australia |
| 5430922 | Connector Reconnection | N975003 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N980302 | Holden Australia |
| 5430922 | Connector Reconnection | N980305 | Holden Australia |
| 5430922 | Connector Reconnection | N980803 | Holden Australia |
| 5430922 | Connector Reconnection | N980804 | Holden Australia |
| 5430922 | Connector Reconnection | N980806 | Holden Australia |
| 5430922 | Connector Reconnection | N980807 | Holden Australia |
| 5430922 | Connector Reconnection | N980808 | Holden Australia |
| 5430922 | Connector Reconnection | N980907 | Holden Australia |
| 5430922 | Connector Reconnection | N980908 | Holden Australia |
| 5430922 | Connector Reconnection | N980910 | Holden Australia |
| 5430922 | Connector Reconnection | N980911 | Holden Australia |
| 5430922 | Connector Reconnection | N980918 | Holden Australia |
| 5430922 | Connector Reconnection | N981005 | Holden Australia |
| 5430922 | Connector Reconnection | N981009 | Holden Australia |
| 5430922 | Connector Reconnection | N981012 | Holden Australia |
| 5430922 | Connector Reconnection | N981101 | Holden Australia |
| 5430922 | Connector Reconnection | N981102 | Holden Australia |
| 5430922 | Connector Reconnection | N981103 | Holden Australia |
| 5430922 | Connector Reconnection | N981104 | Holden Australia |
| 5430922 | Connector Reconnection | N981105 | Holden Australia |
| 5430922 | Connector Reconnection | N981106 | Holden Australia |
| 5430922 | Connector Reconnection | N981203 | Holden Australia |
| 5430922 | Connector Reconnection | N981204 | Holden Australia |
| 5430922 | Connector Reconnection | N981205 | Holden Australia |
| 5430922 | Connector Reconnection | N981209 | Holden Australia |
| 5430922 | Connector Reconnection | N981210 | Holden Australia |
| 5430922 | Connector Reconnection | N981304 | Holden Australia |
| 5430922 | Connector Reconnection | N981305 | Holden Australia |
| 5430922 | Connector Reconnection | N981307 | Holden Australia |
| 5430922 | Connector Reconnection | N981308 | Holden Australia |
| 5430922 | Connector Reconnection | N981309 | Holden Australia |
| 5430922 | Connector Reconnection | N981310 | Holden Australia |
| 5430922 | Connector Reconnection | N981313 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N981315 | Holden Australia |
| 5430922 | Connector Reconnection | N981316 | Holden Australia |
| 5430922 | Connector Reconnection | N981318 | Holden Australia |
| 5430922 | Connector Reconnection | N981320 | Holden Australia |
| 5430922 | Connector Reconnection | N981324 | Holden Australia |
| 5430922 | Connector Reconnection | N981325 | Holden Australia |
| 5430922 | Connector Reconnection | N981503 | Holden Australia |
| 5430922 | Connector Reconnection | N981506 | Holden Australia |
| 5430922 | Connector Reconnection | N981601 | Holden Australia |
| 5430922 | Connector Reconnection | N981609 | Holden Australia |
| 5430922 | Connector Reconnection | N981801 | Holden Australia |
| 5430922 | Connector Reconnection | N981802 | Holden Australia |
| 5430922 | Connector Reconnection | N981804 | Holden Australia |
| 5430922 | Connector Reconnection | N981805 | Holden Australia |
| 5430922 | Connector Reconnection | N981809 | Holden Australia |
| 5430922 | Connector Reconnection | N981812 | Holden Australia |
| 5430922 | Connector Reconnection | N981814 | Holden Australia |
| 5430922 | Connector Reconnection | N981816 | Holden Australia |
| 5430922 | Connector Reconnection | N981817 | Holden Australia |
| 5430922 | Connector Reconnection | N981818 | Holden Australia |
| 5430922 | Connector Reconnection | N981819 | Holden Australia |
| 5430922 | Connector Reconnection | N981821 | Holden Australia |
| 5430922 | Connector Reconnection | N981822 | Holden Australia |
| 5430922 | Connector Reconnection | N981823 | Holden Australia |
| 5430922 | Connector Reconnection | N981824 | Holden Australia |
| 5430922 | Connector Reconnection | N981825 | Holden Australia |
| 5430922 | Connector Reconnection | N981826 | Holden Australia |
| 5430922 | Connector Reconnection | N981827 | Holden Australia |
| 5430922 | Connector Reconnection | N981828 | Holden Australia |
| 5430922 | Connector Reconnection | N981829 | Holden Australia |
| 5430922 | Connector Reconnection | N981831 | Holden Australia |
| 5430922 | Connector Reconnection | N981834 | Holden Australia |
| 5430922 | Connector Reconnection | N981841 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N982103 | Holden Australia |
| 5430922 | Connector Reconnection | N982106 | Holden Australia |
| 5430922 | Connector Reconnection | N982204 | Holden Australia |
| 5430922 | Connector Reconnection | N982205 | Holden Australia |
| 5430922 | Connector Reconnection | N982206 | Holden Australia |
| 5430922 | Connector Reconnection | N982207 | Holden Australia |
| 5430922 | Connector Reconnection | N982302 | Holden Australia |
| 5430922 | Connector Reconnection | N982303 | Holden Australia |
| 5430922 | Connector Reconnection | N982501 | Holden Australia |
| 5430922 | Connector Reconnection | N982503 | Holden Australia |
| 5430922 | Connector Reconnection | N982504 | Holden Australia |
| 5430922 | Connector Reconnection | N982505 | Holden Australia |
| 5430922 | Connector Reconnection | N982506 | Holden Australia |
| 5430922 | Connector Reconnection | N982507 | Holden Australia |
| 5430922 | Connector Reconnection | N982508 | Holden Australia |
| 5430922 | Connector Reconnection | N982510 | Holden Australia |
| 5430922 | Connector Reconnection | N982514 | Holden Australia |
| 5430922 | Connector Reconnection | N982516 | Holden Australia |
| 5430922 | Connector Reconnection | N982517 | Holden Australia |
| 5430922 | Connector Reconnection | N982601 | Holden Australia |
| 5430922 | Connector Reconnection | N982603 | Holden Australia |
| 5430922 | Connector Reconnection | N982702 | Holden Australia |
| 5430922 | Connector Reconnection | N982704 | Holden Australia |
| 5430922 | Connector Reconnection | N982705 | Holden Australia |
| 5430922 | Connector Reconnection | N982708 | Holden Australia |
| 5430922 | Connector Reconnection | N982709 | Holden Australia |
| 5430922 | Connector Reconnection | N982710 | Holden Australia |
| 5430922 | Connector Reconnection | N982712 | Holden Australia |
| 5430922 | Connector Reconnection | N982904 | Holden Australia |
| 5430922 | Connector Reconnection | N982907 | Holden Australia |
| 5430922 | Connector Reconnection | N982908 | Holden Australia |
| 5430922 | Connector Reconnection | N982910 | Holden Australia |
| 5430922 | Connector Reconnection | N982911 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N982912 | Holden Australia |
| 5430922 | Connector Reconnection | N983004 | Holden Australia |
| 5430922 | Connector Reconnection | N983011 | Holden Australia |
| 5430922 | Connector Reconnection | N983102 | Holden Australia |
| 5430922 | Connector Reconnection | N983107 | Holden Australia |
| 5430922 | Connector Reconnection | N983108 | Holden Australia |
| 5430922 | Connector Reconnection | N983109 | Holden Australia |
| 5430922 | Connector Reconnection | N983110 | Holden Australia |
| 5430922 | Connector Reconnection | N983202 | Holden Australia |
| 5430922 | Connector Reconnection | N983204 | Holden Australia |
| 5430922 | Connector Reconnection | N983205 | Holden Australia |
| 5430922 | Connector Reconnection | N983301 | Holden Australia |
| 5430922 | Connector Reconnection | N983303 | Holden Australia |
| 5430922 | Connector Reconnection | N983304 | Holden Australia |
| 5430922 | Connector Reconnection | N983402 | Holden Australia |
| 5430922 | Connector Reconnection | N983403 | Holden Australia |
| 5430922 | Connector Reconnection | N983404 | Holden Australia |
| 5430922 | Connector Reconnection | N983405 | Holden Australia |
| 5430922 | Connector Reconnection | N983407 | Holden Australia |
| 5430922 | Connector Reconnection | N983408 | Holden Australia |
| 5430922 | Connector Reconnection | N983409 | Holden Australia |
| 5430922 | Connector Reconnection | N983412 | Holden Australia |
| 5430922 | Connector Reconnection | N983413 | Holden Australia |
| 5430922 | Connector Reconnection | N983418 | Holden Australia |
| 5430922 | Connector Reconnection | N983501 | Holden Australia |
| 5430922 | Connector Reconnection | N983502 | Holden Australia |
| 5430922 | Connector Reconnection | N983601 | Holden Australia |
| 5430922 | Connector Reconnection | N983701 | Holden Australia |
| 5430922 | Connector Reconnection | N983702 | Holden Australia |
| 5430922 | Connector Reconnection | N983801 | Holden Australia |
| 5430922 | Connector Reconnection | N983802 | Holden Australia |
| 5430922 | Connector Reconnection | N983803 | Holden Australia |
| 5430922 | Connector Reconnection | N983804 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N984003 | Holden Australia |
| 5430922 | Connector Reconnection | N984005 | Holden Australia |
| 5430922 | Connector Reconnection | N984008 | Holden Australia |
| 5430922 | Connector Reconnection | N984009 | Holden Australia |
| 5430922 | Connector Reconnection | N984011 | Holden Australia |
| 5430922 | Connector Reconnection | N984013 | Holden Australia |
| 5430922 | Connector Reconnection | N984015 | Holden Australia |
| 5430922 | Connector Reconnection | N984016 | Holden Australia |
| 5430922 | Connector Reconnection | N984017 | Holden Australia |
| 5430922 | Connector Reconnection | N984018 | Holden Australia |
| 5430922 | Connector Reconnection | N984019 | Holden Australia |
| 5430922 | Connector Reconnection | N984021 | Holden Australia |
| 5430922 | Connector Reconnection | N984023 | Holden Australia |
| 5430922 | Connector Reconnection | N984025 | Holden Australia |
| 5430922 | Connector Reconnection | N984027 | Holden Australia |
| 5430922 | Connector Reconnection | N984102 | Holden Australia |
| 5430922 | Connector Reconnection | N984103 | Holden Australia |
| 5430922 | Connector Reconnection | N984104 | Holden Australia |
| 5430922 | Connector Reconnection | N984105 | Holden Australia |
| 5430922 | Connector Reconnection | N984106 | Holden Australia |
| 5430922 | Connector Reconnection | N984107 | Holden Australia |
| 5430922 | Connector Reconnection | N984108 | Holden Australia |
| 5430922 | Connector Reconnection | N984109 | Holden Australia |
| 5430922 | Connector Reconnection | N984110 | Holden Australia |
| 5430922 | Connector Reconnection | N984112 | Holden Australia |
| 5430922 | Connector Reconnection | N984114 | Holden Australia |
| 5430922 | Connector Reconnection | N984116 | Holden Australia |
| 5430922 | Connector Reconnection | N984117 | Holden Australia |
| 5430922 | Connector Reconnection | N984118 | Holden Australia |
| 5430922 | Connector Reconnection | N984119 | Holden Australia |
| 5430922 | Connector Reconnection | N984201 | Holden Australia |
| 5430922 | Connector Reconnection | N984202 | Holden Australia |
| 5430922 | Connector Reconnection | N984204 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430922 | Connector Reconnection | N984301 | Holden Australia |
| 5430922 | Connector Reconnection | N984303 | Holden Australia |
| 5430922 | Connector Reconnection | N984304 | Holden Australia |
| 5430922 | Connector Reconnection | N984307 | Holden Australia |
| 5430922 | Connector Reconnection | N984310 | Holden Australia |
| 5430922 | Connector Reconnection | N984601 | Holden Australia |
| 5430922 | Connector Reconnection | N984602 | Holden Australia |
| 5430922 | Connector Reconnection | N984803 | Holden Australia |
| 5430922 | Connector Reconnection | N984906 | Holden Australia |
| 5430922 | Connector Reconnection | N984908 | Holden Australia |
| 5430922 | Connector Reconnection | N985001 | Holden Australia |
| 5430922 | Connector Reconnection | N985107 | Holden Australia |
| 5430922 | Connector Reconnection | N985108 | Holden Australia |
| 5430922 | Connector Reconnection | N985110 | Holden Australia |
| 5430922 | Connector Reconnection | N985111 | Holden Australia |
| 5430922 | Connector Reconnection | N985114 | Holden Australia |
| 5430922 | Connector Reconnection | N985115 | Holden Australia |
| 5430922 | Connector Reconnection | N985117 | Holden Australia |
| 5430922 | Connector Reconnection | N985203 | Holden Australia |
| 5430922 | Connector Reconnection | N985204 | Holden Australia |
| 5430922 | Connector Reconnection | r603600 | Holden Australia |
| 5430922 | Connector Reconnection | N000288 | Holden New Zealand |
| 5430922 | Connector Reconnection | N6654 | Holden New Zealand |
| 5430922 | Connector Reconnection | R1861300 | GMK Overseas |
| 5430940 | Harness Replacement | B9787 | GMNA |
| 5430940 | Harness Replacement | C7090 | GMNA |
| 5430940 | Harness Replacement | C9719 | GMNA |
| 5430940 | Harness Replacement | C9738 | GMNA |
| 5430940 | Harness Replacement | C9768 | GMNA |
| 5430940 | Harness Replacement | C9848 | GMNA |
| 5430940 | Harness Replacement | C9852 | GMNA |
| 5430940 | Harness Replacement | D1705 | GMNA |
| 5430940 | Harness Replacement | E5875 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | F9717 | GMNA |
| 5430940 | Harness Replacement | J4675 | GMNA |
| 5430940 | Harness Replacement | J4745 | GMNA |
| 5430940 | Harness Replacement | J6240 | GMNA |
| 5430940 | Harness Replacement | J7709 | GMNA |
| 5430940 | Harness Replacement | J7711 | GMNA |
| 5430940 | Harness Replacement | J7715 | GMNA |
| 5430940 | Harness Replacement | J7720 | GMNA |
| 5430940 | Harness Replacement | J7736 | GMNA |
| 5430940 | Harness Replacement | J7946 | GMNA |
| 5430940 | Harness Replacement | J8309 | GMNA |
| 5430940 | Harness Replacement | J8315 | GMNA |
| 5430940 | Harness Replacement | J8316 | GMNA |
| 5430940 | Harness Replacement | J8317 | GMNA |
| 5430940 | Harness Replacement | K6551 | GMNA |
| 5430940 | Harness Replacement | K6553 | GMNA |
| 5430940 | Harness Replacement | K8190 | GMNA |
| 5430940 | Harness Replacement | K8192 | GMNA |
| 5430940 | Harness Replacement | K9506 | GMNA |
| 5430940 | Harness Replacement | K9552 | GMNA |
| 5430940 | Harness Replacement | N3364 | GMNA |
| 5430940 | Harness Replacement | N3706 | GMNA |
| 5430940 | Harness Replacement | N4803 | GMNA |
| 5430940 | Harness Replacement | N5130 | GMNA |
| 5430940 | Harness Replacement | N5845 | GMNA |
| 5430940 | Harness Replacement | N6025 | GMNA |
| 5430940 | Harness Replacement | N6040 | GMNA |
| 5430940 | Harness Replacement | N6070 | GMNA |
| 5430940 | Harness Replacement | N6080 | GMNA |
| 5430940 | Harness Replacement | N6090 | GMNA |
| 5430940 | Harness Replacement | N6110 | GMNA |
| 5430940 | Harness Replacement | N6111 | GMNA |
| 5430940 | Harness Replacement | N6112 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N6113 | GMNA |
| 5430940 | Harness Replacement | N6124 | GMNA |
| 5430940 | Harness Replacement | N6125 | GMNA |
| 5430940 | Harness Replacement | N6126 | GMNA |
| 5430940 | Harness Replacement | N6127 | GMNA |
| 5430940 | Harness Replacement | N6195 | GMNA |
| 5430940 | Harness Replacement | N6214 | GMNA |
| 5430940 | Harness Replacement | N6215 | GMNA |
| 5430940 | Harness Replacement | N6216 | GMNA |
| 5430940 | Harness Replacement | N6217 | GMNA |
| 5430940 | Harness Replacement | N6218 | GMNA |
| 5430940 | Harness Replacement | N6219 | GMNA |
| 5430940 | Harness Replacement | N6224 | GMNA |
| 5430940 | Harness Replacement | N6225 | GMNA |
| 5430940 | Harness Replacement | N6234 | GMNA |
| 5430940 | Harness Replacement | N6235 | GMNA |
| 5430940 | Harness Replacement | N6236 | GMNA |
| 5430940 | Harness Replacement | N6240 | GMNA |
| 5430940 | Harness Replacement | N6241 | GMNA |
| 5430940 | Harness Replacement | N6242 | GMNA |
| 5430940 | Harness Replacement | N6250 | GMNA |
| 5430940 | Harness Replacement | N6251 | GMNA |
| 5430940 | Harness Replacement | N6254 | GMNA |
| 5430940 | Harness Replacement | N6255 | GMNA |
| 5430940 | Harness Replacement | N6264 | GMNA |
| 5430940 | Harness Replacement | N6265 | GMNA |
| 5430940 | Harness Replacement | N6271 | GMNA |
| 5430940 | Harness Replacement | N6276 | GMNA |
| 5430940 | Harness Replacement | N6278 | GMNA |
| 5430940 | Harness Replacement | N6280 | GMNA |
| 5430940 | Harness Replacement | N6310 | GMNA |
| 5430940 | Harness Replacement | N6320 | GMNA |
| 5430940 | Harness Replacement | N6340 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N6341 | GMNA |
| 5430940 | Harness Replacement | N6347 | GMNA |
| 5430940 | Harness Replacement | N6350 | GMNA |
| 5430940 | Harness Replacement | N6351 | GMNA |
| 5430940 | Harness Replacement | N6355 | GMNA |
| 5430940 | Harness Replacement | N6360 | GMNA |
| 5430940 | Harness Replacement | N6363 | GMNA |
| 5430940 | Harness Replacement | N6396 | GMNA |
| 5430940 | Harness Replacement | N6397 | GMNA |
| 5430940 | Harness Replacement | N6398 | GMNA |
| 5430940 | Harness Replacement | N6401 | GMNA |
| 5430940 | Harness Replacement | N6402 | GMNA |
| 5430940 | Harness Replacement | N6404 | GMNA |
| 5430940 | Harness Replacement | N6405 | GMNA |
| 5430940 | Harness Replacement | N6407 | GMNA |
| 5430940 | Harness Replacement | N6415 | GMNA |
| 5430940 | Harness Replacement | N6419 | GMNA |
| 5430940 | Harness Replacement | N6420 | GMNA |
| 5430940 | Harness Replacement | N6430 | GMNA |
| 5430940 | Harness Replacement | N6440 | GMNA |
| 5430940 | Harness Replacement | N6470 | GMNA |
| 5430940 | Harness Replacement | N6480 | GMNA |
| 5430940 | Harness Replacement | N6487 | GMNA |
| 5430940 | Harness Replacement | N6488 | GMNA |
| 5430940 | Harness Replacement | N6510 | GMNA |
| 5430940 | Harness Replacement | N6520 | GMNA |
| 5430940 | Harness Replacement | N6540 | GMNA |
| 5430940 | Harness Replacement | N6550 | GMNA |
| 5430940 | Harness Replacement | N6555 | GMNA |
| 5430940 | Harness Replacement | N6560 | GMNA |
| 5430940 | Harness Replacement | N6570 | GMNA |
| 5430940 | Harness Replacement | N6585 | GMNA |
| 5430940 | Harness Replacement | N6610 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N6616 | GMNA |
| 5430940 | Harness Replacement | N6630 | GMNA |
| 5430940 | Harness Replacement | N6653 | GMNA |
| 5430940 | Harness Replacement | N6655 | GMNA |
| 5430940 | Harness Replacement | N6780 | GMNA |
| 5430940 | Harness Replacement | N6980 | GMNA |
| 5430940 | Harness Replacement | N6981 | GMNA |
| 5430940 | Harness Replacement | N6982 | GMNA |
| 5430940 | Harness Replacement | N6984 | GMNA |
| 5430940 | Harness Replacement | N6985 | GMNA |
| 5430940 | Harness Replacement | N6990 | GMNA |
| 5430940 | Harness Replacement | N7000 | GMNA |
| 5430940 | Harness Replacement | N7010 | GMNA |
| 5430940 | Harness Replacement | N7060 | GMNA |
| 5430940 | Harness Replacement | N7063 | GMNA |
| 5430940 | Harness Replacement | N7090 | GMNA |
| 5430940 | Harness Replacement | N7093 | GMNA |
| 5430940 | Harness Replacement | N7110 | GMNA |
| 5430940 | Harness Replacement | N7120 | GMNA |
| 5430940 | Harness Replacement | N7130 | GMNA |
| 5430940 | Harness Replacement | N7131 | GMNA |
| 5430940 | Harness Replacement | N7132 | GMNA |
| 5430940 | Harness Replacement | N7134 | GMNA |
| 5430940 | Harness Replacement | N7135 | GMNA |
| 5430940 | Harness Replacement | N7137 | GMNA |
| 5430940 | Harness Replacement | N7140 | GMNA |
| 5430940 | Harness Replacement | N7141 | GMNA |
| 5430940 | Harness Replacement | N7143 | GMNA |
| 5430940 | Harness Replacement | N7144 | GMNA |
| 5430940 | Harness Replacement | N7145 | GMNA |
| 5430940 | Harness Replacement | N7149 | GMNA |
| 5430940 | Harness Replacement | N7150 | GMNA |
| 5430940 | Harness Replacement | N7190 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N7230 | GMNA |
| 5430940 | Harness Replacement | N7265 | GMNA |
| 5430940 | Harness Replacement | N8512 | GMNA |
| 5430940 | Harness Replacement | N9531 | GMNA |
| 5430940 | Harness Replacement | N9537 | GMNA |
| 5430940 | Harness Replacement | N9538 | GMNA |
| 5430940 | Harness Replacement | N9544 | GMNA |
| 5430940 | Harness Replacement | N9561 | GMNA |
| 5430940 | Harness Replacement | N9562 | GMNA |
| 5430940 | Harness Replacement | N9573 | GMNA |
| 5430940 | Harness Replacement | N9575 | GMNA |
| 5430940 | Harness Replacement | N9581 | GMNA |
| 5430940 | Harness Replacement | N9586 | GMNA |
| 5430940 | Harness Replacement | N9587 | GMNA |
| 5430940 | Harness Replacement | N9598 | GMNA |
| 5430940 | Harness Replacement | N9600 | GMNA |
| 5430940 | Harness Replacement | N9601 | GMNA |
| 5430940 | Harness Replacement | N9602 | GMNA |
| 5430940 | Harness Replacement | N9626 | GMNA |
| 5430940 | Harness Replacement | N9637 | GMNA |
| 5430940 | Harness Replacement | N9643 | GMNA |
| 5430940 | Harness Replacement | N9648 | GMNA |
| 5430940 | Harness Replacement | N9661 | GMNA |
| 5430940 | Harness Replacement | N9664 | GMNA |
| 5430940 | Harness Replacement | N9673 | GMNA |
| 5430940 | Harness Replacement | N9674 | GMNA |
| 5430940 | Harness Replacement | R5144 | GMNA |
| 5430940 | Harness Replacement | R9743 | GMNA |
| 5430940 | Harness Replacement | 6110200 | GMK Domestic |
| 5430940 | Harness Replacement | B222222 | Holden Australia |
| 5430940 | Harness Replacement | C000482 | Holden Australia |
| 5430940 | Harness Replacement | C000571 | Holden Australia |
| 5430940 | Harness Replacement | F400800 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | H903000 | Holden Australia |
| 5430940 | Harness Replacement | J000559 | Holden Australia |
| 5430940 | Harness Replacement | J000893 | Holden Australia |
| 5430940 | Harness Replacement | J000896 | Holden Australia |
| 5430940 | Harness Replacement | J589200 | Holden Australia |
| 5430940 | Harness Replacement | K0001 | Holden Australia |
| 5430940 | Harness Replacement | M222222 | Holden Australia |
| 5430940 | Harness Replacement | N000261 | Holden Australia |
| 5430940 | Harness Replacement | N000276 | Holden Australia |
| 5430940 | Harness Replacement | N000279 | Holden Australia |
| 5430940 | Harness Replacement | N000285 | Holden Australia |
| 5430940 | Harness Replacement | N000390 | Holden Australia |
| 5430940 | Harness Replacement | N000411 | Holden Australia |
| 5430940 | Harness Replacement | N000423 | Holden Australia |
| 5430940 | Harness Replacement | N000429 | Holden Australia |
| 5430940 | Harness Replacement | N000432 | Holden Australia |
| 5430940 | Harness Replacement | N000454 | Holden Australia |
| 5430940 | Harness Replacement | N000565 | Holden Australia |
| 5430940 | Harness Replacement | N000571 | Holden Australia |
| 5430940 | Harness Replacement | N000704 | Holden Australia |
| 5430940 | Harness Replacement | N000747 | Holden Australia |
| 5430940 | Harness Replacement | N000759 | Holden Australia |
| 5430940 | Harness Replacement | N000762 | Holden Australia |
| 5430940 | Harness Replacement | N000783 | Holden Australia |
| 5430940 | Harness Replacement | N001710 | Holden Australia |
| 5430940 | Harness Replacement | N001750 | Holden Australia |
| 5430940 | Harness Replacement | N206500 | Holden Australia |
| 5430940 | Harness Replacement | N223400 | Holden Australia |
| 5430940 | Harness Replacement | N303500 | Holden Australia |
| 5430940 | Harness Replacement | N308700 | Holden Australia |
| 5430940 | Harness Replacement | N390000 | Holden Australia |
| 5430940 | Harness Replacement | N401000 | Holden Australia |
| 5430940 | Harness Replacement | N401599 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N401810 | Holden Australia |
| 5430940 | Harness Replacement | N401820 | Holden Australia |
| 5430940 | Harness Replacement | N403499 | Holden Australia |
| 5430940 | Harness Replacement | N403599 | Holden Australia |
| 5430940 | Harness Replacement | N405510 | Holden Australia |
| 5430940 | Harness Replacement | N405599 | Holden Australia |
| 5430940 | Harness Replacement | N407599 | Holden Australia |
| 5430940 | Harness Replacement | N408599 | Holden Australia |
| 5430940 | Harness Replacement | N409599 | Holden Australia |
| 5430940 | Harness Replacement | N410010 | Holden Australia |
| 5430940 | Harness Replacement | N410110 | Holden Australia |
| 5430940 | Harness Replacement | N410210 | Holden Australia |
| 5430940 | Harness Replacement | N410600 | Holden Australia |
| 5430940 | Harness Replacement | N411599 | Holden Australia |
| 5430940 | Harness Replacement | N412000 | Holden Australia |
| 5430940 | Harness Replacement | N413599 | Holden Australia |
| 5430940 | Harness Replacement | N414000 | Holden Australia |
| 5430940 | Harness Replacement | N451599 | Holden Australia |
| 5430940 | Harness Replacement | N453599 | Holden Australia |
| 5430940 | Harness Replacement | N453699 | Holden Australia |
| 5430940 | Harness Replacement | N457199 | Holden Australia |
| 5430940 | Harness Replacement | N457299 | Holden Australia |
| 5430940 | Harness Replacement | N459199 | Holden Australia |
| 5430940 | Harness Replacement | N459299 | Holden Australia |
| 5430940 | Harness Replacement | N466199 | Holden Australia |
| 5430940 | Harness Replacement | N466299 | Holden Australia |
| 5430940 | Harness Replacement | N471599 | Holden Australia |
| 5430940 | Harness Replacement | N481599 | Holden Australia |
| 5430940 | Harness Replacement | N482699 | Holden Australia |
| 5430940 | Harness Replacement | N511000 | Holden Australia |
| 5430940 | Harness Replacement | N541140 | Holden Australia |
| 5430940 | Harness Replacement | N581000 | Holden Australia |
| 5430940 | Harness Replacement | N582000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N603000 | Holden Australia |
| 5430940 | Harness Replacement | N606500 | Holden Australia |
| 5430940 | Harness Replacement | N607000 | Holden Australia |
| 5430940 | Harness Replacement | N611200 | Holden Australia |
| 5430940 | Harness Replacement | N611300 | Holden Australia |
| 5430940 | Harness Replacement | N618000 | Holden Australia |
| 5430940 | Harness Replacement | N622400 | Holden Australia |
| 5430940 | Harness Replacement | N622500 | Holden Australia |
| 5430940 | Harness Replacement | N623400 | Holden Australia |
| 5430940 | Harness Replacement | N623500 | Holden Australia |
| 5430940 | Harness Replacement | N623800 | Holden Australia |
| 5430940 | Harness Replacement | N625400 | Holden Australia |
| 5430940 | Harness Replacement | N625500 | Holden Australia |
| 5430940 | Harness Replacement | N626400 | Holden Australia |
| 5430940 | Harness Replacement | N626500 | Holden Australia |
| 5430940 | Harness Replacement | N627000 | Holden Australia |
| 5430940 | Harness Replacement | N629000 | Holden Australia |
| 5430940 | Harness Replacement | N631000 | Holden Australia |
| 5430940 | Harness Replacement | N636000 | Holden Australia |
| 5430940 | Harness Replacement | N639800 | Holden Australia |
| 5430940 | Harness Replacement | N644000 | Holden Australia |
| 5430940 | Harness Replacement | N6600 | Holden Australia |
| 5430940 | Harness Replacement | N6602 | Holden Australia |
| 5430940 | Harness Replacement | N6604 | Holden Australia |
| 5430940 | Harness Replacement | N6606 | Holden Australia |
| 5430940 | Harness Replacement | N6608 | Holden Australia |
| 5430940 | Harness Replacement | N6612 | Holden Australia |
| 5430940 | Harness Replacement | N6614 | Holden Australia |
| 5430940 | Harness Replacement | N6616 | Holden Australia |
| 5430940 | Harness Replacement | N6618 | Holden Australia |
| 5430940 | Harness Replacement | N6622 | Holden Australia |
| 5430940 | Harness Replacement | N6624 | Holden Australia |
| 5430940 | Harness Replacement | N6626 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N6628 | Holden Australia |
| 5430940 | Harness Replacement | N6629 | Holden Australia |
| 5430940 | Harness Replacement | N6631 | Holden Australia |
| 5430940 | Harness Replacement | N6632 | Holden Australia |
| 5430940 | Harness Replacement | N6634 | Holden Australia |
| 5430940 | Harness Replacement | N6636 | Holden Australia |
| 5430940 | Harness Replacement | N6638 | Holden Australia |
| 5430940 | Harness Replacement | N6642 | Holden Australia |
| 5430940 | Harness Replacement | N6644 | Holden Australia |
| 5430940 | Harness Replacement | N6970 | Holden Australia |
| 5430940 | Harness Replacement | N706000 | Holden Australia |
| 5430940 | Harness Replacement | N706100 | Holden Australia |
| 5430940 | Harness Replacement | N706200 | Holden Australia |
| 5430940 | Harness Replacement | N706300 | Holden Australia |
| 5430940 | Harness Replacement | N706400 | Holden Australia |
| 5430940 | Harness Replacement | N706500 | Holden Australia |
| 5430940 | Harness Replacement | N706600 | Holden Australia |
| 5430940 | Harness Replacement | N706700 | Holden Australia |
| 5430940 | Harness Replacement | N706800 | Holden Australia |
| 5430940 | Harness Replacement | N706900 | Holden Australia |
| 5430940 | Harness Replacement | N707000 | Holden Australia |
| 5430940 | Harness Replacement | N709000 | Holden Australia |
| 5430940 | Harness Replacement | N709300 | Holden Australia |
| 5430940 | Harness Replacement | N710388 | Holden Australia |
| 5430940 | Harness Replacement | N710389 | Holden Australia |
| 5430940 | Harness Replacement | N710390 | Holden Australia |
| 5430940 | Harness Replacement | N710392 | Holden Australia |
| 5430940 | Harness Replacement | N710394 | Holden Australia |
| 5430940 | Harness Replacement | N710397 | Holden Australia |
| 5430940 | Harness Replacement | N710484 | Holden Australia |
| 5430940 | Harness Replacement | N710485 | Holden Australia |
| 5430940 | Harness Replacement | N710486 | Holden Australia |
| 5430940 | Harness Replacement | N710487 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N710488 | Holden Australia |
| 5430940 | Harness Replacement | N710489 | Holden Australia |
| 5430940 | Harness Replacement | N710492 | Holden Australia |
| 5430940 | Harness Replacement | N710493 | Holden Australia |
| 5430940 | Harness Replacement | N710495 | Holden Australia |
| 5430940 | Harness Replacement | N710496 | Holden Australia |
| 5430940 | Harness Replacement | N710584 | Holden Australia |
| 5430940 | Harness Replacement | N710586 | Holden Australia |
| 5430940 | Harness Replacement | N710587 | Holden Australia |
| 5430940 | Harness Replacement | N710588 | Holden Australia |
| 5430940 | Harness Replacement | N710589 | Holden Australia |
| 5430940 | Harness Replacement | N710590 | Holden Australia |
| 5430940 | Harness Replacement | N710594 | Holden Australia |
| 5430940 | Harness Replacement | N710595 | Holden Australia |
| 5430940 | Harness Replacement | N710596 | Holden Australia |
| 5430940 | Harness Replacement | N710684 | Holden Australia |
| 5430940 | Harness Replacement | N710685 | Holden Australia |
| 5430940 | Harness Replacement | N710686 | Holden Australia |
| 5430940 | Harness Replacement | N710687 | Holden Australia |
| 5430940 | Harness Replacement | N710690 | Holden Australia |
| 5430940 | Harness Replacement | N710691 | Holden Australia |
| 5430940 | Harness Replacement | N710692 | Holden Australia |
| 5430940 | Harness Replacement | N710693 | Holden Australia |
| 5430940 | Harness Replacement | N710694 | Holden Australia |
| 5430940 | Harness Replacement | N710695 | Holden Australia |
| 5430940 | Harness Replacement | N710696 | Holden Australia |
| 5430940 | Harness Replacement | N710697 | Holden Australia |
| 5430940 | Harness Replacement | N710786 | Holden Australia |
| 5430940 | Harness Replacement | N710787 | Holden Australia |
| 5430940 | Harness Replacement | N710788 | Holden Australia |
| 5430940 | Harness Replacement | N710789 | Holden Australia |
| 5430940 | Harness Replacement | N710790 | Holden Australia |
| 5430940 | Harness Replacement | N710791 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N710795 | Holden Australia |
| 5430940 | Harness Replacement | N710796 | Holden Australia |
| 5430940 | Harness Replacement | N710797 | Holden Australia |
| 5430940 | Harness Replacement | N710886 | Holden Australia |
| 5430940 | Harness Replacement | N710887 | Holden Australia |
| 5430940 | Harness Replacement | N710888 | Holden Australia |
| 5430940 | Harness Replacement | N710895 | Holden Australia |
| 5430940 | Harness Replacement | N710896 | Holden Australia |
| 5430940 | Harness Replacement | N710993 | Holden Australia |
| 5430940 | Harness Replacement | N710995 | Holden Australia |
| 5430940 | Harness Replacement | N711085 | Holden Australia |
| 5430940 | Harness Replacement | N711086 | Holden Australia |
| 5430940 | Harness Replacement | N711087 | Holden Australia |
| 5430940 | Harness Replacement | N711089 | Holden Australia |
| 5430940 | Harness Replacement | N711090 | Holden Australia |
| 5430940 | Harness Replacement | N711092 | Holden Australia |
| 5430940 | Harness Replacement | N711093 | Holden Australia |
| 5430940 | Harness Replacement | N711095 | Holden Australia |
| 5430940 | Harness Replacement | N711096 | Holden Australia |
| 5430940 | Harness Replacement | N711097 | Holden Australia |
| 5430940 | Harness Replacement | N711186 | Holden Australia |
| 5430940 | Harness Replacement | N711188 | Holden Australia |
| 5430940 | Harness Replacement | N711189 | Holden Australia |
| 5430940 | Harness Replacement | N711193 | Holden Australia |
| 5430940 | Harness Replacement | N711195 | Holden Australia |
| 5430940 | Harness Replacement | N711288 | Holden Australia |
| 5430940 | Harness Replacement | N711289 | Holden Australia |
| 5430940 | Harness Replacement | N711290 | Holden Australia |
| 5430940 | Harness Replacement | N711291 | Holden Australia |
| 5430940 | Harness Replacement | N711295 | Holden Australia |
| 5430940 | Harness Replacement | N711296 | Holden Australia |
| 5430940 | Harness Replacement | N711385 | Holden Australia |
| 5430940 | Harness Replacement | N711387 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N711388 | Holden Australia |
| 5430940 | Harness Replacement | N711391 | Holden Australia |
| 5430940 | Harness Replacement | N711392 | Holden Australia |
| 5430940 | Harness Replacement | N711393 | Holden Australia |
| 5430940 | Harness Replacement | N711395 | Holden Australia |
| 5430940 | Harness Replacement | N711396 | Holden Australia |
| 5430940 | Harness Replacement | N711486 | Holden Australia |
| 5430940 | Harness Replacement | N711487 | Holden Australia |
| 5430940 | Harness Replacement | N711488 | Holden Australia |
| 5430940 | Harness Replacement | N711490 | Holden Australia |
| 5430940 | Harness Replacement | N711491 | Holden Australia |
| 5430940 | Harness Replacement | N711494 | Holden Australia |
| 5430940 | Harness Replacement | N711495 | Holden Australia |
| 5430940 | Harness Replacement | N711496 | Holden Australia |
| 5430940 | Harness Replacement | N711586 | Holden Australia |
| 5430940 | Harness Replacement | N711587 | Holden Australia |
| 5430940 | Harness Replacement | N711588 | Holden Australia |
| 5430940 | Harness Replacement | N711589 | Holden Australia |
| 5430940 | Harness Replacement | N711590 | Holden Australia |
| 5430940 | Harness Replacement | N711594 | Holden Australia |
| 5430940 | Harness Replacement | N711595 | Holden Australia |
| 5430940 | Harness Replacement | N711596 | Holden Australia |
| 5430940 | Harness Replacement | N711686 | Holden Australia |
| 5430940 | Harness Replacement | N711687 | Holden Australia |
| 5430940 | Harness Replacement | N711691 | Holden Australia |
| 5430940 | Harness Replacement | N711692 | Holden Australia |
| 5430940 | Harness Replacement | N711696 | Holden Australia |
| 5430940 | Harness Replacement | N711786 | Holden Australia |
| 5430940 | Harness Replacement | N711790 | Holden Australia |
| 5430940 | Harness Replacement | N711791 | Holden Australia |
| 5430940 | Harness Replacement | N711794 | Holden Australia |
| 5430940 | Harness Replacement | N711797 | Holden Australia |
| 5430940 | Harness Replacement | N711891 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N711892 | Holden Australia |
| 5430940 | Harness Replacement | N711895 | Holden Australia |
| 5430940 | Harness Replacement | N711896 | Holden Australia |
| 5430940 | Harness Replacement | N711990 | Holden Australia |
| 5430940 | Harness Replacement | N711991 | Holden Australia |
| 5430940 | Harness Replacement | N711992 | Holden Australia |
| 5430940 | Harness Replacement | N711993 | Holden Australia |
| 5430940 | Harness Replacement | N711994 | Holden Australia |
| 5430940 | Harness Replacement | N711995 | Holden Australia |
| 5430940 | Harness Replacement | N712188 | Holden Australia |
| 5430940 | Harness Replacement | N712189 | Holden Australia |
| 5430940 | Harness Replacement | N712190 | Holden Australia |
| 5430940 | Harness Replacement | N712191 | Holden Australia |
| 5430940 | Harness Replacement | N712192 | Holden Australia |
| 5430940 | Harness Replacement | N712290 | Holden Australia |
| 5430940 | Harness Replacement | N712291 | Holden Australia |
| 5430940 | Harness Replacement | N712292 | Holden Australia |
| 5430940 | Harness Replacement | N712293 | Holden Australia |
| 5430940 | Harness Replacement | N712294 | Holden Australia |
| 5430940 | Harness Replacement | N712295 | Holden Australia |
| 5430940 | Harness Replacement | N712296 | Holden Australia |
| 5430940 | Harness Replacement | N712390 | Holden Australia |
| 5430940 | Harness Replacement | N712391 | Holden Australia |
| 5430940 | Harness Replacement | N712392 | Holden Australia |
| 5430940 | Harness Replacement | N712393 | Holden Australia |
| 5430940 | Harness Replacement | N712394 | Holden Australia |
| 5430940 | Harness Replacement | N712395 | Holden Australia |
| 5430940 | Harness Replacement | N712492 | Holden Australia |
| 5430940 | Harness Replacement | N712495 | Holden Australia |
| 5430940 | Harness Replacement | N712496 | Holden Australia |
| 5430940 | Harness Replacement | N712589 | Holden Australia |
| 5430940 | Harness Replacement | N712590 | Holden Australia |
| 5430940 | Harness Replacement | N712591 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N712592 | Holden Australia |
| 5430940 | Harness Replacement | N712593 | Holden Australia |
| 5430940 | Harness Replacement | N712594 | Holden Australia |
| 5430940 | Harness Replacement | N712595 | Holden Australia |
| 5430940 | Harness Replacement | N712596 | Holden Australia |
| 5430940 | Harness Replacement | N712685 | Holden Australia |
| 5430940 | Harness Replacement | N712686 | Holden Australia |
| 5430940 | Harness Replacement | N712687 | Holden Australia |
| 5430940 | Harness Replacement | N712690 | Holden Australia |
| 5430940 | Harness Replacement | N712785 | Holden Australia |
| 5430940 | Harness Replacement | N712786 | Holden Australia |
| 5430940 | Harness Replacement | N712787 | Holden Australia |
| 5430940 | Harness Replacement | N712790 | Holden Australia |
| 5430940 | Harness Replacement | N712791 | Holden Australia |
| 5430940 | Harness Replacement | N712792 | Holden Australia |
| 5430940 | Harness Replacement | N712795 | Holden Australia |
| 5430940 | Harness Replacement | N712796 | Holden Australia |
| 5430940 | Harness Replacement | N712893 | Holden Australia |
| 5430940 | Harness Replacement | N712894 | Holden Australia |
| 5430940 | Harness Replacement | N712895 | Holden Australia |
| 5430940 | Harness Replacement | N712896 | Holden Australia |
| 5430940 | Harness Replacement | N712897 | Holden Australia |
| 5430940 | Harness Replacement | N712987 | Holden Australia |
| 5430940 | Harness Replacement | N712988 | Holden Australia |
| 5430940 | Harness Replacement | N712989 | Holden Australia |
| 5430940 | Harness Replacement | N712990 | Holden Australia |
| 5430940 | Harness Replacement | N712991 | Holden Australia |
| 5430940 | Harness Replacement | N712994 | Holden Australia |
| 5430940 | Harness Replacement | N712995 | Holden Australia |
| 5430940 | Harness Replacement | N712996 | Holden Australia |
| 5430940 | Harness Replacement | N713085 | Holden Australia |
| 5430940 | Harness Replacement | N713091 | Holden Australia |
| 5430940 | Harness Replacement | N713092 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N713093 | Holden Australia |
| 5430940 | Harness Replacement | N713094 | Holden Australia |
| 5430940 | Harness Replacement | N713095 | Holden Australia |
| 5430940 | Harness Replacement | N713096 | Holden Australia |
| 5430940 | Harness Replacement | N713097 | Holden Australia |
| 5430940 | Harness Replacement | N713185 | Holden Australia |
| 5430940 | Harness Replacement | N713186 | Holden Australia |
| 5430940 | Harness Replacement | N713187 | Holden Australia |
| 5430940 | Harness Replacement | N713188 | Holden Australia |
| 5430940 | Harness Replacement | N713189 | Holden Australia |
| 5430940 | Harness Replacement | N713190 | Holden Australia |
| 5430940 | Harness Replacement | N713191 | Holden Australia |
| 5430940 | Harness Replacement | N713195 | Holden Australia |
| 5430940 | Harness Replacement | N713196 | Holden Australia |
| 5430940 | Harness Replacement | N713284 | Holden Australia |
| 5430940 | Harness Replacement | N713285 | Holden Australia |
| 5430940 | Harness Replacement | N713286 | Holden Australia |
| 5430940 | Harness Replacement | N713287 | Holden Australia |
| 5430940 | Harness Replacement | N713288 | Holden Australia |
| 5430940 | Harness Replacement | N713289 | Holden Australia |
| 5430940 | Harness Replacement | N713290 | Holden Australia |
| 5430940 | Harness Replacement | N713296 | Holden Australia |
| 5430940 | Harness Replacement | N713389 | Holden Australia |
| 5430940 | Harness Replacement | N713391 | Holden Australia |
| 5430940 | Harness Replacement | N713392 | Holden Australia |
| 5430940 | Harness Replacement | N713393 | Holden Australia |
| 5430940 | Harness Replacement | N713394 | Holden Australia |
| 5430940 | Harness Replacement | N713485 | Holden Australia |
| 5430940 | Harness Replacement | N713486 | Holden Australia |
| 5430940 | Harness Replacement | N713487 | Holden Australia |
| 5430940 | Harness Replacement | N713488 | Holden Australia |
| 5430940 | Harness Replacement | N713490 | Holden Australia |
| 5430940 | Harness Replacement | N713491 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N713494 | Holden Australia |
| 5430940 | Harness Replacement | N713495 | Holden Australia |
| 5430940 | Harness Replacement | N713496 | Holden Australia |
| 5430940 | Harness Replacement | N713589 | Holden Australia |
| 5430940 | Harness Replacement | N713590 | Holden Australia |
| 5430940 | Harness Replacement | N713591 | Holden Australia |
| 5430940 | Harness Replacement | N713596 | Holden Australia |
| 5430940 | Harness Replacement | N713597 | Holden Australia |
| 5430940 | Harness Replacement | N713684 | Holden Australia |
| 5430940 | Harness Replacement | N713685 | Holden Australia |
| 5430940 | Harness Replacement | N713686 | Holden Australia |
| 5430940 | Harness Replacement | N713687 | Holden Australia |
| 5430940 | Harness Replacement | N713688 | Holden Australia |
| 5430940 | Harness Replacement | N713689 | Holden Australia |
| 5430940 | Harness Replacement | N713690 | Holden Australia |
| 5430940 | Harness Replacement | N713691 | Holden Australia |
| 5430940 | Harness Replacement | N713693 | Holden Australia |
| 5430940 | Harness Replacement | N713695 | Holden Australia |
| 5430940 | Harness Replacement | N713696 | Holden Australia |
| 5430940 | Harness Replacement | N713697 | Holden Australia |
| 5430940 | Harness Replacement | N713784 | Holden Australia |
| 5430940 | Harness Replacement | N713785 | Holden Australia |
| 5430940 | Harness Replacement | N713786 | Holden Australia |
| 5430940 | Harness Replacement | N713788 | Holden Australia |
| 5430940 | Harness Replacement | N713792 | Holden Australia |
| 5430940 | Harness Replacement | N713794 | Holden Australia |
| 5430940 | Harness Replacement | N713796 | Holden Australia |
| 5430940 | Harness Replacement | N713797 | Holden Australia |
| 5430940 | Harness Replacement | N713798 | Holden Australia |
| 5430940 | Harness Replacement | N713887 | Holden Australia |
| 5430940 | Harness Replacement | N713888 | Holden Australia |
| 5430940 | Harness Replacement | N713893 | Holden Australia |
| 5430940 | Harness Replacement | N713895 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N713985 | Holden Australia |
| 5430940 | Harness Replacement | N713986 | Holden Australia |
| 5430940 | Harness Replacement | N713987 | Holden Australia |
| 5430940 | Harness Replacement | N713988 | Holden Australia |
| 5430940 | Harness Replacement | N713989 | Holden Australia |
| 5430940 | Harness Replacement | N713994 | Holden Australia |
| 5430940 | Harness Replacement | N713995 | Holden Australia |
| 5430940 | Harness Replacement | N713996 | Holden Australia |
| 5430940 | Harness Replacement | N713997 | Holden Australia |
| 5430940 | Harness Replacement | N713998 | Holden Australia |
| 5430940 | Harness Replacement | N714086 | Holden Australia |
| 5430940 | Harness Replacement | N714087 | Holden Australia |
| 5430940 | Harness Replacement | N714088 | Holden Australia |
| 5430940 | Harness Replacement | N714089 | Holden Australia |
| 5430940 | Harness Replacement | N714090 | Holden Australia |
| 5430940 | Harness Replacement | N714093 | Holden Australia |
| 5430940 | Harness Replacement | N714094 | Holden Australia |
| 5430940 | Harness Replacement | N714186 | Holden Australia |
| 5430940 | Harness Replacement | N714187 | Holden Australia |
| 5430940 | Harness Replacement | N714188 | Holden Australia |
| 5430940 | Harness Replacement | N714191 | Holden Australia |
| 5430940 | Harness Replacement | N714192 | Holden Australia |
| 5430940 | Harness Replacement | N714194 | Holden Australia |
| 5430940 | Harness Replacement | N714195 | Holden Australia |
| 5430940 | Harness Replacement | N714196 | Holden Australia |
| 5430940 | Harness Replacement | N714197 | Holden Australia |
| 5430940 | Harness Replacement | N714286 | Holden Australia |
| 5430940 | Harness Replacement | N714287 | Holden Australia |
| 5430940 | Harness Replacement | N714293 | Holden Australia |
| 5430940 | Harness Replacement | N714385 | Holden Australia |
| 5430940 | Harness Replacement | N714386 | Holden Australia |
| 5430940 | Harness Replacement | N714387 | Holden Australia |
| 5430940 | Harness Replacement | N714388 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N714389 | Holden Australia |
| 5430940 | Harness Replacement | N714390 | Holden Australia |
| 5430940 | Harness Replacement | N714393 | Holden Australia |
| 5430940 | Harness Replacement | N714394 | Holden Australia |
| 5430940 | Harness Replacement | N714397 | Holden Australia |
| 5430940 | Harness Replacement | N714486 | Holden Australia |
| 5430940 | Harness Replacement | N714494 | Holden Australia |
| 5430940 | Harness Replacement | N714496 | Holden Australia |
| 5430940 | Harness Replacement | N714586 | Holden Australia |
| 5430940 | Harness Replacement | N714596 | Holden Australia |
| 5430940 | Harness Replacement | N714685 | Holden Australia |
| 5430940 | Harness Replacement | N714686 | Holden Australia |
| 5430940 | Harness Replacement | N714687 | Holden Australia |
| 5430940 | Harness Replacement | N714691 | Holden Australia |
| 5430940 | Harness Replacement | N714696 | Holden Australia |
| 5430940 | Harness Replacement | N714697 | Holden Australia |
| 5430940 | Harness Replacement | N714784 | Holden Australia |
| 5430940 | Harness Replacement | N714785 | Holden Australia |
| 5430940 | Harness Replacement | N714786 | Holden Australia |
| 5430940 | Harness Replacement | N714787 | Holden Australia |
| 5430940 | Harness Replacement | N714788 | Holden Australia |
| 5430940 | Harness Replacement | N714791 | Holden Australia |
| 5430940 | Harness Replacement | N714792 | Holden Australia |
| 5430940 | Harness Replacement | N714793 | Holden Australia |
| 5430940 | Harness Replacement | N714794 | Holden Australia |
| 5430940 | Harness Replacement | N714795 | Holden Australia |
| 5430940 | Harness Replacement | N714796 | Holden Australia |
| 5430940 | Harness Replacement | N714797 | Holden Australia |
| 5430940 | Harness Replacement | N714886 | Holden Australia |
| 5430940 | Harness Replacement | N714887 | Holden Australia |
| 5430940 | Harness Replacement | N714888 | Holden Australia |
| 5430940 | Harness Replacement | N714889 | Holden Australia |
| 5430940 | Harness Replacement | N714890 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N714894 | Holden Australia |
| 5430940 | Harness Replacement | N714895 | Holden Australia |
| 5430940 | Harness Replacement | N714996 | Holden Australia |
| 5430940 | Harness Replacement | N714997 | Holden Australia |
| 5430940 | Harness Replacement | N715084 | Holden Australia |
| 5430940 | Harness Replacement | N715085 | Holden Australia |
| 5430940 | Harness Replacement | N715086 | Holden Australia |
| 5430940 | Harness Replacement | N715087 | Holden Australia |
| 5430940 | Harness Replacement | N715090 | Holden Australia |
| 5430940 | Harness Replacement | N715091 | Holden Australia |
| 5430940 | Harness Replacement | N715092 | Holden Australia |
| 5430940 | Harness Replacement | N715093 | Holden Australia |
| 5430940 | Harness Replacement | N715095 | Holden Australia |
| 5430940 | Harness Replacement | N715096 | Holden Australia |
| 5430940 | Harness Replacement | N715097 | Holden Australia |
| 5430940 | Harness Replacement | N715185 | Holden Australia |
| 5430940 | Harness Replacement | N715187 | Holden Australia |
| 5430940 | Harness Replacement | N715190 | Holden Australia |
| 5430940 | Harness Replacement | N715191 | Holden Australia |
| 5430940 | Harness Replacement | N715192 | Holden Australia |
| 5430940 | Harness Replacement | N715193 | Holden Australia |
| 5430940 | Harness Replacement | N715286 | Holden Australia |
| 5430940 | Harness Replacement | N715287 | Holden Australia |
| 5430940 | Harness Replacement | N715288 | Holden Australia |
| 5430940 | Harness Replacement | N715292 | Holden Australia |
| 5430940 | Harness Replacement | N715293 | Holden Australia |
| 5430940 | Harness Replacement | N715294 | Holden Australia |
| 5430940 | Harness Replacement | N715390 | Holden Australia |
| 5430940 | Harness Replacement | N715391 | Holden Australia |
| 5430940 | Harness Replacement | N715392 | Holden Australia |
| 5430940 | Harness Replacement | N715393 | Holden Australia |
| 5430940 | Harness Replacement | N715394 | Holden Australia |
| 5430940 | Harness Replacement | N715395 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N715396 | Holden Australia |
| 5430940 | Harness Replacement | N715397 | Holden Australia |
| 5430940 | Harness Replacement | N715398 | Holden Australia |
| 5430940 | Harness Replacement | N715486 | Holden Australia |
| 5430940 | Harness Replacement | N715487 | Holden Australia |
| 5430940 | Harness Replacement | N715488 | Holden Australia |
| 5430940 | Harness Replacement | N715491 | Holden Australia |
| 5430940 | Harness Replacement | N715495 | Holden Australia |
| 5430940 | Harness Replacement | N715496 | Holden Australia |
| 5430940 | Harness Replacement | N715589 | Holden Australia |
| 5430940 | Harness Replacement | N715590 | Holden Australia |
| 5430940 | Harness Replacement | N715592 | Holden Australia |
| 5430940 | Harness Replacement | N715595 | Holden Australia |
| 5430940 | Harness Replacement | N715596 | Holden Australia |
| 5430940 | Harness Replacement | N715688 | Holden Australia |
| 5430940 | Harness Replacement | N715689 | Holden Australia |
| 5430940 | Harness Replacement | N715690 | Holden Australia |
| 5430940 | Harness Replacement | N715692 | Holden Australia |
| 5430940 | Harness Replacement | N715693 | Holden Australia |
| 5430940 | Harness Replacement | N715784 | Holden Australia |
| 5430940 | Harness Replacement | N715785 | Holden Australia |
| 5430940 | Harness Replacement | N715786 | Holden Australia |
| 5430940 | Harness Replacement | N715791 | Holden Australia |
| 5430940 | Harness Replacement | N715792 | Holden Australia |
| 5430940 | Harness Replacement | N715797 | Holden Australia |
| 5430940 | Harness Replacement | N715887 | Holden Australia |
| 5430940 | Harness Replacement | N715888 | Holden Australia |
| 5430940 | Harness Replacement | N715894 | Holden Australia |
| 5430940 | Harness Replacement | N715993 | Holden Australia |
| 5430940 | Harness Replacement | N715994 | Holden Australia |
| 5430940 | Harness Replacement | N716086 | Holden Australia |
| 5430940 | Harness Replacement | N716089 | Holden Australia |
| 5430940 | Harness Replacement | N716092 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N716094 | Holden Australia |
| 5430940 | Harness Replacement | N716185 | Holden Australia |
| 5430940 | Harness Replacement | N716186 | Holden Australia |
| 5430940 | Harness Replacement | N716187 | Holden Australia |
| 5430940 | Harness Replacement | N716191 | Holden Australia |
| 5430940 | Harness Replacement | N716192 | Holden Australia |
| 5430940 | Harness Replacement | N716497 | Holden Australia |
| 5430940 | Harness Replacement | N716585 | Holden Australia |
| 5430940 | Harness Replacement | N716586 | Holden Australia |
| 5430940 | Harness Replacement | N716588 | Holden Australia |
| 5430940 | Harness Replacement | N716589 | Holden Australia |
| 5430940 | Harness Replacement | N716590 | Holden Australia |
| 5430940 | Harness Replacement | N716591 | Holden Australia |
| 5430940 | Harness Replacement | N716592 | Holden Australia |
| 5430940 | Harness Replacement | N716594 | Holden Australia |
| 5430940 | Harness Replacement | N716596 | Holden Australia |
| 5430940 | Harness Replacement | N716597 | Holden Australia |
| 5430940 | Harness Replacement | N716598 | Holden Australia |
| 5430940 | Harness Replacement | N716694 | Holden Australia |
| 5430940 | Harness Replacement | N716695 | Holden Australia |
| 5430940 | Harness Replacement | N716891 | Holden Australia |
| 5430940 | Harness Replacement | N716892 | Holden Australia |
| 5430940 | Harness Replacement | N716895 | Holden Australia |
| 5430940 | Harness Replacement | N716896 | Holden Australia |
| 5430940 | Harness Replacement | N716996 | Holden Australia |
| 5430940 | Harness Replacement | N717085 | Holden Australia |
| 5430940 | Harness Replacement | N717086 | Holden Australia |
| 5430940 | Harness Replacement | N717087 | Holden Australia |
| 5430940 | Harness Replacement | N717089 | Holden Australia |
| 5430940 | Harness Replacement | N717090 | Holden Australia |
| 5430940 | Harness Replacement | N717091 | Holden Australia |
| 5430940 | Harness Replacement | N717096 | Holden Australia |
| 5430940 | Harness Replacement | N717184 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N717185 | Holden Australia |
| 5430940 | Harness Replacement | N717186 | Holden Australia |
| 5430940 | Harness Replacement | N717187 | Holden Australia |
| 5430940 | Harness Replacement | N717190 | Holden Australia |
| 5430940 | Harness Replacement | N717192 | Holden Australia |
| 5430940 | Harness Replacement | N717285 | Holden Australia |
| 5430940 | Harness Replacement | N717286 | Holden Australia |
| 5430940 | Harness Replacement | N717290 | Holden Australia |
| 5430940 | Harness Replacement | N717291 | Holden Australia |
| 5430940 | Harness Replacement | N717293 | Holden Australia |
| 5430940 | Harness Replacement | N717294 | Holden Australia |
| 5430940 | Harness Replacement | N717295 | Holden Australia |
| 5430940 | Harness Replacement | N717388 | Holden Australia |
| 5430940 | Harness Replacement | N717491 | Holden Australia |
| 5430940 | Harness Replacement | N717587 | Holden Australia |
| 5430940 | Harness Replacement | N717588 | Holden Australia |
| 5430940 | Harness Replacement | N717592 | Holden Australia |
| 5430940 | Harness Replacement | N717688 | Holden Australia |
| 5430940 | Harness Replacement | N717691 | Holden Australia |
| 5430940 | Harness Replacement | N717704 | Holden Australia |
| 5430940 | Harness Replacement | N717785 | Holden Australia |
| 5430940 | Harness Replacement | N717786 | Holden Australia |
| 5430940 | Harness Replacement | N717792 | Holden Australia |
| 5430940 | Harness Replacement | N717797 | Holden Australia |
| 5430940 | Harness Replacement | N717988 | Holden Australia |
| 5430940 | Harness Replacement | N717991 | Holden Australia |
| 5430940 | Harness Replacement | N717992 | Holden Australia |
| 5430940 | Harness Replacement | N717993 | Holden Australia |
| 5430940 | Harness Replacement | N718192 | Holden Australia |
| 5430940 | Harness Replacement | N718194 | Holden Australia |
| 5430940 | Harness Replacement | N718290 | Holden Australia |
| 5430940 | Harness Replacement | N718291 | Holden Australia |
| 5430940 | Harness Replacement | N718294 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N718295 | Holden Australia |
| 5430940 | Harness Replacement | N718395 | Holden Australia |
| 5430940 | Harness Replacement | N718396 | Holden Australia |
| 5430940 | Harness Replacement | N718490 | Holden Australia |
| 5430940 | Harness Replacement | N718590 | Holden Australia |
| 5430940 | Harness Replacement | N718591 | Holden Australia |
| 5430940 | Harness Replacement | N718594 | Holden Australia |
| 5430940 | Harness Replacement | N718596 | Holden Australia |
| 5430940 | Harness Replacement | N718785 | Holden Australia |
| 5430940 | Harness Replacement | N718790 | Holden Australia |
| 5430940 | Harness Replacement | N718791 | Holden Australia |
| 5430940 | Harness Replacement | N718793 | Holden Australia |
| 5430940 | Harness Replacement | N718795 | Holden Australia |
| 5430940 | Harness Replacement | N718797 | Holden Australia |
| 5430940 | Harness Replacement | N718992 | Holden Australia |
| 5430940 | Harness Replacement | N719095 | Holden Australia |
| 5430940 | Harness Replacement | N719186 | Holden Australia |
| 5430940 | Harness Replacement | N719187 | Holden Australia |
| 5430940 | Harness Replacement | N719191 | Holden Australia |
| 5430940 | Harness Replacement | N719197 | Holden Australia |
| 5430940 | Harness Replacement | N719285 | Holden Australia |
| 5430940 | Harness Replacement | N719286 | Holden Australia |
| 5430940 | Harness Replacement | N719290 | Holden Australia |
| 5430940 | Harness Replacement | N719295 | Holden Australia |
| 5430940 | Harness Replacement | N719385 | Holden Australia |
| 5430940 | Harness Replacement | N719386 | Holden Australia |
| 5430940 | Harness Replacement | N719388 | Holden Australia |
| 5430940 | Harness Replacement | N719391 | Holden Australia |
| 5430940 | Harness Replacement | N719396 | Holden Australia |
| 5430940 | Harness Replacement | N719487 | Holden Australia |
| 5430940 | Harness Replacement | N719491 | Holden Australia |
| 5430940 | Harness Replacement | N719492 | Holden Australia |
| 5430940 | Harness Replacement | N719496 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N720500 | Holden Australia |
| 5430940 | Harness Replacement | N730388 | Holden Australia |
| 5430940 | Harness Replacement | N730389 | Holden Australia |
| 5430940 | Harness Replacement | N730490 | Holden Australia |
| 5430940 | Harness Replacement | N730696 | Holden Australia |
| 5430940 | Harness Replacement | N730789 | Holden Australia |
| 5430940 | Harness Replacement | N730791 | Holden Australia |
| 5430940 | Harness Replacement | N730796 | Holden Australia |
| 5430940 | Harness Replacement | N730897 | Holden Australia |
| 5430940 | Harness Replacement | N730986 | Holden Australia |
| 5430940 | Harness Replacement | N731095 | Holden Australia |
| 5430940 | Harness Replacement | N731286 | Holden Australia |
| 5430940 | Harness Replacement | N731291 | Holden Australia |
| 5430940 | Harness Replacement | N731292 | Holden Australia |
| 5430940 | Harness Replacement | N731386 | Holden Australia |
| 5430940 | Harness Replacement | N731392 | Holden Australia |
| 5430940 | Harness Replacement | N731485 | Holden Australia |
| 5430940 | Harness Replacement | N731587 | Holden Australia |
| 5430940 | Harness Replacement | N731686 | Holden Australia |
| 5430940 | Harness Replacement | N731688 | Holden Australia |
| 5430940 | Harness Replacement | N731694 | Holden Australia |
| 5430940 | Harness Replacement | N731696 | Holden Australia |
| 5430940 | Harness Replacement | N731790 | Holden Australia |
| 5430940 | Harness Replacement | N731791 | Holden Australia |
| 5430940 | Harness Replacement | N731792 | Holden Australia |
| 5430940 | Harness Replacement | N731794 | Holden Australia |
| 5430940 | Harness Replacement | N732090 | Holden Australia |
| 5430940 | Harness Replacement | N732094 | Holden Australia |
| 5430940 | Harness Replacement | N732095 | Holden Australia |
| 5430940 | Harness Replacement | N732096 | Holden Australia |
| 5430940 | Harness Replacement | N732190 | Holden Australia |
| 5430940 | Harness Replacement | N732191 | Holden Australia |
| 5430940 | Harness Replacement | N732192 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N732193 | Holden Australia |
| 5430940 | Harness Replacement | N732194 | Holden Australia |
| 5430940 | Harness Replacement | N732195 | Holden Australia |
| 5430940 | Harness Replacement | N732389 | Holden Australia |
| 5430940 | Harness Replacement | N732390 | Holden Australia |
| 5430940 | Harness Replacement | N732391 | Holden Australia |
| 5430940 | Harness Replacement | N732395 | Holden Australia |
| 5430940 | Harness Replacement | N732396 | Holden Australia |
| 5430940 | Harness Replacement | N732491 | Holden Australia |
| 5430940 | Harness Replacement | N732494 | Holden Australia |
| 5430940 | Harness Replacement | N732497 | Holden Australia |
| 5430940 | Harness Replacement | N732591 | Holden Australia |
| 5430940 | Harness Replacement | N732594 | Holden Australia |
| 5430940 | Harness Replacement | N732595 | Holden Australia |
| 5430940 | Harness Replacement | N732684 | Holden Australia |
| 5430940 | Harness Replacement | N732693 | Holden Australia |
| 5430940 | Harness Replacement | N732695 | Holden Australia |
| 5430940 | Harness Replacement | N732696 | Holden Australia |
| 5430940 | Harness Replacement | N732697 | Holden Australia |
| 5430940 | Harness Replacement | N732786 | Holden Australia |
| 5430940 | Harness Replacement | N732787 | Holden Australia |
| 5430940 | Harness Replacement | N732788 | Holden Australia |
| 5430940 | Harness Replacement | N732789 | Holden Australia |
| 5430940 | Harness Replacement | N732790 | Holden Australia |
| 5430940 | Harness Replacement | N732791 | Holden Australia |
| 5430940 | Harness Replacement | N732795 | Holden Australia |
| 5430940 | Harness Replacement | N732796 | Holden Australia |
| 5430940 | Harness Replacement | N732885 | Holden Australia |
| 5430940 | Harness Replacement | N732889 | Holden Australia |
| 5430940 | Harness Replacement | N732894 | Holden Australia |
| 5430940 | Harness Replacement | N732896 | Holden Australia |
| 5430940 | Harness Replacement | N732984 | Holden Australia |
| 5430940 | Harness Replacement | N732991 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N732995 | Holden Australia |
| 5430940 | Harness Replacement | N733087 | Holden Australia |
| 5430940 | Harness Replacement | N733186 | Holden Australia |
| 5430940 | Harness Replacement | N733192 | Holden Australia |
| 5430940 | Harness Replacement | N733286 | Holden Australia |
| 5430940 | Harness Replacement | N733287 | Holden Australia |
| 5430940 | Harness Replacement | N733296 | Holden Australia |
| 5430940 | Harness Replacement | N733390 | Holden Australia |
| 5430940 | Harness Replacement | N733391 | Holden Australia |
| 5430940 | Harness Replacement | N733392 | Holden Australia |
| 5430940 | Harness Replacement | N733396 | Holden Australia |
| 5430940 | Harness Replacement | N733397 | Holden Australia |
| 5430940 | Harness Replacement | N733492 | Holden Australia |
| 5430940 | Harness Replacement | N733494 | Holden Australia |
| 5430940 | Harness Replacement | N733584 | Holden Australia |
| 5430940 | Harness Replacement | N733585 | Holden Australia |
| 5430940 | Harness Replacement | N733586 | Holden Australia |
| 5430940 | Harness Replacement | N733588 | Holden Australia |
| 5430940 | Harness Replacement | N733593 | Holden Australia |
| 5430940 | Harness Replacement | N733787 | Holden Australia |
| 5430940 | Harness Replacement | N733789 | Holden Australia |
| 5430940 | Harness Replacement | N733790 | Holden Australia |
| 5430940 | Harness Replacement | N733795 | Holden Australia |
| 5430940 | Harness Replacement | N733796 | Holden Australia |
| 5430940 | Harness Replacement | N733885 | Holden Australia |
| 5430940 | Harness Replacement | N733886 | Holden Australia |
| 5430940 | Harness Replacement | N733890 | Holden Australia |
| 5430940 | Harness Replacement | N733986 | Holden Australia |
| 5430940 | Harness Replacement | N733995 | Holden Australia |
| 5430940 | Harness Replacement | N734087 | Holden Australia |
| 5430940 | Harness Replacement | N734090 | Holden Australia |
| 5430940 | Harness Replacement | N734091 | Holden Australia |
| 5430940 | Harness Replacement | N734193 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N734194 | Holden Australia |
| 5430940 | Harness Replacement | N734195 | Holden Australia |
| 5430940 | Harness Replacement | N734196 | Holden Australia |
| 5430940 | Harness Replacement | N734197 | Holden Australia |
| 5430940 | Harness Replacement | N734198 | Holden Australia |
| 5430940 | Harness Replacement | N734286 | Holden Australia |
| 5430940 | Harness Replacement | N734290 | Holden Australia |
| 5430940 | Harness Replacement | N734291 | Holden Australia |
| 5430940 | Harness Replacement | N734296 | Holden Australia |
| 5430940 | Harness Replacement | N734297 | Holden Australia |
| 5430940 | Harness Replacement | N734390 | Holden Australia |
| 5430940 | Harness Replacement | N734391 | Holden Australia |
| 5430940 | Harness Replacement | N734485 | Holden Australia |
| 5430940 | Harness Replacement | N734486 | Holden Australia |
| 5430940 | Harness Replacement | N734493 | Holden Australia |
| 5430940 | Harness Replacement | N734496 | Holden Australia |
| 5430940 | Harness Replacement | N734585 | Holden Australia |
| 5430940 | Harness Replacement | N734589 | Holden Australia |
| 5430940 | Harness Replacement | N734592 | Holden Australia |
| 5430940 | Harness Replacement | N734596 | Holden Australia |
| 5430940 | Harness Replacement | N734597 | Holden Australia |
| 5430940 | Harness Replacement | N734695 | Holden Australia |
| 5430940 | Harness Replacement | N734696 | Holden Australia |
| 5430940 | Harness Replacement | N734789 | Holden Australia |
| 5430940 | Harness Replacement | N734790 | Holden Australia |
| 5430940 | Harness Replacement | N734795 | Holden Australia |
| 5430940 | Harness Replacement | N734796 | Holden Australia |
| 5430940 | Harness Replacement | N734894 | Holden Australia |
| 5430940 | Harness Replacement | N734985 | Holden Australia |
| 5430940 | Harness Replacement | N734990 | Holden Australia |
| 5430940 | Harness Replacement | N734991 | Holden Australia |
| 5430940 | Harness Replacement | N735085 | Holden Australia |
| 5430940 | Harness Replacement | N735194 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N735289 | Holden Australia |
| 5430940 | Harness Replacement | N735290 | Holden Australia |
| 5430940 | Harness Replacement | N735291 | Holden Australia |
| 5430940 | Harness Replacement | N735294 | Holden Australia |
| 5430940 | Harness Replacement | N735385 | Holden Australia |
| 5430940 | Harness Replacement | N735387 | Holden Australia |
| 5430940 | Harness Replacement | N735389 | Holden Australia |
| 5430940 | Harness Replacement | N735390 | Holden Australia |
| 5430940 | Harness Replacement | N735391 | Holden Australia |
| 5430940 | Harness Replacement | N735392 | Holden Australia |
| 5430940 | Harness Replacement | N735394 | Holden Australia |
| 5430940 | Harness Replacement | N735395 | Holden Australia |
| 5430940 | Harness Replacement | N735396 | Holden Australia |
| 5430940 | Harness Replacement | N735397 | Holden Australia |
| 5430940 | Harness Replacement | N735487 | Holden Australia |
| 5430940 | Harness Replacement | N735496 | Holden Australia |
| 5430940 | Harness Replacement | N735686 | Holden Australia |
| 5430940 | Harness Replacement | N735696 | Holden Australia |
| 5430940 | Harness Replacement | N735794 | Holden Australia |
| 5430940 | Harness Replacement | N760510 | Holden Australia |
| 5430940 | Harness Replacement | N760520 | Holden Australia |
| 5430940 | Harness Replacement | N760530 | Holden Australia |
| 5430940 | Harness Replacement | N780110 | Holden Australia |
| 5430940 | Harness Replacement | N780500 | Holden Australia |
| 5430940 | Harness Replacement | N911390 | Holden Australia |
| 5430940 | Harness Replacement | N911391 | Holden Australia |
| 5430940 | Harness Replacement | N911392 | Holden Australia |
| 5430940 | Harness Replacement | N911393 | Holden Australia |
| 5430940 | Harness Replacement | N911394 | Holden Australia |
| 5430940 | Harness Replacement | N911395 | Holden Australia |
| 5430940 | Harness Replacement | N911690 | Holden Australia |
| 5430940 | Harness Replacement | N911691 | Holden Australia |
| 5430940 | Harness Replacement | N911692 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N911693 | Holden Australia |
| 5430940 | Harness Replacement | N911694 | Holden Australia |
| 5430940 | Harness Replacement | N911695 | Holden Australia |
| 5430940 | Harness Replacement | N911696 | Holden Australia |
| 5430940 | Harness Replacement | N911697 | Holden Australia |
| 5430940 | Harness Replacement | N911790 | Holden Australia |
| 5430940 | Harness Replacement | N911791 | Holden Australia |
| 5430940 | Harness Replacement | N911792 | Holden Australia |
| 5430940 | Harness Replacement | N911793 | Holden Australia |
| 5430940 | Harness Replacement | N911794 | Holden Australia |
| 5430940 | Harness Replacement | N911795 | Holden Australia |
| 5430940 | Harness Replacement | N911796 | Holden Australia |
| 5430940 | Harness Replacement | N911890 | Holden Australia |
| 5430940 | Harness Replacement | N911891 | Holden Australia |
| 5430940 | Harness Replacement | N911892 | Holden Australia |
| 5430940 | Harness Replacement | N911893 | Holden Australia |
| 5430940 | Harness Replacement | N911894 | Holden Australia |
| 5430940 | Harness Replacement | N911895 | Holden Australia |
| 5430940 | Harness Replacement | N911896 | Holden Australia |
| 5430940 | Harness Replacement | N911897 | Holden Australia |
| 5430940 | Harness Replacement | N911989 | Holden Australia |
| 5430940 | Harness Replacement | N911990 | Holden Australia |
| 5430940 | Harness Replacement | N911991 | Holden Australia |
| 5430940 | Harness Replacement | N911992 | Holden Australia |
| 5430940 | Harness Replacement | N911993 | Holden Australia |
| 5430940 | Harness Replacement | N911994 | Holden Australia |
| 5430940 | Harness Replacement | N911995 | Holden Australia |
| 5430940 | Harness Replacement | N912084 | Holden Australia |
| 5430940 | Harness Replacement | N912085 | Holden Australia |
| 5430940 | Harness Replacement | N912086 | Holden Australia |
| 5430940 | Harness Replacement | N912087 | Holden Australia |
| 5430940 | Harness Replacement | N912090 | Holden Australia |
| 5430940 | Harness Replacement | N912091 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N912185 | Holden Australia |
| 5430940 | Harness Replacement | N912186 | Holden Australia |
| 5430940 | Harness Replacement | N912187 | Holden Australia |
| 5430940 | Harness Replacement | N912190 | Holden Australia |
| 5430940 | Harness Replacement | N912191 | Holden Australia |
| 5430940 | Harness Replacement | N912192 | Holden Australia |
| 5430940 | Harness Replacement | N912195 | Holden Australia |
| 5430940 | Harness Replacement | N912196 | Holden Australia |
| 5430940 | Harness Replacement | N912197 | Holden Australia |
| 5430940 | Harness Replacement | N912285 | Holden Australia |
| 5430940 | Harness Replacement | N912286 | Holden Australia |
| 5430940 | Harness Replacement | N912288 | Holden Australia |
| 5430940 | Harness Replacement | N912289 | Holden Australia |
| 5430940 | Harness Replacement | N912291 | Holden Australia |
| 5430940 | Harness Replacement | N912293 | Holden Australia |
| 5430940 | Harness Replacement | N912294 | Holden Australia |
| 5430940 | Harness Replacement | N912295 | Holden Australia |
| 5430940 | Harness Replacement | N912296 | Holden Australia |
| 5430940 | Harness Replacement | N912386 | Holden Australia |
| 5430940 | Harness Replacement | N912387 | Holden Australia |
| 5430940 | Harness Replacement | N912388 | Holden Australia |
| 5430940 | Harness Replacement | N912389 | Holden Australia |
| 5430940 | Harness Replacement | N912390 | Holden Australia |
| 5430940 | Harness Replacement | N912394 | Holden Australia |
| 5430940 | Harness Replacement | N912395 | Holden Australia |
| 5430940 | Harness Replacement | N912396 | Holden Australia |
| 5430940 | Harness Replacement | N912397 | Holden Australia |
| 5430940 | Harness Replacement | N912485 | Holden Australia |
| 5430940 | Harness Replacement | N912486 | Holden Australia |
| 5430940 | Harness Replacement | N912491 | Holden Australia |
| 5430940 | Harness Replacement | N912492 | Holden Australia |
| 5430940 | Harness Replacement | N912493 | Holden Australia |
| 5430940 | Harness Replacement | N912494 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N912495 | Holden Australia |
| 5430940 | Harness Replacement | N912496 | Holden Australia |
| 5430940 | Harness Replacement | N912497 | Holden Australia |
| 5430940 | Harness Replacement | N913486 | Holden Australia |
| 5430940 | Harness Replacement | N913487 | Holden Australia |
| 5430940 | Harness Replacement | N913488 | Holden Australia |
| 5430940 | Harness Replacement | N913490 | Holden Australia |
| 5430940 | Harness Replacement | N913585 | Holden Australia |
| 5430940 | Harness Replacement | N913586 | Holden Australia |
| 5430940 | Harness Replacement | N913587 | Holden Australia |
| 5430940 | Harness Replacement | N913588 | Holden Australia |
| 5430940 | Harness Replacement | N913589 | Holden Australia |
| 5430940 | Harness Replacement | N913590 | Holden Australia |
| 5430940 | Harness Replacement | N913591 | Holden Australia |
| 5430940 | Harness Replacement | N913592 | Holden Australia |
| 5430940 | Harness Replacement | N913593 | Holden Australia |
| 5430940 | Harness Replacement | N913595 | Holden Australia |
| 5430940 | Harness Replacement | N913596 | Holden Australia |
| 5430940 | Harness Replacement | N913597 | Holden Australia |
| 5430940 | Harness Replacement | N913785 | Holden Australia |
| 5430940 | Harness Replacement | N913786 | Holden Australia |
| 5430940 | Harness Replacement | N913787 | Holden Australia |
| 5430940 | Harness Replacement | N913788 | Holden Australia |
| 5430940 | Harness Replacement | N913789 | Holden Australia |
| 5430940 | Harness Replacement | N913790 | Holden Australia |
| 5430940 | Harness Replacement | N913791 | Holden Australia |
| 5430940 | Harness Replacement | N913792 | Holden Australia |
| 5430940 | Harness Replacement | N913793 | Holden Australia |
| 5430940 | Harness Replacement | N913794 | Holden Australia |
| 5430940 | Harness Replacement | N913796 | Holden Australia |
| 5430940 | Harness Replacement | N913797 | Holden Australia |
| 5430940 | Harness Replacement | N913798 | Holden Australia |
| 5430940 | Harness Replacement | N914986 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N914988 | Holden Australia |
| 5430940 | Harness Replacement | N914989 | Holden Australia |
| 5430940 | Harness Replacement | N914991 | Holden Australia |
| 5430940 | Harness Replacement | N914992 | Holden Australia |
| 5430940 | Harness Replacement | N914993 | Holden Australia |
| 5430940 | Harness Replacement | N914996 | Holden Australia |
| 5430940 | Harness Replacement | N914997 | Holden Australia |
| 5430940 | Harness Replacement | N914998 | Holden Australia |
| 5430940 | Harness Replacement | N915086 | Holden Australia |
| 5430940 | Harness Replacement | N915087 | Holden Australia |
| 5430940 | Harness Replacement | N915089 | Holden Australia |
| 5430940 | Harness Replacement | N915090 | Holden Australia |
| 5430940 | Harness Replacement | N915091 | Holden Australia |
| 5430940 | Harness Replacement | N915094 | Holden Australia |
| 5430940 | Harness Replacement | N915096 | Holden Australia |
| 5430940 | Harness Replacement | N915097 | Holden Australia |
| 5430940 | Harness Replacement | N915186 | Holden Australia |
| 5430940 | Harness Replacement | N915187 | Holden Australia |
| 5430940 | Harness Replacement | N915190 | Holden Australia |
| 5430940 | Harness Replacement | N915191 | Holden Australia |
| 5430940 | Harness Replacement | N915193 | Holden Australia |
| 5430940 | Harness Replacement | N915194 | Holden Australia |
| 5430940 | Harness Replacement | N915196 | Holden Australia |
| 5430940 | Harness Replacement | N915285 | Holden Australia |
| 5430940 | Harness Replacement | N915286 | Holden Australia |
| 5430940 | Harness Replacement | N915287 | Holden Australia |
| 5430940 | Harness Replacement | N915288 | Holden Australia |
| 5430940 | Harness Replacement | N915291 | Holden Australia |
| 5430940 | Harness Replacement | N915292 | Holden Australia |
| 5430940 | Harness Replacement | N915295 | Holden Australia |
| 5430940 | Harness Replacement | N915297 | Holden Australia |
| 5430940 | Harness Replacement | N915686 | Holden Australia |
| 5430940 | Harness Replacement | N915688 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N915692 | Holden Australia |
| 5430940 | Harness Replacement | N915786 | Holden Australia |
| 5430940 | Harness Replacement | N915787 | Holden Australia |
| 5430940 | Harness Replacement | N915790 | Holden Australia |
| 5430940 | Harness Replacement | N915791 | Holden Australia |
| 5430940 | Harness Replacement | N915792 | Holden Australia |
| 5430940 | Harness Replacement | N915796 | Holden Australia |
| 5430940 | Harness Replacement | N915895 | Holden Australia |
| 5430940 | Harness Replacement | N916487 | Holden Australia |
| 5430940 | Harness Replacement | N916491 | Holden Australia |
| 5430940 | Harness Replacement | N916492 | Holden Australia |
| 5430940 | Harness Replacement | N916493 | Holden Australia |
| 5430940 | Harness Replacement | N916494 | Holden Australia |
| 5430940 | Harness Replacement | N916495 | Holden Australia |
| 5430940 | Harness Replacement | N916497 | Holden Australia |
| 5430940 | Harness Replacement | N916587 | Holden Australia |
| 5430940 | Harness Replacement | N916590 | Holden Australia |
| 5430940 | Harness Replacement | N916592 | Holden Australia |
| 5430940 | Harness Replacement | N916786 | Holden Australia |
| 5430940 | Harness Replacement | N917190 | Holden Australia |
| 5430940 | Harness Replacement | N917588 | Holden Australia |
| 5430940 | Harness Replacement | N917589 | Holden Australia |
| 5430940 | Harness Replacement | N917595 | Holden Australia |
| 5430940 | Harness Replacement | N917785 | Holden Australia |
| 5430940 | Harness Replacement | N917786 | Holden Australia |
| 5430940 | Harness Replacement | N917787 | Holden Australia |
| 5430940 | Harness Replacement | N917789 | Holden Australia |
| 5430940 | Harness Replacement | N917791 | Holden Australia |
| 5430940 | Harness Replacement | N917795 | Holden Australia |
| 5430940 | Harness Replacement | N917797 | Holden Australia |
| 5430940 | Harness Replacement | N917896 | Holden Australia |
| 5430940 | Harness Replacement | N917994 | Holden Australia |
| 5430940 | Harness Replacement | N918089 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N920706 | Holden Australia |
| 5430940 | Harness Replacement | N921989 | Holden Australia |
| 5430940 | Harness Replacement | N922292 | Holden Australia |
| 5430940 | Harness Replacement | N922913 | Holden Australia |
| 5430940 | Harness Replacement | N931390 | Holden Australia |
| 5430940 | Harness Replacement | N931391 | Holden Australia |
| 5430940 | Harness Replacement | N931392 | Holden Australia |
| 5430940 | Harness Replacement | N931393 | Holden Australia |
| 5430940 | Harness Replacement | N931394 | Holden Australia |
| 5430940 | Harness Replacement | N931690 | Holden Australia |
| 5430940 | Harness Replacement | N931691 | Holden Australia |
| 5430940 | Harness Replacement | N931694 | Holden Australia |
| 5430940 | Harness Replacement | N931695 | Holden Australia |
| 5430940 | Harness Replacement | N931696 | Holden Australia |
| 5430940 | Harness Replacement | N931790 | Holden Australia |
| 5430940 | Harness Replacement | N931791 | Holden Australia |
| 5430940 | Harness Replacement | N931792 | Holden Australia |
| 5430940 | Harness Replacement | N931793 | Holden Australia |
| 5430940 | Harness Replacement | N931794 | Holden Australia |
| 5430940 | Harness Replacement | N931795 | Holden Australia |
| 5430940 | Harness Replacement | N931885 | Holden Australia |
| 5430940 | Harness Replacement | N931887 | Holden Australia |
| 5430940 | Harness Replacement | N931985 | Holden Australia |
| 5430940 | Harness Replacement | N931991 | Holden Australia |
| 5430940 | Harness Replacement | N931996 | Holden Australia |
| 5430940 | Harness Replacement | N932088 | Holden Australia |
| 5430940 | Harness Replacement | N932089 | Holden Australia |
| 5430940 | Harness Replacement | N932090 | Holden Australia |
| 5430940 | Harness Replacement | N932092 | Holden Australia |
| 5430940 | Harness Replacement | N932186 | Holden Australia |
| 5430940 | Harness Replacement | N932187 | Holden Australia |
| 5430940 | Harness Replacement | N932194 | Holden Australia |
| 5430940 | Harness Replacement | N932195 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N932197 | Holden Australia |
| 5430940 | Harness Replacement | N932585 | Holden Australia |
| 5430940 | Harness Replacement | N932586 | Holden Australia |
| 5430940 | Harness Replacement | N932587 | Holden Australia |
| 5430940 | Harness Replacement | N932588 | Holden Australia |
| 5430940 | Harness Replacement | N932590 | Holden Australia |
| 5430940 | Harness Replacement | N932591 | Holden Australia |
| 5430940 | Harness Replacement | N932592 | Holden Australia |
| 5430940 | Harness Replacement | N932594 | Holden Australia |
| 5430940 | Harness Replacement | N932595 | Holden Australia |
| 5430940 | Harness Replacement | N932596 | Holden Australia |
| 5430940 | Harness Replacement | N932597 | Holden Australia |
| 5430940 | Harness Replacement | N932687 | Holden Australia |
| 5430940 | Harness Replacement | N932695 | Holden Australia |
| 5430940 | Harness Replacement | N932696 | Holden Australia |
| 5430940 | Harness Replacement | N932795 | Holden Australia |
| 5430940 | Harness Replacement | N933192 | Holden Australia |
| 5430940 | Harness Replacement | N933193 | Holden Australia |
| 5430940 | Harness Replacement | N933194 | Holden Australia |
| 5430940 | Harness Replacement | N933692 | Holden Australia |
| 5430940 | Harness Replacement | N934387 | Holden Australia |
| 5430940 | Harness Replacement | N934389 | Holden Australia |
| 5430940 | Harness Replacement | N934390 | Holden Australia |
| 5430940 | Harness Replacement | N934394 | Holden Australia |
| 5430940 | Harness Replacement | N934395 | Holden Australia |
| 5430940 | Harness Replacement | N934396 | Holden Australia |
| 5430940 | Harness Replacement | N934486 | Holden Australia |
| 5430940 | Harness Replacement | N934488 | Holden Australia |
| 5430940 | Harness Replacement | N934489 | Holden Australia |
| 5430940 | Harness Replacement | N934490 | Holden Australia |
| 5430940 | Harness Replacement | N934493 | Holden Australia |
| 5430940 | Harness Replacement | N934495 | Holden Australia |
| 5430940 | Harness Replacement | N934496 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N934497 | Holden Australia |
| 5430940 | Harness Replacement | N935086 | Holden Australia |
| 5430940 | Harness Replacement | N935087 | Holden Australia |
| 5430940 | Harness Replacement | N935089 | Holden Australia |
| 5430940 | Harness Replacement | N935090 | Holden Australia |
| 5430940 | Harness Replacement | N935092 | Holden Australia |
| 5430940 | Harness Replacement | N935095 | Holden Australia |
| 5430940 | Harness Replacement | N935096 | Holden Australia |
| 5430940 | Harness Replacement | N935097 | Holden Australia |
| 5430940 | Harness Replacement | N941289 | Holden Australia |
| 5430940 | Harness Replacement | N941290 | Holden Australia |
| 5430940 | Harness Replacement | N941291 | Holden Australia |
| 5430940 | Harness Replacement | N941292 | Holden Australia |
| 5430940 | Harness Replacement | N941294 | Holden Australia |
| 5430940 | Harness Replacement | N941492 | Holden Australia |
| 5430940 | Harness Replacement | N941493 | Holden Australia |
| 5430940 | Harness Replacement | N941592 | Holden Australia |
| 5430940 | Harness Replacement | N941688 | Holden Australia |
| 5430940 | Harness Replacement | N941689 | Holden Australia |
| 5430940 | Harness Replacement | N941691 | Holden Australia |
| 5430940 | Harness Replacement | N941692 | Holden Australia |
| 5430940 | Harness Replacement | N941694 | Holden Australia |
| 5430940 | Harness Replacement | N941695 | Holden Australia |
| 5430940 | Harness Replacement | N941789 | Holden Australia |
| 5430940 | Harness Replacement | N941790 | Holden Australia |
| 5430940 | Harness Replacement | N941791 | Holden Australia |
| 5430940 | Harness Replacement | N941793 | Holden Australia |
| 5430940 | Harness Replacement | N941794 | Holden Australia |
| 5430940 | Harness Replacement | N941988 | Holden Australia |
| 5430940 | Harness Replacement | N941991 | Holden Australia |
| 5430940 | Harness Replacement | N942086 | Holden Australia |
| 5430940 | Harness Replacement | N942088 | Holden Australia |
| 5430940 | Harness Replacement | N942094 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N942095 | Holden Australia |
| 5430940 | Harness Replacement | N942191 | Holden Australia |
| 5430940 | Harness Replacement | N942195 | Holden Australia |
| 5430940 | Harness Replacement | N942196 | Holden Australia |
| 5430940 | Harness Replacement | N942288 | Holden Australia |
| 5430940 | Harness Replacement | N942292 | Holden Australia |
| 5430940 | Harness Replacement | N942294 | Holden Australia |
| 5430940 | Harness Replacement | N942391 | Holden Australia |
| 5430940 | Harness Replacement | N942395 | Holden Australia |
| 5430940 | Harness Replacement | N942487 | Holden Australia |
| 5430940 | Harness Replacement | N942496 | Holden Australia |
| 5430940 | Harness Replacement | N942605 | Holden Australia |
| 5430940 | Harness Replacement | N942607 | Holden Australia |
| 5430940 | Harness Replacement | N943394 | Holden Australia |
| 5430940 | Harness Replacement | N943901 | Holden Australia |
| 5430940 | Harness Replacement | N943902 | Holden Australia |
| 5430940 | Harness Replacement | N944001 | Holden Australia |
| 5430940 | Harness Replacement | N944896 | Holden Australia |
| 5430940 | Harness Replacement | N951390 | Holden Australia |
| 5430940 | Harness Replacement | N951391 | Holden Australia |
| 5430940 | Harness Replacement | N951392 | Holden Australia |
| 5430940 | Harness Replacement | N951393 | Holden Australia |
| 5430940 | Harness Replacement | N951394 | Holden Australia |
| 5430940 | Harness Replacement | N951395 | Holden Australia |
| 5430940 | Harness Replacement | N951396 | Holden Australia |
| 5430940 | Harness Replacement | N951589 | Holden Australia |
| 5430940 | Harness Replacement | N951590 | Holden Australia |
| 5430940 | Harness Replacement | N951591 | Holden Australia |
| 5430940 | Harness Replacement | N951592 | Holden Australia |
| 5430940 | Harness Replacement | N951593 | Holden Australia |
| 5430940 | Harness Replacement | N951594 | Holden Australia |
| 5430940 | Harness Replacement | N951595 | Holden Australia |
| 5430940 | Harness Replacement | N951596 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N951687 | Holden Australia |
| 5430940 | Harness Replacement | N951689 | Holden Australia |
| 5430940 | Harness Replacement | N951690 | Holden Australia |
| 5430940 | Harness Replacement | N951691 | Holden Australia |
| 5430940 | Harness Replacement | N951692 | Holden Australia |
| 5430940 | Harness Replacement | N951693 | Holden Australia |
| 5430940 | Harness Replacement | N951694 | Holden Australia |
| 5430940 | Harness Replacement | N951695 | Holden Australia |
| 5430940 | Harness Replacement | N951785 | Holden Australia |
| 5430940 | Harness Replacement | N951890 | Holden Australia |
| 5430940 | Harness Replacement | N951896 | Holden Australia |
| 5430940 | Harness Replacement | N951986 | Holden Australia |
| 5430940 | Harness Replacement | N951987 | Holden Australia |
| 5430940 | Harness Replacement | N951988 | Holden Australia |
| 5430940 | Harness Replacement | N951991 | Holden Australia |
| 5430940 | Harness Replacement | N951992 | Holden Australia |
| 5430940 | Harness Replacement | N951993 | Holden Australia |
| 5430940 | Harness Replacement | N951994 | Holden Australia |
| 5430940 | Harness Replacement | N951995 | Holden Australia |
| 5430940 | Harness Replacement | N951996 | Holden Australia |
| 5430940 | Harness Replacement | N952088 | Holden Australia |
| 5430940 | Harness Replacement | N952089 | Holden Australia |
| 5430940 | Harness Replacement | N952090 | Holden Australia |
| 5430940 | Harness Replacement | N952091 | Holden Australia |
| 5430940 | Harness Replacement | N952095 | Holden Australia |
| 5430940 | Harness Replacement | N952096 | Holden Australia |
| 5430940 | Harness Replacement | N952097 | Holden Australia |
| 5430940 | Harness Replacement | N952186 | Holden Australia |
| 5430940 | Harness Replacement | N952588 | Holden Australia |
| 5430940 | Harness Replacement | N952589 | Holden Australia |
| 5430940 | Harness Replacement | N952686 | Holden Australia |
| 5430940 | Harness Replacement | N952687 | Holden Australia |
| 5430940 | Harness Replacement | N952691 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N952692 | Holden Australia |
| 5430940 | Harness Replacement | N952693 | Holden Australia |
| 5430940 | Harness Replacement | N952694 | Holden Australia |
| 5430940 | Harness Replacement | N952695 | Holden Australia |
| 5430940 | Harness Replacement | N952696 | Holden Australia |
| 5430940 | Harness Replacement | N952697 | Holden Australia |
| 5430940 | Harness Replacement | N953086 | Holden Australia |
| 5430940 | Harness Replacement | N953087 | Holden Australia |
| 5430940 | Harness Replacement | N953088 | Holden Australia |
| 5430940 | Harness Replacement | N953093 | Holden Australia |
| 5430940 | Harness Replacement | N953094 | Holden Australia |
| 5430940 | Harness Replacement | N953686 | Holden Australia |
| 5430940 | Harness Replacement | N953689 | Holden Australia |
| 5430940 | Harness Replacement | N953697 | Holden Australia |
| 5430940 | Harness Replacement | N953785 | Holden Australia |
| 5430940 | Harness Replacement | N953786 | Holden Australia |
| 5430940 | Harness Replacement | N953787 | Holden Australia |
| 5430940 | Harness Replacement | N953788 | Holden Australia |
| 5430940 | Harness Replacement | N953792 | Holden Australia |
| 5430940 | Harness Replacement | N953793 | Holden Australia |
| 5430940 | Harness Replacement | N953794 | Holden Australia |
| 5430940 | Harness Replacement | N953795 | Holden Australia |
| 5430940 | Harness Replacement | N953796 | Holden Australia |
| 5430940 | Harness Replacement | N953886 | Holden Australia |
| 5430940 | Harness Replacement | N953887 | Holden Australia |
| 5430940 | Harness Replacement | N953888 | Holden Australia |
| 5430940 | Harness Replacement | N953889 | Holden Australia |
| 5430940 | Harness Replacement | N953890 | Holden Australia |
| 5430940 | Harness Replacement | N953895 | Holden Australia |
| 5430940 | Harness Replacement | N953896 | Holden Australia |
| 5430940 | Harness Replacement | N953897 | Holden Australia |
| 5430940 | Harness Replacement | N953987 | Holden Australia |
| 5430940 | Harness Replacement | N953989 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N953990 | Holden Australia |
| 5430940 | Harness Replacement | N953991 | Holden Australia |
| 5430940 | Harness Replacement | N953992 | Holden Australia |
| 5430940 | Harness Replacement | N953993 | Holden Australia |
| 5430940 | Harness Replacement | N953995 | Holden Australia |
| 5430940 | Harness Replacement | N953996 | Holden Australia |
| 5430940 | Harness Replacement | N954088 | Holden Australia |
| 5430940 | Harness Replacement | N954089 | Holden Australia |
| 5430940 | Harness Replacement | N954090 | Holden Australia |
| 5430940 | Harness Replacement | N954093 | Holden Australia |
| 5430940 | Harness Replacement | N954094 | Holden Australia |
| 5430940 | Harness Replacement | N954095 | Holden Australia |
| 5430940 | Harness Replacement | N954284 | Holden Australia |
| 5430940 | Harness Replacement | N954285 | Holden Australia |
| 5430940 | Harness Replacement | N954286 | Holden Australia |
| 5430940 | Harness Replacement | N955090 | Holden Australia |
| 5430940 | Harness Replacement | N955091 | Holden Australia |
| 5430940 | Harness Replacement | N955092 | Holden Australia |
| 5430940 | Harness Replacement | N955093 | Holden Australia |
| 5430940 | Harness Replacement | N955094 | Holden Australia |
| 5430940 | Harness Replacement | N955096 | Holden Australia |
| 5430940 | Harness Replacement | N955189 | Holden Australia |
| 5430940 | Harness Replacement | N955192 | Holden Australia |
| 5430940 | Harness Replacement | N955193 | Holden Australia |
| 5430940 | Harness Replacement | N955288 | Holden Australia |
| 5430940 | Harness Replacement | N955389 | Holden Australia |
| 5430940 | Harness Replacement | N955396 | Holden Australia |
| 5430940 | Harness Replacement | N955397 | Holden Australia |
| 5430940 | Harness Replacement | N961390 | Holden Australia |
| 5430940 | Harness Replacement | N961391 | Holden Australia |
| 5430940 | Harness Replacement | N961392 | Holden Australia |
| 5430940 | Harness Replacement | N961393 | Holden Australia |
| 5430940 | Harness Replacement | N961394 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N961395 | Holden Australia |
| 5430940 | Harness Replacement | N961588 | Holden Australia |
| 5430940 | Harness Replacement | N961589 | Holden Australia |
| 5430940 | Harness Replacement | N961590 | Holden Australia |
| 5430940 | Harness Replacement | N961591 | Holden Australia |
| 5430940 | Harness Replacement | N961592 | Holden Australia |
| 5430940 | Harness Replacement | N961593 | Holden Australia |
| 5430940 | Harness Replacement | N961594 | Holden Australia |
| 5430940 | Harness Replacement | N961595 | Holden Australia |
| 5430940 | Harness Replacement | N961596 | Holden Australia |
| 5430940 | Harness Replacement | N961688 | Holden Australia |
| 5430940 | Harness Replacement | N961689 | Holden Australia |
| 5430940 | Harness Replacement | N961690 | Holden Australia |
| 5430940 | Harness Replacement | N961691 | Holden Australia |
| 5430940 | Harness Replacement | N961692 | Holden Australia |
| 5430940 | Harness Replacement | N961693 | Holden Australia |
| 5430940 | Harness Replacement | N961694 | Holden Australia |
| 5430940 | Harness Replacement | N961695 | Holden Australia |
| 5430940 | Harness Replacement | N961696 | Holden Australia |
| 5430940 | Harness Replacement | N961788 | Holden Australia |
| 5430940 | Harness Replacement | N961789 | Holden Australia |
| 5430940 | Harness Replacement | N961790 | Holden Australia |
| 5430940 | Harness Replacement | N961791 | Holden Australia |
| 5430940 | Harness Replacement | N961792 | Holden Australia |
| 5430940 | Harness Replacement | N961793 | Holden Australia |
| 5430940 | Harness Replacement | N961794 | Holden Australia |
| 5430940 | Harness Replacement | N961795 | Holden Australia |
| 5430940 | Harness Replacement | N961796 | Holden Australia |
| 5430940 | Harness Replacement | N961887 | Holden Australia |
| 5430940 | Harness Replacement | N961888 | Holden Australia |
| 5430940 | Harness Replacement | N961889 | Holden Australia |
| 5430940 | Harness Replacement | N961890 | Holden Australia |
| 5430940 | Harness Replacement | N961891 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N961892 | Holden Australia |
| 5430940 | Harness Replacement | N961893 | Holden Australia |
| 5430940 | Harness Replacement | N961894 | Holden Australia |
| 5430940 | Harness Replacement | N961895 | Holden Australia |
| 5430940 | Harness Replacement | N961896 | Holden Australia |
| 5430940 | Harness Replacement | N961985 | Holden Australia |
| 5430940 | Harness Replacement | N961986 | Holden Australia |
| 5430940 | Harness Replacement | N961988 | Holden Australia |
| 5430940 | Harness Replacement | N962084 | Holden Australia |
| 5430940 | Harness Replacement | N962086 | Holden Australia |
| 5430940 | Harness Replacement | N962087 | Holden Australia |
| 5430940 | Harness Replacement | N962088 | Holden Australia |
| 5430940 | Harness Replacement | N962091 | Holden Australia |
| 5430940 | Harness Replacement | N962096 | Holden Australia |
| 5430940 | Harness Replacement | N962097 | Holden Australia |
| 5430940 | Harness Replacement | N962186 | Holden Australia |
| 5430940 | Harness Replacement | N962187 | Holden Australia |
| 5430940 | Harness Replacement | N962188 | Holden Australia |
| 5430940 | Harness Replacement | N962189 | Holden Australia |
| 5430940 | Harness Replacement | N962192 | Holden Australia |
| 5430940 | Harness Replacement | N962193 | Holden Australia |
| 5430940 | Harness Replacement | N962194 | Holden Australia |
| 5430940 | Harness Replacement | N962195 | Holden Australia |
| 5430940 | Harness Replacement | N962196 | Holden Australia |
| 5430940 | Harness Replacement | N962287 | Holden Australia |
| 5430940 | Harness Replacement | N962288 | Holden Australia |
| 5430940 | Harness Replacement | N962289 | Holden Australia |
| 5430940 | Harness Replacement | N962290 | Holden Australia |
| 5430940 | Harness Replacement | N962291 | Holden Australia |
| 5430940 | Harness Replacement | N962295 | Holden Australia |
| 5430940 | Harness Replacement | N962296 | Holden Australia |
| 5430940 | Harness Replacement | N962297 | Holden Australia |
| 5430940 | Harness Replacement | N962385 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N962386 | Holden Australia |
| 5430940 | Harness Replacement | N962387 | Holden Australia |
| 5430940 | Harness Replacement | N962389 | Holden Australia |
| 5430940 | Harness Replacement | N962390 | Holden Australia |
| 5430940 | Harness Replacement | N962391 | Holden Australia |
| 5430940 | Harness Replacement | N962394 | Holden Australia |
| 5430940 | Harness Replacement | N962704 | Holden Australia |
| 5430940 | Harness Replacement | N962988 | Holden Australia |
| 5430940 | Harness Replacement | N962989 | Holden Australia |
| 5430940 | Harness Replacement | N962990 | Holden Australia |
| 5430940 | Harness Replacement | N962995 | Holden Australia |
| 5430940 | Harness Replacement | N962996 | Holden Australia |
| 5430940 | Harness Replacement | N963085 | Holden Australia |
| 5430940 | Harness Replacement | N963086 | Holden Australia |
| 5430940 | Harness Replacement | N963087 | Holden Australia |
| 5430940 | Harness Replacement | N963088 | Holden Australia |
| 5430940 | Harness Replacement | N963089 | Holden Australia |
| 5430940 | Harness Replacement | N963090 | Holden Australia |
| 5430940 | Harness Replacement | N963091 | Holden Australia |
| 5430940 | Harness Replacement | N963092 | Holden Australia |
| 5430940 | Harness Replacement | N963093 | Holden Australia |
| 5430940 | Harness Replacement | N963094 | Holden Australia |
| 5430940 | Harness Replacement | N963095 | Holden Australia |
| 5430940 | Harness Replacement | N963096 | Holden Australia |
| 5430940 | Harness Replacement | N963097 | Holden Australia |
| 5430940 | Harness Replacement | N963292 | Holden Australia |
| 5430940 | Harness Replacement | N963488 | Holden Australia |
| 5430940 | Harness Replacement | N963493 | Holden Australia |
| 5430940 | Harness Replacement | N963494 | Holden Australia |
| 5430940 | Harness Replacement | N963504 | Holden Australia |
| 5430940 | Harness Replacement | N963686 | Holden Australia |
| 5430940 | Harness Replacement | N963687 | Holden Australia |
| 5430940 | Harness Replacement | N963693 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N963694 | Holden Australia |
| 5430940 | Harness Replacement | N964385 | Holden Australia |
| 5430940 | Harness Replacement | N964386 | Holden Australia |
| 5430940 | Harness Replacement | N964387 | Holden Australia |
| 5430940 | Harness Replacement | N964388 | Holden Australia |
| 5430940 | Harness Replacement | N964390 | Holden Australia |
| 5430940 | Harness Replacement | N964391 | Holden Australia |
| 5430940 | Harness Replacement | N964393 | Holden Australia |
| 5430940 | Harness Replacement | N964394 | Holden Australia |
| 5430940 | Harness Replacement | N964395 | Holden Australia |
| 5430940 | Harness Replacement | N964396 | Holden Australia |
| 5430940 | Harness Replacement | N964485 | Holden Australia |
| 5430940 | Harness Replacement | N964486 | Holden Australia |
| 5430940 | Harness Replacement | N964488 | Holden Australia |
| 5430940 | Harness Replacement | N964489 | Holden Australia |
| 5430940 | Harness Replacement | N964491 | Holden Australia |
| 5430940 | Harness Replacement | N964492 | Holden Australia |
| 5430940 | Harness Replacement | N964495 | Holden Australia |
| 5430940 | Harness Replacement | N964496 | Holden Australia |
| 5430940 | Harness Replacement | N964796 | Holden Australia |
| 5430940 | Harness Replacement | N964988 | Holden Australia |
| 5430940 | Harness Replacement | N964990 | Holden Australia |
| 5430940 | Harness Replacement | N964994 | Holden Australia |
| 5430940 | Harness Replacement | N965089 | Holden Australia |
| 5430940 | Harness Replacement | N965092 | Holden Australia |
| 5430940 | Harness Replacement | N965095 | Holden Australia |
| 5430940 | Harness Replacement | N965096 | Holden Australia |
| 5430940 | Harness Replacement | N965295 | Holden Australia |
| 5430940 | Harness Replacement | N965490 | Holden Australia |
| 5430940 | Harness Replacement | N965497 | Holden Australia |
| 5430940 | Harness Replacement | N965594 | Holden Australia |
| 5430940 | Harness Replacement | N965695 | Holden Australia |
| 5430940 | Harness Replacement | N966290 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N966291 | Holden Australia |
| 5430940 | Harness Replacement | N966292 | Holden Australia |
| 5430940 | Harness Replacement | N966293 | Holden Australia |
| 5430940 | Harness Replacement | N966294 | Holden Australia |
| 5430940 | Harness Replacement | N966295 | Holden Australia |
| 5430940 | Harness Replacement | N966307 | Holden Australia |
| 5430940 | Harness Replacement | N966588 | Holden Australia |
| 5430940 | Harness Replacement | N966589 | Holden Australia |
| 5430940 | Harness Replacement | N966590 | Holden Australia |
| 5430940 | Harness Replacement | N966591 | Holden Australia |
| 5430940 | Harness Replacement | N966592 | Holden Australia |
| 5430940 | Harness Replacement | N966593 | Holden Australia |
| 5430940 | Harness Replacement | N966594 | Holden Australia |
| 5430940 | Harness Replacement | N966595 | Holden Australia |
| 5430940 | Harness Replacement | N966596 | Holden Australia |
| 5430940 | Harness Replacement | N966688 | Holden Australia |
| 5430940 | Harness Replacement | N966690 | Holden Australia |
| 5430940 | Harness Replacement | N966691 | Holden Australia |
| 5430940 | Harness Replacement | N966692 | Holden Australia |
| 5430940 | Harness Replacement | N966693 | Holden Australia |
| 5430940 | Harness Replacement | N966694 | Holden Australia |
| 5430940 | Harness Replacement | N966695 | Holden Australia |
| 5430940 | Harness Replacement | N966788 | Holden Australia |
| 5430940 | Harness Replacement | N966789 | Holden Australia |
| 5430940 | Harness Replacement | N966790 | Holden Australia |
| 5430940 | Harness Replacement | N966791 | Holden Australia |
| 5430940 | Harness Replacement | N966792 | Holden Australia |
| 5430940 | Harness Replacement | N966793 | Holden Australia |
| 5430940 | Harness Replacement | N966794 | Holden Australia |
| 5430940 | Harness Replacement | N966795 | Holden Australia |
| 5430940 | Harness Replacement | N966796 | Holden Australia |
| 5430940 | Harness Replacement | N966888 | Holden Australia |
| 5430940 | Harness Replacement | N966889 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N966890 | Holden Australia |
| 5430940 | Harness Replacement | N966891 | Holden Australia |
| 5430940 | Harness Replacement | N966893 | Holden Australia |
| 5430940 | Harness Replacement | N966894 | Holden Australia |
| 5430940 | Harness Replacement | N966895 | Holden Australia |
| 5430940 | Harness Replacement | N966986 | Holden Australia |
| 5430940 | Harness Replacement | N967087 | Holden Australia |
| 5430940 | Harness Replacement | N967088 | Holden Australia |
| 5430940 | Harness Replacement | N967089 | Holden Australia |
| 5430940 | Harness Replacement | N967090 | Holden Australia |
| 5430940 | Harness Replacement | N967091 | Holden Australia |
| 5430940 | Harness Replacement | N967095 | Holden Australia |
| 5430940 | Harness Replacement | N967096 | Holden Australia |
| 5430940 | Harness Replacement | N967097 | Holden Australia |
| 5430940 | Harness Replacement | N971395 | Holden Australia |
| 5430940 | Harness Replacement | N971396 | Holden Australia |
| 5430940 | Harness Replacement | N971490 | Holden Australia |
| 5430940 | Harness Replacement | N971491 | Holden Australia |
| 5430940 | Harness Replacement | N971494 | Holden Australia |
| 5430940 | Harness Replacement | N971495 | Holden Australia |
| 5430940 | Harness Replacement | N971691 | Holden Australia |
| 5430940 | Harness Replacement | N971692 | Holden Australia |
| 5430940 | Harness Replacement | N971693 | Holden Australia |
| 5430940 | Harness Replacement | N971694 | Holden Australia |
| 5430940 | Harness Replacement | N971695 | Holden Australia |
| 5430940 | Harness Replacement | N971786 | Holden Australia |
| 5430940 | Harness Replacement | N971787 | Holden Australia |
| 5430940 | Harness Replacement | N971892 | Holden Australia |
| 5430940 | Harness Replacement | N971893 | Holden Australia |
| 5430940 | Harness Replacement | N971894 | Holden Australia |
| 5430940 | Harness Replacement | N971895 | Holden Australia |
| 5430940 | Harness Replacement | N971896 | Holden Australia |
| 5430940 | Harness Replacement | N971985 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N971987 | Holden Australia |
| 5430940 | Harness Replacement | N971992 | Holden Australia |
| 5430940 | Harness Replacement | N971993 | Holden Australia |
| 5430940 | Harness Replacement | N972088 | Holden Australia |
| 5430940 | Harness Replacement | N972095 | Holden Australia |
| 5430940 | Harness Replacement | N972096 | Holden Australia |
| 5430940 | Harness Replacement | N972185 | Holden Australia |
| 5430940 | Harness Replacement | N972190 | Holden Australia |
| 5430940 | Harness Replacement | N972191 | Holden Australia |
| 5430940 | Harness Replacement | N972194 | Holden Australia |
| 5430940 | Harness Replacement | N972495 | Holden Australia |
| 5430940 | Harness Replacement | N972496 | Holden Australia |
| 5430940 | Harness Replacement | N972586 | Holden Australia |
| 5430940 | Harness Replacement | N972590 | Holden Australia |
| 5430940 | Harness Replacement | N972594 | Holden Australia |
| 5430940 | Harness Replacement | N972596 | Holden Australia |
| 5430940 | Harness Replacement | N973488 | Holden Australia |
| 5430940 | Harness Replacement | N973489 | Holden Australia |
| 5430940 | Harness Replacement | N973596 | Holden Australia |
| 5430940 | Harness Replacement | N973892 | Holden Australia |
| 5430940 | Harness Replacement | N974391 | Holden Australia |
| 5430940 | Harness Replacement | N974393 | Holden Australia |
| 5430940 | Harness Replacement | N974394 | Holden Australia |
| 5430940 | Harness Replacement | N974395 | Holden Australia |
| 5430940 | Harness Replacement | N974589 | Holden Australia |
| 5430940 | Harness Replacement | N974590 | Holden Australia |
| 5430940 | Harness Replacement | N974591 | Holden Australia |
| 5430940 | Harness Replacement | N974592 | Holden Australia |
| 5430940 | Harness Replacement | N974593 | Holden Australia |
| 5430940 | Harness Replacement | N974594 | Holden Australia |
| 5430940 | Harness Replacement | N974595 | Holden Australia |
| 5430940 | Harness Replacement | N974788 | Holden Australia |
| 5430940 | Harness Replacement | N974789 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N974791 | Holden Australia |
| 5430940 | Harness Replacement | N974795 | Holden Australia |
| 5430940 | Harness Replacement | N974796 | Holden Australia |
| 5430940 | Harness Replacement | N974990 | Holden Australia |
| 5430940 | Harness Replacement | N974992 | Holden Australia |
| 5430940 | Harness Replacement | N974996 | Holden Australia |
| 5430940 | Harness Replacement | N975087 | Holden Australia |
| 5430940 | Harness Replacement | N975088 | Holden Australia |
| 5430940 | Harness Replacement | N975092 | Holden Australia |
| 5430940 | Harness Replacement | N975095 | Holden Australia |
| 5430940 | Harness Replacement | N981391 | Holden Australia |
| 5430940 | Harness Replacement | N981393 | Holden Australia |
| 5430940 | Harness Replacement | N981394 | Holden Australia |
| 5430940 | Harness Replacement | N981395 | Holden Australia |
| 5430940 | Harness Replacement | N981688 | Holden Australia |
| 5430940 | Harness Replacement | N981692 | Holden Australia |
| 5430940 | Harness Replacement | N981693 | Holden Australia |
| 5430940 | Harness Replacement | N981888 | Holden Australia |
| 5430940 | Harness Replacement | N981889 | Holden Australia |
| 5430940 | Harness Replacement | N981890 | Holden Australia |
| 5430940 | Harness Replacement | N981891 | Holden Australia |
| 5430940 | Harness Replacement | N981892 | Holden Australia |
| 5430940 | Harness Replacement | N981893 | Holden Australia |
| 5430940 | Harness Replacement | N981894 | Holden Australia |
| 5430940 | Harness Replacement | N981895 | Holden Australia |
| 5430940 | Harness Replacement | N981896 | Holden Australia |
| 5430940 | Harness Replacement | N981987 | Holden Australia |
| 5430940 | Harness Replacement | N981990 | Holden Australia |
| 5430940 | Harness Replacement | N981991 | Holden Australia |
| 5430940 | Harness Replacement | N981992 | Holden Australia |
| 5430940 | Harness Replacement | N981994 | Holden Australia |
| 5430940 | Harness Replacement | N981995 | Holden Australia |
| 5430940 | Harness Replacement | N982191 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N982196 | Holden Australia |
| 5430940 | Harness Replacement | N982288 | Holden Australia |
| 5430940 | Harness Replacement | N982289 | Holden Australia |
| 5430940 | Harness Replacement | N982292 | Holden Australia |
| 5430940 | Harness Replacement | N982294 | Holden Australia |
| 5430940 | Harness Replacement | N982295 | Holden Australia |
| 5430940 | Harness Replacement | N982387 | Holden Australia |
| 5430940 | Harness Replacement | N982388 | Holden Australia |
| 5430940 | Harness Replacement | N982396 | Holden Australia |
| 5430940 | Harness Replacement | N982397 | Holden Australia |
| 5430940 | Harness Replacement | N982490 | Holden Australia |
| 5430940 | Harness Replacement | N982494 | Holden Australia |
| 5430940 | Harness Replacement | N982890 | Holden Australia |
| 5430940 | Harness Replacement | N982895 | Holden Australia |
| 5430940 | Harness Replacement | N982985 | Holden Australia |
| 5430940 | Harness Replacement | N982992 | Holden Australia |
| 5430940 | Harness Replacement | N982993 | Holden Australia |
| 5430940 | Harness Replacement | N982995 | Holden Australia |
| 5430940 | Harness Replacement | N982996 | Holden Australia |
| 5430940 | Harness Replacement | N982997 | Holden Australia |
| 5430940 | Harness Replacement | N984085 | Holden Australia |
| 5430940 | Harness Replacement | N984087 | Holden Australia |
| 5430940 | Harness Replacement | N984088 | Holden Australia |
| 5430940 | Harness Replacement | N984089 | Holden Australia |
| 5430940 | Harness Replacement | N984090 | Holden Australia |
| 5430940 | Harness Replacement | N984091 | Holden Australia |
| 5430940 | Harness Replacement | N984092 | Holden Australia |
| 5430940 | Harness Replacement | N984093 | Holden Australia |
| 5430940 | Harness Replacement | N984094 | Holden Australia |
| 5430940 | Harness Replacement | N984095 | Holden Australia |
| 5430940 | Harness Replacement | N984097 | Holden Australia |
| 5430940 | Harness Replacement | N984185 | Holden Australia |
| 5430940 | Harness Replacement | N984187 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N984188 | Holden Australia |
| 5430940 | Harness Replacement | N984189 | Holden Australia |
| 5430940 | Harness Replacement | N984190 | Holden Australia |
| 5430940 | Harness Replacement | N984191 | Holden Australia |
| 5430940 | Harness Replacement | N984192 | Holden Australia |
| 5430940 | Harness Replacement | N984193 | Holden Australia |
| 5430940 | Harness Replacement | N984195 | Holden Australia |
| 5430940 | Harness Replacement | N984196 | Holden Australia |
| 5430940 | Harness Replacement | N984891 | Holden Australia |
| 5430940 | Harness Replacement | N984895 | Holden Australia |
| 5430940 | Harness Replacement | N984997 | Holden Australia |
| 5430940 | Harness Replacement | N985096 | Holden Australia |
| 5430940 | Harness Replacement | N985097 | Holden Australia |
| 5430940 | Harness Replacement | N985185 | Holden Australia |
| 5430940 | Harness Replacement | N985186 | Holden Australia |
| 5430940 | Harness Replacement | N985194 | Holden Australia |
| 5430940 | Harness Replacement | N985195 | Holden Australia |
| 5430940 | Harness Replacement | N985196 | Holden Australia |
| 5430940 | Harness Replacement | N985197 | Holden Australia |
| 5430940 | Harness Replacement | N985294 | Holden Australia |
| 5430940 | Harness Replacement | R000082 | Holden Australia |
| 5430940 | Harness Replacement | R200250 | Holden Australia |
| 5430940 | Harness Replacement | R200275 | Holden Australia |
| 5430940 | Harness Replacement | R603600 | Holden Australia |
| 5430940 | Harness Replacement | C000571 | Holden New Zealand |
| 5430940 | Harness Replacement | F400800 | Holden New Zealand |
| 5430940 | Harness Replacement | H903000 | Holden New Zealand |
| 5430940 | Harness Replacement | J000845 | Holden New Zealand |
| 5430940 | Harness Replacement | J000896 | Holden New Zealand |
| 5430940 | Harness Replacement | N000237 | Holden New Zealand |
| 5430940 | Harness Replacement | N000423 | Holden New Zealand |
| 5430940 | Harness Replacement | N000520 | Holden New Zealand |
| 5430940 | Harness Replacement | N000562 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N000765 | Holden New Zealand |
| 5430940 | Harness Replacement | N001710 | Holden New Zealand |
| 5430940 | Harness Replacement | N001790 | Holden New Zealand |
| 5430940 | Harness Replacement | N206500 | Holden New Zealand |
| 5430940 | Harness Replacement | N303500 | Holden New Zealand |
| 5430940 | Harness Replacement | N308700 | Holden New Zealand |
| 5430940 | Harness Replacement | N4000100 | Holden New Zealand |
| 5430940 | Harness Replacement | N400100 | Holden New Zealand |
| 5430940 | Harness Replacement | N401500002 | Holden New Zealand |
| 5430940 | Harness Replacement | N401502 | Holden New Zealand |
| 5430940 | Harness Replacement | N401599 | Holden New Zealand |
| 5430940 | Harness Replacement | N401599R | Holden New Zealand |
| 5430940 | Harness Replacement | N401700 | Holden New Zealand |
| 5430940 | Harness Replacement | N401810 | Holden New Zealand |
| 5430940 | Harness Replacement | N403499 | Holden New Zealand |
| 5430940 | Harness Replacement | N403599 | Holden New Zealand |
| 5430940 | Harness Replacement | N403599R | Holden New Zealand |
| 5430940 | Harness Replacement | N405510 | Holden New Zealand |
| 5430940 | Harness Replacement | N405599 | Holden New Zealand |
| 5430940 | Harness Replacement | N406599 | Holden New Zealand |
| 5430940 | Harness Replacement | N407599 | Holden New Zealand |
| 5430940 | Harness Replacement | N408599 | Holden New Zealand |
| 5430940 | Harness Replacement | N409300 | Holden New Zealand |
| 5430940 | Harness Replacement | N409599 | Holden New Zealand |
| 5430940 | Harness Replacement | N410010 | Holden New Zealand |
| 5430940 | Harness Replacement | N410210 | Holden New Zealand |
| 5430940 | Harness Replacement | N411599 | Holden New Zealand |
| 5430940 | Harness Replacement | N411599A4 | Holden New Zealand |
| 5430940 | Harness Replacement | N411599R | Holden New Zealand |
| 5430940 | Harness Replacement | N412000 | Holden New Zealand |
| 5430940 | Harness Replacement | N413599 | Holden New Zealand |
| 5430940 | Harness Replacement | N451599 | Holden New Zealand |
| 5430940 | Harness Replacement | N451599A2 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N451599R | Holden New Zealand |
| 5430940 | Harness Replacement | N45159A1 | Holden New Zealand |
| 5430940 | Harness Replacement | N451699A1 | Holden New Zealand |
| 5430940 | Harness Replacement | N453599 | Holden New Zealand |
| 5430940 | Harness Replacement | N453699 | Holden New Zealand |
| 5430940 | Harness Replacement | N453699R | Holden New Zealand |
| 5430940 | Harness Replacement | N457199 | Holden New Zealand |
| 5430940 | Harness Replacement | N457199R | Holden New Zealand |
| 5430940 | Harness Replacement | N457299 | Holden New Zealand |
| 5430940 | Harness Replacement | N457299R | Holden New Zealand |
| 5430940 | Harness Replacement | N459199 | Holden New Zealand |
| 5430940 | Harness Replacement | N459199R | Holden New Zealand |
| 5430940 | Harness Replacement | N459299 | Holden New Zealand |
| 5430940 | Harness Replacement | N459299R | Holden New Zealand |
| 5430940 | Harness Replacement | N466199 | Holden New Zealand |
| 5430940 | Harness Replacement | N466199A1 | Holden New Zealand |
| 5430940 | Harness Replacement | N466199R | Holden New Zealand |
| 5430940 | Harness Replacement | N466299 | Holden New Zealand |
| 5430940 | Harness Replacement | N466299R | Holden New Zealand |
| 5430940 | Harness Replacement | N471599 | Holden New Zealand |
| 5430940 | Harness Replacement | N481599 | Holden New Zealand |
| 5430940 | Harness Replacement | N482699 | Holden New Zealand |
| 5430940 | Harness Replacement | N491699 | Holden New Zealand |
| 5430940 | Harness Replacement | N493599 | Holden New Zealand |
| 5430940 | Harness Replacement | N494800 | Holden New Zealand |
| 5430940 | Harness Replacement | N494810 | Holden New Zealand |
| 5430940 | Harness Replacement | N494900 | Holden New Zealand |
| 5430940 | Harness Replacement | N494910 | Holden New Zealand |
| 5430940 | Harness Replacement | N511000 | Holden New Zealand |
| 5430940 | Harness Replacement | N541140 | Holden New Zealand |
| 5430940 | Harness Replacement | N582000 | Holden New Zealand |
| 5430940 | Harness Replacement | N6030 | Holden New Zealand |
| 5430940 | Harness Replacement | N603000 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N606500 | Holden New Zealand |
| 5430940 | Harness Replacement | N6070 | Holden New Zealand |
| 5430940 | Harness Replacement | N607000 | Holden New Zealand |
| 5430940 | Harness Replacement | N6112 | Holden New Zealand |
| 5430940 | Harness Replacement | N611200 | Holden New Zealand |
| 5430940 | Harness Replacement | N6112SG | Holden New Zealand |
| 5430940 | Harness Replacement | N6113 | Holden New Zealand |
| 5430940 | Harness Replacement | N611300 | Holden New Zealand |
| 5430940 | Harness Replacement | N6180 | Holden New Zealand |
| 5430940 | Harness Replacement | N6255 | Holden New Zealand |
| 5430940 | Harness Replacement | N6270 | Holden New Zealand |
| 5430940 | Harness Replacement | N6290 | Holden New Zealand |
| 5430940 | Harness Replacement | N631000 | Holden New Zealand |
| 5430940 | Harness Replacement | N6360 | Holden New Zealand |
| 5430940 | Harness Replacement | N636000 | Holden New Zealand |
| 5430940 | Harness Replacement | N6398 | Holden New Zealand |
| 5430940 | Harness Replacement | N639800 | Holden New Zealand |
| 5430940 | Harness Replacement | N644000 | Holden New Zealand |
| 5430940 | Harness Replacement | N7060 | Holden New Zealand |
| 5430940 | Harness Replacement | N706000 | Holden New Zealand |
| 5430940 | Harness Replacement | N7060530 | Holden New Zealand |
| 5430940 | Harness Replacement | N7061 | Holden New Zealand |
| 5430940 | Harness Replacement | N706800 | Holden New Zealand |
| 5430940 | Harness Replacement | N7112 | Holden New Zealand |
| 5430940 | Harness Replacement | N720500 | Holden New Zealand |
| 5430940 | Harness Replacement | N760510 | Holden New Zealand |
| 5430940 | Harness Replacement | N760510R | Holden New Zealand |
| 5430940 | Harness Replacement | N760520 | Holden New Zealand |
| 5430940 | Harness Replacement | N760520R | Holden New Zealand |
| 5430940 | Harness Replacement | N760530 | Holden New Zealand |
| 5430940 | Harness Replacement | N760530R | Holden New Zealand |
| 5430940 | Harness Replacement | N780110 | Holden New Zealand |
| 5430940 | Harness Replacement | N780500 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 5430940 | Harness Replacement | N913794 | Holden New Zealand |
| 5430940 | Harness Replacement | R000082 | Holden New Zealand |
| 5430940 | Harness Replacement | R603600 | Holden New Zealand |
| 5430962 | Ground Connection Repair | N6478 | GMNA |
| 5430962 | Ground Connection Repair | N6656 | GMNA |
| 5430962 | Ground Connection Repair | N9502 | GMNA |
| 5430962 | Ground Connection Repair | N9517 | GMNA |
| 5430962 | Ground Connection Repair | N9676 | GMNA |
| 5430962 | Ground Connection Repair | J4560 | Holden Australia |
| 5430962 | Ground Connection Repair | N001700 | Holden Australia |
| 5430962 | Ground Connection Repair | N001720 | Holden Australia |
| 5430962 | Ground Connection Repair | N0126 | Holden Australia |
| 5430962 | Ground Connection Repair | N6620 | Holden Australia |
| 5430962 | Ground Connection Repair | N6656 | Holden Australia |
| 5430962 | Ground Connection Repair | N000713 | Holden New Zealand |
| 5430962 | Ground Connection Repair | N001700 | Holden New Zealand |
| 5430962 | Ground Connection Repair | N001720 | Holden New Zealand |
| 6010280 | Folding Top Stowage Compartment Lid Weatherstrip Replacement | B3165 | GMNA |
| 6010300 | Folding Top Front Locating Pin Replacement | B3220 | GMNA |
| 6010350 | Folding Top Front Locating Pin Guide Replacement | B3223 | GMNA |
| 6010370 | Folding Top Front Latch Actuator Replacement | B3225 | GMNA |
| 6010390 | Rear Compartment Lid Position Switch Replacement | B3234 | GMNA |
| 6010530 | Folding Top Front Latch Replacement | B3239 | GMNA |
| 6010530 | Folding Top Front Latch Replacement | C228510 | Holden Australia |
| 6010530 | Folding Top Front Latch Replacement | C228560 | Holden Australia |
| 6010530 | Folding Top Front Latch Replacement | C228610 | Holden Australia |
| 6010530 | Folding Top Front Latch Replacement | C228510 | Holden New Zealand |
| 6010640 | Folding Top Front Latch Striker Replacement | B3245 | GMNA |
| 6010640 | Folding Top Front Latch Striker Replacement | B9985 | GMNA |
| 6010660 | Folding Top Header Latch Hydraulic Cylinder Replacement | B3246 | GMNA |
| 6010660 | Folding Top Header Latch Hydraulic Cylinder Replacement | C226210 | Holden Australia |
| 6010660 | Folding Top Header Latch Hydraulic Cylinder Replacement | C226220 | Holden Australia |
| 6010660 | Folding Top Header Latch Hydraulic Cylinder Replacement | C226400 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6010660 | Folding Top Header Latch Hydraulic Cylinder Replacement | C226500 | Holden Australia |
| 6010660 | Folding Top Header Latch Hydraulic Cylinder Replacement | C226600 | Holden Australia |
| 6010680 | Folding Top Front Latch Handle Replacement | B3247 | GMNA |
| 6010700 | Folding Top Assist Handle Replacement | B3248 | GMNA |
| 6010700 | Folding Top Assist Handle Replacement | B3260 | GMNA |
| 6010700 | Folding Top Assist Handle Replacement | B3261 | GMNA |
| 6010720 | Folding Top Number 1 Bow Garnish Molding Replacement | B3249 | GMNA |
| 6010740 | Folding Top Side Rail Garnish Molding Replacement | B3251 | GMNA |
| 6010760 | Folding Top Number 1 Bow Replacement | B3280 | GMNA |
| 6010780 | Folding Top Number 2 Bow Replacement | B3300 | GMNA |
| 6010800 | Folding Top Number 3 Bow Replacement | B3320 | GMNA |
| 6010820 | Folding Top Number 4 Bow Replacement | B3340 | GMNA |
| 6010840 | Folding Top Number 5 Bow Replacement | B3350 | GMNA |
| 6010860 | Folding Top Counterbalance Spring Replacement | B3358 | GMNA |
| 6010880 | Folding Top Cover Side Tension Cable Replacement | B3360 | GMNA |
| 6010880 | Folding Top Cover Side Tension Cable Replacement | B9979 | GMNA |
| 6010880 | Folding Top Cover Side Tension Cable Replacement | C226000 | Holden Australia |
| 6010880 | Folding Top Cover Side Tension Cable Replacement | C226010 | Holden Australia |
| 6010880 | Folding Top Cover Side Tension Cable Replacement | C226020 | Holden Australia |
| 6010880 | Folding Top Cover Side Tension Cable Replacement | C226000 | Holden New Zealand |
| 6010930 | Folding Top Cover Front Side Tension Cable Replacement | | |
| 6010950 | Folding Top Side Rail Link Replacement | B3375 | GMNA |
| 6011000 | Folding Top Side Rail Assembly Replacement | B3380 | GMNA |
| 6011000 | Folding Top Side Rail Assembly Replacement | B3381 | GMNA |
| 6011000 | Folding Top Side Rail Assembly Replacement | B3390 | GMNA |
| 6011000 | Folding Top Side Rail Assembly Replacement | B3400 | GMNA |
| 6011000 | Folding Top Side Rail Assembly Replacement | B3401 | GMNA |
| 6011110 | Folding Top Cylinder Replacement | B3420 | GMNA |
| 6011110 | Folding Top Cylinder Replacement | C225300 | Holden Australia |
| 6011110 | Folding Top Cylinder Replacement | C225310 | Holden Australia |
| 6011110 | Folding Top Cylinder Replacement | C225320 | Holden Australia |
| 6011110 | Folding Top Cylinder Replacement | C225300 | Holden New Zealand |
| 6011160 | Folding Top Cylinder Hose Replacement | B3442 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6011160 | Folding Top Cylinder Hose Replacement | C225100 | Holden Australia |
| 6011160 | Folding Top Cylinder Hose Replacement | C225100 | Holden New Zealand |
| 6011180 | Folding Top Control Module Replacement | B3446 | GMNA |
| 6011200 | Folding Top Motor Replacement | B3459 | GMNA |
| 6011200 | Folding Top Motor Replacement | C226410 | Holden Australia |
| 6011200 | Folding Top Motor Replacement | C226420 | Holden Australia |
| 6011200 | Folding Top Motor Replacement | C226400 | Holden New Zealand |
| 6011200 | Folding Top Motor Replacement | C226410 | Holden New Zealand |
| 6011200 | Folding Top Motor Replacement | C226420 | Holden New Zealand |
| 6011200 | Folding Top Motor Replacement | N411320 | Holden New Zealand |
| 6011220 | Folding Top Pump with Motor Replacement | B3460 | GMNA |
| 6011220 | Folding Top Pump with Motor Replacement | B3480 | GMNA |
| 6011220 | Folding Top Pump with Motor Replacement | N247500 | Holden Australia |
| 6011220 | Folding Top Pump with Motor Replacement | N247500 | Holden New Zealand |
| 6011260 | Folding Top Stowage Compartment Lid Glare Shield Replacement | B3556 | GMNA |
| 6011280 | Folding Top Quarter Outer Drain Panel Replacement | B3561 | GMNA |
| 6011300 | Folding Top Frame Removal and Installation | B3579 | GMNA |
| 6011300 | Folding Top Frame Removal and Installation | C100390 | Holden Australia |
| 6011300 | Folding Top Frame Removal and Installation | C100390 | Holden New Zealand |
| 6011320 | Folding Top Front Panel Replacement | B3588 | GMNA |
| 6011340 | Folding Top Rear Panel Replacement | B3589 | GMNA |
| 6011360 | Folding Top Cover Replacement | B3590 | GMNA |
| 6011360 | Folding Top Cover Replacement | B9863 | GMNA |
| 6011360 | Folding Top Cover Replacement | B9989 | GMNA |
| 6011360 | Folding Top Cover Replacement | T6578 | GMNA |
| 6011360 | Folding Top Cover Replacement | C100360 | Holden Australia |
| 6011360 | Folding Top Cover Replacement | C100375 | Holden Australia |
| 6011360 | Folding Top Cover Replacement | C100380 | Holden Australia |
| 6011360 | Folding Top Cover Replacement | C100420 | Holden Australia |
| 6011360 | Folding Top Cover Replacement | C100430 | Holden Australia |
| 6011360 | Folding Top Cover Replacement | C100360 | Holden New Zealand |
| 6011360 | Folding Top Cover Replacement | C100375 | Holden New Zealand |
| 6011360 | Folding Top Cover Replacement | C100380 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6011380 | Folding Top Stowage Compartment Boot Replacement | B3610 | GMNA |
| 6011380 | Folding Top Stowage Compartment Boot Replacement | B9969 | GMNA |
| 6011400 | Folding Top Rear Latch Replacement | B3619 | GMNA |
| 6011400 | Folding Top Rear Latch Replacement | B3620 | GMNA |
| 6011420 | Folding Top Stowage Compartment Lid Latch Replacement | B3650 | GMNA |
| 6011440 | Folding Top Stowage Compartment Lid Latch Striker Replacement | B3660 | GMNA |
| 6011440 | Folding Top Stowage Compartment Lid Latch Striker Replacement | C205700 | Holden Australia |
| 6011440 | Folding Top Stowage Compartment Lid Latch Striker Replacement | C228300 | Holden Australia |
| 6011440 | Folding Top Stowage Compartment Lid Latch Striker Replacement | C228400 | Holden Australia |
| 6011440 | Folding Top Stowage Compartment Lid Latch Striker Replacement | C228300 | Holden New Zealand |
| 6011440 | Folding Top Stowage Compartment Lid Latch Striker Replacement | C228400 | Holden New Zealand |
| 6011520 | Folding Top Stowage Compartment Lid Protector Replacement | B3700 | GMNA |
| 6011540 | Folding Top Stowage Compartment Closeout Panel Hinge Replacement | B3701 | GMNA |
| 6011560 | Roof Retractable Position Sensor Replacement | B3708 | GMNA |
| 6011580 | Roof Retractable Luggage Shade Detection Sensor Replacement | B3709 | GMNA |
| 6011600 | Folding Top Stowage Compartment Lid Replacement | | |
| 6011740 | Folding Top Stowage Compartment Extension Outer Panel Replacement | B3716 | GMNA |
| 6011780 | Folding Top Storage Compartment Closeout Panel Adjustment - Front | | |
| 6011800 | Folding Top Stowage Compartment Front Outer Closeout Panel Adjustment | | |
| 6011820 | Folding Top Stowage Compartment Panel Folding Actuator Replacement | B3745 | GMNA |
| 6011840 | Folding Top Stowage Compartment Lid Release Switch Replacement | B3749 | GMNA |
| 6011860 | Roof Retractable Panel Stowage Compartment Lid Cylinder Replacement - Upper | B3755 | GMNA |
| 6011880 | Roof Retractable Panel Stowage Compartment Lid Cylinder Replacement - Rear | B3756 | GMNA |
| 6011900 | Roof Retractable Panel Stowage Compartment Lid Cylinder Replacement - Rear Lower | B3757 | GMNA |
| 6011920 | Folding Top Stowage Compartment Lid Strut Replacement | B3760 | GMNA |
| 6011920 | Folding Top Stowage Compartment Lid Strut Replacement | B3761 | GMNA |
| 6011970 | Roof Retractable Panel Stowage Compartment Lid Cylinder Replacement | B3762 | GMNA |
| 6011970 | Roof Retractable Panel Stowage Compartment Lid Cylinder Replacement | C205800 | Holden Australia |
| 6011970 | Roof Retractable Panel Stowage Compartment Lid Cylinder Replacement | C205810 | Holden Australia |
| 6011970 | Roof Retractable Panel Stowage Compartment Lid Cylinder Replacement | C205820 | Holden Australia |
| 6011970 | Roof Retractable Panel Stowage Compartment Lid Cylinder Replacement | C205800 | Holden New Zealand |
| 6011990 | Roof Retractable Stowage Compartment Closeout Panel Actuator Cable Replacement | B3763 | GMNA |
| 6012010 | Folding Top Stowage Compartment Lid Hinge Replacement | B3765 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6012030 | Folding Top Replacement | B3774 | GMNA |
| 6012030 | Folding Top Replacement | C400400 | Holden Australia |
| 6012030 | Folding Top Replacement | C400400 | Holden New Zealand |
| 6012032 | Folding Top Adjustment | B3980 | GMNA |
| 6012032 | Folding Top Adjustment | B9982 | GMNA |
| 6012032 | Folding Top Adjustment | B9988 | GMNA |
| 6012032 | Folding Top Adjustment | C225200 | Holden Australia |
| 6012032 | Folding Top Adjustment | C225200 | Holden New Zealand |
| 6012100 | Folding Top Rear Seal Replacement | C1015 | GMNA |
| 6012120 | Folding Top Side Front Weatherstrip Replacement | C1016 | GMNA |
| 6012140 | Folding Top Front Weatherstrip Replacement | C1019 | GMNA |
| 6012140 | Folding Top Front Weatherstrip Replacement | C100330 | Holden Australia |
| 6012280 | Folding Top Side Rear Weatherstrip Replacement | C1430 | GMNA |
| 6012330 | Folding Top Switch Replacement | N2233 | GMNA |
| 6012330 | Folding Top Switch Replacement | N000553 | Holden Australia |
| 6012330 | Folding Top Switch Replacement | N000556 | Holden Australia |
| 6012330 | Folding Top Switch Replacement | N244500 | Holden Australia |
| 6012330 | Folding Top Switch Replacement | N410520 | Holden Australia |
| 6012330 | Folding Top Switch Replacement | N410810 | Holden Australia |
| 6012330 | Folding Top Switch Replacement | N410820 | Holden Australia |
| 6012330 | Folding Top Switch Replacement | N244500 | Holden New Zealand |
| 6012350 | Folding Top Position Switch Replacement - Number 5 Bow | N2238 | GMNA |
| 6012400 | Folding Top Front Latch Position Sensor Switch Replacement | N2240 | GMNA |
| 6012420 | Folding Top Front Locating Pin Position Switch Replacement | N2241 | GMNA |
| 6012440 | Roof Retractable Opening Position Switch Replacement | N2242 | GMNA |
| 6012460 | Rear Compartment Lid Pulldown Actuator Replacement | N3272 | GMNA |
| 6020060 | Luggage Carrier Side Rail Replacement | B2943 | GMNA |
| 6020060 | Luggage Carrier Side Rail Replacement | B9785 | GMNA |
| 6020060 | Luggage Carrier Side Rail Replacement | B9795 | GMNA |
| 6020060 | Luggage Carrier Side Rail Replacement | B9796 | GMNA |
| 6020060 | Luggage Carrier Side Rail Replacement | B2943 | Holden Australia |
| 6020060 | Luggage Carrier Side Rail Replacement | C432670 | Holden Australia |
| 6020060 | Luggage Carrier Side Rail Replacement | C829000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6020060 | Luggage Carrier Side Rail Replacement | C829000 | Holden New Zealand |
| 6020060 | Luggage Carrier Side Rail Replacement | 9711500 | GMK Overseas |
| 6020060 | Luggage Carrier Side Rail Replacement | 9713500 | GMK Overseas |
| 6020140 | Luggage Carrier Replacement | A2745 | GMNA |
| 6020140 | Luggage Carrier Replacement | A2750 | GMNA |
| 6020140 | Luggage Carrier Replacement | B2946 | GMNA |
| 6020140 | Luggage Carrier Replacement | B2947 | GMNA |
| 6020140 | Luggage Carrier Replacement | R2320 | GMNA |
| 6020140 | Luggage Carrier Replacement | R2360 | GMNA |
| 6020140 | Luggage Carrier Replacement | R2380 | GMNA |
| 6020140 | Luggage Carrier Replacement | R2390 | GMNA |
| 6020140 | Luggage Carrier Replacement | R9752 | GMNA |
| 6020140 | Luggage Carrier Replacement | B2944 | Holden Australia |
| 6020140 | Luggage Carrier Replacement | C828000 | Holden Australia |
| 6020140 | Luggage Carrier Replacement | C828500 | Holden Australia |
| 6020140 | Luggage Carrier Replacement | C828000 | Holden New Zealand |
| 6020140 | Luggage Carrier Replacement | C828500 | Holden New Zealand |
| 6020160 | Luggage Carrier Side Rear Rail Cap Replacement | B2948 | GMNA |
| 6020180 | Luggage Carrier Side Rail Front Finish Cover Replacement | B2949 | GMNA |
| 6020180 | Luggage Carrier Side Rail Front Finish Cover Replacement | 9713600 | GMK Overseas |
| 6020200 | Ladder Rack Replacement | B2950 | GMNA |
| 6020300 | Luggage Carrier Cross Rail Replacement | B2955 | GMNA |
| 6020300 | Luggage Carrier Cross Rail Replacement | C443900 | Holden Australia |
| 6020300 | Luggage Carrier Cross Rail Replacement | R100100 | Holden Australia |
| 6020300 | Luggage Carrier Cross Rail Replacement | R9300 | Holden Australia |
| 6020300 | Luggage Carrier Cross Rail Replacement | R100100 | Holden New Zealand |
| 6020320 | Luggage Carrier Side Rail Rear Finish Cover Replacement | B2956 | GMNA |
| 6020340 | Luggage Carrier Rear Rail Replacement | B2957 | GMNA |
| 6020340 | Luggage Carrier Rear Rail Replacement | B3379 | GMNA |
| 6030030 | Roof Lift Off Panel Replacement | B2298 | GMNA |
| 6030032 | Roof Lift Off Panel Adjustment | B2297 | GMNA |
| 6030050 | Roof Lift Off Panel/Window Reveal Molding Replacement | B2302 | GMNA |
| 6030070 | Front Side Door Window Upper Weatherstrip Replacement | B2307 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6030240 | Roof Lift Off Panel/Window Latch Handle Replacement | B2369 | GMNA |
| 6030260 | Roof Lift Off Panel/Window Rear Latch Replacement | B2370 | GMNA |
| 6030280 | Roof Lift Off Panel/Window Rear Locator Replacement | B2371 | GMNA |
| 6030300 | Roof Lift Off Panel/Window Rear Locating Pin Replacement | B2372 | GMNA |
| 6030320 | Roof Lift Off Panel/Window Front Striker Replacement | B2373 | GMNA |
| 6030340 | Roof Lift Off Panel/Window Rear Striker Replacement | B2374 | GMNA |
| 6040030 | Roof Stationary Window Replacement | B2180 | GMNA |
| 6040050 | Sunroof Air Deflector Cover Replacement | B2229 | GMNA |
| 6040050 | Sunroof Air Deflector Cover Replacement | C242740 | Holden Australia |
| 6040070 | Sunroof Air Deflector Replacement | B2230 | GMNA |
| 6040070 | Sunroof Air Deflector Replacement | B9953 | GMNA |
| 6040070 | Sunroof Air Deflector Replacement | 8820800 | GMK Domestic |
| 6040070 | Sunroof Air Deflector Replacement | A504150 | Holden Australia |
| 6040070 | Sunroof Air Deflector Replacement | B2230 | Holden Australia |
| 6040070 | Sunroof Air Deflector Replacement | C000580 | Holden Australia |
| 6040070 | Sunroof Air Deflector Replacement | C000647 | Holden Australia |
| 6040070 | Sunroof Air Deflector Replacement | A504150 | Holden New Zealand |
| 6040070 | Sunroof Air Deflector Replacement | C000580 | Holden New Zealand |
| 6040070 | Sunroof Air Deflector Replacement | 9725500 | GMK Overseas |
| 6040070 | Sunroof Air Deflector Replacement | 9726700 | GMK Overseas |
| 6040230 | Sunroof Frame Replacement - Upper | B2722 | GMNA |
| 6040250 | Sunroof Frame Replacement - Lower | B2723 | GMNA |
| 6040270 | Sunroof Frame Replacement | B2278 | GMNA |
| 6040270 | Sunroof Frame Replacement | B2724 | GMNA |
| 6040270 | Sunroof Frame Replacement | B9808 | GMNA |
| 6040270 | Sunroof Frame Replacement | B9876 | GMNA |
| 6040270 | Sunroof Frame Replacement | B2724 | Holden Australia |
| 6040270 | Sunroof Frame Replacement | 9725400 | GMK Overseas |
| 6040290 | Sunroof Housing Replacement | B2725 | GMNA |
| 6040290 | Sunroof Housing Replacement | 8821000 | GMK Domestic |
| 6040290 | Sunroof Housing Replacement | 8821002 | GMK Domestic |
| 6040310 | Roof Stationary Window Frame Replacement | B2726 | GMNA |
| 6040360 | Sunroof Window Replacement | B2760 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6040360 | Sunroof Window Replacement | B2760 | Holden Australia |
| 6040360 | Sunroof Window Replacement | 9725200 | GMK Overseas |
| 6040362 | Sunroof Window Height and Opening Fit Adjustment | B2720 | GMNA |
| 6040362 | Sunroof Window Height and Opening Fit Adjustment | B9951 | GMNA |
| 6040362 | Sunroof Window Height and Opening Fit Adjustment | B9954 | GMNA |
| 6040362 | Sunroof Window Height and Opening Fit Adjustment | 8820400 | GMK Domestic |
| 6040362 | Sunroof Window Height and Opening Fit Adjustment | B2720 | Holden Australia |
| 6040380 | Sunroof Window Replacement - Front | B2762 | GMNA |
| 6040400 | Sunroof Window Replacement - Rear | B2764 | GMNA |
| 6040420 | Sunroof Window Seal Replacement - Front | B2769 | GMNA |
| 6040420 | Sunroof Window Seal Replacement - Front | 9726400 | GMK Overseas |
| 6040440 | Sunroof Window Seal Replacement | B2700 | GMNA |
| 6040440 | Sunroof Window Seal Replacement | B2770 | GMNA |
| 6040440 | Sunroof Window Seal Replacement | T5824 | GMNA |
| 6040440 | Sunroof Window Seal Replacement | T5825 | GMNA |
| 6040440 | Sunroof Window Seal Replacement | T5826 | GMNA |
| 6040440 | Sunroof Window Seal Replacement | A504350 | Holden New Zealand |
| 6040440 | Sunroof Window Seal Replacement | 9725600 | GMK Overseas |
| 6040460 | Sunroof Window Seal Replacement - Rear | B2771 | GMNA |
| 6040480 | Sunroof Window Seal Replacement - Outer | B2772 | GMNA |
| 6040500 | Sunroof Window Seal Replacement - Inner | B2773 | GMNA |
| 6040500 | Sunroof Window Seal Replacement - Inner | 8822000 | GMK Domestic |
| 6040520 | Sunroof Window Rear Seal Replacement - Rear Window Side | B2774 | GMNA |
| 6040540 | Sunroof Window Front Seal Replacement - Front Window Rear | B2775 | GMNA |
| 6040560 | Sunroof Module Assembly Replacement | B2780 | GMNA |
| 6040560 | Sunroof Module Assembly Replacement | A504100 | Holden Australia |
| 6040560 | Sunroof Module Assembly Replacement | A504100 | Holden New Zealand |
| 6040580 | Sunroof Actuator Trim Plate Replacement | B2784 | GMNA |
| 6040690 | Sunroof Window Front Track Assembly Replacement | B2826 | GMNA |
| 6040690 | Sunroof Window Front Track Assembly Replacement | B2845 | GMNA |
| 6040690 | Sunroof Window Front Track Assembly Replacement | B2846 | GMNA |
| 6040710 | Sunroof Window Rear Track Assembly Replacement | B2827 | GMNA |
| 6040730 | Sunroof Window Track Front Extension Replacement | B2828 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6040750 | Sunroof Window Track Rear Extension Replacement | B2829 | GMNA |
| 6040770 | Sunroof Panel/Window Front Guide Replacement | B2832 | GMNA |
| 6040790 | Sunroof Panel/Window Rear Guide Replacement | B2833 | GMNA |
| 6040810 | Sunroof Sunshade Guide Replacement | B2836 | GMNA |
| 6040830 | Sunroof Panel/Window Guide Replacement | B2839 | GMNA |
| 6040830 | Sunroof Panel/Window Guide Replacement | B9942 | GMNA |
| 6040830 | Sunroof Panel/Window Guide Replacement | A504200 | Holden Australia |
| 6040830 | Sunroof Panel/Window Guide Replacement | A504200 | Holden New Zealand |
| 6040850 | Sunroof Panel/Window Guide Replacement - Right Side | B2840 | GMNA |
| 6040870 | Sunroof Panel/Window Guide Replacement - Left Side | B2841 | GMNA |
| 6040922 | Sunroof Drain Inspection and Cleaning | B2849 | GMNA |
| 6040970 | Sunroof Housing Drain Gutter Replacement | B2851 | GMNA |
| 6040990 | Sunroof Housing Front Drain Hose Replacement | B2852 | GMNA |
| 6040990 | Sunroof Housing Front Drain Hose Replacement | B9903 | GMNA |
| 6040990 | Sunroof Housing Front Drain Hose Replacement | 8821200 | GMK Domestic |
| 6040990 | Sunroof Housing Front Drain Hose Replacement | A000339 | Holden Australia |
| 6040990 | Sunroof Housing Front Drain Hose Replacement | B2852 | Holden Australia |
| 6040990 | Sunroof Housing Front Drain Hose Replacement | C248500 | Holden Australia |
| 6040990 | Sunroof Housing Front Drain Hose Replacement | 9726100 | GMK Overseas |
| 6040990 | Sunroof Housing Front Drain Hose Replacement | 9726900 | GMK Overseas |
| 6041010 | Sunroof Housing Rear Drain Hose Replacement | B2853 | GMNA |
| 6041010 | Sunroof Housing Rear Drain Hose Replacement | B9973 | GMNA |
| 6041010 | Sunroof Housing Rear Drain Hose Replacement | C9819 | GMNA |
| 6041010 | Sunroof Housing Rear Drain Hose Replacement | C9820 | GMNA |
| 6041010 | Sunroof Housing Rear Drain Hose Replacement | B2853 | Holden Australia |
| 6041010 | Sunroof Housing Rear Drain Hose Replacement | 9726200 | GMK Overseas |
| 6041030 | Sunroof Panel/Window Garnish Molding Replacement | B2858 | GMNA |
| 6041050 | Sunroof Panel Side Opening Closeout Cover Replacement | B2859 | GMNA |
| 6041070 | Sunroof Opening Trim Finish Lace Replacement | B2860 | GMNA |
| 6041090 | Sunroof Front Trim Cover Replacement | B2861 | GMNA |
| 6041190 | Sunroof Sunshade Cable Assembly Replacement | B2895 | GMNA |
| 6041230 | Sunroof Sunshade Replacement | B2900 | GMNA |
| 6041230 | Sunroof Sunshade Replacement | B3075 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6041230 | Sunroof Sunshade Replacement | B3076 | GMNA |
| 6041230 | Sunroof Sunshade Replacement | B3110 | GMNA |
| 6041230 | Sunroof Sunshade Replacement | B3111 | GMNA |
| 6041230 | Sunroof Sunshade Replacement | 8820402 | GMK Domestic |
| 6041230 | Sunroof Sunshade Replacement | B2900 | Holden Australia |
| 6041230 | Sunroof Sunshade Replacement | B291000 | Holden Australia |
| 6041230 | Sunroof Sunshade Replacement | B291100 | Holden Australia |
| 6041230 | Sunroof Sunshade Replacement | A504400 | Holden New Zealand |
| 6041230 | Sunroof Sunshade Replacement | B291000 | Holden New Zealand |
| 6041230 | Sunroof Sunshade Replacement | 9726800 | GMK Overseas |
| 6041280 | Sunroof Window Weatherstrip Replacement | C1440 | GMNA |
| 6041280 | Sunroof Window Weatherstrip Replacement | C1460 | GMNA |
| 6041280 | Sunroof Window Weatherstrip Replacement | 8820500 | GMK Domestic |
| 6041280 | Sunroof Window Weatherstrip Replacement | A504350 | Holden Australia |
| 6041320 | Sunroof Opening Position Switch Replacement | N2459 | GMNA |
| 6041340 | Sunroof Switch Replacement | N1988 | GMNA |
| 6041340 | Sunroof Switch Replacement | N2460 | GMNA |
| 6041340 | Sunroof Switch Replacement | 8821400 | GMK Domestic |
| 6041340 | Sunroof Switch Replacement | N526010 | Holden Australia |
| 6041340 | Sunroof Switch Replacement | N526010 | Holden New Zealand |
| 6041340 | Sunroof Switch Replacement | 9726500 | GMK Overseas |
| 6041360 | Sunroof Sunshade Switch Replacement | N2462 | GMNA |
| 6041380 | Sunroof Tilt Position Switch Replacement | N2463 | GMNA |
| 6041380 | Sunroof Tilt Position Switch Replacement | 8821900 | GMK Domestic |
| 6041430 | Sunroof Sunshade Motor Replacement | N3358 | GMNA |
| 6041430 | Sunroof Sunshade Motor Replacement | C242515 | Holden Australia |
| 6041450 | Sunroof Window Motor Replacement | N3359 | GMNA |
| 6041450 | Sunroof Window Motor Replacement | N3360 | GMNA |
| 6041450 | Sunroof Window Motor Replacement | A504250 | Holden Australia |
| 6041450 | Sunroof Window Motor Replacement | N3360 | Holden Australia |
| 6041450 | Sunroof Window Motor Replacement | A504250 | Holden New Zealand |
| 6041450 | Sunroof Window Motor Replacement | 9725100 | GMK Overseas |
| 6041500 | Sunroof Actuator Motor Replacement | N3363 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6041580 | Sunroof Control Module Replacement | N4868 | GMNA |
| 6041580 | Sunroof Control Module Replacement | 8821300 | GMK Domestic |
| 6041580 | Sunroof Control Module Replacement | 9725300 | GMK Overseas |
| 6410010 | Hood Ajar Indicator Switch Replacement | N2311 | GMNA |
| 6410010 | Hood Ajar Indicator Switch Replacement | N2382 | GMNA |
| 6410010 | Hood Ajar Indicator Switch Replacement | N9560 | GMNA |
| 6410010 | Hood Ajar Indicator Switch Replacement | N216550 | Holden Australia |
| 6410010 | Hood Ajar Indicator Switch Replacement | N216550 | Holden New Zealand |
| 6410010 | Hood Ajar Indicator Switch Replacement | 5862900 | GMK Overseas |
| 6410010 | Hood Ajar Indicator Switch Replacement | 9282300 | GMK Overseas |
| 6410030 | LED Indicator Replacement - Vehicle Security System | | |
| 6410040 | Theft Deterrent Module Replacement | 8330600 | GMK Overseas |
| 6410070 | Key with Integrated Transmitter Replacement | N9628 | GMNA |
| 6410070 | Key with Integrated Transmitter Replacement | R4489 | GMNA |
| 6410070 | Key with Integrated Transmitter Replacement | 9681600 | GMK Overseas |
| 6410070 | Key with Integrated Transmitter Replacement | 968160A | GMK Overseas |
| 6410070 | Key with Integrated Transmitter Replacement | 968160B | GMK Overseas |
| 6420010 | Side Object Sensor Bracket Replacement | B0649 | GMNA |
| 6420020 | Front Parking Assist Alarm Sensor Bracket Replacement | B0648 | GMNA |
| 6420030 | Front Object Alarm Sensor Housing Replacement | B0650 | GMNA |
| 6420050 | Rear Object Sensor Housing Replacement | B0651 | GMNA |
| 6420060 | Rear Parking Assist Alarm Sensor Bracket Replacement | | |
| 6420100 | Front View Camera Image Display Module Replacement | A000327 | Holden Australia |
| 6420100 | Front View Camera Image Display Module Replacement | R005500 | Holden Australia |
| 6420100 | Front View Camera Image Display Module Replacement | R005600 | Holden Australia |
| 6420100 | Front View Camera Image Display Module Replacement | A000327 | Holden New Zealand |
| 6420100 | Front View Camera Image Display Module Replacement | R005500 | Holden New Zealand |
| 6420100 | Front View Camera Image Display Module Replacement | R005600 | Holden New Zealand |
| 6420120 | Front View Camera Replacement | R3112 | GMNA |
| 6420120 | Front View Camera Replacement | R3120 | GMNA |
| 6420120 | Front View Camera Replacement | 8110120 | GMK Domestic |
| 6420140 | Front View Camera Switch Replacement | R3113 | GMNA |
| 6420160 | Rearview Camera Image Display Module Replacement | R3114 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6420160 | Rearview Camera Image Display Module Replacement | N770100 | Holden Australia |
| 6420160 | Rearview Camera Image Display Module Replacement | N770110 | Holden Australia |
| 6420160 | Rearview Camera Image Display Module Replacement | R9294 | Holden Australia |
| 6420160 | Rearview Camera Image Display Module Replacement | N770100 | Holden New Zealand |
| 6420160 | Rearview Camera Image Display Module Replacement | N770110 | Holden New Zealand |
| 6420180 | Rearview Driver Information Camera Replacement | R3115 | GMNA |
| 6420180 | Rearview Driver Information Camera Replacement | 8010700 | GMK Domestic |
| 6420180 | Rearview Driver Information Camera Replacement | 9671800 | GMK Overseas |
| 6420200 | Information Center Telltale Assembly Replacement | R4110 | GMNA |
| 6420220 | Rear Object Alarm Control Module Replacement | R4111 | GMNA |
| 6420220 | Rear Object Alarm Control Module Replacement | N000798 | Holden New Zealand |
| 6420220 | Rear Object Alarm Control Module Replacement | 4781700 | GMK Overseas |
| 6420240 | Front and Rear Object Alarm Module Replacement | R4112 | GMNA |
| 6420260 | Front Parking Assist Alarm Sensor Replacement | R4113 | GMNA |
| 6420260 | Front Parking Assist Alarm Sensor Replacement | 6424800 | GMK Domestic |
| 6420260 | Front Parking Assist Alarm Sensor Replacement | N770150 | Holden Australia |
| 6420260 | Front Parking Assist Alarm Sensor Replacement | N770150 | Holden New Zealand |
| 6420260 | Front Parking Assist Alarm Sensor Replacement | 4782100 | GMK Overseas |
| 6420280 | Rear Parking Assist Alarm Sensor Replacement | R4114 | GMNA |
| 6420280 | Rear Parking Assist Alarm Sensor Replacement | N770000 | Holden Australia |
| 6420280 | Rear Parking Assist Alarm Sensor Replacement | N770000 | Holden New Zealand |
| 6420280 | Rear Parking Assist Alarm Sensor Replacement | 4781800 | GMK Overseas |
| 6420280 | Rear Parking Assist Alarm Sensor Replacement | 478180A | GMK Overseas |
| 6420280 | Rear Parking Assist Alarm Sensor Replacement | 478180B | GMK Overseas |
| 6420300 | Rear Parking Assist Alarm Control Module Switch Replacement | R4115 | GMNA |
| 6420300 | Rear Parking Assist Alarm Control Module Switch Replacement | RT021 | GMNA |
| 6420300 | Rear Parking Assist Alarm Control Module Switch Replacement | N000798 | Holden Australia |
| 6420300 | Rear Parking Assist Alarm Control Module Switch Replacement | R9192 | Holden Australia |
| 6420300 | Rear Parking Assist Alarm Control Module Switch Replacement | 4782500 | GMK Overseas |
| 6420320 | Side Object Sensor Replacement | R4116 | GMNA |
| 6420340 | Rear Object Alarm Indicator Replacement | R4117 | GMNA |
| 6420360 | Vehicle Direction Alert Alarm Warning Module Replacement | R4118 | GMNA |
| 6420380 | Side Object Sensing Alert Module Replacement | R4119 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6420400 | Advance Parking Assist Side Object Alarm Module Replacement | R4120 | GMNA |
| 6420400 | Advance Parking Assist Side Object Alarm Module Replacement | 4782300 | GMK Overseas |
| 6420420 | Pedestrian Impact Detection Sensor Replacement - Front Upper Beam | R4130 | GMNA |
| 6420440 | Pedestrian Impact Detection Sensor Replacement - Rear Upper Beam | R4131 | GMNA |
| 6420460 | Active Hood Hinge Actuator Replacement | R4132 | GMNA |
| 6420480 | Pedestrian Impact Detection Module Replacement | R4133 | GMNA |
| 6421100 | Active Safety Control Module Replacement | | |
| 6421200 | Forward Collision Alert Display Replacement | | |
| 6421300 | Object Detection Sensor Replacement | | |
| 6421400 | Forward Range Radar Module Replacement | | |
| 6421500 | Front Seat Lane Departure Warning Actuator Replacement | | |
| 6430030 | Keyless Entry Control Module Replacement | R3012 | GMNA |
| 6430030 | Keyless Entry Control Module Replacement | R3019 | GMNA |
| 6430030 | Keyless Entry Control Module Replacement | R4804 | GMNA |
| 6430030 | Keyless Entry Control Module Replacement | R9050 | GMNA |
| 6430030 | Keyless Entry Control Module Replacement | R905000 | Holden Australia |
| 6430030 | Keyless Entry Control Module Replacement | R9049 | Holden New Zealand |
| 6430030 | Keyless Entry Control Module Replacement | R9050 | Holden New Zealand |
| 6430030 | Keyless Entry Control Module Replacement | R905000 | Holden New Zealand |
| 6430030 | Keyless Entry Control Module Replacement | F192012 | GMK Overseas |
| 6430050 | Ignition Lock Key Transmitter Antenna Replacement - Instrument Panel | R3020 | GMNA |
| 6430100 | Ignition Lock Key Transmitter Antenna Replacement - Rear Compartment | R3022 | GMNA |
| 6430120 | Ignition Lock Key Transmitter Antenna Replacement - Right Side | R3023 | GMNA |
| 6430140 | Ignition Lock Key Transmitter Antenna Replacement - Left Side | R3024 | GMNA |
| 6430160 | Ignition Lock Key Transmitter Antenna Replacement - Floor Console | R3025 | GMNA |
| 6430180 | Ignition Lock Key Transmitter Antenna Replacement - Headliner | R3026 | GMNA |
| 6430200 | Ignition Lock Key Transmitter Antenna Replacement - Rear Bumper Fascia | R3027 | GMNA |
| 6430200 | Ignition Lock Key Transmitter Antenna Replacement - Rear Bumper Fascia | 6430200 | GMK Overseas |
| 6430220 | Ignition Lock Key Transmitter Antenna Replacement | R3028 | GMNA |
| 6430240 | Remote Control Door Lock and Theft Deterrent Receiver Replacement | N4797 | GMNA |
| 6430240 | Remote Control Door Lock and Theft Deterrent Receiver Replacement | R3014 | GMNA |
| 6430240 | Remote Control Door Lock and Theft Deterrent Receiver Replacement | R4479 | GMNA |
| 6430240 | Remote Control Door Lock and Theft Deterrent Receiver Replacement | R9706 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6430240 | Remote Control Door Lock and Theft Deterrent Receiver Replacement | R9723 | GMNA |
| 6430240 | Remote Control Door Lock and Theft Deterrent Receiver Replacement | R9724 | GMNA |
| 6430240 | Remote Control Door Lock and Theft Deterrent Receiver Replacement | R9725 | GMNA |
| 6430240 | Remote Control Door Lock and Theft Deterrent Receiver Replacement | N764300 | Holden Australia |
| 6430240 | Remote Control Door Lock and Theft Deterrent Receiver Replacement | N764300 | Holden New Zealand |
| 6430260 | Remote Control Door Lock Receiver Replacement | C9983 | GMNA |
| 6430260 | Remote Control Door Lock Receiver Replacement | R4480 | GMNA |
| 6430260 | Remote Control Door Lock Receiver Replacement | N317720 | Holden New Zealand |
| 6430260 | Remote Control Door Lock Receiver Replacement | 9291100 | GMK Overseas |
| 6430260 | Remote Control Door Lock Receiver Replacement | 9320500 | GMK Overseas |
| 6430280 | Remote Control Door Lock and Theft Deterrent Transmitter Replacement | R4482 | GMNA |
| 6430300 | Transmitter Battery Replacement | R3013 | GMNA |
| 6430300 | Transmitter Battery Replacement | R4485 | GMNA |
| 6430300 | Transmitter Battery Replacement | S0015 | GMNA |
| 6430300 | Transmitter Battery Replacement | N506610 | Holden Australia |
| 6430300 | Transmitter Battery Replacement | R4485 | Holden Australia |
| 6430300 | Transmitter Battery Replacement | R905600 | Holden Australia |
| 6430300 | Transmitter Battery Replacement | N506610 | Holden New Zealand |
| 6430300 | Transmitter Battery Replacement | R9056 | Holden New Zealand |
| 6430300 | Transmitter Battery Replacement | R905600 | Holden New Zealand |
| 6430300 | Transmitter Battery Replacement | R9057 | Holden New Zealand |
| 6430320 | Remote Control Door Lock Transmitter Replacement | R4490 | GMNA |
| 6430320 | Remote Control Door Lock Transmitter Replacement | N000372 | Holden Australia |
| 6430320 | Remote Control Door Lock Transmitter Replacement | R4490 | Holden Australia |
| 6430345 | Remote Control Door Lock Transmitter Programming | R4491 | GMNA |
| 6430345 | Remote Control Door Lock Transmitter Programming | C620700 | Holden Australia |
| 6430345 | Remote Control Door Lock Transmitter Programming | C620800 | Holden Australia |
| 6430345 | Remote Control Door Lock Transmitter Programming | C620900 | Holden Australia |
| 6430345 | Remote Control Door Lock Transmitter Programming | C620700 | Holden New Zealand |
| 6430345 | Remote Control Door Lock Transmitter Programming | C620800 | Holden New Zealand |
| 6430345 | Remote Control Door Lock Transmitter Programming | C620900 | Holden New Zealand |
| 6430360 | Remote Control Door Lock Receiver Antenna Replacement | R4494 | GMNA |
| 6430360 | Remote Control Door Lock Receiver Antenna Replacement | R9746 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6430360 | Remote Control Door Lock Receiver Antenna Replacement | 8110400 | GMK Domestic |
| 6430360 | Remote Control Door Lock Receiver Antenna Replacement | 9291400 | GMK Overseas |
| 6430380 | Garage Door Opener Transmitter Replacement | 9721600 | GMK Overseas |
| 6430400 | Garage Door Opener Transmitter Pushbutton Replacement | R4653 | GMNA |
| 6430400 | Garage Door Opener Transmitter Pushbutton Replacement | 6430400 | GMK Overseas |
| 6440020 | Front Seat Belt Buckle Replacement | 8810100 | GMK Domestic |
| 6440020 | Front Seat Belt Buckle Replacement | C9190 | Holden New Zealand |
| 6440020 | Front Seat Belt Buckle Replacement | 8120100 | GMK Overseas |
| 6440020 | Front Seat Belt Buckle Replacement | 8120200 | GMK Overseas |
| 6440020 | Front Seat Belt Buckle Replacement | 8120300 | GMK Overseas |
| 6440160 | Driver or Passenger Seat Retractor Side Belt Replacement | 8120500 | GMK Overseas |
| 6440230 | Driver or Passenger Seat Shoulder Belt Guide Trim Cover Replacement | C9051 | GMNA |
| 6440230 | Driver or Passenger Seat Shoulder Belt Guide Trim Cover Replacement | 8810400 | GMK Domestic |
| 6440230 | Driver or Passenger Seat Shoulder Belt Guide Trim Cover Replacement | C451160 | Holden Australia |
| 6440230 | Driver or Passenger Seat Shoulder Belt Guide Trim Cover Replacement | 8120900 | GMK Overseas |
| 6440230 | Driver or Passenger Seat Shoulder Belt Guide Trim Cover Replacement | 8121100 | GMK Overseas |
| 6440250 | Driver or Passenger Seat Shoulder Belt Guide Replacement | B9867 | GMNA |
| 6440250 | Driver or Passenger Seat Shoulder Belt Guide Replacement | C9050 | GMNA |
| 6440250 | Driver or Passenger Seat Shoulder Belt Guide Replacement | C9899 | GMNA |
| 6440250 | Driver or Passenger Seat Shoulder Belt Guide Replacement | C451170 | Holden Australia |
| 6440390 | Front Seat Belt Guide Adjuster Replacement | C9082 | GMNA |
| 6440390 | Front Seat Belt Guide Adjuster Replacement | C455700 | Holden Australia |
| 6440390 | Front Seat Belt Guide Adjuster Replacement | C455750 | Holden Australia |
| 6440390 | Front Seat Belt Guide Adjuster Replacement | C455800 | Holden Australia |
| 6440390 | Front Seat Belt Guide Adjuster Replacement | C455850 | Holden Australia |
| 6440390 | Front Seat Belt Guide Adjuster Replacement | C455700 | Holden New Zealand |
| 6440390 | Front Seat Belt Guide Adjuster Replacement | C455750 | Holden New Zealand |
| 6440390 | Front Seat Belt Guide Adjuster Replacement | C455800 | Holden New Zealand |
| 6440390 | Front Seat Belt Guide Adjuster Replacement | C455850 | Holden New Zealand |
| 6440440 | Front Center Seat Belt Buckle Replacement | C9100 | GMNA |
| 6440440 | Front Center Seat Belt Buckle Replacement | C9101 | GMNA |
| 6440440 | Front Center Seat Belt Buckle Replacement | C910000 | Holden Australia |
| 6440440 | Front Center Seat Belt Buckle Replacement | C919200 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6440440 | Front Center Seat Belt Buckle Replacement | C910000 | Holden New Zealand |
| 6440460 | Front Seat Center Belt Replacement | C452310 | Holden Australia |
| 6440460 | Front Seat Center Belt Replacement | C452310 | Holden New Zealand |
| 6440470 | Child Seat Bracket Trim Cover Replacement | N5947 | GMNA |
| 6440570 | Rear Seat Shoulder Belt Guide Cover Replacement | 9428100 | GMK Overseas |
| 6440590 | Rear Seat Belt Intermediate Guide Replacement | C9178 | GMNA |
| 6440610 | Rear Seat Shoulder Belt Guide Adjuster Replacement | C9179 | GMNA |
| 6440630 | Driver or Passenger Seat Belt Replacement | C9047 | GMNA |
| 6440630 | Driver or Passenger Seat Belt Replacement | C9180 | GMNA |
| 6440630 | Driver or Passenger Seat Belt Replacement | C9181 | GMNA |
| 6440630 | Driver or Passenger Seat Belt Replacement | C000553 | Holden New Zealand |
| 6440630 | Driver or Passenger Seat Belt Replacement | NZE5524 | Holden New Zealand |
| 6440630 | Driver or Passenger Seat Belt Replacement | T681201 | Holden New Zealand |
| 6440650 | Rear Seat Buckle Side Belt Replacement | C9190 | GMNA |
| 6440650 | Rear Seat Buckle Side Belt Replacement | C9432 | GMNA |
| 6440650 | Rear Seat Buckle Side Belt Replacement | 8820100 | GMK Domestic |
| 6440650 | Rear Seat Buckle Side Belt Replacement | C452400 | Holden Australia |
| 6440650 | Rear Seat Buckle Side Belt Replacement | C452600 | Holden Australia |
| 6440650 | Rear Seat Buckle Side Belt Replacement | C9190 | Holden Australia |
| 6440650 | Rear Seat Buckle Side Belt Replacement | C919000 | Holden Australia |
| 6440650 | Rear Seat Buckle Side Belt Replacement | C452400 | Holden New Zealand |
| 6440650 | Rear Seat Buckle Side Belt Replacement | C452600 | Holden New Zealand |
| 6440650 | Rear Seat Buckle Side Belt Replacement | 8220910 | GMK Overseas |
| 6440650 | Rear Seat Buckle Side Belt Replacement | 8220920 | GMK Overseas |
| 6440700 | Rear Seat Center Shoulder Belt Replacement | C9198 | GMNA |
| 6440700 | Rear Seat Center Shoulder Belt Replacement | C452300 | Holden Australia |
| 6440700 | Rear Seat Center Shoulder Belt Replacement | C452300 | Holden New Zealand |
| 6440700 | Rear Seat Center Shoulder Belt Replacement | 9429000 | GMK Overseas |
| 6440720 | Rear Seat Retractor Side Belt Replacement | C9199 | GMNA |
| 6440740 | Rear Seat Retractor Side Belt Replacement - Right Side | C9200 | GMNA |
| 6440740 | Rear Seat Retractor Side Belt Replacement - Right Side | C452100 | Holden Australia |
| 6440740 | Rear Seat Retractor Side Belt Replacement - Right Side | C9200 | Holden Australia |
| 6440740 | Rear Seat Retractor Side Belt Replacement - Right Side | C9201 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6440740 | Rear Seat Retractor Side Belt Replacement - Right Side | C452100 | Holden New Zealand |
| 6440740 | Rear Seat Retractor Side Belt Replacement - Right Side | 8220400 | GMK Overseas |
| 6440760 | Rear Seat Retractor Side Belt Replacement - Left Side | C9201 | GMNA |
| 6440760 | Rear Seat Retractor Side Belt Replacement - Left Side | C452200 | Holden Australia |
| 6440760 | Rear Seat Retractor Side Belt Replacement - Left Side | C452200 | Holden New Zealand |
| 6440760 | Rear Seat Retractor Side Belt Replacement - Left Side | C452200A1 | Holden New Zealand |
| 6440760 | Rear Seat Retractor Side Belt Replacement - Left Side | 8220500 | GMK Overseas |
| 6440760 | Rear Seat Retractor Side Belt Replacement - Left Side | 8220600 | GMK Overseas |
| 6440760 | Rear Seat Retractor Side Belt Replacement - Left Side | 8220700 | GMK Overseas |
| 6440780 | Shoulder Belt Replacement - Rear | C9203 | GMNA |
| 6440800 | Rear Seat Center Belt Replacement | C9204 | GMNA |
| 6440800 | Rear Seat Center Belt Replacement | C452500 | Holden Australia |
| 6440800 | Rear Seat Center Belt Replacement | C452500 | Holden New Zealand |
| 6440850 | Rear Seat Center Retractor Side Belt Replacement | C9206 | GMNA |
| 6440850 | Rear Seat Center Retractor Side Belt Replacement | C920200 | Holden Australia |
| 6440850 | Rear Seat Center Retractor Side Belt Replacement | C9206 | Holden Australia |
| 6440850 | Rear Seat Center Retractor Side Belt Replacement | 8220300 | GMK Overseas |
| 6440850 | Rear Seat Center Retractor Side Belt Replacement | 8220800 | GMK Overseas |
| 6440870 | Rear Seat Center Buckle Side Belt Replacement | C9207 | GMNA |
| 6440870 | Rear Seat Center Buckle Side Belt Replacement | C9207 | Holden Australia |
| 6440870 | Rear Seat Center Buckle Side Belt Replacement | 8220100 | GMK Overseas |
| 6440910 | Rear Seat Shoulder Belt Buckle Replacement | C9209 | GMNA |
| 6440910 | Rear Seat Shoulder Belt Buckle Replacement | 8220900 | GMK Overseas |
| 6440930 | Rear Seat Belt Replacement | C9250 | GMNA |
| 6440930 | Rear Seat Belt Replacement | C9251 | GMNA |
| 6440930 | Rear Seat Belt Replacement | C9257 | GMNA |
| 6440930 | Rear Seat Belt Replacement | C9280 | GMNA |
| 6440930 | Rear Seat Belt Replacement | C452410 | Holden Australia |
| 6440930 | Rear Seat Belt Replacement | C452420 | Holden Australia |
| 6440930 | Rear Seat Belt Replacement | C452700 | Holden Australia |
| 6440930 | Rear Seat Belt Replacement | C455100 | Holden Australia |
| 6440930 | Rear Seat Belt Replacement | C593160 | Holden Australia |
| 6440930 | Rear Seat Belt Replacement | C452410 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6440930 | Rear Seat Belt Replacement | C452700 | Holden New Zealand |
| 6440930 | Rear Seat Belt Replacement | C455100 | Holden New Zealand |
| 6440950 | Seat Belt Latch Stop Installation | C9288 | GMNA |
| 6441000 | 3rd Row Center Seat Belt Replacement | C9300 | GMNA |
| 6441080 | Rear Seat Number 2 Retractor Side Belt Replacement | C9399 | GMNA |
| 6441080 | Rear Seat Number 2 Retractor Side Belt Replacement | 8220810 | GMK Overseas |
| 6441080 | Rear Seat Number 2 Retractor Side Belt Replacement | 8220930 | GMK Overseas |
| 6441080 | Rear Seat Number 2 Retractor Side Belt Replacement | 8220940 | GMK Overseas |
| 6441100 | Rear Seat Number 2 Retractor Side Belt Replacement - Right Side | C9400 | GMNA |
| 6441120 | Rear Seat Number 3 Retractor Side Belt Replacement - Right Side | C9401 | GMNA |
| 6441140 | Rear Seat Number 4 Retractor Side Belt Replacement - Right Side | C9402 | GMNA |
| 6441160 | Rear Seat Number 2 Retractor Side Belt Replacement - Left Side | C9406 | GMNA |
| 6441180 | Rear Seat Number 3 Retractor Side Belt Replacement - Left Side | C9407 | GMNA |
| 6441200 | Rear Seat Number 4 Retractor Side Belt Replacement - Left Side | C9408 | GMNA |
| 6441220 | Rear Seat Number 2 Buckle Side Belt Replacement | C9409 | GMNA |
| 6441220 | Rear Seat Number 2 Buckle Side Belt Replacement | 8221000 | GMK Overseas |
| 6441220 | Rear Seat Number 2 Buckle Side Belt Replacement | 8221100 | GMK Overseas |
| 6441230 | 3rd Row Seat Belt Buckle Replacement | | |
| 6450010 | Steering Wheel Airbag Coil Replacement | C8800 | GMNA |
| 6450010 | Steering Wheel Airbag Coil Replacement | C9727 | GMNA |
| 6450010 | Steering Wheel Airbag Coil Replacement | C9728 | GMNA |
| 6450010 | Steering Wheel Airbag Coil Replacement | N5202 | GMNA |
| 6450010 | Steering Wheel Airbag Coil Replacement | N9599 | GMNA |
| 6450010 | Steering Wheel Airbag Coil Replacement | 3322400 | GMK Domestic |
| 6450010 | Steering Wheel Airbag Coil Replacement | 6423600 | GMK Domestic |
| 6450010 | Steering Wheel Airbag Coil Replacement | M200200 | Holden Australia |
| 6450010 | Steering Wheel Airbag Coil Replacement | N202500 | Holden Australia |
| 6450010 | Steering Wheel Airbag Coil Replacement | N732128 | Holden Australia |
| 6450010 | Steering Wheel Airbag Coil Replacement | C452800 | Holden New Zealand |
| 6450010 | Steering Wheel Airbag Coil Replacement | C452800A | Holden New Zealand |
| 6450010 | Steering Wheel Airbag Coil Replacement | C452900 | Holden New Zealand |
| 6450010 | Steering Wheel Airbag Coil Replacement | C453000 | Holden New Zealand |
| 6450010 | Steering Wheel Airbag Coil Replacement | M200200 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6450010 | Steering Wheel Airbag Coil Replacement | N202500 | Holden New Zealand |
| 6450010 | Steering Wheel Airbag Coil Replacement | 8320100 | GMK Overseas |
| 6450010 | Steering Wheel Airbag Coil Replacement | T583001 | GMK Overseas |
| 6450010 | Steering Wheel Airbag Coil Replacement | T583004 | GMK Overseas |
| 6450060 | Front End Inflatable Restraint Discriminating Sensor Replacement | C8810 | GMNA |
| 6450060 | Front End Inflatable Restraint Discriminating Sensor Replacement | C8822 | GMNA |
| 6450060 | Front End Inflatable Restraint Discriminating Sensor Replacement | 8321900 | GMK Overseas |
| 6450080 | Inflatable Restraint Remote Impact Sensor Replacement | C8811 | GMNA |
| 6450100 | Inflatable Restraint Front End Sensor Replacement - Right Side | C8812 | GMNA |
| 6450100 | Inflatable Restraint Front End Sensor Replacement - Right Side | C8812 | Holden Australia |
| 6450100 | Inflatable Restraint Front End Sensor Replacement - Right Side | N506900 | Holden Australia |
| 6450100 | Inflatable Restraint Front End Sensor Replacement - Right Side | N506960 | Holden Australia |
| 6450100 | Inflatable Restraint Front End Sensor Replacement - Right Side | N506900 | Holden New Zealand |
| 6450100 | Inflatable Restraint Front End Sensor Replacement - Right Side | N506960 | Holden New Zealand |
| 6450120 | Inflatable Restraint Front End Sensor Replacement - Left Side | C8813 | GMNA |
| 6450120 | Inflatable Restraint Front End Sensor Replacement - Left Side | C8813 | Holden Australia |
| 6450120 | Inflatable Restraint Front End Sensor Replacement - Left Side | N506950 | Holden Australia |
| 6450120 | Inflatable Restraint Front End Sensor Replacement - Left Side | N506970 | Holden Australia |
| 6450120 | Inflatable Restraint Front End Sensor Replacement - Left Side | N506950 | Holden New Zealand |
| 6450120 | Inflatable Restraint Front End Sensor Replacement - Left Side | N506970 | Holden New Zealand |
| 6450120 | Inflatable Restraint Front End Sensor Replacement - Left Side | 8321100 | GMK Overseas |
| 6450120 | Inflatable Restraint Front End Sensor Replacement - Left Side | T783009 | GMK Overseas |
| 6450140 | Inflatable Restraint Front End Sensor Replacement | C8814 | GMNA |
| 6450140 | Inflatable Restraint Front End Sensor Replacement | 8322100 | GMK Overseas |
| 6450160 | Inflatable Restraint Front Side Door Side Impact Sensor Replacement | C8816 | GMNA |
| 6450180 | Airbag Sensing and Diagnostic Module Replacement | C8815 | GMNA |
| 6450180 | Airbag Sensing and Diagnostic Module Replacement | C8817 | GMNA |
| 6450180 | Airbag Sensing and Diagnostic Module Replacement | C8817 | Holden Australia |
| 6450180 | Airbag Sensing and Diagnostic Module Replacement | M900022 | Holden Australia |
| 6450180 | Airbag Sensing and Diagnostic Module Replacement | M900151 | Holden Australia |
| 6450180 | Airbag Sensing and Diagnostic Module Replacement | M901378 | Holden Australia |
| 6450180 | Airbag Sensing and Diagnostic Module Replacement | N506800 | Holden Australia |
| 6450180 | Airbag Sensing and Diagnostic Module Replacement | N582100 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6450180 | Airbag Sensing and Diagnostic Module Replacement | N506800 | Holden New Zealand |
| 6450180 | Airbag Sensing and Diagnostic Module Replacement | N582100 | Holden New Zealand |
| 6450200 | Inflatable Restraint Front Passenger Position Sensor Replacement - Right Side | C8818 | GMNA |
| 6450200 | Inflatable Restraint Front Passenger Position Sensor Replacement - Right Side | C8819 | GMNA |
| 6450220 | Inflatable Restraint Front Passenger Position Sensor Replacement - Left Side | C8819 | Holden Australia |
| 6450260 | Airbag Side Impact Sensor Replacement | C8820 | GMNA |
| 6450260 | Airbag Side Impact Sensor Replacement | C8823 | GMNA |
| 6450260 | Airbag Side Impact Sensor Replacement | C8823 | Holden Australia |
| 6450260 | Airbag Side Impact Sensor Replacement | 8321000 | GMK Overseas |
| 6450260 | Airbag Side Impact Sensor Replacement | 8321200 | GMK Overseas |
| 6450310 | Inflatable Restraint Side Impact Sensor Replacement - Front | C8825 | GMNA |
| 6450330 | Airbag Rear Side Door Side Impact Sensor Replacement | C8826 | GMNA |
| 6450350 | Inflatable Restraint Side Impact Sensor Replacement - Rear | C8828 | GMNA |
| 6450370 | Steering Wheel Inflatable Restraint Module Replacement | C8834 | GMNA |
| 6450370 | Steering Wheel Inflatable Restraint Module Replacement | C8835 | GMNA |
| 6450370 | Steering Wheel Inflatable Restraint Module Replacement | C9503 | GMNA |
| 6450370 | Steering Wheel Inflatable Restraint Module Replacement | C9875 | GMNA |
| 6450370 | Steering Wheel Inflatable Restraint Module Replacement | C000613 | Holden Australia |
| 6450370 | Steering Wheel Inflatable Restraint Module Replacement | C8835 | Holden Australia |
| 6450370 | Steering Wheel Inflatable Restraint Module Replacement | M200100 | Holden Australia |
| 6450370 | Steering Wheel Inflatable Restraint Module Replacement | M902050 | Holden Australia |
| 6450370 | Steering Wheel Inflatable Restraint Module Replacement | N583000 | Holden Australia |
| 6450370 | Steering Wheel Inflatable Restraint Module Replacement | N584000 | Holden Australia |
| 6450370 | Steering Wheel Inflatable Restraint Module Replacement | N591100 | Holden Australia |
| 6450370 | Steering Wheel Inflatable Restraint Module Replacement | C000613 | Holden New Zealand |
| 6450370 | Steering Wheel Inflatable Restraint Module Replacement | C452720 | Holden New Zealand |
| 6450370 | Steering Wheel Inflatable Restraint Module Replacement | M200100 | Holden New Zealand |
| 6450370 | Steering Wheel Inflatable Restraint Module Replacement | N583000 | Holden New Zealand |
| 6450370 | Steering Wheel Inflatable Restraint Module Replacement | N584000 | Holden New Zealand |
| 6450370 | Steering Wheel Inflatable Restraint Module Replacement | 8320700 | GMK Overseas |
| 6450390 | Instrument Panel Inflatable Restraint Module Replacement | C8836 | GMNA |
| 6450390 | Instrument Panel Inflatable Restraint Module Replacement | C9762 | GMNA |
| 6450390 | Instrument Panel Inflatable Restraint Module Replacement | C000418 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6450390 | Instrument Panel Inflatable Restraint Module Replacement | C8836 | Holden Australia |
| 6450390 | Instrument Panel Inflatable Restraint Module Replacement | M200300 | Holden Australia |
| 6450390 | Instrument Panel Inflatable Restraint Module Replacement | C452710 | Holden New Zealand |
| 6450390 | Instrument Panel Inflatable Restraint Module Replacement | M200300 | Holden New Zealand |
| 6450410 | Inflatable Restraint Driver Seat Position Sensor Replacement | C8837 | GMNA |
| 6450430 | Airbag Front Seat Position Sensor Replacement | C8838 | GMNA |
| 6450440 | Inflatable Restraint Side Impact Sensor Replacement - Center Pillar | | |
| 6450480 | Inflatable Restraint Side Impact Sensor Replacement - Right Side Rear | C8841 | GMNA |
| 6450500 | Inflatable Restraint Side Impact Sensor Replacement - Left Side Rear | C8842 | GMNA |
| 6450520 | Instrument Panel Lower Airbag Replacement - Driver Side | C8843 | GMNA |
| 6450540 | Instrument Panel Lower Airbag Replacement - Passenger Side | C8844 | GMNA |
| 6450560 | Front Seat Outboard Seat Back Airbag Replacement | C8847 | GMNA |
| 6450560 | Front Seat Outboard Seat Back Airbag Replacement | C8855 | GMNA |
| 6450560 | Front Seat Outboard Seat Back Airbag Replacement | C8856 | GMNA |
| 6450560 | Front Seat Outboard Seat Back Airbag Replacement | C885500 | Holden Australia |
| 6450560 | Front Seat Outboard Seat Back Airbag Replacement | C885600 | Holden Australia |
| 6450560 | Front Seat Outboard Seat Back Airbag Replacement | C999000 | Holden Australia |
| 6450560 | Front Seat Outboard Seat Back Airbag Replacement | C885500 | Holden New Zealand |
| 6450560 | Front Seat Outboard Seat Back Airbag Replacement | C885600 | Holden New Zealand |
| 6450560 | Front Seat Outboard Seat Back Airbag Replacement | C9990 | Holden New Zealand |
| 6450560 | Front Seat Outboard Seat Back Airbag Replacement | 8321300 | GMK Overseas |
| 6450560 | Front Seat Outboard Seat Back Airbag Replacement | 8321400 | GMK Overseas |
| 6450560 | Front Seat Outboard Seat Back Airbag Replacement | 8321500 | GMK Overseas |
| 6450640 | Inflatable Restraint Vehicle Rollover Sensor Replacement | C8852 | GMNA |
| 6450640 | Inflatable Restraint Vehicle Rollover Sensor Replacement | C8852 | Holden Australia |
| 6450660 | Inflatable Restraint Roof Side Rail Module Replacement - Right Side | 8321600 | GMK Overseas |
| 6450680 | Inflatable Restraint Roof Side Rail Module Replacement - Left Side | 8321700 | GMK Overseas |
| 6450760 | Roof Side Rail Inflatable Restraint Module Replacement | C9985 | GMNA |
| 6450760 | Roof Side Rail Inflatable Restraint Module Replacement | C454700 | Holden Australia |
| 6450760 | Roof Side Rail Inflatable Restraint Module Replacement | 8321800 | GMK Overseas |
| 6450810 | Inflatable Restraint Roof Side Rail Module Replacement - Front | C8853 | GMNA |
| 6450810 | Inflatable Restraint Roof Side Rail Module Replacement - Front | C8854 | GMNA |
| 6450810 | Inflatable Restraint Roof Side Rail Module Replacement - Front | C8859 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6450810 | Inflatable Restraint Roof Side Rail Module Replacement - Front | C8861 | GMNA |
| 6450810 | Inflatable Restraint Roof Side Rail Module Replacement - Front | C454710 | Holden Australia |
| 6450810 | Inflatable Restraint Roof Side Rail Module Replacement - Front | C454720 | Holden Australia |
| 6450810 | Inflatable Restraint Roof Side Rail Module Replacement - Front | C8853 | Holden Australia |
| 6450810 | Inflatable Restraint Roof Side Rail Module Replacement - Front | C454710 | Holden New Zealand |
| 6450810 | Inflatable Restraint Roof Side Rail Module Replacement - Front | C454720 | Holden New Zealand |
| 6450830 | Inflatable Restraint Roof Side Rail Module Replacement - Rear | C8862 | GMNA |
| 6450850 | Rear Seat Outboard Seat Back Airbag Replacement | C8858 | GMNA |
| 6450850 | Rear Seat Outboard Seat Back Airbag Replacement | C8863 | GMNA |
| 6450850 | Rear Seat Outboard Seat Back Airbag Replacement | C8864 | GMNA |
| 6450850 | Rear Seat Outboard Seat Back Airbag Replacement | 8325200 | GMK Overseas |
| 6450870 | Rear Seat Body Side Inflatable Restraint Module Replacement | 8325300 | GMK Overseas |
| 6450880 | Rear Seat Bolster Airbag Replacement | | |
| 6450890 | Inflatable Restraint Front Passenger Mass Sensor Replacement | C8868 | GMNA |
| 6450910 | Inflatable Restraint Front Passenger Presence Module Replacement | B5506 | GMNA |
| 6450910 | Inflatable Restraint Front Passenger Presence Module Replacement | C8869 | GMNA |
| 6450910 | Inflatable Restraint Front Passenger Presence Module Replacement | C9840 | GMNA |
| 6450910 | Inflatable Restraint Front Passenger Presence Module Replacement | 8320900 | GMK Overseas |
| 6450930 | Inflatable Restraint Passenger Seat Suppression Module Replacement | C8870 | GMNA |
| 6450930 | Inflatable Restraint Passenger Seat Suppression Module Replacement | C8870 | Holden Australia |
| 6450950 | Inflatable Restraint Front Passenger Presence Sensor Replacement | C8871 | GMNA |
| 6450950 | Inflatable Restraint Front Passenger Presence Sensor Replacement | 8322000 | GMK Overseas |
| 6450970 | Instrument Panel Airbag Arming Status Display Replacement | C8873 | GMNA |
| 6451010 | Front Seat Belt Buckle Replacement | C9020 | GMNA |
| 6451010 | Front Seat Belt Buckle Replacement | C9427 | GMNA |
| 6451010 | Front Seat Belt Buckle Replacement | C9433 | GMNA |
| 6451010 | Front Seat Belt Buckle Replacement | C9797 | GMNA |
| 6451010 | Front Seat Belt Buckle Replacement | C451240 | Holden Australia |
| 6451010 | Front Seat Belt Buckle Replacement | C9020 | Holden Australia |
| 6451010 | Front Seat Belt Buckle Replacement | C451240 | Holden New Zealand |
| 6451010 | Front Seat Belt Buckle Replacement | C9020 | Holden New Zealand |
| 6451030 | Front Seat Belt Anchor Plate Tensioner Replacement | C9032 | GMNA |
| 6451030 | Front Seat Belt Anchor Plate Tensioner Replacement | C9142 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6451030 | Front Seat Belt Anchor Plate Tensioner Replacement | C451140 | Holden Australia |
| 6451030 | Front Seat Belt Anchor Plate Tensioner Replacement | N000786 | Holden Australia |
| 6451030 | Front Seat Belt Anchor Plate Tensioner Replacement | C451140 | Holden New Zealand |
| 6451030 | Front Seat Belt Anchor Plate Tensioner Replacement | N000747 | Holden New Zealand |
| 6451030 | Front Seat Belt Anchor Plate Tensioner Replacement | 8122000 | GMK Overseas |
| 6451050 | Driver or Passenger Seat Retractor Side Belt Replacement | C9040 | GMNA |
| 6451050 | Driver or Passenger Seat Retractor Side Belt Replacement | C9060 | GMNA |
| 6451050 | Driver or Passenger Seat Retractor Side Belt Replacement | C9061 | GMNA |
| 6451050 | Driver or Passenger Seat Retractor Side Belt Replacement | N4824 | GMNA |
| 6451050 | Driver or Passenger Seat Retractor Side Belt Replacement | N9624 | GMNA |
| 6451050 | Driver or Passenger Seat Retractor Side Belt Replacement | N9652 | GMNA |
| 6451050 | Driver or Passenger Seat Retractor Side Belt Replacement | C451100 | Holden Australia |
| 6451050 | Driver or Passenger Seat Retractor Side Belt Replacement | C451200 | Holden Australia |
| 6451050 | Driver or Passenger Seat Retractor Side Belt Replacement | C9040 | Holden Australia |
| 6451050 | Driver or Passenger Seat Retractor Side Belt Replacement | C904000 | Holden Australia |
| 6451050 | Driver or Passenger Seat Retractor Side Belt Replacement | C451100 | Holden New Zealand |
| 6451050 | Driver or Passenger Seat Retractor Side Belt Replacement | C451110 | Holden New Zealand |
| 6451050 | Driver or Passenger Seat Retractor Side Belt Replacement | C451200 | Holden New Zealand |
| 6451050 | Driver or Passenger Seat Retractor Side Belt Replacement | C9040 | Holden New Zealand |
| 6451050 | Driver or Passenger Seat Retractor Side Belt Replacement | C904000 | Holden New Zealand |
| 6451050 | Driver or Passenger Seat Retractor Side Belt Replacement | 8120600 | GMK Overseas |
| 6451050 | Driver or Passenger Seat Retractor Side Belt Replacement | 8120700 | GMK Overseas |
| 6451070 | Inflatable Restraint Instrument Panel Compartment Module Disable Switch Replacement | N2325 | GMNA |
| 6451070 | Inflatable Restraint Instrument Panel Compartment Module Disable Switch Replacement | 8661500 | GMK Domestic |
| 6451070 | Inflatable Restraint Instrument Panel Compartment Module Disable Switch Replacement | 8325000 | GMK Overseas |
| 6451070 | Inflatable Restraint Instrument Panel Compartment Module Disable Switch Replacement | 9324000 | GMK Overseas |
| 6451090 | Instrument Panel Inflatable Restraint Module Switch Replacement | N2326 | GMNA |
| 6451090 | Instrument Panel Inflatable Restraint Module Switch Replacement | N2326 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6459939 | Customer Concerned Not Duplicated (CCND) - Electronics/Safety/Seat/Lighting/Keyless Entry/Theft Alarm | C9995 | GMNA |
| 6459939 | Customer Concerned Not Duplicated (CCND) - Electronics/Safety/Seat/Lighting/Keyless Entry/Theft Alarm | R9781 | GMNA |
| 6459939 | Customer Concerned Not Duplicated (CCND) - Electronics/Safety/Seat/Lighting/Keyless Entry/Theft Alarm | 5424120 | GMK Domestic |
| 6460120 | Theft Deterrent Hood Switch Replacement | R2889 | GMNA |
| 6460160 | Ignition Lock Cylinder Theft Deterrent Sensor Antenna Replacement | R2893 | GMNA |
| 6460290 | Theft Deterrent Alarm Indicator Replacement | | |
| 6460310 | Theft Deterrent Passenger Compartment Sensor Disable Switch Replacement | 9295600 | GMK Overseas |
| 6460330 | Theft Deterrent Alarm Cutoff Switch Replacement | R2970 | GMNA |
| 6460380 | Theft Deterrent Sensor Replacement | R2974 | GMNA |
| 6460380 | Theft Deterrent Sensor Replacement | 5415100 | GMK Domestic |
| 6460380 | Theft Deterrent Sensor Replacement | 5714400 | GMK Domestic |
| 6460380 | Theft Deterrent Sensor Replacement | 9291900 | GMK Overseas |
| 6460380 | Theft Deterrent Sensor Replacement | 9721100 | GMK Overseas |
| 6460400 | Theft Deterrent Module Replacement | R2975 | GMNA |
| 6460400 | Theft Deterrent Module Replacement | R9704 | GMNA |
| 6460400 | Theft Deterrent Module Replacement | N506550 | Holden Australia |
| 6460420 | Theft Deterrent Key Transponder Replacement | R2977 | GMNA |
| 6460460 | Theft Deterrent Vehicle Inclination Sensor Replacement | R2979 | GMNA |
| 6460460 | Theft Deterrent Vehicle Inclination Sensor Replacement | N300100 | Holden New Zealand |
| 6460460 | Theft Deterrent Vehicle Inclination Sensor Replacement | 9292000 | GMK Overseas |
| 6460480 | Theft Deterrent Alarm Replacement | N1840 | GMNA |
| 6460480 | Theft Deterrent Alarm Replacement | N1860 | GMNA |
| 6460480 | Theft Deterrent Alarm Replacement | N1894 | GMNA |
| 6460480 | Theft Deterrent Alarm Replacement | N4849 | GMNA |
| 6460480 | Theft Deterrent Alarm Replacement | R2983 | GMNA |
| 6460480 | Theft Deterrent Alarm Replacement | 8522600 | GMK Domestic |
| 6460480 | Theft Deterrent Alarm Replacement | N200600 | Holden Australia |
| 6460480 | Theft Deterrent Alarm Replacement | N200610 | Holden Australia |
| 6460480 | Theft Deterrent Alarm Replacement | R901000 | Holden Australia |
| 6460480 | Theft Deterrent Alarm Replacement | N200600 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 6460480 | Theft Deterrent Alarm Replacement | N200610 | Holden New Zealand |
| 6460480 | Theft Deterrent Alarm Replacement | N500500 | Holden New Zealand |
| 6460480 | Theft Deterrent Alarm Replacement | 8330800 | GMK Overseas |
| 6460480 | Theft Deterrent Alarm Replacement | 9291300 | GMK Overseas |
| 7010010 | Front Seat Adjuster Replacement | | |
| 7010090 | Driver Seat Cushion Frame Replacement | B9981 | GMNA |
| 7010090 | Driver Seat Cushion Frame Replacement | C6056 | GMNA |
| 7010090 | Driver Seat Cushion Frame Replacement | C6833 | GMNA |
| 7010100 | Front Seat Tilt Adjuster Actuator Replacement | | |
| 7010140 | Front Seat Adjuster Actuator Replacement | C6288 | GMNA |
| 7010140 | Front Seat Adjuster Actuator Replacement | C502100 | Holden Australia |
| 7010140 | Front Seat Adjuster Actuator Replacement | C502150 | Holden Australia |
| 7010140 | Front Seat Adjuster Actuator Replacement | C502100 | Holden New Zealand |
| 7010140 | Front Seat Adjuster Actuator Replacement | C502150 | Holden New Zealand |
| 7010160 | Driver Seat Outer Adjuster Rear Vertical Actuator Replacement | C6289 | GMNA |
| 7010240 | Driver or Passenger Seat Adjuster Horizontal Actuator Replacement | C6292 | GMNA |
| 7010260 | Driver or Passenger Seat Recliner Actuator Replacement | C6293 | GMNA |
| 7010260 | Driver or Passenger Seat Recliner Actuator Replacement | C502625 | Holden Australia |
| 7010260 | Driver or Passenger Seat Recliner Actuator Replacement | C502725 | Holden Australia |
| 7010260 | Driver or Passenger Seat Recliner Actuator Replacement | C502625 | Holden New Zealand |
| 7010260 | Driver or Passenger Seat Recliner Actuator Replacement | C502725 | Holden New Zealand |
| 7010280 | Driver or Passenger Seat Vertical Adjuster Actuator Replacement | C6294 | GMNA |
| 7010300 | Driver or Passenger Seat Horizontal Adjuster Cable Replacement | C6400 | GMNA |
| 7010300 | Driver or Passenger Seat Horizontal Adjuster Cable Replacement | C6410 | GMNA |
| 7010300 | Driver or Passenger Seat Horizontal Adjuster Cable Replacement | C6411 | GMNA |
| 7010300 | Driver or Passenger Seat Horizontal Adjuster Cable Replacement | C6420 | GMNA |
| 7010300 | Driver or Passenger Seat Horizontal Adjuster Cable Replacement | C6432 | GMNA |
| 7010300 | Driver or Passenger Seat Horizontal Adjuster Cable Replacement | C9778 | GMNA |
| 7010300 | Driver or Passenger Seat Horizontal Adjuster Cable Replacement | 9417400 | GMK Overseas |
| 7010470 | Driver or Passenger Seat Adjuster Switch Knob Replacement | C6493 | GMNA |
| 7010470 | Driver or Passenger Seat Adjuster Switch Knob Replacement | C6494 | GMNA |
| 7010470 | Driver or Passenger Seat Adjuster Switch Knob Replacement | N264400 | Holden Australia |
| 7010470 | Driver or Passenger Seat Adjuster Switch Knob Replacement | N264500 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7010470 | Driver or Passenger Seat Adjuster Switch Knob Replacement | N264600 | Holden Australia |
| 7010470 | Driver or Passenger Seat Adjuster Switch Knob Replacement | N264300 | Holden New Zealand |
| 7010470 | Driver or Passenger Seat Adjuster Switch Knob Replacement | N264400 | Holden New Zealand |
| 7010470 | Driver or Passenger Seat Adjuster Switch Knob Replacement | N264500 | Holden New Zealand |
| 7010470 | Driver or Passenger Seat Adjuster Switch Knob Replacement | N264600 | Holden New Zealand |
| 7010520 | Driver or Passenger Seat Recliner Lever Knob Replacement | | |
| 7010540 | Driver or Passenger Seat Lumbar Support Actuator Replacement | | |
| 7010550 | Seat Lumbar Sub System Replacement | C6624 | GMNA |
| 7010550 | Seat Lumbar Sub System Replacement | C6629 | GMNA |
| 7010550 | Seat Lumbar Sub System Replacement | C6632 | GMNA |
| 7010550 | Seat Lumbar Sub System Replacement | C6635 | GMNA |
| 7010550 | Seat Lumbar Sub System Replacement | C6636 | GMNA |
| 7010570 | Driver or Passenger Seat Lumbar Support Replacement | C7065 | GMNA |
| 7010570 | Driver or Passenger Seat Lumbar Support Replacement | C7069 | GMNA |
| 7010570 | Driver or Passenger Seat Lumbar Support Replacement | C7095 | GMNA |
| 7010570 | Driver or Passenger Seat Lumbar Support Replacement | C7096 | GMNA |
| 7010570 | Driver or Passenger Seat Lumbar Support Replacement | C7097 | GMNA |
| 7010570 | Driver or Passenger Seat Lumbar Support Replacement | C7098 | GMNA |
| 7010570 | Driver or Passenger Seat Lumbar Support Replacement | C7099 | GMNA |
| 7010570 | Driver or Passenger Seat Lumbar Support Replacement | C7153 | GMNA |
| 7010570 | Driver or Passenger Seat Lumbar Support Replacement | C7154 | GMNA |
| 7010570 | Driver or Passenger Seat Lumbar Support Replacement | C7158 | GMNA |
| 7010590 | Front Seat Lumbar Support Bladder Replacement | C7070 | GMNA |
| 7010610 | Driver or Passenger Seat Cushion Air Pump Replacement | C7157 | GMNA |
| 7010610 | Driver or Passenger Seat Cushion Air Pump Replacement | 9440100 | GMK Overseas |
| 7010630 | Rear Seat Lumbar Support Replacement | C7337 | GMNA |
| 7010920 | Passenger Seat Lumbar Control Switch Replacement | N2415 | GMNA |
| 7010920 | Passenger Seat Lumbar Control Switch Replacement | N2416 | GMNA |
| 7010920 | Passenger Seat Lumbar Control Switch Replacement | N2416 | Holden Australia |
| 7010940 | Driver Seat Lumbar Control Switch Replacement | N2414 | GMNA |
| 7010940 | Driver Seat Lumbar Control Switch Replacement | N2417 | GMNA |
| 7010940 | Driver Seat Lumbar Control Switch Replacement | N2417 | Holden Australia |
| 7010960 | Rear Seat Recliner Switch Replacement | N2419 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7010960 | Rear Seat Recliner Switch Replacement | 8830600 | GMK Domestic |
| 7011010 | Passenger Seat Adjuster Switch Replacement | N2428 | GMNA |
| 7011030 | Driver Seat Adjuster Switch Replacement | N2429 | GMNA |
| 7011030 | Driver Seat Adjuster Switch Replacement | N2430 | GMNA |
| 7011030 | Driver Seat Adjuster Switch Replacement | N2431 | GMNA |
| 7011030 | Driver Seat Adjuster Switch Replacement | N2432 | GMNA |
| 7011030 | Driver Seat Adjuster Switch Replacement | 9414900 | GMK Overseas |
| 7011050 | Rear Seat Lumbar Control Switch Replacement | N2433 | GMNA |
| 7011070 | Driver or Passenger Seat Massage Control Switch Replacement | N2434 | GMNA |
| 7011140 | Rear Seat Recliner Actuator Replacement | C7360 | GMNA |
| 7011140 | Rear Seat Recliner Actuator Replacement | C7950 | GMNA |
| 7011140 | Rear Seat Recliner Actuator Replacement | N3240 | GMNA |
| 7011160 | Front Seat Adjuster Motor Replacement | C9767 | GMNA |
| 7011160 | Front Seat Adjuster Motor Replacement | N3330 | GMNA |
| 7011160 | Front Seat Adjuster Motor Replacement | N3340 | GMNA |
| 7011160 | Front Seat Adjuster Motor Replacement | N3350 | GMNA |
| 7011160 | Front Seat Adjuster Motor Replacement | N3351 | GMNA |
| 7011160 | Front Seat Adjuster Motor Replacement | N3352 | GMNA |
| 7011160 | Front Seat Adjuster Motor Replacement | 9440400 | GMK Overseas |
| 7011210 | Front Seat Recliner Actuator Motor Replacement | N3354 | GMNA |
| 7011210 | Front Seat Recliner Actuator Motor Replacement | C541120 | Holden Australia |
| 7011260 | Sit-N-Lift Control Module Replacement | N5500 | GMNA |
| 7011280 | Sit-N-Lift Remote Control Replacement | N5501 | GMNA |
| 7011320 | Driver or Passenger Seat Adjuster Memory Module Replacement | C6838 | GMNA |
| 7011320 | Driver or Passenger Seat Adjuster Memory Module Replacement | C6839 | GMNA |
| 7011320 | Driver or Passenger Seat Adjuster Memory Module Replacement | N5510 | GMNA |
| 7011320 | Driver or Passenger Seat Adjuster Memory Module Replacement | N9617 | GMNA |
| 7011320 | Driver or Passenger Seat Adjuster Memory Module Replacement | N9623 | GMNA |
| 7011320 | Driver or Passenger Seat Adjuster Memory Module Replacement | 8732600 | GMK Domestic |
| 7011320 | Driver or Passenger Seat Adjuster Memory Module Replacement | N264700 | Holden Australia |
| 7011320 | Driver or Passenger Seat Adjuster Memory Module Replacement | N264700 | Holden New Zealand |
| 7011340 | Front Seat Recliner Position Sensor Replacement | N5511 | GMNA |
| 7011410 | Driver Seat Adjuster Memory Switch Replacement | C9982 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7011410 | Driver Seat Adjuster Memory Switch Replacement | N5520 | GMNA |
| 7011410 | Driver Seat Adjuster Memory Switch Replacement | N264000 | Holden Australia |
| 7011410 | Driver Seat Adjuster Memory Switch Replacement | N264000 | Holden New Zealand |
| 7020030 | Front Seat Adjuster Replacement | | |
| 7020050 | Driver or Passenger Seat Adjuster Track Replacement | B2810 | GMNA |
| 7020050 | Driver or Passenger Seat Adjuster Track Replacement | C6009 | GMNA |
| 7020050 | Driver or Passenger Seat Adjuster Track Replacement | C9685 | GMNA |
| 7020050 | Driver or Passenger Seat Adjuster Track Replacement | C9933 | GMNA |
| 7020050 | Driver or Passenger Seat Adjuster Track Replacement | C9986 | GMNA |
| 7020050 | Driver or Passenger Seat Adjuster Track Replacement | C520200 | Holden Australia |
| 7020050 | Driver or Passenger Seat Adjuster Track Replacement | C521210 | Holden Australia |
| 7020050 | Driver or Passenger Seat Adjuster Track Replacement | C521220 | Holden Australia |
| 7020050 | Driver or Passenger Seat Adjuster Track Replacement | C520200 | Holden New Zealand |
| 7020160 | Front Seat Vertical Adjuster Replacement | C6042 | GMNA |
| 7020160 | Front Seat Vertical Adjuster Replacement | T1773 | GMNA |
| 7020180 | Driver or Passenger Seat Cushion Frame Replacement | C6060 | GMNA |
| 7020180 | Driver or Passenger Seat Cushion Frame Replacement | C6545 | GMNA |
| 7020180 | Driver or Passenger Seat Cushion Frame Replacement | C6546 | GMNA |
| 7020180 | Driver or Passenger Seat Cushion Frame Replacement | C6832 | GMNA |
| 7020180 | Driver or Passenger Seat Cushion Frame Replacement | C6834 | GMNA |
| 7020180 | Driver or Passenger Seat Cushion Frame Replacement | C9743 | GMNA |
| 7020180 | Driver or Passenger Seat Cushion Frame Replacement | C9866 | GMNA |
| 7020180 | Driver or Passenger Seat Cushion Frame Replacement | C9961 | GMNA |
| 7020180 | Driver or Passenger Seat Cushion Frame Replacement | 8680400 | GMK Domestic |
| 7020180 | Driver or Passenger Seat Cushion Frame Replacement | C6060 | Holden Australia |
| 7020180 | Driver or Passenger Seat Cushion Frame Replacement | 9415700 | GMK Overseas |
| 7020180 | Driver or Passenger Seat Cushion Frame Replacement | 9415710 | GMK Overseas |
| 7020200 | Passenger Seat Frame Replacement | C6061 | GMNA |
| 7020200 | Passenger Seat Frame Replacement | 9410100 | GMK Overseas |
| 7020200 | Passenger Seat Frame Replacement | T894002 | GMK Overseas |
| 7020220 | Driver Seat Frame Replacement | C6062 | GMNA |
| 7020220 | Driver Seat Frame Replacement | C9753 | GMNA |
| 7020220 | Driver Seat Frame Replacement | C9965 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7020220 | Driver Seat Frame Replacement | S0790 | GMNA |
| 7020220 | Driver Seat Frame Replacement | S0791 | GMNA |
| 7020220 | Driver Seat Frame Replacement | 8731500 | GMK Domestic |
| 7020220 | Driver Seat Frame Replacement | 8731700 | GMK Domestic |
| 7020220 | Driver Seat Frame Replacement | 8732000 | GMK Domestic |
| 7020220 | Driver Seat Frame Replacement | C000683 | Holden Australia |
| 7020220 | Driver Seat Frame Replacement | C000683 | Holden New Zealand |
| 7020220 | Driver Seat Frame Replacement | 9410300 | GMK Overseas |
| 7020220 | Driver Seat Frame Replacement | 9410400 | GMK Overseas |
| 7020240 | Front Seat Cushion Front Extension Frame Replacement | C6065 | GMNA |
| 7020240 | Front Seat Cushion Front Extension Frame Replacement | C559820 | Holden Australia |
| 7020260 | Driver or Passenger Seat Back Cushion Frame Replacement | C6068 | GMNA |
| 7020260 | Driver or Passenger Seat Back Cushion Frame Replacement | C6835 | GMNA |
| 7020260 | Driver or Passenger Seat Back Cushion Frame Replacement | C6836 | GMNA |
| 7020260 | Driver or Passenger Seat Back Cushion Frame Replacement | C6837 | GMNA |
| 7020260 | Driver or Passenger Seat Back Cushion Frame Replacement | 8724400 | GMK Domestic |
| 7020260 | Driver or Passenger Seat Back Cushion Frame Replacement | C502610 | Holden Australia |
| 7020260 | Driver or Passenger Seat Back Cushion Frame Replacement | C502810 | Holden Australia |
| 7020260 | Driver or Passenger Seat Back Cushion Frame Replacement | C502910 | Holden Australia |
| 7020260 | Driver or Passenger Seat Back Cushion Frame Replacement | C572100 | Holden Australia |
| 7020260 | Driver or Passenger Seat Back Cushion Frame Replacement | C502610 | Holden New Zealand |
| 7020260 | Driver or Passenger Seat Back Cushion Frame Replacement | C502810 | Holden New Zealand |
| 7020260 | Driver or Passenger Seat Back Cushion Frame Replacement | C502910 | Holden New Zealand |
| 7020260 | Driver or Passenger Seat Back Cushion Frame Replacement | C572100 | Holden New Zealand |
| 7020260 | Driver or Passenger Seat Back Cushion Frame Replacement | 9410800 | GMK Overseas |
| 7020260 | Driver or Passenger Seat Back Cushion Frame Replacement | 9410900 | GMK Overseas |
| 7020260 | Driver or Passenger Seat Back Cushion Frame Replacement | 9412600 | GMK Overseas |
| 7020310 | Assist Handle Replacement | | |
| 7020330 | Driver or Passenger Seat Adjuster Handle Replacement | C6150 | GMNA |
| 7020330 | Driver or Passenger Seat Adjuster Handle Replacement | C6152 | GMNA |
| 7020330 | Driver or Passenger Seat Adjuster Handle Replacement | C6150 | Holden Australia |
| 7020350 | Front Seat Belt Anchor Plate Tensioner Cover Replacement | C6153 | GMNA |
| 7020350 | Front Seat Belt Anchor Plate Tensioner Cover Replacement | C520140 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7020350 | Front Seat Belt Anchor Plate Tensioner Cover Replacement | C520240 | Holden Australia |
| 7020350 | Front Seat Belt Anchor Plate Tensioner Cover Replacement | C520140 | Holden New Zealand |
| 7020350 | Front Seat Belt Anchor Plate Tensioner Cover Replacement | C520240 | Holden New Zealand |
| 7020460 | Passenger Seat Riser Replacement | C6210 | GMNA |
| 7020510 | Front Seat Tilt Adjuster Lever Replacement | C6286 | GMNA |
| 7020530 | Front Seat Tilt Adjuster Actuator Replacement | C6287 | GMNA |
| 7020550 | Front Seat Horizontal Adjuster Position Sensor Replacement | C6295 | GMNA |
| 7020570 | Driver Seat Adjuster Horizontal Pinion Gear Shaft Replacement | C6412 | GMNA |
| 7020590 | Driver or Passenger Seat Adjuster Handle Knob Replacement | C6492 | GMNA |
| 7020590 | Driver or Passenger Seat Adjuster Handle Knob Replacement | 8731400 | GMK Domestic |
| 7020640 | Front Seat Tilt Adjuster Lever Bolt Cap Replacement | C6496 | GMNA |
| 7020660 | Passenger Seat Recliner Handle Replacement | C6500 | GMNA |
| 7020680 | Driver Seat Recliner Handle Replacement | C6501 | GMNA |
| 7020700 | Front Seat Back Recliner Handle Replacement | C6502 | GMNA |
| 7020700 | Front Seat Back Recliner Handle Replacement | 9410500 | GMK Overseas |
| 7020700 | Front Seat Back Recliner Handle Replacement | 9410600 | GMK Overseas |
| 7020720 | Driver or Passenger Seat Recliner Lever Replacement | C6503 | GMNA |
| 7020720 | Driver or Passenger Seat Recliner Lever Replacement | C561410 | Holden Australia |
| 7020720 | Driver or Passenger Seat Recliner Lever Replacement | C561420 | Holden Australia |
| 7020720 | Driver or Passenger Seat Recliner Lever Replacement | C561410 | Holden New Zealand |
| 7020720 | Driver or Passenger Seat Recliner Lever Replacement | C561420 | Holden New Zealand |
| 7020720 | Driver or Passenger Seat Recliner Lever Replacement | 9415500 | GMK Overseas |
| 7020740 | Driver or Passenger Seat Back Cushion Latch Release Handle Replacement | C6504 | GMNA |
| 7020760 | Front Seat Back Cushion Latch Release Knob Replacement | C6505 | GMNA |
| 7020760 | Front Seat Back Cushion Latch Release Knob Replacement | C6850 | GMNA |
| 7020780 | Driver Seat Recliner Lever Knob Replacement | C6506 | GMNA |
| 7020800 | Driver or Passenger Seat Recliner Lever Knob Replacement | C6507 | GMNA |
| 7020800 | Driver or Passenger Seat Recliner Lever Knob Replacement | C534500 | Holden Australia |
| 7020800 | Driver or Passenger Seat Recliner Lever Knob Replacement | C534500 | Holden New Zealand |
| 7020880 | Front Seat Recliner Control Replacement | C6513 | GMNA |
| 7020880 | Front Seat Recliner Control Replacement | C9898 | GMNA |
| 7020900 | Driver or Passenger Seat Recliner Replacement | C6518 | GMNA |
| 7020900 | Driver or Passenger Seat Recliner Replacement | 8730100 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7020900 | Driver or Passenger Seat Recliner Replacement | 9413700 | GMK Overseas |
| 7020900 | Driver or Passenger Seat Recliner Replacement | 9413800 | GMK Overseas |
| 7020920 | Driver or Passenger Seat Recliner Actuator Cable Replacement | C6519 | GMNA |
| 7020920 | Driver or Passenger Seat Recliner Actuator Cable Replacement | C9929 | GMNA |
| 7020920 | Driver or Passenger Seat Recliner Actuator Cable Replacement | 8732500 | GMK Domestic |
| 7020940 | Driver Seat Lumbar Support Actuator Knob Bezel Replacement | C6524 | GMNA |
| 7020960 | Driver or Passenger Seat Lumbar Support Actuator Knob Replacement | C6525 | GMNA |
| 7020960 | Driver or Passenger Seat Lumbar Support Actuator Knob Replacement | C6634 | GMNA |
| 7020960 | Driver or Passenger Seat Lumbar Support Actuator Knob Replacement | C9969 | GMNA |
| 7020960 | Driver or Passenger Seat Lumbar Support Actuator Knob Replacement | C502920 | Holden Australia |
| 7020960 | Driver or Passenger Seat Lumbar Support Actuator Knob Replacement | C502920 | Holden New Zealand |
| 7021100 | Front Seat Cushion Front Finish Panel Replacement | C6548 | GMNA |
| 7021100 | Front Seat Cushion Front Finish Panel Replacement | C9949 | GMNA |
| 7021120 | Driver or Passenger Seat Cushion Closeout Cover Replacement | C6549 | GMNA |
| 7021120 | Driver or Passenger Seat Cushion Closeout Cover Replacement | 9418100 | GMK Overseas |
| 7021160 | Driver or Passenger Seat Cushion Outer Finish Panel Replacement | C6554 | GMNA |
| 7021160 | Driver or Passenger Seat Cushion Outer Finish Panel Replacement | 8730400 | GMK Domestic |
| 7021160 | Driver or Passenger Seat Cushion Outer Finish Panel Replacement | 8730900 | GMK Domestic |
| 7021210 | Driver or Passenger Seat Back Cushion Latch Release Cable Replacement | C6559 | GMNA |
| 7021210 | Driver or Passenger Seat Back Cushion Latch Release Cable Replacement | C9958 | GMNA |
| 7021320 | Driver or Passenger Seat Outer Adjuster Lower Finish Cover Replacement | C6567 | GMNA |
| 7021340 | Driver or Passenger Seat Outer Adjuster Upper Finish Cover Replacement | C6568 | GMNA |
| 7021360 | Driver or Passenger Seat Cushion Front Cover Replacement | C6569 | GMNA |
| 7021360 | Driver or Passenger Seat Cushion Front Cover Replacement | C7120 | GMNA |
| 7021360 | Driver or Passenger Seat Cushion Front Cover Replacement | C7130 | GMNA |
| 7021360 | Driver or Passenger Seat Cushion Front Cover Replacement | C7150 | GMNA |
| 7021360 | Driver or Passenger Seat Cushion Front Cover Replacement | C7151 | GMNA |
| 7021360 | Driver or Passenger Seat Cushion Front Cover Replacement | C9922 | GMNA |
| 7021380 | Driver or Passenger Seat Riser Finish Cover Replacement | C6570 | GMNA |
| 7021380 | Driver or Passenger Seat Riser Finish Cover Replacement | 9411600 | GMK Overseas |
| 7021380 | Driver or Passenger Seat Riser Finish Cover Replacement | 9411700 | GMK Overseas |
| 7021400 | Driver or Passenger Seat Adjuster Shield Replacement | C6572 | GMNA |
| 7021420 | Front Seat Adjuster Track Finish Cover Replacement | C6573 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7021420 | Front Seat Adjuster Track Finish Cover Replacement | C7842 | GMNA |
| 7021420 | Front Seat Adjuster Track Finish Cover Replacement | C7843 | GMNA |
| 7021420 | Front Seat Adjuster Track Finish Cover Replacement | C6573 | Holden Australia |
| 7021500 | Driver or Passenger Seat Adjuster Finish Cover Replacement | C6576 | GMNA |
| 7021500 | Driver or Passenger Seat Adjuster Finish Cover Replacement | 8823400 | GMK Domestic |
| 7021500 | Driver or Passenger Seat Adjuster Finish Cover Replacement | C503650 | Holden Australia |
| 7021500 | Driver or Passenger Seat Adjuster Finish Cover Replacement | C6576 | Holden Australia |
| 7021520 | Driver or Passenger Seat Inner Adjuster Rear Finish Cover Replacement | C6577 | GMNA |
| 7021570 | Driver or Passenger Seat Adjuster Switch Bezel Replacement | C6579 | GMNA |
| 7021620 | Front Seat Outer Recliner Upper Finish Cover Replacement | C6581 | GMNA |
| 7021620 | Front Seat Outer Recliner Upper Finish Cover Replacement | 8730202 | GMK Domestic |
| 7021620 | Front Seat Outer Recliner Upper Finish Cover Replacement | 9411200 | GMK Overseas |
| 7021620 | Front Seat Outer Recliner Upper Finish Cover Replacement | 9411300 | GMK Overseas |
| 7021640 | Driver or Passenger Seat Back Cushion Outer Hinge Finish Cover Replacement | C6582 | GMNA |
| 7021660 | Front Seat Back Cushion Latch Finish Cover Replacement | C6583 | GMNA |
| 7021760 | Driver or Passenger Seat Outer Adjuster Finish Cover Replacement | C6587 | GMNA |
| 7021780 | Driver or Passenger Seat Inner Adjuster Finish Cover Replacement | C6588 | GMNA |
| 7021780 | Driver or Passenger Seat Inner Adjuster Finish Cover Replacement | C503200 | Holden Australia |
| 7021780 | Driver or Passenger Seat Inner Adjuster Finish Cover Replacement | C503400 | Holden Australia |
| 7021780 | Driver or Passenger Seat Inner Adjuster Finish Cover Replacement | C503450 | Holden Australia |
| 7021780 | Driver or Passenger Seat Inner Adjuster Finish Cover Replacement | C503200 | Holden New Zealand |
| 7021780 | Driver or Passenger Seat Inner Adjuster Finish Cover Replacement | C503400 | Holden New Zealand |
| 7021780 | Driver or Passenger Seat Inner Adjuster Finish Cover Replacement | C503450 | Holden New Zealand |
| 7021800 | Driver or Passenger Seat Inner Recliner Finish Cover Replacement | C6589 | GMNA |
| 7021820 | Driver or Passenger Seat Outer Recliner Finish Cover Replacement | C6590 | GMNA |
| 7021820 | Driver or Passenger Seat Outer Recliner Finish Cover Replacement | 8638800 | GMK Overseas |
| 7021840 | Passenger Seat Recliner Upper Finish Cover Replacement | C6591 | GMNA |
| 7021840 | Passenger Seat Recliner Upper Finish Cover Replacement | 9417700 | GMK Overseas |
| 7021860 | Driver or Passenger Seat Outer Adjuster Front Finish Cover Replacement | C6594 | GMNA |
| 7021880 | Driver or Passenger Seat Adjuster Vertical Actuator Handle Replacement | C6595 | GMNA |
| 7021900 | Front Seat Outer Adjuster Auxiliary Finish Cover Replacement | C6596 | GMNA |
| 7021920 | Front Seat Outer Recliner Inner Finish Cover Replacement | C6597 | GMNA |
| 7022000 | Front Seat Back Cushion Finish Panel Replacement | C6602 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7022000 | Front Seat Back Cushion Finish Panel Replacement | C6614 | GMNA |
| 7022000 | Front Seat Back Cushion Finish Panel Replacement | C427300 | Holden Australia |
| 7022000 | Front Seat Back Cushion Finish Panel Replacement | C6602 | Holden Australia |
| 7022000 | Front Seat Back Cushion Finish Panel Replacement | C427300 | Holden New Zealand |
| 7022000 | Front Seat Back Cushion Finish Panel Replacement | C427310 | Holden New Zealand |
| 7022000 | Front Seat Back Cushion Finish Panel Replacement | 9416700 | GMK Overseas |
| 7022050 | Driver or Passenger Seat Back Cushion Map Pocket Replacement | C6604 | GMNA |
| 7022050 | Driver or Passenger Seat Back Cushion Map Pocket Replacement | C6675 | GMNA |
| 7022050 | Driver or Passenger Seat Back Cushion Map Pocket Replacement | C6676 | GMNA |
| 7022050 | Driver or Passenger Seat Back Cushion Map Pocket Replacement | C000325 | Holden Australia |
| 7022050 | Driver or Passenger Seat Back Cushion Map Pocket Replacement | C000328 | Holden Australia |
| 7022050 | Driver or Passenger Seat Back Cushion Map Pocket Replacement | C000698 | Holden Australia |
| 7022050 | Driver or Passenger Seat Back Cushion Map Pocket Replacement | C504200 | Holden Australia |
| 7022050 | Driver or Passenger Seat Back Cushion Map Pocket Replacement | C504300 | Holden Australia |
| 7022050 | Driver or Passenger Seat Back Cushion Map Pocket Replacement | C000325 | Holden New Zealand |
| 7022050 | Driver or Passenger Seat Back Cushion Map Pocket Replacement | C000698 | Holden New Zealand |
| 7022050 | Driver or Passenger Seat Back Cushion Map Pocket Replacement | C504200 | Holden New Zealand |
| 7022050 | Driver or Passenger Seat Back Cushion Map Pocket Replacement | C504300 | Holden New Zealand |
| 7022070 | Front Seat Back Trim Replacement | C6605 | GMNA |
| 7022070 | Front Seat Back Trim Replacement | C9954 | GMNA |
| 7022070 | Front Seat Back Trim Replacement | C555100 | Holden Australia |
| 7022070 | Front Seat Back Trim Replacement | C000686 | Holden New Zealand |
| 7022070 | Front Seat Back Trim Replacement | C555100 | Holden New Zealand |
| 7022150 | Driver or Passenger Seat Lumbar Support Actuator Replacement | C6622 | GMNA |
| 7022170 | Front Seat Lumbar Control Replacement | C6623 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | C6633 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | C6637 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | C6638 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | C7067 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | C7068 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | C7071 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | C7074 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | C7075 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7022310 | Seat Lumbar Sub System Replacement | C7076 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | C7077 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | C7078 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | C7079 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | C7080 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | C7081 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | C7085 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | C7086 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | N3480 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | N4832 | GMNA |
| 7022310 | Seat Lumbar Sub System Replacement | 8822100 | GMK Domestic |
| 7022310 | Seat Lumbar Sub System Replacement | 9416600 | GMK Overseas |
| 7022330 | Front Seat Cushion Front Extension Adjust Lever Replacement | C6642 | GMNA |
| 7022350 | Front Seat Cushion Front Extension Pad and Cover Replacement | C502800 | Holden Australia |
| 7022350 | Front Seat Cushion Front Extension Pad and Cover Replacement | C502900 | Holden Australia |
| 7022350 | Front Seat Cushion Front Extension Pad and Cover Replacement | C502800 | Holden New Zealand |
| 7022350 | Front Seat Cushion Front Extension Pad and Cover Replacement | C502900 | Holden New Zealand |
| 7022360 | Front Seat Cushion Front Finish Cover Replacement | | |
| 7022370 | Front Seat Front Extension Cushion Replacement | | |
| 7022400 | Front Seat Head Restraint Guide Bezel Replacement | C6680 | GMNA |
| 7022400 | Front Seat Head Restraint Guide Bezel Replacement | C000665 | Holden Australia |
| 7022450 | Front Seat Head Restraint Adjust Knob Replacement | | |
| 7022470 | Front Seat Head Restraint Cover Replacement | C505150 | Holden Australia |
| 7022470 | Front Seat Head Restraint Cover Replacement | C505250 | Holden Australia |
| 7022470 | Front Seat Head Restraint Cover Replacement | C505150 | Holden New Zealand |
| 7022470 | Front Seat Head Restraint Cover Replacement | C505250 | Holden New Zealand |
| 7022490 | Driver or Passenger Seat Head Restraint Actuator Replacement | C6689 | GMNA |
| 7022510 | Driver or Passenger Seat Head Restraint Replacement | C6690 | GMNA |
| 7022510 | Driver or Passenger Seat Head Restraint Replacement | C7232 | GMNA |
| 7022510 | Driver or Passenger Seat Head Restraint Replacement | 8722700 | GMK Domestic |
| 7022510 | Driver or Passenger Seat Head Restraint Replacement | 8722800 | GMK Domestic |
| 7022510 | Driver or Passenger Seat Head Restraint Replacement | 8723000 | GMK Domestic |
| 7022510 | Driver or Passenger Seat Head Restraint Replacement | C505100 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7022510 | Driver or Passenger Seat Head Restraint Replacement | C505200 | Holden Australia |
| 7022510 | Driver or Passenger Seat Head Restraint Replacement | C505100 | Holden New Zealand |
| 7022510 | Driver or Passenger Seat Head Restraint Replacement | C505200 | Holden New Zealand |
| 7022510 | Driver or Passenger Seat Head Restraint Replacement | 9412700 | GMK Overseas |
| 7022510 | Driver or Passenger Seat Head Restraint Replacement | 9412800 | GMK Overseas |
| 7022510 | Driver or Passenger Seat Head Restraint Replacement | 9412900 | GMK Overseas |
| 7022560 | Front Seat Head Restraint Adjust Rod Guide Replacement | C6692 | GMNA |
| 7022560 | Front Seat Head Restraint Adjust Rod Guide Replacement | 9414100 | GMK Overseas |
| 7022560 | Front Seat Head Restraint Adjust Rod Guide Replacement | 9414200 | GMK Overseas |
| 7022560 | Front Seat Head Restraint Adjust Rod Guide Replacement | 9414300 | GMK Overseas |
| 7022580 | Driver or Passenger Seat Head Restraint Guide Replacement | C6693 | GMNA |
| 7022580 | Driver or Passenger Seat Head Restraint Guide Replacement | C505210 | Holden Australia |
| 7022580 | Driver or Passenger Seat Head Restraint Guide Replacement | C558140 | Holden Australia |
| 7022580 | Driver or Passenger Seat Head Restraint Guide Replacement | C505210 | Holden New Zealand |
| 7022600 | Front Seat Storage Tray Replacement | C6694 | GMNA |
| 7022600 | Front Seat Storage Tray Replacement | 8724600 | GMK Domestic |
| 7022600 | Front Seat Storage Tray Replacement | C520110 | Holden Australia |
| 7022600 | Front Seat Storage Tray Replacement | C520110 | Holden New Zealand |
| 7022600 | Front Seat Storage Tray Replacement | 9392000 | GMK Overseas |
| 7022650 | Front Seat Cup Holder Replacement | | |
| 7022670 | Front Seat Armrest Stowage Compartment Replacement | C6697 | GMNA |
| 7022690 | Front Seat Armrest Lid Replacement | C6698 | GMNA |
| 7022690 | Front Seat Armrest Lid Replacement | C6770 | GMNA |
| 7022690 | Front Seat Armrest Lid Replacement | C6771 | GMNA |
| 7022690 | Front Seat Armrest Lid Replacement | C6774 | GMNA |
| 7022690 | Front Seat Armrest Lid Replacement | C6775 | GMNA |
| 7022690 | Front Seat Armrest Lid Replacement | C6778 | GMNA |
| 7022830 | Front Seat Cushion Side Finish Panel Replacement | C000686 | Holden Australia |
| 7022830 | Front Seat Cushion Side Finish Panel Replacement | C503800 | Holden Australia |
| 7022830 | Front Seat Cushion Side Finish Panel Replacement | C503900 | Holden Australia |
| 7022890 | Front Seat Center Cushion Replacement | C6740 | GMNA |
| 7022910 | Front Seat Cushion Rear Frame Center Cover Replacement | C6741 | GMNA |
| 7022910 | Front Seat Cushion Rear Frame Center Cover Replacement | C504000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7022910 | Front Seat Cushion Rear Frame Center Cover Replacement | C504000 | Holden New Zealand |
| 7022930 | Front Seat Cushion Center Cover Replacement | C6742 | GMNA |
| 7022950 | Front Center Seat Back Cushion Latch Replacement | C6743 | GMNA |
| 7022970 | Front Center Seat Back Cushion Latch Upper Cover Replacement | C6744 | GMNA |
| 7023010 | Front Seat Armrest Hinge Finish Cover Replacement | C6749 | GMNA |
| 7023090 | Front Seat Armrest Hinge Replacement | C6756 | GMNA |
| 7023110 | Front Seat Armrest Latch Replacement | C6757 | GMNA |
| 7023130 | Front Seat Armrest Replacement | C6758 | GMNA |
| 7023130 | Front Seat Armrest Replacement | 8723800 | GMK Domestic |
| 7023130 | Front Seat Armrest Replacement | C534400 | Holden Australia |
| 7023130 | Front Seat Armrest Replacement | 9415300 | GMK Overseas |
| 7023150 | Driver or Passenger Seat Removal and Installation | C6790 | GMNA |
| 7023150 | Driver or Passenger Seat Removal and Installation | 8720900 | GMK Domestic |
| 7023150 | Driver or Passenger Seat Removal and Installation | 8720902 | GMK Domestic |
| 7023150 | Driver or Passenger Seat Removal and Installation | 8721100 | GMK Domestic |
| 7023150 | Driver or Passenger Seat Removal and Installation | 8721102 | GMK Domestic |
| 7023150 | Driver or Passenger Seat Removal and Installation | 8721200 | GMK Domestic |
| 7023150 | Driver or Passenger Seat Removal and Installation | 8721400 | GMK Domestic |
| 7023150 | Driver or Passenger Seat Removal and Installation | 8721402 | GMK Domestic |
| 7023150 | Driver or Passenger Seat Removal and Installation | 8721500 | GMK Domestic |
| 7023150 | Driver or Passenger Seat Removal and Installation | 8721502 | GMK Domestic |
| 7023150 | Driver or Passenger Seat Removal and Installation | C000680 | Holden Australia |
| 7023150 | Driver or Passenger Seat Removal and Installation | C000692 | Holden Australia |
| 7023150 | Driver or Passenger Seat Removal and Installation | C551000 | Holden Australia |
| 7023150 | Driver or Passenger Seat Removal and Installation | C551000 | Holden New Zealand |
| 7023150 | Driver or Passenger Seat Removal and Installation | 9414600 | GMK Overseas |
| 7023150 | Driver or Passenger Seat Removal and Installation | 9414700 | GMK Overseas |
| 7023350 | Front Seat Cushion Cover and Pad Replacement | C6860 | GMNA |
| 7023350 | Front Seat Cushion Cover and Pad Replacement | C6880 | GMNA |
| 7023350 | Front Seat Cushion Cover and Pad Replacement | C6881 | GMNA |
| 7023350 | Front Seat Cushion Cover and Pad Replacement | C7031 | GMNA |
| 7023350 | Front Seat Cushion Cover and Pad Replacement | C552000 | Holden Australia |
| 7023350 | Front Seat Cushion Cover and Pad Replacement | C687000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7023350 | Front Seat Cushion Cover and Pad Replacement | C687100 | Holden Australia |
| 7023350 | Front Seat Cushion Cover and Pad Replacement | C552000 | Holden New Zealand |
| 7023350 | Front Seat Cushion Cover and Pad Replacement | C687000 | Holden New Zealand |
| 7023350 | Front Seat Cushion Cover and Pad Replacement | C687100 | Holden New Zealand |
| 7023370 | Driver or Passenger Seat Cushion Pad Replacement | C6730 | GMNA |
| 7023370 | Driver or Passenger Seat Cushion Pad Replacement | C6732 | GMNA |
| 7023370 | Driver or Passenger Seat Cushion Pad Replacement | C6861 | GMNA |
| 7023370 | Driver or Passenger Seat Cushion Pad Replacement | N3356 | GMNA |
| 7023370 | Driver or Passenger Seat Cushion Pad Replacement | 8721700 | GMK Domestic |
| 7023370 | Driver or Passenger Seat Cushion Pad Replacement | 8721800 | GMK Domestic |
| 7023370 | Driver or Passenger Seat Cushion Pad Replacement | C502700 | Holden Australia |
| 7023370 | Driver or Passenger Seat Cushion Pad Replacement | C502710 | Holden Australia |
| 7023370 | Driver or Passenger Seat Cushion Pad Replacement | C553000 | Holden Australia |
| 7023370 | Driver or Passenger Seat Cushion Pad Replacement | C502700 | Holden New Zealand |
| 7023370 | Driver or Passenger Seat Cushion Pad Replacement | C502710 | Holden New Zealand |
| 7023370 | Driver or Passenger Seat Cushion Pad Replacement | 9411000 | GMK Overseas |
| 7023370 | Driver or Passenger Seat Cushion Pad Replacement | 9415600 | GMK Overseas |
| 7023390 | Front Seat Cushion Cover Replacement | C6868 | GMNA |
| 7023390 | Front Seat Cushion Cover Replacement | C9830 | GMNA |
| 7023390 | Front Seat Cushion Cover Replacement | 8721900 | GMK Domestic |
| 7023390 | Front Seat Cushion Cover Replacement | C553100 | Holden Australia |
| 7023390 | Front Seat Cushion Cover Replacement | C553100 | Holden New Zealand |
| 7023390 | Front Seat Cushion Cover Replacement | 9413100 | GMK Overseas |
| 7023390 | Front Seat Cushion Cover Replacement | 9413200 | GMK Overseas |
| 7023410 | Passenger Seat Cushion Cover Replacement | C6870 | GMNA |
| 7023410 | Passenger Seat Cushion Cover Replacement | C6870 | Holden Australia |
| 7023410 | Passenger Seat Cushion Cover Replacement | C6870 | Holden New Zealand |
| 7023430 | Driver Seat Cushion Cover Replacement | C6871 | GMNA |
| 7023430 | Driver Seat Cushion Cover Replacement | C6871 | Holden Australia |
| 7023430 | Driver Seat Cushion Cover Replacement | C6871 | Holden New Zealand |
| 7023450 | Driver or Passenger Seat Cushion Pad Wire Replacement | C6882 | GMNA |
| 7023450 | Driver or Passenger Seat Cushion Pad Wire Replacement | 9418200 | GMK Overseas |
| 7023470 | Driver or Passenger Seat Back Cushion Insert Cover and Pad Replacement | C6606 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7023470 | Driver or Passenger Seat Back Cushion Insert Cover and Pad Replacement | C6607 | GMNA |
| 7023470 | Driver or Passenger Seat Back Cushion Insert Cover and Pad Replacement | C6995 | GMNA |
| 7023550 | Front Seat Back Cushion Pad Replacement | 8722200 | GMK Domestic |
| 7023550 | Front Seat Back Cushion Pad Replacement | 9412400 | GMK Overseas |
| 7023550 | Front Seat Back Cushion Pad Replacement | 9412500 | GMK Overseas |
| 7023570 | Front Seat Cushion Pad Support Wire Spring Replacement | C7022 | GMNA |
| 7023570 | Front Seat Cushion Pad Support Wire Spring Replacement | C500305 | Holden New Zealand |
| 7023570 | Front Seat Cushion Pad Support Wire Spring Replacement | 9441300 | GMK Overseas |
| 7023590 | Driver or Passenger Seat Back Cushion Pad Wire Replacement | C7023 | GMNA |
| 7023610 | Driver or Passenger Seat Back Cushion Latch Release Lever Bezel Replacement | C7049 | GMNA |
| 7023690 | Passenger Seat Back Cushion Pad Replacement | C7052 | GMNA |
| 7023750 | Driver or Passenger Seat Back Cushion Cover Replacement | C7057 | GMNA |
| 7023750 | Driver or Passenger Seat Back Cushion Cover Replacement | 9413400 | GMK Overseas |
| 7023750 | Driver or Passenger Seat Back Cushion Cover Replacement | 9413500 | GMK Overseas |
| 7023750 | Driver or Passenger Seat Back Cushion Cover Replacement | 9413600 | GMK Overseas |
| 7023770 | Driver or Passenger Seat Back Cushion Cover and Pad Replacement | C7058 | GMNA |
| 7023770 | Driver or Passenger Seat Back Cushion Cover and Pad Replacement | C502600 | Holden Australia |
| 7023770 | Driver or Passenger Seat Back Cushion Cover and Pad Replacement | C502600 | Holden New Zealand |
| 7023790 | Driver Seat Lumbar Support Actuator Lever Replacement | C7062 | GMNA |
| 7023810 | Passenger Seat Lumbar Support Replacement | C7063 | GMNA |
| 7023830 | Driver Seat Lumbar Support Replacement | C7064 | GMNA |
| 7023850 | Driver or Passenger Seat Lumbar Support Replacement | C502750 | Holden Australia |
| 7023850 | Driver or Passenger Seat Lumbar Support Replacement | C506800 | Holden Australia |
| 7023850 | Driver or Passenger Seat Lumbar Support Replacement | C502750 | Holden New Zealand |
| 7023850 | Driver or Passenger Seat Lumbar Support Replacement | C506800 | Holden New Zealand |
| 7023870 | Driver or Passenger Seat Back Cushion Pad Support Replacement | C7066 | GMNA |
| 7023890 | Rear Seat Frame Front Finish Cover Replacement - Upper | C7115 | GMNA |
| 7023890 | Rear Seat Frame Front Finish Cover Replacement - Upper | C7415 | GMNA |
| 7023970 | Rear Seat Back Cushion Panel Replacement | C7188 | GMNA |
| 7023990 | Rear Seat Back Cushion Filler Panel Replacement | C7183 | GMNA |
| 7023990 | Rear Seat Back Cushion Filler Panel Replacement | C7498 | GMNA |
| 7023990 | Rear Seat Back Cushion Filler Panel Replacement | C7499 | GMNA |
| 7024010 | Rear Seat Belt Opening Cover Replacement | C7184 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7024030 | Rear Seat Back Cushion Carpet Replacement | C7185 | GMNA |
| 7024030 | Rear Seat Back Cushion Carpet Replacement | C431300 | Holden Australia |
| 7024030 | Rear Seat Back Cushion Carpet Replacement | C431300 | Holden New Zealand |
| 7024070 | Rear Seat Shoulder Belt Retainer Opening Bezel Replacement | C7187 | GMNA |
| 7024080 | Rear Seat Belt Guide Trim Cover Replacement | | |
| 7024090 | Rear Seat Back Cushion Carpet Replacement - Left Side | C7189 | GMNA |
| 7024110 | Rear Seat Back Cushion Carpet Replacement - Right Side | C7190 | GMNA |
| 7024130 | Rear Seat Armrest Multifunction Compartment Armrest Replacement | C7196 | GMNA |
| 7024140 | Rear Seat Armrest Compartment Door Latch Replacement | | |
| 7024150 | Rear Seat Armrest Cushion Cover Replacement | | |
| 7024170 | Rear Seat Armrest Opening Finish Cover Replacement | C7198 | GMNA |
| 7024190 | Rear Seat Back Cushion Armrest Opening Finish Cover Replacement | C7199 | GMNA |
| 7024210 | Rear Seat Armrest Replacement | C7200 | GMNA |
| 7024210 | Rear Seat Armrest Replacement | C7821 | GMNA |
| 7024210 | Rear Seat Armrest Replacement | C8221 | GMNA |
| 7024210 | Rear Seat Armrest Replacement | 9421100 | GMK Overseas |
| 7024290 | Rear Seat Armrest Closeout Panel Replacement | C7203 | GMNA |
| 7024310 | Rear Seat Armrest Hinge Finish Cover Replacement | C7204 | GMNA |
| 7024330 | Rear Seat Pull Strap Replacement | C7205 | GMNA |
| 7024350 | Rear Seat Latch Striker Bezel Replacement | C7206 | GMNA |
| 7024370 | Rear Seat Cushion Compartment Replacement | C7207 | GMNA |
| 7024410 | Rear Seat Cushion Floor Stowage Compartment Replacement | C7209 | GMNA |
| 7024430 | Rear Seat Armrest Cover Replacement | C7210 | GMNA |
| 7024430 | Rear Seat Armrest Cover Replacement | C7217 | GMNA |
| 7024430 | Rear Seat Armrest Cover Replacement | C7288 | GMNA |
| 7024430 | Rear Seat Armrest Cover Replacement | C572500 | Holden Australia |
| 7024430 | Rear Seat Armrest Cover Replacement | C572800 | Holden Australia |
| 7024430 | Rear Seat Armrest Cover Replacement | C572900 | Holden Australia |
| 7024430 | Rear Seat Armrest Cover Replacement | C572500 | Holden New Zealand |
| 7024430 | Rear Seat Armrest Cover Replacement | C572500A1 | Holden New Zealand |
| 7024430 | Rear Seat Armrest Cover Replacement | C572800 | Holden New Zealand |
| 7024430 | Rear Seat Armrest Cover Replacement | C572900 | Holden New Zealand |
| 7024430 | Rear Seat Armrest Cover Replacement | 9421200 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7024430 | Rear Seat Armrest Cover Replacement | 9423000 | GMK Overseas |
| 7024450 | Rear Seat Cup Holder Replacement | | |
| 7024470 | Rear Seat Armrest Mount Panel Replacement | C7212 | GMNA |
| 7024470 | Rear Seat Armrest Mount Panel Replacement | C572400 | Holden Australia |
| 7024470 | Rear Seat Armrest Mount Panel Replacement | C572600 | Holden Australia |
| 7024470 | Rear Seat Armrest Mount Panel Replacement | C572400 | Holden New Zealand |
| 7024470 | Rear Seat Armrest Mount Panel Replacement | C572600 | Holden New Zealand |
| 7024490 | Rear Seat Armrest Compartment Door Replacement | C7214 | GMNA |
| 7024510 | Rear Seat Armrest Cup Holder Replacement | C7215 | GMNA |
| 7024510 | Rear Seat Armrest Cup Holder Replacement | 9422900 | GMK Overseas |
| 7024530 | Rear Seat Armrest Hinge Replacement | C7216 | GMNA |
| 7024550 | Rear Seat Armrest Multifunction Compartment Bezel Replacement | C7218 | GMNA |
| 7024570 | Rear Compartment Access Door Replacement | | |
| 7024590 | Rear Seat Cushion Spring Replacement | C7224 | GMNA |
| 7024610 | Rear Seat Removal and Installation | C7225 | GMNA |
| 7024610 | Rear Seat Removal and Installation | C9754 | GMNA |
| 7024610 | Rear Seat Removal and Installation | C9957 | GMNA |
| 7024610 | Rear Seat Removal and Installation | 8625200 | GMK Domestic |
| 7024610 | Rear Seat Removal and Installation | C000631 | Holden Australia |
| 7024610 | Rear Seat Removal and Installation | C570200 | Holden Australia |
| 7024610 | Rear Seat Removal and Installation | C570250 | Holden Australia |
| 7024610 | Rear Seat Removal and Installation | C000631 | Holden New Zealand |
| 7024610 | Rear Seat Removal and Installation | C570200 | Holden New Zealand |
| 7024610 | Rear Seat Removal and Installation | C570250 | Holden New Zealand |
| 7024610 | Rear Seat Removal and Installation | 9420100 | GMK Overseas |
| 7024610 | Rear Seat Removal and Installation | 9420110 | GMK Overseas |
| 7024610 | Rear Seat Removal and Installation | 9420120 | GMK Overseas |
| 7024630 | Rear Seat Cushion Pull Handle Replacement | C7228 | GMNA |
| 7024650 | Rear Seat Head Restraint Replacement | 8744600 | GMK Domestic |
| 7024650 | Rear Seat Head Restraint Replacement | 9422500 | GMK Overseas |
| 7024650 | Rear Seat Head Restraint Replacement | 9422510 | GMK Overseas |
| 7024670 | Rear Seat Back Bolster Replacement - Right Side | C7233 | GMNA |
| 7024690 | Rear Seat Back Bolster Replacement - Left Side | C7234 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7024710 | Rear Seat Back Bolster Replacement | C7235 | GMNA |
| 7024710 | Rear Seat Back Bolster Replacement | 8639900 | GMK Domestic |
| 7024710 | Rear Seat Back Bolster Replacement | 9424500 | GMK Overseas |
| 7024730 | Rear Seat Head Restraint Guide Replacement | C7236 | GMNA |
| 7024730 | Rear Seat Head Restraint Guide Replacement | 8628000 | GMK Domestic |
| 7024730 | Rear Seat Head Restraint Guide Replacement | 8744700 | GMK Domestic |
| 7024730 | Rear Seat Head Restraint Guide Replacement | C505230 | Holden Australia |
| 7024730 | Rear Seat Head Restraint Guide Replacement | C505230 | Holden New Zealand |
| 7024730 | Rear Seat Head Restraint Guide Replacement | 9422600 | GMK Overseas |
| 7024730 | Rear Seat Head Restraint Guide Replacement | 9423200 | GMK Overseas |
| 7024780 | Rear Seat Head Restraint Cover Replacement | C7230 | GMNA |
| 7024780 | Rear Seat Head Restraint Cover Replacement | C7231 | GMNA |
| 7024780 | Rear Seat Head Restraint Cover Replacement | 9431000 | GMK Overseas |
| 7024800 | Rear Seat Head Restraint Pad Replacement | | |
| 7024820 | Rear Seat Head Restraint Adjuster Actuator Cable Replacement | C7227 | GMNA |
| 7024820 | Rear Seat Head Restraint Adjuster Actuator Cable Replacement | C7242 | GMNA |
| 7024870 | Rear Seat Cushion Panel Replacement | C7244 | GMNA |
| 7024890 | Rear Seat Back Rear Lower Center Cover Carpet Replacement | C7248 | GMNA |
| 7024940 | Rear Seat Cushion Cover Replacement | C7245 | GMNA |
| 7024940 | Rear Seat Cushion Cover Replacement | C7246 | GMNA |
| 7024940 | Rear Seat Cushion Cover Replacement | C7250 | GMNA |
| 7024940 | Rear Seat Cushion Cover Replacement | C7251 | GMNA |
| 7024940 | Rear Seat Cushion Cover Replacement | C7373 | GMNA |
| 7024940 | Rear Seat Cushion Cover Replacement | C570100 | Holden Australia |
| 7024940 | Rear Seat Cushion Cover Replacement | C7250 | Holden Australia |
| 7024940 | Rear Seat Cushion Cover Replacement | C7251 | Holden Australia |
| 7024940 | Rear Seat Cushion Cover Replacement | C570100 | Holden New Zealand |
| 7024940 | Rear Seat Cushion Cover Replacement | C570110 | Holden New Zealand |
| 7024940 | Rear Seat Cushion Cover Replacement | 9420700 | GMK Overseas |
| 7024940 | Rear Seat Cushion Cover Replacement | 9420710 | GMK Overseas |
| 7024940 | Rear Seat Cushion Cover Replacement | 9420720 | GMK Overseas |
| 7024940 | Rear Seat Cushion Cover Replacement | T294020 | GMK Overseas |
| 7024990 | Rear Seat Back Cushion Opening Panel Replacement | C7252 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7024990 | Rear Seat Back Cushion Opening Panel Replacement | C725200 | Holden Australia |
| 7024990 | Rear Seat Back Cushion Opening Panel Replacement | 9425600 | GMK Overseas |
| 7024990 | Rear Seat Back Cushion Opening Panel Replacement | 9425610 | GMK Overseas |
| 7025010 | Rear Seat Back Cushion Center Panel Replacement | C7253 | GMNA |
| 7025030 | Rear Seat Back Cushion Latch Replacement - Right Side | C7254 | GMNA |
| 7025050 | Rear Seat Back Cushion Latch Replacement - Left Side | C7255 | GMNA |
| 7025070 | Rear Seat Back Cushion Latch Release Handle Bezel Replacement | C7257 | GMNA |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | C7258 | GMNA |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | 8637500 | GMK Domestic |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | C000574 | Holden Australia |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | C570120 | Holden Australia |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | C570130 | Holden Australia |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | C570300 | Holden Australia |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | C570320 | Holden Australia |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | C570330 | Holden Australia |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | C000574 | Holden New Zealand |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | C570120 | Holden New Zealand |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | C570130 | Holden New Zealand |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | C570300 | Holden New Zealand |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | C570320 | Holden New Zealand |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | C570330 | Holden New Zealand |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | 9420200 | GMK Overseas |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | 9420210 | GMK Overseas |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | 9420310 | GMK Overseas |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | 9420320 | GMK Overseas |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | 9425200 | GMK Overseas |
| 7025090 | Rear Seat Cushion Cover and Pad Replacement | 9425210 | GMK Overseas |
| 7025110 | Rear Seat Back Cushion Latch Release Knob Bezel Replacement | C7259 | GMNA |
| 7025110 | Rear Seat Back Cushion Latch Release Knob Bezel Replacement | 9420800 | GMK Overseas |
| 7025110 | Rear Seat Back Cushion Latch Release Knob Bezel Replacement | 9428300 | GMK Overseas |
| 7025110 | Rear Seat Back Cushion Latch Release Knob Bezel Replacement | 9428400 | GMK Overseas |
| 7025130 | Rear Seat Latch Release Handle Replacement | C7261 | GMNA |
| 7025150 | Rear Seat Latch Release Strap Bezel Replacement | C7264 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7025150 | Rear Seat Latch Release Strap Bezel Replacement | 9427500 | GMK Overseas |
| 7025170 | Rear Seat Back Latch Replacement | C7265 | GMNA |
| 7025170 | Rear Seat Back Latch Replacement | C7265 | Holden Australia |
| 7025190 | Rear Seat Back Cushion Latch Release Handle Replacement | C7266 | GMNA |
| 7025190 | Rear Seat Back Cushion Latch Release Handle Replacement | 9421600 | GMK Overseas |
| 7025190 | Rear Seat Back Cushion Latch Release Handle Replacement | 9421700 | GMK Overseas |
| 7025210 | Rear Seat Back Cushion Stowage Latch Actuator Replacement | C7268 | GMNA |
| 7025260 | Rear Seat Back Cover Replacement | C7270 | GMNA |
| 7025260 | Rear Seat Back Cover Replacement | C7290 | GMNA |
| 7025260 | Rear Seat Back Cover Replacement | 9420900 | GMK Overseas |
| 7025260 | Rear Seat Back Cover Replacement | 9420910 | GMK Overseas |
| 7025260 | Rear Seat Back Cover Replacement | 9420920 | GMK Overseas |
| 7025260 | Rear Seat Back Cover Replacement | 9427000 | GMK Overseas |
| 7025260 | Rear Seat Back Cover Replacement | 9427100 | GMK Overseas |
| 7025260 | Rear Seat Back Cover Replacement | 9427200 | GMK Overseas |
| 7025280 | Rear Seat Back Cushion Pad Replacement | C7271 | GMNA |
| 7025280 | Rear Seat Back Cushion Pad Replacement | C727100 | Holden Australia |
| 7025280 | Rear Seat Back Cushion Pad Replacement | C780000 | Holden Australia |
| 7025280 | Rear Seat Back Cushion Pad Replacement | C727100 | Holden New Zealand |
| 7025280 | Rear Seat Back Cushion Pad Replacement | 9420400 | GMK Overseas |
| 7025280 | Rear Seat Back Cushion Pad Replacement | 9420410 | GMK Overseas |
| 7025300 | Rear Seat Latch Cable Replacement | C7274 | GMNA |
| 7025300 | Rear Seat Latch Cable Replacement | C565400 | Holden Australia |
| 7025300 | Rear Seat Latch Cable Replacement | C565500 | Holden Australia |
| 7025300 | Rear Seat Latch Cable Replacement | C565400 | Holden New Zealand |
| 7025300 | Rear Seat Latch Cable Replacement | C565500 | Holden New Zealand |
| 7025320 | Rear Seat Belt Opening Bezel Replacement | C7275 | GMNA |
| 7025340 | Child Seat Bracket Access Hole Cover Replacement | C7276 | GMNA |
| 7025340 | Child Seat Bracket Access Hole Cover Replacement | 9425000 | GMK Overseas |
| 7025340 | Child Seat Bracket Access Hole Cover Replacement | T194008 | GMK Overseas |
| 7025390 | Rear Seat Back Cushion Cover and Pad Replacement | C7278 | GMNA |
| 7025390 | Rear Seat Back Cushion Cover and Pad Replacement | C571020 | Holden Australia |
| 7025390 | Rear Seat Back Cushion Cover and Pad Replacement | C571030 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7025390 | Rear Seat Back Cushion Cover and Pad Replacement | C725000 | Holden Australia |
| 7025390 | Rear Seat Back Cushion Cover and Pad Replacement | C725300 | Holden Australia |
| 7025390 | Rear Seat Back Cushion Cover and Pad Replacement | C727000 | Holden Australia |
| 7025390 | Rear Seat Back Cushion Cover and Pad Replacement | C727300 | Holden Australia |
| 7025390 | Rear Seat Back Cushion Cover and Pad Replacement | C727400 | Holden Australia |
| 7025390 | Rear Seat Back Cushion Cover and Pad Replacement | C727800 | Holden Australia |
| 7025390 | Rear Seat Back Cushion Cover and Pad Replacement | C571020 | Holden New Zealand |
| 7025390 | Rear Seat Back Cushion Cover and Pad Replacement | C571030 | Holden New Zealand |
| 7025390 | Rear Seat Back Cushion Cover and Pad Replacement | C725000 | Holden New Zealand |
| 7025390 | Rear Seat Back Cushion Cover and Pad Replacement | C727800 | Holden New Zealand |
| 7025410 | Rear Seat Anchor Plate Bezel Replacement | C7279 | GMNA |
| 7025490 | Rear Seat Cover and Seat Back Cushion Side Bolster Pad Replacement | C7282 | GMNA |
| 7025510 | Rear Seat Back Cushion Opening Trim Cover and Outer Cover Pad Replacement | C7283 | GMNA |
| 7025510 | Rear Seat Back Cushion Opening Trim Cover and Outer Cover Pad Replacement | C572210 | Holden Australia |
| 7025510 | Rear Seat Back Cushion Opening Trim Cover and Outer Cover Pad Replacement | C582100 | Holden Australia |
| 7025510 | Rear Seat Back Cushion Opening Trim Cover and Outer Cover Pad Replacement | C582200 | Holden Australia |
| 7025510 | Rear Seat Back Cushion Opening Trim Cover and Outer Cover Pad Replacement | C572210 | Holden New Zealand |
| 7025510 | Rear Seat Back Cushion Opening Trim Cover and Outer Cover Pad Replacement | C582100 | Holden New Zealand |
| 7025510 | Rear Seat Back Cushion Opening Trim Cover and Outer Cover Pad Replacement | C582200 | Holden New Zealand |
| 7025560 | Rear Seat Cushion Front Cover Replacement | C7287 | GMNA |
| 7025580 | Rear Seat Support Replacement | C7289 | GMNA |
| 7025600 | Rear Seat Back Side Cushion Pad Replacement | C7291 | GMNA |
| 7025620 | Rear Seat Back Side Cushion Cover Replacement | C7292 | GMNA |
| 7025620 | Rear Seat Back Side Cushion Cover Replacement | C571200 | Holden Australia |
| 7025620 | Rear Seat Back Side Cushion Cover Replacement | C780500 | Holden Australia |
| 7025620 | Rear Seat Back Side Cushion Cover Replacement | C780600 | Holden Australia |
| 7025620 | Rear Seat Back Side Cushion Cover Replacement | C780700 | Holden Australia |
| 7025620 | Rear Seat Back Side Cushion Cover Replacement | C780900 | Holden Australia |
| 7025620 | Rear Seat Back Side Cushion Cover Replacement | C571200 | Holden New Zealand |
| 7025670 | Rear Seat Back Cushion Latch Cable Replacement | C7294 | GMNA |
| 7025670 | Rear Seat Back Cushion Latch Cable Replacement | C9784 | GMNA |
| 7025750 | Rear Seat Latch Replacement | C7297 | GMNA |
| 7025770 | Rear Seat Strut Replacement | C7298 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7025770 | Rear Seat Strut Replacement | 9425300 | GMK Overseas |
| 7025810 | Rear Seat Adjuster Replacement | C7301 | GMNA |
| 7025830 | Rear Seat Track Rear Outboard Cover Replacement | C7304 | GMNA |
| 7025850 | Rear Seat Track Rear Inboard Cover Replacement | C7305 | GMNA |
| 7025870 | Rear Seat Anchor Cable Replacement | C7930 | GMNA |
| 7025870 | Rear Seat Anchor Cable Replacement | C9923 | GMNA |
| 7025890 | Rear Seat Recliner Inner Finish Cover Replacement - Upper | C7312 | GMNA |
| 7025910 | Rear Seat Inner Recliner Cable Replacement | C7313 | GMNA |
| 7025930 | Rear Seat Latch Cable Replacement - Inboard | C7314 | GMNA |
| 7025950 | Rear Seat Latch Cable Replacement - Outboard | C7315 | GMNA |
| 7025970 | Rear Seat Back Cushion Lock Replacement | C7316 | GMNA |
| 7025970 | Rear Seat Back Cushion Lock Replacement | C565700 | Holden Australia |
| 7025970 | Rear Seat Back Cushion Lock Replacement | C565800 | Holden Australia |
| 7025970 | Rear Seat Back Cushion Lock Replacement | C584100 | Holden Australia |
| 7025970 | Rear Seat Back Cushion Lock Replacement | C584200 | Holden Australia |
| 7025970 | Rear Seat Back Cushion Lock Replacement | C584300 | Holden Australia |
| 7025970 | Rear Seat Back Cushion Lock Replacement | C584400 | Holden Australia |
| 7025970 | Rear Seat Back Cushion Lock Replacement | C584450 | Holden Australia |
| 7025970 | Rear Seat Back Cushion Lock Replacement | C565700 | Holden New Zealand |
| 7025970 | Rear Seat Back Cushion Lock Replacement | C565800 | Holden New Zealand |
| 7025970 | Rear Seat Back Cushion Lock Replacement | C584100 | Holden New Zealand |
| 7025970 | Rear Seat Back Cushion Lock Replacement | C584200 | Holden New Zealand |
| 7025970 | Rear Seat Back Cushion Lock Replacement | C584300 | Holden New Zealand |
| 7025970 | Rear Seat Back Cushion Lock Replacement | C584400 | Holden New Zealand |
| 7025970 | Rear Seat Back Cushion Lock Replacement | C584450 | Holden New Zealand |
| 7025970 | Rear Seat Back Cushion Lock Replacement | 9423100 | GMK Overseas |
| 7026010 | Rear Seat Adjuster Handle Replacement | C7319 | GMNA |
| 7026030 | Rear Seat Recliner Handle Replacement | C7320 | GMNA |
| 7026050 | Rear Seat Back Cushion Latch Cover Replacement | C7321 | GMNA |
| 7026050 | Rear Seat Back Cushion Latch Cover Replacement | 8830100 | GMK Domestic |
| 7026070 | Rear Seat Back Cushion Latch Replacement | C7322 | GMNA |
| 7026070 | Rear Seat Back Cushion Latch Replacement | 9421300 | GMK Overseas |
| 7026070 | Rear Seat Back Cushion Latch Replacement | 9421400 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7026090 | Rear Seat Inner Recliner Replacement | C7323 | GMNA |
| 7026110 | Rear Seat Outer Recliner Replacement | C7324 | GMNA |
| 7026130 | Rear Seat Recliner Replacement | C7325 | GMNA |
| 7026130 | Rear Seat Recliner Replacement | 8830300 | GMK Domestic |
| 7026130 | Rear Seat Recliner Replacement | 9423300 | GMK Overseas |
| 7026130 | Rear Seat Recliner Replacement | 9425100 | GMK Overseas |
| 7026130 | Rear Seat Recliner Replacement | 9425110 | GMK Overseas |
| 7026150 | Rear Seat Recliner Outer Finish Cover Replacement - Inboard | C7326 | GMNA |
| 7026170 | Rear Seat Recliner Outer Finish Cover Replacement - Outboard | C7327 | GMNA |
| 7026190 | Rear Seat Back Cushion Hinge Replacement | C7328 | GMNA |
| 7026190 | Rear Seat Back Cushion Hinge Replacement | C572300 | Holden Australia |
| 7026190 | Rear Seat Back Cushion Hinge Replacement | C572300 | Holden New Zealand |
| 7026290 | Rear Seat Recliner Inner Finish Cover Replacement | C7334 | GMNA |
| 7026310 | Rear Seat Recliner Outer Finish Cover Replacement | C7335 | GMNA |
| 7026310 | Rear Seat Recliner Outer Finish Cover Replacement | 9421800 | GMK Overseas |
| 7026330 | Rear Seat Outer Recliner Rear Finish Cover Replacement | C7336 | GMNA |
| 7026350 | Rear Seat Floor Filler Trim Panel Replacement | C7387 | GMNA |
| 7026350 | Rear Seat Floor Filler Trim Panel Replacement | C9924 | GMNA |
| 7026360 | Rear Seat Back Pivot Pin Spring Replacement | | |
| 7026370 | Rear Seat Back Latch Bezel Replacement | | |
| 7026430 | Rear Seat Back Cushion Pivot Support Replacement | C7405 | GMNA |
| 7026430 | Rear Seat Back Cushion Pivot Support Replacement | 9428700 | GMK Overseas |
| 7026450 | Rear Seat Back Cushion Latch Striker Replacement | C7406 | GMNA |
| 7026450 | Rear Seat Back Cushion Latch Striker Replacement | 9422100 | GMK Overseas |
| 7026450 | Rear Seat Back Cushion Latch Striker Replacement | 9422200 | GMK Overseas |
| 7026500 | Rear Seat Cushion Trim Panel Assembly Replacement - Outboard | C7408 | GMNA |
| 7026520 | Rear Seat Cushion Trim Panel Assembly Replacement - Inboard | C7409 | GMNA |
| 7026540 | Rear Seat Cushion Trim Panel Replacement - Inner Outboard | C7410 | GMNA |
| 7026560 | Rear Seat Cushion Trim Panel Replacement - Inner Inboard | C7411 | GMNA |
| 7026560 | Rear Seat Cushion Trim Panel Replacement - Inner Inboard | 9421900 | GMK Overseas |
| 7026580 | Rear Seat Back Cushion Latch Cover Replacement - Inner | C7412 | GMNA |
| 7026600 | Rear Seat Back Cushion Latch Cover Replacement - Outer | C7413 | GMNA |
| 7026620 | Rear Seat Frame Front Finish Cover Replacement - Lower | C7414 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7026620 | Rear Seat Frame Front Finish Cover Replacement - Lower | C7437 | GMNA |
| 7026620 | Rear Seat Frame Front Finish Cover Replacement - Lower | C9968 | GMNA |
| 7026720 | 3rd Row Seat Back Latch Release Handle Replacement | C7438 | GMNA |
| 7026740 | 3rd Row Seat Back Latch Replacement | C7439 | GMNA |
| 7026790 | 3rd Row Seat Back Latch Cable Replacement | C7450 | GMNA |
| 7026920 | Rear Seat Frame Front Finish Cover Replacement | C7469 | GMNA |
| 7027000 | Rear Seat Frame Rear Finish Cover Replacement | C7472 | GMNA |
| 7027020 | Rear Seat Cushion Frame Replacement | C7473 | GMNA |
| 7027020 | Rear Seat Cushion Frame Replacement | 9425400 | GMK Overseas |
| 7027020 | Rear Seat Cushion Frame Replacement | 9425410 | GMK Overseas |
| 7027040 | Rear Seat Back Cushion Frame Replacement | C7474 | GMNA |
| 7027040 | Rear Seat Back Cushion Frame Replacement | C573020 | Holden Australia |
| 7027040 | Rear Seat Back Cushion Frame Replacement | C573030 | Holden Australia |
| 7027040 | Rear Seat Back Cushion Frame Replacement | C573040 | Holden Australia |
| 7027040 | Rear Seat Back Cushion Frame Replacement | C573020 | Holden New Zealand |
| 7027040 | Rear Seat Back Cushion Frame Replacement | C573030 | Holden New Zealand |
| 7027040 | Rear Seat Back Cushion Frame Replacement | C573040 | Holden New Zealand |
| 7027060 | Rear Seat Frame Replacement | C7475 | GMNA |
| 7027060 | Rear Seat Frame Replacement | C9826 | GMNA |
| 7027060 | Rear Seat Frame Replacement | C9960 | GMNA |
| 7027060 | Rear Seat Frame Replacement | C520100 | Holden Australia |
| 7027060 | Rear Seat Frame Replacement | C520100 | Holden New Zealand |
| 7027070 | Rear Seat Back Side Cushion Frame Replacement | | |
| 7027080 | Rear Seat Cushion Frame Retainer Replacement | C7477 | GMNA |
| 7027080 | Rear Seat Cushion Frame Retainer Replacement | C9509 | GMNA |
| 7027100 | Rear Seat Back Cushion Frame Replacement - Right Side | C7478 | GMNA |
| 7027100 | Rear Seat Back Cushion Frame Replacement - Right Side | 9427300 | GMK Overseas |
| 7027120 | Rear Seat Back Cushion Frame Replacement - Left Side | C7479 | GMNA |
| 7027290 | Rear Seat Back Cushion Hinge Cover Replacement | C7488 | GMNA |
| 7027290 | Rear Seat Back Cushion Hinge Cover Replacement | C7494 | GMNA |
| 7027290 | Rear Seat Back Cushion Hinge Cover Replacement | C7495 | GMNA |
| 7027290 | Rear Seat Back Cushion Hinge Cover Replacement | C7488 | Holden Australia |
| 7027310 | Rear Seat Hinge Bracket Replacement | C7489 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7027310 | Rear Seat Hinge Bracket Replacement | C8354 | GMNA |
| 7027310 | Rear Seat Hinge Bracket Replacement | C8355 | GMNA |
| 7027330 | Rear Seat Back Cushion Outer Hinge Replacement | C7490 | GMNA |
| 7027350 | Rear Seat Back Cushion Inner Hinge Replacement | C7491 | GMNA |
| 7027430 | 3rd Row Seat Back Hinge Replacement | C7502 | GMNA |
| 7027450 | 3rd Row Seat Back Latch Cover Replacement | C7504 | GMNA |
| 7027470 | Rear Seat 3rd Row Hinge Finish Cover Replacement | C7505 | GMNA |
| 7027490 | 3rd Row Seat Back Hinge Finish Cover Replacement | C7506 | GMNA |
| 7027510 | Rear Seat 3rd Row Load Floor Latch Replacement | C7507 | GMNA |
| 7027530 | Rear Seat 3rd Row Cushion Side Cover Replacement | C7508 | GMNA |
| 7027550 | Rear Seat Number 2 Recliner Outer Finish Cover Replacement | C7509 | GMNA |
| 7027570 | Rear Seat Number 2 Recliner Inner Finish Cover Replacement | C7510 | GMNA |
| 7027800 | Sit-N-Lift Seat Base Replacement | C7552 | GMNA |
| 7027810 | 3rd Row Seat Recliner Upper Finish Cover Replacement | | |
| 7027820 | 3rd Row Seat Recliner Lower Finish Cover Replacement | | |
| 7027840 | 3rd Row Seat Riser Front Finish Cover Replacement | | |
| 7027850 | 3rd Row Seat Riser Rear Finish Cover Replacement | | |
| 7027910 | Rear Seat Riser Finish Cover Replacement | C7585 | GMNA |
| 7027930 | Rear Seat Riser Replacement | C7586 | GMNA |
| 7027930 | Rear Seat Riser Replacement | C7587 | GMNA |
| 7027930 | Rear Seat Riser Replacement | C7588 | GMNA |
| 7027930 | Rear Seat Riser Replacement | C7589 | GMNA |
| 7027930 | Rear Seat Riser Replacement | C7840 | GMNA |
| 7027930 | Rear Seat Riser Replacement | C7841 | GMNA |
| 7027930 | Rear Seat Riser Replacement | 8638400 | GMK Domestic |
| 7027930 | Rear Seat Riser Replacement | 9425500 | GMK Overseas |
| 7027930 | Rear Seat Riser Replacement | 9425510 | GMK Overseas |
| 7027950 | 3rd Row Seat Head Restraint Replacement | C7810 | GMNA |
| 7027950 | 3rd Row Seat Head Restraint Replacement | 8751800 | GMK Domestic |
| 7027950 | 3rd Row Seat Head Restraint Replacement | C593150 | Holden Australia |
| 7027950 | 3rd Row Seat Head Restraint Replacement | C593150 | Holden New Zealand |
| 7027950 | 3rd Row Seat Head Restraint Replacement | C593160 | Holden New Zealand |
| 7027950 | 3rd Row Seat Head Restraint Replacement | 9423900 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7027950 | 3rd Row Seat Head Restraint Replacement | 9432000 | GMK Overseas |
| 7028030 | 3rd Row Seat Back Latch Cable with Pull Handle Replacement | C7838 | GMNA |
| 7028030 | 3rd Row Seat Back Latch Cable with Pull Handle Replacement | 9424100 | GMK Overseas |
| 7028050 | Rear Seat Number 2 Riser Latch Assembly Replacement | C7839 | GMNA |
| 7028070 | 3rd Row Seat Riser Replacement | C7844 | GMNA |
| 7028090 | 3rd Row Seat Cushion Cover and Pad Replacement | C7880 | GMNA |
| 7028090 | 3rd Row Seat Cushion Cover and Pad Replacement | C590120 | Holden Australia |
| 7028090 | 3rd Row Seat Cushion Cover and Pad Replacement | C590130 | Holden Australia |
| 7028090 | 3rd Row Seat Cushion Cover and Pad Replacement | C590120 | Holden New Zealand |
| 7028090 | 3rd Row Seat Cushion Cover and Pad Replacement | C590130 | Holden New Zealand |
| 7028090 | 3rd Row Seat Cushion Cover and Pad Replacement | 9426100 | GMK Overseas |
| 7028090 | 3rd Row Seat Cushion Cover and Pad Replacement | 9426200 | GMK Overseas |
| 7028090 | 3rd Row Seat Cushion Cover and Pad Replacement | 9426300 | GMK Overseas |
| 7028090 | 3rd Row Seat Cushion Cover and Pad Replacement | 9430500 | GMK Overseas |
| 7028090 | 3rd Row Seat Cushion Cover and Pad Replacement | 9430900 | GMK Overseas |
| 7028110 | 3rd Row Seat Back Cover and Pad Replacement | C7900 | GMNA |
| 7028110 | 3rd Row Seat Back Cover and Pad Replacement | C8100 | GMNA |
| 7028110 | 3rd Row Seat Back Cover and Pad Replacement | 8751700 | GMK Domestic |
| 7028110 | 3rd Row Seat Back Cover and Pad Replacement | 9426400 | GMK Overseas |
| 7028110 | 3rd Row Seat Back Cover and Pad Replacement | 9426500 | GMK Overseas |
| 7028110 | 3rd Row Seat Back Cover and Pad Replacement | 9426600 | GMK Overseas |
| 7028250 | 3rd Row Seat Cushion Frame Replacement | C7907 | GMNA |
| 7028250 | 3rd Row Seat Cushion Frame Replacement | 8823600 | GMK Domestic |
| 7028250 | 3rd Row Seat Cushion Frame Replacement | C593120 | Holden Australia |
| 7028250 | 3rd Row Seat Cushion Frame Replacement | C593130 | Holden Australia |
| 7028250 | 3rd Row Seat Cushion Frame Replacement | C593520 | Holden Australia |
| 7028250 | 3rd Row Seat Cushion Frame Replacement | C593530 | Holden Australia |
| 7028250 | 3rd Row Seat Cushion Frame Replacement | C593120 | Holden New Zealand |
| 7028250 | 3rd Row Seat Cushion Frame Replacement | C593130 | Holden New Zealand |
| 7028250 | 3rd Row Seat Cushion Frame Replacement | C593530 | Holden New Zealand |
| 7028250 | 3rd Row Seat Cushion Frame Replacement | 9431600 | GMK Overseas |
| 7028270 | 3rd Row Seat Back Frame Replacement | C7908 | GMNA |
| 7028270 | 3rd Row Seat Back Frame Replacement | C590520 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7028270 | 3rd Row Seat Back Frame Replacement | C590530 | Holden Australia |
| 7028270 | 3rd Row Seat Back Frame Replacement | C590520 | Holden New Zealand |
| 7028270 | 3rd Row Seat Back Frame Replacement | C590530 | Holden New Zealand |
| 7028270 | 3rd Row Seat Back Frame Replacement | 9431500 | GMK Overseas |
| 7028440 | Rear Seat Adjuster Track Replacement - Right Side | C8326 | GMNA |
| 7028440 | Rear Seat Adjuster Track Replacement - Right Side | 9424900 | GMK Overseas |
| 7028440 | Rear Seat Adjuster Track Replacement - Right Side | 9425700 | GMK Overseas |
| 7028460 | Rear Seat Adjuster Track Replacement - Left Side | C8327 | GMNA |
| 7028460 | Rear Seat Adjuster Track Replacement - Left Side | 9424910 | GMK Overseas |
| 7028460 | Rear Seat Adjuster Track Replacement - Left Side | 9424920 | GMK Overseas |
| 7028460 | Rear Seat Adjuster Track Replacement - Left Side | 9425800 | GMK Overseas |
| 7030010 | Front Seat Cushion Ventilation Blower Replacement | C6840 | GMNA |
| 7030010 | Front Seat Cushion Ventilation Blower Replacement | 9441100 | GMK Overseas |
| 7030030 | Driver or Passenger Seat Back Ventilation Heating and Cooling Blower Replacement | C6841 | GMNA |
| 7030030 | Driver or Passenger Seat Back Ventilation Heating and Cooling Blower Replacement | C7103 | GMNA |
| 7030030 | Driver or Passenger Seat Back Ventilation Heating and Cooling Blower Replacement | 9441200 | GMK Overseas |
| 7030050 | Driver Seat Cushion Ventilation Heating and Cooling Module Replacement | C7101 | GMNA |
| 7030070 | Passenger Seat Cushion Ventilation Heating and Cooling Module Replacement | | |
| 7030090 | Driver or Passenger Seat Back Ventilation Heating and Cooling Module Replacement | | |
| 7030110 | Driver or Passenger Seat Back Ventilation Duct Replacement | C7108 | GMNA |
| 7030130 | Driver Seat Cushion Heater Replacement | C7143 | GMNA |
| 7030150 | Driver Seat Back Cushion Heater Replacement | C7144 | GMNA |
| 7030170 | Front Seat Vent Fan Guard Replacement | C7145 | GMNA |
| 7030190 | Front Seat Vent Fan Replacement | C7146 | GMNA |
| 7030210 | Front Seat Back Cushion Vent Fan Replacement | C7147 | GMNA |
| 7030230 | Front Seat Vent Fan Mat Replacement | C7148 | GMNA |
| 7030250 | Front Seat Back Cushion Vent Fan Mat Replacement | C7149 | GMNA |
| 7030250 | Front Seat Back Cushion Vent Fan Mat Replacement | C9963 | GMNA |
| 7030300 | Driver Seat Climate Control Module Replacement | C7161 | GMNA |
| 7030320 | Front Seat Heater Control Module Replacement | N9605 | GMNA |
| 7030320 | Front Seat Heater Control Module Replacement | N9651 | GMNA |
| 7030320 | Front Seat Heater Control Module Replacement | 9417300 | GMK Overseas |
| 7030400 | Rear Seat Heater Control Module Replacement | C7168 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7030400 | Rear Seat Heater Control Module Replacement | 9011270 | GMK Domestic |
| 7030600 | Rear Seat Heater Switch Replacement | C7179 | GMNA |
| 7030620 | Driver or Passenger Seat Back Cushion Heater Replacement | C7338 | GMNA |
| 7030620 | Driver or Passenger Seat Back Cushion Heater Replacement | 8723300 | GMK Domestic |
| 7030620 | Driver or Passenger Seat Back Cushion Heater Replacement | 8723900 | GMK Domestic |
| 7030620 | Driver or Passenger Seat Back Cushion Heater Replacement | D130700 | Holden Australia |
| 7030620 | Driver or Passenger Seat Back Cushion Heater Replacement | D130710 | Holden Australia |
| 7030620 | Driver or Passenger Seat Back Cushion Heater Replacement | D500000 | Holden Australia |
| 7030620 | Driver or Passenger Seat Back Cushion Heater Replacement | 9416100 | GMK Overseas |
| 7030620 | Driver or Passenger Seat Back Cushion Heater Replacement | 9416200 | GMK Overseas |
| 7030620 | Driver or Passenger Seat Back Cushion Heater Replacement | 9417100 | GMK Overseas |
| 7030620 | Driver or Passenger Seat Back Cushion Heater Replacement | 9417200 | GMK Overseas |
| 7030640 | Driver or Passenger Seat Cushion Heater Replacement | 8723700 | GMK Domestic |
| 7030640 | Driver or Passenger Seat Cushion Heater Replacement | D130600 | Holden Australia |
| 7030640 | Driver or Passenger Seat Cushion Heater Replacement | D130610 | Holden Australia |
| 7030640 | Driver or Passenger Seat Cushion Heater Replacement | D130600 | Holden New Zealand |
| 7030640 | Driver or Passenger Seat Cushion Heater Replacement | D130610 | Holden New Zealand |
| 7030640 | Driver or Passenger Seat Cushion Heater Replacement | 9415800 | GMK Overseas |
| 7030640 | Driver or Passenger Seat Cushion Heater Replacement | 9415900 | GMK Overseas |
| 7030660 | Passenger Seat Cushion Heater Replacement | C7340 | GMNA |
| 7030660 | Passenger Seat Cushion Heater Replacement | C7340 | Holden Australia |
| 7030910 | Rear Seat Back Cushion Heater Replacement | | |
| 7030930 | Passenger Seat Heater Switch Replacement | N2400 | GMNA |
| 7030930 | Passenger Seat Heater Switch Replacement | N2424 | GMNA |
| 7030930 | Passenger Seat Heater Switch Replacement | N264200 | Holden Australia |
| 7030930 | Passenger Seat Heater Switch Replacement | N264200 | Holden New Zealand |
| 7030950 | Driver Seat Heater Switch Replacement | N2401 | GMNA |
| 7030950 | Driver Seat Heater Switch Replacement | N2418 | GMNA |
| 7030950 | Driver Seat Heater Switch Replacement | N2425 | GMNA |
| 7030950 | Driver Seat Heater Switch Replacement | 8724500 | GMK Domestic |
| 7030950 | Driver Seat Heater Switch Replacement | D130800 | Holden Australia |
| 7030950 | Driver Seat Heater Switch Replacement | N264100 | Holden Australia |
| 7030950 | Driver Seat Heater Switch Replacement | N277700 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7030950 | Driver Seat Heater Switch Replacement | D130800 | Holden New Zealand |
| 7030950 | Driver Seat Heater Switch Replacement | N264100 | Holden New Zealand |
| 7030950 | Driver Seat Heater Switch Replacement | 9351400 | GMK Overseas |
| 7030950 | Driver Seat Heater Switch Replacement | 9351410 | GMK Overseas |
| 7030950 | Driver Seat Heater Switch Replacement | 9351420 | GMK Overseas |
| 7411010 | Steering Linkage Outer Tie Rod Replacement | 3324300 | GMK Domestic |
| 7411010 | Steering Linkage Outer Tie Rod Replacement | 6351200 | GMK Overseas |
| 7411011 | Steering Linkage Outer Tie Rod Replacement - Both Sides | 3324100 | GMK Domestic |
| 7411070 | Steering Gear Boot Replacement | | |
| 7412100 | Steering Gear Replacement | 3310200 | GMK Domestic |
| 7412100 | Steering Gear Replacement | 3310400 | GMK Domestic |
| 7412100 | Steering Gear Replacement | 3321100 | GMK Domestic |
| 7412100 | Steering Gear Replacement | 3321400 | GMK Domestic |
| 7412100 | Steering Gear Replacement | M041000 | Holden Australia |
| 7412100 | Steering Gear Replacement | 6210800 | GMK Overseas |
| 7412100 | Steering Gear Replacement | 6210900 | GMK Overseas |
| 7412100 | Steering Gear Replacement | 6211100 | GMK Overseas |
| 7412100 | Steering Gear Replacement | 6350100 | GMK Overseas |
| 7412100 | Steering Gear Replacement | 6350200 | GMK Overseas |
| 7412100 | Steering Gear Replacement | 6350300 | GMK Overseas |
| 7420010 | Steering Gear Drive Coupling Replacement | E7718 | GMNA |
| 7420010 | Steering Gear Drive Coupling Replacement | E778300 | Holden Australia |
| 7420010 | Steering Gear Drive Coupling Replacement | E7783 | Holden New Zealand |
| 7420030 | Steering Gear Heat Shield Replacement | E7745 | GMNA |
| 7420030 | Steering Gear Heat Shield Replacement | E7755 | GMNA |
| 7420030 | Steering Gear Heat Shield Replacement | 6211300 | GMK Overseas |
| 7420040 | Steering Gear Pitman Shaft Replacement | | |
| 7420050 | Steering Gear Pitman Shaft Seal Replacement | E7920 | GMNA |
| 7420060 | Steering Linkage Inner Tie Rod Replacement | 3324000 | GMK Domestic |
| 7420060 | Steering Linkage Inner Tie Rod Replacement | 6470500 | GMK Overseas |
| 7420060 | Steering Linkage Inner Tie Rod Replacement | 6470600 | GMK Overseas |
| 7420060 | Steering Linkage Inner Tie Rod Replacement | 6470700 | GMK Overseas |
| 7420060 | Steering Linkage Inner Tie Rod Replacement | 6471100 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7420060 | Steering Linkage Inner Tie Rod Replacement | 6471200 | GMK Overseas |
| 7420062 | Steering Linkage Inner Tie Rod Replacement - Both Sides | 3323900 | GMK Domestic |
| 7420100 | Steering Linkage Outer Tie Rod Replacement | E8060 | Holden Australia |
| 7420100 | Steering Linkage Outer Tie Rod Replacement | E806000 | Holden Australia |
| 7420100 | Steering Linkage Outer Tie Rod Replacement | E8067 | Holden Australia |
| 7420100 | Steering Linkage Outer Tie Rod Replacement | E806700 | Holden Australia |
| 7420100 | Steering Linkage Outer Tie Rod Replacement | E806000 | Holden New Zealand |
| 7420100 | Steering Linkage Outer Tie Rod Replacement | E806700 | Holden New Zealand |
| 7420102 | Steering Linkage Outer Tie Rod Replacement - Both Sides | | |
| 7420130 | Steering Arm Replacement | E8100 | GMNA |
| 7420130 | Steering Arm Replacement | E8110 | GMNA |
| 7420150 | Power Steering Fluid Reservoir Cap Replacement | E8300 | GMNA |
| 7420150 | Power Steering Fluid Reservoir Cap Replacement | 3332200 | GMK Domestic |
| 7420150 | Power Steering Fluid Reservoir Cap Replacement | E8300 | Holden Australia |
| 7420150 | Power Steering Fluid Reservoir Cap Replacement | E830000 | Holden Australia |
| 7420150 | Power Steering Fluid Reservoir Cap Replacement | M048300 | Holden Australia |
| 7420150 | Power Steering Fluid Reservoir Cap Replacement | M048300 | Holden New Zealand |
| 7420150 | Power Steering Fluid Reservoir Cap Replacement | 6230100 | GMK Overseas |
| 7420170 | Power Steering Pump Belt Replacement | E8354 | GMNA |
| 7420170 | Power Steering Pump Belt Replacement | E975000 | Holden Australia |
| 7420170 | Power Steering Pump Belt Replacement | E975000 | Holden New Zealand |
| 7420170 | Power Steering Pump Belt Replacement | 1132700 | GMK Overseas |
| 7420190 | Power Steering Pump Belt Tensioner Pulley Replacement | E8355 | GMNA |
| 7420210 | Power Steering Pump Pulley Replacement | E8350 | GMNA |
| 7420210 | Power Steering Pump Pulley Replacement | E8360 | GMNA |
| 7420210 | Power Steering Pump Pulley Replacement | J7523 | GMNA |
| 7420210 | Power Steering Pump Pulley Replacement | E836000 | Holden Australia |
| 7420210 | Power Steering Pump Pulley Replacement | J606700 | Holden Australia |
| 7420210 | Power Steering Pump Pulley Replacement | M000214 | Holden Australia |
| 7420210 | Power Steering Pump Pulley Replacement | M043100 | Holden Australia |
| 7420210 | Power Steering Pump Pulley Replacement | E8360 | Holden New Zealand |
| 7420210 | Power Steering Pump Pulley Replacement | J606700 | Holden New Zealand |
| 7420210 | Power Steering Pump Pulley Replacement | M043100 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7420210 | Power Steering Pump Pulley Replacement | 6230300 | GMK Overseas |
| 7420230 | Power Steering Pump Shaft Seal Replacement | E8380 | GMNA |
| 7420230 | Power Steering Pump Shaft Seal Replacement | E838000 | Holden Australia |
| 7420230 | Power Steering Pump Shaft Seal Replacement | M048600 | Holden Australia |
| 7420230 | Power Steering Pump Shaft Seal Replacement | M147100 | Holden Australia |
| 7420230 | Power Steering Pump Shaft Seal Replacement | M048600 | Holden New Zealand |
| 7420230 | Power Steering Pump Shaft Seal Replacement | M147100 | Holden New Zealand |
| 7420250 | Electronic Power Steering Motor Control Module Replacement | E7631 | GMNA |
| 7420250 | Electronic Power Steering Motor Control Module Replacement | E8432 | GMNA |
| 7420250 | Electronic Power Steering Motor Control Module Replacement | E9450 | GMNA |
| 7420250 | Electronic Power Steering Motor Control Module Replacement | N6418 | GMNA |
| 7420250 | Electronic Power Steering Motor Control Module Replacement | T5781 | GMNA |
| 7420250 | Electronic Power Steering Motor Control Module Replacement | T5803 | GMNA |
| 7420250 | Electronic Power Steering Motor Control Module Replacement | N223100 | Holden Australia |
| 7420250 | Electronic Power Steering Motor Control Module Replacement | 6432100 | GMK Overseas |
| 7420270 | Power Steering Assist Motor Replacement | E8434 | GMNA |
| 7420270 | Power Steering Assist Motor Replacement | 3335000 | GMK Domestic |
| 7420270 | Power Steering Assist Motor Replacement | M990035 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M990040 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M990460 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M990670 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M991508 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M991512 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M991517 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M991523 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M991525 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M991526 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M991527 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M991528 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M991530 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M991531 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M991532 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M991533 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7420270 | Power Steering Assist Motor Replacement | M991534 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M991550 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M991690 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M992111 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M992139 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M992142 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M992143 | Holden Australia |
| 7420270 | Power Steering Assist Motor Replacement | M991512 | Holden New Zealand |
| 7420270 | Power Steering Assist Motor Replacement | M991528 | Holden New Zealand |
| 7420270 | Power Steering Assist Motor Replacement | M991533 | Holden New Zealand |
| 7420270 | Power Steering Assist Motor Replacement | M992139 | Holden New Zealand |
| 7420270 | Power Steering Assist Motor Replacement | 6270100 | GMK Overseas |
| 7420340 | Power Steering Pump Flow Control Valve Replacement | E8440 | GMNA |
| 7420340 | Power Steering Pump Flow Control Valve Replacement | E844000 | Holden Australia |
| 7420340 | Power Steering Pump Flow Control Valve Replacement | E8440 | Holden New Zealand |
| 7420360 | Steering Gear Valve Solenoid Replacement | E8441 | GMNA |
| 7420380 | Steering Gear Valve Housing Replacement | E8442 | GMNA |
| 7420430 | Power Steering Gear Inlet Hose Seal Replacement | E8605 | GMNA |
| 7420440 | Power Steering Gear Inlet and Outlet Hose Seal Replacement | | |
| 7420570 | Power Steering Gear Inlet and Outlet Hose Replacement | E8630 | GMNA |
| 7420570 | Power Steering Gear Inlet and Outlet Hose Replacement | 3332400 | GMK Domestic |
| 7420570 | Power Steering Gear Inlet and Outlet Hose Replacement | M144000 | Holden Australia |
| 7420680 | Power Steering Pump Inlet Hose Replacement | E8648 | GMNA |
| 7420680 | Power Steering Pump Inlet Hose Replacement | M048000 | Holden Australia |
| 7420700 | Power Steering Fluid Reservoir Inlet Pipe Replacement | | |
| 7420720 | Power Steering Gear Inlet Hose Replacement - Steering Gear Side | E8674 | GMNA |
| 7420720 | Power Steering Gear Inlet Hose Replacement - Steering Gear Side | 3334100 | GMK Domestic |
| 7420720 | Power Steering Gear Inlet Hose Replacement - Steering Gear Side | 6230900 | GMK Overseas |
| 7420720 | Power Steering Gear Inlet Hose Replacement - Steering Gear Side | 6230910 | GMK Overseas |
| 7420720 | Power Steering Gear Inlet Hose Replacement - Steering Gear Side | 6230920 | GMK Overseas |
| 7420720 | Power Steering Gear Inlet Hose Replacement - Steering Gear Side | 6231510 | GMK Overseas |
| 7420720 | Power Steering Gear Inlet Hose Replacement - Steering Gear Side | 6231520 | GMK Overseas |
| 7420720 | Power Steering Gear Inlet Hose Replacement - Steering Gear Side | 6232500 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7420720 | Power Steering Gear Inlet Hose Replacement - Steering Gear Side | 6232510 | GMK Overseas |
| 7420740 | Power Steering Gear Inlet Hose Replacement - Pump Side | E8675 | GMNA |
| 7420740 | Power Steering Gear Inlet Hose Replacement - Pump Side | 6230510 | GMK Overseas |
| 7420740 | Power Steering Gear Inlet Hose Replacement - Pump Side | 6230520 | GMK Overseas |
| 7420760 | Fluid Cooler Inlet and Outlet Hose Replacement | E8676 | GMNA |
| 7420760 | Fluid Cooler Inlet and Outlet Hose Replacement | 3333200 | GMK Domestic |
| 7420760 | Fluid Cooler Inlet and Outlet Hose Replacement | 6232200 | GMK Overseas |
| 7420780 | Power Steering Fluid Reservoir Outlet Hose Replacement | E8677 | GMNA |
| 7420780 | Power Steering Fluid Reservoir Outlet Hose Replacement | M048400 | Holden Australia |
| 7420780 | Power Steering Fluid Reservoir Outlet Hose Replacement | M048500 | Holden Australia |
| 7420780 | Power Steering Fluid Reservoir Outlet Hose Replacement | M048400 | Holden New Zealand |
| 7420780 | Power Steering Fluid Reservoir Outlet Hose Replacement | M048500 | Holden New Zealand |
| 7420780 | Power Steering Fluid Reservoir Outlet Hose Replacement | 6230500 | GMK Overseas |
| 7420780 | Power Steering Fluid Reservoir Outlet Hose Replacement | 6231500 | GMK Overseas |
| 7420780 | Power Steering Fluid Reservoir Outlet Hose Replacement | 6232700 | GMK Overseas |
| 7420800 | Power Steering Fluid Reservoir Inlet Hose Replacement | E8222 | GMNA |
| 7420800 | Power Steering Fluid Reservoir Inlet Hose Replacement | E8678 | GMNA |
| 7420820 | Power Steering Gear Inlet Pipe/Hose Replacement | E8679 | GMNA |
| 7420820 | Power Steering Gear Inlet Pipe/Hose Replacement | M048200 | Holden Australia |
| 7420820 | Power Steering Gear Inlet Pipe/Hose Replacement | M048200 | Holden New Zealand |
| 7420840 | Power Steering Fluid Reservoir Hose Replacement | E8680 | GMNA |
| 7420840 | Power Steering Fluid Reservoir Hose Replacement | E9479 | GMNA |
| 7420840 | Power Steering Fluid Reservoir Hose Replacement | M044400 | Holden Australia |
| 7420860 | Power Steering Gear Outlet and Fluid Reservoir Inlet Hose Replacement | E8681 | GMNA |
| 7420860 | Power Steering Gear Outlet and Fluid Reservoir Inlet Hose Replacement | M048700 | Holden Australia |
| 7420860 | Power Steering Gear Outlet and Fluid Reservoir Inlet Hose Replacement | M048700 | Holden New Zealand |
| 7420880 | Power Steering Gear Outlet Pipe/Hose Replacement | E8684 | GMNA |
| 7420880 | Power Steering Gear Outlet Pipe/Hose Replacement | E9427 | GMNA |
| 7420880 | Power Steering Gear Outlet Pipe/Hose Replacement | 3334200 | GMK Domestic |
| 7420880 | Power Steering Gear Outlet Pipe/Hose Replacement | 6210100 | GMK Overseas |
| 7420880 | Power Steering Gear Outlet Pipe/Hose Replacement | 6210200 | GMK Overseas |
| 7420880 | Power Steering Gear Outlet Pipe/Hose Replacement | 6210300 | GMK Overseas |
| 7420880 | Power Steering Gear Outlet Pipe/Hose Replacement | 6231000 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7420880 | Power Steering Gear Outlet Pipe/Hose Replacement | 6232300 | GMK Overseas |
| 7420880 | Power Steering Gear Outlet Pipe/Hose Replacement | 6232310 | GMK Overseas |
| 7420900 | Power Steering Gear Outlet Pipe/Hose Replacement - Pump Side | E8685 | GMNA |
| 7420920 | Power Steering Gear Outlet Pipe/Hose Replacement - Reservoir Outlet Side | | |
| 7421030 | Power Brake Booster Inlet Hose Replacement | E8858 | GMNA |
| 7421050 | Power Brake Booster Outlet Hose Replacement | E8859 | GMNA |
| 7421050 | Power Brake Booster Outlet Hose Replacement | H1400 | GMNA |
| 7421130 | Steering Gear Pipe and Seal Replacement | E8901 | GMNA |
| 7421130 | Steering Gear Pipe and Seal Replacement | E9451 | GMNA |
| 7421130 | Steering Gear Pipe and Seal Replacement | E9559 | GMNA |
| 7421130 | Steering Gear Pipe and Seal Replacement | 3332600 | GMK Domestic |
| 7421150 | Power Steering Pump Inlet Pipe Replacement | E8904 | GMNA |
| 7421170 | Power Steering Fluid Cooling Pipe Replacement | E8906 | GMNA |
| 7421170 | Power Steering Fluid Cooling Pipe Replacement | M044400 | Holden New Zealand |
| 7421190 | Fluid Cooler Outlet Hose Replacement | | |
| 7421210 | Power Steering Fluid Cooler Replacement | E8420 | GMNA |
| 7421210 | Power Steering Fluid Cooler Replacement | E8940 | GMNA |
| 7421210 | Power Steering Fluid Cooler Replacement | E9402 | GMNA |
| 7421210 | Power Steering Fluid Cooler Replacement | M048310 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | E8604 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9006 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9050 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9404 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9406 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9409 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9412 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9416 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9421 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9434 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9456 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9790 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9793 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9794 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7421280 | Power Steering Pump Replacement | E9796 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9798 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9851 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9854 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9855 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9856 | GMNA |
| 7421280 | Power Steering Pump Replacement | E9955 | GMNA |
| 7421280 | Power Steering Pump Replacement | J1481 | GMNA |
| 7421280 | Power Steering Pump Replacement | J1504 | GMNA |
| 7421280 | Power Steering Pump Replacement | J7501 | GMNA |
| 7421280 | Power Steering Pump Replacement | K2276 | GMNA |
| 7421280 | Power Steering Pump Replacement | K2285 | GMNA |
| 7421280 | Power Steering Pump Replacement | K2287 | GMNA |
| 7421280 | Power Steering Pump Replacement | K4188 | GMNA |
| 7421280 | Power Steering Pump Replacement | K6725 | GMNA |
| 7421280 | Power Steering Pump Replacement | K9700 | GMNA |
| 7421280 | Power Steering Pump Replacement | K9800 | GMNA |
| 7421280 | Power Steering Pump Replacement | N2907 | GMNA |
| 7421280 | Power Steering Pump Replacement | N3461 | GMNA |
| 7421280 | Power Steering Pump Replacement | N9540 | GMNA |
| 7421280 | Power Steering Pump Replacement | R9702 | GMNA |
| 7421280 | Power Steering Pump Replacement | T1170 | GMNA |
| 7421280 | Power Steering Pump Replacement | T1743 | GMNA |
| 7421280 | Power Steering Pump Replacement | T1853 | GMNA |
| 7421280 | Power Steering Pump Replacement | T5681 | GMNA |
| 7421280 | Power Steering Pump Replacement | T5689 | GMNA |
| 7421280 | Power Steering Pump Replacement | T5690 | GMNA |
| 7421280 | Power Steering Pump Replacement | T7410 | GMNA |
| 7421280 | Power Steering Pump Replacement | 3328400 | GMK Domestic |
| 7421280 | Power Steering Pump Replacement | 3328500 | GMK Domestic |
| 7421280 | Power Steering Pump Replacement | E870000 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | E9050 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | E976000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7421280 | Power Steering Pump Replacement | F000191 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | F504150 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | J150000 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | J150100 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | J150200 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | J150300 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | J150700 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | J150800 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | J151000 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | J151100 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | K228300 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | K228400 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | L202000 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M000157 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M000163 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M000166 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M000172 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M000178 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M000181 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M000184 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M000190 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M000193 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M000196 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M000205 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M000211 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M000217 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M012500 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M036200 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M041100 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M147000 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M147200 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M147500 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M798000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7421280 | Power Steering Pump Replacement | M844000 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M991111 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M991115 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M991121 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M991122 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M991500 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | M991502 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | N221310 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | N221990 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | N502100 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | T080601 | Holden Australia |
| 7421280 | Power Steering Pump Replacement | E9050 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | EBB0211A | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | F000206 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | F00023 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | F100600 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | F109300 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | F202600 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | F212300D2 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | F504150 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | FION111 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | GFN04019 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | GFN04020 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | GFN04021 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | H0000KS | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | H000168 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | H000188 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | H000195A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | H000198A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | H000204A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | H000207A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | H000293 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | H307400 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7421280 | Power Steering Pump Replacement | H670100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | H670200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | H67024 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | H67024A | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | H67024B | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | H67024C | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | H67024D | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | HCC0001 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | HO37500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J000487 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J000695NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J000920 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J000923 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J010100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J010800 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J010900 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J030400 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J030500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J035500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J0356NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J050900 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J070500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J072400 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J077000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J077100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J079400 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J080600 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J082500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J083500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J084200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J085200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J085500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J095500 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7421280 | Power Steering Pump Replacement | J100000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J112500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J112700A2 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J112700A3 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J130400 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J130500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J146200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J1500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J150000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J150100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J1507 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J150700 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J151700 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J164000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J180500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J182500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J188200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J207029NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J213510A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J230000A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J230020A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J230020A3 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J230020ZC | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J301020 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J306300 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J310050A3 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J312000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J313500A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J313550A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J313700 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J313800 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J313910 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J314300A1 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7421280 | Power Steering Pump Replacement | J314500A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J314750A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J315500A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J315600A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J316500A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J316615 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J316700 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J316800 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J317220 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J317410 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J317510 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J320250A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J320250A3 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J330050A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J335550A2 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J338100A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J338200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J338300 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J3391 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J339100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J3392 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J339200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J3394 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J340010A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J340100A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J340300A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J340600 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J340600A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J3421 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J348500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J350100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J350200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J352100 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7421280 | Power Steering Pump Replacement | J4500015 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J450080 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J463005 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J491720 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J491820 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J492500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J494300 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J500500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J533200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J533400 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J539200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J539500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J539600 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J586000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J586100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J586200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J586400 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J591200A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J5921 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J592800NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J595200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J5952NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J595400 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J595500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J595555 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J595700 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J601200A2 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J601640 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J604100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J607100A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J607250A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J607700 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J608700 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7421280 | Power Steering Pump Replacement | J609100A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J609150A2 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J617500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J636100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J638200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J687510 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J700500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J702400A | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J703100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J713100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J735100A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J735100A2 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J735100A3 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J740700 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J740900 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J741000NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J742500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J745500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J745610 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J794000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J794300 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J795200A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J795200A2 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J805170A2 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J850210 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J850220061 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J850233 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J850237 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J851329 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J852600 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J854400 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J982500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | J987510A1 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7421280 | Power Steering Pump Replacement | JO823 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K00013NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K00014NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K00015NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K000324 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K000327 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K012100A4 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K013100A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K013120A3 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K013120A5 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K013500A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K013600A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K063000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K064300 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K0662 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K0664 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K0666 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K080200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K102000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K105100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K1065 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K1162 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K119000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K119300 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K1210 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K121000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K123456 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K202300 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K203000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K204000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K205100A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K205100A3 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K205160 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7421280 | Power Steering Pump Replacement | K2056 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K206120 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K210000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K2145 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K220000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K224100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K224200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K224300 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K228300 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K248000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K2491 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K270200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K2722 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K272200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K272300 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K2724 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K411000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K411200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4405 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4520 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4522 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K452200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K453200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K454200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K455000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4560 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K470000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4720 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K472000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K472010 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4800NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4801NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4802NZ | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7421280 | Power Steering Pump Replacement | K4803NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4804NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4806NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4808NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4809NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4810NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4811NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4812NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4813NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4815NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K4820NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K502100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K502600 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K528000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K607310 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K608200A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K609550 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K6301 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K638500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K655600A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K700100A2 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K700500A3 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K700800 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K703161 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K7102 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K740000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K760000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | K770000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | L002301 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | L006300A3 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | L006310A2 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | L006370 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | L0400 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7421280 | Power Steering Pump Replacement | L116000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | L122000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | L202000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | L2021 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | L5000E1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | L701250A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M000166 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M000172 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M000184 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M000190 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M000193 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M000196 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M000205 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M012500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M018500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M035100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M041100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M044100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M044110 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M044200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M044300 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M047500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M047510 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M147200 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | M147500 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N000010 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N000204 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N000205 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N000494 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N000500003 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N000500A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N000514 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N000600001 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7421280 | Power Steering Pump Replacement | N000771 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N001400001 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N0443300 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N124200A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N1800 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N180000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N221900 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N221940 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N221990 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N223100 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N2680 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N309700 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N310000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N317700A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N317701 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N320003 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N320010 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N320032 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N320037 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N354000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N359400 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N401500001 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N411599A1 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N430000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N437000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N456000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N457599 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N4620 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N501600NZ | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N506026 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N506600001 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N507000001 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N510000 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7421280 | Power Steering Pump Replacement | N760599 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | N8000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NPOLICEBCM | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZE5501 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZE5503 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZE5504 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZE5505 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZE5506 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZE5507 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZE5508 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZE5509 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZE5510 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZE5511 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZE5512 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZE5513 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZE5514 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZE5515 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZE5516 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZE5519 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZEK2720 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | NZPOLBCM | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | PSUBFRMCK | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | R091000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | R094000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | R902400A3 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | ROSCO35 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | RR00020 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | RR00028 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | RR00036 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | S015000A2 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | S020000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | S552000 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | SCH1511A | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7421280 | Power Steering Pump Replacement | SCH3110D | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | SNAPSHOT | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | T081102 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | T582101 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | T780901 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | T781101 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | T881601 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | T881602 | Holden New Zealand |
| 7421280 | Power Steering Pump Replacement | 6231700 | GMK Overseas |
| 7421280 | Power Steering Pump Replacement | 6231710 | GMK Overseas |
| 7421280 | Power Steering Pump Replacement | 6231720 | GMK Overseas |
| 7421280 | Power Steering Pump Replacement | 6231900 | GMK Overseas |
| 7421280 | Power Steering Pump Replacement | 6231910 | GMK Overseas |
| 7421280 | Power Steering Pump Replacement | 6231920 | GMK Overseas |
| 7421280 | Power Steering Pump Replacement | 6231930 | GMK Overseas |
| 7421280 | Power Steering Pump Replacement | 6501006 | GMK Overseas |
| 7421280 | Power Steering Pump Replacement | F333333 | GMK Overseas |
| 7421280 | Power Steering Pump Replacement | H333333 | GMK Overseas |
| 7421280 | Power Steering Pump Replacement | T794005 | GMK Overseas |
| 7421340 | Power Steering Fluid Reservoir Replacement | E9070 | GMNA |
| 7421340 | Power Steering Fluid Reservoir Replacement | E9102 | GMNA |
| 7421340 | Power Steering Fluid Reservoir Replacement | 3330000 | GMK Domestic |
| 7421340 | Power Steering Fluid Reservoir Replacement | E9070 | Holden Australia |
| 7421340 | Power Steering Fluid Reservoir Replacement | E910000 | Holden Australia |
| 7421340 | Power Steering Fluid Reservoir Replacement | M050500 | Holden Australia |
| 7421340 | Power Steering Fluid Reservoir Replacement | E9100 | Holden New Zealand |
| 7421340 | Power Steering Fluid Reservoir Replacement | E910000 | Holden New Zealand |
| 7421340 | Power Steering Fluid Reservoir Replacement | M050500 | Holden New Zealand |
| 7421340 | Power Steering Fluid Reservoir Replacement | 6230600 | GMK Overseas |
| 7421340 | Power Steering Fluid Reservoir Replacement | 6232100 | GMK Overseas |
| 7421340 | Power Steering Fluid Reservoir Replacement | 6261500 | GMK Overseas |
| 7421360 | Power Steering Fluid Reservoir Replacement - Lower | E9071 | GMNA |
| 7421380 | Power Steering Fluid Reservoir Replacement - Upper | E9072 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7421490 | Steering Gear Boot Replacement | E9494 | GMNA |
| 7421490 | Steering Gear Boot Replacement | E9507 | GMNA |
| 7421490 | Steering Gear Boot Replacement | E9527 | GMNA |
| 7421490 | Steering Gear Boot Replacement | E9538 | GMNA |
| 7421490 | Steering Gear Boot Replacement | E9540 | GMNA |
| 7421490 | Steering Gear Boot Replacement | E9558 | GMNA |
| 7421490 | Steering Gear Boot Replacement | E9610 | GMNA |
| 7421490 | Steering Gear Boot Replacement | 3321700 | GMK Domestic |
| 7421490 | Steering Gear Boot Replacement | 6472100 | GMK Overseas |
| 7421490 | Steering Gear Boot Replacement | 6472200 | GMK Overseas |
| 7421490 | Steering Gear Boot Replacement | 6472400 | GMK Overseas |
| 7421630 | Steering Gear Housing Replacement | E9660 | GMNA |
| 7421630 | Steering Gear Housing Replacement | M130050 | Holden New Zealand |
| 7421630 | Steering Gear Housing Replacement | 6351300 | GMK Overseas |
| 7421650 | Steering Gear Stub Shaft Seal and Bearing Replacement | E7694 | GMNA |
| 7421650 | Steering Gear Stub Shaft Seal and Bearing Replacement | E9669 | GMNA |
| 7421730 | Steering Gear Bushing Replacement | E9520 | GMNA |
| 7421730 | Steering Gear Bushing Replacement | E9650 | GMNA |
| 7421730 | Steering Gear Bushing Replacement | E9672 | GMNA |
| 7421740 | Steering Gear Replacement | M041010 | Holden New Zealand |
| 7421740 | Steering Gear Replacement | 6473000 | GMK Overseas |
| 7421740 | Steering Gear Replacement | 7111200 | GMK Overseas |
| 7422160 | Steering Power Variable Control Module Replacement | N5639 | GMNA |
| 7422180 | Power Steering Control Module Replacement | N5640 | GMNA |
| 7429949 | Customer Concern Not Duplicated (CCND) - Steering | 3115720 | GMK Domestic |
| 7429949 | Customer Concern Not Duplicated (CCND) - Steering | 3310100 | GMK Domestic |
| 7430010 | Pitman Arm Replacement | E7900 | GMNA |
| 7430010 | Pitman Arm Replacement | E790000 | Holden Australia |
| 7430010 | Pitman Arm Replacement | E7900 | Holden New Zealand |
| 7430010 | Pitman Arm Replacement | E790000 | Holden New Zealand |
| 7430060 | Idler Arm Replacement | E7901 | GMNA |
| 7430060 | Idler Arm Replacement | E7960 | GMNA |
| 7430060 | Idler Arm Replacement | E7965 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7430060 | Idler Arm Replacement | E7966 | GMNA |
| 7430060 | Idler Arm Replacement | E7967 | GMNA |
| 7430060 | Idler Arm Replacement | E9429 | GMNA |
| 7430060 | Idler Arm Replacement | B432000 | Holden Australia |
| 7430060 | Idler Arm Replacement | E796000 | Holden Australia |
| 7430060 | Idler Arm Replacement | E7960 | Holden New Zealand |
| 7430060 | Idler Arm Replacement | E796000 | Holden New Zealand |
| 7430110 | Relay Rod Replacement | E7980 | GMNA |
| 7430110 | Relay Rod Replacement | E7990 | GMNA |
| 7430110 | Relay Rod Replacement | E798000 | Holden Australia |
| 7430110 | Relay Rod Replacement | E7940 | Holden New Zealand |
| 7430110 | Relay Rod Replacement | E794000 | Holden New Zealand |
| 7430110 | Relay Rod Replacement | E7945 | Holden New Zealand |
| 7430130 | Steering Linkage Shock Absorber Replacement | E8000 | GMNA |
| 7430130 | Steering Linkage Shock Absorber Replacement | E8020 | GMNA |
| 7430130 | Steering Linkage Shock Absorber Replacement | E8030 | GMNA |
| 7430130 | Steering Linkage Shock Absorber Replacement | E8031 | GMNA |
| 7430130 | Steering Linkage Shock Absorber Replacement | E8037 | GMNA |
| 7430130 | Steering Linkage Shock Absorber Replacement | E8050 | GMNA |
| 7430130 | Steering Linkage Shock Absorber Replacement | E8051 | GMNA |
| 7430130 | Steering Linkage Shock Absorber Replacement | E8057 | GMNA |
| 7430130 | Steering Linkage Shock Absorber Replacement | E802000 | Holden Australia |
| 7430130 | Steering Linkage Shock Absorber Replacement | E802000 | Holden New Zealand |
| 7430150 | Steering Linkage Inner Tie Rod Replacement | E8040 | GMNA |
| 7430150 | Steering Linkage Inner Tie Rod Replacement | E804000 | Holden Australia |
| 7430150 | Steering Linkage Inner Tie Rod Replacement | E804100 | Holden Australia |
| 7430150 | Steering Linkage Inner Tie Rod Replacement | E804000 | Holden New Zealand |
| 7430150 | Steering Linkage Inner Tie Rod Replacement | E804100 | Holden New Zealand |
| 7430151 | Steering Linkage Inner Tie Rod Replacement - Both Sides | E8047 | GMNA |
| 7430151 | Steering Linkage Inner Tie Rod Replacement - Both Sides | 3131002 | GMK Domestic |
| 7430151 | Steering Linkage Inner Tie Rod Replacement - Both Sides | E804700 | Holden Australia |
| 7430151 | Steering Linkage Inner Tie Rod Replacement - Both Sides | E804700 | Holden New Zealand |
| 7430220 | Steering Linkage Outer Tie Rod Replacement | E8060 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7430220 | Steering Linkage Outer Tie Rod Replacement | E8061 | Holden New Zealand |
| 7430220 | Steering Linkage Outer Tie Rod Replacement | E8067 | Holden New Zealand |
| 7430220 | Steering Linkage Outer Tie Rod Replacement | E8080 | Holden New Zealand |
| 7430221 | Steering Linkage Outer Tie Rod Replacement - Both Sides | E8067 | GMNA |
| 7430290 | Tie Rod Arm Replacement | E8080 | GMNA |
| 7430290 | Tie Rod Arm Replacement | 6470300 | GMK Overseas |
| 7439949 | Customer Concern Not Duplicated (CCND) - Steering | | |
| 7440030 | Steering Wheel Pad Insert Replacement | 6423300 | GMK Domestic |
| 7440050 | Steering Wheel Spoke Cover Replacement | E7013 | GMNA |
| 7440050 | Steering Wheel Spoke Cover Replacement | E9411 | GMNA |
| 7440050 | Steering Wheel Spoke Cover Replacement | 3221800 | GMK Domestic |
| 7440050 | Steering Wheel Spoke Cover Replacement | C000514 | Holden Australia |
| 7440050 | Steering Wheel Spoke Cover Replacement | C000514 | Holden New Zealand |
| 7440050 | Steering Wheel Spoke Cover Replacement | 6411800 | GMK Overseas |
| 7440070 | Steering Wheel Spoke Lower Cover Replacement | E7014 | GMNA |
| 7440090 | Steering Wheel Opening Cover Replacement | E7016 | GMNA |
| 7440110 | Steering Wheel Horn Cap Replacement | E7019 | GMNA |
| 7440110 | Steering Wheel Horn Cap Replacement | 6411300 | GMK Overseas |
| 7440110 | Steering Wheel Horn Cap Replacement | 641130A | GMK Overseas |
| 7440130 | Steering Wheel Replacement | E7020 | GMNA |
| 7440130 | Steering Wheel Replacement | 3111490 | GMK Domestic |
| 7440130 | Steering Wheel Replacement | 3221100 | GMK Domestic |
| 7440130 | Steering Wheel Replacement | 6410100 | GMK Overseas |
| 7440130 | Steering Wheel Replacement | 641010A | GMK Overseas |
| 7440150 | Steering Wheel Shroud Replacement | E7024 | GMNA |
| 7440150 | Steering Wheel Shroud Replacement | E7030 | GMNA |
| 7440200 | Turn Signal Multifunction Switch Replacement | E7059 | GMNA |
| 7440200 | Turn Signal Multifunction Switch Replacement | E7070 | GMNA |
| 7440200 | Turn Signal Multifunction Switch Replacement | N2229 | GMNA |
| 7440200 | Turn Signal Multifunction Switch Replacement | E7059 | Holden Australia |
| 7440200 | Turn Signal Multifunction Switch Replacement | N202600 | Holden Australia |
| 7440200 | Turn Signal Multifunction Switch Replacement | N218000 | Holden Australia |
| 7440200 | Turn Signal Multifunction Switch Replacement | N202600 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 7440200 | Turn Signal Multifunction Switch Replacement | 6410700 | GMK Overseas |
| 7440280 | Steering Column Tilt Wheel Release Lever Replacement | E7080 | GMNA |
| 7440280 | Steering Column Tilt Wheel Release Lever Replacement | E7085 | GMNA |
| 7440280 | Steering Column Tilt Wheel Release Lever Replacement | E9502 | GMNA |
| 7440280 | Steering Column Tilt Wheel Release Lever Replacement | E708000 | Holden Australia |
| 7440280 | Steering Column Tilt Wheel Release Lever Replacement | M015300 | Holden Australia |
| 7440280 | Steering Column Tilt Wheel Release Lever Replacement | M015300 | Holden New Zealand |
| 7440320 | Turn Signal Switch Cancel Cam Position Plate Replacement | E7102 | GMNA |
| 7440340 | Turn Signal Cancel Cam and Steering Shaft Upper Bearing Spring Replacement | E7103 | GMNA |
| 7440360 | Turn Signal Switch Bracket Replacement | E7104 | GMNA |
| 7440360 | Turn Signal Switch Bracket Replacement | E7265 | GMNA |
| 7440400 | Steering Angle Sensor Replacement | E7115 | GMNA |
| 7440400 | Steering Angle Sensor Replacement | H2579 | GMNA |
| 7440400 | Steering Angle Sensor Replacement | N221300 | Holden Australia |
| 7440400 | Steering Angle Sensor Replacement | N221300 | Holden New Zealand |
| 7440400 | Steering Angle Sensor Replacement | 6432300 | GMK Overseas |
| 7440420 | Steering Column Tilt Wheel Switch Replacement | E7119 | GMNA |
| 7440440 | Steering Column Tilt Wheel and Telescope Switch Replacement | E7120 | GMNA |
| 7440490 | Steering Column Tilt Wheel Actuator Motor Replacement | E7123 | GMNA |
| 7440490 | Steering Column Tilt Wheel Actuator Motor Replacement | E7126 | GMNA |
| 7440540 | Steering Column Telescope Actuator Motor Replacement | E7125 | GMNA |
| 7440590 | Steering Column Telescope Switch Replacement | E7128 | GMNA |
| 7440610 | Steering Column Telescope Actuator Replacement | E7129 | GMNA |
| 7440620 | Steering Column Telescope Actuator Cable Replacement | | |
| 7440630 | Steering Column Tilt Wheel and Telescope Control Module Replacement | | |
| 7440650 | Steering Column Tilt Wheel Actuator Replacement | | |
| 7440700 | Ignition Lock Cylinder Bezel Replacement | | |
| 7440750 | Steering Column Shroud Replacement | E7225 | GMNA |
| 7440770 | Steering Column Upper Trim Cover Replacement | E7073 | GMNA |
| 7440770 | Steering Column Upper Trim Cover Replacement | E7074 | GMNA |
| 7440770 | Steering Column Upper Trim Cover Replacement | E7230 | GMNA |
| 7440770 | Steering Column Upper Trim Cover Replacement | 3224800 | GMK Domestic |
| 7440770 | Steering Column Upper Trim Cover Replacement | M018100 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8030201 | Stabilizer Shaft Link Replacement - Both Sides | F122100 | Holden New Zealand |
| 8030201 | Stabilizer Shaft Link Replacement - Both Sides | 2152900 | GMK Overseas |
| 8030201 | Stabilizer Shaft Link Replacement - Both Sides | 2180300 | GMK Overseas |
| 8030201 | Stabilizer Shaft Link Replacement - Both Sides | 2312700 | GMK Overseas |
| 8030270 | Stabilizer Shaft Replacement | E2160 | GMNA |
| 8030270 | Stabilizer Shaft Replacement | T2601 | GMNA |
| 8030270 | Stabilizer Shaft Replacement | 3410200 | GMK Domestic |
| 8030270 | Stabilizer Shaft Replacement | E109100 | Holden Australia |
| 8030270 | Stabilizer Shaft Replacement | E216000 | Holden Australia |
| 8030270 | Stabilizer Shaft Replacement | E109100 | Holden New Zealand |
| 8030270 | Stabilizer Shaft Replacement | E2160 | Holden New Zealand |
| 8030270 | Stabilizer Shaft Replacement | E216000 | Holden New Zealand |
| 8030270 | Stabilizer Shaft Replacement | 2150500 | GMK Overseas |
| 8030290 | Stabilizer Shaft Insulator Replacement | E2179 | GMNA |
| 8030290 | Stabilizer Shaft Insulator Replacement | E109150 | Holden Australia |
| 8030460 | Front Wheel Bearing Lubricant Cap Replacement | E2230 | GMNA |
| 8030540 | Front Wheel Hub, Bearing, and Seal Replacement | E2239 | GMNA |
| 8030540 | Front Wheel Hub, Bearing, and Seal Replacement | E2530 | GMNA |
| 8030540 | Front Wheel Hub, Bearing, and Seal Replacement | E2531 | GMNA |
| 8030540 | Front Wheel Hub, Bearing, and Seal Replacement | H9744 | GMNA |
| 8030540 | Front Wheel Hub, Bearing, and Seal Replacement | H9759 | GMNA |
| 8030540 | Front Wheel Hub, Bearing, and Seal Replacement | H9765 | GMNA |
| 8030540 | Front Wheel Hub, Bearing, and Seal Replacement | 3440300 | GMK Domestic |
| 8030540 | Front Wheel Hub, Bearing, and Seal Replacement | 3540400 | GMK Domestic |
| 8030540 | Front Wheel Hub, Bearing, and Seal Replacement | E115030 | Holden Australia |
| 8030540 | Front Wheel Hub, Bearing, and Seal Replacement | E115130 | Holden Australia |
| 8030540 | Front Wheel Hub, Bearing, and Seal Replacement | E115230 | Holden Australia |
| 8030540 | Front Wheel Hub, Bearing, and Seal Replacement | E115130 | Holden New Zealand |
| 8030540 | Front Wheel Hub, Bearing, and Seal Replacement | E226800 | Holden New Zealand |
| 8030920 | Front Wheel Bearing and Hub Replacement | E2320 | GMNA |
| 8030920 | Front Wheel Bearing and Hub Replacement | 4310210 | GMK Domestic |
| 8030920 | Front Wheel Bearing and Hub Replacement | 4310400 | GMK Domestic |
| 8030920 | Front Wheel Bearing and Hub Replacement | E115000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8030920 | Front Wheel Bearing and Hub Replacement | E115100 | Holden Australia |
| 8030920 | Front Wheel Bearing and Hub Replacement | E115200 | Holden Australia |
| 8030920 | Front Wheel Bearing and Hub Replacement | E119000 | Holden Australia |
| 8030920 | Front Wheel Bearing and Hub Replacement | E119100 | Holden Australia |
| 8030920 | Front Wheel Bearing and Hub Replacement | E119200 | Holden Australia |
| 8030920 | Front Wheel Bearing and Hub Replacement | E115000 | Holden New Zealand |
| 8030920 | Front Wheel Bearing and Hub Replacement | E115100 | Holden New Zealand |
| 8030920 | Front Wheel Bearing and Hub Replacement | E115200 | Holden New Zealand |
| 8030920 | Front Wheel Bearing and Hub Replacement | E116200 | Holden New Zealand |
| 8030920 | Front Wheel Bearing and Hub Replacement | E119000 | Holden New Zealand |
| 8030920 | Front Wheel Bearing and Hub Replacement | E119100 | Holden New Zealand |
| 8030920 | Front Wheel Bearing and Hub Replacement | 2130500 | GMK Overseas |
| 8030920 | Front Wheel Bearing and Hub Replacement | 2130600 | GMK Overseas |
| 8030920 | Front Wheel Bearing and Hub Replacement | 2133100 | GMK Overseas |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | E2327 | GMNA |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | E2747 | GMNA |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | 3440102 | GMK Domestic |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | 4310200 | GMK Domestic |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | E222800 | Holden New Zealand |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | E224400 | Holden New Zealand |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | E224900 | Holden New Zealand |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | E2264 | Holden New Zealand |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | E226400 | Holden New Zealand |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | E2265 | Holden New Zealand |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | E226500 | Holden New Zealand |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | E2269 | Holden New Zealand |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | E226900 | Holden New Zealand |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | E234000 | Holden New Zealand |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | E234400 | Holden New Zealand |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | E2345 | Holden New Zealand |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | E2348 | Holden New Zealand |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | E2349 | Holden New Zealand |
| 8030921 | Front Wheel Bearing and Hub Replacement - Both Sides | 2130700 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8030960 | Front Wheel Drive Shaft Bearing Replacement | | |
| 8031080 | Steering Knuckle Replacement | E2520 | GMNA |
| 8031080 | Steering Knuckle Replacement | E2540 | GMNA |
| 8031080 | Steering Knuckle Replacement | E2541 | GMNA |
| 8031080 | Steering Knuckle Replacement | E2520 | Holden Australia |
| 8031080 | Steering Knuckle Replacement | E252000 | Holden Australia |
| 8031080 | Steering Knuckle Replacement | E2521 | Holden Australia |
| 8031080 | Steering Knuckle Replacement | E252100 | Holden Australia |
| 8031080 | Steering Knuckle Replacement | E252200 | Holden Australia |
| 8031080 | Steering Knuckle Replacement | E252300 | Holden Australia |
| 8031080 | Steering Knuckle Replacement | E252700 | Holden Australia |
| 8031080 | Steering Knuckle Replacement | E252800 | Holden Australia |
| 8031080 | Steering Knuckle Replacement | E2520 | Holden New Zealand |
| 8031080 | Steering Knuckle Replacement | E252000 | Holden New Zealand |
| 8031080 | Steering Knuckle Replacement | 2131100 | GMK Overseas |
| 8031080 | Steering Knuckle Replacement | 213110B | GMK Overseas |
| 8031080 | Steering Knuckle Replacement | 2131200 | GMK Overseas |
| 8031130 | Steering Knuckle Upper Ball Stud Replacement | E2522 | GMNA |
| 8031160 | Steering Knuckle Lower Ball Stud Replacement | | |
| 8031440 | Jounce Bumper Replacement | C0188 | GMNA |
| 8031440 | Jounce Bumper Replacement | C0189 | GMNA |
| 8031440 | Jounce Bumper Replacement | C0190 | GMNA |
| 8031440 | Jounce Bumper Replacement | E2820 | GMNA |
| 8031440 | Jounce Bumper Replacement | E9546 | GMNA |
| 8031490 | Front Lower Control Arm Bumper Replacement | E2830 | GMNA |
| 8031490 | Front Lower Control Arm Bumper Replacement | R629044 | GMK Overseas |
| 8031540 | Upper Control Arm Ball Joint Replacement | E2920 | GMNA |
| 8031540 | Upper Control Arm Ball Joint Replacement | 3224200 | GMK Domestic |
| 8031540 | Upper Control Arm Ball Joint Replacement | E102000 | Holden Australia |
| 8031540 | Upper Control Arm Ball Joint Replacement | E102000 | Holden New Zealand |
| 8031541 | Upper Control Arm Ball Joint Replacement - Both Sides | E2927 | GMNA |
| 8031541 | Upper Control Arm Ball Joint Replacement - Both Sides | E102300 | Holden Australia |
| 8031541 | Upper Control Arm Ball Joint Replacement - Both Sides | E102400 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8031541 | Upper Control Arm Ball Joint Replacement - Both Sides | E102300 | Holden New Zealand |
| 8031541 | Upper Control Arm Ball Joint Replacement - Both Sides | E102400 | Holden New Zealand |
| 8031650 | Lower Control Arm Ball Joint Replacement | E2930 | GMNA |
| 8031650 | Lower Control Arm Ball Joint Replacement | E5581 | GMNA |
| 8031650 | Lower Control Arm Ball Joint Replacement | E9436 | GMNA |
| 8031650 | Lower Control Arm Ball Joint Replacement | E293100 | Holden Australia |
| 8031650 | Lower Control Arm Ball Joint Replacement | E293700 | Holden Australia |
| 8031650 | Lower Control Arm Ball Joint Replacement | E293000 | Holden New Zealand |
| 8031650 | Lower Control Arm Ball Joint Replacement | E293100 | Holden New Zealand |
| 8031650 | Lower Control Arm Ball Joint Replacement | 2150900 | GMK Overseas |
| 8031650 | Lower Control Arm Ball Joint Replacement | 2151100 | GMK Overseas |
| 8031651 | Lower Control Arm Ball Joint Replacement - Both Sides | E2937 | GMNA |
| 8031651 | Lower Control Arm Ball Joint Replacement - Both Sides | 3224602 | GMK Domestic |
| 8031651 | Lower Control Arm Ball Joint Replacement - Both Sides | 3520200 | GMK Domestic |
| 8031651 | Lower Control Arm Ball Joint Replacement - Both Sides | E103000 | Holden Australia |
| 8031651 | Lower Control Arm Ball Joint Replacement - Both Sides | E103300 | Holden Australia |
| 8031651 | Lower Control Arm Ball Joint Replacement - Both Sides | E103400 | Holden Australia |
| 8031651 | Lower Control Arm Ball Joint Replacement - Both Sides | E103000 | Holden New Zealand |
| 8031651 | Lower Control Arm Ball Joint Replacement - Both Sides | E103300 | Holden New Zealand |
| 8031651 | Lower Control Arm Ball Joint Replacement - Both Sides | E103400 | Holden New Zealand |
| 8031651 | Lower Control Arm Ball Joint Replacement - Both Sides | 2151200 | GMK Overseas |
| 8031850 | Front Spring Replacement | E3020 | GMNA |
| 8031850 | Front Spring Replacement | E3030 | GMNA |
| 8031850 | Front Spring Replacement | E3031 | GMNA |
| 8031850 | Front Spring Replacement | E3037 | GMNA |
| 8031850 | Front Spring Replacement | E3115 | GMNA |
| 8031850 | Front Spring Replacement | E9418 | GMNA |
| 8031850 | Front Spring Replacement | E105000 | Holden Australia |
| 8031850 | Front Spring Replacement | E105100 | Holden Australia |
| 8031850 | Front Spring Replacement | E105200 | Holden Australia |
| 8031850 | Front Spring Replacement | E3020 | Holden Australia |
| 8031850 | Front Spring Replacement | E312700 | Holden Australia |
| 8031850 | Front Spring Replacement | E314700 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8031850 | Front Spring Replacement | E105000 | Holden New Zealand |
| 8031850 | Front Spring Replacement | E105100 | Holden New Zealand |
| 8031850 | Front Spring Replacement | E105200 | Holden New Zealand |
| 8031850 | Front Spring Replacement | 2140100 | GMK Overseas |
| 8031850 | Front Spring Replacement | 2140200 | GMK Overseas |
| 8031851 | Front Spring Replacement - Both Sides | E3027 | GMNA |
| 8031851 | Front Spring Replacement - Both Sides | 3221702 | GMK Domestic |
| 8031851 | Front Spring Replacement - Both Sides | 2140300 | GMK Overseas |
| 8031900 | Front Spring Lower Insulator Replacement | E9518 | GMNA |
| 8031900 | Front Spring Lower Insulator Replacement | E105120 | Holden Australia |
| 8031900 | Front Spring Lower Insulator Replacement | 2142700 | GMK Overseas |
| 8031900 | Front Spring Lower Insulator Replacement | 2142800 | GMK Overseas |
| 8031900 | Front Spring Lower Insulator Replacement | 2142900 | GMK Overseas |
| 8032680 | Front Torsion Bar Replacement | E3320 | GMNA |
| 8032680 | Front Torsion Bar Replacement | E3327 | GMNA |
| 8032680 | Front Torsion Bar Replacement | E106000 | Holden Australia |
| 8032680 | Front Torsion Bar Replacement | E106010 | Holden Australia |
| 8032680 | Front Torsion Bar Replacement | E106020 | Holden Australia |
| 8032680 | Front Torsion Bar Replacement | E3320 | Holden Australia |
| 8032680 | Front Torsion Bar Replacement | E332000 | Holden Australia |
| 8032680 | Front Torsion Bar Replacement | E3321 | Holden Australia |
| 8032680 | Front Torsion Bar Replacement | E332100 | Holden Australia |
| 8032680 | Front Torsion Bar Replacement | E332700 | Holden Australia |
| 8032680 | Front Torsion Bar Replacement | E106000 | Holden New Zealand |
| 8032680 | Front Torsion Bar Replacement | E106020 | Holden New Zealand |
| 8032680 | Front Torsion Bar Replacement | E332700 | Holden New Zealand |
| 8032680 | Front Torsion Bar Replacement | E380000 | Holden New Zealand |
| 8032680 | Front Torsion Bar Replacement | E380100 | Holden New Zealand |
| 8032680 | Front Torsion Bar Replacement | E380700 | Holden New Zealand |
| 8032682 | Front Torsion Bar Adjustment | E3300 | GMNA |
| 8032682 | Front Torsion Bar Adjustment | E3300 | Holden Australia |
| 8032682 | Front Torsion Bar Adjustment | E330000 | Holden Australia |
| 8032682 | Front Torsion Bar Adjustment | E330000 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8032730 | Torsion Bar Anchor Replacement | E3322 | GMNA |
| 8032870 | Torsion Bar Support Insulator Replacement | E3349 | GMNA |
| 8032960 | Front Lower Control Front Link Replacement | E3361 | GMNA |
| 8032970 | Front Lower Control Rear Link Replacement | | |
| 8032980 | Front Lower Control Arm Rod Replacement | E3420 | GMNA |
| 8032980 | Front Lower Control Arm Rod Replacement | 3520400 | GMK Domestic |
| 8032980 | Front Lower Control Arm Rod Replacement | E106200 | Holden Australia |
| 8032980 | Front Lower Control Arm Rod Replacement | E106200 | Holden New Zealand |
| 8033030 | Upper Control Arm Replacement | E3520 | GMNA |
| 8033030 | Upper Control Arm Replacement | E107000 | Holden Australia |
| 8033030 | Upper Control Arm Replacement | E107600 | Holden Australia |
| 8033030 | Upper Control Arm Replacement | E3520 | Holden Australia |
| 8033030 | Upper Control Arm Replacement | F112000 | Holden Australia |
| 8033030 | Upper Control Arm Replacement | F112100 | Holden Australia |
| 8033030 | Upper Control Arm Replacement | F112200 | Holden Australia |
| 8033030 | Upper Control Arm Replacement | E352000 | Holden New Zealand |
| 8033030 | Upper Control Arm Replacement | F112100 | Holden New Zealand |
| 8033030 | Upper Control Arm Replacement | F112200 | Holden New Zealand |
| 8033031 | Front Upper Control Arm Replacement - Both Sides | E3527 | GMNA |
| 8033031 | Front Upper Control Arm Replacement - Both Sides | E3521 | Holden Australia |
| 8033080 | Front Lower Control Front Arm Replacement | E3522 | GMNA |
| 8033100 | Front Lower Control Rear Arm Replacement | E3523 | GMNA |
| 8033140 | Lower Control Arm Replacement | E3530 | GMNA |
| 8033140 | Lower Control Arm Replacement | E9422 | GMNA |
| 8033140 | Lower Control Arm Replacement | E9424 | GMNA |
| 8033140 | Lower Control Arm Replacement | 3335300 | GMK Domestic |
| 8033140 | Lower Control Arm Replacement | 3511600 | GMK Domestic |
| 8033140 | Lower Control Arm Replacement | F110000 | Holden Australia |
| 8033140 | Lower Control Arm Replacement | F110100 | Holden Australia |
| 8033140 | Lower Control Arm Replacement | F110200 | Holden Australia |
| 8033140 | Lower Control Arm Replacement | F110000 | Holden New Zealand |
| 8033140 | Lower Control Arm Replacement | F110100 | Holden New Zealand |
| 8033140 | Lower Control Arm Replacement | F110200 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8033140 | Lower Control Arm Replacement | 2151500 | GMK Overseas |
| 8033140 | Lower Control Arm Replacement | 2151600 | GMK Overseas |
| 8033141 | Lower Control Arm Replacement - Both Sides | E3537 | GMNA |
| 8033141 | Lower Control Arm Replacement - Both Sides | 3224402 | GMK Domestic |
| 8033141 | Lower Control Arm Replacement - Both Sides | E100000 | Holden Australia |
| 8033141 | Lower Control Arm Replacement - Both Sides | E100100 | Holden Australia |
| 8033141 | Lower Control Arm Replacement - Both Sides | E100200 | Holden Australia |
| 8033141 | Lower Control Arm Replacement - Both Sides | E100000 | Holden New Zealand |
| 8033141 | Lower Control Arm Replacement - Both Sides | E100100 | Holden New Zealand |
| 8033141 | Lower Control Arm Replacement - Both Sides | E100200 | Holden New Zealand |
| 8033141 | Lower Control Arm Replacement - Both Sides | 2151700 | GMK Overseas |
| 8033330 | Front Upper Control Arm Bushing Replacement | E3542 | GMNA |
| 8033330 | Front Upper Control Arm Bushing Replacement | E9529 | GMNA |
| 8033330 | Front Upper Control Arm Bushing Replacement | E354000 | Holden Australia |
| 8033330 | Front Upper Control Arm Bushing Replacement | E354100 | Holden Australia |
| 8033330 | Front Upper Control Arm Bushing Replacement | E354700 | Holden Australia |
| 8033330 | Front Upper Control Arm Bushing Replacement | E355000 | Holden Australia |
| 8033330 | Front Upper Control Arm Bushing Replacement | E3551 | Holden Australia |
| 8033330 | Front Upper Control Arm Bushing Replacement | E3557 | Holden Australia |
| 8033330 | Front Upper Control Arm Bushing Replacement | E355700 | Holden Australia |
| 8033330 | Front Upper Control Arm Bushing Replacement | E732100 | Holden Australia |
| 8033330 | Front Upper Control Arm Bushing Replacement | E732000 | Holden New Zealand |
| 8033330 | Front Upper Control Arm Bushing Replacement | E732100 | Holden New Zealand |
| 8033350 | Front Lower Control Arm Bushing Replacement | E3545 | GMNA |
| 8033350 | Front Lower Control Arm Bushing Replacement | E9465 | GMNA |
| 8033350 | Front Lower Control Arm Bushing Replacement | 3520100 | GMK Domestic |
| 8033350 | Front Lower Control Arm Bushing Replacement | E100010 | Holden Australia |
| 8033350 | Front Lower Control Arm Bushing Replacement | E100210 | Holden Australia |
| 8033350 | Front Lower Control Arm Bushing Replacement | E112000 | Holden Australia |
| 8033350 | Front Lower Control Arm Bushing Replacement | E100010 | Holden New Zealand |
| 8033350 | Front Lower Control Arm Bushing Replacement | E100210 | Holden New Zealand |
| 8033350 | Front Lower Control Arm Bushing Replacement | E112000 | Holden New Zealand |
| 8033350 | Front Lower Control Arm Bushing Replacement | 2152400 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8033350 | Front Lower Control Arm Bushing Replacement | 2152500 | GMK Overseas |
| 8033350 | Front Lower Control Arm Bushing Replacement | 2153020 | GMK Overseas |
| 8033351 | Front Lower Control Arm Bushing Replacement - Both Sides | E3547 | GMNA |
| 8033351 | Front Lower Control Arm Bushing Replacement - Both Sides | E3557 | GMNA |
| 8033351 | Front Lower Control Arm Bushing Replacement - Both Sides | 3224502 | GMK Domestic |
| 8033351 | Front Lower Control Arm Bushing Replacement - Both Sides | E100110 | Holden Australia |
| 8033351 | Front Lower Control Arm Bushing Replacement - Both Sides | E100110 | Holden New Zealand |
| 8033351 | Front Lower Control Arm Bushing Replacement - Both Sides | E355000 | Holden New Zealand |
| 8033351 | Front Lower Control Arm Bushing Replacement - Both Sides | 2152600 | GMK Overseas |
| 8033351 | Front Lower Control Arm Bushing Replacement - Both Sides | 2153000 | GMK Overseas |
| 8033351 | Front Lower Control Arm Bushing Replacement - Both Sides | 2153010 | GMK Overseas |
| 8033370 | Front Lower Control Arm Rear Bushing Replacement | E3546 | GMNA |
| 8033370 | Front Lower Control Arm Rear Bushing Replacement | 2152100 | GMK Overseas |
| 8033370 | Front Lower Control Arm Rear Bushing Replacement | 2152200 | GMK Overseas |
| 8033590 | Shock Absorber Replacement | E3800 | GMNA |
| 8033590 | Shock Absorber Replacement | 2143211 | GMK Overseas |
| 8033591 | Front Shock Absorber Replacement - Both Sides | E3807 | GMNA |
| 8033591 | Front Shock Absorber Replacement - Both Sides | E9468 | GMNA |
| 8033591 | Front Shock Absorber Replacement - Both Sides | 2143300 | GMK Overseas |
| 8033640 | Shock Absorber, Shock Absorber Component, or Spring Replacement | E3802 | GMNA |
| 8033640 | Shock Absorber, Shock Absorber Component, or Spring Replacement | E3831 | GMNA |
| 8033641 | Shock Absorber, Shock Absorber Component, or Spring Replacement - Both Sides | E3805 | GMNA |
| 8033680 | Front Shock Absorber Yoke Replacement | E3806 | GMNA |
| 8033680 | Front Shock Absorber Yoke Replacement | E3816 | GMNA |
| 8033720 | Front Suspension Strut Yoke Replacement | E3808 | GMNA |
| 8033740 | Strut Assembly Removal and Installation | E3850 | GMNA |
| 8033740 | Strut Assembly Removal and Installation | 2140500 | GMK Overseas |
| 8033740 | Strut Assembly Removal and Installation | 2140600 | GMK Overseas |
| 8033740 | Strut Assembly Removal and Installation | 2140900 | GMK Overseas |
| 8033740 | Strut Assembly Removal and Installation | 2141100 | GMK Overseas |
| 8033741 | Strut Assembly Replacement - Both Sides | E2107 | GMNA |
| 8033741 | Strut Assembly Replacement - Both Sides | E3857 | GMNA |
| 8033741 | Strut Assembly Replacement - Both Sides | E3917 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8033741 | Strut Assembly Replacement - Both Sides | E108000 | Holden Australia |
| 8033741 | Strut Assembly Replacement - Both Sides | E108100 | Holden Australia |
| 8033741 | Strut Assembly Replacement - Both Sides | E210000 | Holden Australia |
| 8033741 | Strut Assembly Replacement - Both Sides | E210100 | Holden Australia |
| 8033741 | Strut Assembly Replacement - Both Sides | E210700 | Holden Australia |
| 8033741 | Strut Assembly Replacement - Both Sides | E108000 | Holden New Zealand |
| 8033741 | Strut Assembly Replacement - Both Sides | E108100 | Holden New Zealand |
| 8033741 | Strut Assembly Replacement - Both Sides | 2140700 | GMK Overseas |
| 8033741 | Strut Assembly Replacement - Both Sides | 2141200 | GMK Overseas |
| 8033741 | Strut Assembly Replacement - Both Sides | R721035 | GMK Overseas |
| 8033741 | Strut Assembly Replacement - Both Sides | T214120 | GMK Overseas |
| 8033790 | Strut, Strut Component, or Spring Replacement | E3852 | GMNA |
| 8033790 | Strut, Strut Component, or Spring Replacement | E9440 | GMNA |
| 8033790 | Strut, Strut Component, or Spring Replacement | E9441 | GMNA |
| 8033790 | Strut, Strut Component, or Spring Replacement | E9478 | GMNA |
| 8033790 | Strut, Strut Component, or Spring Replacement | E9492 | GMNA |
| 8033790 | Strut, Strut Component, or Spring Replacement | E9534 | GMNA |
| 8033790 | Strut, Strut Component, or Spring Replacement | H2842 | GMNA |
| 8033790 | Strut, Strut Component, or Spring Replacement | H2843 | GMNA |
| 8033790 | Strut, Strut Component, or Spring Replacement | H2844 | GMNA |
| 8033790 | Strut, Strut Component, or Spring Replacement | T9681 | GMNA |
| 8033790 | Strut, Strut Component, or Spring Replacement | 2143100 | GMK Overseas |
| 8033790 | Strut, Strut Component, or Spring Replacement | 2143200 | GMK Overseas |
| 8033791 | Strut, Strut Component, or Spring Replacement - Both Sides | E2101 | GMNA |
| 8033791 | Strut, Strut Component, or Spring Replacement - Both Sides | E3853 | GMNA |
| 8033791 | Strut, Strut Component, or Spring Replacement - Both Sides | E4140 | GMNA |
| 8033791 | Strut, Strut Component, or Spring Replacement - Both Sides | E4141 | GMNA |
| 8033791 | Strut, Strut Component, or Spring Replacement - Both Sides | 3221002 | GMK Domestic |
| 8033791 | Strut, Strut Component, or Spring Replacement - Both Sides | 3440220 | GMK Domestic |
| 8033791 | Strut, Strut Component, or Spring Replacement - Both Sides | E108200 | Holden Australia |
| 8033791 | Strut, Strut Component, or Spring Replacement - Both Sides | E108200 | Holden New Zealand |
| 8033930 | Front Suspension Strut Bumper Replacement | E3909 | GMNA |
| 8033930 | Front Suspension Strut Bumper Replacement | E000430 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8033930 | Front Suspension Strut Bumper Replacement | 2142400 | GMK Overseas |
| 8033930 | Front Suspension Strut Bumper Replacement | 2142500 | GMK Overseas |
| 8033930 | Front Suspension Strut Bumper Replacement | 2142600 | GMK Overseas |
| 8034030 | Front Shock Absorber Upper Mount Replacement | E3919 | GMNA |
| 8034030 | Front Shock Absorber Upper Mount Replacement | E380000 | Holden Australia |
| 8034030 | Front Shock Absorber Upper Mount Replacement | E380100 | Holden Australia |
| 8034030 | Front Shock Absorber Upper Mount Replacement | E380700 | Holden Australia |
| 8034050 | Front Suspension Strut Mount and Bearing Replacement | E3920 | GMNA |
| 8034050 | Front Suspension Strut Mount and Bearing Replacement | 2141800 | GMK Overseas |
| 8034050 | Front Suspension Strut Mount and Bearing Replacement | 2141900 | GMK Overseas |
| 8034050 | Front Suspension Strut Mount and Bearing Replacement | 2142100 | GMK Overseas |
| 8034051 | Front Suspension Strut Mount and Bearing Replacement - Both Sides | E2120 | GMNA |
| 8034051 | Front Suspension Strut Mount and Bearing Replacement - Both Sides | E2121 | GMNA |
| 8034051 | Front Suspension Strut Mount and Bearing Replacement - Both Sides | E2127 | GMNA |
| 8034051 | Front Suspension Strut Mount and Bearing Replacement - Both Sides | E3927 | GMNA |
| 8034051 | Front Suspension Strut Mount and Bearing Replacement - Both Sides | E9525 | GMNA |
| 8034051 | Front Suspension Strut Mount and Bearing Replacement - Both Sides | 2142200 | GMK Overseas |
| 8039929 | Customer Concern Not Duplicated (CCND) - Suspension | E3590 | GMNA |
| 8039929 | Customer Concern Not Duplicated (CCND) - Suspension | E9417 | GMNA |
| 8039929 | Customer Concern Not Duplicated (CCND) - Suspension | E9995 | GMNA |
| 8040010 | Wheel Stud Replacement | E0473 | GMNA |
| 8040010 | Wheel Stud Replacement | E006500 | Holden Australia |
| 8040010 | Wheel Stud Replacement | E006600 | Holden Australia |
| 8040010 | Wheel Stud Replacement | E0474 | Holden Australia |
| 8040010 | Wheel Stud Replacement | E006600 | Holden New Zealand |
| 8040010 | Wheel Stud Replacement | E0473 | Holden New Zealand |
| 8040010 | Wheel Stud Replacement | E047300 | Holden New Zealand |
| 8040010 | Wheel Stud Replacement | 4567100 | GMK Overseas |
| 8040010 | Wheel Stud Replacement | 4567300 | GMK Overseas |
| 8040200 | Rear Suspension Link Replacement - Upper to Lower Control Arm | E4075 | GMNA |
| 8040200 | Rear Suspension Link Replacement - Upper to Lower Control Arm | F104100 | Holden New Zealand |
| 8040220 | Rear Suspension Link Replacement - Toe Link | E4079 | GMNA |
| 8040220 | Rear Suspension Link Replacement - Toe Link | 2318700 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8040220 | Rear Suspension Link Replacement - Toe Link | 2318800 | GMK Overseas |
| 8040220 | Rear Suspension Link Replacement - Toe Link | 2318900 | GMK Overseas |
| 8040240 | Adjust Link Replacement | E4080 | GMNA |
| 8040240 | Adjust Link Replacement | E4517 | GMNA |
| 8040290 | Adjust Link Bushing Replacement | E4082 | GMNA |
| 8040290 | Adjust Link Bushing Replacement | 2313700 | GMK Overseas |
| 8040290 | Adjust Link Bushing Replacement | 2313900 | GMK Overseas |
| 8040460 | Rear Wheel Spindle Rod Replacement | E4100 | GMNA |
| 8040460 | Rear Wheel Spindle Rod Replacement | E4101 | GMNA |
| 8040460 | Rear Wheel Spindle Rod Replacement | E4102 | GMNA |
| 8040460 | Rear Wheel Spindle Rod Replacement | E4107 | GMNA |
| 8040480 | Stabilizer Shaft Replacement | E3997 | GMNA |
| 8040480 | Stabilizer Shaft Replacement | E4160 | GMNA |
| 8040480 | Stabilizer Shaft Replacement | 3521700 | GMK Domestic |
| 8040480 | Stabilizer Shaft Replacement | E416000 | Holden Australia |
| 8040480 | Stabilizer Shaft Replacement | F122100 | Holden Australia |
| 8040480 | Stabilizer Shaft Replacement | E550300 | Holden New Zealand |
| 8040480 | Stabilizer Shaft Replacement | E5504 | Holden New Zealand |
| 8040480 | Stabilizer Shaft Replacement | 2310100 | GMK Overseas |
| 8040530 | Stabilizer Shaft Link Replacement | E4170 | GMNA |
| 8040530 | Stabilizer Shaft Link Replacement | E9472 | GMNA |
| 8040530 | Stabilizer Shaft Link Replacement | E2140 | Holden Australia |
| 8040530 | Stabilizer Shaft Link Replacement | F104000 | Holden Australia |
| 8040530 | Stabilizer Shaft Link Replacement | 2313400 | GMK Overseas |
| 8040530 | Stabilizer Shaft Link Replacement | 2313500 | GMK Overseas |
| 8040531 | Stabilizer Shaft Link Replacement - Both Sides | E4177 | GMNA |
| 8040531 | Stabilizer Shaft Link Replacement - Both Sides | 2313600 | GMK Overseas |
| 8040531 | Stabilizer Shaft Link Replacement - Both Sides | 2314300 | GMK Overseas |
| 8040600 | Stabilizer Shaft Insulator Replacement | E4092 | GMNA |
| 8040600 | Stabilizer Shaft Insulator Replacement | E4180 | GMNA |
| 8040600 | Stabilizer Shaft Insulator Replacement | E4186 | GMNA |
| 8040600 | Stabilizer Shaft Insulator Replacement | E9474 | GMNA |
| 8040600 | Stabilizer Shaft Insulator Replacement | E418000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8040600 | Stabilizer Shaft Insulator Replacement | E418100 | Holden Australia |
| 8040600 | Stabilizer Shaft Insulator Replacement | E418700 | Holden Australia |
| 8040680 | Rear Axle Tie Rod Replacement | E4190 | GMNA |
| 8040820 | Rear Axle Tie Rod Bracket Brace Replacement | E4210 | GMNA |
| 8041250 | Rear Wheel Bearing and Hub Replacement | E4267 | GMNA |
| 8041250 | Rear Wheel Bearing and Hub Replacement | E4297 | GMNA |
| 8041250 | Rear Wheel Bearing and Hub Replacement | E4300 | GMNA |
| 8041250 | Rear Wheel Bearing and Hub Replacement | E4367 | GMNA |
| 8041250 | Rear Wheel Bearing and Hub Replacement | E437100 | Holden Australia |
| 8041250 | Rear Wheel Bearing and Hub Replacement | F701000 | Holden Australia |
| 8041250 | Rear Wheel Bearing and Hub Replacement | F701100 | Holden Australia |
| 8041250 | Rear Wheel Bearing and Hub Replacement | F701200 | Holden Australia |
| 8041250 | Rear Wheel Bearing and Hub Replacement | E4372 | Holden New Zealand |
| 8041250 | Rear Wheel Bearing and Hub Replacement | F701000 | Holden New Zealand |
| 8041250 | Rear Wheel Bearing and Hub Replacement | F701100 | Holden New Zealand |
| 8041250 | Rear Wheel Bearing and Hub Replacement | F701200 | Holden New Zealand |
| 8041250 | Rear Wheel Bearing and Hub Replacement | 4566700 | GMK Overseas |
| 8041250 | Rear Wheel Bearing and Hub Replacement | 4566800 | GMK Overseas |
| 8041250 | Rear Wheel Bearing and Hub Replacement | 4566900 | GMK Overseas |
| 8041540 | Jounce Bumper Replacement | E4400 | GMNA |
| 8041540 | Jounce Bumper Replacement | E440000 | Holden Australia |
| 8041540 | Jounce Bumper Replacement | E440100 | Holden Australia |
| 8041540 | Jounce Bumper Replacement | E440000 | Holden New Zealand |
| 8041540 | Jounce Bumper Replacement | E440100 | Holden New Zealand |
| 8041540 | Jounce Bumper Replacement | 2322400 | GMK Overseas |
| 8041540 | Jounce Bumper Replacement | 2322500 | GMK Overseas |
| 8041540 | Jounce Bumper Replacement | 2322600 | GMK Overseas |
| 8041540 | Jounce Bumper Replacement | 2326100 | GMK Overseas |
| 8041540 | Jounce Bumper Replacement | 2326200 | GMK Overseas |
| 8041540 | Jounce Bumper Replacement | 2326300 | GMK Overseas |
| 8041650 | Trailing Arm Bushing Replacement | E4495 | GMNA |
| 8041650 | Trailing Arm Bushing Replacement | E4497 | GMNA |
| 8041650 | Trailing Arm Bushing Replacement | E9403 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8041650 | Trailing Arm Bushing Replacement | F110500 | Holden Australia |
| 8041650 | Trailing Arm Bushing Replacement | F111300 | Holden Australia |
| 8041650 | Trailing Arm Bushing Replacement | F111400 | Holden Australia |
| 8041650 | Trailing Arm Bushing Replacement | F111000 | Holden New Zealand |
| 8041650 | Trailing Arm Bushing Replacement | F111100 | Holden New Zealand |
| 8041650 | Trailing Arm Bushing Replacement | F111300 | Holden New Zealand |
| 8041650 | Trailing Arm Bushing Replacement | F111400 | Holden New Zealand |
| 8041700 | Trailing Arm Replacement | E4500 | GMNA |
| 8041700 | Trailing Arm Replacement | E4507 | GMNA |
| 8041700 | Trailing Arm Replacement | E9532 | GMNA |
| 8041700 | Trailing Arm Replacement | F110050 | Holden Australia |
| 8041700 | Trailing Arm Replacement | F110150 | Holden Australia |
| 8041700 | Trailing Arm Replacement | F110250 | Holden Australia |
| 8041700 | Trailing Arm Replacement | F111200 | Holden Australia |
| 8041700 | Trailing Arm Replacement | F110050 | Holden New Zealand |
| 8041700 | Trailing Arm Replacement | F110150 | Holden New Zealand |
| 8041700 | Trailing Arm Replacement | F110250 | Holden New Zealand |
| 8041700 | Trailing Arm Replacement | F111200 | Holden New Zealand |
| 8041870 | Rear Wheel Spindle Replacement | E2727 | GMNA |
| 8041870 | Rear Wheel Spindle Replacement | E4720 | GMNA |
| 8041870 | Rear Wheel Spindle Replacement | E4727 | GMNA |
| 8041870 | Rear Wheel Spindle Replacement | F507100 | Holden Australia |
| 8041870 | Rear Wheel Spindle Replacement | F507200 | Holden Australia |
| 8041870 | Rear Wheel Spindle Replacement | F507100 | Holden New Zealand |
| 8041870 | Rear Wheel Spindle Replacement | F507200 | Holden New Zealand |
| 8041870 | Rear Wheel Spindle Replacement | F701210002 | Holden New Zealand |
| 8041870 | Rear Wheel Spindle Replacement | 2311500 | GMK Overseas |
| 8041870 | Rear Wheel Spindle Replacement | 2311600 | GMK Overseas |
| 8041870 | Rear Wheel Spindle Replacement | 2311700 | GMK Overseas |
| 8041870 | Rear Wheel Spindle Replacement | 4567700 | GMK Overseas |
| 8041870 | Rear Wheel Spindle Replacement | 4567800 | GMK Overseas |
| 8041870 | Rear Wheel Spindle Replacement | 4567900 | GMK Overseas |
| 8041920 | Knuckle Replacement | E4760 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8041920 | Knuckle Replacement | E5001 | GMNA |
| 8041920 | Knuckle Replacement | E5007 | GMNA |
| 8041920 | Knuckle Replacement | 3330002 | GMK Domestic |
| 8041920 | Knuckle Replacement | 3332102 | GMK Domestic |
| 8041920 | Knuckle Replacement | 3332202 | GMK Domestic |
| 8041920 | Knuckle Replacement | E253100 | Holden Australia |
| 8041970 | Rear Wheel Hub Bracket Replacement | E4762 | GMNA |
| 8042020 | Lower Control Arm Ball Joint Replacement | E4770 | GMNA |
| 8042060 | Rear Coil Spring Replacement | 2320100 | GMK Overseas |
| 8042060 | Rear Coil Spring Replacement | 2320300 | GMK Overseas |
| 8042070 | Rear Coil Spring Replacement - Both Sides | F100000 | Holden Australia |
| 8042070 | Rear Coil Spring Replacement - Both Sides | 2320400 | GMK Overseas |
| 8042070 | Rear Coil Spring Replacement - Both Sides | 2320500 | GMK Overseas |
| 8042340 | Rear Spring Front Stop Replacement | E5108 | GMNA |
| 8042340 | Rear Spring Front Stop Replacement | E510800 | Holden New Zealand |
| 8042360 | Rear Spring Rear Stop Replacement | E5109 | GMNA |
| 8042380 | Rear Spring Replacement | E3120 | GMNA |
| 8042380 | Rear Spring Replacement | E3121 | GMNA |
| 8042380 | Rear Spring Replacement | E3652 | GMNA |
| 8042380 | Rear Spring Replacement | E3950 | GMNA |
| 8042380 | Rear Spring Replacement | E3952 | GMNA |
| 8042380 | Rear Spring Replacement | E3954 | GMNA |
| 8042380 | Rear Spring Replacement | E3956 | GMNA |
| 8042380 | Rear Spring Replacement | E3960 | GMNA |
| 8042380 | Rear Spring Replacement | E5130 | GMNA |
| 8042380 | Rear Spring Replacement | E5140 | GMNA |
| 8042380 | Rear Spring Replacement | E5147 | GMNA |
| 8042380 | Rear Spring Replacement | E000180 | Holden Australia |
| 8042380 | Rear Spring Replacement | E502000 | Holden Australia |
| 8042380 | Rear Spring Replacement | E502100 | Holden Australia |
| 8042380 | Rear Spring Replacement | E513100 | Holden Australia |
| 8042380 | Rear Spring Replacement | E513700 | Holden Australia |
| 8042380 | Rear Spring Replacement | E514000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8042380 | Rear Spring Replacement | E514100 | Holden Australia |
| 8042380 | Rear Spring Replacement | E514700 | Holden Australia |
| 8042380 | Rear Spring Replacement | E000180 | Holden New Zealand |
| 8042380 | Rear Spring Replacement | E512100 | Holden New Zealand |
| 8042380 | Rear Spring Replacement | E512300 | Holden New Zealand |
| 8042380 | Rear Spring Replacement | E513100 | Holden New Zealand |
| 8042380 | Rear Spring Replacement | E513200 | Holden New Zealand |
| 8042380 | Rear Spring Replacement | E5137 | Holden New Zealand |
| 8042380 | Rear Spring Replacement | E513700 | Holden New Zealand |
| 8042380 | Rear Spring Replacement | E5140 | Holden New Zealand |
| 8042380 | Rear Spring Replacement | E514000 | Holden New Zealand |
| 8042380 | Rear Spring Replacement | E514100 | Holden New Zealand |
| 8042380 | Rear Spring Replacement | E514700 | Holden New Zealand |
| 8042381 | Rear Spring Replacement - Both Sides | E5137 | GMNA |
| 8042381 | Rear Spring Replacement - Both Sides | T7760 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5168 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5670 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5675 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5710 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5730 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5731 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5737 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5747 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5758 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5759 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5802 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5808 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5810 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5811 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5812 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5815 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5816 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5817 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5832 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E9439 | GMNA |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E505000 | Holden Australia |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E505100 | Holden Australia |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E505700 | Holden Australia |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5800 | Holden Australia |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E580000 | Holden Australia |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5801 | Holden Australia |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E580100 | Holden Australia |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5807 | Holden Australia |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E580700 | Holden Australia |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E582100 | Holden Australia |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5800 | Holden New Zealand |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E580000 | Holden New Zealand |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E580100 | Holden New Zealand |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5807 | Holden New Zealand |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E580700 | Holden New Zealand |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5807NZ | Holden New Zealand |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | E5812 | Holden New Zealand |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | 2320700 | GMK Overseas |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | 2320800 | GMK Overseas |
| 8042510 | Rear Spring, Insulator, and Jounce Bumper Replacement | 2320900 | GMK Overseas |
| 8042530 | Spring Bushing Replacement | E5180 | GMNA |
| 8042530 | Spring Bushing Replacement | F102100 | Holden Australia |
| 8042530 | Spring Bushing Replacement | F102200 | Holden Australia |
| 8042530 | Spring Bushing Replacement | E5107 | Holden New Zealand |
| 8042530 | Spring Bushing Replacement | F102100 | Holden New Zealand |
| 8042610 | Rear Spring Shackle Replacement | E5200 | GMNA |
| 8042610 | Rear Spring Shackle Replacement | E5210 | GMNA |
| 8042610 | Rear Spring Shackle Replacement | E5211 | GMNA |
| 8042610 | Rear Spring Shackle Replacement | E5217 | GMNA |
| 8042610 | Rear Spring Shackle Replacement | E9455 | GMNA |
| 8042610 | Rear Spring Shackle Replacement | E5200 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8042610 | Rear Spring Shackle Replacement | E520000 | Holden Australia |
| 8042610 | Rear Spring Shackle Replacement | E5201 | Holden Australia |
| 8042610 | Rear Spring Shackle Replacement | E520100 | Holden Australia |
| 8042610 | Rear Spring Shackle Replacement | E520700 | Holden Australia |
| 8042610 | Rear Spring Shackle Replacement | E522000 | Holden Australia |
| 8042610 | Rear Spring Shackle Replacement | E522100 | Holden Australia |
| 8042610 | Rear Spring Shackle Replacement | E522700 | Holden Australia |
| 8042610 | Rear Spring Shackle Replacement | F105000 | Holden Australia |
| 8042610 | Rear Spring Shackle Replacement | F105200 | Holden Australia |
| 8042610 | Rear Spring Shackle Replacement | E5200 | Holden New Zealand |
| 8042610 | Rear Spring Shackle Replacement | E520000 | Holden New Zealand |
| 8042610 | Rear Spring Shackle Replacement | E520100 | Holden New Zealand |
| 8042610 | Rear Spring Shackle Replacement | E520700 | Holden New Zealand |
| 8042610 | Rear Spring Shackle Replacement | E5220 | Holden New Zealand |
| 8042610 | Rear Spring Shackle Replacement | E522000 | Holden New Zealand |
| 8042610 | Rear Spring Shackle Replacement | E5221 | Holden New Zealand |
| 8042610 | Rear Spring Shackle Replacement | E522100 | Holden New Zealand |
| 8042610 | Rear Spring Shackle Replacement | E522300 | Holden New Zealand |
| 8042610 | Rear Spring Shackle Replacement | E5227 | Holden New Zealand |
| 8042610 | Rear Spring Shackle Replacement | E5460 | Holden New Zealand |
| 8042940 | Rear Suspension Support Mount Replacement | | |
| 8043060 | Rear Suspension Insulator Replacement | E5307 | GMNA |
| 8043060 | Rear Suspension Insulator Replacement | E9419 | GMNA |
| 8043060 | Rear Suspension Insulator Replacement | E9508 | GMNA |
| 8043080 | Rear Suspension Support Insulator Replacement | E5308 | GMNA |
| 8043100 | Rear Suspension Support Crossmember Insulator Replacement | E5309 | GMNA |
| 8043100 | Rear Suspension Support Crossmember Insulator Replacement | E9407 | GMNA |
| 8043100 | Rear Suspension Support Crossmember Insulator Replacement | F000185 | Holden Australia |
| 8043100 | Rear Suspension Support Crossmember Insulator Replacement | F650500 | Holden Australia |
| 8043100 | Rear Suspension Support Crossmember Insulator Replacement | F650510 | Holden Australia |
| 8043100 | Rear Suspension Support Crossmember Insulator Replacement | F000185 | Holden New Zealand |
| 8043100 | Rear Suspension Support Crossmember Insulator Replacement | F650250 | Holden New Zealand |
| 8043100 | Rear Suspension Support Crossmember Insulator Replacement | F650510 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8043300 | Rear Spring Shackle Bushing Replacement | E5420 | GMNA |
| 8043300 | Rear Spring Shackle Bushing Replacement | F105100 | Holden Australia |
| 8043680 | Equalizer Beam Center Link Heat Shield Replacement | E5515 | GMNA |
| 8043700 | Equalizer Beam Link Replacement - Right Side | E5516 | GMNA |
| 8043700 | Equalizer Beam Link Replacement - Right Side | 2360200 | GMK Overseas |
| 8043720 | Equalizer Beam Link Replacement - Left Side | E5517 | GMNA |
| 8043720 | Equalizer Beam Link Replacement - Left Side | 2360300 | GMK Overseas |
| 8043740 | Equalizer Beam Center Link Replacement | E5518 | GMNA |
| 8043740 | Equalizer Beam Center Link Replacement | 2360500 | GMK Overseas |
| 8043760 | Equalizer Beam Support Replacement | E5519 | GMNA |
| 8043960 | Rear Auxiliary Spring Replacement | E5550 | GMNA |
| 8044040 | Rear Suspension Upper Control Arm Bushing Replacement | E5600 | GMNA |
| 8044040 | Rear Suspension Upper Control Arm Bushing Replacement | 4010520 | GMK Domestic |
| 8044090 | Rear Axle Bushing Replacement | F2940 | GMNA |
| 8044090 | Rear Axle Bushing Replacement | F2941 | GMNA |
| 8044110 | Rear Axle Lower Control Arm Bushing Replacement | E5610 | GMNA |
| 8044110 | Rear Axle Lower Control Arm Bushing Replacement | E5617 | GMNA |
| 8044110 | Rear Axle Lower Control Arm Bushing Replacement | 3335100 | GMK Domestic |
| 8044110 | Rear Axle Lower Control Arm Bushing Replacement | 4211700 | GMK Domestic |
| 8044110 | Rear Axle Lower Control Arm Bushing Replacement | F111000 | Holden Australia |
| 8044110 | Rear Axle Lower Control Arm Bushing Replacement | F111100 | Holden Australia |
| 8044110 | Rear Axle Lower Control Arm Bushing Replacement | F650520 | Holden Australia |
| 8044110 | Rear Axle Lower Control Arm Bushing Replacement | F650520 | Holden New Zealand |
| 8044160 | Rear Suspension Control Arm Replacement | E5618 | GMNA |
| 8044160 | Rear Suspension Control Arm Replacement | T980402 | Holden Australia |
| 8044160 | Rear Suspension Control Arm Replacement | T980403 | Holden Australia |
| 8044180 | Rear Suspension Control Arm Bushing Replacement | E5619 | GMNA |
| 8044180 | Rear Suspension Control Arm Bushing Replacement | E9447 | GMNA |
| 8044200 | Upper Control Arm Replacement | E5620 | GMNA |
| 8044200 | Upper Control Arm Replacement | E5626 | GMNA |
| 8044200 | Upper Control Arm Replacement | 3335200 | GMK Domestic |
| 8044200 | Upper Control Arm Replacement | E107500 | Holden Australia |
| 8044200 | Upper Control Arm Replacement | E352000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8044200 | Upper Control Arm Replacement | E352100 | Holden Australia |
| 8044200 | Upper Control Arm Replacement | E352700 | Holden Australia |
| 8044200 | Upper Control Arm Replacement | 2318100 | GMK Overseas |
| 8044200 | Upper Control Arm Replacement | 2318200 | GMK Overseas |
| 8044200 | Upper Control Arm Replacement | 2318300 | GMK Overseas |
| 8044200 | Upper Control Arm Replacement | 2325400 | GMK Overseas |
| 8044200 | Upper Control Arm Replacement | 2325500 | GMK Overseas |
| 8044200 | Upper Control Arm Replacement | 2325600 | GMK Overseas |
| 8044250 | Rear Axle Upper Control Arm Replacement | E5622 | GMNA |
| 8044250 | Rear Axle Upper Control Arm Replacement | F112000 | Holden New Zealand |
| 8044260 | Rear Suspension Lower Control Arm Cover Replacement | | |
| 8044300 | Rear Axle Lower Control Arm Replacement | E5629 | GMNA |
| 8044320 | Lower Control Arm Replacement | E5630 | GMNA |
| 8044320 | Lower Control Arm Replacement | E106100 | Holden Australia |
| 8044320 | Lower Control Arm Replacement | E3530 | Holden Australia |
| 8044320 | Lower Control Arm Replacement | E353000 | Holden Australia |
| 8044320 | Lower Control Arm Replacement | E353100 | Holden Australia |
| 8044320 | Lower Control Arm Replacement | E3537 | Holden Australia |
| 8044320 | Lower Control Arm Replacement | E353700 | Holden Australia |
| 8044320 | Lower Control Arm Replacement | E563000 | Holden Australia |
| 8044320 | Lower Control Arm Replacement | E563700 | Holden Australia |
| 8044320 | Lower Control Arm Replacement | E563800 | Holden Australia |
| 8044320 | Lower Control Arm Replacement | E106100 | Holden New Zealand |
| 8044520 | Rear Axle Replacement | E5700 | GMNA |
| 8044520 | Rear Axle Replacement | F9715 | GMNA |
| 8044520 | Rear Axle Replacement | 2310900 | GMK Overseas |
| 8044520 | Rear Axle Replacement | 2316100 | GMK Overseas |
| 8044600 | Strut Assembly Removal and Installation | E5750 | GMNA |
| 8044601 | Strut Assembly Replacement - Both Sides | E4150 | GMNA |
| 8044601 | Strut Assembly Replacement - Both Sides | E4151 | GMNA |
| 8044601 | Strut Assembly Replacement - Both Sides | E5607 | GMNA |
| 8044601 | Strut Assembly Replacement - Both Sides | E5757 | GMNA |
| 8044601 | Strut Assembly Replacement - Both Sides | E561700 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8044601 | Strut Assembly Replacement - Both Sides | F110010 | Holden Australia |
| 8044601 | Strut Assembly Replacement - Both Sides | F110030 | Holden Australia |
| 8044601 | Strut Assembly Replacement - Both Sides | F125110 | Holden Australia |
| 8044601 | Strut Assembly Replacement - Both Sides | F125150 | Holden Australia |
| 8044601 | Strut Assembly Replacement - Both Sides | F125250 | Holden Australia |
| 8044601 | Strut Assembly Replacement - Both Sides | F202000 | Holden Australia |
| 8044601 | Strut Assembly Replacement - Both Sides | F125110 | Holden New Zealand |
| 8044601 | Strut Assembly Replacement - Both Sides | F125150 | Holden New Zealand |
| 8044601 | Strut Assembly Replacement - Both Sides | F125250 | Holden New Zealand |
| 8044601 | Strut Assembly Replacement - Both Sides | 2321700 | GMK Overseas |
| 8044601 | Strut Assembly Replacement - Both Sides | 2321800 | GMK Overseas |
| 8044601 | Strut Assembly Replacement - Both Sides | 2321900 | GMK Overseas |
| 8044601 | Strut Assembly Replacement - Both Sides | 2322700 | GMK Overseas |
| 8044601 | Strut Assembly Replacement - Both Sides | 2322800 | GMK Overseas |
| 8044601 | Strut Assembly Replacement - Both Sides | 2322900 | GMK Overseas |
| 8044601 | Strut Assembly Replacement - Both Sides | 2360700 | GMK Overseas |
| 8044650 | Shock Absorber, Shock Absorber Component, or Spring Replacement | E5752 | GMNA |
| 8044651 | Shock Absorber, Shock Absorber Component, or Spring Replacement - Both Sides | E5756 | GMNA |
| 8044670 | Strut, Strut Component, or Spring Replacement | E5753 | GMNA |
| 8044670 | Strut, Strut Component, or Spring Replacement | E000347 | Holden Australia |
| 8044670 | Strut, Strut Component, or Spring Replacement | E000347 | Holden New Zealand |
| 8044670 | Strut, Strut Component, or Spring Replacement | E105000A1 | Holden New Zealand |
| 8044671 | Strut, Strut Component, or Spring Replacement - Both Sides | E2100 | GMNA |
| 8044671 | Strut, Strut Component, or Spring Replacement - Both Sides | E5755 | GMNA |
| 8044671 | Strut, Strut Component, or Spring Replacement - Both Sides | E210000 | Holden New Zealand |
| 8044671 | Strut, Strut Component, or Spring Replacement - Both Sides | E210100 | Holden New Zealand |
| 8044671 | Strut, Strut Component, or Spring Replacement - Both Sides | E212100 | Holden New Zealand |
| 8044750 | Shock Absorber Replacement | E5800 | GMNA |
| 8044750 | Shock Absorber Replacement | E9493 | GMNA |
| 8044750 | Shock Absorber Replacement | T1836 | GMNA |
| 8044750 | Shock Absorber Replacement | E3800 | Holden Australia |
| 8044750 | Shock Absorber Replacement | E3801 | Holden Australia |
| 8044750 | Shock Absorber Replacement | F000168 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8044750 | Shock Absorber Replacement | E3800 | Holden New Zealand |
| 8044750 | Shock Absorber Replacement | E3801 | Holden New Zealand |
| 8044750 | Shock Absorber Replacement | E3807 | Holden New Zealand |
| 8044750 | Shock Absorber Replacement | F000168 | Holden New Zealand |
| 8044750 | Shock Absorber Replacement | 2321100 | GMK Overseas |
| 8044750 | Shock Absorber Replacement | 2321200 | GMK Overseas |
| 8044750 | Shock Absorber Replacement | 2321400 | GMK Overseas |
| 8044750 | Shock Absorber Replacement | 2321500 | GMK Overseas |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | E5807 | GMNA |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | E9442 | GMNA |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | E9487 | GMNA |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | 3321002 | GMK Domestic |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | E526700 | Holden Australia |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | F102300 | Holden Australia |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | F102350 | Holden Australia |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | F102400 | Holden Australia |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | F120000 | Holden Australia |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | F120100 | Holden Australia |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | F120200 | Holden Australia |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | F121100 | Holden Australia |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | F121200 | Holden Australia |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | F121300 | Holden Australia |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | F102300 | Holden New Zealand |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | F102400 | Holden New Zealand |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | F120000 | Holden New Zealand |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | F120100 | Holden New Zealand |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | F120200 | Holden New Zealand |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | F121100 | Holden New Zealand |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | F121200 | Holden New Zealand |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | F121300 | Holden New Zealand |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | 2321300 | GMK Overseas |
| 8044751 | Rear Shock Absorber Replacement - Both Sides | 2321600 | GMK Overseas |
| 8044820 | Rear Spring Insulator Replacement | E5830 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8044820 | Rear Spring Insulator Replacement | 3540100 | GMK Domestic |
| 8044820 | Rear Spring Insulator Replacement | E000391 | Holden Australia |
| 8044820 | Rear Spring Insulator Replacement | F202100 | Holden Australia |
| 8044820 | Rear Spring Insulator Replacement | F202110 | Holden Australia |
| 8044820 | Rear Spring Insulator Replacement | F203100 | Holden Australia |
| 8044820 | Rear Spring Insulator Replacement | E000391 | Holden New Zealand |
| 8044820 | Rear Spring Insulator Replacement | F202100 | Holden New Zealand |
| 8044820 | Rear Spring Insulator Replacement | F203100 | Holden New Zealand |
| 8044820 | Rear Spring Insulator Replacement | 2322100 | GMK Overseas |
| 8044820 | Rear Spring Insulator Replacement | 2322200 | GMK Overseas |
| 8044820 | Rear Spring Insulator Replacement | 2322300 | GMK Overseas |
| 8049929 | Customer Concern Not Duplicated (CCND) - Suspension | | |
| 8050079 | Diagnostic System Check - Tire Pressure Monitoring | E0715 | GMNA |
| 8050079 | Diagnostic System Check - Tire Pressure Monitoring | E0716 | GMNA |
| 8050079 | Diagnostic System Check - Tire Pressure Monitoring | ROADTEST | Holden New Zealand |
| 8050090 | Tire Pressure Indicator Receiver Replacement | E0710 | GMNA |
| 8050090 | Tire Pressure Indicator Receiver Replacement | E0717 | GMNA |
| 8050110 | Tire Valve Stem Grommet Replacement | E0719 | GMNA |
| 8050110 | Tire Valve Stem Grommet Replacement | E9463 | GMNA |
| 8050190 | Tire Pressure Indicator Sensor Replacement | E0722 | GMNA |
| 8050190 | Tire Pressure Indicator Sensor Replacement | E0731 | GMNA |
| 8050190 | Tire Pressure Indicator Sensor Replacement | E0732 | GMNA |
| 8050190 | Tire Pressure Indicator Sensor Replacement | E000900 | Holden Australia |
| 8050190 | Tire Pressure Indicator Sensor Replacement | J000917 | Holden Australia |
| 8050190 | Tire Pressure Indicator Sensor Replacement | E000900 | Holden New Zealand |
| 8050190 | Tire Pressure Indicator Sensor Replacement | J000917 | Holden New Zealand |
| 8050210 | Low Tire Pressure Indicator Module Replacement | E0723 | GMNA |
| 8050210 | Low Tire Pressure Indicator Module Replacement | N9649 | GMNA |
| 8050210 | Low Tire Pressure Indicator Module Replacement | R9790 | GMNA |
| 8050210 | Low Tire Pressure Indicator Module Replacement | 2421300 | GMK Overseas |
| 8059949 | Customer Concern Not Duplicated (CCND) - Tire Pressure Monitoring System | N9994 | GMNA |
| 8059949 | Customer Concern Not Duplicated (CCND) - Tire Pressure Monitoring System | 3022620 | GMK Domestic |
| 8060010 | Wheel Trim Cover Replacement | E0022 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8060010 | Wheel Trim Cover Replacement | R9395 | GMNA |
| 8060010 | Wheel Trim Cover Replacement | 3210200 | GMK Domestic |
| 8060010 | Wheel Trim Cover Replacement | E000510 | Holden Australia |
| 8060010 | Wheel Trim Cover Replacement | E0022 | Holden Australia |
| 8060010 | Wheel Trim Cover Replacement | E002200 | Holden Australia |
| 8060010 | Wheel Trim Cover Replacement | E002300 | Holden Australia |
| 8060010 | Wheel Trim Cover Replacement | E002700 | Holden Australia |
| 8060010 | Wheel Trim Cover Replacement | E000510 | Holden New Zealand |
| 8060010 | Wheel Trim Cover Replacement | E0022 | Holden New Zealand |
| 8060010 | Wheel Trim Cover Replacement | E002200 | Holden New Zealand |
| 8060010 | Wheel Trim Cover Replacement | E002300 | Holden New Zealand |
| 8060010 | Wheel Trim Cover Replacement | E002700 | Holden New Zealand |
| 8060090 | Wheel Trim Cover Hub Cap Replacement | E0032 | GMNA |
| 8060090 | Wheel Trim Cover Hub Cap Replacement | E9425 | GMNA |
| 8060090 | Wheel Trim Cover Hub Cap Replacement | 3210100 | GMK Domestic |
| 8060090 | Wheel Trim Cover Hub Cap Replacement | 3440600 | GMK Domestic |
| 8060090 | Wheel Trim Cover Hub Cap Replacement | E000323 | Holden Australia |
| 8060090 | Wheel Trim Cover Hub Cap Replacement | E000500 | Holden Australia |
| 8060090 | Wheel Trim Cover Hub Cap Replacement | E0033 | Holden Australia |
| 8060090 | Wheel Trim Cover Hub Cap Replacement | E0037 | Holden Australia |
| 8060090 | Wheel Trim Cover Hub Cap Replacement | E000421 | Holden New Zealand |
| 8060090 | Wheel Trim Cover Hub Cap Replacement | E000500 | Holden New Zealand |
| 8060090 | Wheel Trim Cover Hub Cap Replacement | 2134500 | GMK Overseas |
| 8060090 | Wheel Trim Cover Hub Cap Replacement | 2134600 | GMK Overseas |
| 8060090 | Wheel Trim Cover Hub Cap Replacement | 2412900 | GMK Overseas |
| 8060170 | Wheel Nut Cap Replacement | E0050 | GMNA |
| 8060170 | Wheel Nut Cap Replacement | E9460 | GMNA |
| 8060170 | Wheel Nut Cap Replacement | E000421 | Holden Australia |
| 8060170 | Wheel Nut Cap Replacement | E000424 | Holden Australia |
| 8060170 | Wheel Nut Cap Replacement | E006400 | Holden Australia |
| 8060170 | Wheel Nut Cap Replacement | E000424 | Holden New Zealand |
| 8060170 | Wheel Nut Cap Replacement | E000500A | Holden New Zealand |
| 8060170 | Wheel Nut Cap Replacement | E006400 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8060170 | Wheel Nut Cap Replacement | 2410600 | GMK Overseas |
| 8060199 | Pull and Torque Steer Analysis | E0100 | GMNA |
| 8060212 | Tire and Wheel Balancing - One | E0200 | GMNA |
| 8060212 | Tire and Wheel Balancing - One | E9498 | GMNA |
| 8060212 | Tire and Wheel Balancing - One | E9499 | GMNA |
| 8060212 | Tire and Wheel Balancing - One | 3020220 | GMK Domestic |
| 8060212 | Tire and Wheel Balancing - One | 3020420 | GMK Domestic |
| 8060212 | Tire and Wheel Balancing - One | E0200 | Holden Australia |
| 8060212 | Tire and Wheel Balancing - One | E020000 | Holden Australia |
| 8060212 | Tire and Wheel Balancing - One | E047500 | Holden Australia |
| 8060212 | Tire and Wheel Balancing - One | E0200 | Holden New Zealand |
| 8060212 | Tire and Wheel Balancing - One | E020000 | Holden New Zealand |
| 8060212 | Tire and Wheel Balancing - One | E0475 | Holden New Zealand |
| 8060212 | Tire and Wheel Balancing - One | E047500 | Holden New Zealand |
| 8060212 | Tire and Wheel Balancing - One | E0476 | Holden New Zealand |
| 8060212 | Tire and Wheel Balancing - One | E0477 | Holden New Zealand |
| 8060212 | Tire and Wheel Balancing - One | E0480 | Holden New Zealand |
| 8060212 | Tire and Wheel Balancing - One | E0482 | Holden New Zealand |
| 8060212 | Tire and Wheel Balancing - One | E0483 | Holden New Zealand |
| 8060212 | Tire and Wheel Balancing - One | 2410700 | GMK Overseas |
| 8060212 | Tire and Wheel Balancing - One | 2413400 | GMK Overseas |
| 8060212 | Tire and Wheel Balancing - One | 2413600 | GMK Overseas |
| 8060213 | Tire and Wheel Balancing - Two | E0201 | GMNA |
| 8060213 | Tire and Wheel Balancing - Two | E020100 | Holden Australia |
| 8060213 | Tire and Wheel Balancing - Two | P207100 | Holden Australia |
| 8060213 | Tire and Wheel Balancing - Two | P207200 | Holden Australia |
| 8060213 | Tire and Wheel Balancing - Two | E002510 | Holden New Zealand |
| 8060213 | Tire and Wheel Balancing - Two | E007210 | Holden New Zealand |
| 8060213 | Tire and Wheel Balancing - Two | E0201 | Holden New Zealand |
| 8060213 | Tire and Wheel Balancing - Two | E020100 | Holden New Zealand |
| 8060213 | Tire and Wheel Balancing - Two | P207100 | Holden New Zealand |
| 8060213 | Tire and Wheel Balancing - Two | P207200 | Holden New Zealand |
| 8060213 | Tire and Wheel Balancing - Two | 2410800 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8060252 | Tire and Wheel Balancing - Three | E0202 | GMNA |
| 8060252 | Tire and Wheel Balancing - Three | 3143300 | GMK Domestic |
| 8060252 | Tire and Wheel Balancing - Three | E020200 | Holden Australia |
| 8060252 | Tire and Wheel Balancing - Three | W200300 | Holden Australia |
| 8060252 | Tire and Wheel Balancing - Three | W200400 | Holden Australia |
| 8060272 | Tire and Wheel Balancing - Four | E0203 | GMNA |
| 8060272 | Tire and Wheel Balancing - Four | E0901 | GMNA |
| 8060272 | Tire and Wheel Balancing - Four | E9462 | GMNA |
| 8060272 | Tire and Wheel Balancing - Four | E020300 | Holden Australia |
| 8060272 | Tire and Wheel Balancing - Four | P207000 | Holden Australia |
| 8060272 | Tire and Wheel Balancing - Four | E007010 | Holden New Zealand |
| 8060272 | Tire and Wheel Balancing - Four | E0203 | Holden New Zealand |
| 8060272 | Tire and Wheel Balancing - Four | E020300 | Holden New Zealand |
| 8060272 | Tire and Wheel Balancing - Four | P207000 | Holden New Zealand |
| 8060272 | Tire and Wheel Balancing - Four | 2410900 | GMK Overseas |
| 8060272 | Tire and Wheel Balancing - Four | 2413200 | GMK Overseas |
| 8060292 | Tire and Wheel Balancing - Six | E0204 | GMNA |
| 8060292 | Tire and Wheel Balancing - Six | E020400 | Holden New Zealand |
| 8060400 | Wheel Replacement | A3311 | GMNA |
| 8060400 | Wheel Replacement | E0040 | GMNA |
| 8060400 | Wheel Replacement | E0041 | GMNA |
| 8060400 | Wheel Replacement | E0047 | GMNA |
| 8060400 | Wheel Replacement | E0420 | GMNA |
| 8060400 | Wheel Replacement | E0422 | GMNA |
| 8060400 | Wheel Replacement | E0423 | GMNA |
| 8060400 | Wheel Replacement | E0501 | GMNA |
| 8060400 | Wheel Replacement | E0508 | GMNA |
| 8060400 | Wheel Replacement | 3020501 | GMK Domestic |
| 8060400 | Wheel Replacement | 3311010 | GMK Domestic |
| 8060400 | Wheel Replacement | E000100 | Holden Australia |
| 8060400 | Wheel Replacement | E000358 | Holden Australia |
| 8060400 | Wheel Replacement | E000364 | Holden Australia |
| 8060400 | Wheel Replacement | E000373 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8060400 | Wheel Replacement | E000394 | Holden Australia |
| 8060400 | Wheel Replacement | E000397 | Holden Australia |
| 8060400 | Wheel Replacement | E000400 | Holden Australia |
| 8060400 | Wheel Replacement | E000418 | Holden Australia |
| 8060400 | Wheel Replacement | E001400 | Holden Australia |
| 8060400 | Wheel Replacement | E041100 | Holden Australia |
| 8060400 | Wheel Replacement | E041300 | Holden Australia |
| 8060400 | Wheel Replacement | E041400 | Holden Australia |
| 8060400 | Wheel Replacement | E0420 | Holden Australia |
| 8060400 | Wheel Replacement | E042000 | Holden Australia |
| 8060400 | Wheel Replacement | E042200 | Holden Australia |
| 8060400 | Wheel Replacement | E042300 | Holden Australia |
| 8060400 | Wheel Replacement | E047400 | Holden Australia |
| 8060400 | Wheel Replacement | E048400 | Holden Australia |
| 8060400 | Wheel Replacement | E048500 | Holden Australia |
| 8060400 | Wheel Replacement | W777999 | Holden Australia |
| 8060400 | Wheel Replacement | A330000 | Holden New Zealand |
| 8060400 | Wheel Replacement | E000100 | Holden New Zealand |
| 8060400 | Wheel Replacement | E000100A | Holden New Zealand |
| 8060400 | Wheel Replacement | E000394 | Holden New Zealand |
| 8060400 | Wheel Replacement | E000397 | Holden New Zealand |
| 8060400 | Wheel Replacement | E000400 | Holden New Zealand |
| 8060400 | Wheel Replacement | E000418 | Holden New Zealand |
| 8060400 | Wheel Replacement | E001400 | Holden New Zealand |
| 8060400 | Wheel Replacement | E002500 | Holden New Zealand |
| 8060400 | Wheel Replacement | E006100 | Holden New Zealand |
| 8060400 | Wheel Replacement | E0411 | Holden New Zealand |
| 8060400 | Wheel Replacement | E041100 | Holden New Zealand |
| 8060400 | Wheel Replacement | E041400 | Holden New Zealand |
| 8060400 | Wheel Replacement | E041400A | Holden New Zealand |
| 8060400 | Wheel Replacement | E0420 | Holden New Zealand |
| 8060400 | Wheel Replacement | E042000 | Holden New Zealand |
| 8060400 | Wheel Replacement | E042100 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8060400 | Wheel Replacement | E0422 | Holden New Zealand |
| 8060400 | Wheel Replacement | E042200 | Holden New Zealand |
| 8060400 | Wheel Replacement | E0423 | Holden New Zealand |
| 8060400 | Wheel Replacement | E042300 | Holden New Zealand |
| 8060400 | Wheel Replacement | E0474 | Holden New Zealand |
| 8060400 | Wheel Replacement | E047400 | Holden New Zealand |
| 8060400 | Wheel Replacement | E0484 | Holden New Zealand |
| 8060400 | Wheel Replacement | E048400 | Holden New Zealand |
| 8060400 | Wheel Replacement | E0485 | Holden New Zealand |
| 8060400 | Wheel Replacement | E048500 | Holden New Zealand |
| 8060400 | Wheel Replacement | E048500C | Holden New Zealand |
| 8060400 | Wheel Replacement | 2411100 | GMK Overseas |
| 8060400 | Wheel Replacement | 241110A | GMK Overseas |
| 8060400 | Wheel Replacement | 2411110 | GMK Overseas |
| 8060400 | Wheel Replacement | 2411120 | GMK Overseas |
| 8060400 | Wheel Replacement | 2411130 | GMK Overseas |
| 8060400 | Wheel Replacement | 2411130B | GMK Overseas |
| 8060400 | Wheel Replacement | 5011014 | GMK Overseas |
| 8060420 | Tire Replacement | D9717 | GMNA |
| 8060420 | Tire Replacement | E0421 | GMNA |
| 8060420 | Tire Replacement | E0427 | GMNA |
| 8060420 | Tire Replacement | E9480 | GMNA |
| 8060420 | Tire Replacement | E9486 | GMNA |
| 8060420 | Tire Replacement | I9185 | GMNA |
| 8060420 | Tire Replacement | S0030 | GMNA |
| 8060420 | Tire Replacement | S1330 | GMNA |
| 8060420 | Tire Replacement | T6366 | GMNA |
| 8060420 | Tire Replacement | 3020100 | GMK Domestic |
| 8060420 | Tire Replacement | 3020500 | GMK Domestic |
| 8060420 | Tire Replacement | 3142700 | GMK Domestic |
| 8060420 | Tire Replacement | 3142900 | GMK Domestic |
| 8060420 | Tire Replacement | A000315 | Holden Australia |
| 8060420 | Tire Replacement | E000095 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8060420 | Tire Replacement | E041200 | Holden Australia |
| 8060420 | Tire Replacement | E042100 | Holden Australia |
| 8060420 | Tire Replacement | F000209 | Holden Australia |
| 8060420 | Tire Replacement | T780502 | Holden Australia |
| 8060420 | Tire Replacement | W200600 | Holden Australia |
| 8060420 | Tire Replacement | W200650 | Holden Australia |
| 8060420 | Tire Replacement | E000110 | Holden New Zealand |
| 8060420 | Tire Replacement | E000130 | Holden New Zealand |
| 8060420 | Tire Replacement | E0421 | Holden New Zealand |
| 8060420 | Tire Replacement | E0610 | Holden New Zealand |
| 8060420 | Tire Replacement | F000209 | Holden New Zealand |
| 8060420 | Tire Replacement | 2411300 | GMK Overseas |
| 8060420 | Tire Replacement | 241130A | GMK Overseas |
| 8060420 | Tire Replacement | 241130B | GMK Overseas |
| 8060420 | Tire Replacement | 2411310 | GMK Overseas |
| 8060420 | Tire Replacement | 24113100 | GMK Overseas |
| 8060420 | Tire Replacement | 2411320 | GMK Overseas |
| 8060420 | Tire Replacement | 2411330 | GMK Overseas |
| 8060440 | Goodyear/Dunlop Tire Replacement | E0431 | GMNA |
| 8060460 | Continental/General Tire Replacement | E0432 | GMNA |
| 8060480 | Michelin Tire Replacement | E0433 | GMNA |
| 8060500 | Uniroyal Tire Replacement | E0434 | GMNA |
| 8060520 | B F Goodrich Tire Replacement | E0435 | GMNA |
| 8060540 | Bridgestone Tire Replacement | E0436 | GMNA |
| 8060540 | Bridgestone Tire Replacement | T780501 | Holden Australia |
| 8060560 | Firestone Tire Replacement | E0437 | GMNA |
| 8060580 | Kumho Tire Replacement | E0438 | GMNA |
| 8060600 | Hankook Tire Replacement | E0439 | GMNA |
| 8060620 | Pirelli Tire Replacement | E0440 | GMNA |
| 8060620 | Pirelli Tire Replacement | R9440 | GMNA |
| 8060640 | Maxxis Tire Replacement | E0441 | GMNA |
| 8060680 | Tire Valve Stem Replacement | E0460 | GMNA |
| 8060680 | Tire Valve Stem Replacement | E0642 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8060680 | Tire Valve Stem Replacement | E0647 | GMNA |
| 8060680 | Tire Valve Stem Replacement | E0713 | GMNA |
| 8060680 | Tire Valve Stem Replacement | 3210300 | GMK Domestic |
| 8060680 | Tire Valve Stem Replacement | 2411500 | GMK Overseas |
| 8060680 | Tire Valve Stem Replacement | 2411530 | GMK Overseas |
| 8060700 | Spare Tire Carrier Replacement | B9000 | GMNA |
| 8060700 | Spare Tire Carrier Replacement | E0570 | GMNA |
| 8060700 | Spare Tire Carrier Replacement | E0590 | GMNA |
| 8060700 | Spare Tire Carrier Replacement | E0903 | GMNA |
| 8060700 | Spare Tire Carrier Replacement | 8647400 | GMK Domestic |
| 8060700 | Spare Tire Carrier Replacement | B9000 | Holden Australia |
| 8060700 | Spare Tire Carrier Replacement | E000341 | Holden Australia |
| 8060700 | Spare Tire Carrier Replacement | E001300 | Holden Australia |
| 8060700 | Spare Tire Carrier Replacement | E001300 | Holden New Zealand |
| 8060700 | Spare Tire Carrier Replacement | 9523900 | GMK Overseas |
| 8060720 | Spare Wheel Carrier Hanger Replacement | S1315 | GMNA |
| 8060860 | Spare Wheel Hoist Replacement | E0605 | GMNA |
| 8060860 | Spare Wheel Hoist Replacement | 3210700 | GMK Domestic |
| 8060860 | Spare Wheel Hoist Replacement | E060500 | Holden Australia |
| 8060860 | Spare Wheel Hoist Replacement | R426500 | Holden Australia |
| 8060860 | Spare Wheel Hoist Replacement | E060500 | Holden New Zealand |
| 8060860 | Spare Wheel Hoist Replacement | R426500 | Holden New Zealand |
| 8060880 | Jack Replacement | E0620 | GMNA |
| 8060880 | Jack Replacement | E0630 | GMNA |
| 8060880 | Jack Replacement | E5310 | GMNA |
| 8060880 | Jack Replacement | E001000 | Holden Australia |
| 8060880 | Jack Replacement | E001500 | Holden Australia |
| 8060880 | Jack Replacement | E062000 | Holden Australia |
| 8060880 | Jack Replacement | E001000 | Holden New Zealand |
| 8060880 | Jack Replacement | E001500 | Holden New Zealand |
| 8060880 | Jack Replacement | E0620 | Holden New Zealand |
| 8060880 | Jack Replacement | E062000 | Holden New Zealand |
| 8060880 | Jack Replacement | E0620000 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8060960 | Tire Air Compressor Replacement | E0645 | GMNA |
| 8060960 | Tire Air Compressor Replacement | E001010 | Holden Australia |
| 8060960 | Tire Air Compressor Replacement | 2413000 | GMK Overseas |
| 8069939 | Customer Concern Not Duplicated (CCND) - Tires and Wheels | E9993 | GMNA |
| 8069939 | Customer Concern Not Duplicated (CCND) - Tires and Wheels | 3022520 | GMK Domestic |
| 8070012 | Wheel Alignment - Steering Wheel Angle and/or Front Toe Adjustment | E2000 | GMNA |
| 8070012 | Wheel Alignment - Steering Wheel Angle and/or Front Toe Adjustment | E7000 | GMNA |
| 8070012 | Wheel Alignment - Steering Wheel Angle and/or Front Toe Adjustment | 3142000 | GMK Domestic |
| 8070012 | Wheel Alignment - Steering Wheel Angle and/or Front Toe Adjustment | 3142200 | GMK Domestic |
| 8070012 | Wheel Alignment - Steering Wheel Angle and/or Front Toe Adjustment | E000427 | Holden Australia |
| 8070012 | Wheel Alignment - Steering Wheel Angle and/or Front Toe Adjustment | E2000 | Holden Australia |
| 8070012 | Wheel Alignment - Steering Wheel Angle and/or Front Toe Adjustment | E200000 | Holden Australia |
| 8070012 | Wheel Alignment - Steering Wheel Angle and/or Front Toe Adjustment | E2020 | Holden Australia |
| 8070012 | Wheel Alignment - Steering Wheel Angle and/or Front Toe Adjustment | E202000 | Holden Australia |
| 8070012 | Wheel Alignment - Steering Wheel Angle and/or Front Toe Adjustment | E2000 | Holden New Zealand |
| 8070012 | Wheel Alignment - Steering Wheel Angle and/or Front Toe Adjustment | E200000 | Holden New Zealand |
| 8070012 | Wheel Alignment - Steering Wheel Angle and/or Front Toe Adjustment | E202000 | Holden New Zealand |
| 8070012 | Wheel Alignment - Steering Wheel Angle and/or Front Toe Adjustment | E301530 | Holden New Zealand |
| 8070012 | Wheel Alignment - Steering Wheel Angle and/or Front Toe Adjustment | E306500 | Holden New Zealand |
| 8070012 | Wheel Alignment - Steering Wheel Angle and/or Front Toe Adjustment | 2130100 | GMK Overseas |
| 8070032 | Wheel Alignment Measurement | E2020 | GMNA |
| 8070032 | Wheel Alignment Measurement | E5110 | GMNA |
| 8070032 | Wheel Alignment Measurement | E9461 | GMNA |
| 8070032 | Wheel Alignment Measurement | 3141900 | GMK Domestic |
| 8070032 | Wheel Alignment Measurement | F000176 | Holden Australia |
| 8070032 | Wheel Alignment Measurement | P201120 | Holden Australia |
| 8070032 | Wheel Alignment Measurement | E2020 | Holden New Zealand |
| 8070032 | Wheel Alignment Measurement | F000176 | Holden New Zealand |
| 8070032 | Wheel Alignment Measurement | P201120 | Holden New Zealand |
| 8070032 | Wheel Alignment Measurement | P201120A1 | Holden New Zealand |
| 8070032 | Wheel Alignment Measurement | 2130300 | GMK Overseas |
| 8070032 | Wheel Alignment Measurement | 213030A | GMK Overseas |
| 8079929 | Customer Concern Not Duplicated (CCND) - Suspension | E9458 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8400010 | Power Take-Off Switch Replacement | N2366 | GMNA |
| 8400030 | Engine Speed Power Take-Off Control Module Replacement | N4898 | GMNA |
| 8400030 | Engine Speed Power Take-Off Control Module Replacement | N312740 | Holden Australia |
| 8400030 | Engine Speed Power Take-Off Control Module Replacement | N312740 | Holden New Zealand |
| 8410030 | Automatic Transmission Shift Lock Control Actuator Replacement | K5125 | GMNA |
| 8410030 | Automatic Transmission Shift Lock Control Actuator Replacement | 2613600 | GMK Domestic |
| 8410030 | Automatic Transmission Shift Lock Control Actuator Replacement | N150400 | Holden Australia |
| 8410030 | Automatic Transmission Shift Lock Control Actuator Replacement | N150410 | Holden Australia |
| 8410030 | Automatic Transmission Shift Lock Control Actuator Replacement | N150400 | Holden New Zealand |
| 8410030 | Automatic Transmission Shift Lock Control Actuator Replacement | N150410 | Holden New Zealand |
| 8410100 | Shift Lock Control Solenoid Replacement | K5124 | GMNA |
| 8410100 | Shift Lock Control Solenoid Replacement | K9521 | GMNA |
| 8410100 | Shift Lock Control Solenoid Replacement | N3460 | GMNA |
| 8410100 | Shift Lock Control Solenoid Replacement | N3475 | GMNA |
| 8410100 | Shift Lock Control Solenoid Replacement | N9647 | GMNA |
| 8410100 | Shift Lock Control Solenoid Replacement | 5270800 | GMK Overseas |
| 8420010 | Transfer Case Shield Replacement | E1060 | GMNA |
| 8420010 | Transfer Case Shield Replacement | 2611800 | GMK Domestic |
| 8420010 | Transfer Case Shield Replacement | 5911300 | GMK Overseas |
| 8420030 | Transfer Case Neutral Position Switch Replacement | K4119 | GMNA |
| 8420050 | Transfer Case Shift Control Module Replacement | K4122 | GMNA |
| 8420050 | Transfer Case Shift Control Module Replacement | K4300 | GMNA |
| 8420050 | Transfer Case Shift Control Module Replacement | K4305 | GMNA |
| 8420050 | Transfer Case Shift Control Module Replacement | K9980 | GMNA |
| 8420050 | Transfer Case Shift Control Module Replacement | N8521 | GMNA |
| 8420050 | Transfer Case Shift Control Module Replacement | K4122 | Holden Australia |
| 8420050 | Transfer Case Shift Control Module Replacement | K430000 | Holden Australia |
| 8420050 | Transfer Case Shift Control Module Replacement | K000339 | Holden New Zealand |
| 8420050 | Transfer Case Shift Control Module Replacement | K430000 | Holden New Zealand |
| 8420070 | Transfer Case Shift Control Switch Replacement | K4123 | GMNA |
| 8420070 | Transfer Case Shift Control Switch Replacement | N2525 | GMNA |
| 8420070 | Transfer Case Shift Control Switch Replacement | K4123 | Holden Australia |
| 8420070 | Transfer Case Shift Control Switch Replacement | N203200 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8420070 | Transfer Case Shift Control Switch Replacement | N225100 | Holden Australia |
| 8420070 | Transfer Case Shift Control Switch Replacement | N2032 | Holden New Zealand |
| 8420090 | Transfer Case Two/Four Wheel Drive Actuator Position Sensor Replacement | K4124 | GMNA |
| 8420110 | Transfer Case Two/Four Wheel Drive Actuator Replacement | K4126 | GMNA |
| 8420160 | Transfer Case Control Lever Replacement | K1520 | GMNA |
| 8420160 | Transfer Case Control Lever Replacement | K1540 | GMNA |
| 8420160 | Transfer Case Control Lever Replacement | K4133 | GMNA |
| 8420160 | Transfer Case Control Lever Replacement | K413300 | Holden Australia |
| 8420160 | Transfer Case Control Lever Replacement | K4133 | Holden New Zealand |
| 8420160 | Transfer Case Control Lever Replacement | K413300 | Holden New Zealand |
| 8420180 | Transfer Case Control Rod Replacement | K4134 | GMNA |
| 8420200 | Transfer Case Fluid Temperature Sensor Replacement | K4153 | GMNA |
| 8420220 | Transfer Case Clutch Coil Resistor Replacement | K4125 | GMNA |
| 8420220 | Transfer Case Clutch Coil Resistor Replacement | K4154 | GMNA |
| 8420240 | Vehicle Speed Sensor Replacement | K4155 | GMNA |
| 8420240 | Vehicle Speed Sensor Replacement | 6311000 | GMK Domestic |
| 8420260 | Transfer Case Rear Output Shaft Speed Sensor Replacement | K4156 | GMNA |
| 8420260 | Transfer Case Rear Output Shaft Speed Sensor Replacement | K9806 | GMNA |
| 8420310 | Front Output Shaft Flange Seal Replacement | | |
| 8420330 | Front Output Shaft Seal Replacement | K4162 | GMNA |
| 8420330 | Front Output Shaft Seal Replacement | 2610100 | GMK Domestic |
| 8420350 | Rear Output Shaft Seal Replacement | K4163 | GMNA |
| 8420350 | Rear Output Shaft Seal Replacement | K4182 | GMNA |
| 8420350 | Rear Output Shaft Seal Replacement | K4183 | GMNA |
| 8420350 | Rear Output Shaft Seal Replacement | K400140 | Holden Australia |
| 8420350 | Rear Output Shaft Seal Replacement | K400150 | Holden Australia |
| 8420350 | Rear Output Shaft Seal Replacement | K416200 | Holden Australia |
| 8420350 | Rear Output Shaft Seal Replacement | K4163 | Holden Australia |
| 8420350 | Rear Output Shaft Seal Replacement | K400140 | Holden New Zealand |
| 8420350 | Rear Output Shaft Seal Replacement | K400150 | Holden New Zealand |
| 8420370 | Input Shaft Seal Replacement | K3177 | GMNA |
| 8420370 | Input Shaft Seal Replacement | K4164 | GMNA |
| 8420370 | Input Shaft Seal Replacement | 2320200 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8420370 | Input Shaft Seal Replacement | 2519920 | GMK Domestic |
| 8420370 | Input Shaft Seal Replacement | K205170 | Holden New Zealand |
| 8420370 | Input Shaft Seal Replacement | 5633700 | GMK Overseas |
| 8420370 | Input Shaft Seal Replacement | 5910300 | GMK Overseas |
| 8420370 | Input Shaft Seal Replacement | 5910400 | GMK Overseas |
| 8420390 | Input Shaft Seal Replacement - Right | K4165 | GMNA |
| 8420410 | Input Shaft Seal Replacement - Left | K4166 | GMNA |
| 8420430 | Front Drive Axle Inner Shaft Seal Replacement | K4168 | GMNA |
| 8420450 | Front Output Shaft Front Bearing Replacement | K4175 | GMNA |
| 8420470 | Input Shaft Bearing Replacement | K4176 | GMNA |
| 8420490 | Rear Output Shaft Rear Bearing Replacement | K4177 | GMNA |
| 8420490 | Rear Output Shaft Rear Bearing Replacement | K9815 | GMNA |
| 8420610 | Oil Pump Replacement | | |
| 8420730 | Transfer Case-to-Transmission Seal Replacement | K4221 | GMNA |
| 8420730 | Transfer Case-to-Transmission Seal Replacement | 5910900 | GMK Overseas |
| 8420750 | Intermediate Drive Shaft Seal Replacement | K4222 | GMNA |
| 8420770 | Transfer Case-To-Rear Extension Seal Replacement | K4223 | GMNA |
| 8420790 | Rear Output Shaft Housing O-Ring Seal Replacement | K4224 | GMNA |
| 8420810 | Intermediate Drive Shaft Bearing Replacement | K4225 | GMNA |
| 8420810 | Intermediate Drive Shaft Bearing Replacement | 3212200 | GMK Overseas |
| 8420830 | Intermediate Drive Shaft Replacement | K4226 | GMNA |
| 8420830 | Intermediate Drive Shaft Replacement | 4223400 | GMK Domestic |
| 8420830 | Intermediate Drive Shaft Replacement | 3211800 | GMK Overseas |
| 8420830 | Intermediate Drive Shaft Replacement | 3212100 | GMK Overseas |
| 8420830 | Intermediate Drive Shaft Replacement | 5911000 | GMK Overseas |
| 8420850 | Rear Output Shaft Flange Replacement | K4227 | GMNA |
| 8420850 | Rear Output Shaft Flange Replacement | 2610200 | GMK Domestic |
| 8420850 | Rear Output Shaft Flange Replacement | 5910500 | GMK Overseas |
| 8420850 | Rear Output Shaft Flange Replacement | 5910600 | GMK Overseas |
| 8420870 | Transfer Case Vent Replacement | K4228 | GMNA |
| 8420870 | Transfer Case Vent Replacement | K9812 | GMNA |
| 8420910 | Idler Gear Shaft Seal Replacement | K4230 | GMNA |
| 8420930 | Rear Output Flange Oil Slinger Replacement | K4231 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8420950 | Transfer Case Two/Four Wheel Drive Shift Fork and Pad Replacement | | |
| 8420970 | Transfer Case High/Low Shift Fork and Pad Replacement | | |
| 8420990 | Transfer Case Two/Four Wheel Drive Actuator Cam Replacement | | |
| 8421010 | Transfer Case Adapter Gasket Replacement | K4250 | GMNA |
| 8421010 | Transfer Case Adapter Gasket Replacement | K6440 | GMNA |
| 8421010 | Transfer Case Adapter Gasket Replacement | K8035 | GMNA |
| 8421030 | Transfer Case Adapter Replacement | K4251 | GMNA |
| 8421050 | Transfer Case Rear Extension Bushing Replacement | K4265 | GMNA |
| 8421090 | Transfer Case Adapter Bushing Replacement | | |
| 8421100 | Drain Plug Replacement | K4290 | GMNA |
| 8421100 | Drain Plug Replacement | 2410500 | GMK Domestic |
| 8421100 | Drain Plug Replacement | K4290 | Holden Australia |
| 8421120 | Fill Plug Replacement | K4291 | GMNA |
| 8421160 | Transfer Case Assembly Replacement | K4410 | GMNA |
| 8421160 | Transfer Case Assembly Replacement | K9507 | GMNA |
| 8421160 | Transfer Case Assembly Replacement | 2481200 | GMK Domestic |
| 8421160 | Transfer Case Assembly Replacement | K400100 | Holden Australia |
| 8421160 | Transfer Case Assembly Replacement | K440900 | Holden Australia |
| 8421160 | Transfer Case Assembly Replacement | K4410 | Holden Australia |
| 8421160 | Transfer Case Assembly Replacement | K441000 | Holden Australia |
| 8421160 | Transfer Case Assembly Replacement | K441100 | Holden Australia |
| 8421160 | Transfer Case Assembly Replacement | K441200 | Holden Australia |
| 8421160 | Transfer Case Assembly Replacement | K441300 | Holden Australia |
| 8421160 | Transfer Case Assembly Replacement | K441500 | Holden Australia |
| 8421160 | Transfer Case Assembly Replacement | K400100 | Holden New Zealand |
| 8421160 | Transfer Case Assembly Replacement | K441200 | Holden New Zealand |
| 8421160 | Transfer Case Assembly Replacement | 5910100 | GMK Overseas |
| 8421162 | Transfer Case Overhaul | J6384 | GMNA |
| 8421162 | Transfer Case Overhaul | K4120 | GMNA |
| 8421162 | Transfer Case Overhaul | K4190 | GMNA |
| 8421162 | Transfer Case Overhaul | K4200 | GMNA |
| 8421162 | Transfer Case Overhaul | K4400 | GMNA |
| 8421162 | Transfer Case Overhaul | K4450 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8421162 | Transfer Case Overhaul | K9813 | GMNA |
| 8421162 | Transfer Case Overhaul | K000339 | Holden Australia |
| 8421162 | Transfer Case Overhaul | K400110 | Holden Australia |
| 8421162 | Transfer Case Overhaul | K4400 | Holden Australia |
| 8421162 | Transfer Case Overhaul | K440000 | Holden Australia |
| 8421162 | Transfer Case Overhaul | K440100 | Holden Australia |
| 8421162 | Transfer Case Overhaul | K651800 | Holden Australia |
| 8421162 | Transfer Case Overhaul | K400110 | Holden New Zealand |
| 8421162 | Transfer Case Overhaul | K4400 | Holden New Zealand |
| 8421162 | Transfer Case Overhaul | K440000 | Holden New Zealand |
| 8421162 | Transfer Case Overhaul | K4700 | Holden New Zealand |
| 8421162 | Transfer Case Overhaul | K651800 | Holden New Zealand |
| 8421200 | Transfer Case Wiring and/or Connector Repair or Replacement | N6631 | GMNA |
| 8422440 | Front Wheel Drive Shaft Seal Replacement - Right Side | | |
| 8422450 | Front Wheel Drive Shaft Seal Replacement - Case Side | | |
| 8429939 | Customer Concern Not Duplicated (CCND) - Transfer Case | K9993 | GMNA |
| 8429939 | Customer Concern Not Duplicated (CCND) - Transfer Case | K9993 | Holden Australia |
| 8430010 | Hydraulic Clutch System Bleeding | K0030 | GMNA |
| 8430010 | Hydraulic Clutch System Bleeding | K0040 | GMNA |
| 8430010 | Hydraulic Clutch System Bleeding | 2130720 | GMK Domestic |
| 8430010 | Hydraulic Clutch System Bleeding | 2260200 | GMK Domestic |
| 8430010 | Hydraulic Clutch System Bleeding | K0040 | Holden New Zealand |
| 8430010 | Hydraulic Clutch System Bleeding | 5820900 | GMK Overseas |
| 8430022 | Clutch Pedal Free Travel Adjustment | K0020 | GMNA |
| 8430022 | Clutch Pedal Free Travel Adjustment | 2223800 | GMK Domestic |
| 8430022 | Clutch Pedal Free Travel Adjustment | K0020 | Holden New Zealand |
| 8430022 | Clutch Pedal Free Travel Adjustment | 5830200 | GMK Overseas |
| 8430060 | Clutch Pedal Replacement | K0060 | GMNA |
| 8430060 | Clutch Pedal Replacement | 2222000 | GMK Domestic |
| 8430060 | Clutch Pedal Replacement | K001100 | Holden Australia |
| 8430060 | Clutch Pedal Replacement | K006000 | Holden Australia |
| 8430060 | Clutch Pedal Replacement | K000363 | Holden New Zealand |
| 8430060 | Clutch Pedal Replacement | K001100 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8430060 | Clutch Pedal Replacement | K006000 | Holden New Zealand |
| 8430060 | Clutch Pedal Replacement | 5830100 | GMK Overseas |
| 8430060 | Clutch Pedal Replacement | 5830110 | GMK Overseas |
| 8430060 | Clutch Pedal Replacement | 5831500 | GMK Overseas |
| 8430160 | Clutch Pedal Arm Replacement | K0140 | GMNA |
| 8430160 | Clutch Pedal Arm Replacement | 5830900 | GMK Overseas |
| 8430210 | Clutch Cable Replacement | K0160 | GMNA |
| 8430210 | Clutch Cable Replacement | K0180 | GMNA |
| 8430210 | Clutch Cable Replacement | K002100 | Holden Australia |
| 8430210 | Clutch Cable Replacement | K018000 | Holden Australia |
| 8430210 | Clutch Cable Replacement | K002100 | Holden New Zealand |
| 8430210 | Clutch Cable Replacement | K018000 | Holden New Zealand |
| 8430210 | Clutch Cable Replacement | 5811900 | GMK Overseas |
| 8430210 | Clutch Cable Replacement | 581190A | GMK Overseas |
| 8430230 | Clutch Pedal Return Spring Replacement | K0220 | GMNA |
| 8430230 | Clutch Pedal Return Spring Replacement | K006100 | Holden New Zealand |
| 8430310 | Clutch Master Cylinder Replacement | K0600 | GMNA |
| 8430310 | Clutch Master Cylinder Replacement | K013750 | Holden Australia |
| 8430310 | Clutch Master Cylinder Replacement | K013800 | Holden Australia |
| 8430310 | Clutch Master Cylinder Replacement | K013850 | Holden Australia |
| 8430310 | Clutch Master Cylinder Replacement | K013900 | Holden Australia |
| 8430310 | Clutch Master Cylinder Replacement | K0600 | Holden Australia |
| 8430310 | Clutch Master Cylinder Replacement | K060000 | Holden Australia |
| 8430310 | Clutch Master Cylinder Replacement | K013750 | Holden New Zealand |
| 8430310 | Clutch Master Cylinder Replacement | K013800 | Holden New Zealand |
| 8430310 | Clutch Master Cylinder Replacement | K013850 | Holden New Zealand |
| 8430310 | Clutch Master Cylinder Replacement | K013900 | Holden New Zealand |
| 8430310 | Clutch Master Cylinder Replacement | K0600 | Holden New Zealand |
| 8430310 | Clutch Master Cylinder Replacement | K060000 | Holden New Zealand |
| 8430310 | Clutch Master Cylinder Replacement | 5820100 | GMK Overseas |
| 8430310 | Clutch Master Cylinder Replacement | 5820110 | GMK Overseas |
| 8430310 | Clutch Master Cylinder Replacement | 5820120 | GMK Overseas |
| 8430360 | Clutch Actuator Cylinder Replacement | K0310 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8430360 | Clutch Actuator Cylinder Replacement | K0620 | GMNA |
| 8430360 | Clutch Actuator Cylinder Replacement | 2260300 | GMK Domestic |
| 8430360 | Clutch Actuator Cylinder Replacement | 2913200 | GMK Domestic |
| 8430360 | Clutch Actuator Cylinder Replacement | J000869 | Holden Australia |
| 8430360 | Clutch Actuator Cylinder Replacement | K013600 | Holden Australia |
| 8430360 | Clutch Actuator Cylinder Replacement | K0620 | Holden Australia |
| 8430360 | Clutch Actuator Cylinder Replacement | K062000 | Holden Australia |
| 8430360 | Clutch Actuator Cylinder Replacement | K054500 | Holden New Zealand |
| 8430360 | Clutch Actuator Cylinder Replacement | K0620 | Holden New Zealand |
| 8430360 | Clutch Actuator Cylinder Replacement | K062000 | Holden New Zealand |
| 8430360 | Clutch Actuator Cylinder Replacement | 5810700 | GMK Overseas |
| 8430360 | Clutch Actuator Cylinder Replacement | 581070A | GMK Overseas |
| 8430360 | Clutch Actuator Cylinder Replacement | 5820700 | GMK Overseas |
| 8430360 | Clutch Actuator Cylinder Replacement | 5820800 | GMK Overseas |
| 8430360 | Clutch Actuator Cylinder Replacement | 5822500 | GMK Overseas |
| 8430360 | Clutch Actuator Cylinder Replacement | 5823000 | GMK Overseas |
| 8430380 | Hydraulic Clutch Low Pressure Hose Replacement | K0641 | GMNA |
| 8430400 | Clutch Master Cylinder Reservoir Hose Replacement | K0640 | GMNA |
| 8430400 | Clutch Master Cylinder Reservoir Hose Replacement | K0642 | GMNA |
| 8430400 | Clutch Master Cylinder Reservoir Hose Replacement | K0643 | GMNA |
| 8430400 | Clutch Master Cylinder Reservoir Hose Replacement | K062500 | Holden Australia |
| 8430400 | Clutch Master Cylinder Reservoir Hose Replacement | K062550 | Holden Australia |
| 8430400 | Clutch Master Cylinder Reservoir Hose Replacement | K062500 | Holden New Zealand |
| 8430400 | Clutch Master Cylinder Reservoir Hose Replacement | K062550 | Holden New Zealand |
| 8430400 | Clutch Master Cylinder Reservoir Hose Replacement | K0642 | Holden New Zealand |
| 8430400 | Clutch Master Cylinder Reservoir Hose Replacement | K0643 | Holden New Zealand |
| 8430400 | Clutch Master Cylinder Reservoir Hose Replacement | 5820300 | GMK Overseas |
| 8430450 | Clutch Actuator Cylinder Front Pipe Replacement | K0644 | GMNA |
| 8430450 | Clutch Actuator Cylinder Front Pipe Replacement | K0645 | GMNA |
| 8430450 | Clutch Actuator Cylinder Front Pipe Replacement | 2132500 | GMK Domestic |
| 8430450 | Clutch Actuator Cylinder Front Pipe Replacement | K064600 | Holden Australia |
| 8430450 | Clutch Actuator Cylinder Front Pipe Replacement | K064600 | Holden New Zealand |
| 8430530 | Clutch Actuator Cylinder Hose Replacement | K0646 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8430530 | Clutch Actuator Cylinder Hose Replacement | K0648 | GMNA |
| 8430530 | Clutch Actuator Cylinder Hose Replacement | 2171500 | GMK Domestic |
| 8430530 | Clutch Actuator Cylinder Hose Replacement | 2310100 | GMK Domestic |
| 8430530 | Clutch Actuator Cylinder Hose Replacement | K064000 | Holden New Zealand |
| 8430530 | Clutch Actuator Cylinder Hose Replacement | K0646 | Holden New Zealand |
| 8430530 | Clutch Actuator Cylinder Hose Replacement | 5821300 | GMK Overseas |
| 8430550 | Clutch Actuator Cylinder Pipe Replacement | K0660 | GMNA |
| 8430550 | Clutch Actuator Cylinder Pipe Replacement | 2250500 | GMK Domestic |
| 8430550 | Clutch Actuator Cylinder Pipe Replacement | K0660 | Holden New Zealand |
| 8430550 | Clutch Actuator Cylinder Pipe Replacement | 5810800 | GMK Overseas |
| 8430550 | Clutch Actuator Cylinder Pipe Replacement | 5820500 | GMK Overseas |
| 8430550 | Clutch Actuator Cylinder Pipe Replacement | 5820510 | GMK Overseas |
| 8430550 | Clutch Actuator Cylinder Pipe Replacement | 5822600 | GMK Overseas |
| 8430550 | Clutch Actuator Cylinder Pipe Replacement | 5822610 | GMK Overseas |
| 8430550 | Clutch Actuator Cylinder Pipe Replacement | 5822700 | GMK Overseas |
| 8430560 | Clutch Release Bearing Replacement | K0700 | GMNA |
| 8430560 | Clutch Release Bearing Replacement | 2230800 | GMK Domestic |
| 8430560 | Clutch Release Bearing Replacement | K012100 | Holden Australia |
| 8430560 | Clutch Release Bearing Replacement | K108300 | Holden Australia |
| 8430560 | Clutch Release Bearing Replacement | K012100 | Holden New Zealand |
| 8430560 | Clutch Release Bearing Replacement | K0700 | Holden New Zealand |
| 8430560 | Clutch Release Bearing Replacement | K0704 | Holden New Zealand |
| 8430560 | Clutch Release Bearing Replacement | K0707 | Holden New Zealand |
| 8430560 | Clutch Release Bearing Replacement | 1222100 | GMK Overseas |
| 8430570 | Clutch Pilot Bearing Replacement | K0701 | GMNA |
| 8430570 | Clutch Pilot Bearing Replacement | K013500 | Holden Australia |
| 8430570 | Clutch Pilot Bearing Replacement | K0701 | Holden New Zealand |
| 8430580 | Clutch Fork Assembly Replacement | K0300 | GMNA |
| 8430580 | Clutch Fork Assembly Replacement | K0720 | GMNA |
| 8430580 | Clutch Fork Assembly Replacement | K012150 | Holden Australia |
| 8430590 | Clutch Pressure and Driven Plate Replacement | K0721 | GMNA |
| 8430590 | Clutch Pressure and Driven Plate Replacement | 2120101 | GMK Domestic |
| 8430590 | Clutch Pressure and Driven Plate Replacement | 2230100 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8430590 | Clutch Pressure and Driven Plate Replacement | 2230200 | GMK Domestic |
| 8430590 | Clutch Pressure and Driven Plate Replacement | 2230300 | GMK Domestic |
| 8430590 | Clutch Pressure and Driven Plate Replacement | 2230400 | GMK Domestic |
| 8430590 | Clutch Pressure and Driven Plate Replacement | K013100 | Holden Australia |
| 8430590 | Clutch Pressure and Driven Plate Replacement | K013120 | Holden Australia |
| 8430590 | Clutch Pressure and Driven Plate Replacement | K063500 | Holden Australia |
| 8430590 | Clutch Pressure and Driven Plate Replacement | K0800 | Holden Australia |
| 8430590 | Clutch Pressure and Driven Plate Replacement | K080000 | Holden Australia |
| 8430590 | Clutch Pressure and Driven Plate Replacement | K080100 | Holden Australia |
| 8430590 | Clutch Pressure and Driven Plate Replacement | K013100 | Holden New Zealand |
| 8430590 | Clutch Pressure and Driven Plate Replacement | K013120 | Holden New Zealand |
| 8430590 | Clutch Pressure and Driven Plate Replacement | K063500 | Holden New Zealand |
| 8430590 | Clutch Pressure and Driven Plate Replacement | K0800 | Holden New Zealand |
| 8430590 | Clutch Pressure and Driven Plate Replacement | K08000 | Holden New Zealand |
| 8430590 | Clutch Pressure and Driven Plate Replacement | K080000 | Holden New Zealand |
| 8430590 | Clutch Pressure and Driven Plate Replacement | K080100 | Holden New Zealand |
| 8430590 | Clutch Pressure and Driven Plate Replacement | K0804 | Holden New Zealand |
| 8430590 | Clutch Pressure and Driven Plate Replacement | 5811100 | GMK Overseas |
| 8430590 | Clutch Pressure and Driven Plate Replacement | 581110A | GMK Overseas |
| 8430590 | Clutch Pressure and Driven Plate Replacement | 581110B | GMK Overseas |
| 8430590 | Clutch Pressure and Driven Plate Replacement | 581110C | GMK Overseas |
| 8430590 | Clutch Pressure and Driven Plate Replacement | 5811110 | GMK Overseas |
| 8430590 | Clutch Pressure and Driven Plate Replacement | 581111B | GMK Overseas |
| 8430610 | Clutch Assembly Replacement | K0800 | GMNA |
| 8430610 | Clutch Assembly Replacement | 2236000 | GMK Domestic |
| 8430620 | Clutch Housing Replacement | 2311500 | GMK Domestic |
| 8430620 | Clutch Housing Replacement | 5612300 | GMK Overseas |
| 8430620 | Clutch Housing Replacement | 5612500 | GMK Overseas |
| 8430650 | Clutch Pedal Position Sensor Replacement | N2358 | GMNA |
| 8430650 | Clutch Pedal Position Sensor Replacement | K0668 | Holden New Zealand |
| 8430650 | Clutch Pedal Position Sensor Replacement | K0669 | Holden New Zealand |
| 8430650 | Clutch Pedal Position Sensor Replacement | 5831100 | GMK Overseas |
| 8430670 | Clutch Pedal Position Switch Replacement | N2359 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8430670 | Clutch Pedal Position Switch Replacement | N000511 | Holden Australia |
| 8430670 | Clutch Pedal Position Switch Replacement | N235000 | Holden New Zealand |
| 8439919 | Customer Concern Not Duplicated (CCND) - Manual Transmission Clutch | K9991 | GMNA |
| 8439919 | Customer Concern Not Duplicated (CCND) - Manual Transmission Clutch | 2221500 | GMK Domestic |
| 8440140 | Manual Transmission Shift Lever and Selector Lever Cable Replacement | K1030 | GMNA |
| 8440140 | Manual Transmission Shift Lever and Selector Lever Cable Replacement | K9706 | GMNA |
| 8440140 | Manual Transmission Shift Lever and Selector Lever Cable Replacement | 2411300 | GMK Domestic |
| 8440140 | Manual Transmission Shift Lever and Selector Lever Cable Replacement | 2512000 | GMK Domestic |
| 8440140 | Manual Transmission Shift Lever and Selector Lever Cable Replacement | 2512100 | GMK Domestic |
| 8440140 | Manual Transmission Shift Lever and Selector Lever Cable Replacement | 3021700 | GMK Domestic |
| 8440140 | Manual Transmission Shift Lever and Selector Lever Cable Replacement | 5490200 | GMK Overseas |
| 8440140 | Manual Transmission Shift Lever and Selector Lever Cable Replacement | 5750400 | GMK Overseas |
| 8440160 | Transmission Control Lever Knob Replacement | K1040 | GMNA |
| 8440160 | Transmission Control Lever Knob Replacement | K8165 | GMNA |
| 8440160 | Transmission Control Lever Knob Replacement | 2170900 | GMK Domestic |
| 8440160 | Transmission Control Lever Knob Replacement | 2280200 | GMK Domestic |
| 8440160 | Transmission Control Lever Knob Replacement | 2280300 | GMK Domestic |
| 8440160 | Transmission Control Lever Knob Replacement | 2291000 | GMK Domestic |
| 8440160 | Transmission Control Lever Knob Replacement | K000418 | Holden Australia |
| 8440160 | Transmission Control Lever Knob Replacement | K100000 | Holden Australia |
| 8440160 | Transmission Control Lever Knob Replacement | K101100 | Holden Australia |
| 8440160 | Transmission Control Lever Knob Replacement | K511000 | Holden Australia |
| 8440160 | Transmission Control Lever Knob Replacement | K101100 | Holden New Zealand |
| 8440160 | Transmission Control Lever Knob Replacement | K511000 | Holden New Zealand |
| 8440160 | Transmission Control Lever Knob Replacement | 5690300 | GMK Overseas |
| 8440160 | Transmission Control Lever Knob Replacement | 5750100 | GMK Overseas |
| 8440180 | Shift Control Lever Replacement | K1060 | GMNA |
| 8440180 | Shift Control Lever Replacement | K104100 | Holden Australia |
| 8440180 | Shift Control Lever Replacement | K1060 | Holden Australia |
| 8440180 | Shift Control Lever Replacement | K500110 | Holden Australia |
| 8440180 | Shift Control Lever Replacement | K5220 | Holden Australia |
| 8440180 | Shift Control Lever Replacement | K1060 | Holden New Zealand |
| 8440180 | Shift Control Lever Replacement | 5660400 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8440180 | Shift Control Lever Replacement | 5662300 | GMK Overseas |
| 8440180 | Shift Control Lever Replacement | 5662500 | GMK Overseas |
| 8440180 | Shift Control Lever Replacement | 5662700 | GMK Overseas |
| 8440180 | Shift Control Lever Replacement | 5690500 | GMK Overseas |
| 8440200 | Transmission Control Lever Boot Replacement | K1080 | GMNA |
| 8440200 | Transmission Control Lever Boot Replacement | 2280500 | GMK Domestic |
| 8440200 | Transmission Control Lever Boot Replacement | K200150 | Holden Australia |
| 8440200 | Transmission Control Lever Boot Replacement | K1080 | Holden New Zealand |
| 8440200 | Transmission Control Lever Boot Replacement | K200150 | Holden New Zealand |
| 8440220 | Transmission Control Mount Plate Replacement | K1083 | GMNA |
| 8440220 | Transmission Control Mount Plate Replacement | C474210 | Holden Australia |
| 8440220 | Transmission Control Mount Plate Replacement | C474210 | Holden New Zealand |
| 8440240 | Transmission Control Replacement | K1120 | GMNA |
| 8440240 | Transmission Control Replacement | 2290100 | GMK Domestic |
| 8440240 | Transmission Control Replacement | K1120 | Holden Australia |
| 8440260 | Shift Rod Replacement | K1159 | GMNA |
| 8440390 | Manual Transmission Shift Lever Cable Replacement | K1200 | GMNA |
| 8440390 | Manual Transmission Shift Lever Cable Replacement | K107500 | Holden Australia |
| 8440390 | Manual Transmission Shift Lever Cable Replacement | 5690810 | GMK Overseas |
| 8440390 | Manual Transmission Shift Lever Cable Replacement | 5690900 | GMK Overseas |
| 8440390 | Manual Transmission Shift Lever Cable Replacement | 5690910 | GMK Overseas |
| 8440390 | Manual Transmission Shift Lever Cable Replacement | 5691500 | GMK Overseas |
| 8440392 | Manual Transmission Shift Lever Cable Adjustment | K1192 | GMNA |
| 8440392 | Manual Transmission Shift Lever Cable Adjustment | K000412 | Holden Australia |
| 8440392 | Manual Transmission Shift Lever Cable Adjustment | 5690800 | GMK Overseas |
| 8440510 | Transmission Fluid Cooler Pipe Replacement - Intermediate | | |
| 8440520 | Transmission Fluid Cooler Lower Pipe Replacement - Intermediate | | |
| 8440600 | Transmission Fluid Cooler Lower Pipe Replacement - Intermediate to Transmission | K603150 | Holden Australia |
| 8440600 | Transmission Fluid Cooler Lower Pipe Replacement - Intermediate to Transmission | K603150 | Holden New Zealand |
| 8440620 | Transmission Fluid Cooler Lower Pipe Replacement - Intermediate to Differential Cooler | | |
| 8440640 | Transmission Fluid Cooler Upper Pipe Replacement - Rear | | |
| 8440660 | Transmission Fluid Cooler Upper Pipe Replacement - Rear to Differential Cooler | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8440740 | Transmission Fluid Cooler Outlet Pipe Replacement | K2016 | GMNA |
| 8440760 | Transmission Fluid Cooler Inlet Pipe Replacement | | |
| 8440770 | Transmission Fluid Cooler Pipe Replacement - Differential Oil Cooler Inlet Hose/Pipe to Rear Transmission Cooler Pipe | | |
| 8440780 | Transmission Fluid Cooler Pipe Replacement - Differential Oil Cooler Outlet Hose/Pipe to Rear Transmission Cooler Pipe | | |
| 8440800 | Transmission Fluid Cooler Pipe Replacement - Rear Transmission Cooler Outlet Pipe to Differential Oil Cooler Hose/Pipe | | |
| 8440810 | Transmission Fluid Cooler Pipe Replacement - Rear Transmission Cooler Inlet Pipe to Differential Oil Cooler Hose/Pipe | | |
| 8440830 | Transmission Fluid Cooler Pipe Replacement - Front Transmission Cooler Line to Radiator Transmission Cooler Hose/Pipe | | |
| 8440870 | Gear Position Sensor Replacement | | |
| 8440890 | Vehicle Speed Sensor Replacement | K2050 | GMNA |
| 8440890 | Vehicle Speed Sensor Replacement | K2052 | GMNA |
| 8440890 | Vehicle Speed Sensor Replacement | 6310800 | GMK Domestic |
| 8440890 | Vehicle Speed Sensor Replacement | K205000 | Holden Australia |
| 8440890 | Vehicle Speed Sensor Replacement | N960602 | Holden Australia |
| 8440890 | Vehicle Speed Sensor Replacement | K2050 | Holden New Zealand |
| 8440890 | Vehicle Speed Sensor Replacement | K205000 | Holden New Zealand |
| 8440890 | Vehicle Speed Sensor Replacement | K2051 | Holden New Zealand |
| 8440890 | Vehicle Speed Sensor Replacement | 5863100 | GMK Overseas |
| 8440910 | Fluid Temperature Sensor Replacement | K2051 | GMNA |
| 8440930 | Reverse Lockout Solenoid Replacement | K2053 | GMNA |
| 8440930 | Reverse Lockout Solenoid Replacement | K500400 | Holden Australia |
| 8440930 | Reverse Lockout Solenoid Replacement | K500310 | Holden New Zealand |
| 8440930 | Reverse Lockout Solenoid Replacement | K500400 | Holden New Zealand |
| 8440950 | 2nd and 3rd Gear Blockout Solenoid Replacement | K2054 | GMNA |
| 8441000 | Speedometer Driven Gear Replacement | K2060 | GMNA |
| 8441000 | Speedometer Driven Gear Replacement | K6320 | GMNA |
| 8441000 | Speedometer Driven Gear Replacement | 2470200 | GMK Domestic |
| 8441000 | Speedometer Driven Gear Replacement | 2515400 | GMK Domestic |
| 8441000 | Speedometer Driven Gear Replacement | K206000 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8441000 | Speedometer Driven Gear Replacement | K2060 | Holden New Zealand |
| 8441000 | Speedometer Driven Gear Replacement | K6320 | Holden New Zealand |
| 8441000 | Speedometer Driven Gear Replacement | 5670900 | GMK Overseas |
| 8441000 | Speedometer Driven Gear Replacement | 5810300 | GMK Overseas |
| 8441000 | Speedometer Driven Gear Replacement | 5810310 | GMK Overseas |
| 8441050 | Transmission Oil Filler or Drain Plug Replacement | K2150 | GMNA |
| 8441120 | Main Shaft Rear Seal Replacement | K2163 | GMNA |
| 8441230 | Front Differential Carrier Cover Replacement | K2239 | GMNA |
| 8441230 | Front Differential Carrier Cover Replacement | K204300 | Holden Australia |
| 8441230 | Front Differential Carrier Cover Replacement | K204300 | Holden New Zealand |
| 8441230 | Front Differential Carrier Cover Replacement | 5811500 | GMK Overseas |
| 8441250 | Shift Control Cover Replacement | K2240 | GMNA |
| 8441250 | Shift Control Cover Replacement | 2410600 | GMK Domestic |
| 8441250 | Shift Control Cover Replacement | K508220 | Holden Australia |
| 8441250 | Shift Control Cover Replacement | 5660100 | GMK Overseas |
| 8441270 | Shift Control Housing Seal Replacement | K2241 | GMNA |
| 8441290 | Shift Control Housing Replacement | A9080 | GMNA |
| 8441290 | Shift Control Housing Replacement | K2242 | GMNA |
| 8441290 | Shift Control Housing Replacement | K1130 | Holden New Zealand |
| 8441290 | Shift Control Housing Replacement | K2240 | Holden New Zealand |
| 8441370 | Transmission Mount Replacement - Left Side | K2281 | GMNA |
| 8441390 | Transmission Front Mount Replacement | K2282 | GMNA |
| 8441390 | Transmission Front Mount Replacement | 2420200 | GMK Domestic |
| 8441390 | Transmission Front Mount Replacement | 1381200 | GMK Overseas |
| 8441410 | Transmission Rear Mount Replacement | K2283 | GMNA |
| 8441410 | Transmission Rear Mount Replacement | K9513 | GMNA |
| 8441430 | Transmission Mount Replacement | K2284 | GMNA |
| 8441430 | Transmission Mount Replacement | K9512 | GMNA |
| 8441690 | Transmission Rear Cover Replacement | K2560 | GMNA |
| 8441690 | Transmission Rear Cover Replacement | 2320100 | GMK Domestic |
| 8441690 | Transmission Rear Cover Replacement | 2401120 | GMK Domestic |
| 8441690 | Transmission Rear Cover Replacement | 2410300 | GMK Domestic |
| 8441690 | Transmission Rear Cover Replacement | 5261700 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8441690 | Transmission Rear Cover Replacement | 5612700 | GMK Overseas |
| 8441690 | Transmission Rear Cover Replacement | 5650100 | GMK Overseas |
| 8441690 | Transmission Rear Cover Replacement | 5650200 | GMK Overseas |
| 8441690 | Transmission Rear Cover Replacement | 5710600 | GMK Overseas |
| 8441710 | Transmission Vent Tube Replacement | K2570 | GMNA |
| 8441710 | Transmission Vent Tube Replacement | K9515 | GMNA |
| 8441710 | Transmission Vent Tube Replacement | K9543 | GMNA |
| 8441710 | Transmission Vent Tube Replacement | 2310500 | GMK Domestic |
| 8441780 | Transmission Replacement | K2720 | GMNA |
| 8441780 | Transmission Replacement | K3120 | GMNA |
| 8441780 | Transmission Replacement | 2311000 | GMK Domestic |
| 8441780 | Transmission Replacement | 2311200 | GMK Domestic |
| 8441780 | Transmission Replacement | 2512500 | GMK Domestic |
| 8441780 | Transmission Replacement | K000264 | Holden Australia |
| 8441780 | Transmission Replacement | K205100 | Holden Australia |
| 8441780 | Transmission Replacement | K205110 | Holden Australia |
| 8441780 | Transmission Replacement | K270000 | Holden Australia |
| 8441780 | Transmission Replacement | K270100 | Holden Australia |
| 8441780 | Transmission Replacement | K2720 | Holden Australia |
| 8441780 | Transmission Replacement | K272000 | Holden Australia |
| 8441780 | Transmission Replacement | K272100 | Holden Australia |
| 8441780 | Transmission Replacement | K205100 | Holden New Zealand |
| 8441780 | Transmission Replacement | K205110 | Holden New Zealand |
| 8441780 | Transmission Replacement | K270000 | Holden New Zealand |
| 8441780 | Transmission Replacement | K270100 | Holden New Zealand |
| 8441780 | Transmission Replacement | K270100B | Holden New Zealand |
| 8441780 | Transmission Replacement | K2720 | Holden New Zealand |
| 8441780 | Transmission Replacement | K272000 | Holden New Zealand |
| 8441780 | Transmission Replacement | K272100 | Holden New Zealand |
| 8441780 | Transmission Replacement | K2725 | Holden New Zealand |
| 8441780 | Transmission Replacement | 5610100 | GMK Overseas |
| 8441780 | Transmission Replacement | 561010A | GMK Overseas |
| 8441780 | Transmission Replacement | 561010B | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8441780 | Transmission Replacement | 5710100 | GMK Overseas |
| 8441782 | Transmission Overhaul | K2700 | GMNA |
| 8441782 | Transmission Overhaul | K8030 | GMNA |
| 8441782 | Transmission Overhaul | N6045 | GMNA |
| 8441782 | Transmission Overhaul | N6046 | GMNA |
| 8441782 | Transmission Overhaul | 2210110 | GMK Domestic |
| 8441782 | Transmission Overhaul | 2311300 | GMK Domestic |
| 8441782 | Transmission Overhaul | 2311400 | GMK Domestic |
| 8441782 | Transmission Overhaul | 2512600 | GMK Domestic |
| 8441782 | Transmission Overhaul | K205110A3 | Holden New Zealand |
| 8441782 | Transmission Overhaul | K2700 | Holden New Zealand |
| 8441782 | Transmission Overhaul | K2701 | Holden New Zealand |
| 8441782 | Transmission Overhaul | K2702 | Holden New Zealand |
| 8441782 | Transmission Overhaul | K2703 | Holden New Zealand |
| 8441782 | Transmission Overhaul | K2705 | Holden New Zealand |
| 8441782 | Transmission Overhaul | K2706 | Holden New Zealand |
| 8441782 | Transmission Overhaul | K2707 | Holden New Zealand |
| 8441782 | Transmission Overhaul | K2710 | Holden New Zealand |
| 8441782 | Transmission Overhaul | 5240100 | GMK Overseas |
| 8441782 | Transmission Overhaul | 5310400 | GMK Overseas |
| 8441782 | Transmission Overhaul | 5410300 | GMK Overseas |
| 8441782 | Transmission Overhaul | 5610300 | GMK Overseas |
| 8441782 | Transmission Overhaul | 561030A | GMK Overseas |
| 8441782 | Transmission Overhaul | 561030D | GMK Overseas |
| 8441800 | Input Shaft Bearing Retainer Replacement | K2736 | GMNA |
| 8441850 | Input Shaft Bearing Replacement | K2739 | GMNA |
| 8441850 | Input Shaft Bearing Replacement | 2230600 | GMK Domestic |
| 8441850 | Input Shaft Bearing Replacement | K108700 | Holden Australia |
| 8441850 | Input Shaft Bearing Replacement | K108700 | Holden New Zealand |
| 8441870 | Transmission Fluid Pump Replacement | K2740 | GMNA |
| 8441890 | Power Take-Off Cover Replacement | K2744 | GMNA |
| 8441940 | 4th Gear Replacement | K2749 | GMNA |
| 8441940 | 4th Gear Replacement | K3141 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8441940 | 4th Gear Replacement | 2234500 | GMK Domestic |
| 8441940 | 4th Gear Replacement | K108230 | Holden Australia |
| 8441940 | 4th Gear Replacement | 5630300 | GMK Overseas |
| 8441940 | 4th Gear Replacement | 5633900 | GMK Overseas |
| 8441940 | 4th Gear Replacement | 5720200 | GMK Overseas |
| 8441960 | Reverse Gear Replacement | K2750 | GMNA |
| 8441960 | Reverse Gear Replacement | K108280 | Holden Australia |
| 8441960 | Reverse Gear Replacement | F000156 | Holden New Zealand |
| 8441960 | Reverse Gear Replacement | K108280 | Holden New Zealand |
| 8441980 | 5th Gear Replacement | K2751 | GMNA |
| 8441980 | 5th Gear Replacement | K2773 | GMNA |
| 8441980 | 5th Gear Replacement | 2480200 | GMK Domestic |
| 8441980 | 5th Gear Replacement | K000258 | Holden Australia |
| 8441980 | 5th Gear Replacement | K108240 | Holden Australia |
| 8441980 | 5th Gear Replacement | K108240 | Holden New Zealand |
| 8441980 | 5th Gear Replacement | 5630100 | GMK Overseas |
| 8441980 | 5th Gear Replacement | 5633800 | GMK Overseas |
| 8441980 | 5th Gear Replacement | 5720100 | GMK Overseas |
| 8442000 | 3rd Gear Replacement | K2752 | GMNA |
| 8442000 | 3rd Gear Replacement | 2233500 | GMK Domestic |
| 8442000 | 3rd Gear Replacement | K108220 | Holden Australia |
| 8442000 | 3rd Gear Replacement | K108220 | Holden New Zealand |
| 8442000 | 3rd Gear Replacement | 5630500 | GMK Overseas |
| 8442000 | 3rd Gear Replacement | 563050A | GMK Overseas |
| 8442000 | 3rd Gear Replacement | 5634100 | GMK Overseas |
| 8442000 | 3rd Gear Replacement | 5720300 | GMK Overseas |
| 8442010 | Input 3rd Gear Replacement | K3142 | GMNA |
| 8442020 | 2nd Gear Replacement | K2753 | GMNA |
| 8442020 | 2nd Gear Replacement | K3139 | GMNA |
| 8442020 | 2nd Gear Replacement | K108210 | Holden Australia |
| 8442020 | 2nd Gear Replacement | K108210 | Holden New Zealand |
| 8442020 | 2nd Gear Replacement | 5630700 | GMK Overseas |
| 8442020 | 2nd Gear Replacement | 5720400 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8442030 | Intermediate 2nd Counter Gear Replacement | | |
| 8442040 | 1st Gear Replacement | K2754 | GMNA |
| 8442040 | 1st Gear Replacement | 2232400 | GMK Domestic |
| 8442040 | 1st Gear Replacement | K108200 | Holden Australia |
| 8442040 | 1st Gear Replacement | K108200 | Holden New Zealand |
| 8442040 | 1st Gear Replacement | 5630900 | GMK Overseas |
| 8442040 | 1st Gear Replacement | 5720500 | GMK Overseas |
| 8442050 | Intermediate 1st Gear Replacement | K3138 | GMNA |
| 8442060 | 1st and 2nd Gear Synchronizer Replacement | K2755 | GMNA |
| 8442060 | 1st and 2nd Gear Synchronizer Replacement | 2461000 | GMK Domestic |
| 8442060 | 1st and 2nd Gear Synchronizer Replacement | 5631700 | GMK Overseas |
| 8442060 | 1st and 2nd Gear Synchronizer Replacement | 5631900 | GMK Overseas |
| 8442060 | 1st and 2nd Gear Synchronizer Replacement | 5720900 | GMK Overseas |
| 8442060 | 1st and 2nd Gear Synchronizer Replacement | 5721000 | GMK Overseas |
| 8442080 | 3rd and 4th Gear Synchronizer Replacement | K2756 | GMNA |
| 8442080 | 3rd and 4th Gear Synchronizer Replacement | 2480100 | GMK Domestic |
| 8442080 | 3rd and 4th Gear Synchronizer Replacement | 5631500 | GMK Overseas |
| 8442080 | 3rd and 4th Gear Synchronizer Replacement | 563150A | GMK Overseas |
| 8442080 | 3rd and 4th Gear Synchronizer Replacement | 5632100 | GMK Overseas |
| 8442080 | 3rd and 4th Gear Synchronizer Replacement | 5720800 | GMK Overseas |
| 8442080 | 3rd and 4th Gear Synchronizer Replacement | 5721100 | GMK Overseas |
| 8442100 | 5th and Reverse Gear Synchronizer Replacement | K2757 | GMNA |
| 8442100 | 5th and Reverse Gear Synchronizer Replacement | 5632300 | GMK Overseas |
| 8442100 | 5th and Reverse Gear Synchronizer Replacement | 5721200 | GMK Overseas |
| 8442120 | Input Shaft Replacement | K2758 | GMNA |
| 8442120 | Input Shaft Replacement | 2615000 | GMK Domestic |
| 8442120 | Input Shaft Replacement | 2912800 | GMK Domestic |
| 8442120 | Input Shaft Replacement | K108800 | Holden Australia |
| 8442120 | Input Shaft Replacement | 5631000 | GMK Overseas |
| 8442120 | Input Shaft Replacement | 5633100 | GMK Overseas |
| 8442120 | Input Shaft Replacement | 5633300 | GMK Overseas |
| 8442120 | Input Shaft Replacement | 5640500 | GMK Overseas |
| 8442120 | Input Shaft Replacement | 5721300 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8442120 | Input Shaft Replacement | 5721400 | GMK Overseas |
| 8442122 | Input Shaft Overhaul | K3145 | GMNA |
| 8442140 | Main Shaft Replacement | K2759 | GMNA |
| 8442140 | Main Shaft Replacement | K108400 | Holden Australia |
| 8442140 | Main Shaft Replacement | 5631100 | GMK Overseas |
| 8442160 | Reverse Idler Gear Replacement | K2760 | GMNA |
| 8442160 | Reverse Idler Gear Replacement | 5633400 | GMK Overseas |
| 8442160 | Reverse Idler Gear Replacement | 5640900 | GMK Overseas |
| 8442160 | Reverse Idler Gear Replacement | 5721500 | GMK Overseas |
| 8442180 | Counter Gear Shaft Assembly Replacement | K2761 | GMNA |
| 8442180 | Counter Gear Shaft Assembly Replacement | 5631200 | GMK Overseas |
| 8442180 | Counter Gear Shaft Assembly Replacement | 5633500 | GMK Overseas |
| 8442180 | Counter Gear Shaft Assembly Replacement | 5721600 | GMK Overseas |
| 8442200 | Counter Gear Front Bearing Replacement | K2762 | GMNA |
| 8442220 | Transmission Adapter Replacement | K2763 | GMNA |
| 8442270 | 1st and 2nd Shift Fork Replacement | K2765 | GMNA |
| 8442270 | 1st and 2nd Shift Fork Replacement | K2770 | GMNA |
| 8442270 | 1st and 2nd Shift Fork Replacement | K2771 | GMNA |
| 8442270 | 1st and 2nd Shift Fork Replacement | K3185 | GMNA |
| 8442270 | 1st and 2nd Shift Fork Replacement | 2223400 | GMK Domestic |
| 8442270 | 1st and 2nd Shift Fork Replacement | 2224100 | GMK Domestic |
| 8442270 | 1st and 2nd Shift Fork Replacement | 2422200 | GMK Domestic |
| 8442270 | 1st and 2nd Shift Fork Replacement | 2512720 | GMK Domestic |
| 8442270 | 1st and 2nd Shift Fork Replacement | 5660300 | GMK Overseas |
| 8442270 | 1st and 2nd Shift Fork Replacement | 5730400 | GMK Overseas |
| 8442290 | 3rd and 4th Shift Fork Replacement | K2766 | GMNA |
| 8442290 | 3rd and 4th Shift Fork Replacement | K3186 | GMNA |
| 8442290 | 3rd and 4th Shift Fork Replacement | 2223100 | GMK Domestic |
| 8442290 | 3rd and 4th Shift Fork Replacement | 2223500 | GMK Domestic |
| 8442290 | 3rd and 4th Shift Fork Replacement | 2224200 | GMK Domestic |
| 8442290 | 3rd and 4th Shift Fork Replacement | 2422000 | GMK Domestic |
| 8442290 | 3rd and 4th Shift Fork Replacement | 5660500 | GMK Overseas |
| 8442290 | 3rd and 4th Shift Fork Replacement | 5730500 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8442310 | 5th and Reverse Shift Fork Replacement | K2767 | GMNA |
| 8442310 | 5th and Reverse Shift Fork Replacement | 2223600 | GMK Domestic |
| 8442310 | 5th and Reverse Shift Fork Replacement | 2224300 | GMK Domestic |
| 8442310 | 5th and Reverse Shift Fork Replacement | 2420900 | GMK Domestic |
| 8442330 | Shift Interlock Detent Replacement | K2768 | GMNA |
| 8442410 | 6th Gear Replacement | K2748 | GMNA |
| 8442410 | 6th Gear Replacement | K2775 | GMNA |
| 8442410 | 6th Gear Replacement | K108250 | Holden Australia |
| 8442432 | Shift Shaft and Fork Assemblies Overhaul | K2776 | GMNA |
| 8442450 | 5th Gear Synchronizer Replacement | K2778 | GMNA |
| 8442450 | 5th Gear Synchronizer Replacement | 5631300 | GMK Overseas |
| 8442450 | 5th Gear Synchronizer Replacement | 5720700 | GMK Overseas |
| 8442470 | Reverse Gear Synchronizer Replacement | K2780 | GMNA |
| 8442490 | 5th and 6th Shift Fork Replacement | K2785 | GMNA |
| 8442490 | 5th and 6th Shift Fork Replacement | 5650900 | GMK Overseas |
| 8442490 | 5th and 6th Shift Fork Replacement | 5661900 | GMK Overseas |
| 8442490 | 5th and 6th Shift Fork Replacement | 5662400 | GMK Overseas |
| 8442510 | Reverse Shift Fork Replacement | K2788 | GMNA |
| 8442510 | Reverse Shift Fork Replacement | 2223300 | GMK Domestic |
| 8442510 | Reverse Shift Fork Replacement | 2223700 | GMK Domestic |
| 8442510 | Reverse Shift Fork Replacement | 2422100 | GMK Domestic |
| 8442510 | Reverse Shift Fork Replacement | 2422300 | GMK Domestic |
| 8442510 | Reverse Shift Fork Replacement | 5660900 | GMK Overseas |
| 8442510 | Reverse Shift Fork Replacement | 5730600 | GMK Overseas |
| 8442530 | 5th and 6th and Reverse Shift Shaft Replacement | K2789 | GMNA |
| 8442582 | Extension Overhaul | K2791 | GMNA |
| 8442680 | Input Shaft Seal Replacement | K2823 | GMNA |
| 8442680 | Input Shaft Seal Replacement | K108600 | Holden Australia |
| 8442680 | Input Shaft Seal Replacement | K205120 | Holden Australia |
| 8442680 | Input Shaft Seal Replacement | K205130 | Holden Australia |
| 8442680 | Input Shaft Seal Replacement | K108600 | Holden New Zealand |
| 8442680 | Input Shaft Seal Replacement | K205120 | Holden New Zealand |
| 8442680 | Input Shaft Seal Replacement | K205130 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8442680 | Input Shaft Seal Replacement | K2200 | Holden New Zealand |
| 8442680 | Input Shaft Seal Replacement | K2201 | Holden New Zealand |
| 8442680 | Input Shaft Seal Replacement | K220100 | Holden New Zealand |
| 8442680 | Input Shaft Seal Replacement | K220200 | Holden New Zealand |
| 8442680 | Input Shaft Seal Replacement | K2203 | Holden New Zealand |
| 8442680 | Input Shaft Seal Replacement | K220300 | Holden New Zealand |
| 8442680 | Input Shaft Seal Replacement | 5721800 | GMK Overseas |
| 8442700 | Shift Control Lever Bracket Replacement | K2824 | GMNA |
| 8442700 | Shift Control Lever Bracket Replacement | K000415 | Holden Australia |
| 8442700 | Shift Control Lever Bracket Replacement | 5371000 | GMK Overseas |
| 8443020 | Front Wheel Drive Shaft Seal Replacement - Right Side | K3010 | GMNA |
| 8443020 | Front Wheel Drive Shaft Seal Replacement - Right Side | 5740700 | GMK Overseas |
| 8443040 | Front Wheel Drive Shaft Seal Replacement - Left Side | K3011 | GMNA |
| 8443040 | Front Wheel Drive Shaft Seal Replacement - Left Side | 2480302 | GMK Domestic |
| 8443040 | Front Wheel Drive Shaft Seal Replacement - Left Side | 2610202 | GMK Domestic |
| 8443040 | Front Wheel Drive Shaft Seal Replacement - Left Side | 5740800 | GMK Overseas |
| 8443060 | Front Wheel Drive Shaft Seal Replacement | K3012 | GMNA |
| 8443060 | Front Wheel Drive Shaft Seal Replacement | 2510800 | GMK Domestic |
| 8443060 | Front Wheel Drive Shaft Seal Replacement | 2510900 | GMK Domestic |
| 8443060 | Front Wheel Drive Shaft Seal Replacement | 2515600 | GMK Domestic |
| 8443060 | Front Wheel Drive Shaft Seal Replacement | 5421000 | GMK Overseas |
| 8443140 | Front Differential Assembly Replacement | K3130 | GMNA |
| 8443140 | Front Differential Assembly Replacement | 2621700 | GMK Domestic |
| 8443140 | Front Differential Assembly Replacement | 5011400 | GMK Overseas |
| 8443140 | Front Differential Assembly Replacement | 5670100 | GMK Overseas |
| 8443140 | Front Differential Assembly Replacement | 5670200 | GMK Overseas |
| 8443140 | Front Differential Assembly Replacement | 5740100 | GMK Overseas |
| 8443140 | Front Differential Assembly Replacement | 5740600 | GMK Overseas |
| 8443160 | Differential Bearing Replacement | K3131 | GMNA |
| 8443160 | Differential Bearing Replacement | 5671900 | GMK Overseas |
| 8443180 | Differential Ring Gear Replacement | K3132 | GMNA |
| 8443180 | Differential Ring Gear Replacement | 5241200 | GMK Overseas |
| 8443180 | Differential Ring Gear Replacement | 5670500 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8443180 | Differential Ring Gear Replacement | 5740300 | GMK Overseas |
| 8443200 | Differential Pinion Gear and Side Gear Replacement | K3133 | GMNA |
| 8443200 | Differential Pinion Gear and Side Gear Replacement | 2280600 | GMK Domestic |
| 8443200 | Differential Pinion Gear and Side Gear Replacement | 2280700 | GMK Domestic |
| 8443200 | Differential Pinion Gear and Side Gear Replacement | 2511300 | GMK Domestic |
| 8443200 | Differential Pinion Gear and Side Gear Replacement | 2511700 | GMK Domestic |
| 8443200 | Differential Pinion Gear and Side Gear Replacement | 5670700 | GMK Overseas |
| 8443220 | Front Wheel Speed Sensor Reluctor Wheel Replacement | K3134 | GMNA |
| 8443220 | Front Wheel Speed Sensor Reluctor Wheel Replacement | 2470100 | GMK Domestic |
| 8443240 | Differential Case Replacement | K3135 | GMNA |
| 8443310 | Input 4th Gear Replacement | | |
| 8443320 | Input 5th Gear Replacement | K3140 | GMNA |
| 8443320 | Input 5th Gear Replacement | 5640100 | GMK Overseas |
| 8443320 | Input 5th Gear Replacement | 5721900 | GMK Overseas |
| 8443430 | Output 5th Gear Replacement | K3150 | GMNA |
| 8443450 | Output 4th Gear Replacement | K3151 | GMNA |
| 8443470 | Output 3rd Gear Replacement | K3152 | GMNA |
| 8443490 | Output 2nd Gear Replacement | K3153 | GMNA |
| 8443510 | Output 1st Gear Replacement | K3154 | GMNA |
| 8443530 | Output Main Shaft Assembly Replacement | K3155 | GMNA |
| 8443550 | Output Reverse Gear Replacement | K3156 | GMNA |
| 8443550 | Output Reverse Gear Replacement | K3157 | GMNA |
| 8443600 | 5th Gear Synchronizer Hub Replacement | K3160 | GMNA |
| 8443600 | 5th Gear Synchronizer Hub Replacement | 2235600 | GMK Domestic |
| 8443600 | 5th Gear Synchronizer Hub Replacement | 2480300 | GMK Domestic |
| 8443620 | 3rd and 4th Gear Synchronizer Hub Replacement | K3161 | GMNA |
| 8443620 | 3rd and 4th Gear Synchronizer Hub Replacement | 2233600 | GMK Domestic |
| 8443620 | 3rd and 4th Gear Synchronizer Hub Replacement | 2470300 | GMK Domestic |
| 8443640 | 1st and 2nd Gear Synchronizer Hub Replacement | K3162 | GMNA |
| 8443690 | Clutch Housing Replacement | K3170 | GMNA |
| 8443760 | Output Main Shaft Bearing Replacement | K3178 | GMNA |
| 8443760 | Output Main Shaft Bearing Replacement | K3179 | GMNA |
| 8443810 | Transmission Case Replacement | K3180 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8443810 | Transmission Case Replacement | 2410110 | GMK Domestic |
| 8443810 | Transmission Case Replacement | 2410120 | GMK Domestic |
| 8443810 | Transmission Case Replacement | K205200 | Holden Australia |
| 8443810 | Transmission Case Replacement | K201500 | Holden New Zealand |
| 8443810 | Transmission Case Replacement | K205200 | Holden New Zealand |
| 8443810 | Transmission Case Replacement | 5021000 | GMK Overseas |
| 8443810 | Transmission Case Replacement | 5661100 | GMK Overseas |
| 8443870 | 5th Shift Fork Replacement | K3187 | GMNA |
| 8443870 | 5th Shift Fork Replacement | K3189 | GMNA |
| 8443870 | 5th Shift Fork Replacement | 5660700 | GMK Overseas |
| 8443870 | 5th Shift Fork Replacement | 5730700 | GMK Overseas |
| 8443930 | Shift Control Housing Cover Gasket Replacement | | |
| 8443990 | Shift Control Housing Cover Replacement | | |
| 8444140 | Backup Lamp Switch Replacement | N2030 | GMNA |
| 8444140 | Backup Lamp Switch Replacement | 5810200 | GMK Domestic |
| 8444140 | Backup Lamp Switch Replacement | N2030 | Holden New Zealand |
| 8444140 | Backup Lamp Switch Replacement | 5811300 | GMK Overseas |
| 8444160 | Backup Lamp Switch with Transmission Position Sensor Replacement | N2031 | GMNA |
| 8449929 | Customer Concern Not Duplicated (CCND) - Manual Transmission | K9992 | GMNA |
| 8449929 | Customer Concern Not Duplicated (CCND) - Manual Transmission | K9992 | Holden Australia |
| 8460070 | Transmission Control Lever Boot Replacement | K5103 | GMNA |
| 8460110 | Automatic Transmission Control Indicator Replacement | K5105 | GMNA |
| 8460110 | Automatic Transmission Control Indicator Replacement | 5040300 | GMK Overseas |
| 8460130 | Control Lever Housing Bezel Replacement | K5106 | GMNA |
| 8460150 | Transmission Control Lever Knob Cover Replacement | K5109 | GMNA |
| 8460170 | Transmission Control Lever Knob Replacement | K5110 | GMNA |
| 8460170 | Transmission Control Lever Knob Replacement | 5190100 | GMK Overseas |
| 8460170 | Transmission Control Lever Knob Replacement | 5270100 | GMK Overseas |
| 8460170 | Transmission Control Lever Knob Replacement | 5490100 | GMK Overseas |
| 8460190 | Control Lever Handle Replacement | K5111 | GMNA |
| 8460210 | Automatic Transmission Range Selector Lever Replacement | K5119 | GMNA |
| 8460210 | Automatic Transmission Range Selector Lever Replacement | K9525 | GMNA |
| 8460290 | Manual Shift Auxiliary Position Switch Replacement - Steering Wheel | K5159 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8460330 | Park Lock Cable Replacement | K5165 | GMNA |
| 8460332 | Park Lock Cable Adjustment | K5173 | GMNA |
| 8460370 | Range Selector Lever Cable Replacement | J5332 | GMNA |
| 8460370 | Range Selector Lever Cable Replacement | K5168 | GMNA |
| 8460370 | Range Selector Lever Cable Replacement | K503100 | Holden New Zealand |
| 8460370 | Range Selector Lever Cable Replacement | 5040900 | GMK Overseas |
| 8460370 | Range Selector Lever Cable Replacement | 5190500 | GMK Overseas |
| 8460370 | Range Selector Lever Cable Replacement | 5270200 | GMK Overseas |
| 8460372 | Range Selector Lever Cable Adjustment | K5167 | GMNA |
| 8460372 | Range Selector Lever Cable Adjustment | 5490400 | GMK Overseas |
| 8460510 | Range Selector Lever Link Replacement | K5181 | GMNA |
| 8460512 | Range Selector Lever Link Adjustment | K5182 | GMNA |
| 8460670 | Transmission Control Replacement | K5222 | GMNA |
| 8460670 | Transmission Control Replacement | K2960 | Holden New Zealand |
| 8460670 | Transmission Control Replacement | K2960NZ | Holden New Zealand |
| 8460670 | Transmission Control Replacement | 5490300 | GMK Overseas |
| 8460680 | Transmission Fluid Auxiliary Cooler Replacement | | |
| 8460710 | Automatic Transmission Control Base Replacement | K5224 | GMNA |
| 8460790 | Park/Neutral Position Switch Replacement | J6383 | GMNA |
| 8460790 | Park/Neutral Position Switch Replacement | K5228 | GMNA |
| 8460790 | Park/Neutral Position Switch Replacement | N2323 | GMNA |
| 8460790 | Park/Neutral Position Switch Replacement | N209510 | Holden Australia |
| 8460790 | Park/Neutral Position Switch Replacement | N209510 | Holden New Zealand |
| 8460790 | Park/Neutral Position Switch Replacement | N2323 | Holden New Zealand |
| 8460790 | Park/Neutral Position Switch Replacement | 5011700 | GMK Overseas |
| 8460790 | Park/Neutral Position Switch Replacement | 5191300 | GMK Overseas |
| 8460790 | Park/Neutral Position Switch Replacement | 5240900 | GMK Overseas |
| 8460790 | Park/Neutral Position Switch Replacement | 5270600 | GMK Overseas |
| 8460790 | Park/Neutral Position Switch Replacement | 5370600 | GMK Overseas |
| 8460792 | Park/Neutral Position Switch Adjustment | K5230 | GMNA |
| 8460792 | Park/Neutral Position Switch Adjustment | N9656 | GMNA |
| 8460930 | Transmission Fluid Auxiliary Cooler Kit Replacement | | |
| 8461090 | Transmission Fluid Cooler Inlet Pipe Replacement | 2719100 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8461090 | Transmission Fluid Cooler Inlet Pipe Replacement | 5251100 | GMK Overseas |
| 8461110 | Transmission Fluid Cooler Outlet Pipe Replacement | 5251200 | GMK Overseas |
| 8461240 | Transmission Fluid Cooler Pipe Connector Replacement - Radiator | | |
| 8461270 | Transmission Fluid Cooler Hose Replacement | | |
| 8461290 | Engine Oil and Transmission Fluid Cooler Replacement | K5289 | GMNA |
| 8461330 | Transmission Fluid Cooler Pipe Replacement | K2008 | GMNA |
| 8461330 | Transmission Fluid Cooler Pipe Replacement | K5270 | GMNA |
| 8461330 | Transmission Fluid Cooler Pipe Replacement | K5271 | GMNA |
| 8461330 | Transmission Fluid Cooler Pipe Replacement | K5294 | GMNA |
| 8461330 | Transmission Fluid Cooler Pipe Replacement | K5396 | GMNA |
| 8461330 | Transmission Fluid Cooler Pipe Replacement | K5399 | GMNA |
| 8461350 | Transmission Fluid Cooler Pipe Fitting Replacement | K5295 | GMNA |
| 8461350 | Transmission Fluid Cooler Pipe Fitting Replacement | K603000 | Holden Australia |
| 8461350 | Transmission Fluid Cooler Pipe Fitting Replacement | K603000 | Holden New Zealand |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | K2006 | GMNA |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | K5283 | GMNA |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | K5288 | GMNA |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | K5296 | GMNA |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | K5384 | GMNA |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | 2630700 | GMK Domestic |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | 3122600 | GMK Domestic |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | K603100 | Holden Australia |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | K603200 | Holden Australia |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | K605200 | Holden Australia |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | K605300 | Holden Australia |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | K605400 | Holden Australia |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | K603200 | Holden New Zealand |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | K605200 | Holden New Zealand |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | K605300 | Holden New Zealand |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | K605400 | Holden New Zealand |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | 5021900 | GMK Overseas |
| 8461370 | Transmission Fluid Cooler Hose/Pipe Replacement | 5480400 | GMK Overseas |
| 8461390 | Transmission Fluid Auxiliary Cooler Pipe Replacement | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8461430 | Transmission Control Module Replacement | K5365 | GMNA |
| 8461430 | Transmission Control Module Replacement | K6517 | GMNA |
| 8461430 | Transmission Control Module Replacement | K9522 | GMNA |
| 8461430 | Transmission Control Module Replacement | K9534 | GMNA |
| 8461430 | Transmission Control Module Replacement | 2716300 | GMK Domestic |
| 8461430 | Transmission Control Module Replacement | K509600 | Holden Australia |
| 8461430 | Transmission Control Module Replacement | K651700 | Holden Australia |
| 8461430 | Transmission Control Module Replacement | K509600 | Holden New Zealand |
| 8461430 | Transmission Control Module Replacement | K6517 | Holden New Zealand |
| 8461430 | Transmission Control Module Replacement | K651700 | Holden New Zealand |
| 8461430 | Transmission Control Module Replacement | 1860500 | GMK Overseas |
| 8461430 | Transmission Control Module Replacement | 1862500 | GMK Overseas |
| 8461450 | Auxiliary Fluid Pump Control Module Replacement | K5370 | GMNA |
| 8461470 | Transmission Fluid Cooler Upper Pipe Replacement - Rear | | |
| 8461490 | Transmission Fluid Cooler Upper Pipe Replacement - Rear to Differential Cooler | | |
| 8461510 | Transmission Fluid Cooler Lower Pipe Replacement - Intermediate | | |
| 8461530 | Transmission Fluid Cooler Lower Pipe Replacement - Intermediate to Differential Cooler | | |
| 8461550 | Transmission Fluid Cooler Thermal Bypass Valve Replacement | K5383 | GMNA |
| 8461590 | Transmission Fluid Auxiliary Cooler Outlet Pipe Replacement | | |
| 8461610 | Transmission Fluid Auxiliary Cooler Outlet Hose Replacement | K5386 | GMNA |
| 8461610 | Transmission Fluid Auxiliary Cooler Outlet Hose Replacement | K605100 | Holden Australia |
| 8461620 | Transmission Fluid Auxiliary Cooler Inlet Hose Replacement | | |
| 8461630 | Transmission Fluid Cooler Upper Pipe Assembly Replacement | | |
| 8461750 | Fluid Cooler Inlet Hose Replacement | K5394 | GMNA |
| 8461770 | Fluid Cooler Outlet Hose Replacement | E8934 | GMNA |
| 8461770 | Fluid Cooler Outlet Hose Replacement | K5395 | GMNA |
| 8461790 | Transmission Fluid Cooler Inlet and Outlet Pipe Replacement | 5480300 | GMK Overseas |
| 8461810 | Transmission Fluid Auxiliary Cooler Inlet Pipe Replacement | | |
| 8461830 | Transmission Fluid Cooler Upper Extension Pipe Replacement | | |
| 8461840 | Transmission Fluid Auxiliary Cooler Pipe Replacement - Front Transmission Cooler Line to Auxiliary Transmission Cooler Hose/Pipe | | |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8461860 | Transmission Fluid Cooler Pipe Replacement - Front Transmission Cooler Line to Radiator Transmission Cooler Hose/Pipe | | |
| 8461870 | Transmission Fluid Cooler Pipe Replacement - Front | K5400 | GMNA |
| 8461870 | Transmission Fluid Cooler Pipe Replacement - Front | 5251500 | GMK Overseas |
| 8461880 | Transmission Fluid Auxiliary Cooler Pipe Replacement - Transmission Cooler Hose/Pipe to Radiator Transmission Cooler | | |
| 8461900 | Transmission Fluid Auxiliary Cooler Inlet Pipe Replacement - Radiator Transmission Cooler Pipe to Auxiliary Cooler | | |
| 8461920 | Transmission Fluid Auxiliary Cooler Outlet Pipe Replacement - Auxiliary Transmission Cooler Hose/Pipe to Front Transmission Cooler Pipe | | |
| 8461940 | Transmission Fluid Cooler Pipe Replacement - Differential Oil Cooler Inlet Hose/Pipe to Rear Transmission Cooler Pipe | | |
| 8461960 | Transmission Fluid Cooler Pipe Replacement - Differential Oil Cooler Outlet Hose/Pipe to Rear Transmission Cooler Pipe | | |
| 8461970 | Transmission Fluid Cooler Pipe Seal Replacement | K6120 | GMNA |
| 8461970 | Transmission Fluid Cooler Pipe Seal Replacement | 5251700 | GMK Overseas |
| 8461980 | Transmission Fluid Cooler Pipe Replacement - Rear Transmission Cooler Outlet Pipe to Differential Oil Cooler Hose/Pipe | | |
| 8461990 | Transmission Fluid Level Indicator Replacement | K6130 | GMNA |
| 8461990 | Transmission Fluid Level Indicator Replacement | K6130 | Holden Australia |
| 8462000 | Transmission Fluid Cooler Pipe Replacement - Rear Transmission Cooler Inlet Pipe to Differential Oil Cooler Hose/Pipe | | |
| 8462010 | Transmission Fluid Filler Tube and Seal Replacement | K6140 | GMNA |
| 8462010 | Transmission Fluid Filler Tube and Seal Replacement | 2623800 | GMK Domestic |
| 8462010 | Transmission Fluid Filler Tube and Seal Replacement | K6140 | Holden Australia |
| 8462010 | Transmission Fluid Filler Tube and Seal Replacement | K6140 | Holden New Zealand |
| 8462010 | Transmission Fluid Filler Tube and Seal Replacement | K7500 | Holden New Zealand |
| 8462010 | Transmission Fluid Filler Tube and Seal Replacement | 5310500 | GMK Overseas |
| 8462030 | Transmission Fluid Filter Adapter Replacement | K6148 | GMNA |
| 8462050 | Transmission Fluid Filler Tube Plug Replacement | K6149 | GMNA |
| 8462070 | Automatic Transmission Fluid Pan Drain Plug Replacement | K6150 | GMNA |
| 8462090 | Propeller Shaft Transmission Flange Replacement | | |
| 8462130 | Power Take-Off Cover Gasket Replacement | K6280 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8462150 | Transmission Converter Cover Replacement | K6295 | GMNA |
| 8462150 | Transmission Converter Cover Replacement | K9554 | GMNA |
| 8462150 | Transmission Converter Cover Replacement | K604400 | Holden Australia |
| 8462150 | Transmission Converter Cover Replacement | K604400 | Holden New Zealand |
| 8462170 | Torque Converter Bolt Replacement | K6300 | GMNA |
| 8462170 | Torque Converter Bolt Replacement | 1152300 | GMK Domestic |
| 8462170 | Torque Converter Bolt Replacement | K604500 | Holden Australia |
| 8462170 | Torque Converter Bolt Replacement | K630000 | Holden Australia |
| 8462170 | Torque Converter Bolt Replacement | K604500 | Holden New Zealand |
| 8462170 | Torque Converter Bolt Replacement | 5110100 | GMK Overseas |
| 8462170 | Torque Converter Bolt Replacement | 5310200 | GMK Overseas |
| 8462190 | Fluid Temperature Sensor Replacement | K6305 | GMNA |
| 8462190 | Fluid Temperature Sensor Replacement | K6306 | GMNA |
| 8462210 | Vehicle Speed Sensor Replacement | J6373 | GMNA |
| 8462210 | Vehicle Speed Sensor Replacement | K6310 | GMNA |
| 8462210 | Vehicle Speed Sensor Replacement | 2802020 | GMK Domestic |
| 8462210 | Vehicle Speed Sensor Replacement | K607100 | Holden Australia |
| 8462210 | Vehicle Speed Sensor Replacement | K607250 | Holden Australia |
| 8462210 | Vehicle Speed Sensor Replacement | K6310 | Holden Australia |
| 8462210 | Vehicle Speed Sensor Replacement | K633000 | Holden Australia |
| 8462210 | Vehicle Speed Sensor Replacement | K633100 | Holden Australia |
| 8462210 | Vehicle Speed Sensor Replacement | K651600 | Holden Australia |
| 8462210 | Vehicle Speed Sensor Replacement | N316600 | Holden Australia |
| 8462210 | Vehicle Speed Sensor Replacement | N316650 | Holden Australia |
| 8462210 | Vehicle Speed Sensor Replacement | K607250 | Holden New Zealand |
| 8462210 | Vehicle Speed Sensor Replacement | K633000 | Holden New Zealand |
| 8462210 | Vehicle Speed Sensor Replacement | K6331 | Holden New Zealand |
| 8462210 | Vehicle Speed Sensor Replacement | K651600 | Holden New Zealand |
| 8462210 | Vehicle Speed Sensor Replacement | N316650 | Holden New Zealand |
| 8462210 | Vehicle Speed Sensor Replacement | 1861100 | GMK Overseas |
| 8462210 | Vehicle Speed Sensor Replacement | 5021300 | GMK Overseas |
| 8462210 | Vehicle Speed Sensor Replacement | 5120100 | GMK Overseas |
| 8462210 | Vehicle Speed Sensor Replacement | 5212900 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8462230 | Input Speed Sensor Replacement | K6311 | GMNA |
| 8462230 | Input Speed Sensor Replacement | K7524 | GMNA |
| 8462230 | Input Speed Sensor Replacement | N316850 | Holden Australia |
| 8462230 | Input Speed Sensor Replacement | N316850 | Holden New Zealand |
| 8462230 | Input Speed Sensor Replacement | 5411500 | GMK Overseas |
| 8462230 | Input Speed Sensor Replacement | 5411510 | GMK Overseas |
| 8462250 | Output Speed Sensor Replacement | K6312 | GMNA |
| 8462250 | Output Speed Sensor Replacement | N316800 | Holden Australia |
| 8462250 | Output Speed Sensor Replacement | N316800 | Holden New Zealand |
| 8462250 | Output Speed Sensor Replacement | 5241800 | GMK Overseas |
| 8462250 | Output Speed Sensor Replacement | 5411300 | GMK Overseas |
| 8462270 | Input Speed Sensor Seal Replacement | K6313 | GMNA |
| 8462330 | Manual Shift Detent Lever with Shaft Position Switch Assembly Replacement | K6349 | GMNA |
| 8462350 | Manual Shift Shaft Position Switch Replacement | N2453 | Holden New Zealand |
| 8462360 | Manual Shift Shaft and Seal Replacement | K6350 | GMNA |
| 8462370 | Transmission Fluid Pressure Switch Replacement | K6351 | GMNA |
| 8462370 | Transmission Fluid Pressure Switch Replacement | K6354 | GMNA |
| 8462410 | Pressure Control Solenoid Valve Replacement | J6337 | GMNA |
| 8462410 | Pressure Control Solenoid Valve Replacement | K6353 | GMNA |
| 8462410 | Pressure Control Solenoid Valve Replacement | K635300 | Holden Australia |
| 8462410 | Pressure Control Solenoid Valve Replacement | 5241400 | GMK Overseas |
| 8462410 | Pressure Control Solenoid Valve Replacement | 5241500 | GMK Overseas |
| 8462430 | Pressure Switch Manifold Replacement | K6356 | GMNA |
| 8462450 | Propeller Shaft Front Slip Yoke Oil Seal Replacement | K6360 | GMNA |
| 8462450 | Propeller Shaft Front Slip Yoke Oil Seal Replacement | K6360 | Holden Australia |
| 8462450 | Propeller Shaft Front Slip Yoke Oil Seal Replacement | K636000 | Holden Australia |
| 8462450 | Propeller Shaft Front Slip Yoke Oil Seal Replacement | K6360 | Holden New Zealand |
| 8462450 | Propeller Shaft Front Slip Yoke Oil Seal Replacement | K636000 | Holden New Zealand |
| 8462470 | Output Shaft Bearing Replacement - Case | K6361 | GMNA |
| 8462470 | Output Shaft Bearing Replacement - Case | K7105 | GMNA |
| 8462470 | Output Shaft Bearing Replacement - Case | K7173 | GMNA |
| 8462490 | Output Shaft Bearing Replacement - Case Extension | K6362 | GMNA |
| 8462490 | Output Shaft Bearing Replacement - Case Extension | 2410100 | GMK Domestic |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8462490 | Output Shaft Bearing Replacement - Case Extension | 5650300 | GMK Overseas |
| 8462510 | Input and Output Speed Sensor Replacement | K6364 | GMNA |
| 8462550 | Differential Drive Pinion Gear Yoke Replacement | K6366 | GMNA |
| 8462570 | Automatic Transmission Fluid Pressure Test Hole Plug Replacement | K6367 | GMNA |
| 8462610 | Transmission Rear Cover Replacement | K7130 | GMNA |
| 8462630 | Rear Case and Gasket Replacement | K6388 | GMNA |
| 8462650 | Case Extension and Gasket Replacement | K4220 | GMNA |
| 8462650 | Case Extension and Gasket Replacement | K6380 | GMNA |
| 8462650 | Case Extension and Gasket Replacement | K6390 | GMNA |
| 8462650 | Case Extension and Gasket Replacement | K9526 | GMNA |
| 8462650 | Case Extension and Gasket Replacement | 2413100 | GMK Domestic |
| 8462650 | Case Extension and Gasket Replacement | 2616000 | GMK Domestic |
| 8462650 | Case Extension and Gasket Replacement | 2717100 | GMK Domestic |
| 8462650 | Case Extension and Gasket Replacement | K202100 | Holden Australia |
| 8462650 | Case Extension and Gasket Replacement | K608150 | Holden Australia |
| 8462650 | Case Extension and Gasket Replacement | K608200 | Holden Australia |
| 8462650 | Case Extension and Gasket Replacement | K202100 | Holden New Zealand |
| 8462650 | Case Extension and Gasket Replacement | K608150 | Holden New Zealand |
| 8462650 | Case Extension and Gasket Replacement | K608200 | Holden New Zealand |
| 8462660 | Front Differential Carrier Sun Gear Replacement | | |
| 8462910 | Park Pawl Actuator Guide and Seal Replacement | K6496 | GMNA |
| 8462930 | Transmission Fluid Pan Replacement | K6500 | GMNA |
| 8462930 | Transmission Fluid Pan Replacement | 2630200 | GMK Domestic |
| 8462930 | Transmission Fluid Pan Replacement | 3121700 | GMK Domestic |
| 8462930 | Transmission Fluid Pan Replacement | 3121800 | GMK Domestic |
| 8462930 | Transmission Fluid Pan Replacement | K611100 | Holden Australia |
| 8462930 | Transmission Fluid Pan Replacement | K649000 | Holden Australia |
| 8462930 | Transmission Fluid Pan Replacement | K6500 | Holden Australia |
| 8462930 | Transmission Fluid Pan Replacement | K650000 | Holden Australia |
| 8462930 | Transmission Fluid Pan Replacement | K650100 | Holden Australia |
| 8462930 | Transmission Fluid Pan Replacement | K611100 | Holden New Zealand |
| 8462930 | Transmission Fluid Pan Replacement | K6500 | Holden New Zealand |
| 8462930 | Transmission Fluid Pan Replacement | K650000 | Holden New Zealand |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8462930 | Transmission Fluid Pan Replacement | 5010900 | GMK Overseas |
| 8462930 | Transmission Fluid Pan Replacement | 5241700 | GMK Overseas |
| 8462950 | Manual Shift Shaft Replacement | K6501 | GMNA |
| 8462950 | Manual Shift Shaft Replacement | 2420500 | GMK Domestic |
| 8462970 | Manual Shift Detent Lever and Park Pawl Actuator Replacement | K6502 | GMNA |
| 8462970 | Manual Shift Detent Lever and Park Pawl Actuator Replacement | 2211300 | GMK Domestic |
| 8462970 | Manual Shift Detent Lever and Park Pawl Actuator Replacement | 2410200 | GMK Domestic |
| 8462970 | Manual Shift Detent Lever and Park Pawl Actuator Replacement | K5125 | Holden Australia |
| 8462970 | Manual Shift Detent Lever and Park Pawl Actuator Replacement | K6502 | Holden Australia |
| 8463170 | Fluid Level Control Valve Replacement | K6514 | GMNA |
| 8463290 | Manual Shift Shaft Seal Replacement | K5223 | GMNA |
| 8463290 | Manual Shift Shaft Seal Replacement | K6529 | GMNA |
| 8463290 | Manual Shift Shaft Seal Replacement | K200100 | Holden New Zealand |
| 8463390 | Automatic Transmission Electrical Connector Passage Sleeve Replacement | K6539 | GMNA |
| 8463410 | Control Valve Body Cover Replacement | K6519 | GMNA |
| 8463410 | Control Valve Body Cover Replacement | K6540 | GMNA |
| 8463410 | Control Valve Body Cover Replacement | K6545 | GMNA |
| 8463410 | Control Valve Body Cover Replacement | K7228 | GMNA |
| 8463410 | Control Valve Body Cover Replacement | K7615 | GMNA |
| 8463410 | Control Valve Body Cover Replacement | 5121300 | GMK Overseas |
| 8463410 | Control Valve Body Cover Replacement | 5410600 | GMK Overseas |
| 8463470 | Transmission Fluid Pump Replacement | K6543 | GMNA |
| 8463490 | Auxiliary Fluid Pump Replacement | K6544 | GMNA |
| 8463490 | Auxiliary Fluid Pump Replacement | N9655 | GMNA |
| 8463510 | Torque Converter Clutch Valve and Spring Replacement | K6548 | GMNA |
| 8463530 | Pressure Regulator Valve Replacement | K6547 | GMNA |
| 8463530 | Pressure Regulator Valve Replacement | K6550 | GMNA |
| 8463570 | Automatic Transmission Wiring Harness Replacement | K6520 | GMNA |
| 8463570 | Automatic Transmission Wiring Harness Replacement | K6554 | GMNA |
| 8463570 | Automatic Transmission Wiring Harness Replacement | K600200 | Holden Australia |
| 8463570 | Automatic Transmission Wiring Harness Replacement | K6554 | Holden Australia |
| 8463570 | Automatic Transmission Wiring Harness Replacement | K600200 | Holden New Zealand |
| 8463590 | 1-2 Shift Solenoid Valve Replacement | K6526 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8463590 | 1-2 Shift Solenoid Valve Replacement | K6555 | GMNA |
| 8463590 | 1-2 Shift Solenoid Valve Replacement | K6566 | GMNA |
| 8463610 | 2-3 Shift Solenoid Valve Replacement | K6527 | GMNA |
| 8463610 | 2-3 Shift Solenoid Valve Replacement | K6556 | GMNA |
| 8463630 | Torque Converter Clutch Pulse Width Modulation Solenoid Valve Replacement | K6557 | GMNA |
| 8463630 | Torque Converter Clutch Pulse Width Modulation Solenoid Valve Replacement | 5021600 | GMK Overseas |
| 8463690 | Control Valve Body Replacement | K2850 | GMNA |
| 8463690 | Control Valve Body Replacement | K6560 | GMNA |
| 8463690 | Control Valve Body Replacement | K6563 | GMNA |
| 8463690 | Control Valve Body Replacement | K6568 | GMNA |
| 8463690 | Control Valve Body Replacement | K6570 | GMNA |
| 8463690 | Control Valve Body Replacement | K6575 | GMNA |
| 8463690 | Control Valve Body Replacement | K6860 | GMNA |
| 8463690 | Control Valve Body Replacement | K508200 | Holden Australia |
| 8463690 | Control Valve Body Replacement | K600320 | Holden Australia |
| 8463690 | Control Valve Body Replacement | K6560 | Holden Australia |
| 8463690 | Control Valve Body Replacement | K600320 | Holden New Zealand |
| 8463690 | Control Valve Body Replacement | K655900 | Holden New Zealand |
| 8463690 | Control Valve Body Replacement | 5021500 | GMK Overseas |
| 8463690 | Control Valve Body Replacement | 5131100 | GMK Overseas |
| 8463690 | Control Valve Body Replacement | 5241300 | GMK Overseas |
| 8463730 | Control Solenoid Valve and Transmission Control Module Assembly Replacement | K6562 | GMNA |
| 8463730 | Control Solenoid Valve and Transmission Control Module Assembly Replacement | 5410700 | GMK Overseas |
| 8463730 | Control Solenoid Valve and Transmission Control Module Assembly Replacement | 5410710 | GMK Overseas |
| 8463770 | Torque Converter Clutch Solenoid Valve Replacement | K6567 | GMNA |
| 8463810 | 1-2,3-4 Shift Solenoid Valve Replacement | K6569 | GMNA |
| 8463830 | Radiator Upper Grille Replacement | K6571 | GMNA |
| 8463850 | Auxiliary Fluid Pump Outlet Pipe Replacement | K6572 | GMNA |
| 8463870 | Control Valve Lower Body and Upper Body Replacement | K6564 | GMNA |
| 8463870 | Control Valve Lower Body and Upper Body Replacement | K6610 | GMNA |
| 8463870 | Control Valve Lower Body and Upper Body Replacement | K7123 | GMNA |
| 8463870 | Control Valve Lower Body and Upper Body Replacement | 2632000 | GMK Domestic |
| 8463870 | Control Valve Lower Body and Upper Body Replacement | K615100 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8463870 | Control Valve Lower Body and Upper Body Replacement | K615120 | Holden Australia |
| 8463870 | Control Valve Lower Body and Upper Body Replacement | K615150 | Holden Australia |
| 8463870 | Control Valve Lower Body and Upper Body Replacement | K656000 | Holden Australia |
| 8463870 | Control Valve Lower Body and Upper Body Replacement | K656100 | Holden Australia |
| 8463870 | Control Valve Lower Body and Upper Body Replacement | K615100 | Holden New Zealand |
| 8463870 | Control Valve Lower Body and Upper Body Replacement | K615120 | Holden New Zealand |
| 8463870 | Control Valve Lower Body and Upper Body Replacement | K615150 | Holden New Zealand |
| 8463870 | Control Valve Lower Body and Upper Body Replacement | K656000 | Holden New Zealand |
| 8463870 | Control Valve Lower Body and Upper Body Replacement | 4650300 | GMK Overseas |
| 8463870 | Control Valve Lower Body and Upper Body Replacement | 5440400 | GMK Overseas |
| 8463950 | Reverse Band Servo Piston Replacement | K6590 | GMNA |
| 8463950 | Reverse Band Servo Piston Replacement | K6623 | GMNA |
| 8463970 | Forward Band Servo Piston Replacement | K6624 | GMNA |
| 8464010 | 2-4 Band Servo Piston Replacement | K6630 | GMNA |
| 8464030 | Park Pawl Cover and Gasket Replacement | K6639 | GMNA |
| 8464050 | Park Pawl and Actuator Replacement | K6640 | GMNA |
| 8464050 | Park Pawl and Actuator Replacement | 2614000 | GMK Domestic |
| 8464050 | Park Pawl and Actuator Replacement | 3020600 | GMK Domestic |
| 8464050 | Park Pawl and Actuator Replacement | K616100 | Holden Australia |
| 8464050 | Park Pawl and Actuator Replacement | K616100 | Holden New Zealand |
| 8464210 | Transmission Mount Replacement - Left Side | K6721 | GMNA |
| 8464210 | Transmission Mount Replacement - Left Side | 2420100 | GMK Domestic |
| 8464210 | Transmission Mount Replacement - Left Side | 1380900 | GMK Overseas |
| 8464210 | Transmission Mount Replacement - Left Side | 1383100 | GMK Overseas |
| 8464230 | Transmission Front Mount Replacement | K6722 | GMNA |
| 8464250 | Transmission Rear Mount Replacement | K6723 | GMNA |
| 8464270 | Transmission Mount Replacement | K6724 | GMNA |
| 8464270 | Transmission Mount Replacement | 2420300 | GMK Domestic |
| 8464270 | Transmission Mount Replacement | J000830 | Holden New Zealand |
| 8464270 | Transmission Mount Replacement | J338000 | Holden New Zealand |
| 8464330 | Transmission Mount Strut Replacement | K2300 | GMNA |
| 8464330 | Transmission Mount Strut Replacement | K6730 | GMNA |
| 8464330 | Transmission Mount Strut Replacement | K6740 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8464330 | Transmission Mount Strut Replacement | 2216000 | GMK Domestic |
| 8464430 | Front Wheel Drive Shaft Seal Replacement - Right Side | K6900 | GMNA |
| 8464430 | Front Wheel Drive Shaft Seal Replacement - Right Side | 2633400 | GMK Domestic |
| 8464430 | Front Wheel Drive Shaft Seal Replacement - Right Side | 2710600 | GMK Domestic |
| 8464430 | Front Wheel Drive Shaft Seal Replacement - Right Side | 2719400 | GMK Domestic |
| 8464430 | Front Wheel Drive Shaft Seal Replacement - Right Side | 5240500 | GMK Overseas |
| 8464430 | Front Wheel Drive Shaft Seal Replacement - Right Side | 5420800 | GMK Overseas |
| 8464430 | Front Wheel Drive Shaft Seal Replacement - Right Side | 5420900 | GMK Overseas |
| 8464430 | Front Wheel Drive Shaft Seal Replacement - Right Side | 5671300 | GMK Overseas |
| 8464430 | Front Wheel Drive Shaft Seal Replacement - Right Side | 5671310 | GMK Overseas |
| 8464450 | Front Wheel Drive Shaft Seal Replacement - Left Side | K6901 | GMNA |
| 8464450 | Front Wheel Drive Shaft Seal Replacement - Left Side | 3112800 | GMK Domestic |
| 8464450 | Front Wheel Drive Shaft Seal Replacement - Left Side | E302210 | Holden New Zealand |
| 8464450 | Front Wheel Drive Shaft Seal Replacement - Left Side | 5121900 | GMK Overseas |
| 8464450 | Front Wheel Drive Shaft Seal Replacement - Left Side | 5122100 | GMK Overseas |
| 8464450 | Front Wheel Drive Shaft Seal Replacement - Left Side | 5240600 | GMK Overseas |
| 8464450 | Front Wheel Drive Shaft Seal Replacement - Left Side | 5671400 | GMK Overseas |
| 8464570 | Output Shaft Seal Replacement | K6941 | GMNA |
| 8464630 | Drive Motor Power Inverter Module Cable Replacement - First Position | K6960 | GMNA |
| 8464650 | Drive Motor Power Inverter Module Cable Replacement - Second Position | K6961 | GMNA |
| 8464670 | Transmission Replacement | I9220 | GMNA |
| 8464670 | Transmission Replacement | K6990 | GMNA |
| 8464670 | Transmission Replacement | K7000 | GMNA |
| 8464670 | Transmission Replacement | K7900 | GMNA |
| 8464670 | Transmission Replacement | K8020 | GMNA |
| 8464670 | Transmission Replacement | 2615500 | GMK Domestic |
| 8464670 | Transmission Replacement | 2616300 | GMK Domestic |
| 8464670 | Transmission Replacement | 3112100 | GMK Domestic |
| 8464670 | Transmission Replacement | 3131120 | GMK Domestic |
| 8464670 | Transmission Replacement | K000225 | Holden Australia |
| 8464670 | Transmission Replacement | K000297 | Holden Australia |
| 8464670 | Transmission Replacement | K000300 | Holden Australia |
| 8464670 | Transmission Replacement | K000500 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8464670 | Transmission Replacement | K7000 | Holden Australia |
| 8464670 | Transmission Replacement | K700000 | Holden Australia |
| 8464670 | Transmission Replacement | K700100 | Holden Australia |
| 8464670 | Transmission Replacement | K700500 | Holden Australia |
| 8464670 | Transmission Replacement | K790000 | Holden Australia |
| 8464670 | Transmission Replacement | K000225 | Holden New Zealand |
| 8464670 | Transmission Replacement | K2721 | Holden New Zealand |
| 8464670 | Transmission Replacement | K7000 | Holden New Zealand |
| 8464670 | Transmission Replacement | K700000 | Holden New Zealand |
| 8464670 | Transmission Replacement | K700100 | Holden New Zealand |
| 8464670 | Transmission Replacement | K7002 | Holden New Zealand |
| 8464670 | Transmission Replacement | K700500 | Holden New Zealand |
| 8464670 | Transmission Replacement | K7900 | Holden New Zealand |
| 8464670 | Transmission Replacement | K790000 | Holden New Zealand |
| 8464670 | Transmission Replacement | 5010100 | GMK Overseas |
| 8464670 | Transmission Replacement | 5010200 | GMK Overseas |
| 8464670 | Transmission Replacement | 5110300 | GMK Overseas |
| 8464670 | Transmission Replacement | 5210300 | GMK Overseas |
| 8464670 | Transmission Replacement | 5240300 | GMK Overseas |
| 8464670 | Transmission Replacement | 5310300 | GMK Overseas |
| 8464670 | Transmission Replacement | 5410100 | GMK Overseas |
| 8464670 | Transmission Replacement | 541010B | GMK Overseas |
| 8464670 | Transmission Replacement | 5410110 | GMK Overseas |
| 8464670 | Transmission Replacement | 5710200 | GMK Overseas |
| 8464710 | Drive Motor Power Inverter Module Cable Terminal Insulator Block Replacement | | |
| 8464730 | Torque Dampener Replacement | K7011 | GMNA |
| 8464752 | Torque Dampener Housing Overhaul | K7013 | GMNA |
| 8464790 | Torque Dampener and Differential Housing Replacement | | |
| 8464810 | Torque Converter Replacement | K7020 | GMNA |
| 8464810 | Torque Converter Replacement | K7021 | GMNA |
| 8464810 | Torque Converter Replacement | K7022 | GMNA |
| 8464810 | Torque Converter Replacement | K8000 | GMNA |
| 8464810 | Torque Converter Replacement | K9508 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8464810 | Torque Converter Replacement | 2614900 | GMK Domestic |
| 8464810 | Torque Converter Replacement | 3121600 | GMK Domestic |
| 8464810 | Torque Converter Replacement | K701100 | Holden Australia |
| 8464810 | Torque Converter Replacement | K7020 | Holden Australia |
| 8464810 | Torque Converter Replacement | K702000 | Holden Australia |
| 8464810 | Torque Converter Replacement | K701100 | Holden New Zealand |
| 8464810 | Torque Converter Replacement | 5010300 | GMK Overseas |
| 8464810 | Torque Converter Replacement | 5010400 | GMK Overseas |
| 8464810 | Torque Converter Replacement | 5250100 | GMK Overseas |
| 8464810 | Torque Converter Replacement | 5310100 | GMK Overseas |
| 8464810 | Torque Converter Replacement | 5410400 | GMK Overseas |
| 8464850 | Manual Shift Shaft and Manual Shift Detent Lever Replacement | K7024 | GMNA |
| 8464850 | Manual Shift Shaft and Manual Shift Detent Lever Replacement | 5470300 | GMK Overseas |
| 8464890 | Torque Converter Housing Bolt Seal Replacement | K7039 | GMNA |
| 8464910 | Torque Converter Housing Replacement | K7040 | GMNA |
| 8464910 | Torque Converter Housing Replacement | 2618000 | GMK Domestic |
| 8464910 | Torque Converter Housing Replacement | 3112700 | GMK Domestic |
| 8464910 | Torque Converter Housing Replacement | K704000 | Holden Australia |
| 8464910 | Torque Converter Housing Replacement | 5020900 | GMK Overseas |
| 8464910 | Torque Converter Housing Replacement | 5210600 | GMK Overseas |
| 8464910 | Torque Converter Housing Replacement | 5211300 | GMK Overseas |
| 8464910 | Torque Converter Housing Replacement | 5250300 | GMK Overseas |
| 8464910 | Torque Converter Housing Replacement | 5421100 | GMK Overseas |
| 8464910 | Torque Converter Housing Replacement | 5421400 | GMK Overseas |
| 8464910 | Torque Converter Housing Replacement | 5421410 | GMK Overseas |
| 8464912 | Torque Converter Housing Overhaul | K7556 | GMNA |
| 8464912 | Torque Converter Housing Overhaul | 2411310 | GMK Domestic |
| 8464912 | Torque Converter Housing Overhaul | 5422400 | GMK Overseas |
| 8464970 | Torque Converter Fluid Seal Replacement | K7023 | GMNA |
| 8464970 | Torque Converter Fluid Seal Replacement | K7060 | GMNA |
| 8464970 | Torque Converter Fluid Seal Replacement | 2412100 | GMK Domestic |
| 8464970 | Torque Converter Fluid Seal Replacement | 3030400 | GMK Domestic |
| 8464970 | Torque Converter Fluid Seal Replacement | K702100 | Holden Australia |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8464970 | Torque Converter Fluid Seal Replacement | K702100 | Holden New Zealand |
| 8464970 | Torque Converter Fluid Seal Replacement | 5021200 | GMK Overseas |
| 8464970 | Torque Converter Fluid Seal Replacement | 5422200 | GMK Overseas |
| 8464990 | Transmission Fluid Pump Seal Replacement | K7100 | GMNA |
| 8464990 | Transmission Fluid Pump Seal Replacement | 2710200 | GMK Domestic |
| 8464990 | Transmission Fluid Pump Seal Replacement | K7100 | Holden Australia |
| 8464990 | Transmission Fluid Pump Seal Replacement | 5211100 | GMK Overseas |
| 8464990 | Transmission Fluid Pump Seal Replacement | 5412100 | GMK Overseas |
| 8465010 | Stator Shaft Replacement | K7115 | GMNA |
| 8465050 | Oil Pump Replacement | K7120 | GMNA |
| 8465050 | Oil Pump Replacement | K7121 | GMNA |
| 8465050 | Oil Pump Replacement | K7245 | GMNA |
| 8465050 | Oil Pump Replacement | K703100 | Holden Australia |
| 8465050 | Oil Pump Replacement | K703100 | Holden New Zealand |
| 8465050 | Oil Pump Replacement | K7120 | Holden New Zealand |
| 8465050 | Oil Pump Replacement | 5020400 | GMK Overseas |
| 8465050 | Oil Pump Replacement | 5130900 | GMK Overseas |
| 8465050 | Oil Pump Replacement | 5250700 | GMK Overseas |
| 8465050 | Oil Pump Replacement | 5422100 | GMK Overseas |
| 8465070 | Transmission Fluid Pump Gasket Replacement | K7122 | GMNA |
| 8465070 | Transmission Fluid Pump Gasket Replacement | 2630100 | GMK Domestic |
| 8465070 | Transmission Fluid Pump Gasket Replacement | 2710400 | GMK Domestic |
| 8465070 | Transmission Fluid Pump Gasket Replacement | K7122 | Holden Australia |
| 8465070 | Transmission Fluid Pump Gasket Replacement | 5241600 | GMK Overseas |
| 8465130 | Control Valve Body Spacer Plate Replacement | K6611 | GMNA |
| 8465130 | Control Valve Body Spacer Plate Replacement | K7128 | GMNA |
| 8465130 | Control Valve Body Spacer Plate Replacement | 2911700 | GMK Domestic |
| 8465332 | 4th Clutch Assembly Overhaul | K7151 | GMNA |
| 8465332 | 4th Clutch Assembly Overhaul | K7528 | GMNA |
| 8465332 | 4th Clutch Assembly Overhaul | K7611 | GMNA |
| 8465352 | Overdrive Carrier Assembly Overhaul | K7152 | GMNA |
| 8465372 | Direct Clutch Overhaul | K7200 | GMNA |
| 8465372 | Direct Clutch Overhaul | K7201 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8465432 | Forward Clutch Overhaul | K7202 | GMNA |
| 8465432 | Forward Clutch Overhaul | K7210 | GMNA |
| 8465432 | Forward Clutch Overhaul | K7220 | GMNA |
| 8465432 | Forward Clutch Overhaul | K7221 | GMNA |
| 8465432 | Forward Clutch Overhaul | K7579 | GMNA |
| 8465432 | Forward Clutch Overhaul | K703181 | Holden Australia |
| 8465452 | Turbine Shaft Overhaul | K7222 | GMNA |
| 8465452 | Turbine Shaft Overhaul | 3111200 | GMK Domestic |
| 8465490 | Turbine Shaft Seal Replacement | K7224 | GMNA |
| 8465490 | Turbine Shaft Seal Replacement | 5135500 | GMK Overseas |
| 8465510 | Oil Pump Drive Shaft Replacement | K7226 | GMNA |
| 8465510 | Oil Pump Drive Shaft Replacement | 1423600 | GMK Domestic |
| 8465510 | Oil Pump Drive Shaft Replacement | 2624600 | GMK Domestic |
| 8465550 | Reverse Input Clutch Housing Replacement | K7231 | GMNA |
| 8465570 | Reverse Input Clutch Replacement | K7232 | GMNA |
| 8465572 | Reverse Input Clutch Overhaul | K7571 | GMNA |
| 8465590 | Direct and Reverse Clutch Replacement | K7234 | GMNA |
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | K5280 | GMNA |
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | K6330 | GMNA |
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | K7109 | GMNA |
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | K7243 | GMNA |
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | 2421400 | GMK Domestic |
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | 2622100 | GMK Domestic |
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | K611200 | Holden Australia |
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | K703170 | Holden Australia |
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | K710000 | Holden Australia |
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | K712000 | Holden Australia |
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | K5280 | Holden New Zealand |
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | K611200 | Holden New Zealand |
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | K703170 | Holden New Zealand |
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | K712000 | Holden New Zealand |
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | 5021700 | GMK Overseas |
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | 5122900 | GMK Overseas |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | 5250600 | GMK Overseas |
| 8465610 | Automatic Transmission Fluid Filter and Seal Replacement | 5421500 | GMK Overseas |
| 8465650 | Control Valve Upper Body Replacement | K7248 | GMNA |
| 8465672 | Input Clutch Housing Assembly Overhaul | K7251 | GMNA |
| 8465690 | 3-4 Clutch Plate Replacement | K7252 | GMNA |
| 8465690 | 3-4 Clutch Plate Replacement | K7532 | GMNA |
| 8465710 | Forward Clutch Sprag Replacement | K7253 | GMNA |
| 8465732 | 2-6 Clutch Plate Overhaul | K7254 | GMNA |
| 8465732 | 2-6 Clutch Plate Overhaul | 5450210 | GMK Overseas |
| 8465750 | Overrun Clutch Replacement | K7255 | GMNA |
| 8465750 | Overrun Clutch Replacement | K7609 | GMNA |
| 8465770 | 2-6 Clutch Piston Replacement | K7257 | GMNA |
| 8465770 | 2-6 Clutch Piston Replacement | 5450100 | GMK Overseas |
| 8465810 | 2-4 Band Replacement | K7270 | GMNA |
| 8465810 | 2-4 Band Replacement | K7271 | GMNA |
| 8465830 | Input Carrier Replacement | K7272 | GMNA |
| 8465830 | Input Carrier Replacement | K7590 | GMNA |
| 8465870 | Reaction Internal Gear Replacement | K7285 | GMNA |
| 8465870 | Reaction Internal Gear Replacement | K7594 | GMNA |
| 8465950 | Low Clutch Roller Replacement | K7321 | GMNA |
| 8465970 | Low and Reverse Clutch Support Replacement | K7322 | GMNA |
| 8465990 | Low and Reverse Clutch Plate Replacement | K7323 | GMNA |
| 8465990 | Low and Reverse Clutch Plate Replacement | 3110100 | GMK Domestic |
| 8466012 | Reaction Carrier Overhaul | K7324 | GMNA |
| 8466012 | Reaction Carrier Overhaul | K7565 | GMNA |
| 8466030 | Output Shaft Replacement | K6940 | GMNA |
| 8466030 | Output Shaft Replacement | K7325 | GMNA |
| 8466030 | Output Shaft Replacement | K9547 | GMNA |
| 8466050 | Low and Reverse Clutch Piston Replacement | K7340 | GMNA |
| 8466110 | Input Sun Gear Shaft Replacement | K7364 | GMNA |
| 8466150 | Center Support Replacement | K7381 | GMNA |
| 8466230 | Front Differential Drive Pinion Gear and Carrier Replacement | K7392 | GMNA |
| 8466290 | 4-5-6 Clutch Dampener Replacement | K7395 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8466370 | 1-3-Reverse Clutch Replacement | | |
| 8466390 | 2nd Clutch Replacement | K7400 | GMNA |
| 8466390 | 2nd Clutch Replacement | K7402 | GMNA |
| 8466410 | 1-2-3-4 Clutch Plate Replacement | K7403 | GMNA |
| 8466410 | 1-2-3-4 Clutch Plate Replacement | K7409 | GMNA |
| 8466430 | 4-5-6 Clutch Plate Replacement | K7405 | GMNA |
| 8466430 | 4-5-6 Clutch Plate Replacement | 2633700 | GMK Domestic |
| 8466430 | 4-5-6 Clutch Plate Replacement | 5456600 | GMK Overseas |
| 8466450 | 3-5-Reverse Clutch Plate Replacement | K7406 | GMNA |
| 8466450 | 3-5-Reverse Clutch Plate Replacement | K7407 | GMNA |
| 8466450 | 3-5-Reverse Clutch Plate Replacement | 5456110 | GMK Overseas |
| 8466490 | Input Sun Gear Replacement | K7410 | GMNA |
| 8466490 | Input Sun Gear Replacement | K7412 | GMNA |
| 8466490 | Input Sun Gear Replacement | K7414 | GMNA |
| 8466490 | Input Sun Gear Replacement | K7420 | GMNA |
| 8466490 | Input Sun Gear Replacement | K7562 | GMNA |
| 8466490 | Input Sun Gear Replacement | K7563 | GMNA |
| 8466510 | 1-3-Reverse Clutch Housing Seal Replacement | | |
| 8466530 | Automatic Transmission Case Cover Seal Replacement | K7450 | GMNA |
| 8466550 | Variable Low and 1-2 Reverse Clutch Housing Replacement | K7455 | GMNA |
| 8466570 | Case Cover Replacement | K7461 | GMNA |
| 8466570 | Case Cover Replacement | K9555 | GMNA |
| 8466570 | Case Cover Replacement | K205170 | Holden Australia |
| 8466570 | Case Cover Replacement | 5021100 | GMK Overseas |
| 8466570 | Case Cover Replacement | 5710400 | GMK Overseas |
| 8466570 | Case Cover Replacement | 5710500 | GMK Overseas |
| 8466590 | Automatic Transmission Case Cover Gasket Replacement | K7462 | GMNA |
| 8466590 | Automatic Transmission Case Cover Gasket Replacement | K203200 | Holden New Zealand |
| 8466610 | 1-2 Accumulator Replacement | K6506 | GMNA |
| 8466610 | 1-2 Accumulator Replacement | K6507 | GMNA |
| 8466610 | 1-2 Accumulator Replacement | K6536 | GMNA |
| 8466610 | 1-2 Accumulator Replacement | K6660 | GMNA |
| 8466610 | 1-2 Accumulator Replacement | K6675 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8466610 | 1-2 Accumulator Replacement | K6690 | GMNA |
| 8466610 | 1-2 Accumulator Replacement | K6691 | GMNA |
| 8466610 | 1-2 Accumulator Replacement | K6692 | GMNA |
| 8466610 | 1-2 Accumulator Replacement | K7465 | GMNA |
| 8466610 | 1-2 Accumulator Replacement | K7466 | GMNA |
| 8466610 | 1-2 Accumulator Replacement | K9551 | GMNA |
| 8466610 | 1-2 Accumulator Replacement | K000276 | Holden Australia |
| 8466610 | 1-2 Accumulator Replacement | K602200 | Holden Australia |
| 8466610 | 1-2 Accumulator Replacement | K000276 | Holden New Zealand |
| 8466650 | 3-4 Accumulator Replacement | K6561 | GMNA |
| 8466650 | 3-4 Accumulator Replacement | K7467 | GMNA |
| 8466710 | Variable High and 2-3-4 Clutch Accumulator Piston Replacement | K7501 | GMNA |
| 8466730 | Variable High and 2-3-4 Clutch Seal Replacement | K7502 | GMNA |
| 8466770 | Variable High and 2-3-4 Clutch Replacement | | |
| 8466800 | Drive Motor Rotor Bearing Replacement | | |
| 8466810 | Auxiliary Fluid Pump Motor Replacement | K7507 | GMNA |
| 8466850 | Drive Motor Generator Rotor and Stator Replacement | K6951 | GMNA |
| 8466850 | Drive Motor Generator Rotor and Stator Replacement | K7514 | GMNA |
| 8466870 | Hybrid Direct, 2-3-4 Clutch Housing Replacement | K7515 | GMNA |
| 8466890 | Hybrid Low, 1-2 Clutch Piston Replacement | F9742 | GMNA |
| 8466890 | Hybrid Low, 1-2 Clutch Piston Replacement | K7516 | GMNA |
| 8466912 | 1-3 Clutch Housing Overhaul | K7523 | GMNA |
| 8466930 | Drive Motor with Generator Assembly Replacement | K7518 | GMNA |
| 8466972 | Drive Sprocket, Driven Sprocket, and Drive Link Overhaul | K7520 | GMNA |
| 8466972 | Drive Sprocket, Driven Sprocket, and Drive Link Overhaul | 2912600 | GMK Domestic |
| 8466972 | Drive Sprocket, Driven Sprocket, and Drive Link Overhaul | K703180 | Holden Australia |
| 8467090 | Driven Sprocket Support Replacement | K7529 | GMNA |
| 8467110 | Low and Reverse Clutch Housing Replacement | K7530 | GMNA |
| 8467130 | 2nd Clutch Plate Replacement | K7531 | GMNA |
| 8467190 | Reverse Band Replacement | K7534 | GMNA |
| 8467210 | Input and 3rd Clutch Replacement | K7536 | GMNA |
| 8467230 | Input Clutch Sprag Replacement | K7537 | GMNA |
| 8467250 | Reverse Reaction Drum Replacement | K7538 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8467292 | 3-5-Reverse and 4-5-6 Clutch Housing Overhaul | K7540 | GMNA |
| 8467330 | 2nd Clutch Sprag Replacement | K7543 | GMNA |
| 8467352 | Low and Reverse and 1-2-3-4 Clutch Housing Overhaul | K7544 | GMNA |
| 8467390 | Manual 2-1 Band Replacement | K7547 | GMNA |
| 8467412 | Input, Reaction, and Output Carrier Overhaul | K7548 | GMNA |
| 8467412 | Input, Reaction, and Output Carrier Overhaul | 5460600 | GMK Overseas |
| 8467470 | Input and Reaction Carrier Replacement | K7551 | GMNA |
| 8467490 | Reaction Sun Gear Replacement | K7552 | GMNA |
| 8467570 | Forward Band Replacement | K7557 | GMNA |
| 8467770 | 4th Band Replacement | K7546 | GMNA |
| 8467770 | 4th Band Replacement | K7573 | GMNA |
| 8467812 | Intermediate Clutch Overhaul | K7576 | GMNA |
| 8467850 | Direct Clutch Hub Replacement | K7578 | GMNA |
| 8467850 | Direct Clutch Hub Replacement | K7582 | GMNA |
| 8467890 | Low and Reverse Clutch Replacement | K7580 | GMNA |
| 8467890 | Low and Reverse Clutch Replacement | K7595 | GMNA |
| 8467890 | Low and Reverse Clutch Replacement | 3110000 | GMK Domestic |
| 8467890 | Low and Reverse Clutch Replacement | K703182 | Holden Australia |
| 8467910 | Direct and Coast Clutch Housing Replacement | K7572 | GMNA |
| 8467910 | Direct and Coast Clutch Housing Replacement | K7581 | GMNA |
| 8467950 | Forward Clutch Hub Replacement | K7583 | GMNA |
| 8467970 | Forward Clutch Roller Replacement | K7584 | GMNA |
| 8468010 | Overdrive Clutch Housing Replacement | K7586 | GMNA |
| 8468010 | Overdrive Clutch Housing Replacement | K7612 | GMNA |
| 8468010 | Overdrive Clutch Housing Replacement | K7613 | GMNA |
| 8468030 | 4-5-6 Clutch Hub Replacement | K7587 | GMNA |
| 8468072 | Sun Gear Carrier and Sun Gear Overhaul | K7589 | GMNA |
| 8468110 | Output Carrier Replacement | K7591 | GMNA |
| 8468190 | Low and Reverse Band Replacement | K7596 | GMNA |
| 8468210 | Output Carrier Transfer Drive Gear Hub Replacement | K7598 | GMNA |
| 8468230 | Front Differential Transfer Drive Gear Support Replacement | K7599 | GMNA |
| 8468330 | Front Differential Drive Pinion Bearing Cup, Washer, and Lubricant Dam Replacement - Torque Converter Housing Side | K7106 | GMNA |

| Global Labor Code | Labor Code Description | Old Labor Code | Country of Sale Index |
|---|---|---|---|
| 8468330 | Front Differential Drive Pinion Bearing Cup, Washer, and Lubricant Dam Replacement - Torque Converter Housing Side | K7605 | GMNA |
| 8468350 | Front Differential Drive Pinion Gear Bearing Cup and Lubricant Dam Replacement | | |
| 8468450 | Front Differential Carrier Assembly Replacement | K7619 | GMNA |
| 8468470 | Differential and Final Drive Assembly Replacement | K7620 | GMNA |
| 8468470 | Differential and Final Drive Assembly Replacement | K7640 | GMNA |
| 8468470 | Differential and Final Drive Assembly Replacement | K703155 | Holden Australia |
| 8468470 | Differential and Final Drive Assembly Replacement | K703156 | Holden Australia |
| 8468470 | Differential and Final Drive Assembly Replacement | K703155 | Holden New Zealand |
| 8468470 | Differential and Final Drive Assembly Replacement | K703156 | Holden New Zealand |
| 8468492 | Final Drive Assembly Overhaul | K7629 | GMNA |
| 8468550 | Differential Carrier Replacement | K7660 | GMNA |
| 8468550 | Differential Carrier Replacement | 2316600 | GMK Overseas |
| 8468590 | Final Drive Internal Gear Replacement | K6399 | GMNA |
| 8468590 | Final Drive Internal Gear Replacement | K7750 | GMNA |
| 8468612 | Rear Case Overhaul | K7751 | GMNA |
| 8468630 | Transmission Case Replacement | K2600 | GMNA |
| 8468630 | Transmission Case Replacement | K7800 | GMNA |
| 8468630 | Transmission Case Replacement | 2211100 | GMK Domestic |
| 8468630 | Transmission Case Replacement | K703160 | Holden Australia |
| 8468630 | Transmission Case Replacement | K7800 | Holden Australia |
| 8468630 | Transmission Case Replacement | K703160 | Holden New Zealand |
| 8468630 | Transmission Case Replacement | K7800 | Holden New Zealand |
| 8468630 | Transmission Case Replacement | 5240400 | GMK Overseas |
| 8468630 | Transmission Case Replacement | 5420100 | GMK Overseas |
| 8468710 | Tow/Haul Switch Replacement | N2581 | GMNA |
| 8468730 | Transmission Wiring and/or Connector Repair or Replacement | N6629 | GMNA |
| 8468730 | Transmission Wiring and/or Connector Repair or Replacement | 2512800 | GMK Domestic |
| 8468730 | Transmission Wiring and/or Connector Repair or Replacement | 5422700 | GMK Domestic |
| 8468730 | Transmission Wiring and/or Connector Repair or Replacement | 5320600 | GMK Overseas |
| 8469959 | Customer Concern Not Duplicated (CCND) - Automatic Transmission | | |