

# BEDLINER, BED MAT AND TAILGATE MAT FOR GMC SIERRA AND CANYON BY BEDRUG™



## BEDLINER

For the ultimate in innovative and unique truck bedliners, choose the BedRug™<sup>1</sup> Bedliner. It offers the look and comfort of carpet in ultra-tough 100% polypropylene (essentially plastic) construction while protecting the truck bed from impact dings and damage. It stands up to the most harsh conditions owners can throw at it – from gravel to battery acid – and still protects precious cargo and your knees!

- Molded to fit specific GMC pickup models to look great and fit like a glove
- Creates a void-free surface without damaging the cargo bed and allows easy access to Original Equipment cargo tie-downs and accessories
- Non-skid surface keeps cargo in place
- A built-in hinge between the truck bed and tailgate prevents debris from collecting
- Fade- and UV-resistant foam is similar to that used in life jackets. It won't absorb water and will not mold or mildew
- Water simply runs off the surface, through the zippered perimeter and out the cargo bed's factory drain holes – drying in as little as 20 minutes
- Cleans easily with a garden hose, power washer or vacuum to look good as new

## BED MAT

With cutting-edge materials designed especially for outside use, BedRug™<sup>1</sup> brings next-gen performance to bed and tailgate protection for Sierra and Canyon. Featuring an ultra-tough 100% polypropylene mat that's fade- and UV-resistant, the BedRug™<sup>1</sup> Bed Mat offers the look and feel of carpet in a water-resistant fiber that's slip- and skid-resistant and dries in as little as 20 minutes. Added features include:

- A ¾-inch-thick custom-molded foam backing that conforms to the cargo bed contours while protecting cargo and providing a comfortable kneeling surface
- Foam backing that won't scratch the truck bed or allow mold or mildew to form – water simply runs out the factory drain holes in the truck bed
- A contact surface that stands up to nearly any spill imaginable – bleach, battery acid, oil or gasoline washes right off
- Cleans easily with a hose, power washer or vacuum to look as good as new
- Installs in minutes with hook-and-loop fasteners
- Includes tailgate mat on Next Generation 2019 Sierra 1500
- Not compatible with MultiPro™ tailgate

## TAILGATE MAT

- Available separately – use independently or with the Bed Mat
- Features a ¼-inch-thick foam backing to provide a comfortable kneeling surface
- Same surface composition, water resistance and easy cleanup as the Bed Mat
- Installs in minutes with hook-and-loop fasteners – no drilling

FOR MORE INFORMATION, VISIT YOUR LOCAL GMC DEALER OR [GMC.COM/ACCESSORIES](https://www.gmc.com/accessories).

<sup>1</sup> Ⓐ Non-GM warranty. Limited warranty by BedRug™, 3 years/36,000 miles (whichever occurs first). For more information, contact your dealer.

**BEDRUG**  
NEXT GENERATION BEDLINERS

**GMC**  
ACCESSORIES

# BEDLINER, BED MAT AND TAILGATE MAT FOR GMC SIERRA AND COLORADO

## BED MAT

PART #	BED SIZE	VEHICLE	MSRP <sup>1</sup>	INSTALL TIME
19417380 <sup>2,3</sup>	Short Box	Next Generation 2019 Sierra 1500	\$209	0.3 hr
19417381 <sup>2,3</sup>	Standard Box	Next Generation 2019 Sierra 1500	\$209	0.3 hr
19417382 <sup>2,3</sup>	Long Box	Next Generation 2019 Sierra 1500	\$209	0.3 hr
19333191	Short Box	2014-18 Sierra	\$159	0.3 hr
19333192	Standard Box	2014-18 Sierra 2019 Sierra Limited 1500 2015-19 Sierra HD	\$159	0.3 hr
19333193	Long Box	2014-18 Sierra 2019 Sierra Limited 1500 2015-19 Sierra HD	\$169	0.3 hr
19333194	Short Box	2015-19 Canyon	\$159	0.3 hr
19333195	Long Box	2015-19 Canyon	\$159	0.3 hr

## BEDLINER

PART #	BED SIZE	VEHICLE	MSRP <sup>1</sup>	INSTALL TIME
19333198	Short Box	2015-2019 Canyon	\$429	0.8 hr
19333199	Long Box	2015-2019 Canyon	\$429	0.8 hr

## TAILGATE MAT

PART #	BED SIZE	VEHICLE	MSRP <sup>1</sup>	INSTALL TIME
19333196	NA	2014-18 Sierra 2015-18 Sierra HD	\$49	0.2 hr
19333197	NA	2015-19 Canyon	\$49	0.2 hr

<sup>1</sup> Manufacturer's Suggested Retail Price. Tax and installation extra. See dealer for details.

<sup>2</sup> Includes tailgate mat.

<sup>3</sup> Not compatible with MultiPro™ tailgate.

October 2018

